

2009/2010

ASS. REC. BY:

REF: es/ASM/2017/418/Rqd302

Special Instruction:

Surveyor: Rasul

ASSIGNMENT (Office)

From (Person): Jas Tan

of

ASM (AXA)

Date/Time:

03/10/2019

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / ENV / MV / CS

To Inspect Vehicle No:

SGL 1952A

Insured:

at Workshop m/s

Hin Tung Workshop

Tel:

6858 3000

of

Blk 1008 Bkt Merah Lane 3 # 01-20

Policy No:

Claim No:

S9M 022HJ

Sum Insured:

Excess:

NIL

Make of Veh
(Client's Record)

D.O.A.

01/10/2019

CA

REV

REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:40am @ 3/10/19

Person Contacted:

Susun

Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
3/10/2019	Bryan ask surveyor to conduct normal survey and the investigation pccs to shenwin.
	SGL1952A-X
03/10/19 @	10.28am revert to Jas Tan via Summit Clinic
14/10/19	Submit extensive Total Loss Report.

Mr Teo. 1222hrs.
15 Oct checking
67495658.

ASS. REC. BY:

[Signature]

REF:

CS1 ASM 19017418/R17203

023F

COXPIRY: 2026/AUG

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SHL 1952A

at Workshop m/s HIN LUNG

of 1008, BUKIT MERAH L3 #01-20

Insured: ASM (AYA)

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: NIL

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 48K *40%*

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHL 1952A Yr Regn: 2006 / AUG

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: FIAT M. SCHUMACHER cc 2446

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ZFA 192 00000575116

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rm / STD A/Rim or _____

Tyre Size: F: 215/45R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIRELLI / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 01/10/19 D.O.I. 03/10/19

Survey held at HIN LUNG

Des. of Damages: FR Rear / O/S / N/S / UIC / Rooftop or _____

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TOTAL LOSS
RECEIVED 14 NOV 2019	

Date/Time, File Pass to?

: Prel. Report

11/11/19

: Final Report

Date/Time, File Return to?

3

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: 200

Transportation: _____

_____ S + RS _____

Pinns _____

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech. Invt (\$)

: Wheel end (\$)

Report Format: Smart claim / TL &

Long Form / TL & _____


[Signature]
\$170.00 of 9/10/19

◀ Service Request Details

Claim

S9M022HJ

Reference

None 

Loss Date

October 1, 2019

Report Date

Oct 3, 2019 8:50:29 AM

Request Date

October 3, 2019

Due Date

October 10, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Fire

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SGL1952A

Model
STILO SCHUMACHER 2.4

Service Address

...

Primary Contact/Insured

TEO TEE HUA
100E PASIR PANJANG ROAD, #07-05 CENTURY WAREHOUSE, 118521, Singapore

ADMIN@ICAREGIA.COM.SG

Claim Handler

TAN Jas
6568804844
jas.tan@axa.com.sg

Additional Instructions
OD - HIN LUNG OD XS NIL please conduct survey and fire investigation

[Messages](#)
[Invoices](#)
[History](#)
[Documents](#)
[Assessment](#)
[Metrics](#)
[Notes](#)

Document Type
 Document SubType

[+ Upload Documents](#)

NAME	 DL.jpg
TYPE	Forms / Claim Documents
SUB-TYPE	Driver's License / IDP
AUTHOR	HIN LUNG WORKSHOP
DATE UPLOADED	October 3, 2019

NAME	 ADVISE.jpg
TYPE	Forms / Claim Documents

AUTHOR HIN LUNG WORKSHOP

DATE UPLOADED October 3, 2019

NAME  OD HIN LUNG-ESTIMATE.jpg

TYPE Reports & Statement

SUB-TYPE Estimate / Quotation

AUTHOR HIN LUNG WORKSHOP

DATE UPLOADED October 3, 2019

NAME  SAS2679237.pdf

TYPE Reports & Statement

SUB-TYPE GIA Report

AUTHOR HIN LUNG WORKSHOP

DATE UPLOADED October 3, 2019

NAME  GA120540-Certificate of Insurance.pdf

TYPE Forms / Claim Documents

SUB-TYPE Policy Schedule / Covernote / Certificate of insurance

AUTHOR DHIWAR Namrata

DATE UPLOADED October 3, 2019

NAME  GA120540-Policy Schedule.pdf

TYPE Forms / Claim Documents

SUB-TYPE Policy Schedule / Covernote / Certificate of insurance

DATE UPLOADED October 3, 2019

NAME  SGL1952A INS GIA.pdf

TYPE Reports & Statement

SUB-TYPE GIA Report

AUTHOR DHIWAR Namrata

DATE UPLOADED October 3, 2019

NAME  OD EMAIL FROM WORKSHOP.pdf

TYPE Letters and Correspondence

SUB-TYPE Workshop

AUTHOR DHIWAR Namrata

DATE UPLOADED October 3, 2019



SINGAPORE CIVIL DEFENCE FORCE

FIRE REPORT

1. GENERAL INFORMATION			
INCIDENT NO. : /20191001/0486	LOCATION OF FIRE:		
FIRE REPORTED ON : 01 October 2019	At the junction of Lorong 1 & 6 Toa Payoh		
TIME OF CALL : 14:15:02 hrs	Singapore		
STATION COVERAGE : Bishan Fire Station			
2. INCIDENT INFORMATION			
FIRE INVOLVED: The engine of a Fiat car (SGL1952A).			
METHOD OF EXTINGUISHMENT: By SCDF crew using two compressed air foam backpacks and a 38mm hoseline jet from fire appliances.			
PROBABLE CAUSE OF FIRE: Accidental (Overheating at engine compartment)			
DAMAGE SUSTAINED: As a result of the fire, the engine, windscreen and front parts of the car were damaged. The interior of the car sustained varying degrees of heat and smoke damage.			
3. FATALITY/INJURY INFORMATION			
NAME	PIN/FIN	ADDRESS	DEAD/INJURIES SUSTAINED
NIL	NIL	NIL	NIL
REPORT CERTIFIED TRUE AND CORRECT BY:			
HUANG WEI KANG for COMMISSIONER SINGAPORE CIVIL DEFENCE FORCE			

This is a computer generated Fire Report. No signature is required.



SINGAPORE CIVIL DEFENCE FORCE
91 UBI AVENUE 4
SINGAPORE 408827
TELEPHONE: 6280 0000
GST REG NO: MG-8400000-5

TAX INVOICE/RECEIPT

Name : SIEW SHIAU CHAN
Address : 51 UBI AVE 51 UBI AVENUE 1
#01-25 PAYA UBI INDUSTRIAL PARK
Singapore 408933

Receipt No : 5706065615336631303045
Date/Time : 09/10/2019 15:34
eService ID : FR2019100903952

S/No	Payment Mode	Description	Reference No	Net Amount	GST (7% GST)	Gross Amount
1	Credit Card	Fire Report	FR2019100903952	170.00	0.00	170.00
					Total Amount (SGD)	170.00

REMARKS:

Date and Time [01/10/2019 14:05] - Location of Fire [T JUNCTION OF TOA PAYOH LOR 1 & LOR 2 T AFFIC LIGHT]

Note: This is a computer generated receipt. No signature is required. Receipt is void if payment is dishonoured.



Fire Report Application

Your request for the Fire Report has been confirmed and the amount of SGD170.00 will be deducted from your account. You will receive the report within 8 working days upon completion of investigations. Please quote the following transaction number when making enquiries.

Download Tax Invoice/Receipt

Transaction Number: FR2019100903952

Date/Time: 09/10/2019 15:34

INCIDENT DETAILS						
Date and Time	01/10/2019 14:05					
Location of Fire	T JUNCTION OF TOA PAYOH LOR 1 & LOR 2 TRAFFIC LIGHT					
Fire Involved	MOTORCAR - SGL 1952A					
REQUESTOR DETAILS						
Requestor Type	Insurance Companies					
Requestor ID Type	Foreign International	Requestor ID	G8012183R			
Name of Applicant	SIEW SHIAU CHAN					
Company Name	LKK AUTO CONSULTANTS PTE LTD					
Company UEN						
Company Reference Number	CS/ASM19017418/R1qd3					
CONTACT DETAILS						
Mode of Collection	Email					
Main Contact No.	62563561	Office No.				
Handphone No.		Fax No.				
Email Address	sur@lkkauto.com					
Address	Block No.	51 UBI AVE	Floor No.	01	Unit No.	25
	Street Name	51 UBI AVENUE 1				
	Building Name	PAYA UBI INDUSTRIAL PARK	Postal Code	408933		
PAYMENT DETAILS						
Payment Mode	Credit/Debit Card					
EP Reference No.	5706065615336631303045					
PSI Reference No.	45416441-f825-4478-a665-708514498c63					
Total Fees	SGD170.00					

DHIWAR Namrata

From: hlungws <hlungws@singnet.com.sg>
Sent: Wednesday, October 02, 2019 4:33 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Subject: [EXTERNAL] Re : SGL1952A , AD : 01/10/2019 , OD Claim , Appointment for Survey.
Attachments: SAS2679237.pdf

Categories: Namrata

Dear Sirs,

We refer to the above subject and kindly take note that the vehicle is already in our workshop (warded) on 01/10/2019.

Please arrange for survey and the vehicle is beyond repair.

Thank you and please let us hear from you.

Regards,
Anna
Hin Lung Workshop
Tel: 6858 3000 Fax: 6476 0075
Address: Blk 1008 Bukit Merah Lane 3 #01-20 Singapore 159722



Auto
Consultants
Pte Ltd

31 UBI AVE L #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564312

Immediate Advice

To : AXA Insurance Pte Ltd

7/10/2019

Survey Details:

Date of loss	1-Oct-19
Date of appointment	3-Oct-19
Date of survey	3-Oct-19
Location of survey	HIN LUNG WORKSHOP

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SGL 1952A
Make and Model	FIAT M.SCHUMACHER
Date of registration	28/8/2006
Excess	\$ -
Market Value	\$ 40,000.00
Parf Rebate	\$ 37,597.00
Nett Loss	\$ 2,403.00

Repair details:

Initial Estimate	TOTAL LOSS
------------------	------------

Proposed/Revised repair cost:

Parts	TOTAL LOSS
Check items (estimate)	\$ -
Labour	\$ -
Total	#VALUE!
Lump Sum(if applicable)	-

Number of days for repair	<u>0</u>
---------------------------	----------



Remarks:

PENDING FOR INVESTIGATION. REPAIR COST NOT ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.

Mandate:

Liability(TP)		%
Proposed repair cost		\$
Loss of use		\$ no. of days
Loss of rental		\$ no. of days
Loss of income		\$ no. of days
LTA search fees		\$
Others		\$
Proposed Total		#VALUE!

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
 Owner ID: 023F

Vehicle Details

Vehicle No.: SGL1952A
 Vehicle to be Exported: Yes
 Intended Deregistration Date: 01 Oct 2019
 Vehicle Make: FIAT
 Vehicle Model: M.SCHUMACHER
 Primary Colour: Red
 Manufacturing Year: 2005
 Engine No.: 192A20004528404
 Chassis No.: ZFA19200000575116
 Maximum Power Output: 125.0 kW (167 bhp)
 Open Market Value: \$27,003.00
 Original Registration Date: 28 Aug 2006
 First Registration Date: 28 Aug 2006
 Transfer Count: 1
 Actual ARF Paid: \$29,704.00

*Depreciation @ 5.5%
 40k.
 8/5.*

Intended PARF Rebate Details

PARF Eligibility: Forfeited
 PARF Eligibility Expiry Date: -
 PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 27 Aug 2026
 COE Category: E - Open Category
 COE Period(Years): 10
 PQP Paid: \$54,463.00
 COE Rebate Amount: \$37,597.00
Total Rebate Amount: \$37,597.00

The information contained herein is correct as at 01 Oct 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/10/2019 14:25
Date Of Accident	01/10/2019 14:05
Exact Location Of Accident	T JUNCTION OF TOA PAYOH LOR 1 & LOR 2 TRAFFIC LIGHT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGL1952A
Insured/Policyholder	
Name Of Registered Owner	TEO TEE HUA
NRIC No	S0117023F
Email Address	THAPL@SINGNET.COM.SG
Mobile Phone No	(LOCAL) +65-96730038
Alternative Phone No	OFFICE-62742111

Vehicle Particulars

Manufacturer	FIAT
Model	M.SCHUMACHER
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA120540
Cover Note Number	

Driver

Name of Driver	TEO TEE HUA
NRIC No	S0117023F
Date Of Birth	08/03/1952
Occupation	INDOOR
Date Of Driving Pass	06/09/1972
Driving Experience	47 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96730038
Fax Number	
Contact Number	OFFICE-62742111
EMail Address	THAPL@SINGNET.COM.SG

Address	62 TELOK BLANGAH HEIGHTS #12-205
Postcode	100062
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	FIRE, EXPLOSION OR LIGHTNING
Weather Conditions	SUNNY AND WARM
Road Surface	HOT

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	1
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	999 (TEL)
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time: 2/10/2019
12:00 noon

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name: *Ann... 116*
NRIC/FIN No.:



**SINGAPORE POLICE FORCE
CASE CARD**

Report Number: *E/2019 1001/0068*

Classification: *No offence disclosed*

Actions Taken

Police Advisory Issued

Community Mediation

Magistrate's Complaint

Investigation Branch

Others :

Officer's Name:

Aio Yan Tiezheng

Contact Number:

6391 0000

Useful Website Addresses:-

Magistrate's Complaint -
www.statecourts.gov.sg

Community Mediation Centre:-
<https://www.mlaw.gov.sg/content/cmcc/en.html>

Samaritans of Singapore:-
<https://sos.org.sg/>

Family Service Centre:-
<http://www.ncss.gov.sg/>



**SINGAPORE
POLICE FORCE**



D/20191007/2025

1 of 2

POLICE REPORT (NP299)

Report No. D/20191007/2025

Police Station Of Origin
Telok Blangah NPP
51 Telok Blangah Drive #01-116
SINGAPORE 100055
Tel No: 1800-2729999


Date/Time Report Made 07/10/2019 13:21	Vide Report No. E/20191001/0068	Station Diary No. 11	
Name Of Informant TEO TEE HUA	Address APT BLK 62 TELOK BLANGAH HEIGHTS #12-205 SINGAPORE 100062		
ID Type / ID No. NRIC NO / S0117023F	Contact No. Home/Office	Mobile 96730038	
Nationality SINGAPORE CITIZEN	Email Address		
Occupation Photographer	Sex Male	Age 67	Date of Birth 08/03/1952
Institution/School Name	Race Chinese		
Date/Time Of Incident 01/10/2019 13:55	Language		
	Location Of Incident LORONG 6 TOA PAYOH SINGAPORE In front of Seu Teck Sean Tong Temple		

Brief details.

On the 01/10/2019 at 1355hrs, I was driving my vehicle regn no. SGL 1952 A (Red Fiat Stilo 2.4) along Lor 6 Toa Payoh in front of Seu Teck Sean Tong Temple. At that point of time, I was waiting at the junction and my car was 3rd from the traffic light. Subsequently, I realized there was white smoke coming out from the front left side of my vehicle and I immediately alighted my vehicle and went to the road side and fire started to engulf my vehicle's engine. At that point of time, I was alone.

Signature Of Officer Recording The Report: D / Sgt 2 MOHAMMED.MUNZIR BIN AZIZ	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 07/10/2019 13:21
Officer In-Charge Of Case: D / Clementi Police Divisional Investigation Branch / Insp JELENE ONG WEE SUAN Contact No.: 68727203	Classification Of Case:

Authentication Stamp






POLICE REPORT (NP299)


CONTINUATION OF REPORT

Report No. D/20191007/2025


I called for emergency services and in a short while after they arrived, they managed to put out the fire. After all is done, I contacted my office colleague who contacted AXA insurance and my vehicle was towed to their authorized workshop. I wish to add that my vehicle's engine compartment is totally burnt.

I am lodging this report for insurance purpose.

Signature Of Officer Recording The Report: D / Sgt 2 MOHAMMED MUNZIR BIN AZIZ	
Signature Of Interpreter: Not applicable	
Officer In-Charge Of Case: D / Clementi Police Divisional Investigation Branch / Insp JELENE ONG WEE SUAN Contact No.: 68727203	

Signature Of Informant: 
Date/Time: 07/10/2019 13:21
Classification Of Case:

Authentication Stamp





Your Ref : S9M022HJ

Date: 19th November 2019

Our Ref : CS/ASM19017418/R1qd3e2

M/s AXA Insurance Pte Ltd
8 Shenton Way #24-01
AXA Tower
Singapore 068811
(The Motor Claims Department)

Attn: Jas Tan

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SGL 1952A
ACCIDENT ON 01/10/2019**

Instruction was received to inspect the vehicle Reg. No. SGL 1952A. The inspection was conducted on 03/10/2019 at the premises of M/s Hin Lung Workshop, Blk 1008 Bukit Merah Lane 3 #01-20, Singapore 159722.

The following vehicle information was recorded:

Registration Number	: SGL 1952A
Make/Model	: Fiat M.Schumacher
Year of Registration	: 2006
Body Colour	: Red
Chassis Number	: ZFA19200000575116
Engine Capacity	: 2446 cc
Speedometer Reading	: -

The vehicle sustained damages at the front portion. (Details see photographs enclosed).



In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as "**uneconomical Total Loss**".

Market Value	SS	40,000.00
Less: LTA Reimbursement Value (RV)	(SS	37,597.00)
Nett Liability	SS	<u>2,403.00</u>

Vehicle Inspected By:

MOHD. RASUL BIN MOHD YUNUS
AMSOE, AMIRTE, AMSAE-A, M.MATAI
Automotive Assessor

K.K.LAU
MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.