

ASS. REC. BY:

REF: CS/CT117017447/T19-1301 Special Instruction:

Survivor: Taufiqh

ASSIGNMENT (Office)

From (Person): Elaine Chong of CTI Date/Time: 3.10.19 13.49p.m.

Estimated cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FBJ 8246D Insured: GY 4181U

at Workshop n/s Pang Scooter Service Tel: 62714618

of BIK 1006 Bukit Merah Lane 2 # 01-06

Policy No: DMCR SA 30403018033 Claim No: SVM 19D 204116 C02

Sum Insured: Excess:

Make of Vcl: D.O.A. 8.6.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS up 4.10.2019

Date/Time: 3/10/19 3.49p.m. Person Contacted: Michael

H.O.D. Endorsement:

Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	FBJ 8246D - NSA / Fwd 19/10/2019 / Y DCA - 02/06/2019
	GY 4181U - NSA / Fwd 19/10/2019 / Y DCA - 05/06/2019

Tanpin


REF: CTE

ASSIGNMENT

From: 7/10/2019 Date: 7/10/2019
 Estimated Cost: FBJ 8246D
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: Pang Scooter
 at Workshop m/s: Blk 1006 Blk marsh lane 2 # 01-06
 of: Blk 1006 Blk marsh lane 2 # 01-06
 Insured:
 Policy No:
 Claims No:
 Sum Insured: Excess:
 (Client's Record)
 Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$6000
 IDAC Accident Rpt: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: 5 days Res: Yes or No
 Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS lup

Date: Person Contacted: Vehicle: IN / OUT
Michael

Veh No: FBJ 8246D Yt Regn: 2014 NOV
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Yamaha YZF-R15 C.C. 150
 Colour: Black/Orange A/C: Insured / Std / NI / NA
 Sp. Reading: — T/Radio: Insured / Std / NI / NA
 Eng/No:
 C/No: ME 111K041E2017751
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 90/80/147
 R: 140/70/17
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: Rear:
 R/Bal: 5 mm R/Bal: 5 mm
 L/Bal: mm L/Bal: mm
 D.O.A. D.O.I. 7/10/19Q 420p
 Survey held at Pang Scooter
 Des. of Damages (Frt) / Rear / (O/S) / (N/S) / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
14/11/19	* Battery weak 4/5 \$ 3200, 5 days confirm with Michael thru phone. LRA \$ 1568, 33%.

RECEIVED 15 NOV 2019

Date/Time, File Pass to? ☐ : Preli. Report

15/11/19 tanpin ☐ : Final Report

Date/Time, File Return to?

0

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Insp (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation

S + PS \$

Phone

Other

TOTAL

Report Format:

Lump Sum / TP

MEK-TP

3200

Ta

220

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Oct 2019		03 Oct 2019 13:49 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:									
Main Claimant: ABU BAKAR BIN HAMZAH , ID: S1193182									
Vehicle Reg. No.:		FBJ8246D	Date of Loss:	08/06/2019 14:00 - :59					
Claim Type:		TP / SNM19D204616C02	Policy/Cover Note No.:	DMCVSN30403018033					
Vehicle Reg. No. (Insured):		GY4181U	Policy No. (Claimant):	PNMC2019-00002204					
		Excess:	S\$0.00						
Repairer: Pang Scooter Service (HQ) BLK 1006 BUKIT MERAH LANE 2 #01-06, 159762 Bukit Merah - Tel: 62714618									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]									
Claimant's Insurer: FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 14/10/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	182J
Vehicle Details	
Vehicle No.:	FBJ8246D
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Nov 2019
Vehicle Make:	YAMAHA
Vehicle Model:	YZF-R15 MANUAL
Primary Colour:	Black
Manufacturing Year:	2014
Engine No.:	1CK4017687
Chassis No.:	ME11CK041E2017751
Maximum Power Output:	-
Open Market Value:	\$2,867.00
Original Registration Date:	17 Nov 2014
First Registration Date:	17 Nov 2014
Transfer Count:	4
Actual ARF Paid:	\$431.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	16 Nov 2024
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$4,290.00
COE Rebate Amount:	\$2,147.00
Total Rebate Amount:	\$2,147.00

The information contained herein is correct as at 14 Nov 2019

OK

Blk 1006 Bukit Merah Lane 2 #01-06 Singapore 159762
Tel : 6271 4618 Fax : 6273 2632

Tel : 6271 4618 Fax : 6273 2632

BIKE NO.: FBJ 8246D

DATE ACCIDENT : 8.06.2019

MAKE / MODEL : YAMAHA/R15-150CC(M)

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date:

4269



**SINGAPORE
POLICE FORCE**

Traffic Police
10 Ubi Avenue 3
Singapore 408865
Tel +65 6547 0000
Fax +65 6547 4883
www.police.gov.sg

Our Ref : TP/IP/38977/2019
Date : 1 AUGUST 2019

JAUHARI BIN ABU BAKAR
BLK 939 TAMPINES AVENUE 5
#03-167
SINGAPORE 520939

Dear Sir/Madam

**ROAD TRAFFIC ACCIDENT INVOLVING FBJ8246D AND GY4181U ALONG SIMS AVENUE ON
08/06/2019 AT ABOUT 2.00PM**

I refer to the above accident.

Please be informed that we have completed our investigations which revealed that the driver of **GY4181U** had committed an offence of **Inconsiderate Driving under Section 65(b) of the Road Traffic Act Chapter 276**. Action has been initiated against the driver for the said offence.

Yours faithfully

**HEAD INVESTIGATION
TRAFFIC POLICE
SINGAPORE POLICE FORCE**

This is a computer-generated letter. No signature is required.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/08/2019 10:37
Date Of Accident	08/06/2019 14:00
Exact Location Of Accident	ALONG SIMS AVENUE NEAR GEYLANG SERAI JUNCTION
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBJ8246D
Insured/Policyholder	
Name Of Registered Owner	ABU BAKAR BIN HAMZAH
NRIC No	S1193182J
Email Address	BOIKEYJAUHARI@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96121370
Alternative Phone No	OFFICE-97260421

Vehicle Particulars

Manufacturer	YAMAHA
Model	YZF-R15-150CC (M)
Exact Purpose for which vehicle was being used at time of accident	WORKING PURPOSES
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	PNMC2019-00002204
Cover Note Number	

Driver

Name of Driver	JAUHARI BIN ABU BAKAR
NRIC No	T0013343J
Date Of Birth	21/04/2000
Occupation	OUTDOOR
Date Of Driving Pass	14/02/2019
Driving Experience	0 YEAR AND 3 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-96121370
Fax Number	
Contact Number	OFFICE-97260421
EEmail Address	BOIKEYJAUHARI@GMAIL.COM

Address	BLK 939 TAMPINES AVENUE 5 #03-167
Postcode	520939
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO POLICE REPORT T/20190609/2003

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GY4180U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	ARUMUGAM MURUGANANDHAM
NRIC/Passport Number	G7506283W
Contact Number	87867809
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	2

Passenger 1

NAME: : AH HONG

GENDER: : MALE

DETAILS OF INJURED PERSON 1

Name JAUHARI BIN ABU BAKAR

Approximate Age

Injuries Sustain SLIGHT INJURY

Injured person in which vehicle? FBJ8246D

Were seat belts worn?

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

 1 Aug 2014
Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre
Name:
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN

SIMS AVENUE TOWARDS EAST COAST COORR 1



A) 88J 8246D
B) G/4181U

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ms *Report to Police Report*
7/2019 0609/2003

DECLARATION

I/We declare the foregoing particulars are true in every respect

Policyholder's Signature
Date & Time

John *1 Aug 2019*
Driver's Signature
(If driver is not the policyholder)
Date & Time

01/08/2019
Reporting Centre Personnel Signature
Name:
NRIC/TIN No:

POLICE REPORT



**SINGAPORE
POLICE FORCE**



T/20190029/2003

1 of 4

Police Station Of Origin:
Tampines N.P.C.
6 Tampines Avenue 4 SINGAPORE 529652
Tel No. 1800-5871999

Report No. T/20190029/2003

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 09/08/2019 00:34		Vide Report No.		Station Diary No. 16	
Informant's Particulars					
Name of Informant: JAUHARI BIN ABU BAKAR		Address: APT BLK 939 TAMPINES AVENUE 5 #03-167 SINGAPORE 520939			
ID Type / ID No.: NRIC NO / T0013343J		Contact No.: Home/Office:		Mobile: 97260421	
Nationality: SINGAPORE CITIZEN		Email:			
Sex: Male	Age: 19	Date of Birth: 21/04/2000	Type of Informant: Rider		
Race: Malay		Language:		Institution / School Name:	
Occupation: FOOD PANDA RIDER		Driving Licence Information: Class: 2B		Date of Expiry:	

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 08/08/2019 14:00	Type of Location: Straight Road
Location: Along Road 1 SIMS AVENUE ALONG SIMS AVENUE NEAR TO THE RIGHT SIDE OF GEYLANG SERAI JUNCTION				
Weather: Drizzling		Road Surface: Wet		Road Speed Limit:
Traffic Flow:		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: BIKE SKIDDED TO AVOID COLLISION				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBJ8246D	Motorcycle				Seriously Damaged	0
GY4181U	Lorry				No Damage	1

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

POLICE REPORT



**SINGAPORE
POLICE FORCE**



T/20190609/2003

Police Station Of Origin
Tampines N.P.C

2 of 4

6 Tampines Avenue 4 SINGAPORE 529682

Report No. T/20190609/2003

Tel No: 1800-5871999

CONTINUATION OF REPORT

Rider			
Name	JAUHARI BIN ABU BAKAR	ID No	T0013343J
Related Vehicle	FBJ8248D (Motorcycle)	Contact No	97260421
Hospital/Clinic	CHANGI GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B Date of Expiry: NIL
Date Treatment	08/08/2019	Date Discharge	08/08/2019
No. of Days granted Medical Leave	07	Degree of Injury	Slight
MANAGER			
Name	AH HONG	ID No	NIL
Related Vehicle	GY4181U (Lorry)	Contact No	87867809
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	ARUMUGAM MURUGANANDHAM	ID No	G7506283W
Related Vehicle	GY4181U (Lorry)	Contact No	98650810
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details:

On the above mentioned date, time and place, I was riding my bike along Sims Ave going towards East coast at lane 1. Suddenly the vehicle that was in lane 2 made an abrupt change of lane to my lane 1. I didn't manage to stop my vehicle but I have changed to lane 2 to avoid the collision with the lorry. However, the lorry left rear portion swipe on my right handle and my bike skidded. I have to pushed myself out from my motorcycle and I had landed onto my left ankle and fell onto the ground.

The lorry stopped their vehicle at the side road and assisted me. They brought me to Changi General Hospital and had assisted to send my motorbike to my house. I managed to get their particulars and also their manager number.

No ambulance or traffic police at scene

POLICE REPORT



**SINGAPORE
POLICE FORCE**



T/20190808/2003

Police Station Of Origin:
Tampines N.P.C.
6 Tampines Avenue 4 SINGAPORE 529682
Tel No: 1800-5871999

4 of 4

Report No: T/20190808/2003

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: G / Sgt 3 NUR HAFIDAH BINTE KAMURIDIN	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 09/08/2019 00:34
Officer In Charge Of Case: TP / AEIT / Sgt 3 KOH CHEE SENG, KEVIN Contact No.: 65472073	Classification Of Case:
Authentication Stamp NP108	 SIGNATURE

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo




Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Oct 2019		03 Oct 2019 13:49 Edit Adj Rpt	S\$3,200.00 Edit Estimates	S\$3,200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: -, Co. Reg. No.: -									
Main Claimant: ABU BAKAR BIN HAMZAH , ID: 511931821									
Vehicle Reg. No.: FBJ8246D		Date of Loss: 08/06/2019 14:00 - :59 [54 Months and 22 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM19D204616C02		Policy/Cover Note No.: DMCVSN30403018033							
Vehicle Reg. No. (Insured): GY4181U		Policy No. (Claimant): PNMC2019-00002204							
		Excess: S\$0.00							
Repairer: Pang Scooter Service (HQ) BLK 1006 BUKIT MERAH LANE 2 #01-06, 159762 Bukit Merah - Tel: 62714618									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]									
Claimant's Insurer: FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 14/10/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBJ8246D (SNM19D204616C02)

[GY4181U]

TP

ABU BAKAR BIN HAMZAH

Jun 8 2019 2:00PM

[-]

Pang Scooter Service

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Assessment Reports									1 per page		☒
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)							Thumbnail	Print	
1	10/06/19 13:24	Accident Statement							 Load HTM		
Photos/Images									3 per page		☒
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)							Thumbnail	Print	
1	10/06/19 13:17	Accident Photo [Linked Accident Report Documents]							 Load JPG	☒	
2	10/06/19 13:17	Accident Photo [Linked Accident Report Documents]							 Load JPG	☒	
3	10/06/19 13:17	Accident Photo [Linked Accident Report Documents]							 Load JPG	☒	
4	10/06/19 13:17	Accident Photo [Linked Accident Report Documents]							 Load JPG	☒	
5	10/06/19 13:17	Accident Photo [Linked Accident Report Documents]							 Load JPG	☒	
6	10/06/19 13:18	Accident Photo [Linked Accident Report Documents]							 Load JPG	☒	
7	10/06/19 13:18	Accident Photo [Linked Accident Report Documents]							 Load JPG	☒	
8	10/06/19 13:18	Accident Photo [Linked Accident Report Documents]							 Load JPG	☒	
9	10/06/19 13:19	Accident Photo [Linked Accident Report Documents]							 Load JPG	☒	
10	10/06/19 13:19	Identification Card [Linked Accident Report Documents]							 Load JPG	☒	
11	10/06/19 13:19	Identification Card [Linked Accident Report Documents]							 Load JPG	☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	15/11/19 11:21	General View							 Load JPG	☒	
2	15/11/19 11:21	General View							 Load JPG	☒	
3	15/11/19 11:21	General View							 Load JPG	☒	
4	15/11/19 11:21	General View							 Load JPG	☒	
5	15/11/19 11:21	General View							 Load JPG	☒	
6	15/11/19 11:21	General View							 Load JPG	☒	
7	15/11/19 11:21	General View							 Load JPG	☒	
8	15/11/19 11:21	General View							 Load JPG	☒	
9	15/11/19 11:21	General View							 Load JPG	☒	
10	15/11/19 11:21	General View							 Load JPG	☒	
11	15/11/19 11:21	General View							 Load JPG	☒	
12	15/11/19 11:21	General View							 Load JPG	☒	
13	15/11/19 11:21	General View							 Load JPG	☒	
14	15/11/19 11:21	General View							 Load JPG	☒	
15	15/11/19 11:21	General View							 Load JPG	☒	
16	15/11/19 11:21	General View							 Load JPG	☒	
17	15/11/19 11:21	General View							 Load JPG	☒	
18	15/11/19 11:21	General View							 Load JPG	☒	
19	15/11/19 11:21	General View							Load JPG	☒	
20	15/11/19 11:21	General View							Load JPG	☒	
21	15/11/19 11:21	General View							Load JPG	☒	
22	15/11/19 11:21	General View							Load JPG	☒	
23	15/11/19 11:21	General View							Load JPG	☒	
24	15/11/19 11:21	General View							Load JPG	☒	

Assessment Reports			1 per page	☒
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
25	15/11/19 11:21	General View	 Load JPG	☒
26	15/11/19 11:21	General View	 Load JPG	☒
27	15/11/19 11:21	General View	 Load JPG	☒
28	15/11/19 11:21	General View	 Load JPG	☒
29	15/11/19 11:21	General View	 Load JPG	☒
30	15/11/19 11:21	General View	 Load JPG	☒
31	15/11/19 11:21	General View	 Load JPG	☒
32	15/11/19 11:21	General View	 Load JPG	☒
33	15/11/19 11:21	General View	 Load JPG	☒
34	15/11/19 11:21	General View	 Load JPG	☒
35	15/11/19 11:21	General View	 Load JPG	☒
36	15/11/19 11:21	General View	 Load JPG	☒
37	15/11/19 11:21	General View	 Load JPG	☒
38	15/11/19 11:21	General View	 Load JPG	☒
39	15/11/19 11:21	General View	 Load JPG	☒
40	15/11/19 11:21	General View	 Load JPG	☒
41	15/11/19 11:21	General View	 Load JPG	☒
42	15/11/19 11:21	General View	 Load JPG	☒
43	15/11/19 11:21	General View	 Load JPG	☒
44	15/11/19 11:21	General View	 Load JPG	☒
45	15/11/19 11:21	General View	 Load JPG	☒
46	15/11/19 11:21	General View	 Load JPG	☒
47	15/11/19 11:21	General View	 Load JPG	☒
48	15/11/19 11:21	General View	 Load JPG	☒
49	15/11/19 11:21	General View	 Load JPG	☒
50	15/11/19 11:21	General View	 Load JPG	☒
51	15/11/19 11:21	General View	 Load JPG	☒
52	15/11/19 11:21	General View	 Load JPG	☒
53	15/11/19 11:21	General View	 Load JPG	☒
54	15/11/19 11:21	General View	 Load JPG	☒
55	15/11/19 11:21	General View	 Load JPG	☒
56	15/11/19 11:21	General View	 Load JPG	☒
57	15/11/19 11:21	General View	 Load JPG	☒
58	15/11/19 11:21	General View	 Load JPG	☒
59	15/11/19 11:21	General View	 Load JPG	☒
60	15/11/19 11:21	General View	 Load JPG	☒
61	15/11/19 11:21	General View	 Load JPG	☒
62	15/11/19 11:21	General View	 Load JPG	☒
63	15/11/19 11:21	General View	 Load JPG	☒
64	15/11/19 11:21	General View	 Load JPG	☒
65	15/11/19 11:21	General View	 Load JPG	☒
66	15/11/19 11:21	General View	 Load JPG	☒
67	15/11/19 11:21	General View	 Load JPG	☒
68	15/11/19 11:21	General View	 Load JPG	☒
69	15/11/19 11:21	General View	 Load JPG	☒
70	15/11/19 11:21	General View	 Load JPG	☒
71	15/11/19 11:21	General View	Load JPG	☒
72	15/11/19 11:21	General View	Load JPG	☒
73	15/11/19 11:21	General View	Load JPG	☒
74	15/11/19 11:21	General View	Load JPG	☒
75	15/11/19 11:21	General View	Load JPG	☒
76	15/11/19 11:21	General View	Load JPG	☒
77	15/11/19 11:21	General View	Load JPG	☒
78	15/11/19 11:21	General View	Load JPG	☒
79	15/11/19 11:21	General View	Load JPG	☒
80	15/11/19 11:21	General View	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
81	15/11/19 11:21	General View	 Load JPG	☒
82	15/11/19 11:21	General View	 Load JPG	☒
83	15/11/19 11:21	General View	 Load JPG	☒
84	15/11/19 11:21	General View	 Load JPG	☒
85	15/11/19 11:21	General View	 Load JPG	☒
86	15/11/19 11:32	Reinspection Photo	 Load JPG	☒
87	15/11/19 11:32	Reinspection Photo	 Load JPG	☒
88	15/11/19 11:32	Reinspection Photo	 Load JPG	☒
89	15/11/19 11:32	Reinspection Photo	 Load JPG	☒
90	15/11/19 11:32	Reinspection Photo	 Load JPG	☒
91	15/11/19 11:32	Reinspection Photo	 Load JPG	☒
92	15/11/19 11:32	Reinspection Photo	 Load JPG	☒
93	15/11/19 11:32	Reinspection Photo	 Load JPG	☒
94	15/11/19 11:32	Reinspection Photo	 Load JPG	☒
95	15/11/19 11:32	Reinspection Photo	 Load JPG	☒
96	15/11/19 11:32	Reinspection Photo	 Load JPG	☒
97	15/11/19 11:32	Reinspection Photo	 Load JPG	☒
98	15/11/19 11:32	Reinspection Photo	 Load JPG	☒
99	15/11/19 11:32	Reinspection Photo	 Load JPG	☒
100	15/11/19 11:32	Reinspection Photo	 Load JPG	☒
101	15/11/19 11:32	Reinspection Photo	 Load JPG	☒
102	15/11/19 11:32	Reinspection Photo	 Load JPG	☒
103	15/11/19 11:32	Reinspection Photo	 Load JPG	☒
104	15/11/19 11:32	Reinspection Photo	 Load JPG	☒
105	15/11/19 11:32	Reinspection Photo	 Load JPG	☒
106	15/11/19 11:32	Reinspection Photo	 Load JPG	☒
107	15/11/19 11:32	Reinspection Photo	 Load JPG	☒
108	15/11/19 11:32	Reinspection Photo	 Load JPG	☒
109	15/11/19 11:32	Reinspection Photo	 Load JPG	☒
110	15/11/19 11:32	Reinspection Photo	 Load JPG	☒
111	15/11/19 11:32	Reinspection Photo	 Load JPG	☒
112	15/11/19 11:32	Reinspection Photo	 Load JPG	☒
113	15/11/19 11:32	Reinspection Photo	 Load JPG	☒
114	15/11/19 11:32	Reinspection Photo	 Load JPG	☒
115	15/11/19 11:32	Reinspection Photo	 Load JPG	☒
116	15/11/19 11:32	Reinspection Photo	 Load JPG	☒
117	15/11/19 11:32	Reinspection Photo	 Load JPG	☒
118	15/11/19 11:32	Reinspection Photo	 Load JPG	☒
119	15/11/19 11:32	Reinspection Photo	 Load JPG	☒
120	15/11/19 11:32	Reinspection Photo	 Load JPG	☒
121	15/11/19 11:32	Reinspection Photo	 Load JPG	☒
122	15/11/19 11:32	Reinspection Photo	 Load JPG	☒
123	15/11/19 11:32	Reinspection Photo	 Load JPG	☒
124	15/11/19 11:32	Reinspection Photo	 Load JPG	☒
125	15/11/19 11:32	Reinspection Photo	 Load JPG	☒
126	15/11/19 11:32	Reinspection Photo	 Load JPG	☒
127	15/11/19 11:32	Reinspection Photo	 Load JPG	☒
128	15/11/19 11:34	Replacement Part Photo	 Load JPG	☒
129	15/11/19 11:34	Replacement Part Photo	 Load JPG	☒
130	15/11/19 11:34	Replacement Part Photo	 Load JPG	☒
131	15/11/19 11:34	Replacement Part Photo	 Load JPG	☒
132	15/11/19 11:34	Replacement Part Photo	 Load JPG	☒
133	15/11/19 11:34	Replacement Part Photo	 Load JPG	☒
134	15/11/19 11:34	Replacement Part Photo	 Load JPG	☒
135	15/11/19 11:34	Replacement Part Photo	Load JPG	☒
136	15/11/19 11:34	Replacement Part Photo	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
137	15/11/19 11:34	Replacement Part Photo	 Load JPG	☒
138	15/11/19 11:34	Replacement Part Photo	 Load JPG	☒
139	15/11/19 11:34	Replacement Part Photo	 Load JPG	☒
140	15/11/19 11:34	Replacement Part Photo	 Load JPG	☒
141	15/11/19 11:34	Replacement Part Photo	 Load JPG	☒
142	15/11/19 11:34	Replacement Part Photo	 Load JPG	☒
143	15/11/19 11:34	Replacement Part Photo	 Load JPG	☒
144	15/11/19 11:34	Replacement Part Photo	 Load JPG	☒
145	15/11/19 11:34	Replacement Part Photo	 Load JPG	☒
146	15/11/19 11:34	Replacement Part Photo	 Load JPG	☒
147	15/11/19 11:34	Replacement Part Photo	 Load JPG	☒
148	15/11/19 11:34	Replacement Part Photo	 Load JPG	☒
149	15/11/19 11:34	Replacement Part Photo	 Load JPG	☒
150	15/11/19 11:34	Replacement Part Photo	 Load JPG	☒
151	15/11/19 11:34	Replacement Part Photo	 Load JPG	☒
152	15/11/19 11:34	Replacement Part Photo	 Load JPG	☒
153	15/11/19 11:34	Replacement Part Photo	 Load JPG	☒
154	15/11/19 11:34	Replacement Part Photo	 Load JPG	☒
155	15/11/19 11:34	Replacement Part Photo	 Load JPG	☒
156	15/11/19 11:34	Replacement Part Photo	 Load JPG	☒
157	15/11/19 11:34	Replacement Part Photo	 Load JPG	☒
158	15/11/19 11:34	Replacement Part Photo	 Load JPG	☒
159	15/11/19 11:34	Replacement Part Photo	 Load JPG	☒
160	15/11/19 11:34	Replacement Part Photo	 Load JPG	☒
161	15/11/19 11:34	Replacement Part Photo	 Load JPG	☒
162	15/11/19 11:35	Photographs of Damaged Parts	 Load JPG	☒
163	15/11/19 11:35	Photographs of Damaged Parts	 Load JPG	☒
164	15/11/19 11:35	Photographs of Damaged Parts	 Load JPG	☒
165	15/11/19 11:35	Photographs of Damaged Parts	 Load JPG	☒
166	15/11/19 11:35	Photographs of Damaged Parts	 Load JPG	☒
167	15/11/19 11:35	Photographs of Damaged Parts	 Load JPG	☒
168	15/11/19 11:35	Photographs of Damaged Parts	 Load JPG	☒
169	15/11/19 11:35	Photographs of Damaged Parts	 Load JPG	☒
170	15/11/19 11:35	Photographs of Damaged Parts	 Load JPG	☒
171	15/11/19 11:35	Photographs of Damaged Parts	 Load JPG	☒
172	15/11/19 11:35	Photographs of Damaged Parts	 Load JPG	☒
173	15/11/19 11:35	Photographs of Damaged Parts	 Load JPG	☒
174	15/11/19 11:35	Photographs of Damaged Parts	 Load JPG	☒
175	15/11/19 11:35	Photographs of Damaged Parts	 Load JPG	☒
176	15/11/19 11:35	Photographs of Damaged Parts	 Load JPG	☒
177	15/11/19 11:35	Photographs of Damaged Parts	 Load JPG	☒
178	15/11/19 11:35	Photographs of Damaged Parts	 Load JPG	☒
179	15/11/19 11:35	Photographs of Damaged Parts	 Load JPG	☒
180	15/11/19 11:35	Photographs of Damaged Parts	 Load JPG	☒
181	15/11/19 11:35	Photographs of Damaged Parts	 Load JPG	☒
182	15/11/19 11:35	Photographs of Damaged Parts	 Load JPG	☒
183	15/11/19 11:35	Photographs of Damaged Parts	 Load JPG	☒
184	15/11/19 11:35	Photographs of Damaged Parts	 Load JPG	☒
185	15/11/19 11:35	Photographs of Damaged Parts	 Load JPG	☒
186	15/11/19 11:35	Photographs of Damaged Parts	 Load JPG	☒
187	15/11/19 11:35	Photographs of Damaged Parts	 Load JPG	☒
188	15/11/19 11:35	Photographs of Damaged Parts	 Load JPG	☒
189	15/11/19 11:35	Photographs of Damaged Parts	 Load JPG	☒
190	15/11/19 11:35	Photographs of Damaged Parts	 Load JPG	☒
191	15/11/19 11:35	Photographs of Damaged Parts	Load JPG	☒
192	15/11/19 11:35	Photographs of Damaged Parts	Load JPG	☒

Assessment Reports				1 per page	☒
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)		Thumbnail	Print
193	15/11/19 11:35	Photographs of Damaged Parts		Load JPG	☒
194	15/11/19 11:35	Photographs of Damaged Parts		Load JPG	☒
195	15/11/19 11:35	Photographs of Damaged Parts		Load JPG	☒
196	15/11/19 11:35	Photographs of Damaged Parts		Load JPG	☒
197	15/11/19 11:35	Photographs of Damaged Parts		Load JPG	☒
198	15/11/19 11:35	Photographs of Damaged Parts		Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	03/10/19 13:50	PRS - FBJ8246D		Load PDF	
2	03/10/19 13:50	REPAIR ESTIMATE		Load PDF	
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)		Thumbnail	Print
1	10/06/19 13:17	Sketch Plan [Linked Accident Report Documents]		Load JPG	☒
2	10/06/19 13:20	POLICE REPORT [Linked Accident Report Documents]		Load JPG	☒
3	10/06/19 13:20	POLICE REPORT [Linked Accident Report Documents]		Load JPG	☒
4	10/06/19 13:20	POLICE REPORT [Linked Accident Report Documents]		Load JPG	☒
5	10/06/19 13:20	POLICE REPORT [Linked Accident Report Documents]		Load JPG	☒

Linked Accident Report Documents

Assessment Reports				1 per page	☒
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)		Thumbnail	Print
1	10/06/19 13:24	Accident Statement		Load HTM	
Photos/Images				3 per page	☒
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)		Thumbnail	Print
1	10/06/19 13:17	Accident Photo		Load JPG	☒
2	10/06/19 13:17	Accident Photo		Load JPG	☒
3	10/06/19 13:17	Accident Photo		Load JPG	☒
4	10/06/19 13:17	Accident Photo		Load JPG	☒
5	10/06/19 13:17	Accident Photo		Load JPG	☒
6	10/06/19 13:18	Accident Photo		Load JPG	☒
7	10/06/19 13:18	Accident Photo		Load JPG	☒
8	10/06/19 13:18	Accident Photo		Load JPG	☒
9	10/06/19 13:19	Accident Photo		Load JPG	☒
10	10/06/19 13:19	Identification Card		Load JPG	☒
11	10/06/19 13:19	Identification Card		Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)		Thumbnail	Print
1	10/06/19 13:17	Sketch Plan		Load JPG	☒
2	10/06/19 13:20	POLICE REPORT		Load JPG	☒
3	10/06/19 13:20	POLICE REPORT		Load JPG	☒
4	10/06/19 13:20	POLICE REPORT		Load JPG	☒
5	10/06/19 13:20	POLICE REPORT		Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119017447/T1QF3E2

Date: 19/11/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN30403018033

Claimant Vehicle No: FBJ8246D Insured Vehicle No: GY4181U

Date of Loss: 08/06/2019 Nature of Claim: TP Claim No: SNM19D204616C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBJ8246D

Make & Model: YAMAHA YZF-R15, 150cc (M) Engine No: 1CK4017687

Reg. Date: 17/11/2014 (Man. Year: 2014) Chassis No: ME11CK041E2017751

Colour: Orange/Black Odometer: 0 km

Engine Capacity: 150 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 90/80 R17 Rear Tyre Size: 140/70 R17

Front Left Side: Dunlop 5 mm Rear Left Side: Dunlop 5 mm

Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,638.00	3,152.70	485.30	13.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,130.00	620.00	510.00	45.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,768.00	3,772.70	995.30	20.87
Approved Total (Overridden) (S\$)		3,200.00		
Nett Amount (S\$)	4,768.00	3,200.00	1,568.00	32.89

INSPECTION

Date of Assignment: 03/10/2019

Date Inspected: 07/10/2019 Inspected At: Pang Scooter Service (HQ)
BLK 1006 BUKIT MERAH LANE 2
#01-06
Singapore 159762

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 19 Nov 2019)	
Parts:	N/A	YAMAHA YZF-R15 150cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBJ8246D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TOP COWLING	Cracked	365.00 F	*365.00 FL
2	1		*HEAD LIGHT ASSY	Cut	385.00 F	*385.00 FL
3	1		*FRONT WHEEL RIM	Bent	395.00 F	*395.00 FL
4	1		*FRONT BRAKE DISC	Bent	195.00 F	*195.00 FL
5	2		*FORK INNER TUBE	Bent	260.00 F	*260.00 FL
6	1		*UNDER BRACKET	Bent	285.00 F	*285.00 FL
7	1		*STEERING CON	Necessary	110.00 F	*110.00 FL
8	1		*RIGHT SIDE MIRROR	Cut	95.00 F	*95.00 FL
9	1		*RIGHT SIDE HANDLE BAR	Not Necessary	135.00 F	*- FL
10	1		*BRAKE LEVER	Cut	65.00 F	*65.00 FL
11	1		*COWLING STAY	Bent	185.00 F	*185.00 FL
12	1		*RIGHT HAND SIDE PANEL	Cut	285.00 F	*285.00 FL
13	1		*BRAKE PEDAL	Bent	65.00 F	*65.00 FL
14	1		*MUFFLER ASSY	Bent	550.00 F	*550.00 FL
15	1		*MUFFLER COVER	Cracked	98.00 F	*98.00 FL
16	1		*RIGHT SIDE SIGNAL LIGHT	Cracked	45.00 F	*45.00 FL
17	2		*FORK SEAL	Necessary	60.00 F	*60.00 FL
18	1		*FORK OIL	Necessary	60.00 F	*60.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	3,638.00	3,503.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	350.30
Total Parts (\$\$)	3,638.00	3,152.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TRANSPORT	New	80.00	60.00
2	LABOUR	New	350.00	250.00
3	SPRAY PAINTING	New	600.00	250.00
4	WIRING	New	50.00	30.00
5	RIM BALANCING	New	50.00	30.00
Gross Labour Cost (S\$)			1,130.00	620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >