

22/03/2002

ASS. REC. BY:

REF: CS3/ASM 19017448/Gcf322 Special Instruction:

Surveyor: Kalvin

ASSIGNMENT (Office)

From (Person): Liu Yi Wenof ASM (AXA)Date/Time: 3.10.19 11.00am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: PB17 8364CInsured: SHD 454Hat Workshop m/s Sang MotorTel: 9689221890301070 Irene.of Vicom Inspection Centre (Changi) 20 Changi North Crescent

Policy No:

Claim No: S9M0230V

Sum Insured:

Excess:

Make of Veh:

D.O.A. 22.9.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D Endorsement:

Date/Time: 3.10.19 3.41p.mPerson Contacted: An SangVehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate
	PB17 8364C - X
	SHD 454H - CCH/ASM 1800674/ tina3 D.O.A - 31/12/2018
	after repair : 10/10/2019

(08/11/13)

Surveyor: Kalvin

REF: _____

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspected Vehicle No: _____

at Workshop n/s _____

of 9689 2218

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$3500

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: F B 08364C Yr Regn: 17 Aug, 2009

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda / wave 125 X A c.c. 125Colour: Red / Black A/C: Insured / Std / NASp. Reading: 560129 T/Radio: Insured / Std / NA

Eng/No: _____

C/No: NF1255T0027380

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim orTyre Size: F: 80-90 / 17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or 19 m mds

Front

Rear

R/Bal. 2 mm R/Bal. 2 mmL/Bal. — mm L/Bal. — mmD.O.A. _____ D.O.I. 24 3/10/19 1224pmSurvey held at Sany Motor 20 Chng North

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

n/s / n/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>PRS</u>
	<u>\$2200 - \$2000</u>

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS \$

Photos

Others

Report Format: PRS

Lump Sum / I.B.I. is

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

TOTAL

100



Service Request Details

Claim

S9M0230V

Reference

None 

Loss Date

September 22, 2019

Report Date

Oct 10, 2019 4:52:00 PM

Request Date

November 29, 2019

Due Date

November 29, 2020

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Direct settlement

Actions

Next Step

Finish the work

Complete Work

More ▾

Vehicle Information

Incident Vehicle Registration #

FBD8364C

Model
WAVE 125X A

Service Address

51 Ubi Avenue 1, #01-25, , 408933

Primary Contact/Insured

TRANS-CAB SERVICES PTE LTD
No.2 ANG MO KIO STREET 63, 569111, Singapore

Claim Handler



WANG Peter

peter.wang@axa.com.sg

Additional Instructions
Duplicated case as S9M02244. Please submit report and invoice here.

Messages	Invoices	History	Documents	Assessment	Metrics	Notes
----------	----------	---------	-----------	------------	---------	-------

New Message

TYPE	
SENT	11/29/19 10:25 AM
FROM	WANG Peter
SUBJECT	Pls submit report and invoice here
BODY	



Service Request Details

Claim

S9M02244

Reference

None 

Loss Date

September 22, 2019

Report Date

Oct 3, 2019 11:02:00 AM

Request Date

October 3, 2019

Due Date

October 10, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pre-Repair Survey

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

FBD8364C

Model

UNKNOWN

Service Address

51 Ubi Avenue 1, #01-25, , , 408933

Primary Contact/Insured

TRANS-CAB SERVICES PTE LTD

No.2 ANG MO KIO STREET 63, 569111, Singapore

Claim Handler

LIU Yiwen

yiwen.liu@axa.com.sg

Additional Instructions

Urgent PRI: Vehicle already dismantle at the workshop. Company Name : Sang Motor Address : 20, Cha...
(expand)

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

Summer Lee (LKK Auto)

From: OH Vale
Sent: Wednesday, 2 October, 2019 10:00 AM
To: SG AXA Insurance SM DC Motor
Cc: GOH Allen; NIKAM Santosh Pandurang
Subject: RE: [EXTERNAL] Re: Urgent PRI-TRANSCAB P1680520-SHD454H RISK 716

Follow Up Flag: Follow up
Flag Status: Flagged

Hi Sentosh

Pls follow up on the registration and send it to the correct handler, thanks.

Aside to Allen & Idah

Thanks for informing!

Best Regards

Vale Oh/A.Manager – Motor Claims

AXA Insurance Pte Ltd/ 8 Shenton Way, #24-01 AXA Tower, Singapore 068811/www.axa.com.sg

vale.oh@axa.com.sg

Customer Care No. 1800 8804741



Please consider the environment before printing this message

This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Distributor.care.motor <distributor.care.motor@axa.com.sg>

Sent: Wednesday, October 2, 2019 9:26 AM

To: OH Vale <vale.oh@axa.com.sg>

Cc: GOH Allen <allen.goh@axa.com.sg>; NIKAM Santosh Pandurang <santosh.nikam@axa.com.sg>

Subject: RE: [EXTERNAL] Re: Urgent PRI-TRANSCAB P1680520-SHD454H RISK 716

Hi Vale,

Its under P2203857 risk 627. i will endorse to amend the VRN to appear as SHD454H as omitted to remove the 0 before adding.

Regards,

Idah

----- Original Message -----

From: vale.oh@axa.com.sg

Sent: 01/10/2019

To: santosh.nikam@axa.com.sg; allen.goh@axa.com.sg; distributor.care.motor@axa.com.sg

Subject: RE: [EXTERNAL] Re: Urgent PRI-TRANSCAB P1680520-SHD454H RISK 716

Hi DC/Allen

Please check urgently if we are at risk for SHD454H, we are not able to do registration as system shown not at risk!

Best Regards

Vale Oh/A.Manager – Motor Claims

AXA Insurance Pte Ltd/ 8 Shenton Way, #24-01 AXA Tower, Singapore 068811/www.axa.com.sg

vale.oh@axa.com.sg<<mailto:tiongbenq.tan@axa.com.sg>>

Customer Care No. 1800 8804741

[InternalComm_EmailSignature_50_Brand (003)]

Please consider the environment before printing this message

This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: NIKAM Santosh Pandurang

Sent: Tuesday, October 1, 2019 11:21 AM

To: OH Vale <vale.oh@axa.com.sg>

Subject: FW: [EXTERNAL] Re: Urgent PRI

Hi Vale

Please assist on the below email.

Please assist as the RISK id 716 is not showing on smart claim and the termination date is showing on AS400 21/12/2018 what action need to be taken.

Regards,
Santosh Nikam

From: Eddy Yap <<mailto:EddyYap@arcclaimslc.com>>

Sent: Tuesday, October 01, 2019 10:42 AM

To: NIKAM Santosh Pandurang <santosh.nikam@axa.com.sg<<mailto:santosh.nikam@axa.com.sg>>>; SG AXA Insurance SM Motor Doc <motor.doc@axa.com.sg<<mailto:motor.doc@axa.com.sg>>>; SG AXA Insurance SM AXA SGP - Motor Survey <motor.survey@axa.com.sg<<mailto:motor.survey@axa.com.sg>>>

Subject: [EXTERNAL] Re: Urgent PRI

Can we start to repair our vehicle after our surveyor have inspected or we still have to wait for your surveyor which might take more then two days ?

Please advise urgently.

Thank You.
Eddy

On Mon, 30 Sep 2019 at 16:35, Eddy Yap <EddyYap@arcclaimslc.com<<mailto:EddyYap@arcclaimslc.com>>> wrote:
Can we start to repair our vehicle after our surveyor have inspected or we still have to wait for your surveyor which might take more then two days ?

Please advise urgently.

Thank You.
Eddy

On Mon, 30 Sep 2019 at 16:02, NIKAM Santosh Pandurang <santosh.nikam@axa.com.sg<<mailto:santosh.nikam@axa.com.sg>>> wrote:
Without Prejudice

Dear Sir

We regret that we are unable to arrange a survey for your client's vehicle as we need more time to confirm the vehicle no. SHD454H. In order not to delay any further, you may proceed to arrange your own surveyor as deemed fit.

Regards
Santosh

From: Eddy Yap [mailto:EddyYap@arcclaimsllc.com<mailto:EddyYap@arcclaimsllc.com>]
Sent: Monday, September 30, 2019 2:42 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey
<motor.survey@axa.com.sg<mailto:motor.survey@axa.com.sg>>; SG AXA Insurance SM Motor Doc
<motor.doc@axa.com.sg<mailto:motor.doc@axa.com.sg>>
Cc: Irene Seow Siew Eng <irene@arcclaimsllc.com<mailto:irene@arcclaimsllc.com>>
Subject: [EXTERNAL] Urgent PRI

Dear Sir,

Kindly arrange your surveyor to conduct a PRI. Please let us have you list of surveyors for SJE.

Details are as follow :

Company Name : Sang Motor
Address : 20, Changi North Crescent VICOM Vehicle Inspection Centre, 499613 Singapore

Our Vehicle : FBD8364C
Your Vehicle : SHD454H
Date of Accident : 22.09.2019

Our Fax : 68153273

Thank You.

-----Disclaimer-----

This message may contain confidential information intended solely for the use of the named addressee. If you are not the intended recipient, you should not read, use, disclose or reproduce the content of this message. If you have received this message by mistake, please notify the sender immediately. Any views or opinions presented in this message are solely those of the author and do not necessarily represent those of AXA Singapore - Externals or any other entity of the AXA Group, unless otherwise stated by the sender and duly authorized by the said companies.

-----Disclaimer-----

This message may contain confidential information intended solely for the use of the named addressee. If you are not the intended recipient, you should not read, use, disclose or reproduce the content of this message. If you have received this message by mistake, please notify the sender immediately. Any views or opinions presented in this message are solely those of the author and do not necessarily represent those of AXA Insurance Pte Ltd or any other entity of the AXA Group, unless otherwise stated by the sender and duly authorized by the said companies.

Regards,

Idah 

This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

ref:_00Db0Ky1f._5002v2VG6j7:ref

Sang Motor

Vicom Inspection Centre (Changi), 20 Changi North Crescent, (S)499613

Your Ref : SHD454H

Our Ref : FBD8364C

Date : 02.10.2019

AXA INSURANCE

Shenton Way, #24-01

AXA Tower, Singapore 068811

Dear Sirs,

ACCIDENT INVOLVING MOTOR VEHICLE FBD8364C AND SHD454H ON 22.09.2019 ALONG CHANGI BUSINESS PARK CENTRAL 2 ABOUT 13:45.

We act for the owner of vehicle no. FBD8364C.

We are instructed to claim damages against you in connection with the above accident.

Pursuant to NIMA protocol, we hereby give you notice to conduct a pre-repair inspection of our client's motor vehicle at the under-stated workshop: -

Sang Motor

Vicom Inspection Centre (Changi),

20 Changi North Crescent

Singapore 499613

Tel : 9689 2218 (Ah Sang)

Fax : 6548 2352

TAKE NOTICE that you are required to respond to us within 2 working days (excluding Saturday, Sunday and Public Holiday) of receipt of this notice as to whether you wish to carry out or waive a pre-repair inspection. If we do not hear from you in this regard by the stipulated time, we shall construe your silence as waiver of the requirement for a pre-repair inspection and our client's repairers shall proceed to repair our client's vehicle.

Yours faithfully,



Sang Motor



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62563562

To : AXA Insurance Pte Ltd

29/11/2019

Survey details

Date of loss	22-Sep-19
Date of appointment	3-Oct-19
Date of survey	3-Oct-19
Location of survey	SANG MOTOR

Vehicle Details:

Claim Type:	Third Party
Vehicle number	FBD 8364C
Make and Model	HONDA WAVE 125X A
Date of registration	17-Aug-09
Excess	
Market Value	\$3,500
Parf Rebate	\$1,551
Nett Loss	\$1,949

Repair details

Initial Estimate	
------------------	--

Proposed/Revised repair cost:

Parts	
Check item	
Labour	
Total	
Lump Sum(if applicable)	

Number of days of repair	4
--------------------------	---

Remarks:

The estimated repair cost of the damaged vehicle is in the region of \$2,000.00 - \$3,000.00

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	305G
Vehicle Details	
Vehicle No.:	FBD8364C
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Nov 2019
Vehicle Make:	HONDA
Vehicle Model:	WAVE 125X A
Primary Colour:	Red
Manufacturing Year:	2009
Engine No.:	NF125STE0027380
Chassis No.:	NF125ST0027380
Maximum Power Output:	-
Open Market Value:	\$1,789.00
Original Registration Date:	17 Aug 2009
First Registration Date:	17 Aug 2009
Transfer Count:	4
Actual ARF Paid:	\$269.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Jul 2024
COE Category:	D - Motorcycle
COE Period(Years):	5
PQP Paid:	\$1,634.00
COE Rebate Amount:	\$1,551.00
Total Rebate Amount:	\$1,551.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 01 Nov 2019

OK

REPORT ERROR (/LISTING/LISTING/ERROR/USEDBIKE/15076/)

+ ADD TO SHORTLIST

Like 0

Share

SHARE (WHATSAPP://SEND?TEXT=HTTPS://WWW.SGBIKEMART.COM.SG/LISTING/USEDBIKE/HONDA-HONDA-WAVE-125/15076/)

Honda Wave 125

Listing Type	Paid Ad
Brand	Honda (/listing/usedbike/brand/honda/)
Model	Honda Wave 125 (/listing/usedbike/model/honda-wave-125/)
Engine Capacity	125cc
Classification	Class 2B (/listing/usedbike/model/motorcycle-for-sale/class/class-2b/)
Registration Date	17/08/2009
COE Expiry Date	16/08/2024 (4 years 8 months left)
Mileage	-
No. of owners	-
Type of Vehicle	Cubs (/listing/usedbike/model/motorcycle-for-sale/cubs/)

Price: ^{SGD}\$3500

DETAILS

Honda Wave 125. COE Till Aug 2024. Good Condition. Loan Available, Welcome Trade In. Come Visit Us At Sin Boon Motor. Interested Buyers Are Welcome To Negotiate.

SIMILAR BIKES

VIEW ALL (/LISTING/USEDBIKES/LISTING/)



Honda Wave 125



Honda Wave 125



**SINGAPORE
POLICE FORCE**



T/20190922/2061

Police Station Of Origin:
Pasir Ris N.P.C
1 Pasir Ris Drive 4 #01-01 SINGAPORE
519457
Tel No: 1800-5852609

1 of 4

Report No: T/20190922/2061

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 22/09/2019 15:58	Vide Report No.:	Station Diary No.: 60
--	------------------	--------------------------

Informant's Particulars

Name of Informant: MUHAMMAD SHAFIZ BIN ABDUL AZIZ	Address: APT BLK 207 PASIR RIS STREET 21 #03-362 SINGAPORE 510207		
ID Type / ID No.: NRIC NO / S9521305G	Contact No.: Home/Office: Mobile: 81390797		
Nationality: SINGAPORE CITIZEN	Email:		
Sex: Male	Age: 24	Date of Birth: 15/06/1995	Type of Informant: Rider
Race: Malay	Language: English		Institution / School Name:
Occupation: NS FULL TIME	Driving Licence Information: Class: 2B, 2A, 2, 3		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 22/09/2019 13:45	Type of Location: Straight Road
Location: Along Road 1 CHANGI BUSINESS PARK CENTRAL 2				
Outside gantry of office building "The Signature"				
Weather: Clear	Road Surface: Dry		Road Speed Limit:	
Traffic Flow: One Way	Traffic Control: Not Controlled		Traffic Volume: No Traffic	
Type of Collision: Between Moving Vehicles - Head To Side			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBD8364C	Motorcycle	HONDA	WAVE 125X A	Red	Totally Damaged	0
SHD454H	TAXI	TOYOTA	PRIUS	Red	Slightly Damaged	1

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FBD8364C	NTUC Income Insurance Co-Operative Limited	5109537069	13/05/2019	29/05/2020



**SINGAPORE
POLICE FORCE**



T/20190922/2061

2 of 4

Police Station Of Origin:

Pasir Ris N.P.C

1 Pasir Ris Drive 4 #01-01 SINGAPORE

519457

Tel No. 1800-5852999

Report No. T/20190922/2061

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	MUHAMMAD SHAFIZ BIN ABDUL AZIZ	ID No.	S9521305G
Related Vehicle	FBD8364C (Motorcycle)	Contact No.	81390797
Hospital/Clinic	LIFE-LINK CLINIC & SURGERY	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	22/09/2019	Date Discharge	22/09/2019
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Driver			
Name	LIM TZE KHIN	ID No.	S1402498J
Related Vehicle	SHD454H (TAXI)	Contact No.	98511755
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the 22/9/2019 at about 1:45pm, I was riding along Changi Business park Central 2. I was riding along a straight road and I saw a taxi SHD454D that was driving in the same direction on the left lane of 2 lanes. It was driving slowly on the left lane. I maintained on the second lane in the same direction. As I was side by side with the taxi, it abruptly turned to the right and collided with me. I fell off from my motorcycle and landed on my left then right. The taxi driver immediately stopped and came over to assist. He was apologetic and asked me whether I needed any ambulance and I was injured. I told him that I am having pain in my left shoulder and did not want ambulance. I also asked him why he made a right turn and he told me that he did not see me on the right. Both the taxi driver and the passenger came to help me and sat me at the pavement. He asked me whether I wanted to settle privately. He offered me \$300 in the beginning but After consulting my friend and NTUC Insurance, I returned his offer and wish to go for insurance claim. We exchanged particulars and contact number. He told me that he will make a report as well. I took photos of the scene and he then continued to his journey.

I then took Grab to seek medical attention in Pasir Ris. I left my motorcycle there for towing and my motorcycle had scratches on the right fairing and left gear paddle was bent. The damages on the taxi was scratches and dent on the right front mud guard. The right rear mirror was also bent.

I suffered abrasions on my left elbow, abrasions on both knee caps and uneasy feeling; and my top right foot sustained abrasions.

Individual Statement



SINGAPORE
POLICE FORCE



T/20190922/2061

4 of 4

Police Station Of Origin:

Pasir Ris N.P.C

1 Pasir Ris Drive 4 #01-01 SINGAPORE

519457

Tel No. 1800-5852999

Report No. T/20190922/2061

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /

Staff Sgt MUHAMMAD AMINULLAH BIN MOHD
YUSOF

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

22/09/2019 15:58

Officer In Charge Of Case:

TP / AEIT /

SI ANG YI TING, STEPHANIE

Contact No.: 65476414

Classification Of Case:

Authentication Stamp

NP-158



SINGAPORE
POLICE FORCE



SINGAPORE
POLICE FORCE



T/20190922/001

Police Station Of Origin:
Pasir Ris N.P.C
1 Pasir Ris Drive 4 #01-01 SINGAPORE
519457
Tel No: 1800-5852999

3 of 4

Report No. T/20190922/001

CONTINUATION OF REPORT

Page 3 of 4



life-link clinic & surgery

Blk 446, #01-120, Pagar Road Drive 6, Singapore 510446, Tel: 65834402

Medical Certificate

Date of Visit: 22-Sep-2019

MC No. : GPC-20190922-0673

This is to certify that

Name: MUHAMMAD SHAFIZ BIN ABDUL AZIZ

NRIC: S9521305G

is Unfit for Work

for 3 day(s) from 22-Sep-2019 to 24-Sep-2019

Remarks:

Life-link Clinic & Surgery

Blk 446 Pagar Road Drive 6

#01-120 Singapore 510446

Tel: 6583 4402 Fax: 6582 1671

Doctor Name: Attending Doctor

MCR: M04321D





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
AXA INSURANCE PTE LTD		Ref: CS3/ASM19017448/Gcf3e2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE		Date: 29-11-2019		
068811				
ATTN : LIU YI WEN		Code: ASM		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SHD 454H	Veh. Inspected	FBD 8364C	
Policy No.		Coverage (\$)	0.00	
Claim No.	S9M0230V	Excess (\$)	0.00	
Assign From	LIU YI WEN	Assign Date	03/10/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA WAVE 125X A	c.c	125	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	NF125ST0027380	Colour	RED / BLACK	
Odometer	560129 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	80-90/17	DIAMONDS	2 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	80-90/17	DIAMONDS	2 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY.				
5. General Information				
Accident Date	22/09/2019	Inspect Date / Time	03/10/2019 (12:24 PM)	
Survey held at	SANG MOTOR NO. 20 CHANGI NORTH CRESCENT(VICOM INSPECTION CENTRE)SINGAPORE 499613			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		

Report Ref No. CS3/ASM19017448/Gcf3e2

Inspected By



XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.