

ASS. REC. BY:

REF:

ASM (AXA)

ASSIGNMENT

From:

Date:

3.10.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLD 8821G

at Workshop m/s

Premier

of

8 Paki Bukit Mx 4 7 08-09

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLD8821G

Yr Regn:

2016 June

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Kia Forte K3

C.C 1591

Colour

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

69069

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KNAFX411MG5586634

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ~~Order~~ / Jammed / Leaked / Burnt orBrake: ~~Order~~ / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 205/55R16

R: 205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

03/10/19

Survey held at

Vision

Des. of Damages: Frt / ~~Rear~~ / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP AXA

MV: 561K

PV: 46.9K

Nett: 9.1K

Date/Time, File Pass to?

☐

Preli. Report

1)

Date/Time, File Return to?

☐

Final Report

2)

Rep. Format:

Lump Sum / F.B. / C

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL