

22/03/2002

ASS. REC. BY:

REF:

CS3/FCI/19017463/R/cd30

Special Instruction:

SUNAJOR: RASU

## ASSIGNMENT (Office)

From (Person):

Marina Chra Son San

of FCI

Date/Time:

2.11.19 11:51am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKH 8704C

Insured:

SHB 3018A

at Workshop m/s

V- TECH AUTO

Tel:

62646211

of

NO 1 San Lu ST 1106-04/05/06/07

Policy No:

Claim No:

D19006274m FSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

29.9.2019

CA / REV / REP. / REV 24 HRS

Date/Time:

26.11.19 12.00p.m

Person Contacted:

Ms chung

H.O.D. Endorsement:

Vehicle: IN / OUT

Date/Time

Action/Instruction ( X ) Estimate

SKH 8704C - CS1 FCI 19017463 T114 d3

DCA - 29/09/2019

SHB 3018A - CS1 FCI 19017463 T114 d3

DCA -

Dismantle: 27/11/2019

After repair: 2/12/2019



**MOTOR SURVEY ASSIGNMENT**

<b>Date</b>	01-10-2019	<b>Our Ref No.</b> D19006274MFSH
<b>Accident Date</b>	29-09-2019	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SHB3018A	<b>Third Party Vehicle.</b> SKH8704C
<b>Survey Location</b>	NO 1 SOON LEE ST #06-04/05/06/07 PIONEER CENTRE	
<b>Contact Person.</b>	SIM TEO KOON	
<b>Contact No.</b>	62646211/ 0	<b>Fax No.</b> 62646233
<b>Survey Type</b>	WITHOUT PREJUDICE:	
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

<b>Cc : Workshop</b>	V-TECH AUTO SERVICE	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	JUSEQUITY LAW CORPORATION	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	MERINA CHIA SAN SAN	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	852C
Vehicle Details	
Vehicle No.:	SKH8704C
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Nov 2019
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	JETTA 1.4 TSI AT 1622G5
Primary Colour:	Grey
Manufacturing Year:	2012
Engine No.:	CAXC55061
Chassis No.:	WWZZZ16ZDM040423
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$18,871.00
Original Registration Date:	24 Jan 2013
First Registration Date:	24 Jan 2013
Transfer Count:	1
Actual ARF Paid:	\$8,871.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Jan 2023
PARF Rebate Amount:	\$5,766.00
Intended COE Rebate Details	
COE Expiry Date:	23 Jan 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$71,001.00
COE Rebate Amount:	\$22,407.00
Total Rebate Amount:	\$28,173.00

The information contained herein is correct as at 27 Nov 2019

OK

34,000  
28173  

---

5827  

---

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	30/09/2019 09:24
Date Of Accident	29/09/2019 14:45
Exact Location Of Accident	JURONG WEST AVE 1
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKH8704C
<b>Insured/Policyholder</b>	
Name Of Registered Owner	DESIRE DESIGN PTE. LTD.
Co Reg No	201611852C
Email Address	ASKDESIREDESIGN@GMAIL.COM
Mobile Phone No	
Alternative Phone No	OFFICE-91707929

### Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	JETTA-1.4 TSI 1622G5 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5095273005
Cover Note Number	

### Driver

Name of Driver	RICHARD SIM
NRIC No	S8871870D
Date Of Birth	08/05/1988
Occupation	OUTDOOR
Date Of Driving Pass	01/04/2008
Driving Experience	11 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91707929
Fax Number	
Contact Number	
EMail Address	IAMRICHARDSIM@GMAIL.COM

Address	BLK 331 JURONG EAST AVE 1 #09-1732
Postcode	600331
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5
Passenger 1	NAME: : RIANI GENDER: : FEMALE
Passenger 2	NAME: : SHERRELLE SIM GENDER: : FEMALE
Passenger 3	NAME: : SHERNISE SIM GENDER: : FEMALE
Passenger 4	NAME: : SCHUYLER SIM GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

I WAS TRAVELLING ALONG JURONG WEST ST 1 TOWARDS JURONG EAST AVE 1. OUT OF SUDDEN, SHB 3018 A CAME OUT FROM A MINOR WHICH IS CARPARK AND HE COLLIDED TO MY CAR.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHB3018A
Vehicle Make/Model/Colour	HYUNDAI / SONATA / YELLOW
Details Of Properties	

Vehicle Category	TAXI
Name of Driver	LOY SAI CHEE
NRIC/Passport Number	
Contact Number	90254816
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature  
Date & Time

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time

  
Reporting Centre Personnel's Signature  
Name:   
NRIC / ID No: 

### Sketch Plan #2

### SKETCH PLAN

Refer to Attached.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along Turing West Ave 1 towards Turing  
east Ave 1. Out of sudden, SHB 3018A came out from  
a minor which is ~~at~~ carpark and he collided to my ~~at~~ car.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature \_\_\_\_\_  
Date & Time \_\_\_\_\_

Driver's Signature \_\_\_\_\_  
 If driver is not the pack handler \_\_\_\_\_  
 Date & Time \_\_\_\_\_

Reporting Centre Personnel's Signature  
Name: David Hill  
Title: Director

Sketch Plan #3



- 1) Front light and bumper
- 2) Windscreen crack
- 3) ABS signal
- 4) Pick up excessive accelerate
- 5) Air-100
- 6) Bottom Foot (Relax)



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
MS FIRST CAPITAL INSURANCE LTD		Ref: CS3/FCI19017463/R1cd3e2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date: 26-12-2019		
Code: FCI2				
<b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>				
Insured Veh.	SHB 3018A	Veh. Inspected	SKH 8704C	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19006274MFSH	Excess (\$)	0.00	
Assign From	MERINA CHIA	Assign Date	26/11/2019	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	VOLKSWAGEN JETTA 1.4 TSI	c.c	1390	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	WWZZZ16ZDM040423	Colour	GREY	
Odometer	179657 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	YOKOHAMA	6 mm	
L/H Front Tyre	205/55 R16	YOKOHAMA	6 mm	
R/H Rear Tyre	205/55 R16	YOKOHAMA	6 mm	
L/H Rear Tyre	205/55 R16	YOKOHAMA	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.				
<b>5. General Information</b>				
Accident Date	29/09/2019	Inspect Date / Time	26/11/2019 ( 03:25 PM )	
Survey held at	V-TECH AUTO SERVICE No.1 SOON LEE STREET #06-04/05/06/07 PIONEER CENTRE SINGAPORE 627605			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D)MARKET VALUE:\$34,000.00				

Report Ref No. CS3/FCI19017463/R1cd3e2

Inspected By



MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor



K.K.LAU CPT (RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.