

ŠKODA Centre Singapore

26 Leng Kee Rd
Singapore 159104
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page 1/2

Company
INDIA INTERNATIONAL INSURANCE
64 CECIL STREET
#04-05 IOB BUILDING
Singapore 049711

Customer Details:
Mr
ADRIAN
LAM KIN HO
465 JURONG WEST STREET 41
#09-540
Singapore 640465

Document no.
Document date 03-10-2019
Customer no. 5211000972
Customer GST-ID 198703792K
Dealer 39999
Job order number 2019002170/ 1
Job order date 30-09-2019
Service Advisor CHARMAINE KONG

License plate	Model code	First registration	VIN	Model	Mileage
SMK8808Y	NU73ND	12-03-2019	TMBKR7NU8K5024183	Karoq Ambition 1.5 I TSI 110kW DSG	18

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	Diagnostic and Programming	1	pcs.	480.00 ✓	#1	480.00	513.60
	Check Short Circuit / Harness Repair	1	pcs.	280.00 ✓	#1	280.00	299.60
57A807218	Cover For	1	pcs.	1,355.00 R ²	#1	1,355.00	1,449.85
57A807061 9B9	Front Spoi	1	pcs.	276.00 ?	#1	276.00	295.32
57A853677 9B9	Cooling Ai	1	pcs.	163.00 ?	#1	163.00	174.41
57A853761 2ZZ	Cover Stri	1	pcs.	295.00 ?	#1	295.00	315.65
57A853653B ZD4	Grille	1	pcs.	284.00 ?	#1	284.00	303.88
57A853343 9B9	Connecting	1	pcs.	166.00 ?	#1	166.00	177.62
57A807183	Guide Piec (BUMPER BRACKET LH)	1	pcs.	46.00 ?	#1	46.00	49.22
57A807184	Guide Piec (BUMPER BRACKET RH)	1	pcs.	46.00 ?	#1	46.00	49.22
57A121764	Air Duct (RHS OUTER)	1	pcs.	28.90 X	#1	28.90	30.92
57A121764A	Air Duct (RHF INNER)	1	pcs.	28.90 X	#1	28.90	30.92
57A807367 9B9	Cap (LHF FOGLAMP GRILLE)	1	pcs.	55.20 ?	#1	55.20	59.06
57A807368 9B9	Cap (RHF FOGLAMP GRILLE)	1	pcs.	55.20 X	#1	55.20	59.06
57A919488	Sensor Bra	1	pcs.	39.60 X	#1	39.60	42.37
57A919491A	Sensor Bra	1	pcs.	23.40 X	#1	23.40	25.04
57A919491	Sensor Bra	1	pcs.	23.40 X	#1	23.40	25.04
57A919491A	Sensor Bra	1	pcs.	23.40 X	#1	23.40	25.04
D 822150A1	Bonding Agent For Plastic	1	pcs.	56.90 X	#1	56.90	60.88
D 180KU2A1	2k-Plastic Adhesive	1	pcs.	74.29 X	#1	74.29	79.49
	FRONT NUMBER PLATE	1	pcs.	80.00 cut ✓	#1	80.00	85.60
	Spray Painting	3	pcs.	800.00	#1 Box	2,400.00	2,568.00
	LABOUR	3	pcs.	840.00	#1 R40	2,520.00	2,696.40

Quotation valid till 07-10-2019

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	760.00	8,040.19	7%	616.01	8,800.19	9,416.20
Total	760.00	8,040.19		616.01	8,800.19	9,416.20

Customer

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 97495749
WP

07/10/19 @ 220pm

03 Soleys

Service Advisor

surellmants.com

Resurvey before/after part

ŠKODA Centre Singapore

26 Leng Kee Rd
Singapore 159104
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page 2/2

Company
INDIA INTERNATIONAL INSURANCE
64 CECIL STREET
#04-05 IOB BUILDING
Singapore 049711

Customer Details:
Mr
ADRIAN
LAM KIN HO
465 JURONG WEST STREET 41
#09-540
Singapore 640465

Document no.
Document date
Customer no.
Customer GST-ID
Dealer
Job order number
Job order date
Service Advisor

03-10-2019
5211000972
198703792K
39999
2019002170/ 1
30-09-2019
CHARMAINE KONG

License plate	Model code	First registration	VIN	Model	Mileage
SMK8808Y	NU73ND	12-03-2019	TMBKR7NU8K5024183	Karoq Ambition 1.5 I TSI 110kW DSG	18

-----VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).-----

LKK Auto Consultants hence notify
the Reparer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplemental work(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Reparer

Signature

Date