

ASS. REC. BY: _____

REF: CS/AIG/19017484/MSD302 Special Instruction: etc

ASSIGNMENT (Office)

From (Person): Chin Lee Ying of AIG Date/Time: 3/10/2019 (2)

Estimated Cost: _____ Bill to: _____

(OD) IP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: FBK 6195A Insured: _____at Workshop m/s: Bike production Tel: wendyof 610 Serangoon Road

Policy No: _____ Claim No: _____

Sum Insured: _____ Excess: TBAMake of Veh: _____ D.O.A. 1/10/2019
(Client's Record)CA / (REV) / REP. / REV 24 HRS H.O.D. Endorsement: _____Date/Time: 9:10am 4/10/19 Person Contacted: wendy Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>FBK 6195A-X</u>
<u>04/10/19</u>	<u>@ 17:21 pm revised SA to AIG via merimen</u>
<u>04/10/19</u>	<u>@ 17:22 pm mandate request authorize repair to AIG via merimen</u>
<u>7/10/19</u>	<u>Rece approved \$6932.20 from Thatchers by merimen</u>

N/A

REF:

ALR

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: FBK 6195A Yr Regn: 4 NOV 2015
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: HONDA CR400SF MANUAL cc 399
 Colour: WHITE A/C: Insured / Std / NI / NA
 Sp. Reading: 48,361 T/Radio: Insured / Std / NI / NA
 Eng No: _____
 C/Nr: NC421603953
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Modl: Nil / S/Rim / STD A/Rim or _____

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Tyre Size: F: 120/60 R17
 R: 160/60 R17
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or METZELER
 Front R/Bal: 4 mm Rear R/Bal: 5 mm
 L/Bal: - mm L/Bal: - mm
 D.O.A: 1/10/19 D.O.I: 4/10/19
 Survey held at: BIKE PRODUCTION
 Des. of Damages: (Fr) / Rear / O/S / N/S / U/C / Rooftop or _____

Bal. or Market Value: 13K
 IDAC Accident Rpt: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: 3 days Res.: Yes or No
 Lum Sum: % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	COE Rebate \$3,779.00
	Repair Limit 8K

RECEIVED 3 NOV 2019

7/10/19 Informed Mr Kwan CIA on LS repair ex TBA by email
 8/11/19 FINALIZED LUMP SUM REPAIR \$3,950.00 / 3 REPAIR DAYS
 (\$ 7,324.90 Red - 65%)

[Signature]
 19/11/2019

Date/Time, File Pass to? 19/11/19
 1) Typist
 Date/Time, File Return to? _____
 : Prel. Report
 : Final Report

Days Of Repair: 3
 Resurvey No. of Trip: 2

Report Format :
 Lump Sum / I.B.I: (\$ 3,950 / L/S)

Add Fee: Site Insp (\$)
 Interview (\$)
 Tech Invs (\$)
 Weekend (\$)

Survey Fee:	700
Transportation:	
3 + RS. 01	
Photos	
Items	11
TOTAL	711

NEW OD CLAIM - FBK6195A

From: Chip, Lee-Ying
To: assignments, Admin A
Cc: Fong, Andy-SY
Sent: 10/3/2019 4:30:23 PM
Attachments:  20191003_155411.jpg  FBK6195A CIA.PDF

HI LKK,

Kindly appoint Xing Guo Qiang to conduct survey.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel: +(65) 6419 1947
Lee-Ying.Chin@aig.com | www.aig.sg

-----Original Message-----

From: Sbk E [mailto:sbk5643@yahoo.com]
Sent: Thursday, October 03, 2019 3:58 PM
To: AIG SGP, Claims-Survey
Subject: [EXTERNAL] Re: NEW OD CLAIM - FBK6195A

This message is from an external sender; be cautious with links and attachments.

Dear Sir,

Good Day. Please refer to the attached file. Please contact us at 62995177 for pre-repair inspection appointment. Thank you very much for your attention.

Regards,

Ewan S. H.
Director
Bike Production Pte Ltd

IMPORTANT NOTICE:
The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If y

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Details	
Owner ID Type:	Singapore NRIC
Owner ID:	848G
Vehicle Details	
Vehicle No.:	FBK6195A
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Oct 2019
Vehicle Make:	HONDA
Vehicle Model:	CB400SF MANUAL
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	NC42E1203953
Chassis No.:	NC421603953
Maximum Power Output:	-
Open Market Value:	\$7,610.00
Original Registration Date:	09 Nov 2015
First Registration Date:	09 Nov 2015
Transfer Count:	2
Actual ARF Paid:	\$1,142.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	08 Nov 2025
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$6,201.00
COE Rebate Amount:	\$3,779.00
Total Rebate Amount:	\$3,779.00

The information contained herein is correct as at 04 Oct 2019

OK

Enquire Vehicle Transfer Fee

Vehicle Details

Vehicle No.
FBK6195A

Make / Model
HONDA / CB400SF MANUAL

Vehicle Type :
P00 - Passenger Motorcycle/Autocycle/Moped

Vehicle Scheme :
Normal

Propellant :
Petrol

Motor No. :
-

Power Rating :
-

Maximum Laden Weight :
300 kg

Year Of Manufacture :
2015

Lifespan Expiry Date :
-

Quota Premium :
\$6,201.00

Road Tax Expiry Date :
08 Nov 2019

Inspection Due Date :
08 Nov 2019

CO2 Emission :
-

CO Emission :
-

NOx Emission :
-

Vehicle Attachment 1 :
No Attachment

Chassis No. :
NC421603953

Engine No. :
NC42E1203953

Engine Capacity :
399 cc

Maximum Power Output :
-

Unladen Weight :
190 kg

Original Registration Date :
09 Nov 2015

COE Category :
D - Motorcycle

COE Expiry Date :
08 Nov 2025

PARF Eligibility Expiry Date :
-

Intended Transfer Date :
04 Oct 2019

CEV/VES Rebate Utilised Amount :
-

HC Emission :
-

PM Emission :
-

Honda CB400 Super 4 Revo

SGD \$15300

Reg : 21/04/2016

Type: Street Bikes

399cc

36181km

Bike Is In Good Condition, Visit Us At Ah Fook Motor, Well Maintained Condition. Trade In Welcome / Loan Available.

Posted on : 17/09/2019

PAID AD

DEALER AD

COMPARE

DETAILS

Honda CB400 Super 4 Revo

SGD \$14800

Reg : 31/08/2015

Type: Street Bikes

399cc

Honda CB400 Super 4 Revo For Sale, Interested Parties Are Welcome To Neg. Trade/Loan Available. Do Visit Us At Wing Fuat @ Sims Place. No Early Settlement Fee.

Posted on : 29/09/2019

PAID AD

DEALER AD

COMPARE

DETAILS

Honda CB400 Super 4 Revo

SGD \$13000

Reg : 03/12/2014

Type: Street Bikes

399cc

Trade In/Loan Available. Visit Bike Dynamic Centre.

Posted on : 16/09/2019

PAID AD

DEALER AD

COMPARE

DETAILS

Honda CB400 Super 4 Revo



SGD **\$15000**

Reg : 14/01/2016

Type: **Street Bikes**

399cc

63000km

Selling A Good Condition Honda CB400 Revolver. 1st Owner. Regular Servicing Done At Soon Him Motors. Last Servicing Done On Sept 2019. Selling To Finance Bike Upgrade. Col Payment Option Availa...

Posted on : 04/10/2019

[DIRECT SELLER](#)

[COMPARE](#)

Shirley Hiew (LKK Auto)

From: Sbk E <sbk5643e@yahoo.com>
Sent: Sunday, 17 November 2019 10:05 am
To: Naz (LKKAuto)
Cc: SUR; Shirley Hiew (LKK Auto)
Subject: Re: FBK 6195A INVOICE DV
Attachments: FBK6195InvDV.pdf

Regards,

Kwan S. H.
Director
Bike Production Pte Ltd

On Wednesday, November 13, 2019, 6:05:04 PM GMT+8, Sbk E <sbk5643e@yahoo.com> wrote:

Dear Naz,

Please kindly proceed to close at \$3,950.00 before Excess and GST. Thanks.

Regards,

Kwan S. H.
Director
Bike Production Pte Ltd

On Wednesday, November 13, 2019, 5:41:58 PM GMT+8, Naz (LKKAuto) <naz@lkkauto.com> wrote:

Dear Mr Kwan,

Apologies for the late reply. Attached herewith is the amended marked estimate. We will proceed to finalize if you are agreeable with the amended Lump Sum COR of \$3950.00 / 3 REPAIR DAYS

Thank you.

Best Regards,
Naz | Technical Investigator
LKK Auto Consultants
Phone: 6841-2157 | Email: Naz@lkkauto.com | Fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Naz (LKKAuto)
Sent: Monday, 4 November 2019 5:21 PM
To: Sbk E <sbk5643e@yahoo.com>
Cc: SUR <sur@lkkauto.com>; Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Subject: FBK 6195A FINALIZATION

Dear Mr Kwan,

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Monday, 21 October 2019 9:14 am
To: Sbk E
Cc: SUR
Subject: RE: FBK 6195A-DOA:1/10/2019 (AIG OD)

Dear All,

Supplementary approved by AIG.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Wednesday, 16 October 2019 1:11 pm
To: Sbk E <sbk5643e@yahoo.com>; SUR <sur@lkkauto.com>
Subject: Re: FBK 6195A-DOA:1/10/2019 (AIG OD)

Hi All,

Excess is \$ 500.00

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 7 October 2019 9:40 AM
To: 'Sbk E'; SUR
Subject: FBK 6194A-DOA:1/10/2019 (AIG OD)
5

Dear Mr Kwan,

As instructed by our client , please proceed to repair the insured vehicle **FBK 6195A on Lump Sum Repair, (Excess TBA).**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair

NOTE: "Stock Exhaust" for OD claim. Pricing to be revise. "Exhaust Slider" not for OD claim. For recovery purpose only. "To Knock, Straighten Chassis & Body Balancing" not require unless body alignment report provided. "Lumpsum insured acknowledge letter" require for lumpsum repair.

Best Regards,

Veron Chen | Case Handler **on behalf of Shirley**

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

RE: RE: Authorise Repair, Re: FBK 6195A OD (AIG) Date of Loss: 01/10/2019 - Revise Estimate

Ng, Thaddaeus-HC <Thaddaeus-HC.Ng@aig.com>

Mon 7/10/2019 8:27 AM

To: Sbk E <sbk5643e@yahoo.com>; Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Cc: Fong, Andy-SY <Andy-SY.Fong@aig.com>

Hi Both,

Mandate Approved.

Damaged parts as require only approval with Surveyor acknowledgement for your attention. Kindly do not hesitate to arrange photo taking for check, supplementary item and after repair.

"Stock Exhaust" for OD claim. Pricing to be revise.

"Exhaust Slider" not for OD claim. For recovery purpose only.

"To Knock, Straighten Chassis & Body Balancing" not require unless body alignment report provided.

"Lumpsum insured acknowledge letter" require for lumpsum repair.

*Regards,***Thaddaeus Ng****AIG**

Motor Claims Surveyor

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1929 | Fax +(65) 6835 7416 Hp +(65) 8876 5433

Thaddaeus-HC.Ng@AIG.com | www.AIG.com.sg**From:** Sbk E <sbk5643e@yahoo.com>**Sent:** Saturday, October 5, 2019 4:08 PM**To:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>**Cc:** Ng, Thaddaeus-HC <Thaddaeus-HC.Ng@aig.com>**Subject:** [EXTERNAL] RE: Authorise Repair, Re: FBK 6195A OD (AIG) Date of Loss: 01/10/2019**This message is from an external sender; be cautious with links and attachments.**

Dear Shirley,

I have just whatapps Veron. Please kindly authorize repair. I have also included Thadd in this email. Thanks.

Regards,

Kwan S. H.

Director

Bike Production Pte Ltd

On Friday, October 4, 2019, 5:25:44 PM GMT+8, Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com> wrote:

Hi Wendy,

Driving please provide us.

Shirley Hiew (LKK Auto)

From: Ng, Thaddaeus-HC <Thaddaeus-HC.Ng@aig.com>
Sent: Sunday, 20 October 2019 7:31 pm
To: Shirley Hiew (LKK Auto)
Cc: Fong, Andy-SY; SUR
Subject: RE: FBK 6195A OD / 9238911753SG - Mandate Approved With Revise

Hi,

Content noted as advise. Mandate approved.

- Left fork does not warrant a replacement
- Rim was grazed hence stated as repair

Regards,

Thaddaeus Ng

AIG

Motor Claims Surveyor

Claims|AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1929|Fax +(65) 6835 7416 Hp +(65) 8876 5433

Thaddaeus-HC.Ng@AIG.com | www.AIG.com.sg

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, October 18, 2019 1:05 PM
To: Ng, Thaddaeus-HC <Thaddaeus-HC.Ng@aig.com>
Cc: Fong, Andy-SY <Andy-SY.Fong@aig.com>; SUR <sur@lkkauto.com>
Subject: [EXTERNAL] RE: FBK 6195A OD / 9238911753SG

This message is from an external sender; be cautious with links and attachments.

Dear Thaddaeus,

We refer to your below email above matter. According to our surveyor,

1. The left front wheel was hit by the car while reversing. During operational test the front left disc was grinding against the left front brake caliper, which caused the left front brake disc warped. Refer to Refer to the arrow in the photo below.



2. The impact from the fall caused the bike to be misaligned. However the left fork does not warrant a replacement. Labour was provided.
3. The impact hit the front wheel rim, the white mark is not a scratch mark, the rim was grazed hence stated as repair. Refer to the arrow in the photo below.



Thank you.

Best Regards,

Shirley Hlew | Case Handler

LKK Auto Consultants Pte Ltd

Shirley Hiew (LKK Auto)

To: Ng, Thaddaeus-HC
Cc: Fong, Andy-SY; SUR
Subject: RE: FBK 6195A OD / 92389117535G

Dear Thaddaeus,

We refer to your below email above matter. According to our surveyor,

- 1) The left front wheel was hit by the car while reversing. During operational test the front left disc was grinding against the left front brake caliper, which caused the left front brake disc warped. *Refer photo 47, 48*
- 2) The impact from the fall caused the bike to be misaligned. The left fork ~~which~~ does not warrant a replacement. Labour was provided. *How*
- 3) The impact hit the front wheel rim, the white mark is not a scratch mark, the rim was grazed hence stated as repair. *Refer to photo 47-48*. The impact onto the bike was at the left side of the front wheel as there were no impact damage observed on the left side of the bike

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

See photo here
See photo below
See photo here

From: Ng, Thaddaeus-HC <Thaddaeus-HC.Ng@aig.com>
Sent: Tuesday, 15 October 2019 10:56 pm
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Cc: Fong, Andy-SY <Andy-SY.Fong@aig.com>; SUR <sur@lkkauto.com>
Subject: RE: FBK 6195A OD / 92389117535G

Hi Shirley,

Supplementary below not consistence to a station bike fall and cause the damage unless specific.

- Front Left Brake Disc - How it would have affected from a fall?
- Front Left Fork Assy – How it would have affected from a fall?
- Front Sport Rim – Scratch cause by a fall?

For your assisting.

Regards,
Thaddaeus Ng
AIG
Motor Claims Surveyor
Claims|AIG Asia Pacific Insurance Pte. Ltd.

RE: FBK 6195A OD / 9238911753SG

Ng, Thaddaeus-HC <Thaddaeus-HC.Ng@aig.com>

Tue 15/10/2019 10:56 PM

To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Cc: Fong, Andy-SY <Andy-SY.Fong@aig.com>; SUR <sur@lkkauto.com>

3 attachments (3 MB)

Accident Scene.PNG; Capture.PNG; Revise Estimate.PNG;

Hi Shirley,

Supplementary below not consistence to a station bike fall and cause the damage unless specific.

- Front Left Brake Disc - How it would have affected from a fall?
- Front Left Fork Assy - How it would have affected from a fall?
- Front Sport Rim - Scratch cause by a fall?

For your assisting.

Regards,
Thaddaeus Ng
AIG

Motor Claims Surveyor

Claims|AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1929|Fax +(65) 6835 7416 Hp +(65) 8876 5433

Thaddaeus-HC.Ng@aig.com | www.AIG.com.sg

1) The left front wheel was hit by the car while reversing. During operational test the front left disc was grinding against the left front brake caliper, which ~~was~~ the left front brake disc is warped. *caused*

2) The impact from the fall caused the bike to be misaligned. The left fork ~~was not possibly bent~~ *which does not*

3) The bumper hit the front wheel ^{rim} the white mark is not a scratch mark. *the rim was grazed here stated as repair.*

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
 Sent: Tuesday, October 15, 2019 2:56 PM
 To: Ng, Thaddaeus-HC <Thaddaeus-HC.Ng@aig.com>
 Cc: Fong, Andy-SY <Andy-SY.Fong@aig.com>; SUR <sur@lkkauto.com>
 Subject: [EXTERNAL] FBK 6195A OD / 9238911753SG

warrant a replacement labor was provided. Provided.

This message is from an external sender; be cautious with links and attachments.

Dear Thaddaeus, *\$ Rev to mar 47 9 48*

Kindly let us have your supplementary approval.

~~There was~~ The impact onto the ~~bike~~ bike was at

Thank you. *the front left side of the front wheel. as there were were no impact damage ~~was~~ observed on the left side of the bike.*

Best Regards,
Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***FBK6195A (92389117535G)**

OD

Oct 1 2019 7:50AM

[TAN YOK SONG]

Bike Production Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 20/10/2019 19:30 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$6535.50) - FBK6195A - Claim Handler: Azlan, Syazairdina

Approved:6535.50:Damaged parts as require only approval with Surveyor acknowledgement for your attention. Kindly do not hesitate to arrange photo taking for check, supplementary item and after repair. "Stock Exhaust" for OD claim. Pricing to be re

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

***FBK6195A**
OD
Oct 1 2019 7:50AM
[TAN YOK SONG]
Bike Production Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on **07/10/2019 08:27 AM**.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$6932.20) - FBK6195A

Approved:6932.20:Damaged parts as require only approval with Surveyor acknowledgement for your attention. Kindly do not hesitate to arrange photo taking for check, supplementary item and after repair, "Stock Exhaust" for OD claim. Pricing to be re

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Azlan, Syazairdina

Date: 14 Oct 2019

Preliminary Advice

Vehicle No	: FBK6195A	Accident Date	: 01/10/2019
Make	: HONDA CB400SF	Policy No.	: 1700073770
Assignment Date	: 04/10/2019	Excess	: S\$0.00
Date of Inspection	: 04/10/2019	Est. Duration of Repair	: 3.00
Inspection At	: BIKE PRODUCTION PIE LTD (HQ) 610 SERANGOON ROAD SINGAPORE 218216		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion, o/s & n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,274.90 (inclusive supp)
Revised Amount	:S\$	4,843.50 (inclusive supp)
Check Items (Estimated)	:S\$	1,692.00
Total	:S\$	6,535.50
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	13,000.00
COE / PARF Rebate	:S\$	3,779.00
Salvage Value	:S\$	
Margin for Repair	:S\$	9,221.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Supplementary amount is \$ 594.00.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 04 Oct 2019

Preliminary Advice

Vehicle No	: FBK6195A	Accident Date	: 01/10/2019
Make	: HONDA CB400SF	Policy No.	: 1700073770
Assignment Date	: 04/10/2019	Excess	: S\$0.00
Date of Inspection	: 04/10/2019	Est. Duration of Repair	: 3 days
Inspection At	: Bike Production Pte Ltd (HQ) 610 SERANGOON ROAD Singapore 218216		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion, o/s & n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,560.90
Revised Amount	:S\$	2,710.50
Check Items (Estimated)	:S\$	4,221.70
Total	:S\$	6,932.20

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	13,000.00
COE / PARF Rebate	:S\$	3,779.00
Salvage Value	:S\$	
Margin for Repair	:S\$	9,221.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	01/10/2019 13:41
Date Of Accident	01/10/2019 07:50
Exact Location Of Accident	CHOA CHU KANG CRESCENT LOADING BAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBK6195A
Insured/Policyholder	
Name Of Registered Owner	TAN YOK SONG
NRIC No	S1201848G
Email Address	SBK5643E@YAHOO.COM
Mobile Phone No	(LOCAL) +65-98344066
Alternative Phone No	OFFICE-98344066

Vehicle Particulars

Manufacturer	HONDA
Model	CB400SF MANUAL

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	MOTORCYCLE
------------------	------------

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1700073770
Cover Note Number	

Driver

Name of Driver	TAN YOK SONG
NRIC No	S1201848G
Date Of Birth	27/12/1956
Occupation	INDOOR
Date Of Driving Pass	20/07/1977
Driving Experience	42 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98344066
Fax Number	
Contact Number	OFFICE-98344066
EEmail Address	SBK5643E@YAHOO.COM

Address	BLK 692A CHOA CHU KANG CRESCENT #23-14
Postcode	681692
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO ATTACHED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLP7259Z
Vehicle Make/Model/Colour	HONDA / SHUTTLE / RED
Details Of Properties	
Vehicle Category	PRIVATE HIRE
Name of Driver	CHIA TIAN SEAH
NRIC/Passport Number	S0030952D
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	TAN YOK SONG
------	--------------

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

PAIN AT BACK AREA

FBK6195A

NO

YES

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

please refer to attach.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

please refer to Police report
T/2019/001/2055


DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:


Driver's Signature
(if driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/IN No.:





**SINGAPORE
POLICE FORCE**



T/20191001/2055

1 of 3

Report No. T/20191001/2055

Police Station Of Origin:
Kim Keat NPP
231 Lorong 8 Toa Payoh #01-186
SINGAPORE 310231
Tel No: 1800-2529999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 01/10/2019 12:28	Video Report No.:	Station Diary No.: 9
--	-------------------	-------------------------

Informant's Particulars

Name of Informant: TAN YOK SONG			Address: APT BLK 692A CHOA CHU KANG CRESCENT #23-14 SINGAPORE 681692		
ID Type / ID No.: NRIC NO / S1201848G			Contact No.:		Mobile: 98344066
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 62	Date of Birth: 27/12/1956	Type of Informant: Rider		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Lorry driver			Driving Licence Information: Class: 2B,2A,2,3,4,5		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 01/10/2019 07:50	Type of Location: Straight Road
Location: Along Road 1 CHOA CHU KANG CRESCENT Along Choa Chu Kang Crescent near to blk 661 Choa Chu Kang Cr				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Not Controlled		Traffic Volume: No Traffic
Type of Collision: Moving Vehicle Against - Parked Vehicle				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No	Type	Make	Model	Color	Condition	No of Passenger
FBK6195A	Motorcycle	HONDA	CB400SF MANUAL	White	Totally Damaged	0
SLP7259Z	Car					0

Details of Vehicle Insurance

Vehicle No	Insurance Company	Insurance No	Effective	Expiry Date
FBK6195A	AIG ASIA PACIFIC INSURANCE PTE. LTD.	1700073770-01	01/11/2018	08/11/2019



**SINGAPORE
POLICE FORCE**



T/20191001/2055

2 of 3

Report No. T/20191001/2055

Police Station Of Origin:
Kim Keat NPP
231 Lorong 8 Toa Payoh #01-186
SINGAPORE 310231
Tel No: 1800-2529999

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	TAN YOK SONG	ID No.	S1201848G
Related Vehicle	FBK6195A (Motorcycle)	Contact No.	98344066
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3,4,5 Date of Expiry: NIL
Date Treatment	01/10/2019	Date Discharge	01/10/2019
No. of Days granted Medical Leave	05	Degree of Injury	Slight
Driver			
Name	CHIA TIAN SEAH	ID No.	S0030952D
Related Vehicle	SLP7259Z (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 01/10/2019 at about 0750hrs, I was on my motorcycle in front of Blk 661 Choa Chu Kang Crescent. At that point of time, my motorcycle was stationary at that point. That was one vehicle that was on my left hand side. I saw that vehicle had drove forward, out of a sudden the vehicle reverse to me and the next moment I was on the floor. The vehicle came in a fast speed. The driver stopped and came to me. the driver asked me how much I request he wish to pay me. As I felt pain at my back area therefore I called for ambulance myself. I was being convey to Ng Teng Fong Hospital and was given 5 days medical leave.



SINGAPORE
POLICE FORCE



T/20191001/2055

3 of 3

Report No. T/20191001/2055


Police Station Of Origin:
Kim Keat NPP
231 Lorong 8 Toa Payoh #01-186
SINGAPORE 310231
Tel No: 1800-2529999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: E / Sgt 2 LIM JIAN HONG	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 01/10/2019 12:28
Officer In Charge Of Case: TP / GIT / Sr Staff Sgt NORAMEERA BINTE MOHAMED HUSSEIN Contact No.: 65476238	Classification Of Case: SN 64
Authentication Stamp NP168 	 SIGNATURE

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	01/10/2019 13:41
Date Of Accident	01/10/2019 07:50
Exact Location Of Accident	CHOA CHU KANG CRESCENT LOADING BAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBK6195A
Insured/Policyholder	
Name Of Registered Owner	TAN YOK SONG
NRIC No	S1201848G
Email Address	SBK5643E@YAHOO.COM
Mobile Phone No	(LOCAL) +65-98344066
Alternative Phone No	OFFICE-98344066

Vehicle Particulars

Manufacturer	HONDA
Model	CB400SF MANUAL

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	MOTORCYCLE
------------------	------------

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1700073770
Cover Note Number	

Driver

Name of Driver	TAN YOK SONG
NRIC No	S1201848G
Date Of Birth	27/12/1956
Occupation	INDOOR
Date Of Driving Pass	20/07/1977
Driving Experience	42 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98344066
Fax Number	
Contact Number	OFFICE-98344066
Email Address	SBK5643E@YAHOO.COM

Address	BLK 692A CHOA CHU KANG CRESCENT #23-14
Postcode	681692
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO ATTACHED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLP7259Z
Vehicle Make/Model/Colour	HONDA / SHUTTLE / RED
Details Of Properties	
Vehicle Category	PRIVATE HIRE
Name of Driver	CHIA TIAN SEAH
NRIC/Passport Number	S0030952D
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	TAN YOK SONG
------	--------------

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

PAIN AT BACK AREA

FBK6195A

NO

YES

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under [d] above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

please refer to attach

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

please refer to Police report
T/20191001/2055

DECLARATION

I/We declare the foregoing particulars are true in every respect.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:





**SINGAPORE
POLICE FORCE**



T/20191001/2055

1 of 3

Report No. T/20191001/2055

Police Station Of Origin:
Kim Keat NPP
231 Lorong 8 Toa Payoh #01-186
SINGAPORE 310231
Tel No: 1800-2529999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 01/10/2019 12:28		Vide Report No.:		Station Diary No.: 9	
Informant's Particulars					
Name of Informant: TAN YOK SONG			Address: APT BLK 692A CHOA CHU KANG CRESCENT #23-14 SINGAPORE 681692		
ID Type / ID No.: NRIC NO / S1201848G			Contact No.: Home/Office: Mobile: 98344066		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 62	Date of Birth: 27/12/1956	Type of Informant: Rider		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Lorry driver			Driving Licence Information: Class: 2B,2A,2,3,4,5		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 01/10/2019 07:50	Type of Location: Straight Road
Location: Along Road 1 CHOA CHU KANG CRESCENT Along Choa Chu Kang Crescent near to blk 661 Choa Chu Kang Cr				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Not Controlled		Traffic Volume: No Traffic
Type of Collision: Moving Vehicle Against - Parked Vehicle				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBK6195A	Motorcycle	HONDA	CB400SF MANUAL	White	Totally Damaged	0
SLP7259Z	Car					0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
FBK6195A	AIG ASIA PACIFIC INSURANCE PTE. LTD.	1700073770-01	01/11/2018	08/11/2019



**SINGAPORE
POLICE FORCE**



T/20191001/2055

2 of 3

Police Station Of Origin:
Kim Keat NPP
231 Lorong 8 Toa Payoh #01-186
SINGAPORE 310231
Tel No: 1800-2529999

Report No. T/20191001/2055

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	TAN YOK SONG	ID No.	S1201848G
Related Vehicle	FBK6195A (Motorcycle)	Contact No.	98344066
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3,4,5 Date of Expiry: NIL
Date Treatment	01/10/2019	Date Discharge	01/10/2019
No. of Days granted Medical Leave	05	Degree of Injury	Slight
Driver			
Name	CHIA TIAN SEAH	ID No.	S0030952D
Related Vehicle	SLP7259Z (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 01/10/2019 at about 0750hrs, I was on my motorcycle in front of Blk 661 Choa Chu Kang Crescent. At that point of time, my motorcycle was stationary at that point. That was one vehicle that was on my left hand side. I saw that vehicle had drove forward, out of a sudden the vehicle reverse to me and the next moment I was on the floor. The vehicle came in a fast speed. The driver stopped and came to me. the driver asked me how much I request he wish to pay me. As I felt pain at my back area therefore I called for ambulance myself. I was being convey to Ng Teng Fong Hospital and was given 5 days medical leave.



SINGAPORE POLICE FORCE



T/20191001/2055

3 of 3

Report No. T/20191001/2055

Police Station Of Origin:
Kim Keat NPP
231 Lorong 8 Toa Payoh #01-186
SINGAPORE 310231
Tel No: 1800-2529999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: E / Sgt 2 LIM JIAN HONG	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 01/10/2019 12:28
Officer In Charge Of Case: TP / GIT / Sr Staff Sgt NORAMEERA BINTE MOHAMED HUSSEIN Contact No.: 65476236	Classification Of Case: SN 64
Authentication Stamp NP168 	



CERTIFICATE OF INSURANCE

MOTORCYCLE AUTOVANTAGE MOTORCYCLE

Name of Policyholder : TAN YOK SONG
 Period of Insurance : 01 Nov 2018 To 31 Oct 2019
 Engine No. : NC42E1203953
 Chassis No. : NC421603953

Vehicle No. : FBK6195A
 Policy No. : 1700073770-01
 Endorsement No. :
 Issued Date : 04 Oct 2018

ABOUT THE COVER

Make/Model : HONDA CB400SF
 Engine Capacity/Tonnage : 399.00 CC
 Driver Restriction : Named Driver Basis
 Sum Insured : Market Value
 Off Peak Use : No
 First Year of Registration : 2015
 Insuring with COE/PARF : Yes

Beneficiaries of Persons Entitled to Drive* :

- a) The Policyholder
- b) Any person who is named as a "named driver" under this Policy.

Age Condition : Not Applicable

Limitation as to use* :

- Use only for social, domestic and pleasure purposes and for the Policyholder's business. The Policy does not cover:
- 1) use for hire or reward;
 - 2) use for driving tuition, driving test, racing, pace-making, reliability trial or speed-testing;
 - 3) use for the carriage of goods (other than samples) in connection with any trade or business; and
 - 4) use for any purpose in connection with Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 85 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
 Fire - \$0 Own Damage - \$500 Theft - \$0

Section 2
 Property Damage - \$0

Windscreen : NA

Please note that this vehicle is under hire purchase with **BIKE PRODUCTION PTE LTD** and transfer of endorsement is allowed *only with the written consent*

Named Driver and Excess (where applicable)

TAN YOK SONG

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

Any accident repairs to the Vehicle must be carried out by one of our Authorized Repairers. Within the first 3 years of the first registration of the Vehicle in Singapore, You have the option of having the accident repairs carried out at the Sole Agent's workshop. For other Approved Reporting Centres/AIG Authorized Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, You may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: BIKE PRODUCTION PTE LTD

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0500650018

COWELL - BIKE PRODUCTION
 8 BURN ROAD #09-09 TRIVEX
 SINGAPORE 369577 ANSP-NONLIFE

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

BIKE PRODUCTION PTE LTD
 Co Reg No: 200007407G
 610 Serangoon Road
 Singapore 215216
 Tel: 63922665 Fax: 63975400

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

1001873356AC

Note: The above estimate is subjected to the prevailing GST of 7%



[Handwritten signature]

For Bike Production Pte Ltd

NA2 LKX

4/10/19 1100

LIS

3 days

[Handwritten signature]
4/10/19

CHECK ITEM PHOTOS
AFTER REPAIR PHOTOS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

00

BIKE PRODUCTION PTE LTD
 610, Serangoon Road S(218216)
 Tel: 63922555, 62995177 Fax: 62975400
 ROC/ GST Reg No.: 200007407G


Date: 1 Oct 2019

ASSESSMENT FOR REPAIR: HONDA CB400SF MANUAL - FBK6195A

Chassis No.: NC421603953
 Engine No.: NC42E1203953

<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
1 pc	• Front wheel axle	110 \$115.00 ? BT
1 pc	• Front left fork assy	\$1,088.00 X SWL X R
1 pc	Front right fork assy	\$1,088.00 X SWL
1 pc	• Front left brake disk	120 \$350.00 BT
1 pc	Front Right brake disk	\$350.00 X SWL
1 pc	Front fork steering head crown	\$450.00 X SWL
1 pc	Front fork steering stem	\$490.00 X SWL
2 pcs	Steering stem bearing @ \$45.00	\$90.00 SWL
1 pc	Brake lever	120 \$145.00 BR
1 pc	• Steering handle	110 \$180.00 BT
1 pc	Right front signal	120 \$145.00 SWL
1 pc	Right handle bar balancer	\$55.00 SWL
1 pc	View mirror right	\$140.00 SWL
1 pc	• Meter assy	\$900.00 X SWL
1 pc	Brake pedal assy	\$165.00 SWL
1 set	Right crash bar	200 \$220.00 SWL
1 pc	• Right rear footrest holder	\$265.00 X SWL BT
1 pc	Exhaust slider	\$105.00 SWL
1 pc	Rear right footrest	80 \$95.00 SWL
1 pc	Front right footrest	80 \$95.00 SWL
4 pcs	Exhaust gasket @ \$15.00	\$60.00 X reuse
1 pc	• Exhaust assembly	FT 1,780 \$1,880.00 ? check exhaust muffer to be separately
	Less discount 10%	\$8,551.00 \$855.10 \$7,695.90
	Special nett items	
1 pc	• Front sport rim	\$790.00 X SWL X R
1 pc	Box rack	\$195.00 X SWL
1 pc	Top case	\$300.00 SWL
1)	Towing charges	\$100.00 80
	Replace, realign and adjust above damaged parts, check wiring and lighting system	\$700.00 150 300
2)	• To replace and balance front wheel rim	\$150.00 X SWL Repair front rim
3)	To knock, straighten chassis & body balancing	W X \$450.00
4)	• To remove/refit, replace (if damage) check and straighten front fork tubes.	400 \$180.00 300 Repair and refit front fork
	Total Estimate	<u>\$10,560.90</u>

Note: The above estimate is subjected to the prevailing GST of 7%



NA2 LK

4/10/19 1100

LIS

3 days

CHECK ITEM PHOTOS

AFTER REPAIR PHOTOS

LKK Auto Centre hereby notify
the Reparer of the following:

- To identify colorant for spray painting
- To display damaged part(s) during resurvey
- Part notes are subject to confirmation
- This survey is on a "Without Prejudice" basis
- No legal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Reparer

Signature:

Date:

BIKE PRODUCTION PTE LTD
 610, Serangoon Road S(218216)
 Tel: 63922555, 62995177 Fax: 62975400
 ROC/ GST Reg No.: 200007407G

Date: 9 Oct 2019

SUPPLEMENTARY FOR REPAIR: HONDA CB400SF MANUAL - FBK6195A

Chassis No.: NC421603953
 Engine No.: NC42E1203953

1 PC METER CENTRE COVER @ 195/SCR
 1 PC METER RIGHT COCKPIT COVER @ 105/90/SCR

Qty	Description	Estimate
1 pc	Front mudguard	200 \$220.00 / SCR
1 pc	Right side cover	120 \$140.00 / SCR
		\$360.00
	Less discount 10%	\$36.00
		<u>\$324.00</u>
	Special nett items	
	Total Estimate	<u><u>\$324.00</u></u>

Note: The above estimate is subjected to the prevailing GST of 7%



For Bike Production Pte Ltd

PARTS \$4,200
 ESS 10% \$3,870
 SINNET \$330
 ABOVE \$750
\$4,950

ESS 1/520% \$3,960
\$3,950 / 3 DAYS

LIK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

FINALIZED LUMP SUM REPAIR \$3,950.00 / 3 DAYS

NA
 NAZUK
 13/11/19

BIKE PRODUCTION PTE. LTD.

610, Serangoon Road Singapore 218216
Tel: 6392 2555 Fax: 6297 5400

TAX INVOICE

Co. Registration No. 200007407G
GST Reg. No: 200007407G
GST Inclusive

No: 6149

Name : AIG ASIA PACIFIC INSURANCE PTE LTD Date : 13/11/2019
Address : 78 SHENTON WAY #07-16 AIG BUILDING SE 079120
I/C No : _____ Occupation : _____ DOB : _____
Tel : (H)64193000 (F)64153723 Driving Licence : _____

Particulars		Amount
Reg. No: <u>FBK6195A</u>	Selling Price	<u>\$ 3,691.50</u>
Make & Model: <u>HONDA CB400SF MANUAL</u>	+ Insurance	<u>\$ 0</u>
Engine No: <u>NC42E1203953</u>	+ Retention	<u>\$ 0</u>
Chassis No: <u>NC421603953</u>	TOTAL PRICE	<u>\$ 3,691.50</u>
Insurance Type: <input type="checkbox"/> Comprehensive <input type="checkbox"/> Third Party Fire Theft <input type="checkbox"/> Third Party Only		
Colour: <u>WHITE</u>	LUMP SUM REPAIRS	Downpayment <u>\$ 3,950.00</u>
	LESS EXCESS	<u>\$ 500.00</u>
Loan Amount _____	Interest rates _____ p.a.	<u>\$ 3,450.00</u>
Terms: (_____)	Monthly Instalments of \$ <u>GST 7%</u>)	<u>\$ 241.50</u>
N/R: _____	TEL: _____	<u>\$ 3,691.50</u>
GTR: _____	TEL: _____	
COE NO: _____	TR	

Note:

- Above prices do not include ERP IU.
- Deposit is not refundable.
- Balance amount must be cleared within 3 days of the invoice date. Deposit will be forfeited if the buyer fails to clear the full balance amount within the stated period.
- Title to the above-mentioned goods will not be handed to the buyer until the full amount and/or changes are paid
- All cheque payments are to be crossed and made payable to **Bike Production Pte Ltd**. If cheque dishonoured, the buyer has to pay **Bike Production Pte Ltd** by cash and a service charge of S\$30.00 plus prevailing GST.
- Bike Production Pte Ltd** will have full rights to repossess the above-mentioned goods without notice in case of default in payment.
- The buyer shall inspect the above-mentioned goods immediately on notification that goods are due and ready for collection. The buyer shall give notice in writing to the seller of any matter or thing by reason whereof he alleges that the goods are not in acceptable conditions. If the buyer fails to give notice, the above-mentioned goods shall be deemed to be in accordance with the contract and the buyer shall be bound to accept and pay for the same accordingly.
- For hire purchase, no alteration of the hire-purchase agreement and its terms, including down payment and installment period, is allowed once the hire-purchase agreement is made. In the event of cancellation, the buyer shall compensate **Bike Production Pte Ltd** 20% of the total price plus prevailing GST and the deposit shall be forfeited.
- For hire purchase, a Singaporean guarantor between 21 year & 60 year of age and with a different residential address from the buyer is required before the collection of the above-mentioned goods. The guarantor shall not be an undischarged bankrupt and is subject to financial approval.
- I confirm that the information I have provided is my personal data and, where it is not my personal data, that I have the consent of the owner of such personal data to provide such information. By providing this information I understand and give my consent for **Bike Production Pte Ltd** to collect, use, store, transfer and / or disclose personal data about me or us and those whose personal data I or we have provided from sources other than myself or us for the purposes.

For **Bike Production Pte Ltd**

I accept the above terms and conditions

Tan Yok Song
Blk 692A Choa Chu Kang Crescent
#23-14
Singapore 681692

Date: 14 Oct 2019

To: Mr Kwan Say Hwee
Bike Production Pte Ltd
610, Serangoon Road
Singapore 218216

Dear Sir,

**RE: AKNOWLEDGEMENT OF THE ACCIDENT REPAIR AND COLLECTION
OF HONDA CB400SF MANUAL VEHICLE NO.: FBK6195A**

I, Tan Yok Song, NRIC No.: 848G, have inspected the repair done by Bike Production Pte Ltd and the repair is in accordance to the repair quotation and/or surveyor report.

I have collected the above mentioned vehicle on 14-10-19 at 5.45 pm.

Thank you very much for your attention.

Yours faithfully,



Tan Yok Song

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Oct 2019 09:26		04 Oct 2019 10:12 Edit Adj Rpt	S\$3,950.00 Edit Estimates	S\$3,950.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	TAN YOK SONG, ID: S1201848G, Tel: +6598344066, Email: sbk5643e@yahoo.com								
Vehicle Reg. No.:	FBK6195A	Date of Loss:	01/10/2019 07:00 - :59 [46 Months and 22 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 9238911753SG	Policy/Cover Note No.:	1700073770 (Comprehensive)						
		Excess:	S\$500.00						
Repairer:	Bike Production Pie Ltd (HQ) 610 SERANGOON ROAD, 218216 Serangoon - Tel: 63922555								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Azlan, Syazairdina] syazairdina.azlan@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 15/10/2019]								
Driver/Custodian:	TAN YOK SONG (62 / Male), NRIC: S1201848G, Tel: +6598344066 Email: sbk5643e@yahoo.com								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (20/10/2019): Alert - Adj Mandate Approved (S\$6535.50) - FBK6195A - Claim Handler: Azlan, Syaz... AIG_SG (15/10/2019): FBK6195A / OD / 01/10/2019 / Coverage & Excess update AIG_SG (07/10/2019): Alert - Adj Mandate Approved (S\$6932.20) - FBK6195A 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBK6195A (9238911753SG)

OD

Oct 1 2019 7:50AM

[TAN YOK SONG]

Bike Production Pie Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser		
Assessment Reports										1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print	
1	04/10/19 17:21	Adjuster Immediate Advice									Load HTM	<input type="checkbox"/>
2	14/10/19 09:14	Adjuster Immediate Advice									Load HTM	<input type="checkbox"/>
Photos/Images										3 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print	
1	04/10/19 17:17	General View									Load JPG	<input checked="" type="checkbox"/>
2	04/10/19 17:17	General View									Load JPG	<input checked="" type="checkbox"/>
3	04/10/19 17:17	General View									Load JPG	<input checked="" type="checkbox"/>
4	04/10/19 17:17	General View									Load JPG	<input checked="" type="checkbox"/>
5	04/10/19 17:17	General View									Load JPG	<input checked="" type="checkbox"/>
6	04/10/19 17:17	General View									Load JPG	<input checked="" type="checkbox"/>
7	04/10/19 17:17	General View									Load JPG	<input checked="" type="checkbox"/>
8	04/10/19 17:17	General View									Load JPG	<input checked="" type="checkbox"/>
9	04/10/19 17:17	General View									Load JPG	<input checked="" type="checkbox"/>
10	04/10/19 17:17	General View									Load JPG	<input checked="" type="checkbox"/>
11	04/10/19 17:17	General View									Load JPG	<input checked="" type="checkbox"/>
12	04/10/19 17:17	General View									Load JPG	<input checked="" type="checkbox"/>
13	04/10/19 17:17	General View									Load JPG	<input checked="" type="checkbox"/>
14	04/10/19 17:17	General View									Load JPG	<input checked="" type="checkbox"/>
15	04/10/19 17:17	General View									Load JPG	<input checked="" type="checkbox"/>
16	04/10/19 17:17	General View									Load JPG	<input checked="" type="checkbox"/>
17	04/10/19 17:17	General View									Load JPG	<input checked="" type="checkbox"/>
18	04/10/19 17:17	General View									Load JPG	<input checked="" type="checkbox"/>
19	04/10/19 17:17	General View									Load JPG	<input checked="" type="checkbox"/>
20	04/10/19 17:17	General View									Load JPG	<input checked="" type="checkbox"/>
21	04/10/19 17:17	General View									Load JPG	<input checked="" type="checkbox"/>
22	04/10/19 17:17	General View									Load JPG	<input checked="" type="checkbox"/>
23	04/10/19 17:17	General View									Load JPG	<input checked="" type="checkbox"/>
24	04/10/19 17:17	General View									Load JPG	<input checked="" type="checkbox"/>
25	04/10/19 17:17	General View									Load JPG	<input checked="" type="checkbox"/>
26	04/10/19 17:17	General View									Load JPG	<input checked="" type="checkbox"/>
27	04/10/19 17:17	General View									Load JPG	<input checked="" type="checkbox"/>
28	04/10/19 17:17	General View									Load JPG	<input checked="" type="checkbox"/>
29	04/10/19 17:17	General View									Load JPG	<input checked="" type="checkbox"/>
30	04/10/19 17:17	General View									Load JPG	<input checked="" type="checkbox"/>
31	04/10/19 17:17	General View									Load JPG	<input checked="" type="checkbox"/>
32	04/10/19 17:17	General View									Load JPG	<input checked="" type="checkbox"/>
33	04/10/19 17:17	General View									Load JPG	<input checked="" type="checkbox"/>
34	04/10/19 17:17	General View									Load JPG	<input checked="" type="checkbox"/>
35	04/10/19 17:17	General View									Load JPG	<input checked="" type="checkbox"/>
36	04/10/19 17:17	General View									Load JPG	<input checked="" type="checkbox"/>
37	04/10/19 17:17	General View									Load JPG	<input checked="" type="checkbox"/>
38	04/10/19 17:17	General View									Load JPG	<input checked="" type="checkbox"/>
39	04/10/19 17:17	General View									Load JPG	<input checked="" type="checkbox"/>
40	04/10/19 17:17	General View									Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
41	04/10/19 17:17	General View		<input checked="" type="checkbox"/>
42	04/10/19 17:17	General View		<input checked="" type="checkbox"/>
43	04/10/19 17:17	General View		<input checked="" type="checkbox"/>
44	04/10/19 17:17	General View		<input checked="" type="checkbox"/>
45	04/10/19 17:17	General View		<input checked="" type="checkbox"/>
46	04/10/19 17:17	General View		<input checked="" type="checkbox"/>
47	04/10/19 17:17	General View		<input checked="" type="checkbox"/>
48	04/10/19 17:17	General View		<input checked="" type="checkbox"/>
49	04/10/19 17:17	General View		<input checked="" type="checkbox"/>
50	04/10/19 17:17	General View		<input checked="" type="checkbox"/>
51	04/10/19 17:17	General View		<input checked="" type="checkbox"/>
52	14/10/19 09:16	Reinspection Photo		<input checked="" type="checkbox"/>
53	14/10/19 09:16	Reinspection Photo		<input checked="" type="checkbox"/>
54	14/10/19 09:16	Reinspection Photo		<input checked="" type="checkbox"/>
55	14/10/19 09:16	Reinspection Photo		<input checked="" type="checkbox"/>
56	14/10/19 09:16	Reinspection Photo		<input checked="" type="checkbox"/>
57	14/10/19 09:16	Reinspection Photo		<input checked="" type="checkbox"/>
58	14/10/19 09:16	Reinspection Photo		<input checked="" type="checkbox"/>
59	14/10/19 09:16	Reinspection Photo		<input checked="" type="checkbox"/>
60	14/10/19 09:16	Reinspection Photo		<input checked="" type="checkbox"/>
61	14/10/19 09:16	Reinspection Photo		<input checked="" type="checkbox"/>
62	14/10/19 09:16	Reinspection Photo		<input checked="" type="checkbox"/>
63	14/10/19 09:16	Reinspection Photo		<input checked="" type="checkbox"/>
64	14/10/19 09:16	Reinspection Photo		<input checked="" type="checkbox"/>
65	14/10/19 09:16	Reinspection Photo		<input checked="" type="checkbox"/>
66	14/10/19 09:16	Reinspection Photo		<input checked="" type="checkbox"/>
67	14/10/19 09:16	Reinspection Photo		<input checked="" type="checkbox"/>
68	14/10/19 09:16	Reinspection Photo		<input checked="" type="checkbox"/>
69	14/10/19 09:16	Reinspection Photo		<input checked="" type="checkbox"/>
70	13/11/19 17:47	Photo After Spray		<input checked="" type="checkbox"/>
71	13/11/19 17:47	Photo After Spray		<input checked="" type="checkbox"/>
72	13/11/19 17:47	Photo After Spray		<input checked="" type="checkbox"/>
73	13/11/19 17:47	Photo After Spray		<input checked="" type="checkbox"/>
74	13/11/19 17:47	Photo After Spray		<input checked="" type="checkbox"/>
75	13/11/19 17:47	Photo After Spray		<input checked="" type="checkbox"/>
76	13/11/19 17:47	Photo After Spray		<input checked="" type="checkbox"/>
77	13/11/19 17:47	Photo After Spray		<input checked="" type="checkbox"/>
78	13/11/19 17:47	Photo After Spray		<input checked="" type="checkbox"/>
79	13/11/19 17:47	Photo After Spray		<input checked="" type="checkbox"/>
80	13/11/19 17:47	Photo After Spray		<input checked="" type="checkbox"/>
81	13/11/19 17:47	Photo After Spray		<input checked="" type="checkbox"/>
82	13/11/19 17:47	Photo After Spray		<input checked="" type="checkbox"/>
83	13/11/19 17:47	Photo After Spray		<input checked="" type="checkbox"/>
84	13/11/19 17:47	Photo After Spray		<input checked="" type="checkbox"/>
85	13/11/19 17:47	Photo After Spray		<input checked="" type="checkbox"/>
86	13/11/19 17:47	Photo After Spray		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/10/19 17:15	FBK 6195A GIA.pdf		<input type="checkbox"/>
2	04/10/19 17:15	POLICE REPORT.pdf		<input type="checkbox"/>
3	04/10/19 17:15	CI.pdf		<input type="checkbox"/>
4	04/10/19 17:15	ESTIMATE.pdf		<input type="checkbox"/>
5	14/10/19 09:15	ESTIMATE & SUPP 1.pdf		<input type="checkbox"/>
6	18/11/19 10:49	ESTIMATE & SUPP MARKED.pdf		<input type="checkbox"/>
7	28/11/19 09:42	Workshop Invoice		<input type="checkbox"/>
8	28/11/19 09:42	Discharge Voucher		<input type="checkbox"/>

Linked Accident Report Documents

			View	View in Browser
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
1	02/10/19 16:04	Accident Statement	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
1	01/10/19 14:06	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	01/10/19 14:06	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	01/10/19 14:06	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	01/10/19 14:06	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	01/10/19 14:06	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	01/10/19 14:06	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	01/10/19 14:06	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	02/10/19 16:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	02/10/19 16:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
10	02/10/19 16:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
11	02/10/19 16:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
12	02/10/19 16:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
13	02/10/19 16:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
14	02/10/19 16:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
15	02/10/19 16:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
1	01/10/19 13:59	Sketch Plan	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CS/AIG19017484/NSD3E2

Date: 28/11/2019

REFERENCE

Insured/Claimant:	TAN YOK SONG	Policy No:	1700073770	
Date of Loss:	01/10/2019	Nature of Claim:	OD	Claim No: 9238911753SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBK6195A		
Make & Model:	HONDA CB400SF, 399cc	Engine No:	NC42E1203953
Reg. Date:	09/11/2015 (Man. Year: 2015)	Chassis No:	NC421603953
Colour:	White	Odometer:	48361 km
Engine Capacity:	399 cc		
Market Value/New Car Price:	S\$13,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	120/60 R17	Rear Tyre Size:	160/60 R17
Front Left Side:	Metzeler 4 mm	Rear Left Side:	Metzeler 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,574.90	4,120.00	5,454.90	56.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,800.00	830.00	970.00	53.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,374.90	4,950.00	6,424.90	56.48
Approved Total (Overridden) (S\$)		3,950.00		
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	10,874.90	3,450.00	7,424.90	68.28
+ GST 7.00/7.00% (S\$)	761.24	241.50	519.74	68.28
Nett Amount (S\$)	11,636.14	3,691.50	7,944.64	68.28

INSPECTION

Date of Assignment:	04/10/2019		
Date Inspected:	04/10/2019	Inspected At:	Bike Production Pte Ltd (HQ) 610 SERANGOON ROAD Singapore 218216
Estimated Period of Repair:	3.0 days		

Adjuster: Muhammad Nazril Bin Abdullah

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WHEEL AXLE	Bent	115.00 FL	*110.00 FL
2	1		*FRONT LEFT FORK ASSY	Repair	1,088.00 FL	*- FL
3	1		*FRONT RIGHT FORK ASSY	Serviceable	1,088.00 FL	*- FL
4	1		*FRONT LEFT BRAKE DISK	Bent	350.00 FL	*320.00 FL
5	1		*FRONT RIGHT BRAKE DISK	Serviceable	350.00 FL	*- FL
6	1		*FRONT FORK STEERING HEAD CROWN	Serviceable	450.00 FL	*- FL
7	1		*FRONT FORK STEERING STEM	Serviceable	490.00 FL	*- FL
8	2		*STEERING STEM BEARING	Serviceable	90.00 FL	*- FL
9	1		*BRAKE LEVER	Broken	145.00 FL	*120.00 FL
10	1		*STEERING HANDLE	Bent	180.00 FL	*160.00 FL
11	1		*RIGHT FRONT SIGNAL	Scratched	145.00 FL	*120.00 FL
12	1		*RIGHT HANDLE BAR BALANCER	Scratched	55.00 FL	*55.00 FL
13	1		*VIEW MIRROR RIGHT	Scratched	140.00 FL	*140.00 FL
14	1		*METER ASSY	Serviceable	980.00 FL	*- FL
15	1		*BRAKE PEDAL ASSY	Scratched	165.00 FL	*165.00 FL
16	1		*SET RIGHT CRASH BAR	Scratched	220.00 FL	*200.00 FL
17	1		*RIGHT REAR FOOTREST HOLDER	Bent	265.00 FL	*265.00 FL
18	1		*EXHAUST SLIDER	Scratched	105.00 FL	*105.00 FL
19	1		*REAR RIGHT FOOTREST	Scratched	95.00 FL	*80.00 FL
20	1		*FRONT RIGHT FOOTREST	Scratched	95.00 FL	*80.00 FL
21	4		*EXHAUST GASKET	Reuse	60.00 FL	*- FL
22	1		*EXHAUST ASSEMBLY	Bent	1,880.00 FL	*1,780.00 FL
23	1		*FRONT SPORT RIM	Repair	790.00 FS	*- FS
24	1		*BOX RACK	Serviceable	195.00 FS	*- FS
25	1		*TOP CASE	Scratched	300.00 FS	*250.00 FS
26	1		*FRONT MUDGUARD	Scratched	220.00 FL	*200.00 FL
27	1		*RIGHT SIDE COVER	Scratched	140.00 FL	*120.00 FL
28	1		*METER CENTRE COVER	Scratched	195.00 FL	*190.00 FL
29	1		*METER RIGHT LOWER COVER	Scratched	105.00 FL	*90.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,496.00	4,550.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	921.10	430.00
Total Parts (\$\$)	9,574.90	4,120.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING CHARGES	New	100.00	80.00
2	REPLACE, REALIGN AND ADJUST ABOVE DAMAGED PARTS, CHECK WIRING AND LIGHTING SYSTEM	New	700.00	300.00
3	TO REPLACE AND BALANCE FRONT WHEEL RIM	New	150.00	150.00
4	TO KNOCK, STRAIGHTEN CHASSIS & BODY BALANCING	New	450.00	0.00
5	TO REMOVE/REFIT, REPLACE (IF DAMAGE) CHECK AND STRAIGHTEN FRONT FORK TUBES	New	400.00	300.00
Gross Labour Cost (\$\$)			1,800.00	830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >