

220002001

ASS. REC. BY:

REF: CSB/MSG18022267/Gy03-1

Special Instruction:

Surveyor: Quo Quang Menmen

ASSIGNMENT (Office)

From (Person): Monica chung

of MSIG

Date/Time: 03/10/2019

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SDN 6064E

Insured:

SDG 9978K

at Workshop n/s

Wee Hwe Auto

Tel:

6858 0019

of

19 Kim chuan Terrace

Policy No:

28827818QMY

Claim No:

578450

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

10/12/18

12/12/18

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

lup?

Date/Time:

3/11/2018

Person Contacted:

Kiat

Vehicle:

IN/OUT

Date/Time	Action/Instruction	(+) Estimate
	SDN 6064E - NBA/MSG18022267/y	D.O.A 10/12/18
	SDG 9978K - NBA/MSG18022267/y	D.O.A 10/12/18
	Disassemble: 13/12/2018	

\$2600, 5 Days.  
(Red \$2928-83, 52%)

18/10/2019

Do Not Finalise

21/10/19 Typist

RECEIVED 22 OCT 2019

SWHDP  
Maximen (PSS)

REF: MSIG

B3200K /  
(-249)

ASSIGNMENT

From: Date: 12/12/2018

Vehicle: SDN 6064E 15 Oct 2009

Estimated Cost:

Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Private Mover /

OD: (P) WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To inspect Vehicle No: SDN 6064E

Make: Toyota Altis 1598

at Workshop no: Wee Hoe Auto

Colour: Silver A/C Insured / Std / NI / NA

of 19 Kim Chuan Terrace

Sp Reading: 282056 ((Rear): Insured / Std / NI / NA

Issued:

Engine: MR0532EE 106156613

Policy No:

Gen. Cond: Good / Fair / Poor / Burnt

Claims No:

Steering: In order / Jammed / Leaked / Burnt or

Item Insured:

Brake: In order / Jammed / Leaked / Burnt or

(Client's Record)

Mod: NI / SRim / STD A/C or


Make of Veh:

Tyre Size: F: 195/65 R15

(Policy Condition)

R: 11

Remark: The veh had commenced its repair at the time of inspection.



Est. or Market Value:

\$17K

BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /

IDAC Accident Report:

Consistent? : Yes or No

TOYO / YOKO or

linglong

GIA / PR. Sent:

Consistent? : Yes or No

Front

Rear

Est. Repairs:

5

days

Res.: Yes or No

R/Bal

5

mm

R/Bal

5

mm

Lump Sum:

20

%

3 Val.: Yes or No

L/Bal

5

mm

L/Bal

5

mm

CA / REV / REP. / 24 HRS

1up

D.O.A.

D.O.A.

12-12-18

Survey held at

w/s

1:45pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Tot, O/S Tot.

Date:

Person Contacted:

Vehicle: IN / OUT

The (O/C) Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$5000 - \$6000

CoE: 10280

Date/Time, File Path to:

☐

: Prel. Report

Days Of Repair: 5

1)

☐

: Final Report

Resurvey No. of Trip: 1

Survey Fee:

Date/Time, File Path to:

Add Fee:

☐

Site Insp: 1\$

Transportation:

2)

☐

Interview: 1\$

1) Photo:

Report Format:

PRE.

☐

Tech. Insp: 1\$

1) Other:

Lump Sum / L.B.F: 1\$

☐

Weekend: 1\$

1)

120
10
130

## Nivitha (LKK Auto)

---

**From:** Accounts (LKKAuto) <account@lkkauto.com>  
**Sent:** Thursday, 3 October 2019 12:07 PM  
**To:** Admin-D (LKKAuto)  
**Cc:** Accounts (LKKAuto)  
**Subject:** RE: Report Send Back Alerts - SDN6064E (TP)

Dear Nivitha,

FYNA Please....

### Pending for Survey Report- CS3/MSG18022277/GCD3E2

19 03 Oct 2019 10:12	<b>Ins Send Back Adj Rpt</b>	Paper adjustment	[I] Monica Chung Pei Zhe
20 03 Oct 2019 10:12	<b>Adj Next Rpt Changed</b>	Next Rpt:Final Rpt.Due Date:2019/10/07	[I] Merimen Administrator
21 03 Oct 2019 10:12	<b>Adj Mandate Set</b>	Maintained.	[I] Merimen Administrator

Thank You

Best Regards,



SuthaShelia (Shelia) | Accounts Dept.

LKK Auto Consultants Pte Ltd

Phone: **6841 1891** | email: [account@lkkauto.com](mailto:account@lkkauto.com) | fax: 6844-8805

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Do-Not-Reply <do-not-reply@merimen.com>

**Sent:** Thursday, 3 October 2019 10:20 AM

**To:** account@lkkauto.com

**Subject:** Report Send Back Alerts - SDN6064E (TP)

Dear Sir / Madam,

Please login to Merimen Online at [www.merimen.com.sg](http://www.merimen.com.sg) for more information.

Thanks,

The Merimen Team



**AVG**

This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)



# PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529990)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

## INVOICE

M/s. Moo Auto  
C/o. 19 Kim Chuan Terrace  
Singapore 537041

Invoice No. : HA/1901-40

Date : 25/01/2019

Descriptions	Amount (SGD)
Services rendered for appraiser / inspection report :-	
Survey Fee	
Photographs	
Transport Fees	
Re-inspection Fees	
Total :	SGD : \$ 444.00
SGD Dollar : Four Hundred Forty Four Dollars Only.	
Our Reference : PAS/TP/0261218	
Vehicle No. : SDN6064E	
Make & Model : Toyota Corolla Altis 1.6	
Your Claim No. : Third Party Claim	

### Notes:

All cheque payment should be Crossed and made payable to "PROMINENT APPRAISER SERVICES PTE LTD".

Please indicate our "INVOICE NO." on the reverse side of the cheque.

Should you have any enquiries, please do not hesitate to contact us.



For PROMINENT APPRAISER SERVICES PTE LTD



# PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

## VEHICLE INSPECTION REPORT

Report No. : PAS/TP/0261218

Date of Report : 25/01/2019

To : M/s. Moo Auto  
C/o. 19 Kim Chuan Terrace  
Singapore 537041

Date of Assignment : 12/12/2018  
Report requested by : M/s. Moo Auto  
Date of Accident : 10/12/2018  
Date of Inspection : 12/12/2018  
Claim No. : Third Party Claim  
Policy No. : -

### PARTICULARS OF DAMAGED VEHICLE

Vehicle Registration No. : SDN6064E  
Make & Model : Toyota Corolla Altis 1.6  
Date of Registration : 15/10/2009  
Colour : Met. Silver

Engine Capacity (cc) : 1598cc  
Mileage (km) : 242056km  
Chassis / Frame No. : MR053ZEE106156613  
Engine No. : 3ZZ4937196

### TYRE CONDITION

Front LH : 5 mm	Front RH : 5 mm
Make : Linglong	Make : Linglong
Rear LH : 7 mm	Rear RH : 7 mm
Make : Nexen	Make : Nexen

Road wheels Type : Alloy

(The above represents the approximate remaining life of tyre treads)

### PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Bodywork	: Good
Paintwork	: Good
Handbrake	: Serviceable
Footbrake	: Serviceable
Steering	: Serviceable
Apparent Engine Modification	: Nil

### PLACE OF REPAIRER OFFICE/WORKSHOP

Location : M/s. Wee Hoe Auto Service  
19, Kim Chuan Terrace, Singapore 537041

### ASSESSMENT

Repairer's Estimate	: \$ 6,884.88
Revised Amount	: \$ 5,528.83
Less Excess	: \$ -
Recommended Reserve	: \$ 4,420.00 (Lump Sum)

Estimated Normal Period of Repairs : 6 Working Days

*Disclaimer: This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle involved. No liability or responsibility whatsoever shall be held by PROMINENT APPRAISER SERVICES PTE LTD for any reliance on this report by any third party.*



# PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No : SDN6064E

Report No. : PAS/TP/0261218

## GENERAL REMARKS

WITHOUT PREJUDICE

### THE ASSIGNMENT

The survey was conducted at M/s. Wee Hoe Auto Service, 19, Kim Chuan Terrace, Singapore 537041.

(Subsequent inspections have been conducted)

### POINT OF IMPACT

At the LHF portion. (The RHF roadwheel was also affected)

### DAMAGES

The bonnet, front support panel, front bumper, LHF fender, LHF fender inner panel, RHF alloy rim, RHF knuckle arm, RHF lower arm, RHF shock absorber, etc.

*Other parts were also found damaged. (See schedule for details)*

### ADJUSTMENT / RECOMMENDATION

We have inspected thoroughly each and every item on the repairer's estimate against the actual damaged found on the vehicle. We list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is SGD \$5,528.83.

### CONCLUSION


The repairer has agreed to undertake the repairs at a lump sum of SGD \$4,420.00.

This inspection was conducted entirely on a 'Without Prejudice' basis. We have not given an authorization and/or instruction to the repairer to proceed with the repairs.

We hereby reverting the matter to you for your discretion on repairs.

Assuring you of our best services always.

Yours Truly,  
**Prominent Appraiser Services Pte Ltd**

  
**Andrew How**  
Automobile Appraiser  
MSAAA  
Licensed Appraiser



# PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No. : SDN6064E

Report No. : PAS/TP/0261218

## APPRAISEMENT SCHEDULE

S/No.	Qty	Parts Descriptions	Condition		Repairer's Estimate (\$S)	Our Assessment (\$S)
1	1 pc	Headlamp LH	Defaced/Loop Broken		\$ 708.40 <i>485.2</i>	\$ / 708.40
2	1 pc	Frt bumper	Dented		\$ 458.40	\$ / 458.40
3	1 pc	Frt grille	Refit <i>SVC</i>		\$ 301.90	\$ -
4	1 pc	Frt grille emblem	Necessary		\$ 71.00	\$ / 71.00
5	1 pc	Frt bumper reinforcement	Refit <i>SVC</i>		\$ 341.10	\$ -
6	6 pcs	Frt bumper clip	Necessary	\$ 3.50	\$ 21.00	\$ / 21.00
7	2 pcs	Frt bumper retainer R/L <i>part x 2</i>	Cracked/Necessary	\$ 54.60	\$ 109.20 <i>456</i>	\$ / 109.20
8	1 pc	Frt fog lamp LH	Refit <i>SVC</i>		\$ 238.40	\$ -
9	1 pc	Frt fog lamp cover LH <i>SVC</i>	Cracked		\$ 61.50	\$ X 61.50
10	1 pc	Frt fender LH <i>repair</i>	Dented		\$ 616.90	\$ X 616.90
11	1 pc	Frt fender cowl LH <i>No such item</i>	Torn/Deformed		\$ 169.20	\$ X 169.20
12	7 pcs	Frt fender cowl clip LH <i>item</i>	Necessary	\$ 3.20	\$ 22.40	\$ X 22.40
13	1 pc	Frt fender emblem (VVTi) LH	Necessary		\$ 41.70	\$ / 41.70
14	1 pc	Frt shock absorber RH	Bent/Jammed		\$ 393.70 <i>235.2</i>	\$ / 393.70
15	1 pc	Frt wheel hub RH	Warped		\$ 214.00	\$ / 214.00
16	1 pc	Frt wheel bearing RH	Necessary		\$ 101.70 <i>130.9</i>	\$ / 101.70
17	1 pc	Frt knuckle arm RH	Bent		\$ 478.10	\$ / 478.10
18	1 pc	Frt lower ball joint RH <i>SVC</i>	Bent		\$ 215.80	\$ X 215.80
19	1 pc	Frt lower arm RH	Bent		\$ 602.10 <i>371.8</i>	\$ / 602.10
20	1 pc	Bonnet	Dented/Repair			(Refer labour no. 4 & 5)
21	1 pc	Frt support panel	Dented/Repair			(Refer labour no. 4 & 5)
					\$ 5,166.50	\$ 4,285.10
					Less Discount : 25%	25%
					\$ 1,291.63	\$ 1,071.28
					List Parts Sub-Total :	\$ 3,874.88
						\$ 3,213.83
1	1 pc	Frt alloy rim RH	Dented/Defaced	S/N	\$ 300.00	\$ 300.00 <i>250</i>
2	1 pc	Frt tyre RH (Depreciate 10%)	Cut	S/N	\$ 250.00	\$ 225.00 <i>100</i>
3	1 bot	Brake fluid <i>SVC</i>	Necessary	S/N	\$ 20.00	\$ X 20.00
					Special Nett Sub-Total :	\$ 570.00
						\$ 545.00 <i>350</i>
					Parts Total :	\$ 4,444.88
						\$ 3,758.83



# PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simel St.3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pesvos@hotmail.com

Business Reg. 201404434D

Vehicle No. : SDN6064E

Report No. : PAS/TP/0261218

S/No.	Labour Descriptions	Repairer's Estimate (S\$)	Our Assessment (S\$)
1	To check electrical system and focus headlamp.	\$ 50.00	\$ / 30.00
2	To remove, check and replace RHF undercarriage parts. (Include flush and bleed brakes system)	\$ 220.00	\$ / 180.00
3	To conduct wheel alignment.	\$ 120.00	\$ <sup>60</sup> 120.00
4	To straighten, repair, realign on affected area and replace damaged parts.	\$ 1,000.00	\$ <sup>600</sup> 660.00
5	To spray painting, blending on affected and adjacent area.	\$ 1,000.00	\$ <sup>400</sup> 750.00
6	To spray anti-rust coating on new and affected panels.	\$ 50.00	\$ / 30.00
Labour Total :		\$ 2,440.00	\$ 1,770.00
Total (Parts & Labour) :		\$ 6,884.88	\$ 5,528.83

## For Lump Sum Repairs

The final adjusted Lump Sum contract amount is \$ 4,420.00

Under normal circumstances, the repairs should be completed within a reasonable period of 6 Working Days. (Exclude waiting days of PRI, Sunday, Public Holiday and awaiting of shipment for spare parts)

44 Photographs were taken at the time of inspection.

**I.B:** By accepting to carry out the repairs on a contract Lump Sum basis, the repairer shall has the prerogative and discretion to replace the damaged parts with new, used, OEM or reconditioned parts and/or to repair the vehicle on a roadworthy condition to the entire satisfaction of owner.

3249.18

20% : 2600

5 Days



**FINAL REPAIR BILL**

**WEE HOE AUTO SERVICE**

Business Reg No: 32889700X  
19 Kim Chuan Terrace Singapore 537041  
Tel: 6858 0019 Fax: 6858 6470 Tow: 9666 5566

**MSIG Insurance (Singapore) Pte. Ltd.**  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

Attn: Motor Claims Department

Invoice No: WA19-005

Claims No: T/P Claim

Date: 2-Feb-19

Our Car No: SDN6064E

Your Car No: SDG9978K

**Description**

**Amount (S\$)**

Supply of parts, labour charges and spray painting

4,420.00

**Total:**

**Singapore Dollars Four Thousand Four Hundred Twenty**

4,420.00

Crossed cheques should be made payable to "Wee Auto Service" and  
mailed to 19 Kim Chuan Terrace S(537041)

**WEE AUTO SERVICE**

Business Regn: 53206799A

19 Kim Chuan Terrace

Singapore 537041

Tel: 6858 0019

  
\_\_\_\_\_  
Authorised signatory

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Information	
Owner ID Type:	Business
Owner ID:	3000K
Vehicle Details	
Vehicle No.:	SDN6064E
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Dec 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	3ZZ4937196
Chassis No.:	MR053ZEE106156613
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$17,853.00
Original Registration Date:	15 Oct 2009
First Registration Date:	15 Oct 2009
Transfer Count:	1
Actual ARF Paid:	\$17,853.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Oct 2019
PARF Rebate Amount:	\$8,926.00
Intended COE Rebate Details	
COE Expiry Date:	14 Oct 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$16,201.00
COE Rebate Amount:	\$1,354.00
<b>Total Rebate Amount:</b>	<b>\$10,280.00</b>

The information contained herein is correct as at 13 Dec 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	10/12/2018 10:01
Date Of Accident	10/12/2018 08:20
Exact Location Of Accident	HOLLAND RD NEAR ESSO
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDN6064E
<b>Insured/Policyholder</b>	
Name Of Registered Owner	MOO AUTO
Co Reg No	53373000K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-90088701

### Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS 1.6 AUTO
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5097144301
Cover Note Number	-

### Driver

Name of Driver	LEW FAN JONG
NRIC No	S7001624I
Date Of Birth	18/01/1970
Occupation	OUTDOOR
Date Of Driving Pass	27/05/1993
Driving Experience	25 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97558835
Fax Number	
Contact Number	

Address	BLK 353 BUKIT BATOK ST 34 #03-150
Postcode	650353
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	
	NAME: : SOPHIA LEE SOK FUN
	GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

Sequence of events as follow: 1. I have been on first lane of Holland road towards Holland Flyover direction since junction of Holland road and North Buona Vista road ; 2. When approaching Esso station, I noticed from rear mirror SDG9978K (Car B) driving fast from 2nd lane; 3. I also noticed there was a Car X (red or orange) on 2nd lane which was ahead of Car B and has a 1.5 to 2 car length gap from me on first lane; 4. When approaching before the bend around traffic light at junction of Holland Road and Belmont Road, I noticed Car B is almost side by side with me due to the fast speed which I reckon the speed should be in excess of 60km road limit; 5. Car B did not reduce speed to maintain a safe distance from Car X and within split of second suddenly force cut into my lane without ensuring is safe to do so; 6. From the Speed Car B traveled and has no intention to reduce speed, I think Car B is trying to avoid collided with Car X and don't intend to apply hard braking due to the fast speed and decided to cut into my lane without ensuring is safe to do so; 6. From the picture of both damage car, is clear that Car B did not maintain safety gap yet still decided to force its way cut into my lane without considering the safety of my car and passengers and caused damages to my car by forcing my car swaying to the right and resulting in right wheel mounting to the kerb yet still cannot avoid left front bumper being pull off by Car B right rear wheel arch garnish. Appreciate you can update the report accordingly and do not hesitate to contact me should you need clarification.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SDG9978K
Vehicle Make/Model/Colour	
Details Of Properties	

NRIC/Passport Number S8007043H

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

## Accident Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by The General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/email packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Insurer's Stamp  
Date & Time

Driver's Signature  
(If driver is not the policyholder)  
Date & Time

Reporting Centre Personnel's Signature  
Name  
Title/File No.

# Accident Sketch Plan

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please Refer to Statement

## DECLARATION

I/We declare that the foregoing particulars are true in every respect



1. Policyholder's Signature  
2. Date & Time

*[Signature]*

Driver's Signature  
(If driver is not the policyholder)  
Date & Time

*[Signature]*

Reporting Centre Personnel's Signature  
Name  
NRIC/ID No.

Accident Photo





Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



## Addendum Sheet



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE**  
 9 Raffles Quay #18-00 Singapore 048580  
 Tel: (65) 6224 0010 Fax: (65) 6224 0030  
 Operating Hours: Monday to Friday, 09:00 - 17:00  
 UEN: S46500380 / GST Reg. No.: S4600017705

**IMPORTANT NOTE:** Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

### ADDENDUM

**(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:**

Original Report No: 201411150027 Vehicle Registration No: SDN60170  
 Name (as shown on NRIC): LEE KAY HONG NRIC/FIN/Passport No: S7011141  
 (\* Vehicle Driver / Vehicle Owner) [\*] Please delete as appropriate  
 Address: 11A Hill Street, #11-01, Hill Street, Singapore 058111 Singapore: 058111  
 Contact (Tel): \_\_\_\_\_ Mobile No.: 97981112  
 Email Address: \_\_\_\_\_  
 Date of Accident: 11/11/14 Time of Accident: 11:10  
 Place of Accident: 11A Hill Street, #11-01, Hill Street, Singapore 058111  
 Insurance Company: MSA

**(B) ADDITIONAL INFORMATION / AMENDMENTS:**

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

1. A statement of damage to my car was made.  
2. No further.

	<input checked="" type="checkbox"/>	<u>MOTORIST</u>
	<input checked="" type="checkbox"/>	<u>WITNESS</u>
<u>A - SANGHVI</u>	<input checked="" type="checkbox"/>	
<u>B - SONGHVI</u>	<input checked="" type="checkbox"/>	

Policyholder / Driver's Signature  
 Date: 11/11/14

Reporting Centre Personnel's Signature  
 Name: \_\_\_\_\_  
 NRIC/FIN No.: \_\_\_\_\_  
 Date: \_\_\_\_\_

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	11/12/2018 12:50
Date Of Accident	10/12/2018 08:15
Exact Location Of Accident	ALONG HOLLAND ROAD OUTSIDE BELMONT ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDG9978K
<b>Insured/Policyholder</b>	
Name Of Registered Owner	KHOR POH HWA
Co Reg No	-
Email Address	THIOCHRISTINA@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96550507
Alternative Phone No	Office-96550507

### **Vehicle Particulars**

Manufacturer	NISSAN
Model	QASHQAI
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE

Are you claiming under your own insurance policy for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

PRIVATE CAR

### **Insurance Company**

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A 28827818 QMY
Cover Note Number	

### **Driver**

Name of Driver	THIO SHU-MAN CHRISTINA
NRIC No	S8007043H
Date Of Birth	14/03/1980
Occupation	INDOOR
Date Of Driving Pass	18/08/2006

Driving Experience	12 YEARS AND 3 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96550507
Fax Number	
Contact Number	
EMail Address	THIOCHRISTINA@GMAIL.COM
Address	30 MOUNT ELIZABETH #02-32
Postcode	228519
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - DAUGHTER IN LAW
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SDN6064E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR



Name of Driver	LEW FAN JONG
NRIC/Passport Number	S7001624I
Contact Number	97558835
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

## Accident Sketch Plan

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
  - (ii) for complying with requirements under any regulations, laws or court orders

Policyholder's Signature  
Date & Time

Driver's Signature  
(If driver is not the policyholder)  
Date & Time

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No:

*[Signature]*

11 DEC 2018

*[Signature]*

11/12/2018

*[Signature]*

# Accident Sketch Plan

## SKETCH PLAN

ALONG HONARD ROAD UNSIDE BELMONT ROAD

A) SDG 992K

B) SDN 6064 E



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Along Honard Road, at the traffic intersection turning into Belmont Road, I was on the centre lane, filtering into the outer lane. Gave the right signal and attended across. Out of a sudden, there was a hit onto my car's right back bumper.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

11 DEC 2018

11/12/2018

11/12/2018

ID

Accident Photo



Accident Photo



Accident Photo





Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





Accident Photo



**Accident Photo**



Accident Photo



Accident Photo



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Dec 2018		11 Dec 2018 14:28 <a href="#">Edit Adj Rpt</a>	<b>S\$2,600.00</b> <a href="#">Edit Estimates</a>	<b>S\$2,600.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by Insurer]</span>									
Insured: <b>Khor Poh Hwa</b> , ID: S18520848									
Main Claimant: <b>MOO AUTO</b> , Co. Reg. No.: 53373000K									
Vehicle Reg. No.:	<b>SDN6064E</b>	Date of Loss:	10/12/2018 08:00 - :59 [109 Months and 25 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 578450</b>	Policy/Cover Note No.:	26827818QMY (Comprehensive) Coverage: 23/10/2018 - 22/10/2019						
Vehicle Reg. No. (Insured):	<b>SDG9978K</b>	Policy No. (Claimant):							
		Excess:							
Repairer: <b>Wee Hoe Auto Service (HQ)</b> 19 Kim Chuan Terrace, Singapore 537041, 537041 Kaki Bukit - Tel: 68580019									
Handling Insurer: <b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Monica Chung Pei Zhen</b> - 6594 2552]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... [Final Rpt due 07/10/2019]									
Adj Asg. Remarks: sje disagree appoint lkk. Liability (Non-reporting) pls contact Kiat @ 6858 0019									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
• MSIG_SG (03/10/2019): Report Send Back Alerts - SDN6064E (TP)									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SDN6064E (578450)  
[SDG9978K]  
TP  
MOO AUTO  
Dec 10 2018 8:00AM  
[Khor Poh Hwa]  
Wee Hoe Auto Service

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Assessment Reports

1 per page

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	17/01/19 09:34	<b>Accident Statement</b> <small>From: SC - Reg. No: SOG9978K, Claimant: KHOR POH HWA</small>	<div>1</div> <div>Load HTM</div>	

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/12/18 14:08	General View	<div>1</div> <div>Load JPG</div>	<div></div>
2	17/12/18 14:08	General View	<div>1</div> <div>Load JPG</div>	<div></div>
3	17/12/18 14:08	General View	<div>1</div> <div>Load JPG</div>	<div></div>
4	17/12/18 14:08	General View	<div>1</div> <div>Load JPG</div>	<div></div>
5	17/12/18 14:08	General View	<div>1</div> <div>Load JPG</div>	<div></div>
6	17/12/18 14:08	General View	<div>1</div> <div>Load JPG</div>	<div></div>
7	17/12/18 14:08	General View	<div>1</div> <div>Load JPG</div>	<div></div>
8	17/12/18 14:08	General View	<div>1</div> <div>Load JPG</div>	<div></div>
9	17/12/18 14:08	General View	<div>1</div> <div>Load JPG</div>	<div></div>
10	17/12/18 14:08	General View	<div>1</div> <div>Load JPG</div>	<div></div>
11	17/12/18 14:08	General View	<div>1</div> <div>Load JPG</div>	<div></div>
12	17/12/18 14:08	General View	<div>1</div> <div>Load JPG</div>	<div></div>
13	17/12/18 14:08	General View	<div>1</div> <div>Load JPG</div>	<div></div>
14	17/12/18 14:08	General View	<div>1</div> <div>Load JPG</div>	<div></div>
15	17/12/18 14:08	General View	<div>1</div> <div>Load JPG</div>	<div></div>
16	17/12/18 14:08	General View	<div>1</div> <div>Load JPG</div>	<div></div>
17	17/12/18 14:08	General View	<div>1</div> <div>Load JPG</div>	<div></div>
18	17/12/18 14:08	General View	<div>1</div> <div>Load JPG</div>	<div></div>
19	17/12/18 14:08	General View	<div>1</div> <div>Load JPG</div>	<div></div>
20	17/12/18 14:08	General View	<div>1</div> <div>Load JPG</div>	<div></div>
21	17/12/18 14:08	General View	<div>1</div> <div>Load JPG</div>	<div></div>
22	17/12/18 14:08	General View	<div>1</div> <div>Load JPG</div>	<div></div>
23	17/12/18 14:08	General View	<div>1</div> <div>Load JPG</div>	<div></div>
24	17/12/18 14:08	General View	<div>1</div> <div>Load JPG</div>	<div></div>
25	17/12/18 14:08	General View	<div>1</div> <div>Load JPG</div>	<div></div>
26	17/12/18 14:08	General View	<div>1</div> <div>Load JPG</div>	<div></div>
27	17/12/18 14:08	General View	<div>1</div> <div>Load JPG</div>	<div></div>
28	17/12/18 14:08	General View	<div>1</div> <div>Load JPG</div>	<div></div>
29	17/12/18 14:08	General View	<div>1</div> <div>Load JPG</div>	<div></div>
30	17/12/18 14:08	General View	<div>1</div> <div>Load JPG</div>	<div></div>
31	17/12/18 14:08	General View	<div>1</div> <div>Load JPG</div>	<div></div>
32	17/12/18 14:08	General View	<div>1</div> <div>Load JPG</div>	<div></div>
33	17/12/18 14:08	General View	<div>1</div> <div>Load JPG</div>	<div></div>
34	17/12/18 14:08	General View	<div>1</div> <div>Load JPG</div>	<div></div>
35	17/12/18 14:09	Photographs of Damaged Parts	<div>1</div> <div>Load JPG</div>	<div></div>
36	17/12/18 14:09	Photographs of Damaged Parts	<div>1</div> <div>Load JPG</div>	<div></div>
37	17/12/18 14:09	Photographs of Damaged Parts	<div>1</div> <div>Load JPG</div>	<div></div>
38	17/12/18 14:09	Photographs of Damaged Parts	<div>1</div> <div>Load JPG</div>	<div></div>
39	17/12/18 14:09	Photographs of Damaged Parts	<div>1</div> <div>Load JPG</div>	<div></div>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
40	17/12/18 14:09	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
41	17/12/18 14:09	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
42	17/12/18 14:09	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
43	17/12/18 14:09	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
44	17/12/18 14:09	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
45	17/12/18 14:09	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
46	17/12/18 14:09	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
47	17/12/18 14:09	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
48	17/12/18 14:09	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
49	17/12/18 14:09	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
50	17/12/18 14:09	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
51	17/12/18 14:09	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
52	17/12/18 14:09	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
53	17/12/18 14:09	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
54	17/12/18 14:09	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
55	17/12/18 14:09	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
56	17/12/18 14:09	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
57	17/12/18 14:09	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
58	17/12/18 14:09	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
59	17/12/18 14:09	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
60	17/12/18 14:09	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	11/12/18 14:22	WORKSHOP DETAILS		<input type="checkbox"/>
2	11/12/18 14:22	REJECT SURVEYOR LIST GIVEN BY LAWYER		<input type="checkbox"/>
3	11/12/18 14:22	PRI		<input type="checkbox"/>
4	11/12/18 14:22	sje disagree appoint lkk		<input type="checkbox"/>
5	03/10/19 10:09	SURVEY REPORT & REPAIR BILL		<input type="checkbox"/>
6	03/10/19 10:09	SURVEY PHOTOS1		<input type="checkbox"/>
7	03/10/19 10:11	SDN6064E		<input type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	22/10/19 10:34	Colour Photo		<input type="checkbox"/>
2	22/10/19 10:34	PRS Invoice		<input type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<div> Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div> ^ v </div> </div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18022277/GYD3E2-1

Date: 22/10/2019

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28827818QMY

Claimant Vehicle No: SDN6064E

Insured Vehicle No: SDG9978K

Date of Loss: 10/12/2018

Nature of Claim: TP

Claim No: 578450

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SDN6064E

Make &amp; Model: TOYOTA COROLLA ALTIS, 1.6 (A)

Engine No: 3ZZ4937196

Reg. Date: 15/10/2009 (Man. Year: 2009)

Chassis No: MR053ZEE106156613

Colour: Silver

Odometer: 242056 km

Engine Capacity: 1598 cc

Market Value/New Car

N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size:

195/65 R15

Front Left Side: Linglong 5 mm

Rear Left Side:

Linglong 5 mm

Front Right Side: Linglong 5 mm

Rear Right Side:

Linglong 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,444.87	2,149.17	2,295.70	51.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,440.00	1,100.00	1,340.00	54.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,884.87</b>	<b>3,249.17</b>	<b>3,635.70</b>	<b>52.81</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,600.00</b>		
<b>Nett Amount (S\$)</b>	<b>6,884.87</b>	<b>2,600.00</b>	<b>4,284.87</b>	<b>62.24</b>

## INSPECTION

Date of Assignment: 11/12/2018

Date Inspected: 12/12/2018 Inspected At:

Wee Hoe Auto Service (HQ)

19 Kim Chuan Terrace, Singapore

537041

Singapore 537041

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 22 Oct 2019)
<b>Parts:</b>	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SDN6064E)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP LH	Defaced / Loop Broken	708.40 FL	*445.20 FL
2	1		*FRT BUMPER	Dented	458.40 FL	*458.40 FL
3	1		*FRT GRILLE	Serviceable	301.90 FL	*- FL
4	1		*FRT GRILLE EMBLEM	Necessary	71.00 FL	*71.00 FL
5	1		*FRT BUMPER REINFORCEMENT	Serviceable	341.10 FL	*- FL
6	6		*FRT BUMPER CLIP	Necessary	21.00 FL	*21.00 FL
7	1		*FRT BUMPER RETAINER R/L	N/S Deformed / O/S Serviceable	109.20 FL	*45.60 FL
8	1		*FRT FOG LAMP LH	Serviceable	238.40 FL	*- FL
9	1		*FRT FOG LAMP COVER LH	Serviceable	61.50 FL	*- FL
10	1		*FRT FENDER LH	Repair	616.90 FL	*- FL
11	1		*FRT FENDER COWLING LH	No such part	169.20 FL	*- FL
12	7		*FRT FENDER COWLING CLIP LH	No such part	22.40 FL	*- FL
13	1		*FRT FENDER EMBLEM (VVTI) LH	Necessary	41.70 FL	*41.70 FL
14	1		*FRT SHOCK ABSORBER RH	Bent / Jammed	393.70 FL	*335.20 FL
15	1		*FRT WHEEL HUB RH }	Warped	214.00 FL	*130.90 FL
16	1		*FRT WHEEL BEARING RH }	Necessary	101.70 FL	*- FL
17	1		*FRT KNUCKLE ARM RH	Bent	478.10 FL	*478.10 FL
18	1		*FRT LOWER BALL JOINT RH	Serviceable	215.80 FL	*- FL
19	1		*FRT LOWER ARM RH	Bent	602.10 FL	*371.80 FL
20	1		*BONNET (NPA)	Repair	0.00 FL	*- FL
21	1		*FRT SUPPORT PANEL (NPA)	Repair	0.00 FL	*- FL
22	1		*FRT ALLOY RIM RH	Dented / Defaced	300.00 FS	*250.00 FS
23	1		*FRT TYRE RH	Cut	250.00 FS	*100.00 FS
24	1		*BOT BRAKE FLUID	Serviceable	20.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)    **5,736.50    2,748.90**

- List Item Discount on L Items 25.00/25.00% (\$\$)    1,291.63    599.73

Total Parts (\$\$)    **4,444.87    2,149.17**

Report was unsubmitted during this print-out.
-----------------------------------------------

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK ELECTRICAL SYSTEM AND FOCUS HEADLAMP	New	50.00	30.00
2	TO REMOVE, CHECK AND REPLACE RHF UNDERCARRIAGE PARTS. (INCLUDE FLUSH AND BLEED BRAKES SYSTEM)	New	220.00	180.00
3	TO CONDUCT WHEEL ALIGNMENT	New	120.00	60.00
4	TO STRAIGHTEN, REPAIR, REALIGN ON AFFECTED AREA AND REPLACE DAMAGED PARTS	New	1,000.00	400.00
5	TO SPRAY PAINTING, BLENDING ON AFFECTED AND ADJACENT AREA	New	1,000.00	400.00
6	TO SPRAY ANTI-RUST COATING ON NEW AND AFFECTED PANELS	New	50.00	30.00
Gross Labour Cost (S\$)			2,440.00	1,100.00

Report was unsubmitted during this print-out.

&lt; END OF ESTIMATES &gt;