

ASS. REC. BY:

REF:

CS/AIG19017510/Uq36

Special Instruction:

Surveyor *
Mehmet

marcus

ASSIGNMENT (Office)

From (Person):

Perthiban theerthan

of

AIG

Date/Time:

4/10/19 @ 9.30am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBF 5092X

Insured:

SKN 9902J

at Workshop m/s

Eun Success

Tel:

9828 9277

of

1 Leaki Bukit Ave 6 # 02-03 Autobuy

Policy No:

Claim No:

273234806655

Sum Insured:

Excess:

Make of Veh:

D.O.A.

2/10/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10am @ 4/10/19

Person Contacted:

Ah Hwat

Vehicle-IN (OUT)

Date/Time

Action/Instruction (✓) Estimate

SKN 9902J : X

FBF 5092X : X

9/10/19-
10.05pm.

checked with Ah Hwat, He said want to go by lawyer which is (wp).

(08/11/13) wef

REF:

AIW/

ASS. REC. BY: MAR 26/13

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: FBF5092X
 at Workshop m/s Euro Services
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: FBF5092X Yr Regn: 8, 11
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Yamaha X-1R c.c 135
 Colour multi colour A/C: Insured / Std / NI / NA
 Sp. Reading 67784 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: 453304610
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 80-90-17
 R: 90-80-17
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front R/Bal. 6 mm Rear 6 mm
 L/Bal. mm L/Bal. mm
 D.O.A. 2/10/19 D.O.I. 8/10/19
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
L1, 215304
 The UIC / Chassis frame / Body Structure affected due to collision.

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 2900 new 600
 IDAC Accident Rpt: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS L1A348
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Date / Time Action / Instruction

10/11/13 (see renew) 31-10-2019 #3836

16/10/19 confirmed 4/5 = 2500 with weijie (red \$ 4465.20, 64%)

RECEIVED 16 OCT 2019

Date/Time, File Pass to?

1) 16/10/19
 Date/Time, File Return to?

: Preli. Report
 : Final Report

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee: 290

Transportation:

Add Fee: : Site Insp (\$ _____)) S + RS, SI
 : Interview (\$ _____)) Photos
 : Tech. Invs (\$ _____)) Others
 : Weekend (\$ _____))

Report Format : MER-TP

Lump Sum / I.P.T. (\$ 2500)

TOTAL

<u>290</u>
<u>11</u>
<u>261</u>

PRE-REPAIR INSPECTION REQUEST – FBF5092X vs SKN9902J on 02.10.2019

From: Parthiban, Theerthan
To: assignments@lkkauto.com, Admin A
Cc: Fong, Andy-SY, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Hor, Yinrul, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Parthiban, Theerthan, Subran
Sent: 10/4/2019 9:28:58 AM
Attachments:  Euro Success - Pre-Repair Notice AIG FBF5092X.pdf

Hi,

Please refer to the enclosed request from **CrossBorders LLC**.
Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.
Kindly assist to assign **Marcus Chua** as Single Joint Expert as requested.

Thank you.

Regards,

Theerthan R Parthiban (Troy)
AIG
Senior Claims Examiner, Auto
Singapore Claims Operations | AIG Shared Services

Tel: 8001206556 Ext: 1002217
Theerthan.Parthiban@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Pam Cheong <pam@crossbordersllc.com>
Sent: Thursday, October 3, 2019 5:05 PM
To: Parthiban, Theerthan <Theerthan.Parthiban@aig.com>; Corene Chong <corene@crossbordersllc.com>; Tang Hui Ting <huiting@crossbordersllc.com>; Celeste Ng <celeste@crossbordersllc.com>
Cc: Fong, Andy-SY <Andy-SY.Fong@aig.com>; Chin, Lee-Ying <Lee-Ying.Chin@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Azlan, Syazairdina <Syazairdina.Azlan@aig.com>; Chan, Yoke Shi <yokeshi.chan@aig.com>; Hor, Yinrul <Yinrul.Hor@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>; Mithoosingh, Aashweenjeetkaur <Aashweenjeetkaur.Mithoosingh@aig.com>; Subramaniam, Divyashni <Divyashni.Subramaniam@aig.com>
Subject: [EXTERNAL] RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKN9902J AND FBF5092X (EURO) ON 02.10.2019

This message is from an external sender; be cautious with links and attachments.

Your attention is drawn to the CONFIDENTIALITY NOTICE below.

WITHOUT PREJUDICE

Dear Sirs

1. We refer to your email dated 3.10.2019.
2. We are instructed that our client has confirmed Marcus Chua-- LKK Auto Consultants Pte Ltd as a single joint expert.
3. Please be informed that the said vehicle can be inspected at:

Venue: Euro Success Serv Pte Ltd
Address: 1 Kaki Bukit Avenue 6
#02-03 Autobay @ Kaki Bukit
Singapore 417883
Contact: Ah Huat @ 6742 6231 / 9828 9277

4. Please liaise with the above workshop.

Regards

Pam

TEL: 6438 1323 ext 2020

CrossBorders LLC
133 New Bridge Road
#23-03/04/05 Chinatown Point
Singapore 059413
Tel: (65) 6438 1323
Fax: (65) 6438 2313

CONFIDENTIALITY NOTICE

This e-mail from CrossBorders LLC (including any attachment(s) to it) is confidential and may also be privileged and exempt from disclosure under applicable law. Accordingly, if you are not the intended recipient please notify us immediately, delete this e-mail (including any attachment to it) from your computer system and do not disclose or distribute it to any other person or continue to read this e-mail. Thank you.

CrossBorders LLC DOES NOT ACCEPT SERVICE OF COURT DOCUMENTS OR NOTICE OF ANY PROCEEDINGS BY FACSIMILE OR EMAIL

From: Parthiban, Theerthan <Theerthan.Parthiban@aig.com>

Sent: Thursday, October 3, 2019 4:42 PM

To: pam@crossbordersllc.com; corene@crossbordersllc.com; huiying@crossbordersllc.com; celeste@crossbordersllc.com

Cc: Fong, Andy-SY <Andy-SY.Fong@aig.com>; Chin, Lee-Ying <Lee-Ying.Chin@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Azlan, Syazairdina <Syazairdina.Azlan@aig.com>; Chan, Yoke Shi <yokeshi.chan@aig.com>; Hor, Yinrul <Yinrul.Hor@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>; Mithoosingh, Aashweenjeetkaur <Aashweenjeetkaur.Mithoosingh@aig.com>; Parthiban, Theerthan <Theerthan.Parthiban@aig.com>; Subramaniam, Divyashni <Divyashni.Subramaniam@aig.com>

Subject: aigencrypt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKN9902J AND FBF5092X ON 02.10.2019

Without Prejudice

Your Reference : AJ.tk.SH (EURO) (FBF5092X)

Our Reference : SKN9902J

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards,

Theerthan R Parthiban (Troy)

AIG

Senior Claims Examiner, Auto

Singapore Claims Operations | AIG Shared Services

Tel: 8001206556 Ext: 1002217

Theerthan.Parthiban@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Pam Cheong [<mailto:pam@crossbordersllc.com>]

Sent: Thursday, October 03, 2019 3:49 PM

To: AIG SGP, Claims-Survey

Cc: Corene Chong; Tang Hui Ting; Celeste Ng

Subject: [EXTERNAL] Re: Our client's vehicle no. FBF 5092X (Euro); Your insured's vehicle no. SKN 9902J - PRI

This message is from an external sender; be cautious with links and attachments.

Your attention is drawn to the CONFIDENTIALITY NOTICE below.

WITHOUT PREJUDICE,

Dear Sir/ Madam,

1. Please find attached our PRI notice dated 3 October 2019 for your kind attention.
2. Please reply email to corane@crossbordersllc.com & huiting@crossbordersllc.com & pam@crossbordersllc.com & celeste@crossbordersllc.com

With regards,

Pam

TEL: 6438 1323 ext 2020

CrossBorders LLC
133 New Bridge Road
#23-03/04/05 Chinatown Point
Singapore 059413
Tel: (65) 6438 1323
Fax: (65) 6438 2313

CONFIDENTIALITY NOTICE

This e-mail from CrossBorders LLC (including any attachment(s) to it) is confidential and may also be privileged and exempt from disclosure under applicable law. Accordingly, if you are not the intended recipient please notify us immediately, delete this e-mail (including any attachment to it) from your computer system and do not disclose or distribute it to any other person or continue to read this e-mail. Thank you.

CrossBorders LLC DOES NOT ACCEPT SERVICE OF COURT DOCUMENTS OR NOTICE OF ANY PROCEEDINGS BY FACSIMILE OR EMAIL

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

CROSSBORDERS LLC

Advocates & Solicitors | Commissioner for Oaths | Notary Public

Our Ref: AJ.tk.SH (EURO) (FBF5092X)
Your Ref: SKN9902J

3 October 2019

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#08-16 AIG Building
Singapore 079120
Attn: Motor Claims Department

URGENT

BY FAX: 6415 3727 & EMAIL

MAIN OFFICE
133 NEW BRIDGE ROAD
#23-03/04/05
CHINATOWN POINT
SINGAPORE 059413
TEL: 6438 1323
FAX: 6438 2313

BRANCH OFFICE
1 JALAN BERSEH
#03-12 NEW WORLD CENTR
SINGAPORE 209037

PLEASE SEND ALL
CORRESPONDENCES TO
THE MAIN OFFICE

WE DO NOT ACCEPT
SERVICE BY FAX

Dear Sirs

NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY
CLAIMANT: CHONG YIN FONG
TRAFFIC ACCIDENT ON 2 OCTOBER 2019 AT 21:10 HRS ALONG 271 TANJONG KATONG
ROAD OUTSIDE CALTEX INVOLVING VEHICLES NO. FBF5092X & SKN9902J

We are instructed by Chong Yin Fong to notify you of a road accident on 2 October 2019 at about 21:10 hrs along 271 Tanjong Katong Road outside Caltex involving our client's vehicle registration number FBF5092X and vehicle registration number SKN9902J driven by your insured at the material time. We will forward a copy of the Singapore accident statement/traffic police report filed in due course.


As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days (excluding any intervening Saturday, Sunday and Public Holiday) of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please be informed that the said vehicle can be inspected at:

Venue: Euro Success Serv Pte Ltd
Address: 1 Kaki Bukit Avenue 6
#02-03 Autobay @ Kaki Bukit
Singapore 417883
Contact: Ah Huat @ 6742 6231 / 9828 9277

Please liaise with the above workshop directly.

Yours faithfully


Crossborders LLC

Email: corene@crossbordersllc.com /
huiting@crossbordersllc.com

encs

PLEASE LET US KNOW THE DATE
OF THE PRE-REPAIR INSPECTION

.....

CONFIDENTIALITY CAUTION

THIS DOCUMENT IS FOR THE ADDRESSEE(S) ONLY AND MAY CONTAIN CONFIDENTIAL INFORMATION AND/OR MAY BE SUBJECT TO LEGAL PRIVILEGE. IF YOU HAVE RECEIVED THIS IN ERROR, PLEASE CONTACT US IMMEDIATELY.

CROSSBORDERS LLC

A LIMITED LIABILITY CORPORATION, REGISTRATION NUMBER 201305284K
GST REGISTRATION NUMBER 201305284K

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Foreign Identification Number
Owner ID:	182U
Vehicle Details	
Vehicle No.:	FBF5092X
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Oct 2019
Vehicle Make:	YAMAHA
Vehicle Model:	X-1R
Primary Colour:	Red
Manufacturing Year:	2011
Engine No.:	4S3304610
Chassis No.:	4S3304610
Maximum Power Output:	-
Open Market Value:	\$1,840.00
Original Registration Date:	12 Aug 2011
First Registration Date:	12 Aug 2011
Transfer Count:	1
Actual ARF Paid:	\$276.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	11 Aug 2021
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$1,890.00
COE Rebate Amount:	\$348.00
Total Rebate Amount:	\$348.00

The information contained herein is correct as at 08 Oct 2019

OK

Brand	Yamaha (/listing/usedbike/brand/yamaha/)
Model	Yamaha X1-R 135 (/listing/usedbike/model/yamaha-x1-r-135/)
Engine Capacity	135cc
Classification	Class 2B (/listing/usedbike/model/motorcycle-for-sale/class/class-2b/)
Registration Date	29/09/2009
COE Expiry Date	28/09/2024 (4 years 11 months left)
Mileage	-
No. of owners	-
Type of Vehicle	Cubs (/listing/usedbike/model/motorcycle-for-sale/cubs/)

Price: SGD\$3600

DETAILS

Tip Top Condition. COE till 28 Sep 2024. Original Parts. Visit Us At Aljunied Motor Works. Well Maintained Condition. Seldom Use, Trade In Welcome



INTRODUCING A PLAN TO GET THE COE YOU REALLY WANT.
All-New Mazda3 M-Hybrid [BOOK A TEST DRIVE](#)

The banner features a dark background with images of Mazda cars and the Mazda logo on the right. The text is white and includes a call to action to book a test drive.

SIMILAR BIKES

[VIEW ALL \(/LISTING/USEDBIKES/LISTING/\)](#)



Yamaha X1-R 135



Yamaha X1-R 135

[\(/listing/usedbike/yamaha-yamaha-x1-r-135/14400/\)](#)

[\(/listing/usedbike/yamaha-yamaha-x1-r-135/14509/\)](#)



Yamaha X1-R 135



Yamaha X1-R 135

Date of Accident: 02/10/2019 Accident Time: 2110 (24-HR-Format)

Accident Place: 271 Tanjong Katong Road outside Caltex

Vehicle No. (Car Plate No.): FBF5092X Make/Model: Yamaha FI 135

Insurance Company: MSIG Policy No: _____

Owner or Company Name / IC No.: CHONG YIN FONG F8335182U

Owner or Company Contact No.: 9102 0081 Owner's Hp _____ Company Tel _____

DRIVER'S Name / IC No.: CHONG YIN FONG F8335182U

DRIVER'S Date Of Birth: 12 Apr 1978 DRIVER'S License Pass Date 07 Dec 2017

Relationship of Owner & Driver: Spouse \ Parents \ Children \ Sibling \ Employee \ Others

DRIVER'S Address: Blk 20 Balam Rd #01-154 S(370020)

DRIVER'S Contact No. / Alt No.: 1) 9102 0081 2) _____

DRIVER'S Occupation: INDOOR \ OUTDOOR (e.g. working inside or outside office)

Email Address: kdctof32@gmail.com

Weather & Road Surface: CLEAR & DRY \ RAINING & WET \ AFTER RAIN & WET

Reporting Type: Reporting Only \ Claim Other Party \ Claim Own Insurance

Number of Passengers (Including Driver): 01

Was there any video Captured by car camera: YES \ NO

Exact purpose for which vehicle was being used at the time of accident: Private use \ Work purpose

Any Injury (If YES, Pls state): _____

Other Party Driver's Particular (if any)

Vehicle No: SKN9902J

Vehicle No: _____

Vehicle Make/Model: Mercedes - Benz

Vehicle Make/Model: _____

Name Driver: _____

Name Driver: _____


IC No. Driver/Contact: 8255 1794

IC No. Driver/Contact: _____

* NEW - Passenger's name & gender:

SKETCH PLAN 271 Tanjong Katong Road

427
023



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the above stated date and time, I was traveling along 271 Tanjong Katong Road. I was traveling straight when suddenly vehicle B came out from the side road and collided on to my vehicle front left portion, and due to the impact my bike fell on the right.

DECLARATION

We declare the foregoing particulars true in every respect.

Chong Yea T-00
Policyholder's Signature
Date & Time

Chong Yea T-00
Driver's Signature
If driver is not the policyholder
Date & Time

IDAC KAKI BUKIT (VA)
23 Kaki Bukit Ave 4
Reporting Centre, Singapore 415933
Tel: 67416697 Fax: 674923
Email: yackb@singnet.com

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	03/10/2019 15:10
Date Of Accident	02/10/2019 21:10
Exact Location Of Accident	271 TANJONG KATONG ROAD (OUTSIDE CALTEX)
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	FBF5092X
Insured/Policyholder	
Name Of Registered Owner	CHONG YIN FOO
Passport No/FIN	F8335182U
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91020081
Alternative Phone No	OFFICE-91020081
Vehicle Particulars	
Manufacturer	YAMAHA
Model	X-1R
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	MSCN: 60866220 (TPFT)
Cover Note Number	
Driver	
Name of Driver	CHONG YIN FOO
Passport No/FIN	F8335182U
Date Of Birth	12/04/1978
Occupation	OUTDOOR
Date Of Driving Pass	07/12/2017
Driving Experience	1 YEAR AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91020081
Fax Number	
Contact Number	OFFICE-91020081
EMail Address	NOEMAIL

Address	BLK 20 BALAM ROAD #01-154
Postcode	370020
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	AFTER RAIN
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKN9902J
Vehicle Make/Model/Colour	MERCEDES BENZ / S400L (R19 LED)
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	82551794
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insured companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the C.A. Roadside Management Centre established by the General Insurance Association of Singapore (GIAS) for archiving and that copies of this report will have to be made available upon application by interested parties.
7. By my lodgement of this report to the insurers, you hereby consent to the archiving of this report in the claims and insurance records being made available if needed.
8. **Consent under the Personal Data Protection Act (PDPA)**

I/We hereby acknowledge, agree and consent that:

- (a) My insurer, my working and the General Insurance Association of Singapore (GIAS) may be permitted to collect, use, disclose and/or process my personal data (personal information set out in this "form" and any other personal information provided by me or provided by my insurer) (collectively the "Personal Information") and disclose and make such Personal Information to all insurers who have insured vehicles involved in this accident (all insurers who have insured vehicles involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers, law firms, the Monetary Authority of Singapore and any relevant government agency/authority (collectively the "Purposes"):
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any ancillary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with the instructions or responding to any enquiries to me;
 - (iv) administering the claims (including the mailing of correspondence, statements, invoices, reports, notices to me which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law or administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) All Insurers who have insured vehicles involved in this accident and the Insurers' lawyers/law firms may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes.
- (c) My Personal Information may also be disclosed by any of the Insurers and/or link to their third party service providers/agents (including their lawyers/law firms) which may be used outside of Singapore, for one or more of the above Purposes.
- (d) My Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management, prevention and all future claims.
- (e) The information so collected, used and/or above may be shared, disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Chong Yen Too
Policyholder's Signature
Date & Time

7 OCT 2015




Chong Yen Too
Driver's Signature
(If driver is not the policyholder)
Date & Time

IDAC KAKI BUKIT (VAC)

Reporting Centre
23 Kaki Bukit Ave 4
Singapore 415933
Name
Tel: 67416697 Fax: 67492305
Email: yackb@singnet.com.sg

Sketch Plan #2



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the above stated date and time, I was traveling along 271 Tanjong Katong Road. I was traveling straight when suddenly vehicle B came out from the side road and collided on to my vehicle front left portion, and due to the impact my bike fell on the right.

DECLARATION

(I/We declare the foregoing particulars to be true in every respect)

Cheng Yin E-00
 Policyholder's Signature
 Date & Time - 3 OCT 2019

Cheng Yin E-00
 Driver's Signature
 (If driver is not the policyholder)
 Date & Time

IDAC KAKI BUKIT (VAC)
 23 Kaki Bukit Ave 4
 Singapore 415933
 Tel: 67416697 Fax: 67492305
 Email: vackb@singnet.com.sg

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Foreign Identification Number
Owner ID:	182U
Vehicle Details	
Vehicle No.:	FBF5092X
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Nov 2019
Vehicle Make:	YAMAHA
Vehicle Model:	X-1R
Primary Colour:	Red
Manufacturing Year:	2011
Engine No.:	4S3304610
Chassis No.:	4S3304610
Maximum Power Output:	-
Open Market Value:	\$1,840.00
Original Registration Date:	12 Aug 2011
First Registration Date:	12 Aug 2011
Transfer Count:	1
Actual ARF Paid:	\$276.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Oct 2029
COE Category:	D - Motorcycle
COE Period(Years):	10
PQP Paid:	\$3,838.00
COE Rebate Amount:	\$3,836.00
Total Rebate Amount:	\$3,836.00

The information contained herein is correct as at 15 Oct 2019

OK

EURO SUCCESS SERV PTE. LTD
Blk 1 Kaki Bukit 6, #02-03 Singapore 417883

TEL: 67426231 FAX: 67411019 H/P: 98289277 (AH HUAT)

Vehicle No: FBF5092X Model: YAHAMA X-1R

*not authorized
- 2500
1/3
8/10/18
take the other way
4 day.*

QTY	List Items	Price \$
1	Headlamp	scr 380.00 ✓
1	Headlamp top fairing	cut 105.00 ✓
1	Hadle bar bracket	scr 105.00 X
1	Handle bar	scr 120.00 X
2	R/H handle grips @28	17 56.00 X
1	R/H handle bar balancers @ 16	obs scr 32.00 100
1	R/H mirrors @65	obs scr 130.00 100
1	Rear R/H footrest stay rubber	17 32.00 X
1	Fairing	one 500.00 ✓
1	Front fender	scr 85.00 ✓
2	Front L-R fork assys @450	640 215 scr/17m 900.00 ✓
1	Front fork under bracket	17 355.00 ✓
1	Front fender	scr 95.00 X
1	Front sport wheel	17 225.00 X
1	Front sport wheel shaft	17 35.00 X
1	Front wheel bearing	17 40.00 X
1	Brake level	scr 45.00 ✓
1	Brake pedal	cut 95.00 ✓
1	Front footrest stay	scr 155.00 X
1	Front R/H foot rest stay rubbers @32	17 32.00 X
1	Gear pedal	17 85.00 X
1	Engine magnet cover	17 320.00 X
1	Front sport gear cover	17 90.00 X
1	Exhaust muffler	17 350.00 X
1	Exhaust muffler cover front	scr 85.00 ✓
1	Exhaust muffler cover rear	scr 120.00 ✓
1	Meter	one 450.00 ✓
1	Meter cover	scr 90.00 X
1	FRONT SIGNAL L-R @68	obs scr 136.00 100
1	BRAKE CALIPER	scr 180.00 X

Total \$5,428.00 P-2869
Less 10% \$542.80 102
Total \$4,885.20 2882.1

Special Nett Items		
1	Front tyre	17 150.00 X
1	Rear box bracket	scr 80.00 X
1	Rear box	scr 250.00 ✓
1	Engine oil	17 60.00 X
1set	Body sticker	17 120.00 X

\$660.00

Labour Charges

Transportation charges
To check front and rear electrical wiring
To remove, refix and realign front fork
To straighten, repair and realign chassis
frame member
To respray painting and etc
Panel beating, cut, weld remove and replacing
above parts

50.00 35
11 50.00 X
11 120.00 X
11 350.00 X
11 400.00 X
450.00 280

\$1,420.00 3147.1

ESTIMATE PARTS AND LABOUR CHANGES

\$6,965.20

LKK Auto Consultants hence notify
the Repairer of the following:

- * Repairs before/after spray painting
- * Repairs damages part(s) during resurvey
- * Parts subject to confirmation
- * Repairs on a "Without Prejudice" basis
- * Repairs (positions) is allowed
- * Repairs (items) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	09 Oct 2019 Edit Reg		04 Oct 2019 00:00 Edit Adj Rpt	S\$2,500.00 Edit Estimates	S\$2,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: DAIMLER FLEET MAANAGEMENT, Co. Reg. No.: -									
Main Claimant: CHONG YIN FOO, ID: F8335182U									
Vehicle Reg. No.:	FBF5092X	Date of Loss:	02/10/2019 21:00 - :59 [97 Months and 20 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 2732348066SG	Policy/Cover Note No.:							
Vehicle Reg. No. (Insured):	SKN9902J	Policy No. (Claimant):							
		Excess:							
Repairer: Euro Success Services Pte Ltd (HQ) 1 KAKI BUKIT AVENUE 6 #02-03 AUTOBAY, 417883 Kaki Bukit - Tel:									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 18/10/2019]									
ASSOCIATED MAIL RECEIVED				View All	Compose Case Mail				
<ul style="list-style-type: none"> AIG_SG (10/10/2019): No OI GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBF5092X (2732348066SG)
[SKN9902J]
TP
CHONG YIN FOO
Oct 2 2019 9:00PM
[DAIMLER FLEET MAANAGEMENT]
Euro Success Services Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View	View in Browser	
Photos/Images											3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print			
1	16/10/19 11:46	Odometer Reading							Load JPG	<input checked="" type="checkbox"/>		
2	16/10/19 11:46	General View							Load JPG	<input checked="" type="checkbox"/>		
3	16/10/19 11:46	General View							Load JPG	<input checked="" type="checkbox"/>		
4	16/10/19 11:46	General View							Load JPG	<input checked="" type="checkbox"/>		
5	16/10/19 11:46	General View							Load JPG	<input checked="" type="checkbox"/>		
6	16/10/19 11:46	General View							Load JPG	<input checked="" type="checkbox"/>		
7	16/10/19 11:46	General View							Load JPG	<input checked="" type="checkbox"/>		
8	16/10/19 11:46	General View							Load JPG	<input checked="" type="checkbox"/>		
9	16/10/19 11:46	General View							Load JPG	<input checked="" type="checkbox"/>		
10	16/10/19 11:46	General View							Load JPG	<input checked="" type="checkbox"/>		
11	16/10/19 11:46	General View							Load JPG	<input checked="" type="checkbox"/>		
12	16/10/19 11:46	General View							Load JPG	<input checked="" type="checkbox"/>		
13	16/10/19 11:46	General View							Load JPG	<input checked="" type="checkbox"/>		
14	16/10/19 11:46	General View							Load JPG	<input checked="" type="checkbox"/>		
15	16/10/19 11:46	General View							Load JPG	<input checked="" type="checkbox"/>		
16	16/10/19 11:46	General View							Load JPG	<input checked="" type="checkbox"/>		
17	16/10/19 11:46	General View							Load JPG	<input checked="" type="checkbox"/>		
18	16/10/19 11:46	General View							Load JPG	<input checked="" type="checkbox"/>		
19	16/10/19 11:46	General View							Load JPG	<input checked="" type="checkbox"/>		
20	16/10/19 11:46	General View							Load JPG	<input checked="" type="checkbox"/>		
21	16/10/19 11:46	General View							Load JPG	<input checked="" type="checkbox"/>		
22	16/10/19 11:46	General View							Load JPG	<input checked="" type="checkbox"/>		
23	16/10/19 11:46	General View							Load JPG	<input checked="" type="checkbox"/>		
24	16/10/19 11:46	General View							Load JPG	<input checked="" type="checkbox"/>		
25	16/10/19 11:46	General View							Load JPG	<input checked="" type="checkbox"/>		
26	16/10/19 11:46	General View							Load JPG	<input checked="" type="checkbox"/>		
27	16/10/19 11:46	General View							Load JPG	<input checked="" type="checkbox"/>		
28	16/10/19 11:46	General View							Load JPG	<input checked="" type="checkbox"/>		
29	16/10/19 11:46	General View							Load JPG	<input checked="" type="checkbox"/>		
30	16/10/19 11:46	General View							Load JPG	<input checked="" type="checkbox"/>		
31	16/10/19 11:46	General View							Load JPG	<input checked="" type="checkbox"/>		
32	16/10/19 11:46	General View							Load JPG	<input checked="" type="checkbox"/>		
33	16/10/19 11:46	General View							Load JPG	<input checked="" type="checkbox"/>		
34	16/10/19 11:46	General View							Load JPG	<input checked="" type="checkbox"/>		
35	16/10/19 11:46	General View							Load JPG	<input checked="" type="checkbox"/>		
36	16/10/19 11:46	General View							Load JPG	<input checked="" type="checkbox"/>		
37	16/10/19 11:46	General View							Load JPG	<input checked="" type="checkbox"/>		
38	16/10/19 11:46	General View							Load JPG	<input checked="" type="checkbox"/>		
39	16/10/19 11:46	General View							Load JPG	<input checked="" type="checkbox"/>		
40	16/10/19 11:46	General View							Load JPG	<input checked="" type="checkbox"/>		
41	16/10/19 11:46	General View							Load JPG	<input checked="" type="checkbox"/>		
42	16/10/19 11:46	General View							Load JPG	<input checked="" type="checkbox"/>		
43	16/10/19 11:46	General View							Load JPG	<input checked="" type="checkbox"/>		

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	16/10/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
45	16/10/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
46	16/10/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
47	16/10/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
48	16/10/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
49	16/10/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
50	16/10/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
51	16/10/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
52	16/10/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
53	16/10/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
54	16/10/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
55	16/10/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
56	16/10/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
57	16/10/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
58	16/10/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
59	16/10/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
60	16/10/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
61	16/10/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
62	16/10/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
63	16/10/19 11:46	General View	 Load JPG	<input checked="" type="checkbox"/>
64	16/10/19 11:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	16/10/19 11:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	16/10/19 11:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	16/10/19 11:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	16/10/19 11:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	16/10/19 11:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	16/10/19 11:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	16/10/19 11:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	16/10/19 11:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	16/10/19 11:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	16/10/19 11:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	16/10/19 11:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	16/10/19 11:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	16/10/19 11:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	16/10/19 11:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	16/10/19 11:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	16/10/19 11:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	16/10/19 11:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	16/10/19 11:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	16/10/19 11:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	16/10/19 11:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	16/10/19 11:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	16/10/19 11:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	16/10/19 11:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	16/10/19 11:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	16/10/19 11:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	16/10/19 11:47	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
91	16/10/19 11:47	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
92	16/10/19 11:47	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
93	16/10/19 11:47	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
94	16/10/19 11:47	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
95	16/10/19 11:47	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
96	16/10/19 11:47	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/10/19 13:14	TP GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG19017510/UQD3E2

Date: 16/10/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : FBF5092X

Insured Vehicle No : SKN9902J

Date of Loss: 02/10/2019

Nature of Claim: TP

Claim No: 2732348066SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBF5092X**

Make & Model: YAMAHA X-1R, 135cc (M)

Engine No: 4S3304610

Reg. Date: 12/08/2011 (Man. Year: 2011)

Chassis No: 4S3304610

Colour: Multi-colour

Odometer: 67784 km

Engine Capacity: 135 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 80-90-17

Rear Tyre Size: 90-80-17

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,545.20	2,832.10	2,713.10	48.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,420.00	315.00	1,105.00	77.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,965.20	3,147.10	3,818.10	54.82
Approved Total (Overridden) (S\$)		2,500.00		
Nett Amount (S\$)	6,965.20	2,500.00	4,465.20	64.11

INSPECTION

Date of Assignment: 04/10/2019

Date Inspected: 08/10/2019 Inspected At:

Euro Success Services Pte Ltd (HQ)

1 KAKI BUKIT AVENUE 6 #02-03

AUTOBAY

Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP	Scratched	380.00 FL	*380.00 FL
2	1		*HEADLAMP TOP FAIRING	Cut	105.00 FL	*105.00 FL
3	1		*HANDLE BAR BRACKET	Serviceable	105.00 FL	*- FL
4	1		*HANDLE BAR	Serviceable	120.00 FL	*- FL
5	2		*R/H HANDLE GRIPS	Not Necessary	56.00 FL	*- FL
6	1		*R/H HANDLE BAR BALANCERS	O/S Scratched	32.00 FL	*16.00 FL
7	1		*R/H MIRRORS	O/S Scratched	130.00 FL	*65.00 FL
8	1		*REAR R/H FOOTREST STAY RUBBER	Not Necessary	32.00 FL	*- FL
9	1		*FAIRING	Cracked	500.00 FL	*500.00 FL
10	1		*FRONT FENDER	Scratched	85.00 FL	*85.00 FL
11	2		*FRONT L-R FORK ASSYS	Bent / Twisted	900.00 FL	*640.00 FL
12	1		*FRONT FORK UNDER BRACKET	Twisted	355.00 FL	*215.00 FL
13	1		*FRONT FENDER	Repeated	95.00 FL	*- FL
14	1		*FRONT SPORT WHEEL	Repair	225.00 FL	*- FL
15	1		*FRONT SPORT WHEEL SHAFT	Not Necessary	35.00 FL	*- FL
16	1		*FRONT WHEEL BEARING	Not Necessary	40.00 FL	*- FL
17	1		*BRAKE LEVEL	Scratched	45.00 FL	*45.00 FL
18	1		*BRAKE PEDAL	Cut	95.00 FL	*95.00 FL
19	1		*FRONT FOOTREST STAY	Serviceable	155.00 FL	*- FL
20	1		*FRONT R/H FOOT REST STAY RUBBERS	Not Necessary	32.00 FL	*- FL
21	1		*GEAR PEDAL	Not Necessary	85.00 FL	*- FL
22	1		*ENGINE MAGNET COVER	Not Necessary	320.00 FL	*- FL
23	1		*FRONT SPORT GEAR COVER	Not Necessary	90.00 FL	*- FL
24	1		*EXHAUST MUFFLER	Repair	350.00 FL	*- FL
25	1		*EXHAUST MUFFLER COVER FRONT	Scratched	85.00 FL	*85.00 FL
26	1		*EXHAUST MUFFLER COVER REAR	Scratched	120.00 FL	*120.00 FL
27	1		*METER	Cracked	450.00 FL	*450.00 FL
28	1		*METER COVER	Serviceable	90.00 FL	*- FL
29	1		*FRONT SIGNAL L-R	O/S Scratched	136.00 FL	*68.00 FL
30	1		*BRAKE CALIPER	Serviceable	180.00 FL	*- FL
31	1		*FRONT TYRE	Not Necessary	150.00 FS	*- FS
32	1		*REAR BOX BRACKET	Serviceable	80.00 FS	*- FS
33	1		*REAR BOX	Grazed	250.00 FS	*250.00 FS
34	1		*ENGINE OIL	Not Necessary	60.00 FS	*- FS
35	1		*SET BODY STICKER	Not Necessary	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,088.00	3,119.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	542.80	286.90
Total Parts (\$\$)	5,545.20	2,832.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TRANSPORTATION CHARGES	New	50.00	35.00
2	TO CHECK FRONT AND REAR ELECTRICAL WIRING	New	50.00	0.00
3	TO REMOVE, REFIX AND REALIGN FRONT FORK	New	120.00	0.00
4	TO STRAIGHTEN, REPAIR AND REALIGN CHASSIS FRAME MEMBER	New	350.00	0.00
5	TO RESPRAY PAINTING AND ETC	New	400.00	0.00
6	PANEL BEATING, CUT, WELD REMOVE AND REPLACING ABOVE PARTS	New	450.00	280.00
Gross Labour Cost (\$\$)			1,420.00	315.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >