

15/01/2019

INS. CASE OWNER:

Lynthia

CC 4 ASM
AXA1901

7512

H 9/10/19

LKK:
IDAC:

Surveyor:

HOCK ANN

DOI:

9/10/19

Date / Time:

4/10/19

Registered in Merit:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHC 5570C

Name of Insured:

TRANS - OR SERVICES P/L

Insured Tel No.:

HP:

Excess Sec II :\$5

\$5000

D.O.A.:

1/10/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

WONG LITHUAN SHUN

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

SAMOYFE | 140472

Policy No.:

VFX | P1080520

Make / Model:

RENAULT

Place of Accident:

URSS CYED HWI RD

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SGP 4AT



INSRS:

WSP:

Tel:

Liability:

RMKS:

Triple T



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

SGP 4AT - SHC 5570C

STAGE

DATE / PIC

Non-Reporting 1st (1st):

Non-Reporting 1st (2nd):

Non-Reporting 1st (Final):

Notification 1st (if non-pickup):

Call OI:

After call 1st to OI:

Documentation Check List: Handler Typist

Notification 1st (if non-pickup)

After call 1st to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$5

\$600.00

(14

days)

Reduction:

1150.00

%

62

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

NIL

Repair Cost:

\$5

\$600.00

Loss of Rental (LOR):

\$5

-

(1

days)

Loss of Use (LOU):

\$5

\$420.00

(15

x 7

days)

Loss of Income (LOI):

\$5

-

(5

x

days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

\$5

7.45

Medical:

\$5

Disbursement:

\$5

(e.g. Tow/ Independent)

Legal Cost:

\$5

\$562.00

Total:

\$5

\$3529.45

Global Sum \$5:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$5

\$3529.45

Name 1:

Triple-T Automobile

Payee 2: (Strike if N.A.)

\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5

Name 3:

COPY SENT
30/11/20202 in amount different
in self lent amount.

REFERENCE

ASS. REC. BY:

REF: CS/ASM/19017512/Hcd3 Special Instruction:

Surveyor: Hock Ann

ASSIGNMENT (Office)

From (Person): Cynthia Kott of ASM (AXA) Date/Time: 4/10/2019

Estimated Cost: Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SGP 49T Insured: SHC 5570C

at Workshop m/s Triple-T Automobile Tel: 63851171

of Blk 5 Defu lane 10 # 01-574

Policy No: Claim No: S9M022FE

Sum Insured: Excess:

Make of Veh: D.O.A. 1/10/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: Person Contacted: Irene Vehicle: IN OUT

Date/Time	Action/Instruction
	Shimulig (X)
	SGP49T-X
	SHC 5570C - CS/190119017630/Ktd3 D.O.A: 1/10/2019

REF: 14-ANNN

REF: ASM(CAXA)

recall case

ASSIGNMENT

From: Date: 8/10/2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SGP 49T

at Workshop n/s Triple - T Automobile

of 25 Kaki Bukit Road 4 # 06. 46

Insured: synergy

Policy No.

Claims No.

Sum Insured Excess:

(Client's Record)

Make of Veh: 2pm (waiting)

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res: Yes or No

Lum. Sum: 70 % S Val: Yes or No

CA / REV / REP. / 24 HRS 14p

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SGP 49T Yr Regn: 10/04/2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: CHEVROLET ORLANDO cc 1362

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: P0289 km T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KL1YA7589HK 814352

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215 / 60 / R16

R: 215 / 60 / R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or First and Rear same Rad

Front R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 1/10/19 D.O.I. 7/10/17

Survey held at Triple - T

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	PLS obtain evidence such as Insured's CCTV-PIR
	Range - 3K - 4K
	repair days - 5 days
	mv - 67800
	pv - 51581
	nv - 16200
	46 \$2600 - (Red - \$4250.00)
	671.00
	mv - 66-67K
	* 4 repair days + 2 PRRs + 1 Sunday = 7 days.

SGP 49T
NON Estimate
(PRI case)
workshop repair 1
PRI

Date/Time, File Path to?	<input type="checkbox"/> : Prel. Report	Days Of Repair: 5	Survey Fee:
1) <input type="checkbox"/> : Final Report	Resurvey No. of Trip:	Transportation:	
Date/Time, File Path to?	Add Fee: <input type="checkbox"/> : Site Insp (\$)	3 - RS 31	
2) <input type="checkbox"/> : Interview (\$)	<input type="checkbox"/> : Tech. Insp (\$)	Time:	
	<input type="checkbox"/> : Material (\$)	Other:	
Report Format: PRS			
Long Sum / U/C: 12			

Our reference 20-01-9000

Date 3/1/2019

Page 2

Section A: Damaged Parts Assessment

Part's Description	Qty	Condition As inspected	Repairer's Estimate	Our Adjustment
--------------------	-----	------------------------	---------------------	----------------

List Items:

Rear bumper ✓ <i>CR</i>	1	deformed	785.40	785.40 685.40 ✓
Rear bumper lower lip ✓ <i>SR</i>	1	deformed	552.30	552.30 490.70 ✓
Rear bumper side retainer rear rh ✓ <i>CR</i>	1	damaged	65.00	65.00 48.00 ✓
Rear bumper side retainer front rh ✓ <i>CR</i>	1	damaged	55.00	58.00 48.00 ✓
Rear bumper reflector rh <i>X (CR)</i>	1	holder torn	75.00	75.00
Tail lamp rh ✓ <i>CR</i>	1	holder torn	412.00	412.00 ✓
Rear fender <i>X (R)</i>	1	repair.respray	952.00	0.00
Rear fender air vent rh <i>X (SR)</i>	1	deformed	102.30	102.30
Rear fender protector rh ✓ <i>SR</i>	1	grazed/cut	177.00	177.00 81.00 ✓
Rear fender splash shield rh <i>X (SR)</i>	1	damaged	121.00	121.00
Rear end panel <i>X (SR)</i>	1	repair	557.40	0.00
Rear wheel bearing rh ✓ <i>CR</i>	1	necessary	174.20	174.20 ✓
Sub- Total costs			4028.60	2519.20
Percentage discount : 10%			402.85	251.92
Sub-Total costs for parts			3625.74	2267.28

Special Nett Items:

Rear bumper clips ✓ <i>CR</i>	set	necessary	55.00	55.00 25 ✓
Rear reverse sensor ✓ <i>SR</i>	1	malfunction	280.00	280.00 200 ✓
Rear tyre rim rh <i>X (100% repair)</i>	1	repair	578.00	0.00 100 ✓
Sub-Total costs for parts			913.00	335.00

Parts Repair

			0.00	0.00
Sub- Total costs			0.00	0.00
Total costs for parts			4538.74	2602.28

Subsidiaries of Impact Analysis Consultant:

• Impact Analysis Consulting Pte Ltd • Impact Analysis Academy Pte Ltd • IA Racking Solutions Pte Ltd
• IA Accounting & Consultancy Pte Ltd • Infoknights International Services (Philippines) • IABN Pte Ltd
www.iaconsulting.sg

Our reference 20-01-9000

Date 3/1/2019

Page 3

Section B: Labour Cost Calculation

	Hourly rate	Manhr. Req.	Total
To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-mentioned on the 'Parts Repair' column inclusive of replacement parts.	\$ 48.00	23	\$ 1,104.00 500✓
Putty & Spray painting to adjacent panels. Job allowance. Paint / material.	Sub-contract work.		\$ 800.00 500✓
Apply rust proofing on the adjacent panels.	Sub-contract work.		\$ 50.00 30✓
Remove and refix rear undercarriage works rh	\$ 48.00	4	\$ 192.00 60✓
Remove and replace rear bumper reverse sensor & conduct distance safety setting.	\$ 48.00	1.7	\$ 81.60 20✓
Specialist charges - Wheel alignment	-	-	\$ 60.00 ✓
Wiring and bulb checking	\$ 48.00	0.5	\$ 24.00 30✓
Total labour cost			\$ 2,311.60

Manhour rate and the number of manhours required for each repairing task are formulated based on individual workshop's operating cost and in-house@ IA Research Guidelines respectively.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

paper survey 10.30h
12/3/20
without prejudice
running after part
4 day (1hr)
H-ANN
L/s repair

parts 1941.70

parts less 10%

1747.53

sep. out 325

labour 1200

3272.53

4/s less 20%

2618.02

total
L/s part
↓
\$ 2600

6850.74

Subsidiaries of Impact Analysis Consultant:

- Impact Analysis Consulting Pte Ltd • Impact Analysis Academy Pte Ltd • IA Racking Solutions Pte Ltd
- IA Accounting & Consultancy Pte Ltd • Infoknights International Services (Philippines) • IABN Pte Ltd

www.iaconsultingse.com

Our reference 20-01-9000
 Date 3/1/2019

Section C: Summary Table of Total Repair Cost

Description		Cost	
Damaged Parts Assessment (See section A)		\$2,602.28	
Further discount	20%	\$520.46	
Recommended cost of parts		\$2,081.82	(1)
Labour Cost Calculation (See section B)		\$2,311.60	(2)
Total Repair Cost (Round off to hundred)		\$4,300.00	(1) + (2)

We would recommend a sum of \$4,300.00 and 4 working days for repair.
 No further items will be approved without our expressed written agreement. Any significant additional items will be subject to a supplementary report.


 Mechanical Engineer, Accident Expert Witness, Licensed Appraiser (Automobile)
 B.Eng. (Hons, NUS)
 Diploma Mechanical Engineering
 NTC-2 Automovite Technology
 Sr.MIES, Institution of Engineers, Singapore (#20100091)
 MATAI, Maryland Association of Traffic Accident Investigators
 IAARS, International Association of Accident Reconstruction Specialists
 PMC of Singapore Business Advisors & Consultants Council
 ACTA certified Trainer, Singapore
 SPRING- Recognised Certification for Management Consultants

Subsidiaries of Impact Analysis Consultant:

• Impact Analysis Consulting Pte Ltd • Impact Analysis Academy Pte Ltd • IA Racking Solutions Pte Ltd
 • IA Accounting & Consultancy Pte Ltd • Infoknights International Services (Philippines) • IABN Pte Ltd
 www.iaconsulting.com

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	248I
Vehicle Details	
Vehicle No.:	SGP49T
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Oct 2019
Vehicle Make:	CHEVROLET
Vehicle Model:	ORLANDO 1.4AT TURBO
Primary Colour:	Black
Manufacturing Year:	2017
Engine No.:	B14NET170180094
Chassis No.:	KL1YA7589HK614352
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$15,807.00
Original Registration Date:	10 Apr 2017
First Registration Date:	10 Apr 2017
Transfer Count:	0
Actual ARF Paid:	\$15,807.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Apr 2027
PARF Rebate Amount:	\$11,855.00
Intended COE Rebate Details	
COE Expiry Date:	09 Apr 2027
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$53,001.00
COE Rebate Amount:	\$39,726.00
Total Rebate Amount:	\$51,581.00

The information contained herein is correct as at 11 Oct 2019

NOA = 1/10/19

OK

MV - 67800

PV - 51581

NV - 16200

MV - 66-67k

Balance - 7 year 6 months

Depreciation - 8000 year

$8000 \div 12 = 666$ months

$56000 + 7903 + 3996$

$= 67899$



Impact Analysis Consultant

Practicing Management Consultant (PMC) of SBACC
Approved Training Organisation (ATO) of Workforce Singapore

No.25 Kaki Bukit Road 4
#06-46 Synergy @KB
Singapore 417800
Hotline: 6385 1171

Our reference: 20-01-9000

Date: 3/1/2019

INVOICE NO. 9000

Ong Bin
c/o Triple-T Automobile
Blk 6 Defu Lane 10
#01- 556
Singapore 539187

Registration No. SGP49T

We enclose our fee note for your kind attention, which remains payable irrespective of the outcome of this case.

S/No.	Description of Services Provided	Qty	Amount
1	Being vehicle damage assessment report, inspection, photographs, transport and miscellaneous.	1	\$ 562.00
Total amount			<u>\$ 562.00</u>

Please kindly cross all cheques made payable to "Impact Analysis Consultant".

We thank you in anticipation for your prompt payment.

L. L. Tan (Ms)
Principal Consultant

paper survey nearby upheld
redu first page survey
and adjustment total
labor cost Amt
\$2600 4/5 uper
4 day
accition case#

Subsidiaries of Impact Analysis Consultant:

• Impact Analysis Consulting Pte Ltd • Impact Analysis Academy Pte Ltd • IA Racking Solutions Pte Ltd
• IA Accounting & Consultancy Pte Ltd • Infoknights International Services (Philippines) • IABN Pte Ltd
www.iaconsultingse.com

Our reference: 20-01-9000

Date: 3/1/2019

c/o Triple-T Automobile
Blk 6 Defu Lane 10
#01- 556
Singapore 539187

Dear Sirs

RE: Road Traffic Accident on 1/10/2019
Ong Bin

In accordance with your instructions received in this office on 27/12/2019, we made arrangements to examine the vehicle on 27/12/2019 at above-mentioned address. The following data was recorded:


Vehicle details

Make	Chevrolet	Registration	SGP49T
Model	Orlando	Chassis	KL1YA7589HK614352
Colour	Black	Gearbox	Auto
Odometer	87027km	Paintwork	Good
Steering	Good	Brakes	Good
Condition	Good		

Tyre Depths

Front left	215/60R16	85% Bridgestone
Front right	215/60R16	85% Bridgestone
Rear left	215/60R16	85% Bridgestone
Rear right	215/60R16	85% Bridgestone

Impact Direction & Area of Damage:



Status	REPAIRABLE
Magnitude	Medium
Legal status	Unroadworthy

Following our examination of the accident damage, we have calculated repair times and method, which are detailed on page 2 & 3. We would recommend a sum of \$4,300.00 and 6 working days for repair, which is sufficiently lower than the pre accident value to render the vehicle an economically and physically reliable proposition.

Subsidiaries of Impact Analysis Consultant:

• Impact Analysis Consulting Pte Ltd • Impact Analysis Academy Pte Ltd • IA Racking Solutions Pte Ltd
• IA Accounting & Consultancy Pte Ltd • Infoknights International Services (Philippines) • IABN Pte Ltd
www.laconsultingsg.com

⏪ Service Request Details

Claim

S9M022FE

Reference

None ✎

Loss Date

October 1, 2019

Report Date

Oct 4, 2019 11:17:00 AM

Request Date

October 4, 2019

Due Date

October 11, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

p: Irvin
T: 209 p.m
V: All
E: ✓

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SGP49T



Model

ORLANDO 1.4AT TURBO

Service Address

...

Primary Contact/Insured

TRANS-CAB SERVICES PTE LTD
No.2 ANG MO KIO STREET 63, 569111, Singapore

Claim Handler

LOH Cynthia
6568804843
cynthia.loh@axa.com.sg

Additional Instructions

5

Messages	Invoices	History	Documents	Assessment	Metrics	Notes
----------	----------	---------	-----------	------------	---------	-------

New Message

Summer Lee (LKK Auto)

From: Irene <motor@iaconsultingsg.com>
Sent: Friday, 4 October, 2019 10:32 AM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Cc: candy@iaconsultingsg.com
Subject: [EXTERNAL] ACCIDENT INVOLVING SGP49T AND SHC5570C ALONG JUNCTION OF SYED ALWI ROAD AND LAMPONG KAPOOR ON 01.10.2019
Attachments: doc00812720191004102223.pdf
Categories: Mateen

Dear Sir,

attached herewith the Notification Of Accident for your reference.

Kindly let us have a list of your ten surveyors as your nominated SJE for our consideration within the stipulated timeline under the NIMA Protocol.

Best Regards,
Irene Tan
Triple-T Automobile
Tel: 6385 1171



TRIPLE-T AUTOMOBILE

BLK 5 DEFU LANE 10 #01-574 SINGAPORE 539186

TEL: 6385 1171

Email: motor@tiaconsultingsg.com

Date: 4/10/19

To AXA INSURANCE SINGAPORE PTE LTD

Motor Claims Department

By fax only

8 SHENTON WAY #24-01

AXA TOWER SINGAPORE

Singapore 068811

Dear Sir/Mdm,

NOTIFICATION OF ACCIDENT

Please be informed that an accident involving my/our vehicle no. SGP49T and vehicle(s) no. SHC5570C had taken place at / along Junction of Syed Aliji Rd and Kampong Kapoor on date 1/10/2019 at time 2:35 HRS.

Kindly let us know within 2 working days from the date of this notice if you wish to carry out or waive a pre-repair inspection.

If we do not hear from you within 2 working days, we shall proceed to repair the vehicle without further notice and our client shall claim for the additional loss of use arising from the giving of this notification to you.

Please call Ms Tan at 98388224 to arrange.

Yours sincerely,

PRI

Date / Time	
Company Name	
Surveyor	
Contact No.	
Signature	

DISMANTLED PARTS

Date / Time	
Surveyor	

AFTER REPAIR

Date / Time	
Surveyor	

Enquire Vehicle Transfer Fee

Vehicle Details

Vehicle No: SGP49T	
Make / Model CHEVROLET / ORLANDO 1.4AT TURBO	
Vehicle Type: P11 - Passenger Station Wagon/Jeep/Land Rover	Vehicle Attachment 1: No Attachment
Vehicle Scheme: Normal	Chassis No.: KL1YA7589HK614352
Propellant: Petrol	Engine No.: 814NET170180094
Motor No.: -	Engine Capacity: 1362 cc
Power Rating: -	Maximum Power Output: 103.0 kW (138 bhp)
Maximum Laden Weight: 2200 kg	Unladen Weight: 1650 kg
Year Of Manufacture: 2017	Original Registration Date: 10 Apr 2017
Lifespan Expiry Date: -	COE Category: E - Open Category
Quota Premium: \$53,001.00	COE Expiry Date: 09 Apr 2027
Road Tax Expiry Date: 09 Apr 2020	PARF Eligibility Expiry Date: 09 Apr 2027
Inspection Due Date: 09 Apr 2020	Intended Transfer Date: 11 Oct 2019
CO2 Emission: 165.00 (g/km)	CEV/VES Rebate Utilised Amount: -
CO Emission: -	HC Emission: -
NOx Emission: -	PM Emission: -

Fees To Be Paid For Transfer

Transfer Fees	\$25.00
---------------	---------

Print

Save as PDF

Copy as Text

OK ➔



We're revving up our celebrations for our first-year milestone

Chevrolet Orlando

Price Range

Depreciation

2017

Vehicle Type

Home » Used Cars » KelvinCarz Automobile » Chevrolet Orlando 1.4A Turbo LS

Chevrolet Orlando 1.4A Turbo LS

- Overview
- Financial
- Insurance
- Accessories
- Similar
- Research
- Photos
- Map
- DETAILED

Price

\$72,955

Depreciation

\$8,810 /yr

View models with similar depre

Reg Date

28-Feb-2017

(7yrs 4mths 16days COE left)

Mileage

40,000 km (15.3k /yr)

Manufactured

2016

Road Tax

\$604 /yr

Transmission

Auto

Dereg Value

\$49,160 as of today (change)

OMV

\$15,693

COE

\$50,621

ARF

\$15,693

Engine Cap

1,362 cc

Power

103.0 kW (138 bhp)

Curb Weight

1,650 kg

No. of Owners

1

Type of Vehicle

MPV

Features

1.4L Turbocharged Engine Producing 138 Bhp. 6 Speed Fully Auto Gearbox With Manual Select. Fold Flat 2nd And 3rd Row Seat. Multi Function Steering. View specs of the Chevrolet Orlando (2011-2018)

Accessories

Chocolate Dark Brown With Black Leather Interior. Factory Fitted Navigation, Bluetooth, Reverse Camera/Sensors, Etc.

Description

1 Owner. Fully Serviced And Maintained By The Authorised Distributor Alpine Chevrolet With Valid 5 Years Warranty. Accident Free With Original Paint Work. Almost New In Condition. Road Tax Till 2/2020. View And Test Drive It Today For A Further Discussion To Enjoy A Better From Us. Affordable Monthly Installment Plan.


Category

PARF Car, Premium Ad Car


Status

Available


Resources





Vehicle Evaluation
Afraid of lemons? Request to have this car evaluated professionally. Find out more





Car Valuation - Free
Find out the market value of your existing car for free. Get started






























Location Map

Price Chart



Click on the point to view the vehicle

Shortlist

Compare

Add nc

Report Error

More Actions

Seller Information

Posted: 05-Oct-2019

https://www.sgcarmart.com/used_cars/info.php?ID=844566&DL=2934

1/2



PROCEED DS / TP EXCESS \$5000

Type

🔔 Question

Message

ID COUNTER CLAIM TP (PD + INJURY). Please obtain evidence such as Insured's CCTV, PIR and liaise with Insured before any settlement.

Reply

<< Service Request Details

Claim

S9M023YO

Reference

None 

Loss Date

October 16, 2019

Report Date

Oct 17, 2019 12:00:00 AM

Request Date

October 17, 2019

Due Date

October 24, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

p: ms Hong

T: 2.33p.m

V: In

E ✓

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SFD89C

Model
HONDA

Service Address

...

Primary Contact/Insured

BOON LAY CORPORATION CLINIC PTE LTD
BLK 350 JURONG EAST AVE 1, #01-1225, 600350, Singapore

BCCPL_05@SINGNET.COM.SG

Claim Handler

CHAN Kian Chuan
68805444
kianchuan.chan@axa.com.sg

Additional Instructions

3

Messages	Invoices	History	Documents	Assessment	Metrics	Notes
----------	----------	---------	-----------	------------	---------	-------

New Message

Summer Lee (LKK Auto)

From: MG Solution <mg3solution@gmail.com>
Sent: Thursday, 17 October, 2019 1:09 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Subject: [EXTERNAL] SFD89C-(PRE-INS-INSPECTION)YOUR REF : SMD3808S-DOA ON 16/10/2019
Attachments: SFD89C (PRE-INSPECTION) ;YOUR REF SMD3808S.pdf
Categories: Shailendra

Dear All,

Please refer to attach file and arrange for pre-inspection.

Thank You.

Best Regards,

MS hong

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing)

#02-03B Vicom Inspection Centre

Singapore 415933

Tel : 6744 4165

Fax : 6744 4604

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Thursday, 17 October 2019 3:53 PM
To: Erwin Ho; 'sur@lkkauto.com'; Admin-D (LKKAuto)
Cc: Sundari Nagarajan - III
Subject: RE: Request for Pre-Repairs Survey
Attachments: SMN4525Z GIA.PDF

4:46pm 17/10/2019
vehicle in
p: Erwin
s: Raphael

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SMN4525Z and let us have your report urgently.

This claim will be handled by Ms Sundari.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: Erwin Ho [mailto:Fujimotorsports@hotmail.com]
Sent: 17 October, 2019 1:17 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: Re: Request for Pre-Repairs Survey

HiGabriel

Please LKK Mr. Taufikh urgently

Thank you
Erwin Ho
m. 92210404
MTM Performance Auto Pte Ltd
42 Toh Guan Road East
#01-78 EnterpriseHub
Singapore608583

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Wednesday, 16 October 2019 8:48 AM

To: Erwin Ho <Fujimotorsports@hotmail.com>

Subject: RE: Request for Pre-Repairs Survey

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext – 248

From: Erwin Ho [<mailto:Fujimotorsports@hotmail.com>]

Sent: 15 October, 2019 3:08 PM

To: Motor Claim - III <motorclaim@iii.com.sg>

Subject: Fw: Request for Pre-Repairs Survey

Dear Mr. Meka

As spoken, please arrange surveyor urgently as vehicle is already in our workshop

Thank you
Erwin Ho

From: Erwin Ho

Sent: Friday, 11 October 2019 4:19 PM

To: motorclaims@iii.com.sg <motorclaims@iii.com.sg>

Subject: Request for Pre-Repairs Survey

Dear Mr. Mekavathanan/Claims

We are requesting for a PRS to our client's vehicle SMN4525Z damaged by the reckless driving of your Insured's vehicle SHD3033U. GIA report of SMN4525Z is attached.

Kindly arrange surveyor to contact the undersign soonest.

Thank you

Erwin Ho

m. 92210404

MTM Performance Auto Pte Ltd

42 Toh Guan Road East

#01-78 Enterprise Hub

Singapore 608583

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths

Agents for Trade Marks

(Incorporated with limited liability)

ERIC NG CITING BOON
WONG KENG LEONG RAYNEY
AUDREY WONG SU-HSIEN
PAUL YAP TAI SAN
ANJALI DO MUNDANDY
ANG KIM NOI DIANE
RAVENDRA KRISHNASAMY
TAN YINXIANG, SELWYN
CHRONO YUNHUI, CLARISSA
SONIA LIM WITI LEE

Unique Entity Number :200721148H

✓ **HEAD OFFICE:** 133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413

Branch: 490 Toa Payoh Lorong 6
#03-11 HDB Hub
Singapore 310490

✓ HEAD OFFICE

TEL : (65) 65342811 (Hunting)

FAX ✓ : (65) 65356802 (General)

: (65) 65355905 (Litigation)

E-mail : jactan@visionlawllc.com

BRANCH

TEL : 65 63580703

FAX : 65 63580448 (Conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE- KINDLY REPLY TO **HEAD OFFICE** FOR THIS MATTER

Our Ref: AM.jt.ins.K88.111848.19 (sj)
Your Ref: SJJ 8188 T

16 October 2019

MSIG INSURANCE (S'PORE) PTE LTD
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807
Attention: Motor Claims Department

BY FAX: 6225-6371
motorsurvey@sg.msig-asia.com
claims@sg.msig-asia.com
helene_phua@sg.msig-asia.com

Dear Sirs,

ACCIDENT INVOLVING SMN 3882 Z & SJJ 8188 T ON 11 OCTOBER 2019 ALONG 355 BUKIT TIMAH ROAD AT ABOUT 1110 HOURS (NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES)

We refer to your email 16 October 2019 of even date informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment of Marcus from LKK Auto Consultants Pte Ltd as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

Venue: Kaizen Motors Pte Ltd
68 Kaki Bukit Avenue 6
#02-12 ARK@KB
Singapore 417896
Contact Person: Shawn Yap 9150-0670 /6384-1956

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully

ANJALI M
(HEAD OFFICE)

FOR SURVEYOR

Please initial here after completion of pre-repair inspection.
Thank you.

1st Survey on _____
Appointed surveyor : _____
(Name & Signature)

2nd Survey on _____
Appointed surveyor : _____
(Name & Signature)

3rd Survey on _____
Appointed Surveyor : _____
(Name & signature)

cc: **SMN 3882 Z** – Email: claims@kaizenmotors.com.sg only

NB.: Any settlement of offer is on the express condition that this settlement is in respect of our client's claim for property-related damages only and shall not preclude our client from claiming injury-related damages arising from this accident.

CONFIDENTIALITY
THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 17/03/2020

Survey Details:

Date of loss	1-Oct-19
Date of appointment	4-Oct-19
Date of survey	9-Oct-19
Location of survey	TRIPLE-T AUTOMOBILE

Vehicle Details:

Claim Type:	Third party
Vehicle number	SGP 49T
Make and Model	CHEVROLET ORLANDO
Date of registration	10/4/2017
Excess	
Market Value	\$67,800
Parf Rebate	\$51,581
Nett Loss	\$16,200

Repair details:

Initial Estimate	\$ 6,850.34
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 2,072.53
Check items (estimate)	\$ -
Labour	\$ 1,200.00
Total	\$ 3,272.53
Lump Sum(if applicable)	\$ 2,600.00

Number of days for repair	4
---------------------------	---



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

04 RECOMMENDED REPAIR DAYS + 2PRS + 1SUNDAY = 7DAYS

Mandate:

Liability(TP)		100%
Proposed repair cost	\$	2,600.00
Loss of use	\$	420.00
Loss of rental	\$	-
Loss of income	\$	-
LTA search fees	\$	7.45
Others	\$	562.00
Proposed Total	\$	3,589.45

SURVEY REPORT



<MANDATE IA> - S9M022FE {ACCIDENT INVOLVING SHC 5570C (OI) & SGP 49T (TP) ON 01/10/2019}

Type

🔗 Question

Message

LIABILITY: 100% BOLA NIL (OI CHARGED FOR CARELESS DRIVING) - INFORM OI ABOUT TP CLAIM AND NCD ISSUE. AGREED TO SETTLE AT BEST. WE SEEK YOUR MANDATE AT \$3589.45 (CLAIMING LOU). MANDATE IA HAS BEEN UPLOADED IN SMARTCLAIM. KINDLY LET US HAVE YOUR APPROVAL/INSTRUCTION. THANKS - CCL 17/03/2020

Reply

TRIPLE-T AUTOMOBILE

BLK 5 DEFU LANE 10 #01-574 SINGAPORE 539186
TEL: 63851171 FAX: 63851141

INVOICE

To: Ong Bin

Invoice No. : CL19073
Date : 24/02/2020
Vehicle No. : SGP49T

No.	Description	Qty	Unit Price	Amount
1	REPAIR COST		\$ 4,300.00	\$ 4,300.00
Total:				\$ 4,300.00

Payment by cheque should be crossed and made payable to 'Triple-T Automobile'

Issued By:

.....
Authorised Signature



SINGAPORE
POLICE FORCE

Our Ref : TP/IP/63317/2019
Date : 16 December 2019

Police Station
10 Lido Avenue 2
Singapore 438001
Tel: 6742 1000
Fax: 6742 4000
www.police.gov.sg

ONG BIN
8 EDEN GROVE
#03-02
SINGAPORE 539102

Dear Sir/Madam

ROAD TRAFFIC ACCIDENT INVOLVING SHC 5570 C AND SGP 49 T ALONG KAMPONG
KAPOR ROAD ON 01.10.2019 AT ABOUT 10.00PM

I refer to the above accident.

2. Please be informed that we have completed our investigations which revealed that the driver/rider of SHC 5570 C had committed an offence of Careless Driving under Rule 25 of the Road Traffic Rules. Action has been initiated against the driver/rider for the said offence.
3. If you have any clarification, you may contact the Investigation Officer, Sergeant Sharifah Nor Farizan at office number: 65476172.
4. Thank you.

Yours faithfully

HEAD INVESTIGATION
TRAFFIC POLICE
SINGAPORE POLICE FORCE

This is a computer-generated letter. No signature is required.



Re:<MANDATE IA> - S9M022FE {ACCIDENT INVOLVING
SHC 5570C (OI) & SGP 49T (TP) ON 01/10/2019}

Type

🔗 Question

Message

APPROVE MAX AT \$3589.45

Reply

TRIPLE-T AUTOMOBILE

BLK 5 DEFU LANE 10 #01-574 SINGAPORE 539186

TEL: 6385 1171

BUS. REG. NO. 53176519M

25th February 2020

Our Ref: CL19073

Your Ref: SHC5570C

AXA Insurance Singapore Pte Ltd

Motor Claims Department

8 Shenton Way

#24-01 AXA Tower

Singapore 068811

Dear Sirs,

ACCIDENT INVOLVING SGP49T AND SHC5570C ALONG JUNCTION OF SYED ALWI ROAD AND KAMPONG KAPOOR ON 01.10.2019

We are the representative for Mr Ong Bin, whose vehicle registration number **SGP49T** was damaged in the above accident.

We are instructed to claim for damages against your insured in connection with the above-captioned road traffic accident driven by your insured.

We are instructed that the accident was caused by your insured's negligence and/or management of motor vehicle registration **SHC5570C**. As a result of the accident, our client's vehicle was damaged and our client had been put to loss and expense, particulars of which are as follows:-

Cost of repairs	\$ 4,300.00
Loss of use for 07 day @\$120.00	\$ 840.00
Survey report	\$ 562.00
LTA search fee	\$ 7.45
	<u>\$ 5,709.45</u>

Enclosed are the supporting documents for your perusal:-

GIA

LTA search

Repair bill

Kindly let us have your payment of **\$5,709.45** in our workshop's name within the next 14 days.

Please do not hesitate to contact our Ms Tan at 9838 8224 or email motor@iaconsultingsg.com should you have any queries on your matter. We thank you for your kind attention and appreciate your quick remittance.

Yours faithfully,

Encl.

Calculation

Analysis tant

nt (PMC) of SBACC
ATO) of Workforce Singapore

No.25 Kaki Bukit Road 4
#06-46 Synergy @KB
Singapore 417800
Hotline: 6385 1171

Our reference: 20-01-9000

Date: 3/1/2019

INVOICE NO. 9000

Ong Bin
c/o Triple-T Automobile
Blk 5 Detu Lane 10
#01-558
Singapore 339187

Registration No. SGP49T

We enclose our fee note for your kind attention, which remains payable irrespective of the outcome of this case.

S/No.	Description of Services Provided	Qty	Amount
1	Being vehicle damage assessment report, inspection, photographs, transport and miscellaneous.	1	\$ 562.00
Total amount			<u>\$ 562.00</u>

Please kindly cross all cheques made payable to "Impact Analysis Consultant".

We thank you in anticipation for your prompt payment.

L. L. Tan
Principal Consultant

Subsidiaries of Impact Analysis Consultant:

• Impact Analysis Consulting Pte Ltd • Impact Analysis Academy Pte Ltd • IA Racking Solutions Pte Ltd
• Accounting & Consultancy Pte Ltd • Infoknights International Services (Philippines) • IABN Pte Ltd
www.iaconsulting.sg



Impact Analysis Consultant

Practising Management Consultant (PMC) of SBACC
Approved Training Organisation (ATO) of Workforce Singapore

No.25 Kaki Bukit Road 4
#06-46 Synergy @KB
Singapore 41780
Hotline: 6385 1171

Our reference: 20-01-9000

Date: 3/1/2019

c/o Triple-T Automobile
Blk 5 Debu Lane 10
#01-556
Singapore 539187

Dear Sirs

RE: Road Traffic Accident on 1/10/2019
Ong Bin

In accordance with your instructions received in this office on 27/12/2019, we made arrangements to examine the vehicle on 27/12/2019 at above-mentioned address. The following data was recorded:


Vehicle details

Make	Chevrolet	Registration	SGP49T
Model	Orlando	Chassis	KL1YA7589HK614352
Colour	Black	Gearbox	Auto
Odometer	87027km	Paintwork	Good
Steering	Good	Brakes	Good
Condition	Good		

Tyre Details

Front left	215/60R16	85% Bridgestone
Front right	215/60R16	85% Bridgestone
Rear left	215/60R16	85% Bridgestone
Rear right	215/60R16	85% Bridgestone

Impact Direction & Area of Damage:



Status	REPAIRABLE
Magnitude	Medium
Legal status	Unroadworthy

Following our examination of the accident damage, we have calculated repair times and method, which are detailed on page 2 & 3. We would recommend a sum of \$4,300.00 and 6 working days for repair, which is sufficiently lower than the pre accident value to render the vehicle an economically and physically reliable proposition.

Subsidiaries of Impact Analysis Consultant:

• Impact Analysis Consulting Pte Ltd • Impact Analysis Academy Pte Ltd • IA Racking Solutions Pte Ltd
• IA Accounting & Consultancy Pte Ltd • Infoknights International Services (Philippines) • IABN Pte Ltd
www.iaconsulting.sg



Our reference: 20-01-9000

Date: 3/1/2019

Page: 2

Section A: Damaged Parts Assessment

Part's Description	Qty	Condition As Inspected	Repairer's Estimate	Our Adjustment
<u>List Items:</u>				
Rear bumper	1	deformed	785.40	785.40
Rear bumper lower lip	1	deformed	552.30	552.30
Rear bumper side retainer rear rh	1	damaged	65.00	65.00
Rear bumper side retainer front rh	1	damaged	55.00	55.00
Rear bumper reflector rh	1	holder torn	75.00	75.00
Tail lamp rh	1	holder torn	412.00	412.00
Rear fender	1	repair.respray	952.00	0.00
Rear fender air vent rh	1	deformed	102.30	102.30
Rear fender protector rh	1	grazed/cut	177.00	177.00
Rear fender splash shield rh	1	damaged	121.00	121.00
Rear end panel	1	repair	557.40	0.00
Rear wheel bearing rh	1	necessary	174.20	174.20
Sub- Total costs			4028.60	2519.20
Percentage discount : 10%			402.86	251.92
Sub-Total costs for parts			3625.74	2267.28

Special Vert Items:

Rear bumper clips	set	necessary	55.00	55.00
Rear reverse sensor	1	malfunction	280.00	280.00
Rear tyre rim rh	1	repair	578.00	0.00
Sub-Total costs for parts			913.00	335.00

Parts Repair

•			0.00	0.00
Sub- Total costs			0.00	0.00
Total costs for parts			4538.74	2602.28

Subsidiaries of Impact Analysis Consultant:

• Impact Analysis Consulting Pte Ltd • Impact Analysis Academy Pte Ltd • IA Racking Solutions Pte Ltd
• IA Accounting & Consultancy Pte Ltd • Infoknights International Services (Philippines) • IABN Pte Ltd
www.iaconsulting.sg.com

Our reference: 20-01-9000

Date: 3/1/2019

Page: 3

Section B: Labour Cost Calculation

	Hourly rate	Manhr. Req.	Total
To dismantle, replace, cut, weld, knock out dents to straighten accident parts as mentioned on the 'Parts Repair' column inclusive of replacement parts	\$ 48.00	23	\$ 1,104.00
Putty & Spray painting to adjacent panels. Job allowance. Paint / material.	Sub-contract work.		\$ 800.00
Apply rust proofing on the adjacent panels.	Sub-contract work.		\$ 50.00
Remove and refix rear undercarriage works rh	\$ 48.00	4	\$ 192.00
Remove and replace rear bumper reverse sensor & conduct distance safety setting	\$ 48.00	1.7	\$ 81.60
Specialist charges - Wheel alignment	-	-	\$ 60.00
Wiring and bulb checking	\$ 48.00	0.5	\$ 24.00
Total labour cost			\$ 2,311.60

Manhour rate and the number of manhours required for each repairing task are formulated based on individual workshop's operating cost and in-house @ IA Research Guidelines respectively.

Subsidiaries of Impact Analysis Consultant:

• Impact Analysis Consulting Pte Ltd • Impact Analysis Academy Pte Ltd • IA Racking Solutions Pte Ltd
• IA Accounting & Consultancy Pte Ltd • Infoknights International Services (Philippines) • IABN Pte Ltd
www.laconsulting.com



Impact Analysis Consultant

Practising Management Consultant (PMC) of SBACC
Approved Training Organisation (ATO) of Workforce Singapore

No.25 Kaki Bukit Road 4
#06-46 Synergy @KB
Singapore 41780
Hotline: 6385 1171

Our reference: 20-01-9000

Date: 3/1/2019

Section C: Summary Table of Total Repair Cost

Description		Cost	
Damaged Parts Assessment (See section A)		\$2,602.28	
Further discount		\$520.46	
	20%		
Recommended cost of parts		\$2,081.82	(1)
Labour Cost Calculation (See section B)		\$2,311.60	(2)
Total Repair Cost (Round off to hundred)		\$4,300.00	(1) + (2)

We would recommend a sum of \$4,300.00 and 6 working days for repair.
No further items will be approved without our expressed written agreement. Any significant additional items will be subject to a supplementary report.

(Signature)
Mechanical Engineer, Accident Expert Witness, Licensed Appraiser (Automobile)
B.Eng. (Hons. NUS)
Diploma Mechanical Engineering
NTC's Automotive Technology
Sr.MTES, Institution of Engineers, Singapore (#20100091)
MATAI, Maryland Association of Traffic Accident Investigators
IAARS, International Association of Accident Reconstruction Specialists
PMC of Singapore Business Advisors & Consultants Council
ACTA certified Trainer, Singapore
SPRING- Recognised Certification for Management Consultants


Subsidiaries of Impact Analysis Consultant:

Impact Analysis Consulting Pte Ltd • Impact Analysis Academy Pte Ltd • IA Racking Solutions Pte Ltd
WIA Accounting & Consultancy Pte Ltd • Infoknights International Services (Philippines) • IABN Pte Ltd
www.iaconsulting.com








































LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19017512/Hga3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 03-04-2020



ATTN: CYNTHIA LOH

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 5570C	Veh. Inspected	SGP 49T
Policy No.	VFX/P1680520	Coverage (\$)	0.00
Claim No.	S9M022FE	Excess (\$)	0.00
Assign From		Assign Date	04/10/2019

2. Vehicle Particulars & Condition

Make & Model	CHEVROLET ORLANDO	c.c	1362
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	KL1YA7589HK614352	Colour	BLACK
Odometer	80289	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	BRIDGESTONE	6 mm
L/H Front Tyre	215/60 R16	BRIDGESTONE	6 mm
R/H Rear Tyre	215/60 R16	BRIDGESTONE	6 mm
L/H Rear Tyre	215/60 R16	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	01/10/2019	Inspection Date	09/10/2019
Survey held at	25 KAKI BUKIT RD 4 # 06-46		
Repairer	TRIPLE-T AUTOMOBILE		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGP 49T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER (CONSISTENT)	CRUSHED	785.40	685.40
1	REAR BUMPER LOWER LIP (CONSISTENT)	SCRATCHED	552.30	490.70
1	REAR BUMPER SIDE RETAINER REAR RH (CONSISTENT)	NECESSARY	65.00	48.80
1	REAR BUMPER SIDE RETAINER FRONT RH (CONSISTENT)	NECESSARY	55.00	48.80
1	REAR BUMPER REFLECTOR RH (CONSISTENT)	SERVICEABLE	75.00	-
1	TAIL LAMP RH (CONSISTENT)	CRACKED	412.00	412.00
1	REAR FENDER (CONSISTENT)	TO REPAIR SEE LABOUR	952.00	-
1	REAR FENDER AIR VENT RH (CONSISTENT)	SERVICEABLE	102.30	-
1	REAR FENDER PROTECTOR RH (CONSISTENT)	SCRATCHED	177.00	81.80
1	REAR FENDER SPLASH SHIELD RH (CONSISTENT)	SERVICEABLE	121.00	-
1	REAR END PANEL (CONSISTENT)	SERVICEABLE	557.40	-
1	REAR WHEEL BEARING RH (CONSISTENT)	CRUMPLED	174.20	174.20
	LESS 10% DISCOUNT		-402.86	-194.17
			3,625.74	1,747.53
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	55.00	25.00
1	REAR REVERSE SENSOR (SN) (CONSISTENT)	SHORTED	280.00	200.00
1	REAR TYRE RIM RH (LOCAL REPAIR) (SN) (CONSISTENT)	SCRATCHED	578.00	100.00
			913.00	325.00
<u>LABOUR</u>				
	TO DISMANTLE ,REPLACE ,CUT,WELD ,KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTIONED ON THE 'PARTS REPAIR' COLUMN INCLUSIVE OF REPLACEMENT PARTS.INCLUSIVE OF THE REPAIR OF REAR FENDER.		1,104.00	500.00
	PUTTY & SPRAY PAINTING TO ADJACENT PANELS ,JOB ALLOWANCE ,PAINT/MATERIAL.		800.00	500.00
	APPLY RUST PROOFING ON THE ADJACENT PANELS.		50.00	30.00
	REMOVE AND REFIX REAR UNDERCARRIAGE WORKS R		192.00	60.00

Report Ref No. CC4/ASM19017512/Hga3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE AND REPLACE REAR BUMPER REVERSE SENSOR & CONDUCT DISTANCE SAFETY SETTING.		81.00	20.00
	SPECIALIST CHARGES -WHEEL ALIGNMENT.		60.00	60.00
	WIRING AND BULB CHECKING.		30.00	30.00
			2,317.00	1,200.00
GRAND TOTAL			6,855.74	3,272.53
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,600.00

Report Ref No. CC4/ASM19017512/Hga3q2

LEE HOCK ANN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim	59M022FE
Reference	C33/ASIM19017512/Hga3a2
Loss Date	3 October 2019
Report Date	4 Oct 2019 11:17:00 AM
Request Date	4 October 2019
Due Date	
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Actions

Next Step

Wait for Approve Invoice

Add Invoice

Vehicle Information	
Incident Vehicle Registration #	SGP49T
Make	TPVD CHEVROLET
Model	ORLANDO 1.4AT TURBO
Service Address	
...	
Primary Contact/Insured	
TRANS-CAB SERVICES PTE LTD	
No.2 ANG MO KHO STREET 63, 569111, Singapore	
Claim Handler	
LOH Cynthia	
6568804843	
cynthia.loh@axa.com.sg	















Additional Instructions











Document Type

Document SubType

Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LKKInvoice1 (2).pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	6 April 2020

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LTA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	6 April 2020
 LKKInspection.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	6 April 2020
 LKKAdjustment1a (1).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	6 April 2020
 PAYMENT BREAKDOWN EXPRESS SETTLEMENT FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	6 April 2020
 AUTHOREATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	6 April 2020
 LETTER TO CL.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	6 April 2020
 TP PH.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	17 March 2020
 LKK SURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	17 March 2020
 LKK RESURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	17 March 2020
 LOD AND OTHER DOCUMENTS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	17 March 2020
 MANDATE IA DO 17032020.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	17 March 2020
 PARF COE REBATE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	17 March 2020
 TP FINAL EST LIST.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	17 March 2020
 EMAIL TO LKK_ID was charged by Traffic Police.mtg	Letters and Correspondence	Internal	VISHNU BATHAM Shukhar	20 December 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 Inspection Photographs.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	17 October 2019
 SGH49T Video footage.mp4	Evidence	Videos	LKK AUTO CONSULTANTS PTE LTD (TP)	17 October 2019
 ACCIDENT LOCATION MAP.jpg	Evidence	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	9 October 2019
 SGH49T VIDEO.mp4	Evidence	Videos	LKK AUTO CONSULTANTS PTE LTD (TP)	9 October 2019
 GIA REPORT OF SGH49T.PDF	Reports & Statement	GIA Report	KADRI Majeen	4 October 2019
 GIA REPORT OF SHCS370C (INSO).PDF	Reports & Statement	GIA Report	KADRI Majeen	4 October 2019
 SURVEY LIST SEND TO WORKSHOP.msg	Letters and Correspondence	Workshop	KADRI Majeen	4 October 2019
 EMAIL FROM WORKSHOP (THIRD PARTY PHU).msg	Letters and Correspondence	Workshop	KADRI Majeen	4 October 2019
 SPM022FE TP Video - Accident.MP4	Evidence	Videos	LOH Cynthia	4 October 2019
 EMAIL.msg	Letters and Correspondence	Others	KADRI Majeen	4 October 2019