

INS. CASE OWNER:

Jamie Tay

CC4/EQ119017520/K1ga3

LKK:

IDAC:

ASSIGNMENT

Surveyor:

KALVIN

DOI: 04/10/2019

Date / Time : 04/10/2019

Registered in Merimen: 03/10/2019 by wksp

Pre-assign / CCU / FTE



Insured Vehicle No. : GBE 5927T

Claim No. : DM19HO02721

Name of Insured : YONG SON INTERIOR DECORATION CENTRE

Policy No. : DMCPHQ19-000223

Insured Tel No. : HP: 90069039

Make / Model : TOYOTA DYNA 150 D-3.0 D (M)

Excess Sec II : S\$ D.O.A : 02/10/2019 11:30

Place of Accident : TAMPINES AVE 10

Is driver the owner? (YES / NO) Nature of Accident :

If NO, Driver Name / Age : CHAN BENG CHEONG

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. : +65-90069039 (V/L: YES / NO)

Insured Liability : % Final ? Yes / No

SHC 1290L



INSRS: WSP: CDGE LOYANG



INSRS: WSP:



INSRS: WSP:



INSRS: WSP:

Tel : Liability :

Tel : Liability :

Tel : Liability :

Tel : Liability :

RMKS:

RMKS:

RMKS:

RMKS:

Date/ Time	SHC 1290L - NBA/MSG16015999/Y; DOA: 9/7/16 - CS/FCI13020431/Ucbk3; DOA: 25/10/13 GBE 5927T - CC4/AIG16013879/Kpbs2; DOA: 24/7/16 - NA/EQ117013064/r3; DOA: 05/7/17	STAGE	DATE / PIC
		Non-Reporting ltr (1st):	
		Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
		Call OI:	
		After call ltr to OI:	
		Documentation Check List:	Handler Typist
		Notification ltr (if non-pickup)	☐ ☐
		After call ltr to OI:	☐ ☐
		Authorisation To Act:	☐ ☐
		Release Voucher:	☐ ☐
		Final Repair Bill:	☐ ☐
		Car Rental Invoice:	☐ ☐
		Towing Invoice	☐ ☐
		LTA / GIA :	☐ ☐
		Medical Bill:	☐ ☐
		PIR:	☐ ☐
		Mandate/Reject Instruction:	☐ ☐
		LOD	☐ ☐
		Payment Breakdown Form:	☐ ☐
		Post-Repair Photos:	☐ ☐
		Others:	☐ ☐
PRELIMINARY ADVICE Date/Time: Sent By:			
FINALIZATION Date/Time: Confirm with: Confirm by:			
Repair Cost:	S\$ (days) Reduction: %	Email ☐ Call ☐	
FINAL SETTLEMENT Date/Time: Confirm with: Email ☐ Call ☐			
Final Liability:	% (Agreed / Assessed) BOLA S/N No. :	If NO or B 28, Ass. Lia :	
Repair Cost:	S\$		
Loss of Rental (LOR):	S\$ (days)		
Loss of Use (LOU):	S\$ (\$ x days)		
Loss of Income (LOI):	S\$ (\$ x days)		
LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]			
GIA/LTA Search	S\$		
Medical:	S\$	1) Claim status: Normal/Reject/Private Settle	
Disbursement:	S\$ (e.g. Tow/ Independent)	2) Report Format:	
Legal Cost	S\$	3) Survey fee:	
Total:	S\$ Global Sum S\$:		
FINAL PAYMENT Date/Time: Confirm with: Email ☐ Call ☐			
Payee 1:	S\$ Name 1:		
Payee 2: (Strike if N.A.)	S\$ Name 2:		
Payee 3: (Strike if N.A.)	S\$ Name 3:		

ASS. REC. BY:

Kotun

REF:

EQ

ASSIGNMENT

From:

Date:

4.10.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SHC 1290L

at Workshop m/s

Confort delgro

of

59 Ioyang drive

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SHC 1290L

Yr Regn:

5 Apr 2012

Type: M.Car / M.Cycle / Bus / Van / Lorry / T/Tr / Prime Mover /

Truck / Trailer or

Make:

Myon di Sanchi

C.C

1991

Colour

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

15 658

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KMH6741VMCA 82260

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

2/10/19

D.O.I.

4/10/19

Survey held at

CDHE (Loyang)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

EQ

4/10/19

1/2 year bill

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format:

Lump Sum / L.B.I. (%)

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	821R
Vehicle Details	
Vehicle No.:	SHC1290L
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Oct 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	SONATA NF 2.0 CRDI AT ABS 2WD 4DR TURBO
Primary Colour:	Blue
Manufacturing Year:	2012
Engine No.:	D4EAC068084
Chassis No.:	KMHET41VMCA822600
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$14,668.00
Original Registration Date:	05 Apr 2012
First Registration Date:	05 Apr 2012
Transfer Count:	0
Actual ARF Paid:	\$14,668.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Apr 2020
PARF Rebate Amount:	\$8,800.00
Intended COE Rebate Details	
COE Expiry Date:	04 Apr 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$42,384.00
COE Rebate Amount:	\$2,649.00
Total Rebate Amount:	\$11,449.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 04 Oct 2019

OK

Team: IN ARC Repair TP(CLSO)1

JOB CARD


Sales Order: 3958762 JC NO.: 305338291

OMER	REGN NO.: SHC1290L	MILEAGE
IS COMFORT TRANSPORTATION PTE LTD	MAKE : HYUNDAI	FUEL
OMER NO. 7010045	MODEL SONATA	E.....1/2.....F
LESS 383 SIN MING DRIVE	YR OF MANU 05.04.2012	DATE/TIME IN 02.10.2019 11:30
IESS Singapore SINGAPORE 575717	CHASSIS CODE RMHET41VMCA822600	TARGET DATE
65508755 (R) (P)		COMPLETION DATE/TIME:
DUNT CARD NO.		

Accident Date: 02.10.2019
NATURE: 3P 02.10.19

JOB DESCRIPTION

S/NO LABOR CODE DESCRIPTION
00010 23-01 TOWING FEE



KED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

Vehicle No.: SHC1290L JU EQ

Vehicle No.: SHC1290L

Service Advisor

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

To be kept by Security Guard

COMFORTDELGRO
ENGINEERING

Our Job Ref No 305338291
Date : 07/10/19

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM


To : LKK
Attn : KALVIN
: SHC1290L

Fax :
305333809 02/10/19

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: EQ --- GBE5927T
###
2. The finalized amount shall be:
 - (a) Spare Parts after List discount
 - (b) Labour Charges ###
 - Total for Part-By-Part Repair Cost** ###
 - (c.) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20% **\$2,550.00**
Final Lumpsum Repair cost
3. Estimated normal period for repairs: 3 working days
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : JUMANI
Tel : 6214 8315
Fax : 65468156

Signature : 
Name : Kalvin
Date : 8/10/19

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				


Remarks:

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER:
CTPL

EQ Insurance Company Ltd (HQ)



Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	02/10/2019
Vehicle Reg. No.:	SHC1290L	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI SONATA, 2.0 CRDI (A)	Vehicle Reg. Date:	05/04/2012
Vehicle Colour:	BLUE		
Engine No:	D4EAC068084	Chassis No:	KMHET41VMCA822600
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS	Amount
Parts	4,253.12
Miscellaneous Items	0.00
Labour	2,161.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	6,414.12
+ GST 7.00% (S\$)	448.99
Nett Amount (S\$)	6,863.11

This claim is handled by: JUMANI BIN MASUDIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 03 Oct 2019)

Parts: 143 HYUNDAI SONATA 2.0 CRDI (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHC1290L/03/10/2019 10:31

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*RADIATOR GRILLE /	20.00	0.00	*282.10 FL
2	1		*RADIATOR GRILLE U MOULDING /	20.00	0.00	*108.90 FL
3	1	Frt	*REAR BUMPER ASSY /	20.00	0.00	*538.80 FL
4	1	Frt	*REAR BUMPER SPONGE /	20.00	0.00	*136.30 FL
5	1	Frt	*REAR BUMPER GRILLE LH X	20.00	0.00	*17.60 FL
6	1	Frt	*REAR BUMPER GRILLE RH X	20.00	0.00	*17.60 FL
7	1	Frt	*REAR BUMPER GRILLE CENTRE X	20.00	0.00	*131.10 FL
8	1	Frt	*REAR BUMPER LIP X	20.00	0.00	*59.90 FL
9	1	Frt	*REAR BUMPER BRACKET TOP LH X	20.00	0.00	*22.40 FL
10	1	Frt	*REAR BUMPER BRACKET TOP RH X	20.00	0.00	*22.40 FL
11	1	Frt	*REAR BUMPER BRACKET RH /	20.00	0.00	*20.10 FL
12	1	Frt	*REAR BUMPER BRACKET LH X	20.00	0.00	*20.10 FL
13	1	Frt	*REAR BUMPER PROTECTOR LH X	20.00	0.00	*29.20 FL
14	1	Frt	*REAR BUMPER PROTECTOR RH X	20.00	0.00	*29.20 FL
15	10	Frt	*REAR BUMPER CLIPS /	20.00	0.00	*22.00 FL
16	1		*HEADLAMP SUPPORT PANEL X	20.00	0.00	*1,023.00 FL
17	1		*HEADLAMP RH /	20.00	0.00	*797.90 FL
18	1		*HEADLAMP LH X	20.00	0.00	*797.90 FL
19	1		*FRT FENDER RH /	20.00	0.00	*593.00 FL
20	1		*FRT FENDER SHIELD RH /	20.00	0.00	*86.00 FL
21	1		*FRT FENDER SHIELD LH /	20.00	0.00	*86.00 FL
22	1		*FRT FENDER LAMP RH /	20.00	0.00	*45.40 FL
23	1		*WIPER CONTAINER MOTOR X	20.00	0.00	*63.00 FL
24	1		*WIPER CONTAINER X	20.00	0.00	*59.00 FL
25	1		*FRT WHEEL HUB CAP RH X	20.00	0.00	*145.00 FL
26	1		*FRT NUMBER PLATE X	0.00	0.00	*25.00 F
27	1		*FRT NUMBER PLATE COVER X	0.00	0.00	*30.00 F
28	1		*FRT DOOR COMFORT LOGO X	0.00	0.00	*75.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	5,283.90
- List Item Discount on L Items (\$\$)	1,030.78
Total Parts (\$\$)	4,253.12

ComfortDelGro Engineering Pte Ltd/SHC1290L/03/10/2019 10:31. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	MERIMEN FEE	New	11.00 ✓
2	PANEL BEATING	New	1,000.00 480
3	SPRAYPAINT	New	750.00 400
4	WIRING	New	50.00 20
5	TUFF KOTE	New	50.00 20
6	FRT WHELL ALIGNMENT	New	120.00 X
7	REMOVE/REFIX AIRCON & REFILL GAS	New	120.00 X
8	TOWING FEE	New	60.00 ✓
Gross Labour Cost (S\$)			2,161.00

ComfortDelGro Engineering Pte Ltd/SHC1290L/03/10/2019 10:31. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Ka/m 1(100)

4/10/19 11 45 hrs

3 hrs

L/S

After Repair

LKK Auto Consultants hence notify the Repairer of the following:

- No resurvey before/after spray painting
- No display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary (and/or) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____