

22/03/2002

ASS. REC. BY:

REF: CSB/AIG/19017522/Bf d3ek Special Instruction:

ASSIGNMENT (Office)

Mr-him  
MURMAN  
From (Person): Chin Lee Ying

of AIG

Date/Time: 4/11/2019 @ 12:30pm

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD /  TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FBG 8730M

Insured: SMD 642Y

at Workshop m/s Wing Yap Motor

Tel: 8233 7210

of 615 Balestier Road

Policy No: \_\_\_\_\_ Claim No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 29/09/2019  
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 207pm @ 4/11/2019 Person Contacted: Kelvin

Vehicle-IN  OUT

Date/Time	Action/Instruction ( X ) Estimate
	BK 4003 Amk Ind. Part 1 #01-114
	FBG 8730M-X
	SMD 642Y-X
4/11/19	Vehicle already in. But Kelvin said he's not in the office today, so he ask to arrange on Monday.


REP: **AIQ**

SS REC. BY:

**PRS**

**ASSIGNMENT**

From: \_\_\_\_\_ Date: **7/10/2019**  
 Estimated Cost: \_\_\_\_\_  
 OD/TP WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: **FBG 8730M**  
 at Workshop n/s **Wing Yap Motor**  
 of **Blk 4003 Amk Ind. Park I # 01-114**  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: **Kelvin @ 82337210**



(Policy Condition)  
 Remark: **The veh had commenced its repair at the time of inspection.**  
 Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rport: \_\_\_\_\_ Consistent?: **Yes or No**  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: **Yes or No**  
 Est. Repairs: **3** days Res.: **Yes or No**  
 Lum Sum: \_\_\_\_\_ % 3 Val.: **Yes or No**  
 CA / REV / REP. / 24 HRS **up**  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: **IN / OUT**

Veh No: **FBG 8730M** Yr Regn: **27/4/2012**  
 Type: M.Car / **M.Cycle** / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: **Baja** c.c **200**  
 Colour: **Yellow** A/C: **Insured / Std / NI / NA**  
 Sp. Reading: **140736** T/Radio: **Insured / Std / NI / NA**  
 Eng/No: **JL8CCH41845**  
 C/No: **MD2A36F82CCH48494**  
 Gen. Cond: **Good / Fair** / Poor / Burnt  
 Steering: **Inorder** / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: **Inorder** / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modi: **Nil / S/Rim** / STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: **110/70/17 BATTLEX**  
 R: **140/70/17 PIRELLI**  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or **Battlex fit / PIRELLI**  
 Front \_\_\_\_\_ Rear \_\_\_\_\_  
 R/Bal. **6** mm R/Bal. **6** mm  
 L/Bal. **6** mm L/Bal. **6** mm  
 D.O.A. **29/9/19** D.O.I. **7/10/19**  
 Survey held at **Wing Yap Motor**  
 Des. of Damages **Frt / Rear / O/S / N/S / UIC / Rooftop** or \_\_\_\_\_  
 The **UIC / Chassis frame / Body Structure** affected due to collision.

Date / Time	Action / Instruction
	<b>DAR</b> pending GIA already report from workshop.
	<b>Submit DAR report.</b>
	<b>RECEIVED 21 JAN 2020</b>
	<b>RECEIVED 17 JAN 2020</b>

Date/Time, File Pass to?  : Preli. Report  
 1) **PHI TYAST**  : Final Report  
 Date/Time, File Return to? \_\_\_\_\_  
 2) \_\_\_\_\_  
 Report Format: **DAR**  
 Lump Sum / LB.L: (\$) \_\_\_\_\_

Days Of Repair: **3**  
 Resurvey No. of Trip: **1**

Add Fee:  : Site Insp (\$) \_\_\_\_\_  
 : Interview (\$) \_\_\_\_\_  
 : Tech. Invs (\$) \_\_\_\_\_  
 : W/week end (\$) \_\_\_\_\_

Survey Fee: **180**  
 Transportation: \_\_\_\_\_  
 S + RS: \$ \_\_\_\_\_  
 Photos \_\_\_\_\_  
 Others: **11**  
 TOTAL: **191**

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	02/10/2019 14:35
Date Of Accident	29/09/2019 19:00
Exact Location Of Accident	RACE COURSE ROAD TOWARDS CTE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBG8730M
<b>Insured/Policyholder</b>	
Name Of Registered Owner	KULATHUNKAL JOSHUA PHILIP
NRIC No	S7163762Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97884926
Alternative Phone No	OFFICE-97884926

### Vehicle Particulars

Manufacturer	BAJAJ
Model	PULSAR 200
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5100839811-01
Cover Note Number	

### Driver

Name of Driver	KULATHUNKAL JOSHUA PHILIP
NRIC No	S7163762Z
Date Of Birth	11/03/1971
Occupation	INDOOR
Date Of Driving Pass	21/07/2010
Driving Experience	9 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97884926
Fax Number	
Contact Number	OFFICE-97884926
EEmail Address	NOEMAIL

Address	BLK411 ANG MO KIO AVENUE 10 #11-879
Postcode	560411
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	AFTER-RAIN
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	ANG MO KIO SOUTH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	<b>ROAD:</b> 81 ANG MO KIO AVE 3 , <b>POSTCODE:</b> 569929 , <b>COUNTRY:</b> SINGAPORE
Police Station Contact	<b>TEL NO:</b> 1800-4519999 - <b>FAX NO:</b> 65535679
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER POLICE REPORT AND ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMD642Y
Vehicle Make/Model/Colour	
Details Of Properties	REFER POLICE REPORT AND ATTACHED
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name	KULATHUNKAL JOSHUA PHILIP
Approximate Age	
Injuries Sustain	REFER POLICE REPORT AND ATTACHED
Injured person in which vehicle?	FBG8730M
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

Sketch Plan Pg. 1

SKETCH PLAN

FBG 8730M

SMD 642 X



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report No. T/20190930/2137

DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature  
Date & Time:

\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
 \_\_\_\_\_  
 Policyholder's Signature  
 Date & Time:

\_\_\_\_\_  
 Driver's Signature  
 (if driver is not the policyholder)  
 Date & Time:

  
 \_\_\_\_\_  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	762Z
Vehicle Details	
Vehicle No.:	FBG8730M
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Jan 2020
Vehicle Make:	BAJAJ
Vehicle Model:	PULSAR 200 NS MANUAL
Primary Colour:	Yellow
Manufacturing Year:	2012
Engine No.:	JLZCCH41845
Chassis No.:	MD2A36FZ2CCH48494
Maximum Power Output:	-
Open Market Value:	\$1,698.00
Original Registration Date:	27 Dec 2012
First Registration Date:	27 Dec 2012
Transfer Count:	2
Actual ARF Paid:	\$255.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	26 Dec 2022
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$1,701.00
COE Rebate Amount:	\$498.00
<b>Total Rebate Amount:</b>	<b>\$498.00</b>

The information contained herein is correct as at 21 Jan 2020

OK





**SINGAPORE  
POLICE FORCE**

Police Station Of Origin:  
Ang Mo Kio South N.P.C  
81 Ang Mo Kio Avenue 3 SINGAPORE  
569929  
Tel No: 1800-4519999



T/20190930/2137

2 of 3

Report No. T/20190930/2137

## CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
FBG8730M	NTUC Income Insurance Co-Operative Limited	5100839811-01	27/06/2019	26/06/2020

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Rider				
Name	KULATHUNKAL JOSHUA PHILIP	ID No.	S7163762Z	
Related Vehicle	FBG8730M (Motorcycle)	Contact No.	97834926	
Hospital/Clinic	NATIONAL UNIVERSITY HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL	
Date Treatment	29/09/2019	Date Discharge	29/09/2019	
No. of Days granted Medical Leave	02	Degree of Injury	Slight	

**Brief Details.**

On 29/09/2019 at about 1900hrs, I was riding my motorcycle; FBG8730M, along Race course road towards CTE. Behind me, there was a car; SMD642Y. Suddenly, the car filtered right and its front collided with the back rear of my motorcycle. I then fell over from my motorcycle. I was then attended by TP and ambulance and conveyed to Tan Tock Seng hospital. I sustained minor injuries and was given medical certificate from 29/09/2019 to 30/09/2019 of two days.



SINGAPORE  
POLICE FORCE



T/20190930/2137

3 of 3

Police Station Or Origin:  
Ang Mo Kio South N.P.C  
81 Ang Mo Kio Avenue 3 SINGAPORE  
569929  
Tel No: 1800-4519999

Report No. T/20190930/2137

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: F / Sgt 3 MASHIDAYAT BIN MASZENI 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 30/09/2019 15:35
Officer In Charge Of Case: TP / GIT / Sgt 2 PHUA TIAK YEE Contact No.: <u>65472077</u>	Classification Of Case: 

Authentication Stamp  
NP168



## PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHIC...

From: Chin, Lee-Ying  
To: assignments, Admin A  
Cc: Fong, Andy-SY  
Sent: 10/4/2019 12:30:23 PM

---

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards  
Lee Ying, Chin  
AIG  
Claims | AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way #08-16 Singapore 079120  
Tel +(65) 6419 1947  
[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com) | [www.aig.sg](http://www.aig.sg)

---

**From:** Prestina [mailto:[prestina@jklc.com.sg](mailto:prestina@jklc.com.sg)]

**Sent:** Friday, October 04, 2019 11:10 AM

**To:** Parthiban, Theerthan

**Cc:** Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Azlan, Syzairdina; Chan, Yoke Shi; Hor, Yinrul; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Subramaniam, Divyashni

**Subject:** [EXTERNAL] BLOCKED ATTACHMENT: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SMD642Y AND FBG8730M ON 29.09.2019

**This message is from an external sender; be cautious with links and attachments.**

This email contained an attachment that is potentially malicious. To protect the AIG network and users, the attachment named image001.wmz.gz,image001.wmz.wmf was removed from the email. If you believe that this is a legitimate email from a trusted source, please contact either the sender or your helpdesk to have the message resent in compliance with the corporate electronic messaging standard.

Please be aware that SPAM and other malicious email often have a forged sender to make it appear to be sent from someone on your contact list or otherwise trust.

---

WITHOUT PREJUDICE  
OUR REF: JK.19.FBG 8730M.PD

Dear Sir/Mdm,

We refer to your email of even date whereby parties are not agreeable to each other's list of motor surveyors.

Under the circumstances, no Single Joint has been agreed for this matter.

Please be informed that the said vehicle can be inspected at:

**Venue: WING YAP MOTOR  
615 Balestier Road  
Singapore 329910**

**Contact No: Mr. Kelvin @ 8233 7210 (Please call before going)**

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Regards,  
Prestina  
Legal Executive

UEN No. 53394571B  
6A Shenton Way  
#04-02 to 08  
OUE Downtown Gallery  
Singapore 068815

Tel: 6914 2682  
Fax: 6429 1048  
Email: [prestina@jklc.com.sg](mailto:prestina@jklc.com.sg)

---

**From:** Parthiban, Theerthan <[Theerthan.Parthiban@aig.com](mailto:Theerthan.Parthiban@aig.com)>

**Sent:** Friday, October 4, 2019 10:57 AM

**To:** Prestina <[prestina@jklc.com.sg](mailto:prestina@jklc.com.sg)>

**Cc:** Fong, Andy-SY <[Andy-SY.Fong@aig.com](mailto:Andy-SY.Fong@aig.com)>; Chin, Lee-Ying <[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com)>; Abu Kassim, Noor Mariesa <[NoorMariesa.AbuKassim@aig.com](mailto:NoorMariesa.AbuKassim@aig.com)>; Azlan, Syazairdina <[Syazairdina.Azlan@aig.com](mailto:Syazairdina.Azlan@aig.com)>; Chan, Yoke Shi <[yokeshi.chan@aig.com](mailto:yokeshi.chan@aig.com)>; Hor, Yinrul <[Yinrul.Hor@aig.com](mailto:Yinrul.Hor@aig.com)>; Lim, Sheng Yang <[ShengYang.Lim@aig.com](mailto:ShengYang.Lim@aig.com)>; Mithoosingh, Aashweenjeetkaur <[Aashweenjeetkaur.Mithoosingh@aig.com](mailto:Aashweenjeetkaur.Mithoosingh@aig.com)>; Parthiban, Theerthan <[Theerthan.Parthiban@aig.com](mailto:Theerthan.Parthiban@aig.com)>; Subramaniam, Divyashni <[Divyashni.Subramaniam@aig.com](mailto:Divyashni.Subramaniam@aig.com)>

**Subject:** PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SMD642Y AND FBG8730M ON 29.09.2019

This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยข้อความที่เข้ารหัสลับ เพื่ออ่านมันให้เปิดไฟล์ที่แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려면 첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka attachment.

[Click here](#) by 2019-10-11 10:56 +08 to read your message.  
After that, open the attachment.

[More Info](#)

**Disclaimer:** This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption, Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

**From:** Theerthan.Parthiban@aig.com

**To:** prestina@jklc.com.sg

**Cc:** Andy-SY.Fong@aig.com ,Lee-Ying.Chin@aig.com ,NoorMariesa.AbuKassim@aig.com ,Syazairdina.Azlan@aig.com ,yokeshi.chan@aig.com ,Yinrul.Hor@aig.com ,ShengYang.Lim@aig.com ,Aashweenjeetkaur.Mithoosingh@aig.com ,Theerthan.Parthiban@aig.com ,Divyashni.Subramaniam@aig.com

**Subject:** aigencrypt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SMD642Y AND FBG8730M ON 29.09.2019

**Date:** Fri, 4 Oct 2019 01:40:41 +0000

Without Prejudice

Your Reference : JK.19.FBG 8730M.PD

Our Reference : SMD642Y

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards,

Theerthan R Parthiban (Troy)  
AIG  
Senior Claims Examiner, Auto  
Singapore Claims Operations | AIG Shared Services

Tel: 8001206556 Ext: 1002217

[Theerthan.Parthiban@aig.com](mailto:Theerthan.Parthiban@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

**IMPORTANT NOTICE:**

*The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.*

---

**From:** Prestina [<mailto:prestina@jklc.com.sg>]  
**Sent:** Thursday, October 03, 2019 4:45 PM  
**To:** Lim, Sheng Yang; Azlan, Syazairdina; Mithoosingh, Aashweenjeetkaur  
**Cc:** General  
**Subject:** [EXTERNAL] PRE-REPAIR NOTICE OF ROAD TRAFFIC ACCIDENT ON 29.09.2019 at about 1900 HOURS ALONG RACE COURSE ROAD TWDS CTE involving our client's vehicle registration number FBG 8730M and SMD 642Y (PURSUANT TO PARAGRAPH 2.2 OF THE PRE-ACTION PROTOCOL FO...

**This message is from an external sender; be cautious with links and attachments.**

WITHOUT PREJUDICE  
OUR REF: JK.19.FBG 8730M.PD

Dear Sir/Mdm,

We are instructed by **KULATHUNKAL JOSHUA PHILIP** to notify you of a road traffic accident on **29.09.2019 at about 1900 HOURS ALONG RACE COURSE ROAD TOWARDS CTE** involving our client's vehicle registration number **FBG 8730M** and vehicle registration number **SMD 642Y** driven by you/your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not received any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Regards,  
Prestina

Legal Executive



UEN No. 53394571B  
6A Shenton Way  
#04-02 to 08  
OUE Downtown Gallery  
Singapore 068815

Tel: 6914 2682  
Fax: 6429 1048  
Email: [prestina@jklc.com.sg](mailto:prestina@jklc.com.sg)

Condition (CON)

(1) Bent (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scratched  
 (7) Deformed (8) Shifted (9) Buckled (10) Broken (11) Necessary  
 (12) Missing (13) Torn (14) Unconfirmed (15) Not Working

**FOR MOTORCYCLE**

ACTION (AC)

1. Replace (✓) 2. Repair (X) 3. Check (?)  
 4. Not Consistent (NC)

May 2005

Motorcycle

Vehicle No: FBG 8730M

NAC	INC	Item	CON	AC	Qty
1001	991886	Front Number Plate	BT	✓	
3001	995065	Front Tyre			
3002	995095	Front Rim			
3003	994872	Front Tyre Rim Spoke			
3004	991771	Front Fender Wheel Guard	R	X	
3005	991283	Front Brake Disc			
3006	991281	Front Brake Caliper			
3007	991785	Front Fork Assy			
3008	991787	Front Fork Inner Tube			
3009	991789	Front Fork Outer Tube			
3010	991167	Front Fork Bracket			
3011	991182	Front Fork Oil Seal			
3012	991174	Front Fork Garnish			
3013	992376	Front Headlamp Rim			
3014	992328	Front Headlamp	CUT	✓	
3015	992337	Front Headlamp Bracket			
3016	992345	Front Headlamp Fairing	CUT	✓	
3017	992130	Front Windshield			
3018	992134	Front Wing Mirror LH	CUT	✓	
3019	995245	Front LH Signal Lamp			
3020	995246	Front RH Signal Lamp	BR	✓	
3021	992556	Meter Casing			
3022	992553	Meter Assy			
1118	991019	ERP Bracket			
1119	991020	ERP Unit	CUT	✓	
3023	992446	Ignition Switch			
3024	992442	Ignition Key Assy			
3025	990706	Cowling Stay			
3026	994470	Steering Stem			
3027	994427	Steering Cone			
3028	992299	Handle Bar	BT	✓	
3029	992312	Handle Bar Switch			
3030	992310	Handle Bar Grip	NEC	✓	2
3031	995184	Handle Bar Balancer LH	CUT	✓	
3032	992300	Handle Bar Balancer RH			
1252	992179	Fuel Tank			
3033	990438	Brake Reservoir			
3034	990621	Clutch Lever	BR	✓	
3035	992293	Hand Brake Lever			
3036	991119	Side Fairing			
3037	994220	Side Fairing Top Garnish			
3038	994219	Side Fairing Inner Garnish			
3039	991118	Fairing Shield			
3040	992047	Front Top Fairing Inner Garnish			
3041	991123	Fairing Top Garnish			
3042	990538	Center Fairing			
3043	993378	Rear Fairing			
3044	991121	Fairing Stopper			
3045	991117	Fairing Lower			

NAC	INC	Item	CON	AC	Qty
1052	995074	Radiator			
1053	992738	Radiator Cowling			
3046	994146	Seat Assy			
3047	990915	Engine Crash Bar			
3048	990928	Engine Guard	BT	✓	
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
3049	991144	Foot Brake			
3050	991154	Front Foot Rest	BR	✓	
3051	991779	Front Foot Rest Bracket			
3052	994269	Side Stand			
3053	992549	Main Stand			
3054	990615	Clutch Engine Cover			
3055	992478	Kick Starter Rubber			
3056	992477	Kick Starter Lever			
3057	991145	Foot Gear Shifter	BR	✓	
3058	993500	Rear Foot Rest			
3059	993501	Rear Foot Rest Bracket			
3060	992581	Exhaust Muffler Heat Shield			
3061	991058	Exhaust Muffler Assy			
1405	993719	Rear LH Shock Absorber			
1445	993720	Rear RH Shock Absorber			
3062	995065	Rear Tyre			
3063	991200	Rear Rim			
3064	994872	Rear Tyre Rim Spoke			
3065	993474	Rear Fender Wheel Guard			
3066	993443	Rear Fender Mudflap			
3067	992940	Rear Brake Disc			
3068	992936	Rear Brake Caliper			
3069	995236	Rear Spocket			
3070	990585	Chain			
3071	990580	Chain Guard			
3072	994530	Swing Arm			
1420	993819	Rear Sub frame			
3073	995245	Rear LH Signal Lamp			
3074	995246	Rear RH Signal Lamp			
3075	995251	Rear Taillamp			
1087	993626	Rear Number Plate			
3076	994192	Side Box			
3077	992927	Rear Box	CUT	✓	
3078	992928	Rear Box Bracket	BT	✓	
3079	991328	Emblem			
1136	990247	Sticker			

No of Items: 14

Assessor: Tajim Min 7/10/19

Repair days 3

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Oct 2019 <a href="#">Edit Reg</a>		04 Oct 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	<b>Jasmine Kaur D/O Daljit Singh</b> , Co. Reg. No.: -								
Main Claimant:	<b>KULATHUNKAL JOSHUA PHILIP</b>								
Vehicle Reg. No.:	<b>FBG8730M</b>	Date of Loss:	29/09/2019 18:00 - :59 [81 Months and 2 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 4465450787SG</b>	Policy/Cover Note No.:	1800091940-01 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>SMD642Y</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Wing Yap Motor (HQ)</b> BLOCK 1003 ANG MO KIO AVENUE 10 #01-114 INDUSTRIAL PARK 1, 569624 Ang Mo Kio - Tel:								
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>MdNoor, Norsiah</b> ] Norsiah.MdNoor@aig.com								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>Lim Teow Guan</b> ] ... [Final Rpt due 15/10/2019]								
Claimant's Solicitor:	<b>JK LAW CHAMBERS</b> - Tel: 69142681								
<b>ASSOCIATED MAIL RECEIVED</b>				<a href="#">View All</a>	<a href="#">Compose Case Mail</a>				
• AIG_SG (07/10/2019): TP GIA report									
<b>ALL ASSOCIATED TASKS</b> <input type="checkbox"/>									
<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

## Claim Documents

\*FBG8730M (4465450787SG)  
[SMD642Y]  
TP  
KULATHUNKAL JOSHUA PHILIP  
Sep 29 2019 6:55PM  
[Jasmine Kaur D/O Daljit Singh]  
Wing Yap Motor

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View <input type="button" value="View in Browser"/>	
<b>Photos/Images</b>										3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	17/01/20 09:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
2	17/01/20 09:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
3	17/01/20 09:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
4	17/01/20 09:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
5	17/01/20 09:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
6	17/01/20 09:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
7	17/01/20 09:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
8	17/01/20 09:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
9	17/01/20 09:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
10	17/01/20 09:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
11	17/01/20 09:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
12	17/01/20 09:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
13	17/01/20 09:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
14	17/01/20 09:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
15	17/01/20 09:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
16	17/01/20 09:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
17	17/01/20 09:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
18	17/01/20 09:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
19	17/01/20 09:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
20	17/01/20 09:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
21	17/01/20 09:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
22	17/01/20 09:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
23	17/01/20 09:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
24	17/01/20 09:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
25	17/01/20 09:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
26	17/01/20 09:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
27	17/01/20 09:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
28	17/01/20 09:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
29	17/01/20 09:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
30	17/01/20 09:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
31	17/01/20 09:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
32	17/01/20 09:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
33	17/01/20 09:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
34	17/01/20 09:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
35	17/01/20 09:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
36	17/01/20 09:56	General View						 Load JPG	<input checked="" type="checkbox"/>		
37	17/01/20 09:56	General View						 Load JPG	<input checked="" type="checkbox"/>		

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	17/01/20 09:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	17/01/20 09:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	17/01/20 09:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	17/01/20 09:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	17/01/20 09:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	17/01/20 09:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	17/01/20 09:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	17/01/20 09:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	17/01/20 09:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	17/01/20 09:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	17/01/20 09:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	17/01/20 09:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	17/01/20 09:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	17/01/20 09:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	17/01/20 09:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	17/01/20 09:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	17/01/20 09:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	17/01/20 09:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	17/01/20 09:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	17/01/20 09:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	17/01/20 09:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	17/01/20 09:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	17/01/20 09:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	17/01/20 09:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	17/01/20 09:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	17/01/20 09:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	17/01/20 09:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	17/01/20 09:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	17/01/20 09:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	17/01/20 09:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	17/01/20 09:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	17/01/20 09:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	17/01/20 09:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	17/01/20 09:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	17/01/20 09:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	17/01/20 09:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	17/01/20 09:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	17/01/20 09:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	17/01/20 09:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	17/01/20 09:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	17/01/20 09:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	17/01/20 09:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	07/10/19 15:36	oi gia report	 Load PDF	<input type="checkbox"/>

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	<input type="button" value="Reset"/> <input type="button" value="Save"/> <input type="button" value="Print"/>
----------------------------	---

There are no document checklists configured.

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:**  Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG19017522/BTD3E2

**Date:** 23/01/2020

#### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800091940-01  
**Claimant Vehicle No :** FBG8730M **Insured Vehicle No :** SMD642Y  
 Date of Loss: 29/09/2019 Nature of Claim: TP Claim No: 4465450787SG

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBG8730M**  
 Make & Model: BAJAJ PULSAR 200 NS, 200cc Engine No: JLZCCH41845  
 Reg. Date: 27/12/2012 (Man. Year: 2012) Chassis No: MD2A36FZ2CCH48494  
 Colour: Yellow Odometer: 140736 km  
 Engine Capacity: 200 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size: 110/70/17 Rear Tyre Size: 140/70/17  
 Front Left Side: Battlax 6 mm Rear Left Side: Pirelli 6 mm  
 Front Right Side: 0 mm Rear Right Side: 0 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

#### INSPECTION

Date of Assignment: 04/10/2019  
 Date Inspected: 07/10/2019 Inspected At: BLK 4003 #01-114  
 Repairer : Wing Yap Motor (HQ)  
 Estimated Period of Repair: 3.0 days

**Adjuster:** Lim Teow Guan

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE	Bent	0.00 F	*- F
2	1		*FRONT FENDER WHEEL GUARD	Repair	0.00 F	*- F
3	1		*FRONT HEADLAMP	Cut	0.00 F	*- F
4	1		*FRONT HEADLAMP FAIRING	Cut	0.00 F	*- F
5	1		*FRONT WING MIRROR LH	Cut	0.00 F	*- F
6	1		*FRONT RH SIGNAL LAMP	Broken	0.00 F	*- F
7	1		*ERP UNIT	Cut	0.00 F	*- F
8	1		*HANDLE BAR	Bent	0.00 F	*- F
9	2		*HANDLE BAR GRIP	Necessary	0.00 F	*- F
10	1		*HANDLE BAR BALANCER LH	Cut	0.00 F	*- F
11	1		*CLUTCH LEVER	Broken	0.00 F	*- F
12	1		*ENGINE GUARD	Bent	0.00 F	*- F
13	1		*FRONT FOOT REST	Broken	0.00 F	*- F
14	1		*FOOT GEAR SHIFTER	Broken	0.00 F	*- F
15	1		*REAR BOX	Cut	0.00 F	*- F
16	1		*REAR BOX BRACKET	Bent	0.00 F	*- F

F=Franchise part.

<b>Total Parts (S\$)</b>	<b>0.00</b>	<b>0.00</b>
--------------------------	-------------	-------------

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >