

Your Ref : D16/11504/TPD&TPI/KT

Date: 02nd December 2019

Our Ref : CS/FCI19017536/Dvd3s2

M/s MS First Capital Insurance Ltd

36 Robinson Road

#16-01 City House

Singapore 068877

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE FBK 3958K
ACCIDENT ON 14/11/2016 INSURED VEHICLE SHC 1056Y**

Instruction was received to inspect the vehicle Reg. No. FBK 3958K. The inspection was conducted on 04/10/2019 at the premises of M/s 1 Kaki Bukit Avenue 6 #02-62 Singapore 417883.

The following vehicle information was recorded:

Registration Number	: FBK 3958K
Make/Model	: Kawasaki ZZR1400
Year of Registration	: 2015
Body Colour	: Green
Chassis Number	: JKBZXT40EFA016563
Engine Capacity	: 1441 cc

The vehicle sustained damages at the front o/s body and chassis frame cracked. The chassis frame affected due to collision. (Details see photographs enclosed).

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **"Total Loss"**.

Market Value	S\$ 38,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 5,694.00)
Nett Liability	<u>S\$ 32,306.00</u>

Vehicle Inspected By:



ANG BRYAN TANI
Automotive Assessor / Investigator

K.K.LAU
MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCIARD, AM, NIJAAR(USA),
AM CATARI(CAN), M. MATA(USA), M. MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.