

ASS. REC. BY:

REF: CS/ALG 1909565/ Nuf301

Special Instruction:

SURVIVOR: Nuz

ASSIGNMENT (Office)

From (Person): Chen Lee Yung of ALG Date/Time: 7.10.19 9.25a.m

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FBM 958 U Insured:

at Workshop m/s Bike Production Tel: 6299577

of 610 Serangoon Road

Policy No: 1900115577 Claim No:

Sum Insured: Excess: 300

Make of Veh: D.O.A. 2.10.2019
(Client's Record)

CA REV / REP. / REV 24 HRS

Date/Time: 7.10.19 10.19a.m Person Contacted: Yuki

H.O.D. Endorsement:

Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	FBM 958 U -
8/10/19	Revert via merimen
8/10/19	Rec approved \$2207 from Thaddeus by merimen
8/10/19	Informed Mr Kwan c/A on LS repair ex TBA

REF:

A14

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

8K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

FBM 9584

Yr Regn: 3 JUL 2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

YAMAHA SNIPER T150 cc 150

Colour:

MULTI COLOUR AG: Insured / Std / NI / NA

Sp. Reading:

35, 354

T/Radio: Insured / Std / NI / NA

Eng/No:

C/N:

MH3U40740A0046815

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

80/90 -17

R:

100/70 -17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

MAXXIS

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

-

mm

L/Bal.

-

mm

D.O.A.

2/10/19

D.O.A.

7/10/19

Survey held at

BIKE PRODUCTION

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision:

Date / Time

Action / Instruction

CIE Rebate \$4642.00

Repair Limit \$3,000.00

8/11/19

FINALIZED Lump Sum REPAIR \$2,050.00 (2 REPAIR DAY)

(Red 3826.90, 6590)

RECEIVED 12 NOV 2019

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

11/11 - typist

Days Of Repair:

2

Resurvey No. of Trip:

2

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation

3 + RS. \$

Photos

Others

TOTAL

Report Format :

menmen

Lump Sum / I.B.I. (\$)

2050/2

300

11

211

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 17 October 2019 8:55 AM
To: Sbk E; SUR
Subject: RE: FBM 958U-DOA: 2/10/2019 (AIG OD)
Attachments: SUPPLEMENTARY.pdf

Dear Mr Kwan,

Supplementary approved.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 8 October 2019 3:30 PM
To: Sbk E <sbk5643e@yahoo.com>; SUR <sur@lkkauto.com>
Subject: RE: FBM 958U-DOA: 2/10/2019 (AIG OD)

Dear Mr Kwan,

Vehicle excess \$300

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 8 October 2019 10:48 AM
To: Sbk E <sbk5643e@yahoo.com>; SUR <sur@lkkauto.com>
Subject: FBM 958U-DOA: 2/10/2019 (AIG OD)

Dear Mr Kwan,

As instructed by our client , please proceed to repair the **insured vehicle FBM 958U on Lump Sum Repair ,(Excess TBA).**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

NOTE: To arrange photo taking for check, supplementary item & after repair. Lump Sum repair insured sign acknowledge letter require to confirm.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 17 October 2019 7:46 AM
To: Ng, Thaddaeus-HC; SUR
Subject: RE: FBM 958U-DOA: 2/10/19 - Mandate Approved & X's

Dear Thaddaeus,

Noted with thanks.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ng, Thaddaeus-HC <Thaddaeus-HC.Ng@aig.com>
Sent: Wednesday, 16 October 2019 8:39 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: RE: FBM 958U-DOA: 2/10/19 - Mandate Approved & X's

Hi,

X's= \$300/- (As Per Merimen Update)

Suppl Mandate Approved for your update.

Regards,

Thaddaeus Ng

AIG

Motor Claims Surveyor

Claims|AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1929|Fax +(65) 6835 7416 Hp +(65) 8876 5433

Thaddaeus-HC.Ng@AIG.com | www.AIG.com.sg

From: Ng, Thaddaeus-HC
Sent: Tuesday, October 8, 2019 10:38 AM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Cc: Fong, Andy-SY <Andy-SY.Fong@aig.com>; SUR <sur@lkkauto.com>
Subject: RE: FBM 958U-DOA: 2/10/19 - Mandate Approved

Hi,

Excess yet to be confirm.

Will advise accordingly.

Regards,

Thaddaeus Ng

AIG

Motor Claims Surveyor
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel + (65) 6419 1929 | Fax + (65) 6835 7416 Hp + (65) 8876 5433
Thaddaeus-HC.Ng@AIG.com | www.AIG.com.sg

From: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Sent: Tuesday, October 8, 2019 10:35 AM
To: Ng, Thaddaeus-HC <Thaddaeus-HC.Ng@aig.com>
Cc: Fong, Andy-SY <Andy-SY.Fong@aig.com>; SUR <sur@lkkauto.com>
Subject: [EXTERNAL] RE: FBM 958U-DOA: 2/10/19 - Mandate Approved

This message is from an external sender; be cautious with links and attachments.

Dear Thaddaeus,

Thanks for the approval.

Please advised policy excess.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ng, Thaddaeus-HC <Thaddaeus-HC.Ng@aig.com>
Sent: Tuesday, 8 October 2019 10:10 AM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Cc: Fong, Andy-SY <Andy-SY.Fong@aig.com>; SUR <sur@lkkauto.com>
Subject: RE: FBM 958U-DOA: 2/10/19 - Mandate Approved

Hi,

Mandate Approved.

Damaged parts as require only approval with surveyor acknowledgement for your attention. Kindly do not hesitate to arrange photo taking for check, supplementary item & after repair.

Lumpsum repair insured sign acknowledge letter require to confirm.

Regards,
Thaddaeus Ng

AIG
Motor Claims Surveyor
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel + (65) 6419 1929 | Fax + (65) 6835 7416 Hp + (65) 8876 5433
Thaddaeus-HC.Ng@AIG.com | www.AIG.com.sg

From: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Sent: Tuesday, October 8, 2019 9:51 AM
To: Ng, Thaddaeus-HC <Thaddaeus-HC.Ng@aig.com>

Cc: Fong, Andy-SY <Andy-SY.Fong@aig.com>; SUR <sur@lkkauto.com>

Subject: [EXTERNAL] FBM 958U-DOA: 2/10/19

This message is from an external sender; be cautious with links and attachments.

Dear Thaddaeus,

Kindly assist mandate approval in merimen.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199807198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Khoo, Kay-Eng

Date: 16 Oct 2019

Preliminary Advice

Vehicle No	: FBM958U	Accident Date	: 02/10/2019
Make	: YAMAHA SNIPER	Policy No.	: 1900115577
Assignment Date	: 07/10/2019	Excess	: S\$300.00
Date of Inspection	: 07/10/2019	Est. Duration of Repair	: 2.00
Inspection At	: BIKE PRODUCTION (HQ) NO 610 SERANGOON ROAD SINGAPORE 218216		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion, o/s and n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	: S\$	5,886.90 (incl. supplementary \$602.40)
Revised Amount	: S\$	2,664.90 (incl. supplementary \$602.40)
Check Items (Estimated)	: S\$	0.00
Total	: S\$	2,664.90

Lump Sum Repair	: S\$	
-----------------	-------	--

Total Loss Consideration

New for Old Value	: S\$	
Pre-Accident Value	: S\$	8,000.00
COE / PARF Rebate	: S\$	4,642.00
Salvage Value	: S\$	
Margin for Repair	: S\$	3,358.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments : Kindly approved on the supplementary.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 8 October 2019 3:30 PM
To: Sbk E; SUR
Subject: RE: FBM 958U-DOA: 2/10/2019 (AIG OD)

Dear Mr Kwan,

Vehicle excess \$300

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 8 October 2019 10:48 AM
To: Sbk E <sbk5643e@yahoo.com>; SUR <sur@lkkauto.com>
Subject: FBM 958U-DOA: 2/10/2019 (AIG OD)

Dear Mr Kwan,

As instructed by our client , please proceed to repair the **insured vehicle FBM 958U on Lump Sum Repair ,(Excess TBA).**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

NOTE: To arrange photo taking for check, supplementary item & after repair. Lump Sum repair insured sign acknowledge letter require to confirm.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 8 October 2019 10:48 AM
To: 'Sbk E'; SUR
Subject: FBM 958U-DOA: 2/10/2019 (AIG OD)

Dear Mr Kwan,

As instructed by our client , please proceed to repair the **insured vehicle FBM 958U on Lump Sum Repair ,(Excess TBA).**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

NOTE: To arrange photo taking for check, supplementary item & after repair. Lump Sum repair insured sign acknowledge letter require to confirm.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***FBM958U**
OD
Oct 2 2019 8:55PM
[KHAIRIL ANUAR BIN KHAIRUDIN]
Bike Production

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 08/10/2019 10:09 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$2207.00) - FBM958U

Approved:2207.00:Damaged parts as require only approval with surveyor acknowledgement for your attention. Kindly do not hesitate to arrange photo taking for check, supplementary item & after repair. Lumpsum repair insured sign acknowledge letter

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd. AIG Building 78 Shenton Way #08-16 Singapore 079120	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
---	---

Attn:

Date: 08 Oct 2019

Preliminary Advice

Vehicle No	: FBM958U	Accident Date	: 02/10/2019
Make	: YAMAHA SNIPER	Policy No.	: 1900115577
Assignment Date	: 07/10/2019	Excess	: S\$0.00
Date of Inspection	: 07/10/2019	Est. Duration of Repair	: 2.00
Inspection At	: BIKE PRODUCTION (HQ) NO 610 SERANGOON ROAD SINGAPORE 218216		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion, o/s and n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,284.50
Revised Amount	:S\$	1,365.50
Check Items (Estimated)	:S\$	841.50
Total	:S\$	2,207.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	8,000.00
COE / PARF Rebate	:S\$	4,642.00
Salvage Value	:S\$	
Margin for Repair	:S\$	3,358.00


Remarks

☒ (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

☐ () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

☐ () Other comments :

NEW OD CLAIM - FBM958U

From: Chin, Lee-Ying
To: assignments, Admin A
Cc: Fong, Andy-SY
Sent: Monday, 7 October, 2019 9:25:29 AM
Attachments:  20191005_120801.jpg  gia.pdf

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947
Lee-Ying.Chin@aig.com | www.aig.sg

-----Original Message-----

From: Sbk E [mailto:sbk5643e@yahoo.com]
Sent: Saturday, October 05, 2019 12:11 PM
To: AIG SGP, Claims-Survey
Subject: [EXTERNAL] RE: NEW OD CLAIM - FBM958U

This message is from an external sender; be cautious with links and attachments.

Dear Sir,

Good Day. Please refer to the attached file. Please contact us at 62995177 for pre-repair inspection appointment. Thank you very much for your attention.

Regards,

Kwan S. H.
Director
Bike Production Pte Ltd

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

[Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	373E
Vehicle No:	FBM95BU
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Oct 2019
Vehicle Make:	YAMAHA
Vehicle Model:	SNIPER T150
Primary Colour:	White
Manufacturing Year:	2017
Engine No:	G3E6E0262053
Chassis No:	MH3UG0740H0046815
Maximum Power Output:	-
Open Market Value:	\$1,976.00
Original Registration Date:	03 Jul 2017
First Registration Date:	03 Jul 2017
Transfer Count:	1
Actual ARF Paid:	\$297.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	02 Jul 2027
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$4,001.00
COE Rebate Amount:	\$4,642.00
Total Rebate Amount:	\$4,642.00

The information contained herein is correct as at 07 Oct 2019

OK

Enquire Vehicle Transfer Fee

Vehicle Details

Vehicle No.
FBM958U

Make / Model
YAMAHA / SNIPER T150

Vehicle Type :
P00 - Passenger Motorcycle/Autocycle/Moped

Vehicle Scheme :
Normal

Propellant :
Petrol

Motor No. :
-

Power Rating :
-

Maximum Laden Weight :
266 kg

Year Of Manufacture :
2017

Lifespan Expiry Date :
-

Quota Premium :
\$6,001.00

Road Tax Expiry Date :
02 Jan 2020

Inspection Due Date :
02 Jul 2020

CO2 Emission :
-

CO Emission :
-

NOx Emission :
-

Vehicle Attachment 1 :
No Attachment

Chassis No. :
MH3UG0740H0046815

Engine No. :
G3E6E0262053

Engine Capacity :
150 cc

Maximum Power Output :
-

Unladen Weight :
116 kg

Original Registration Date :
03 Jul 2017

COE Category :
D - Motorcycle

COE Expiry Date :
02 Jul 2027

PARF Eligibility Expiry Date :
-

Intended Transfer Date :
07 Oct 2019

CEV/VES Rebate Utilised Amount :
-

HC Emission :
-

PM Emission :
-

Yamaha MXI T150 Sniper



SGD\$7000

Reg : 12/02/2016

Type: Cubs

150cc

-

Yamaha MXI T150 Sniper For Sale. Interested Parties Are Welcome To Neg. Trade/Loan Available. Do Visit Us At Wing Fuat @ Sims Place. No Early Settlement Fee.

Posted on : 23/09/2019

PAID AD

DEALER AD

COMPARE

DETAILS

Yamaha MXI T150 Sniper



SGD\$6500

Reg : 20/05/2016

Type: Cubs

150cc

70000km

Used Yamaha Sniper T150 With Original Coverset For Sale. Viewing At Soon Hin Motors Pte Ltd. Address: Yishun Industrial Park A Block 1018 S768760. Tel 67524893. We Accept Trade In And Many Oth...

Posted on : 04/10/2019

PAID AD

DEALER AD

COMPARE



CERTIFICATE OF INSURANCE

MOTORCYCLE AUTOVANTAGE MOTORCYCLE

Name of Policyholder : KHAIRIL ANUAR BIN KHAIRUDIN
Period of Insurance : 03 Jul 2019 To 02 Jul 2020
Engine No. : G3E6E0262053
Chassis No. : MH3UG0740H0046815

Vehicle No. : FBM958U
Policy No. : 1900115577
Endorsement No. :
Issued Date : 01 Jul 2019

ABOUT THE COVER

Make/Model : YAMAHA SNIPER T150
Engine Capacity/Tonnage : 150.00 CC
Driver Restriction : Named Driver Basis
Person or Classes of Persons Entitled to Drive* :

Sum Insured : Market Value
Off Peak Car : No

First Year of Registration : 2017
Insuring with COE/PAF : Yes

a) The Policyholder
 b) Any person who is named as a "named driver" under this Policy.

Age Condition : Not Applicable

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 The Policy does not cover:

- 1) use for hire or reward;
- 2) use for driving tuition, driving test, racing, pace-making, reliability trial or speed-testing;
- 3) use for the carriage of goods (other than samples) in connection with any trade or business; and
- 4) use for any purpose in connection with Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 188), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings

EXCESS

Section 1
 Fire - \$0 Own Damage - \$300 Theft - \$0

Section 2
 Property Damage - \$0

Windscreens : NA

Please note that this vehicle
 is under hire purchase with
Bike Production Pte Ltd
 No transfer or endorsement is allowed
 unless with our written consent

Named Driver and Excess (where applicable)

AZRIJL BIN KHAIRUDIN - \$300 (Own Damage), KHAIRIL ANUAR BIN KHAIRUDIN - \$300 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

Any accident repairs to the Vehicle must be carried out by one of our Authorised Repairers. Within the first 3 years of the first registration of the Vehicle in Singapore, You have the option of having the accident repairs carried out at the Sole Agent's workshop.
 For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 8336 6200. Alternatively, You may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: BIKE PRODUCTION PTE LTD

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 188), Part IV of the Road Transport Act, 1987 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1988 (Malaysia)

BIKE PRODUCTION PTE LTD

Co Reg No: 200007407G

610 Serangoon Road

Singapore 218216

Tel: 63922555 Fax: 62975400

0500656016

COWELL - BIKE PRODUCTION

8 BURN ROAD #09-09 TRIVEX

SINGAPORE 369977 ANSP-NONLIFE

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Janik

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/10/2019 16:35
Date Of Accident	02/10/2019 20:55
Exact Location Of Accident	UPPER BUKIT TIMAH ROAD OUTSIDE BEAUTY WORLD PLAZA
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBM958U
Insured/Policyholder	
Name Of Registered Owner	KHAIRIL ANUAR BIN KHAIRUDIN
NRIC No	S8308373E
Email Address	KAIRILASADE7@GMAIL.COM
Mobile Phone No	(LOCAL) +65-93880090
Alternative Phone No	OFFICE-87493961

Vehicle Particulars

Manufacturer	YAMAHA
Model	SNIPER-150CC

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	MOTORCYCLE
------------------	------------

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1900115577
Cover Note Number	

Driver

Name of Driver	AZRUL BIN KAIRUDIN
NRIC No	S8619862B
Date Of Birth	07/07/1986
Occupation	OUTDOOR
Date Of Driving Pass	23/08/2006
Driving Experience	13 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-87493961
Fax Number	
Contact Number	
EMail Address	YANT_NIE@HOTMAIL.COM

Address	BLK 412 BUKIT BATOK WEST AVENUE 4 #08-320
Postcode	850412
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SIBLING
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	HONG KAH NORTH NPP
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT AND STATEMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHF1588M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TAN CHOON YAM
NRIC/Passport Number	S0221687F
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1



Name

Approximate Age

Injuries Sustain

Injured person in which vehicle? SHF1588M

Were seat belts worn?

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report No. T/20191003/2019

Vehicle A was in static while i move at a low speed beside vehicle A & a sudden impact towards me out of nowhere & i was flying more then a meter near to the next lane of incoming traffic. Due to his careless reaction without giving any signal or checking blind spot i may had resulted in a very serious injury of even death. ~~but~~

Vehicle A driver came out to apologize to me & said that he did not see me coming & also the passenger last min instructed him to turn right.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____
Date & Time: _____

Driver's Signature:
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20191003/2104

1 of 3

Report No. T/20191003/2104

Police Station Of Origin:
Hong Kah North NPP
370 Bukit Batok Street 31 #01-201
SINGAPORE 650370
Tel No: 1800-5679999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 03/10/2019 15:52	Vide Report No.:	Station Diary No.: 45
--	------------------	--------------------------

Informant's Particulars

Name of Informant: AZRUL BIN KHAIRUDIN			Address: APT BLK 412 BUKIT BATOK WEST AVENUE 4 #08-320 SINGAPORE 650412		
ID Type / ID No.: NRIC NO / S8619862B			Contact No.: Home/Office: Mobile: 87493961		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 33	Date of Birth: 07/07/1986	Type of Informant: Rider		
Race: Malay			Language:		Institution / School Name:
Occupation: Private security officer			Driving Licence Information: Class: 2B Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 02/10/2019 20:55	Type of Location: Straight Road
Location: UPPER BUKIT TIMAH ROAD The road outside of Beauty World Plaza				
Weather: Clear		Road Surface: Wet		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Not Controlled		Traffic Volume: No Traffic
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBM958U	Motorcycle	YAMAHA	150 sniper	Blue	Seriously Damaged	0
SHF1588M	Car			Green	Slightly Damaged	1

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20191003/2104

2 of 3

Report No. T/20191003/2104

Police Station Of Origin:
Hong Kah North NPP
370 Bukit Batok Street 31 #01-201
SINGAPORE 650370
Tel No: 1800-5679999

CONTINUATION OF REPORT

Rider:			
Name	AZRUL BIN KHAIRUDIN	ID No.	S8619862B
Related Vehicle	FBM958U (Motorcycle)	Contact No.	87493971
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B Date of Expiry: NIL
Date Treatment	02/10/2019	Date Discharge	03/10/2019
No. of Days granted Medical Leave	05	Degree of Injury	Slight
Driver:			
Name	TAN CHOON YAM	ID No.	S0221687F
Related Vehicle	SHF1588M (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 02/10/2019 at about 2050hrs I was riding along the road in front on Beauty world plaza. suddenly a Green Taxi Reg: SHF1588M came of from the divider between the straight road and Beauty world plaza and his front right bumper collided onto the side of my motorcycle, as the impact is too big, I fell off my motorcycle. My motorcycle suffered serious damage and I was conveyed by the ambulance to Ng Teng Fong General Hospital. I was given 5 days of medical leave. Traffic Police was at scene.
I wish to state that I am riding at a very slow speed at about 30km/h at that point of time before the accident.



**SINGAPORE
POLICE FORCE**



T/20191003/2104

3 of 3

Report No. T/20191003/2104

Police Station Of Origin:
Hong Kah North NPP
370 Bukit Batok Street 31 #01-201
SINGAPORE 650370
Tel No: 1800-5679999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J /

Sgt 2 JACKY ONG CHUN HENG

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIT /

Sr Staff Sgt CHONG GUAN FATT

Contact No.: 65476083

Signature Of Informant:

Date/Time:

03/10/2019 15:52

Classification Of Case:

Authentication Stamp

NP168


BIKE PRODUCTION PTE LTD
 610, Serangoon Road S(218216)
 Tel: 63922555, 62995177 Fax: 62975400
ROC/ GST Reg No.: 200007407G

Date: 3 Oct 2019

ASSESSMENT FOR REPAIR: YAMAHA SNIPER T150 - FBM958U

Chassis No.: MH3UG0740H0046815

Engine No.: G3E6E0262053



Qty	Description	Estimate
1 pc	Front disk	\$140.00 X SVL
1 pc	Front wheel axle	\$75.00 X SVL
1 pc	Left fork assembly	\$390.00 X SVL
1 pc	Front fairing cover inner	\$150.00 ?
1 pc	Left fairing assembly	\$270.00 ✓ CLK
1 pc	Right fairing assembly	\$270.00
1 pc	Left fairing assembly labels	\$65.00 ✓ NFA
1 pc	Right fairing assembly labels	\$65.00 ?
2 pcs	Yamaha amblem @ \$20.00	\$40.00 ✓ NFA
1 pc	Lower centre cover	\$120.00 ?
1 pc	Left signal assy	\$75.00 ✓ SVL
2 pcs	Steering stem bearing @ \$45.00	\$90.00 X SVL
1 pc	Steering stem bracket assembly	\$195.00 X SVL ?
1 pc	Handle bar	\$135.00 ?
1 pc	Brake lever	\$40.00 ✓ SVL
1 pc	Right view mirror	\$40.00 ✓ SVL
1 pc	Right balancer	\$35.00 ✓ SVL
1 pc	Gear pedal assy	\$75.00 ✓ ST
1 pc	Right side rear cover	\$120.00 ✓ SVL
1 pc	Right rear footrest	\$45.00 ✓ SVL
1 pc	Front footrest holder assembly	\$145.00 X SVL
1 pc	Exhaust assy	\$380.00 ✓ SVL
1 pc	Left front footrest	\$45.00 ✓ ST
1 pc	Right front footrest	\$45.00 ✓ SVL
1 pc	Brake pedal assy	\$55.00 ✓ SVL
		\$3,105.00
	Less discount 10%	\$310.50
		\$2,794.50
	Special nett items	
1 pc	Front sport rim	\$350.00 X SVL
1 pc	Box rack	\$350.00 X SVL
1)	Towing charges	\$100.00 80
2)	Dismantle, replace, realign and adjust above damaged parts	\$200.00 200
4)	To knock, straighten chassis & body balancing	\$380.00 X NN
5)	To remove/refit, replace (if damage) check and straighten front fork tubes	\$180.00 X SVL
6)	To remove/refit, replace (if damage) check and replace front sport rim	\$180.00 X NN
7)	Spray painting	\$250.00 160
	Total Estimate	\$5,284.50

Note: The above estimate is subjected to the prevailing GST of 7%

05

Tel: 63922555, 62995177 Fax: 62975400

Date: 3 Oct 2019

Chassis No.: MH3UG0740H0046815

Engine No.: G3E6E0262053

Note:

Page 1

BIKE PRODUCTION PTE LTD
 610, Serangoon Road S(218216)
 Tel: 63922555, 62995177 Fax: 62975400
 ROC/ GST Reg No.: 200007407G

Date: 12 Oct 2019

ASSESSMENT FOR REPAIR: YAMAHA SNIPER T150 - FBM958U

Chassis No.: MH3UG0740H0046815
 Engine No.: G3E6E0262053

*EXHAUST BLACK COVERN @ 98 / SCR
 EXHAUST SILVER COVERN @ 75 / SCR*

<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
1 pc	Front mudguard	\$98.00 / SCR
1 pc	Headlamp cover	\$55.00 / SCR
1 pc	Front body fairing	\$95.00 / SCR
1 pc	Centre body cover	\$65.00 / CRK
		\$313.00
	Less discount 10%	\$31.30
		<u>\$281.70</u>
	<u>Special nett items</u>	
1 pc	Front number plate	\$15.00 / NCC
	<i>(LABOUR) EXHAUST REPAIR</i>	<i>@ 150 / 100</i>
	Total Estimate	<u><u>\$296.70</u></u> <i>603.40</i>

Note: The above estimate is subjected to the prevailing GST of 7%



For Bike Production Pte Ltd

*PARTS \$2,336
 LESS 10% \$2,102.40
 SINNET \$ 15
 LABOUR \$ 480
 TOTAL \$2,597.40
 LESS 4.52% \$2,077.92
 L/S TOTAL \$2,050.00 / 2 REPAIR DAYS*

Veron Chen (LKKAUTO)

From: Sbk E <sbk5643e@yahoo.com>
Sent: Friday, 8 November 2019 11:07 AM
To: Naz (LKKAUTO)
Cc: Veron Chen (LKKAUTO); SUR
Subject: RE: FINALIZATION APPROVAL, Re: FINALIZATION CONFIRMATION, Re: RE-FINALIZATION, Re: FBM 958U FINALIZATION

Dear Veron,

Please kindly confirm if the amount of \$2,050.00 before Excess and GST is approved?

Regards,

Kwan S. H.
Director
Bike Production Pte Ltd

On Friday, November 8, 2019, 10:17:17 AM GMT+8, Naz (LKKAUTO) <naz@lkkauto.com> wrote:

Dear Mr Kwan,

Finalized Lump Sum Repair \$2,050.00 / 2 Repair Days subject to insurance approval.

Thank you.

Best Regards,

Naz | Technical Investigator

LKK Auto Consultants

Phone: 6841-2157 | Email: Naz@lkkauto.com | Fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sbk E <sbk5643e@yahoo.com>
Sent: Tuesday, 5 November 2019 11:40 AM
To: Naz (LKKAUTO) <Naz@lkkauto.com>
Cc: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: FINALIZATION CONFIRMATION, Re: RE-FINALIZATION, Re: FBM 958U FINALIZATION

Dear Naz,

Please confirm that the finalization amount is \$2,050.00 before Excess and GST. Thanks.

Regards,

Kwan S. H.

Director
Bike Production Pte Ltd

On Saturday, November 2, 2019, 5:17:17 PM GMT+8, Sbk E <sbk5643e@yahoo.com> wrote:

Dear Naz,,

Good Day. We can settle at \$2,100.00 before Excess and GST. Please kindly assist on this matter. Thanks.

Regards,

Kwan S. H.
Director
Bike Production Pte Ltd

On Thursday, October 31, 2019, 4:11:14 PM GMT+8, Naz (LKKAuto) <naz@lkkauto.com> wrote:

Dear Mr Kwan,

Apologies for the late reply. Attached herewith is the amended marked estimate following a check on part prices. We will proceed to finalize if you are agreeable with the amended Lump Sum COR of \$1800.00 / 2 REPAIR DAYS

Thank you.

Best Regards,

Naz | Technical Investigator

LKK Auto Consultants

Phone: 6841-2157 | Email: Naz@lkkauto.com | Fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Veron Chen (LKKAUTO)

From: Sbk E <sbk5643e@yahoo.com>
Sent: Monday, 11 November 2019 6:18 AM
To: Naz (LKKAUTO)
Cc: Veron Chen (LKKAUTO); SUR
Subject: RE: INVOICE AND DV, Re: FINALIZATION CONFIRMATION, Re: RE-FINALIZATION, Re: FBM 958U FINALIZATION
Attachments: FBM958UInvDV.pdf

Dear Veron,

For your action. Thanks.

Regards,

Kwan S. H.
Director
Bike Production Pte Ltd

On Friday, November 8, 2019, 10:17:17 AM GMT+8, Naz (LKKAUTO) <naz@lkkauto.com> wrote:

Dear Mr Kwan,

Finalized Lump Sum Repair \$2,050.00 / 2 Repair Days subject to insurance approval.

Thank you.

Best Regards,

Naz | Technical Investigator

LKK Auto Consultants

Phone: 6841-2157 | Email: Naz@lkkauto.com | Fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sbk E <sbk5643e@yahoo.com>
Sent: Tuesday, 5 November 2019 11:40 AM
To: Naz (LKKAUTO) <Naz@lkkauto.com>
Cc: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: FINALIZATION CONFIRMATION, Re: RE-FINALIZATION, Re: FBM 958U FINALIZATION

Dear Naz,

Please confirm that the finalization amount is \$2,050.00 before Excess and GST. Thanks.

Regards,

Kwan S. H.

Director
Bike Production Pte Ltd

On Saturday, November 2, 2019, 5:17:17 PM GMT+8, Sbk E <sbk5643e@yahoo.com> wrote:

Dear Naz,,

Good Day. We can settle at \$2,100.00 before Excess and GST. Please kindly assist on this matter. Thanks.

Regards,

Kwan S. H.
Director
Bike Production Pte Ltd

On Thursday, October 31, 2019, 4:11:14 PM GMT+8, Naz (LKKAuto) <naz@lkkauto.com> wrote:

Dear Mr Kwan,

Apologies for the late reply. Attached herewith is the amended marked estimate following a check on part prices. We will proceed to finalize if you are agreeable with the amended Lump Sum COR of \$1800.00 / 2 REPAIR DAYS

Thank you.

Best Regards,

Naz | Technical Investigator

LKK Auto Consultants

Phone: 6841-2157 | Email: Naz@lkkauto.com | Fax: 6256-4315

Blk S1, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

BIKE PRODUCTION PTE. LTD.

610, Serangoon Road Singapore 218216
Tel: 6392 2555 Fax: 6297 5400

TAX INVOICE

Co. Registration No. 200007407G
GST Reg. No. 200007407G
GST Inclusive

No: 6143

Name : AIG ASIA PACIFIC INSURANCE PTE LTD

Date : 05/11/2019

Address : 8 BURN ROAD #09-09 TRIVEX S (369977)

78 Shenton Way #07-16 AIG BUILDING SGO 79120

I/C No : _____ Occupation : _____

DOB

Tel : (T) 6419 3000

Driving Licence : _____



Particulars		Amount
Reg. No : <u>FBM9584</u>	Selling Price	<u>\$1872.50</u>
Make & Model : <u>YAMAHA SNIPER T150</u>	+ Insurance	<u>\$ 0</u>
Engine No : <u>G3E6E0262053</u>	+ Retention	<u>\$ 0</u>
Chassis No : <u>MH3UG0740H0046815</u>	TOTAL PRICE	<u>\$1872.50</u>
Insurance Type: <input type="checkbox"/> Comprehensive <input type="checkbox"/> Third Party Fire Theft <input type="checkbox"/> Third Party Only		
Colour : <u>WHITE</u>	LUMP SUM REPAIRS Downpayment	<u>\$2050</u>
	LESS EXCESS	<u>\$ 300</u>
Loan Amount _____ Interest rates _____ p.a.		<u>\$1750</u>
Terms : (_____ Monthly Instalments of \$ _____	GST 7%	<u>\$122.50</u>
N/R : _____ TEL : _____		<u>\$1872.50</u>
GTR : _____ TEL : _____		
COE NO : _____	TR	

Note:

- Above prices do not include ERP IU.
- Deposit is not refundable.
- Balance amount must be cleared within 3 days of the invoice date. Deposit will be forfeited if the buyer fails to clear the full balance amount within the stated period.
- Title to the above-mentioned goods will not be handed to the buyer until the full amount and/or changes are paid
- All cheque payments are to be crossed and made payable to **Bike Production Pte Ltd**. If cheque dishonoured, the buyer has to pay **Bike Production Pte Ltd** by cash and a service charge of S\$30.00 plus prevailing GST.
- Bike Production Pte Ltd** will have full rights to repossess the above-mentioned goods without notice in case of default in payment.
- The buyer shall inspect the above-mentioned goods immediately on notification that goods are due and ready for collection. The buyer shall give notice in writing to the seller of any matter or thing by reason whereof he alleges that the goods are not in acceptable conditions, if the buyer fails to give notice, the above-mentioned goods shall be deemed to be in accordance with the contract and the buyer shall be bound to accept and pay for the same accordingly.
- For hire purchase, no alteration of the hire-purchase agreement and its terms, including down payment and installment period, is allowed once the hire-purchase agreement is made. In the event of cancellation, the buyer shall compensate **Bike Production Pte Ltd** 20% of the total price plus prevailing GST and the deposit shall be forfeited.
- For hire purchase, a Singaporean guarantor between 21 year & 60 year of age and with a different residential address from the buyer is required before the collection of the above-mentioned goods. The guarantor shall not be an undischarged bankrupt and is subject to financial approval.
- I confirm that the information I have provided is my personal data and, where it is not my personal data, that I have the consent of the owner of such personal data to provide such information. By providing this information I understand and give my consent for **Bike Production Pte Ltd** to collect, use, store, transfer and / or disclose personal data about me or us and those whose personal data I or we have provided from sources other than myself or us for the purposes.

For **Bike Production Pte Ltd**

I accept the above terms and conditions

Khairil Anuar Bin Khairudin
Blk 817B Keat Hong Link
#03-95
Singapore 682817


Date: 16 Oct 2019

To: Mr Kwan Say Hwee
Bike Production Pte Ltd
610, Serangoon Road
Singapore 218216

Dear Sir,


**RE: ACKNOWLEDGEMENT OF THE ACCIDENT REPAIR AND COLLECTION
OF YAMAHA SNIPER T150 VEHICLE NO.: FBM958U**

I, Khairil Anuar Bin Khairudin, NRIC No.: 373E, have inspected the repair done by Bike Production Pte Ltd and the repair is in accordance to the repair quotation and/or surveyor report.

I have collected the above mentioned vehicle on 16/10/19 at 15 DOHKS 

Thank you very much for your attention.

Yours faithfully,



Khairil Anuar Bin Khairudin











































...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Oct 2019 17:41		07 Oct 2019 11:03 Edit Adj Rpt	\$2,050.00 Edit Estimates	\$2,050.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	KHAIRIL ANUAR BIN KHAIRUDIN , ID: S8308373E, Tel: +6593880090								
Vehicle Reg. No.:	FBM958U	Date of Loss:	02/10/2019 21:00 - :59 [26 Months and 29 Days From LTA Reg Date (Mon Yr)]						
Claim Type:	OD / 4412909390SG	Policy/Cover Note No.:	1900115577 (Comprehensive)						
		Excess:	\$4300.00						
Repairer:	Bike Production (HQ) No 610 Serangoon Road, 218216 Serangoon - Tel: 6299-5177								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Khoo, Kay-Eng - 6419 1026] Kay-Eng.Khoo@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 16/10/2019]								
Driver/Custodian:	AZRUL BIN KAIRUDIN (33 / Male), NRIC: S8619862B, Tel: +6587493961 Email: yant_nie@hotmail.com								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (16/10/2019): Alert - Adj Mandate Approved (\$2664.90) - FBM958U - Claim Handler: Khoo, Kay-Eng... AIG_SG (08/10/2019): FBM958U / OD / 02/10/2019 / Coverage & Excess update AIG_SG (08/10/2019): Alert - Adj Mandate Approved (\$2207.00) - FBM958U 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBM958U (4412909390SG)
OD
Oct 2 2019 9:00PM
[KHAIRIL ANUAR BIN KHAIRUDIN]
Bike Production

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View View in Browser		
Assessment Reports															1 per page		<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print
1	08/10/19 09:47	Adjuster Immediate Advice														Load HTM	
2	16/10/19 15:48	Adjuster Immediate Advice														Load HTM	
Photos/Images															3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print
1	07/10/19 17:02	General View														Load JPG	<input checked="" type="checkbox"/>
2	07/10/19 17:02	General View														Load JPG	<input checked="" type="checkbox"/>
3	07/10/19 17:02	General View														Load JPG	<input checked="" type="checkbox"/>
4	07/10/19 17:02	General View														Load JPG	<input checked="" type="checkbox"/>
5	07/10/19 17:02	General View														Load JPG	<input checked="" type="checkbox"/>
6	07/10/19 17:02	General View														Load JPG	<input checked="" type="checkbox"/>
7	07/10/19 17:02	General View														Load JPG	<input checked="" type="checkbox"/>
8	07/10/19 17:02	General View														Load JPG	<input checked="" type="checkbox"/>
9	07/10/19 17:02	General View														Load JPG	<input checked="" type="checkbox"/>
10	07/10/19 17:02	General View														Load JPG	<input checked="" type="checkbox"/>
11	07/10/19 17:02	General View														Load JPG	<input checked="" type="checkbox"/>
12	07/10/19 17:02	General View														Load JPG	<input checked="" type="checkbox"/>
13	07/10/19 17:02	General View														Load JPG	<input checked="" type="checkbox"/>
14	07/10/19 17:02	General View														Load JPG	<input checked="" type="checkbox"/>
15	07/10/19 17:02	General View														Load JPG	<input checked="" type="checkbox"/>
16	07/10/19 17:02	General View														Load JPG	<input checked="" type="checkbox"/>
17	07/10/19 17:02	General View														Load JPG	<input checked="" type="checkbox"/>
18	07/10/19 17:02	General View														Load JPG	<input checked="" type="checkbox"/>
19	07/10/19 17:02	General View														Load JPG	<input checked="" type="checkbox"/>
20	07/10/19 17:02	General View														Load JPG	<input checked="" type="checkbox"/>
21	07/10/19 17:02	General View														Load JPG	<input checked="" type="checkbox"/>
22	07/10/19 17:02	General View														Load JPG	<input checked="" type="checkbox"/>
23	07/10/19 17:02	General View														Load JPG	<input checked="" type="checkbox"/>
24	07/10/19 17:02	General View														Load JPG	<input checked="" type="checkbox"/>
25	07/10/19 17:02	General View														Load JPG	<input checked="" type="checkbox"/>
26	07/10/19 17:02	General View														Load JPG	<input checked="" type="checkbox"/>
27	07/10/19 17:02	General View														Load JPG	<input checked="" type="checkbox"/>
28	07/10/19 17:02	General View														Load JPG	<input checked="" type="checkbox"/>
29	07/10/19 17:02	General View														Load JPG	<input checked="" type="checkbox"/>
30	07/10/19 17:02	General View														Load JPG	<input checked="" type="checkbox"/>
31	07/10/19 17:02	General View														Load JPG	<input checked="" type="checkbox"/>
32	07/10/19 17:02	General View														Load JPG	<input checked="" type="checkbox"/>
33	07/10/19 17:02	General View														Load JPG	<input checked="" type="checkbox"/>
34	15/10/19 17:30	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>
35	15/10/19 17:30	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>
36	15/10/19 17:30	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>
37	15/10/19 17:30	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>
38	15/10/19 17:30	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>
39	15/10/19 17:30	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>
40	15/10/19 17:30	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
41	15/10/19 17:30	Dismantled Parts		<input checked="" type="checkbox"/>
42	15/10/19 17:30	Dismantled Parts		<input checked="" type="checkbox"/>
43	15/10/19 17:30	Dismantled Parts		<input checked="" type="checkbox"/>
44	15/10/19 17:30	Dismantled Parts		<input checked="" type="checkbox"/>
45	15/10/19 17:30	Dismantled Parts		<input checked="" type="checkbox"/>
46	15/10/19 17:30	Dismantled Parts		<input checked="" type="checkbox"/>
47	15/10/19 17:30	Dismantled Parts		<input checked="" type="checkbox"/>
48	15/10/19 17:30	Dismantled Parts		<input checked="" type="checkbox"/>
49	15/10/19 17:30	Dismantled Parts		<input checked="" type="checkbox"/>
50	15/10/19 17:30	Dismantled Parts		<input checked="" type="checkbox"/>
51	15/10/19 17:30	Dismantled Parts		<input checked="" type="checkbox"/>
52	15/10/19 17:30	Dismantled Parts		<input checked="" type="checkbox"/>
53	15/10/19 17:30	Dismantled Parts		<input checked="" type="checkbox"/>
54	15/10/19 17:30	Dismantled Parts		<input checked="" type="checkbox"/>
55	15/10/19 17:30	Dismantled Parts		<input checked="" type="checkbox"/>
56	15/10/19 17:30	Dismantled Parts		<input checked="" type="checkbox"/>
57	15/10/19 17:30	Dismantled Parts		<input checked="" type="checkbox"/>
58	15/10/19 17:30	Dismantled Parts		<input checked="" type="checkbox"/>
59	15/10/19 17:30	Dismantled Parts		<input checked="" type="checkbox"/>
60	15/10/19 17:30	Dismantled Parts		<input checked="" type="checkbox"/>
61	15/10/19 17:30	Dismantled Parts		<input checked="" type="checkbox"/>
62	15/10/19 17:30	Dismantled Parts		<input checked="" type="checkbox"/>
63	08/11/19 10:28	Photo After Spray		<input checked="" type="checkbox"/>
64	08/11/19 10:28	Photo After Spray		<input checked="" type="checkbox"/>
65	08/11/19 10:28	Photo After Spray		<input checked="" type="checkbox"/>
66	08/11/19 10:28	Photo After Spray		<input checked="" type="checkbox"/>
67	08/11/19 10:28	Photo After Spray		<input checked="" type="checkbox"/>
68	08/11/19 10:28	Photo After Spray		<input checked="" type="checkbox"/>
69	08/11/19 10:28	Photo After Spray		<input checked="" type="checkbox"/>
70	08/11/19 10:28	Photo After Spray		<input checked="" type="checkbox"/>
71	08/11/19 10:28	Photo After Spray		<input checked="" type="checkbox"/>
72	08/11/19 10:28	Photo After Spray		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/10/19 09:37	GIA AND POLICE REPORT		<input checked="" type="checkbox"/>
2	08/10/19 09:37	Certificate of Insurance		<input checked="" type="checkbox"/>
3	08/10/19 09:37	Driver's Driving License		<input checked="" type="checkbox"/>
4	08/10/19 09:37	MARK ESTIMATE		<input checked="" type="checkbox"/>
5	16/10/19 15:48	SUPPLEMENTARY		<input checked="" type="checkbox"/>
6	25/11/19 10:16	Workshop Invoice		<input checked="" type="checkbox"/>
7	25/11/19 10:16	Discharge Voucher		<input checked="" type="checkbox"/>

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
1	04/10/19 16:15	Accident Statement		<input checked="" type="checkbox"/>
2	07/10/19 13:47	Addendum Sheet		<input checked="" type="checkbox"/>
3	07/10/19 13:50	Accident Statement Addm. #1		<input checked="" type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
1	04/10/19 16:12	Accident Photo		<input checked="" type="checkbox"/>
2	04/10/19 16:12	Accident Photo		<input checked="" type="checkbox"/>
3	04/10/19 16:12	Accident Photo		<input checked="" type="checkbox"/>
4	04/10/19 16:12	Accident Photo		<input checked="" type="checkbox"/>
5	04/10/19 16:12	Accident Photo		<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
				<input checked="" type="checkbox"/>
6	04/10/19 16:12	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	04/10/19 16:12	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	04/10/19 16:12	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	04/10/19 16:12	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
10	04/10/19 16:12	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
11	04/10/19 16:12	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
12	04/10/19 16:12	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
13	04/10/19 16:12	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
14	04/10/19 16:12	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
15	04/10/19 16:12	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
16	04/10/19 16:12	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
1	04/10/19 16:14	Sketch Plan	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CS/AIG19017565/NVF3E2

Date: 25/11/2019

REFERENCE

Insured/Claimant: KHAIRIL ANUAR BIN KHAIRUDIN

Policy No: 1900115577

Date of Loss: 02/10/2019

Nature of Claim: OD

Claim No: 4412909390SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBM958U

Make & Model: YAMAHA SNIPER, 150cc

Reg. Date: 03/07/2017 (Man. Year: 2017)

Colour: Multi-colour

Engine Capacity: 150 cc

Market Value/New Car Price: S\$8,000.00

Sum Insured (S\$): Market Value/New Car Price

Engine No: G3E6E0262053

Chassis No: MH3UG0740H0046815

Odometer: 35354 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 80/90-17

Rear Tyre Size: 100/70-17

Front Left Side: Maxxis 5 mm

Rear Left Side: Maxxis 5 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,946.90	2,184.90	1,762.00	44.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,940.00	480.00	1,460.00	75.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,886.90	2,664.90	3,222.00	54.73
Approved Total (Overridden) (S\$)		2,050.00		
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	5,586.90	1,750.00	3,836.90	68.68
+ GST 7.00/7.00% (S\$)	391.08	122.50	268.58	68.68
Nett Amount (S\$)	5,977.98	1,872.50	4,105.48	68.68

INSPECTION

Date of Assignment: 07/10/2019

Date Inspected: 07/10/2019 Inspected At:

Bike Production (HQ)
No 610 Serangoon Road
Singapore 218216

Estimated Period of Repair: 2.0 days

Adjuster: Muhammad Nazril Bin Abdullah

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DISK	Serviceable	140.00 FL	*- FL
2	1		*FRONT WHEEL AXLE	Serviceable	75.00 FL	*- FL
3	1		*LEFT FORK ASSEMBLY	Serviceable	390.00 FL	*- FL
4	1		*FRONT FAIRING COVER INNER	Scratched	150.00 FL	*150.00 FL
5	1		*LEFT FAIRING ASSEMBLY	Cracked	270.00 FL	*270.00 FL
6	1		*RIGHT FAIRING ASSEMBLY	Scratched	270.00 FL	*270.00 FL
7	1		*LEFT FAIRING ASSEMBLY LABELS	Necessary	65.00 FL	*65.00 FL
8	1		*RIGHT FAIRING ASSEMBLY LABELS	Necessary	65.00 FL	*65.00 FL
9	2		*YAMAHA EMBLEM	Necessary	40.00 FL	*40.00 FL
10	1		*LOWER CENTRE COVER	Broken	120.00 FL	*120.00 FL
11	1		*LEFT SIGNAL ASSY	Scratched	75.00 FL	*75.00 FL
12	2		*STEERING STEM BEARING	Necessary	90.00 FL	*90.00 FL
13	1		*STEERING STEM BRACKET ASSEMBLY	Serviceable	195.00 FL	*- FL
14	1		*HANDLE BAR	Bent	135.00 FL	*135.00 FL
15	1		*BRAKE LEVER	Scratched	40.00 FL	*40.00 FL
16	1		*RIGHT VIEW MIRROR	Scratched	40.00 FL	*40.00 FL
17	1		*RIGHT BALANCER	Scratched	35.00 FL	*35.00 FL
18	1		*GEAR PEDAL ASSY	Bent	75.00 FL	*75.00 FL
19	1		*RIGHT SIDE REAR COVER	Scratched	120.00 FL	*120.00 FL
20	1		*RIGHT REAR FOOTREST	Scratched	45.00 FL	*45.00 FL
21	1		*FRONT FOOTREST HOLDER ASSEMBLY	Broken	145.00 FL	*145.00 FL
22	1		*EXHAUST ASSY	Repair	380.00 FL	*- FL
23	1		*LEFT FRONT FOOTREST	Bent	45.00 FL	*45.00 FL
24	1		*RIGHT FRONT FOOTREST	Scratched	45.00 FL	*45.00 FL
25	1		*BRAKE PEDAL ASSY	Scratched	55.00 FL	*55.00 FL
26	1		*FRONT SPORT RIM	Serviceable	350.00 FS	*- FS
27	1		*BOX RACK	Serviceable	350.00 FS	*- FS
28	1		*FRONT MUDGUARD	Scratched	98.00 FL	*98.00 FL
29	1		*HEADLAMP COVER	Scratched	55.00 FL	*55.00 FL
30	1		*FRONT BODY FAIRING	Scratched	95.00 FL	*95.00 FL
31	1		*CENTRE BODY COVER	Cracked	65.00 FL	*65.00 FL
32	1		*EXHAUST BLACK COVER	Scratched	98.00 FL	*98.00 FL
33	1		*EXHAUST SILVER COVER	Scratched	75.00 FL	*75.00 FL
34	1		*FRONT NUMBER PLATE	Necessary	15.00 FS	*15.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,306.00	2,426.00
- List Item Discount on L Items 10.00/10.00% (S\$)	359.10	241.10
Total Parts (S\$)	3,946.90	2,184.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	EXHAUST REPAIR	New	150.00	100.00
2	TOWING CHARGES	New	100.00	80.00
3	DISMANTLE, REPLACE, REALIGN AND ADJUST ABOVE DAMAGED PARTS	New	700.00	200.00
4	TO KNOCK, STRAIGHTEN CHASSIS & BODY BALANCING	New	380.00	0.00
5	TO REMOVE / REFIT, REPLACE (IF DAMAGE) CHECK AND STRAIGHTEN FRONT FORK TUBES	New	180.00	0.00
6	TO REMOVE / REFIT, REPLACE (IF DAMAGE) CHECK AND REPLACE FRONT SPORT RIM	New	180.00	0.00
7	SPRAY PAINTING	New	250.00	100.00
Gross Labour Cost (S\$)			1,940.00	480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >