

22/03/2002

ASS. REC. BY:

REF: CS3/CT11904585/R2CF3 Special Instruction:

Surveyor: Rasul

ASSIGNMENT (Office)

From (Person): Glane Cheong

of C12

Date/Time: 7.10.19 13.26 p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

PC1275L

Insured:

SJY 75045

at Workshop m/s

MSM Logistic

Tel:

91074212

of 160 Sn ming Drive #03-08

Policy No: DMPCSX3056011900

Claim No: SNM190204617602

Sum Insured:

Excess:

D.O.A. 1.10.2019

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 7.10.19 1.41 p.m

Person Contacted:

Joann Tan

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	Insured 160 Sn Drw #01-12
	PC 1275L - X
	SJY 75045 - X
	Dismantle: 8/10/2019

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Oct 2019		07 Oct 2019 13:23 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:									
Main Claimant: COMMUTOR - PLUS EXPRESS PTE LTD, Co. Reg. No.: 52807178E									
Vehicle Reg. No.:		PC1275L	Date of Loss:	01/10/2019 05:00 - :59					
Claim Type:		TP / SNM19D204617C02	Policy/Cover Note No.:	DMPCSN3056011900					
Vehicle Reg. No. (Insured):		SJY7504S	Policy No. (Claimant):	5084957714-02					
		Excess:	S\$0.00						
Repairer: Msm Logistics Pte Ltd- Sin Ming (HQ) 160 Sin Ming Drive #03-08 Sin Ming Auto City, 575722 Sin Ming - Tel: 91074212									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]									
Claimant's Insurer: NTUC Income Insurance Co-operative Ltd (HQ) - Tel:									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 16/10/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Summer Lee (LKK Auto)

From: Elaine Cheong <elaine.cheong@sg.cntaiping.com>
Sent: Monday, 7 October, 2019 1:18 PM
To: 'Hong Kuin'; assignments
Cc: Claims Dept of CTI
Subject: RE: YOUR REF: SNM19D204617-SJY7504S-CML- 1st Notice to conduct pre-repair survey (Our Ref: PC 1275L/MSM/ca/hk)
Attachments: RE:YOUR REF: SNM19D204617-SJY7504S-CML- 1st Notice to conduct pre-repair ... (245 KB)

WITHOUT PREJUDICE

Dear Hong Kuin,

We refer to your email of 07.10.19.

We are not agreeable to your proposed surveyors and will still assign our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below with attachment and liaise with third party workshop accordingly.

Thank you.

Regards,

Elaine Cheong
Executive (Motor Claims)
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389 6530
Fax: 6224 7478 / 6224 7175
Email: elaine.cheong@sg.cntaiping.com
Website: www.sg.cntaiping.com

From: Hong Kuin [mailto:accident@kscgp.com]
Sent: Monday, 7 October, 2019 1:13 PM
To: Elaine Cheong <elaine.cheong@sg.cntaiping.com>
Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: RE: YOUR REF: SNM19D204617-SJY7504S-CML- 1st Notice to conduct pre-repair survey (Our Ref: PC 1275L/MSM/ca/hk)
Importance: High

Dear Elaine,

We refer to the above matter and to our email dated 4 October 2019 below

Your surveyors has yet to attend at our client's workshop to-date.

Please contact Ms Joann at 9107 4212 to arrange for the inspection urgently.

All our clients' right remain strictly reserved.

Thank you.

Regards,

Hong Kuin

for and on behalf of Mr Gurdeep Singh Sekhon

KSCGP Juris LLP

10 Hoe Chiang Road

#13-03A Keppel Towers

Singapore 089315

Tel: 6538 3611 / DID: 3152 0989 / Fax: 6538 3708

Email: accident@kscgp.com

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

From: Accident@kscgp.com [<mailto:Accident@kscgp.com>]

Sent: Friday, October 4, 2019 3:52 PM

To: elaine.cheong@sg.cntaiping.com

Cc: claimsdept@sg.cntaiping.com

Subject: RE:YOUR REF: SNM19D204617-SJY7504S-CML- 1st Notice to conduct pre-repair survey (Our Ref: PC 1275L/MSM/ca/hk)

Dear Sirs,

We refer to the matter above and your email of even date.

Please see enclosed our 2nd Notice to Conduct Pre-Repair Survey. Our client is not agreeable to your proposed motor surveyors as a Single Joint Expert.

The workshop details are as follows:

MSM Logistics Pte Ltd

160 Sin Ming Drive,

#01-12 Sin Ming Autocity,

Singapore 575722

Contact person: Joann (9107 4212)

Thank you.

Regards,

for and on behalf of Mr Gurdeep Singh Sekhon
KSCGP Juris LLP
10 Hoe Chiang Road
#13-03A Keppel Towers
Singapore 089315
Tel: 6538 3611 / DID: 3152 0989 / Fax: 6538 3708
Email: accident@kscgp.com

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

----- Original Message -----

From: Elaine Cheong [<mailto:elaine.cheong@sg.cntaiping.com>]
To: accident@kscgp.com
Cc: claimsdept@sg.cntaiping.com
Sent: Fri, 4 Oct 2019 06:20:39 +0000
Subject:

WITHOUT PREJUDICE

Dear Hong Kuin,

We refer to your email of 02.10.19.

We would like to conduct pre-repair survey of the vehicle at the appointed workshop.

We propose the following list of surveyors to be nominated as the Single Joint Expert to conduct survey of the claimant's vehicle:-

1. ADRIAN LING	6. KENNETH KONG
2. Kelvin Ang	7. SIMON HO
3. SEE CHEW SENG	8. CHUA WEIJIE
4. MOHD FADHILAH BIN OSMAN	9. MARCUS CHUA
5. XING QUO QIANG	10. HENRY NG

If we do not hear from you within two days of this letter, you shall have deemed to have agreed that the surveyor appointed by us shall be Single Joint Expert for this matter.

As per the NIMA Protocol, the survey by our appointed surveyor would include survey of your vehicle pre-repair, after it is dismantled, and post repairs. Hence, you need to provide us / our surveyors with the list of items that were damaged and required to be replaced or repaired to facilitate an effective survey.

As stated above, please inform us and our surveyor after the claimant's vehicle had been repaired so that our surveyor can carry out post repair inspection before the vehicle is returned to your client. Please co-ordinate with our surveyor immediately after the repair is completed.

Regards,

Elaine Cheong
Executive (Motor Claims)
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389 6530
Fax: 6224 7478 / 6224 7175
Email: elaine.cheong@sg.cntaiping.com
Website: www.sg.cntaiping.com

From: Hong Kuin [<mailto:accident@kscgp.com>]

Sent: Wednesday, 2 October, 2019 2:33 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Elaine Cheong <elaine.cheong@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>

Subject: RE: OUR REF: SNM19D204617-SJY7504S-CML- 1st Notice to conduct pre-repair survey (Your Ref: SJY 7504S; Our Ref: PC 1275L/MSM/ca/hk)

Dear Sir/Mdm,

We refer to your email of even date.
Please let us have your proposed list of surveyors, for our client's consideration.

In the meantime, the workshop's details are as follows: -

MSM Logistics Pte Ltd
160 Sin Ming Drive,
#01-12 Sin Ming Autocity,
Singapore 575722

Contact person: Joann (9107 4212)

Thank you.

Regards,
Hong Kuin
for and on behalf of Mr Gurdeep Singh Sekhon
KSCGP Juris LLP
10 Hoe Chiang Road
#13-03A Keppel Towers
Singapore 089315
Tel: 6538 3611 / DID: 3152 0989 / Fax: 6538 3708
Email: accident@kscgp.com

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or

entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

From: Claims Dept of CTI [<mailto:claimsdept@sg.cntaiping.com>]

Sent: Wednesday, October 2, 2019 2:26 PM

To: Elaine Cheong; Alfred Toh; Chee So Chow; Accident@kscgp.com

Subject: OUR REF: SNM19D204617-SJY7504S-CML- 1st Notice to conduct pre-repair survey (Your Ref: SJY 7504S; Our Ref: PC 1275L/MSM/ca/hk)

Dear Elaine,

Please conduct PRS for PC1275L.

Note : officer in charge - Elaine Cheong 63896530.

Thank you

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Hong Kuin [<mailto:accident@kscgp.com>]

Sent: Wednesday, October 02, 2019 9:58 AM

To: Claims Dept of CTI

Subject: 1st Notice to conduct pre-repair survey (Your Ref: SJY 7504S; Our Ref: PC 1275L/MSM/ca/hk)

Dear Sirs,

We enclose herewith our 1st Notice to conduct pre-repair survey for your necessary action.

Thank you.

Regards,

Hong Kuin

for and on behalf of Mr Gurdeep Singh Sekhon

KSCGP Juris LLP

10 Hoe Chiang Road

#13-03A Keppel Towers

Singapore 089315

Tel: 6538 3611 / DID: 3152 0989 / Fax: 6538 3708

Email: accident@kscgp.com

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or

entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

This email has been scanned by the MxScan Email Security System.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the MxScan Email Security System.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	01/10/2019 10:52
Date Of Accident	01/10/2019 05:30
Exact Location Of Accident	ORCHARD RD TURNING TO SLIP RD OF MOUNT ELIZABETH H
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	PC1275L
Insured/Policyholder	
Name Of Registered Owner	COMMUTOR - PLUS EXPRESS PTE LTD
Co Reg No	52807178E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90691234
Alternative Phone No	OFFICE-90691234
Vehicle Particulars	
Manufacturer	TOYOTA
Model	HIACE-3.0 D HIGH-ROOF 14 SEATER (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	BUS
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5084957714-02
Cover Note Number	
Driver	
Name of Driver	ONG CHIN HUAT
NRIC No	S1434105F
Date Of Birth	24/05/1960
Occupation	OUTDOOR
Date Of Driving Pass	13/01/1987
Driving Experience	32 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82889710
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

 **COMMUTER-PLUS EXPRESS**
Policyholder's Signature Date
& Time: **01 OCT 2019**


Driver's Signature
(If driver is not the policyholder) Date
& Time: **01 OCT 2019**


Reporting Centre Personnel's Signature
Name: **Venus Lee**
NRIC/FIN No.: **S7488991A**

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	178E
Vehicle Details	
Vehicle No.:	PC1275L
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Oct 2019
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA HIACE HIROOF AUTO 14 SEATER
Primary Colour:	White
Manufacturing Year:	2012
Engine No.:	1KD2169699
Chassis No.:	JTFST22P000013232
Maximum Power Output:	-
Open Market Value:	\$37,122.00
Original Registration Date:	16 Mar 2012
First Registration Date:	16 Mar 2012
Transfer Count:	3
Actual ARF Paid:	\$1,857.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	15 Mar 2022
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$38,699.00
COE Rebate Amount:	\$9,570.00
Total Rebate Amount:	\$9,570.00

The information contained herein is correct as at 08 Oct 2019

OK

28,000
9,570

18,430

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Oct 2019		07 Oct 2019 13:23 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	-, Co. Reg. No.: -		
Main Claimant:	COMMUTOR - PLUS EXPRESS PTE LTD, Co. Reg. No.: 52807178E		
Vehicle Reg. No.:	PC1275L	Date of Loss:	01/10/2019 05:00 - :59 [90 Months and 15 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D204617C02	Policy/Cover Note No.:	DMPCSN3056011900
Vehicle Reg. No. (Insured):	SJY7504S	Policy No. (Claimant):	5084957714-02
		Excess:	S\$0.00
Repairer:	Msm Logistics Pte Ltd- Sin Ming (HQ) 160 Sin Ming Drive #03-08 Sin Ming Auto City, 575722 Sin Ming - Tel: 91074212		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 16/10/2019]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									















































Claim Documents

***PC1275L (SNM19D204617C02)**
[SJY7504S]
TP
COMMUTOR - PLUS EXPRESS PTE LTD
Oct 1 2019 5:00AM
[-]
Msm Logistics Pte Ltd- Sin Ming

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)





















[View](#)
[View in Browser](#)

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lim Tan Motor Pte Ltd (HQ)	Thumbnail	Print
1	01/10/19 11:09	Accident Statement	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lim Tan Motor Pte Ltd (HQ)	Thumbnail	Print
1	01/10/19 11:05	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	01/10/19 11:05	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	01/10/19 11:05	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	01/10/19 11:05	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
5	01/10/19 11:05	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
6	01/10/19 11:05	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
7	01/10/19 11:05	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
8	01/10/19 11:05	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
9	01/10/19 11:07	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
10	01/10/19 11:07	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
11	01/10/19 11:07	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
12	01/10/19 11:07	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
13	01/10/19 11:07	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
14	01/10/19 11:07	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
15	01/10/19 11:07	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
16	01/10/19 11:07	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
17	01/10/19 11:07	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/10/19 17:22	General View	Load JPG	<input checked="" type="checkbox"/>
2	10/10/19 17:22	General View	Load JPG	<input checked="" type="checkbox"/>
3	10/10/19 17:22	General View	Load JPG	<input checked="" type="checkbox"/>
4	10/10/19 17:22	General View	Load JPG	<input checked="" type="checkbox"/>
5	10/10/19 17:22	General View	Load JPG	<input checked="" type="checkbox"/>
6	10/10/19 17:22	General View	Load JPG	<input checked="" type="checkbox"/>
7	10/10/19 17:22	General View	Load JPG	<input checked="" type="checkbox"/>
8	10/10/19 17:22	General View	Load JPG	<input checked="" type="checkbox"/>
9	10/10/19 17:22	General View	Load JPG	<input checked="" type="checkbox"/>
10	10/10/19 17:22	General View	Load JPG	<input checked="" type="checkbox"/>
11	10/10/19 17:22	General View	Load JPG	<input checked="" type="checkbox"/>
12	10/10/19 17:22	General View	Load JPG	<input checked="" type="checkbox"/>
13	10/10/19 17:22	General View	Load JPG	<input checked="" type="checkbox"/>
14	10/10/19 17:22	General View	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lim Tan Motor Pte Ltd (HQ)	Thumbnail	Print
15	10/10/19 17:22	General View	 Load JPG	<input checked="" type="checkbox"/>
16	10/10/19 17:22	General View	 Load JPG	<input checked="" type="checkbox"/>
17	10/10/19 17:22	General View	 Load JPG	<input checked="" type="checkbox"/>
18	10/10/19 17:22	General View	 Load JPG	<input checked="" type="checkbox"/>
19	10/10/19 17:22	General View	 Load JPG	<input checked="" type="checkbox"/>
20	10/10/19 17:22	General View	 Load JPG	<input checked="" type="checkbox"/>
21	10/10/19 17:22	General View	 Load JPG	<input checked="" type="checkbox"/>
22	10/10/19 17:22	General View	 Load JPG	<input checked="" type="checkbox"/>
23	10/10/19 17:22	General View	 Load JPG	<input checked="" type="checkbox"/>
24	10/10/19 17:22	General View	 Load JPG	<input checked="" type="checkbox"/>
25	10/10/19 17:22	General View	 Load JPG	<input checked="" type="checkbox"/>
26	10/10/19 17:22	General View	 Load JPG	<input checked="" type="checkbox"/>
27	10/10/19 17:22	General View	 Load JPG	<input checked="" type="checkbox"/>
28	10/10/19 17:22	General View	 Load JPG	<input checked="" type="checkbox"/>
29	10/10/19 17:22	General View	 Load JPG	<input checked="" type="checkbox"/>
30	10/10/19 17:22	General View	 Load JPG	<input checked="" type="checkbox"/>
31	10/10/19 17:22	General View	 Load JPG	<input checked="" type="checkbox"/>
32	10/10/19 17:22	General View	 Load JPG	<input checked="" type="checkbox"/>
33	10/10/19 17:22	General View	 Load JPG	<input checked="" type="checkbox"/>
34	10/10/19 17:22	General View	 Load JPG	<input checked="" type="checkbox"/>
35	10/10/19 17:22	General View	 Load JPG	<input checked="" type="checkbox"/>
36	10/10/19 17:22	General View	 Load JPG	<input checked="" type="checkbox"/>
37	10/10/19 17:22	General View	 Load JPG	<input checked="" type="checkbox"/>
38	10/10/19 17:22	General View	 Load JPG	<input checked="" type="checkbox"/>
39	10/10/19 17:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	10/10/19 17:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	10/10/19 17:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	10/10/19 17:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	10/10/19 17:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	10/10/19 17:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	10/10/19 17:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	10/10/19 17:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	10/10/19 17:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	10/10/19 17:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	10/10/19 17:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	10/10/19 17:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	10/10/19 17:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	10/10/19 17:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	10/10/19 17:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	10/10/19 17:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	10/10/19 17:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	10/10/19 17:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	10/10/19 17:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	10/10/19 17:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	10/10/19 17:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	10/10/19 17:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	10/10/19 17:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	10/10/19 17:22	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
63	10/10/19 17:22	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
64	10/10/19 17:22	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
65	10/10/19 17:22	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
66	10/10/19 17:22	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
67	10/10/19 17:22	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lim Tan Motor Pte Ltd (HQ)	Thumbnail	Print
68	10/10/19 17:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	10/10/19 17:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	10/10/19 17:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	10/10/19 17:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	10/10/19 17:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	07/10/19 13:24	PRS - PC1275L	 Load PDF	
No	Finalized On	Lim Tan Motor Pte Ltd (HQ)	Thumbnail	Print
1	01/10/19 11:02	Sketch Plan [Linked Accident Report Documents]	 Load TIF	
2	01/10/19 11:02	Sketch Plan #2 [Linked Accident Report Documents]	 Load TIF	


Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lim Tan Motor Pte Ltd (HQ)	Thumbnail	Print
1	01/10/19 11:09	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lim Tan Motor Pte Ltd (HQ)	Thumbnail	Print
1	01/10/19 11:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	01/10/19 11:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	01/10/19 11:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	01/10/19 11:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	01/10/19 11:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	01/10/19 11:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	01/10/19 11:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	01/10/19 11:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	01/10/19 11:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	01/10/19 11:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	01/10/19 11:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	01/10/19 11:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
13	01/10/19 11:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
14	01/10/19 11:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
15	01/10/19 11:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
16	01/10/19 11:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
17	01/10/19 11:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lim Tan Motor Pte Ltd (HQ)	Thumbnail	Print
1	01/10/19 11:02	Sketch Plan	 Load TIF	
2	01/10/19 11:02	Sketch Plan #2	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:  Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19017585/R1CF3S2
Date: 14/10/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3056011900	
Claimant Vehicle No :	PC1275L	Insured Vehicle No :	SJY7504S	
Date of Loss:	01/10/2019	Nature of Claim:	TP	Claim No: SNM19D204617C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC1275L		Engine No:	1KD2169699
Make & Model:	TOYOTA HIACE, 3.0 D High-roof 14 Seater (A)		Chassis No:	JTFST22P000013232
Reg. Date:	16/03/2012 (Man. Year: 2012)		Odometer:	425557 km
Colour:	White			
Engine Capacity:	2982 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	07/10/2019		160 Sin Ming Drive #01-12
Date Inspected:	07/10/2019	Inspected At:	Singapore 575722
			Repairer: MSM Logistics Pte Ltd
Estimated Period of Repair:	5.0 days		

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000.00 - \$6,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 14 Oct 2019)

Parts: 213 TOYOTA HIACE 3.0 D High-roof 14 Seater (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for PC1275L)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >