



Case Details

Case Reference Number : BUS/09/19/5054
 Type of Repair : Accident Repair
 Vehicle Registration Number : SMB1475S

Company Type : SMRT Buses Ltd
 Estimation ID : EST-8769-ID
 Assigned By : Claiming Case Owner Team

Insurance Company Name : India International Insurance Pte Ltd
 Accident Date and Time : 23/09/2019 09:25 AM
 Vehicle Age(In Months) : 60

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main	BODY LH	6009999	PANEL, SIDE: L5, FOR MAN A22 BUS	1	1,776.80	1,776.80	100.00	0.00	Repair	1	0.00	Repair	XR
Total Spare Part Cost									0.00		Surveyor Total		0.00	
Lump Sum Discount (%)									0.00		Lump Sum Dis (%)		0	
Final Spare Part Cost									0.00		Final Sur Total		0.00	

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR ALL AFFECTED AREA	530.00	265	
Total:			530.00	265.00	


Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO PUTTY & RESPRAY	708.00	538	
Total:			708.00	538.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	ADVERTISEMENT STICKER	480.00	480.00	
Total:			480.00	480.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	0.00	0.00
Total Labour Cost	530.00	265.00
Total Spray Painting	708.00	538.00
Other	480.00	480.00
Overall Total	1,718.00	1,283.00
Lump Sum Repair Option	☐	☐
Lump Sum Total	0.00	1,283.00
Surveyor Approved Amount		1,283.00
No of Repair Days*	3	2
Remarks	-	lumpsum repair, take aft spray
Surveyor Name		STEVE CHEN
Signature		 Save Clear
Survey Date	07/10/2019	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: