

Surveyor: Kalvin

ASSIGNMENT (Office)

From (Person): Crystal Lu

of MSIG

Date/Time: 7.10.19 5.00p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / ENV / MV / CS

To Inspect Vehicle No: YP 1918 R

Insured: SLL 8839P

at Workshop m/s Efficient Motor

Tel: 92399009

of 56 Longang way #06-07

Policy No: A29114756 MKF

Claim No: 607781

Sum Insured:

Excess:

Make of Veh:

D.O.A. 25.9.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 7.10.19 5.13p.m

Person Contacted:

Mr Eric

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	YP 1918 R - X
	SLL 8839 P - X
11/10/19	Send preli. revised via meriman

(08/11/13)

REF:

Surveyor: Kalvin

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspected Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: YP 1918RYr Regn: 7 Apr, 2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mitsubishi Canter c.c. 2998Colour: White A/C: Insured / Std / NI / NASp. Reading: 154845 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: FEB2EA20336

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size: F: 195 / 85 R17

R: _____

BS / DUN / EXNOVA / CY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Double star

Front

Rear

R/Bal. 4 mm R/Bal. 4-5 mmL/Bal. 4 mm L/Bal. 4-5 mmD.O.A. 25/4/19 D.O.I. 10/10/19Survey held at Elmhurst Mh

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

n/s Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

22/10/19 Chs L/S \$ 2150 / 3 Rep. (Red 1892.93, 4710) MSH

RECEIVED 22 OCT 2019

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 22/10 - typistReport Format: merimenLump Sum / I.B.I: (\$) 2150/2Days Of Repair: 3Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

150
11
161

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Koh Ming Shao

Date: 11 Oct 2019

Preliminary Advice

Insured Vehicle No	: SLL8839P	Accident Date	: 25/09/2019
TP Vehicle No	: YP1918R	Assignment Date	: 08/10/2019
Make	: MITSUBISHI CANTER	Est. Duration of Repair	: 3.00
Date of Inspection	: 10/10/2019		
Inspection At	: EFFICIENT MOTOR & ENGINEERING WORKS PTE LTD (HQ) 56 LOYANG WAY #06-07, LOYANG ENTERPRISE BUILDING SINGAPORE 508775		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,042.93
Revised Amount	:S\$	3,082.73
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,082.73

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Oct 2019		08 Oct 2019 16:06 Edit Adj Rpt		Last: IA 11 Oct 2019 10:06		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
[Created by insurer]									
CLAIM SUBFOLDER DETAILS									
Insured:	GRAB RENTALS PTE.LTD., Co. Reg. No.: 201617200G								
Main Claimant:	PAN PACIFIC VAN & TRUCK LEASING PTE LTD, Co. Reg. No.: 201511635R								
Vehicle Reg. No.:	YP1918R	Date of Loss:	25/09/2019 14:00 - :59 [35 Months and 18 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 607781	Policy/Cover Note No.:	A29114756MKF (Comprehensive) Coverage: 26/08/2019 - 31/01/2020						
Vehicle Reg. No. (Insured):	SLL8839P	Policy No. (Claimant):							
		Excess:	S\$2,000.00						
Repairer:	Efficient Motor & Engineering Works Pte Ltd (HQ) 56 Loyang Way #06-07, Loyang Enterprise Building, 508775 Loyang - Tel: 63416758 / 62840827								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Koh Ming Shao - 6594 2546]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN] ... [Final Rpt due 07/11/2019]								
Driver/Custodian (Insured):	KWEK CHIANG MIANG (57 / Male) , NRIC: S1505084E, Tel: +6598155110 Email:								
Adj Asg. Remarks:	on WP. Manual assigned to LKK via email on 07/10/19. (Manual Assign). OI:Grab. Liab: unclear. Agree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: Mr Eric Kee @ 9239 9009.								
View All Compose Case Mail									
ASSOCIATED MAIL RECEIVED									
There are no mail for this case.									
View All Search Tasks Create New Task Complete									
ALL ASSOCIATED TASKS									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Summer Lee (LKK Auto)

From: Crystal Lee <crystal_lee@sg.msig-asia.com>
Sent: Monday, 7 October, 2019 5:02 PM
To: Admin-D (LKKAuto); assignments
Cc: Ong Zi Hui
Subject: FW: SURVEY INVITATION for accident on 25/09/2019 at Sims Dr Open Carpark (in frt of Blk 42) involving vehicles YP1918R & SLL8839P (GRAB)

SURVEY INVITATION for accident on 25/09/2019 at Sims Dr Open Carpark (in frt of Blk 42) involving vehicles YP1918R & SLL8839P (GRAB)

Manual Assigned

Dear LKK,

Refer to the email below, please arrange survey the vehicle.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment

Thank you & Best regards,
Crystal Lee
Admin Officer, Claims Services (In-House Survey)
D: +65 6594 2535 | F: +65 6643 1349 | crystal_lee@sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Helene Phua
Sent: Monday, 7 October, 2019 4:26 PM
To: Crystal Lee <crystal_lee@sg.msig-asia.com>; Ong Zi Hui <zihui_ong@sg.msig-asia.com>
Subject: FW: SURVEY INVITATION for accident on 25/09/2019 at Sims Dr Open Carpark (in frt of Blk 42) involving vehicles YP1918R & SLL8839P (GRAB)

Have a great week ahead!

Helene Phua
Admin Assistant, Claims Services
D: +65 6594 2493 | F: +65 6225 7402 | helene_phua@sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Helene Phua

Sent: Monday, 7 October, 2019 4:26 PM

To: 'efficient loyang' <efficientloyang@gmail.com>

Cc: Koh Ming Shao <MingShao_Koh@sg.msig-asia.com>

Subject: RE: SURVEY INVITATION for accident on 25/09/2019 at Sims Dr Open Carpark (in frt of Blk 42) involving vehicles YP1918R & SLL8839P (GRAB)

Hi,

Thank you for your selection.

We will proceed to assign LKK Auto Consultants Pte Ltd via Merimen at our end and update you upon confirmation.

Please do not contact them directly to prevent confusion. Any arrangement or appointment of surveyor must come from MSIG.

Please be informed that our surveyor will also be conducting a post repair inspection within the stipulated timeline under the protocol.

Have a great week ahead!

Helene Phua

Admin Assistant, Claims Services

D: +65 6594 2493 | F: +65 6225 7402 | helene_phua@sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: efficient loyang [<mailto:efficientloyang@gmail.com>]

Sent: Monday, 7 October, 2019 3:40 PM

To: Helene Phua <helene_phua@sg.msig-asia.com>

Subject: Re: SURVEY INVITATION for accident on 25/09/2019 at Sims Dr Open Carpark (in frt of Blk 42) involving vehicles YP1918R & SLL8839P (GRAB)

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Hi

Please appoint LKK auto to survey the mentioned vehicle

Thank you
Regards
Eric

On Mon, 7 Oct 2019, 14:25 Helene Phua, <helene_phua@sg.msig-asia.com> wrote:

Hi,

We refer to your email dated 07/10/2019.

Please choose one surveyor from the list that you wish for us to appoint to conduct the pre-repair inspection:

- 1) LKK Auto Consultants Pte Ltd
- 2) Formteam Consultancy Pte Ltd
- 3) A-Pac Adjusters & Surveyors Pte Ltd
- 4) STA Inspection Pte Ltd
- 5) Appraisal VP Pte Ltd
- 6) AutoProbe Consultants
- 7) **MSIG In-House Surveyors**

This Fast-Lane settlement option is for clear-cut liability which MSIG will expedite offer @ 100% with express payment. Priority will be given to those opted for our in-house surveyor

To facilitate an expeditious claim settlement, we hope you are agreeable for the above surveyor to be the SJE (Single Joint Expert).

If not, you may wish to nominate any of the 10 surveyors listed below as the SJE, depending on their availability:

1) Calvin Ang	6) Chow Bo Xiong
2) Kenneth Kong	7) Siew Meng Hui
3) Marcus Chua	8) Daniel Chan
4) Ng You Han	9) Victor Png
5) Gary Soon	10) Samuel Phun

In your response, please also provide us a list of 10 surveyors as your nominated SJE, regardless of whether you agree or disagree to our above nominated SJE. We may consider appointing one of your nominated SJE in case of any of our nominated SJE is not available.

NB:

(a) ***Fast lane settlement is not applicable for cases that liability is in dispute***

(b) If both of us could not agree with each other's list of nominated SJE, we may still proceed to appoint a motor surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.

We have created a dedicated motor survey mailbox for your motor survey request and pre-repair inspection. Please contact us (MSIG) by clicking this link: motorsurvey@sg.msig-asia.com

Have a great week ahead!


Helene Phua

Admin Assistant, Claims Services

D: +65 6594 2493 | F: +65 6225 7402 | helene_phua@sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



From: efficient loyang [<mailto:efficientloyang@gmail.com>]

Sent: Monday, 7 October 2019 12:16 PM

To: Motor Survey <motorsurvey@sg.msig-asia.com>; Claims <claims@sg.msig-asia.com>

Cc: Eric <eric@panpacificleasing.com.sg>

Subject: SURVEY INVITATION for accident on 25/09/2019 at Sims Dr Open Carpark (in frt of Blk 42) involving vehicles YP1918R & SLL8839P

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Dear Claim Officer,

We refer to the above matter.

We are the appointed repair workshop of vehicle no. YP1918R.

We understand that you are the insurer of vehicle no. SLL8839P.

The owner of the vehicle no. YP1918R has authorised us to carry out the repairs to their vehicle which was damaged by your insured's vehicle. The owner intends to make a claim against your insured and/or insured's authorised driver for the accident which is caused wholly and /or contributed by your insured and/or your insured's authorised driver's negligence.

We hereby give you notice of the accident and an opportunity to inspect the damages to the vehicle prior to the commencement of the repair.

Contact Person: Mr Eric Kee H/P: 9239 9009

Best Regards,

Mas Ariyanti

Efficient Motor & Engineering Works Pte Ltd

56 Loyang Way #06-07 Loyang Enterprise Building, S(508775)

Tel: 6284 0827 Fax: 6341 6758

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/09/2019 17:10
Date Of Accident	25/09/2019 14:00
Exact Location Of Accident	SIMS DRIVE OPEN CARPARK (IN FRT OF BLK 42)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YP1918R
Insured/Policyholder	
Name Of Registered Owner	PAN PACIFIC VAN & TRUCK LEASING PTE LTD
Co Reg No	201511635R
Email Address	EFFICIENTLOYANG@GMAIL.COM
Mobile Phone No	
Alternative Phone No	OFFICE-62840827

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	CANTER-3.0 D FEB21 (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	18-MJ001454-R00
Cover Note Number	

Driver

Name of Driver	MUHAMMAD ASHRAF BIN DAUD
NRIC No	S9710960E
Date Of Birth	03/04/1997
Occupation	OUTDOOR
Date Of Driving Pass	26/06/2018
Driving Experience	1 YEAR AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96690234
Fax Number	
Contact Number	
Email Address	NOEMAIL

R12g Tkpts
PP201908-000001
BXCESS \$2500
Inexp Ania \$3k.
AD 1909032-250919.
TP Insurer: MSIG

Address	BLK 438 JURONG WEST AVE 1 #01-408
Postcode	640438
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : AIDIL GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO STATEMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLL8839P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE HIRE
Name of Driver	KWEK CHIANG MIANG
NRIC/Passport Number	S1505084E
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

[Signature]


Driver's Signature
(If driver is not the policyholder)
Date & Time:

25/09/2019 18.00



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving my vehicle^A to block 42 for some delivery job with my colleague. I found a parking lot and decide to park my vehicle. I on my hazard light as there's vehicle^B behind me and I proceed to reverse into the parking lot. While reversing but before I complete parking the vehicle B tried to overtake from the left. He collided into my LH door. The impact cost damage to both vehicle. It was raining quite heavy.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

EFFICIENT MOTOR & ENGINEERING WORK PTE LTD

56 LOYANG WAY # 06-07 ENTERPRISE BUILDING SINGAPORE 508775

VEHICLE NO : YP1918R

MAKE & MODEL : MITSUBISHI FUSO CANTER

CHASSIS NO : FEB21EA20336

DATE : 08/10/2019

CLAIM TYPE : TP CLAIM

TO : MSIG INSURANCE (SINGAPORE) PTE LTD

PARTS DESCRIPTION

QTY UNTIL PRICE AMOUNT

- LIST ITEMS
- 1 LH FRONT DOOR *B.M.S*
 - 2 LH STEP GARNISH *x repr*
 - 3 LH FRONT BUMPER GUIDE *cut*

1	\$	2,071.55	\$	2,071.55
1	\$	622.44	\$	622.44
1	\$	353.71	\$	353.71

TOTAL :	\$	3,047.70	\$	3,047.70
LESS 10% <i>25%</i>	\$	304.77	\$	304.77
TOTAL :	\$	2,742.93	\$	2,742.93

TOTAL PARTS : \$ 2,742.93 \$ 2,742.93

LABOUR

- 1 LABOUR FOR PANEL BEATING
- 2 LABOUR FOR SPRAYPAINTING
- 3 WIRNG
- 4 LABOUR FOR TRANSFER ALL LH FRONT DOOR FITTING

	\$	600.00 <i>400</i>
	\$	500.00 <i>400</i>
	\$	50.00 <i>20</i>
	\$	150.00 <i>80</i>
TOTAL :	\$	1,300.00

TOTAL PARTS AND LABOUR : \$ 4,042.93

PREPARE BY:

Eric S
11/10/19

Kalir, HKG

10/10/19

3 Day

4s
After Repair

1700h

Acknowledged by Repairer
Signature: _____
Date: _____

4582150

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19017636/K1VF3N2

Date: 24/10/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A29114756MKF
Claimant Vehicle No :	YP1918R	Insured Vehicle No :	SLL8839P
Date of Loss:	25/09/2019	Nature of Claim:	TP
		Claim No:	607781

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YP1918R	Engine No:	4P10C06497
Make & Model:	MITSUBISHI CANTER, 3.0 D FEB21ER3SDEB (CBU) (M)	Chassis No:	FEB21EA20336
Reg. Date:	07/04/2016 (Man. Year: 2016)	Odometer:	154845 km
Colour:	White		
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/85R15 LT	Rear Tyre Size:	195/85R15 LT (D)
Front Left Side:	Double Star 4 mm	Rear Left Side:	Double Star 4/4 mm
Front Right Side:	Double Star 4 mm	Rear Right Side:	Double Star 4/4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,742.93	1,818.94	923.99	33.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,300.00	900.00	400.00	30.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,042.93	2,718.94	1,323.99	32.75
Approved Total (Overridden) (S\$)		2,150.00		
(S\$)	4,042.93	2,150.00	1,892.93	46.82
+ GST 7.00/7.00% (S\$)	283.01	150.50	132.51	46.82
Nett Amount (S\$)	4,325.94	2,300.50	2,025.44	46.82

INSPECTION

Date of Assignment:	08/10/2019	
Date Inspected:	10/10/2019 Inspected At:	Efficient Motor & Engineering Works Pte Ltd (HQ)

56 Loyang Way #06-07, Loyang
Enterprise Building
Singapore 508775

Estimated Period of Repair: 3.0 days

Adjuster: KALVIN ANG WEI KUN

Manager: VERON CHEN

Adjuster Report

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 23 Oct 2019)	
Parts:	N/A	MITSUBISHI CANTER 3.0 D FEB21ER3SDEB (CBU) (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YP1918R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH FRONT DOOR	Buckled	2,071.55 FL	*2,071.55 FL
2	1		*LH STEP GARNISH	Repair	622.44 FL	*- FL
3	1		*LH FRONT BUMPER GUIDE	Cut	353.71 FL	*353.71 FL
					Sub Total (S\$)	2,425.26
					- List Item Discount on L Items 10.00/25.00% (S\$)	606.32
					Total Parts (S\$)	1,818.94

F=Franchise part, L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING	New	600.00	400.00
2	LABOUR FOR SPRAYPAINTING	New	500.00	400.00
3	WIRING	New	50.00	20.00
4	LABOUR FOR TRANSFER ALL LH FRONT DOOR FITTING	New	150.00	80.00
Gross Labour Cost (\$\$)			1,300.00	900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >