

2200/2001

ASS. REC. BY:

REF: CS3/CT118018623/G9037

and instructions:

Supervisor: Guo Qiang

ASSIGNMENT (Office)

From (Person): Zhong Hsien

of Ray Louis Law

Date/Tu: 30/07/2019

Estimated Cost:

Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No: GBD1786P

Insured: YN 8201P

at Workshop m/s: Alpha Car Services

Tel: 65096258

of 1 kaki 3rd Ave 6 # 01-59

Policy No: DMCVSN3054361801

Claim No: 8NM18D04837C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 07/10/2018

CA / REV / REP. / REV 24 HRS hup

H.O.D. Enforcement:

Date/Time: 11:58am @ 15/10/18 Person Contacted: cai ling

Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

GBD1786P - NA / CT118018623/13

DA: 7/10/2018

YN 8201P - NA / CT118018623/13

DA: 7/10/2018

Dismantle: 16/10/2018

check MV

\$2450, 4 Days.

(Red \$7150, 74%)

AAV \$36K (est); VA: 7895; NV: \$28105

[Signature]
4/10/2019

RECEIVED 07 OCT 2019

1107
Xed

REF: 91

COB762 /

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop no: **Alpha Car**

of _____

Insured _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection

Bal. or Market Value: **\$36K.**

IDAC Accident Report: _____ Consistent? Yes or No

GIA / PR Seen: _____ Consistent? Yes or No

Est. Repairs: **4** days Res: Yes or No

Lump Sum: **20** % 3 Val: Yes or No

CA / REV / REP / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT



Sub No: **GBD1786P** V/Type: **16 Jul 2014**

Type: M/Car / M/Cycle / Bus / Van / **Truck** / Taxi / Prime Mover /

Truck / Trailer or _____

Make: **Nissan Cabstar** cc: **2953**

Colour: **Blue** A/C: Insured / Std / NI / NA

Sp Reading: **70245** T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **JNISC2F 24Z 0855762**

Gen Cond: **Good** / Fair / Poor / Burnt

Steering: **In** / Jammed / Leaked / Burnt or

Brake: **In** / Jammed / Leaked / Burnt or

Mod: **Al** / S/Rim / STD A/Rim or

Tyre Size: F: **195 R15**
R: **155 R13**

(F/R) **ES / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /**

TOYO / YOKO or **Condor (Rear)**

Front: _____ Rear: _____

R/Bal: **5** mm R/Bal: **5/45** mm

L/Bal: **5** mm L/Bal: **5/45** mm

D.O.A: _____ D.O.I: **15-10-18**

Survey held at: **w/s**

Des. of Damages: **Fr / Rear** / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision:

Date / Time: _____ Action / Instruction: _____

\$3000 - \$4000

COE: 7895

Date/Time: File Pass to? : Prel. Report

: Final Report

Days Of Repair: **4**

Resurvey No. of Trip: **1**

Survey Fee: _____

Transportation: _____

Add Fee: Site Insp: \$5

Interview: \$5

Tach. Invs: \$5

Wheel-bal: \$5

Report Format: **PRG.**

Lump Sum / LB.1: ()

Celine Fong (LKKAuto)

From: admin@raylouis.com.sg
Sent: Tuesday, 1 October 2019 9:00 AM
To: Admin-D (LKKAuto); justice@raylouis.com.sg
Cc: ray@raylouis.com.sg; assignments
Subject: RE: Request to conduct re-inspection to GBD 1786P; Our Ref: RL/GEN/207

Dear Sirs,

Your email of 24 September 2019 refers.

Please proceed with paper resurvey on the claimant's vehicle.

Please advise the lead time in coming up with the resurvey report.

Thank you.

For and on behalf of Mr Raphael Louis

Yours sincerely,
Ong Zhong Hsien (Mr.)
Legal Executive



(Reg No 201416160D)



 [101 Upper Cross Street, #06-05,
People's Park Centre
Singapore 058357](#)
 +65 6557 2725
 +65 6532 0023
 ray@raylouis.com.sg
 www.raylouis.com.sg

This email, its content and any files transmitted with it are intended solely for the addressee(s) and are legally privileged and/or confidential. Access by any other party is unauthorized, without the express written permission of the sender. If you have received this email in error, you may not copy or use the contents, attachments or information in any way. This email has been prepared using information believed by the author to be reliable and accurate, but Ray Louis Law Corporation makes no warranty as to accuracy or completeness.

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Tuesday, September 24, 2019 6:12 PM
To: admin@raylouis.com.sg; justice@raylouis.com.sg
Cc: ray@raylouis.com.sg; assignments <assignments@lkkauto.com>
Subject: RE: Request to conduct re-inspection to GBD 1786P; Our Ref: RL/GEN/207

Dear Sir/Mdm,

Apologize for the late reply.

Please be informed that we are able to conduct a paper resurvey on the claimant's vehicle and the cost of the resurvey report is as below :

Paper survey charges : \$350.00 (Before GST).

Nivitha (LKK Auto)

From: admin@raylouis.com.sg
Sent: Tuesday, 30 July 2019 2:47 PM
To: assignments@lkkauto.com
Cc: Ray Louis Law
Subject: Request to conduct re-inspection to GBD 1786P
Attachments: 207 letter to LKK - 30.07.19.pdf; police report of YN 8201P.pdf; GIA report GBD 1786P.pdf; rental docs.pdf; CL Appraiser survey report.pdf

Dear Sirs,

Please find attached our letter of even date for your kind attention.

Due to the large file size of the attachments, we will split the attachments into a few emails.

For and on behalf of Mr Raphael Louis

Yours sincerely,

Ong Zhong Hsien (Mr.)

Legal Executive



(Reg No 201418169G)



 [101 Upper Cross Street, #06-05,
People's Park Centre
Singapore 058357](#)
 +65 6557 2725
 +65 6532 0023
 ray@raylouis.com.sg
 www.raylouis.com.sg

This email, its content and any files transmitted with it are intended solely for the addressee(s) and are legally privileged and/or confidential. Access by any other party is unauthorized, without the express written permission of the sender. If you have received this email in error, you may not copy or use the contents, attachments or information in any way. This email has been prepared using information believed by the author to be reliable and accurate, but Ray Louis Law Corporation makes no warranty as to accuracy or completeness.



RAY LOUIS LAW

CORPORATION

Advocates & Solicitors

101 Upper Cross Street, #06-05,
People's Park Centre, Singapore 058357

T : 6557 2725

F : 6532 0023

E : ray@raylouis.com.sg ; admin@raylouis.com.sg

Date 30 July 2019
Our Ref RL/GEN/207
Your Ref To be advised
No of pages 1

LKK AUTO CONSULTANTS
51 Ubi Avenue 1
#01-25 Paya Ubi Industrial Park
Singapore 408933

BY EMAIL
(assignments@lkkauto.com)


Dear Sirs,

**REQUEST TO CONDUCT REINSPECTION TO GBD 1786P
ACCIDENT INVOLVING GBD 1786P & YN 8201P ON OR ABOUT 7 OCTOBER
2018 AT OR ALONG KJE SLIP ROAD TOWARDS CHOA CHU KANG WAY**

1. We refer to the above matter whereby we act for M/s ISO Integrated M&E Pte Ltd ("our client").
2. We are assisting our client, the owners of YN 8201P to defend a property damage claim commenced by the owner of GBD 1786P in relation to the above captioned accident.
3. We are instructed to engage your good office to conduct a re-inspection on GBD 1786P. In your re-inspection report, we shall be grateful if you could consider amongst other things, the following questions:
 - a. Whether it is economical/justifiable for the owners of GBD 1786P to effect repairs to their vehicle taking into account the market value of the vehicle at the time of accident of 7 October 2018, remaining life span, COE/PARF etc;
 - b. The estimated costs of repairs and number of days for repairs to GBD 1786P, as well as the reason(s) for the same;
 - c. Even as you carry out the re-inspection, to also look into whether the parts that were allegedly repaired/replaced actually carried out; and

- d. In relation to the pricing of the allegedly replaced parts/components and/or labour, whether you would be able to give us your comments on the pricing.
4. In light of the above, we attach herein, the relevant documents as below:-
 - a. Vehicle inspection report from CL Appraiser Pte Ltd dated 31 October 2018 together with supporting photographs showing damage to GBD 1786P (colour photographs to be provided once available);
 - b. Rental invoice/agreement from 159 Vehicle Rental LLP dated 19 October 2018 for the period of 8 October 2018 to 19 October 2018 for \$1,320.00;
 - c. GIA report of the driver of GBD 1786P filed on 8 October 2018;
 - d. Police report of Subramaniyan Pushparaju, the driver of YN 8201P filed on 17 May 2019;
 - e. Coloured photographs taken at the accident scene;
 5. Meanwhile, please also let us know the fees/costs chargeable for the re-inspection and preparation of the re-inspection report.
 6. We will keep you informed once the solicitors acting for GBD 1786P confirms the availability of the re-inspection.
 7. Please let us hear from you on the above soonest possible.
 8. Thank you.

Yours faithfully,



Ray Louis Law Corporation

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0676Z
Vehicle Details	
Vehicle No.:	GBD1786P
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Oct 2018
Vehicle Make:	NISSAN
Vehicle Model:	CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5
Primary Colour:	Blue
Manufacturing Year:	2014
Engine No.:	ZD30338479K
Chassis No.:	JN15C2F24Z0855762
Maximum Power Output:	-
Open Market Value:	\$25,081.00
Original Registration Date:	16 Jul 2014
First Registration Date:	16 Jul 2014
Transfer Count:	0
Actual ARF Paid:	\$1,255.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	15 Jul 2024
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$13,741.00
COE Rebate Amount:	\$7,895.00
Total Rebate Amount:	\$7,895.00

The information contained herein is correct as at 16 Oct 2018

OK

CL APPRAISER PTE LTD

24 Peshurst Place, Singapore 556440
Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783
Reg No: 201000228E

VEHICLE INSPECTION REPORT

To: Chiam Garden Landscape & Construction Pte Ltd
C/o: Alpha Car Services Pte Ltd
No.1 Kaki Bukit Ave 6 #01-59
Kaki Bukit AutoBay, Singapore 417883

Date : 31 October 2018
Our ref : ACS/10/1802/TP

Accident Date : 07 October 2018
Inspection Date : 08 October 2018
Repairer Name : Alpha Car Services Pte Ltd
No.1 Kaki Bukit Ave 6 #01-59
Kaki Bukit AutoBay, Singapore 417883

Type of Survey : Third Party

PARTICULARS OF VEHICLE

Registration No : GBD 1786 P
Make / Model : Nissan Cabstar
Chassis No : JN1SC2F24Z0855762
Engine No : ZD30338479K

Year / Capacity : 2014 / 2953 cc
Colour : Blue
Mileage : 70234

CONDITION OF TYRES

	Make	Size	Thread Balance	Rim
Front Nearside	: Bridgestone	195 R15	5 mm	Sport
Front Offside	: Bridgestone	195 R15	5 mm	Sport
Rear Nearside	: Condor	155 R13	5 mm	Sport
Rear Offside	: Condor	155 R13	5 mm	Sport

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the rear portion.
(Details refer to the photographs attached)

Enclosed number of photographs: 81 copies

REMARKS

This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis and we have not given authorization and instruction to the repairer to proceed with the repair

RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a **Lump Sum of \$ 9,600.00** on a contractual basis.

Under normal circumstances, the repair period would be about 11 (Eleven) working days.

SC L APPRAISER PTE LTD

Vehicle Registration No: GBD 1786 P

Our Ref No: ACS/10/1802/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
-----	-------------	------------	---------------------	----------------

SPARE PARTS - NETT ITEMS

1	Rear tailgate	Damage	\$ 1,939.10	\$ / 1,939.10 / 299.7
2	Rear tailgate lock hinges	Damage	\$ 297.00	\$ / 297.00 / 119
1	Rear tailgate "NISSAN" sticker	Necessary	\$ 105.80	\$ / 105.80
2	Rear tailgate stopper brackets	Damage	\$ 327.20	\$ X 327.20 X SVC
2	Rear tailgate stopper rubbers	Damage	\$ 85.00	\$ X 85.00 X SVC
2	Rear taillamps	Damage	\$ 915.60	\$ 915.60 / 225
1	Rear number plate panel	Damage	\$ 89.50	\$ X 89.50 X SVC
1	Rear floor panel	Damage	\$ 1,538.00	\$ X 1,538.00 X SVC
2	Rear side gates	N/S Damage	\$ 4,403.80	\$ X 2,201.90 X Repair
1	Front n/s door rear pillar	Damage	\$ 970.00	\$ X 970.00 X Repair
			\$ 10,671.00	\$ 8,469.10
		Less 10%	\$ 1,067.10	\$ 846.91
	Total Cost - Nett Items		\$ 9,603.90	\$ 7,622.19

SPECIAL NETT ITEMS

1	Rear tailgate "70KM/H" sticker	Necessary	\$ 25.00	\$ 25.00 / 10
1	Rear tailgate "6PAX" sticker	Necessary	\$ 25.00	\$ 25.00 / 10
1	Rear number plate	Damage	\$ 45.00	\$ 45.00 X SVC
1	Rear reverse sensor (1 set)	Damage	\$ 350.00	\$ 350.00 / 200
	Total Cost - Special Nett items		\$ 445.00	\$ 445.00 / 220

1849.5

10% = 1664.55

Total cost of parts

\$ 10,048.90 \$ 8,067.19

SC L APPRAISER PTE LTD

Vehicle Registration No: GBD 1786 P

Our Ref No: ACS/10/1802/TP

S/No	Description	Repairer's Estimate	Revised Amount
	Total cost of parts c/f	\$ 10,048.90	\$ 8,067.19

LABOUR

1	To remove, refit, replaced damaged lamps and check up rear electrical wiring	\$ 80.00	\$ 50.00 30
2	To remove and refit rear reverse sensor.	\$ 120.00	\$ 80.00 40
3	To apply undercoating on repaired and replaced panel.	\$ 200.00	\$ 150.00 X
4	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld ; re-align body structure and damaged consistent to the accident.	\$ 1,800.00	\$ 1,500.00 600
5	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$ 1,600.00	\$ 1,320.00 500
6	To straighten rear chassis frame member and re-align chassis frame.	\$ 800.00	\$ X 800.00 1170
GRAND TOTAL		\$ 14,648.90	\$ <u>11,967.19</u>

3054.55
20%: 2450

C L APPRAISER PTE LTD

Vehicle Registration No: GBD 1786 P

Our Ref No: ACS/10/1802/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a **Lump Sum Repair Contract of : \$ 9,600.00**

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notified the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deem to be valid.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.

C L APPRAISER PTE LTD



Cheong K. H
Automotive Appraiser



RAY LOUIS LAW

CORPORATION

Advocates & Solicitors

101 Upper Cross Street, #06-05,
People's Park Centre, Singapore 058357

T : 6557 2725

F : 6532 0023

E : ray@raylouis.com.sg ; admin@raylouis.com.sg

Date 30 July 2019
Our Ref RL/GEN/207
Your Ref To be advised
No of pages 1

LKK AUTO CONSULTANTS

51 Ubi Avenue 1
#01-25 Paya Ubi Industrial Park
Singapore 408933

BY EMAIL

(assignments@lkkauto.com)


Dear Sirs,

**REQUEST TO CONDUCT REINSPECTION TO GBD 1786P
ACCIDENT INVOLVING GBD 1786P & YN 8201P ON OR ABOUT 7 OCTOBER
2018 AT OR ALONG KJE SLIP ROAD TOWARDS CHOA CHU KANG WAY**

1. We refer to the above matter whereby we act for M/s ISO Integrated M&E Pte Ltd ("our client").
2. We are assisting our client, the owners of YN 8201P to defend a property damage claim commenced by the owner of GBD 1786P in relation to the above captioned accident.
3. We are instructed to engage your good office to conduct a re-inspection on GBD 1786P. In your re-inspection report, we shall be grateful if you could consider amongst other things, the following questions:
 - a. Whether it is economical/justifiable for the owners of GBD 1786P to effect repairs to their vehicle taking into account the market value of the vehicle at the time of accident of 7 October 2018, remaining life span, COE/PARF etc;
 - b. The estimated costs of repairs and number of days for repairs to GBD 1786P, as well as the reason(s) for the same;
 - c. Even as you carry out the re-inspection, to also look into whether the parts that were allegedly repaired/replaced actually carried out; and

- d. In relation to the pricing of the allegedly replaced parts/components and/or labour, whether you would be able to give us your comments on the pricing.
4. In light of the above, we attach herein, the relevant documents as below:-
- a. Vehicle inspection report from CL Appraiser Pte Ltd dated 31 October 2018 together with supporting photographs showing damage to GBD 1786P (colour photographs to be provided once available);
 - b. Rental invoice/agreement from 159 Vehicle Rental LLP dated 19 October 2018 for the period of 8 October 2018 to 19 October 2018 for \$1,320.00;
 - c. GIA report of the driver of GBD 1786P filed on 8 October 2018;
 - d. Police report of Subramaniyan Pushparaju, the driver of YN 8201P filed on 17 May 2019;
 - e. Coloured photographs taken at the accident scene;
5. Meanwhile, please also let us know the fees/costs chargeable for the re-inspection and preparation of the re-inspection report.
6. We will keep you informed once the solicitors acting for GBD 1786P confirms the availability of the re-inspection.
7. Please let us hear from you on the above soonest possible.
8. Thank you.

Yours faithfully,



Ray Louis Law Corporation

159 Vehicle Rental LLP

Blk 1 Kaki Bukit Ave 6 #01-54 Autobay@ Kaki Bukit
Singapore 417883
68429089
Company Registration No. T16LL1863K

INVOICE

INVOICE TO

Chiam Garden Landscape &
Construction Pte Ltd
22 Tampines Road
Singapore 535071

INVOICE NO. 1248

DATE 19/10/2018

AGREEMENT NO.

0253

ACTIVITY	QTY	RATE	AMOUNT
GBA9644D (T. Dyna)			1,320.00

Rental Period : 8/10/18 - 19/10/18 (11 days)

Rental Rate : \$120 / day

All cheques should be made payable to "159 Vehicle Rental LLP".

BALANCE DUE

S\$1,320.00

Issued By :



159 VEHICLE RENTAL LLP

1 Kaki Bukit Avenue 6 #01-54 AutoBay @ Kaki Bukit Singapore 417883
 Tel: 6842 9089 HP: 9048 0641 Fax: 6841 2669
 Email: admin@tickhalmotor.com

VRA No.: 0253

ROC No: T16LL1863K

VEHICLE RENTAL AGREEMENT

HIRER'S PARTICULAR

Name: (as in I/C) Chiam Fanden Landscape & Construction P/L

NRIC/PASSPORT No: 200006762

Address (Res) 22 Tampines Road Singapore 535071

Name & Address of Employer _____

Occupation: _____ Driving Exp: _____

Driving Licence No: _____ D/L Type: Local / International

Issue Date: _____ Date of Birth: _____

Tel: (O): _____ (F) _____ HP _____

ADDITIONAL DRIVER'S PARTICULARS

Name: (as in I/C) NA BAK SENJA

NRIC/PASSPORT No: S0182005B

Address (Res): Bik 118 Yishun Ring Road
#02-659 Singapore 760118.

Driving Licence No: S0182005B D/L Type: Local / International

Issue Date: 20/10/1972 Date of Birth: 13/06/1952

Occupation: _____ Driving Exp: 45y 11 mths.

Vehicle No: G8A9644 Replace Veh No: G8D 1786 P

Mileage Out: _____ Mileage Out: _____

Make & Model: T. Dyna Auto / Manual: _____
 Group: _____

Out : Date 8/10/18 Time: 9.50am

HIRE / PERIOD EXPIRY _____ Time: _____

NON-WAIVER EXCESS=\$ 2500

CHARGES

Daily 11 @ \$ 120 per day 1320 00

Weekly @ \$ _____ per week

Monthly @ \$ _____ per month

Hours @ \$ _____ per hour

Others @ \$ _____

CDW @ \$ _____ per day/month

PAI @ \$ _____ per day/month

Delivery/Collection Service _____

SUB-TOTAL \$ _____

PETROL LEVEL

Out E 1/4 1/2 3/4 F _____

In E 1/4 1/2 3/4 F _____


EXTENSION

Misc. _____

TOTAL CHARGES \$ 1320 00

VEHICLE CHECK LIST

INDICATE:
 D - DENTS
 S - SCRATCHES
 A - ACCIDENTS




ACCESSORIES CHECK

- Ashtray Cig Lighter S/Tyre
 STD Tools Jack Hub Caps
 Radio/Cass CD Cartridges

Hirer's Signature _____

Additional Driver's Signature _____



I have read and agree to the terms and condition on both sides of the agreement, if i have presented a charge/credit card for payment. I agree that all amounts payable under this agreement and for parking and traffic infringements may be billed to that account and my signature above will be considered to have been made on the charge/credit card voucher. All information I have given 159 VEHICLE RENTAL LLP in connection with this agreement is true.

* IMPORTANT

- ONLY PERSON ABOVE 22 YEARS OF AGE WITH MORE THAN 2 YEARS DRIVING EXPERIENCE, AUTHORISED, LICENSED AND SIGNING THIS AGREEMENT MAY DRIVE THE VEHICLE.
- ALL PARKING AND TRAFFIC VIOLATIONS ARE THE RESPONSIBILITY OF THE HIRER. AN ADMINISTRATIVE CHARGE WILL BE LEVIED ON ANY TRAFFIC VIOLATIONS REDIRECTED.
- THE HIRER SHALL BE LIABLE FOR EXCESS CHARGES FOR ANY LATE RETURN AT THE RATE SHOWN PER HOUR OR PER DAY, INCLUSIVE OF CDW AND/OR PAI WHERE APPLICABLE.
- IN CASE OF ACCIDENT, THE HIRER SHALL REPORT TO RENTAL OFFICE IMMEDIATELY, IF THERE IS BODILY INJURIES, A POLICE REPORT MUST BE MADE WITHIN 24 HOURS.
- VEHICLE IS STRICTLY FOR SINGAPORE USE ONLY, AND MAY NOT BE DRIVEN OUT OF SINGAPORE WITHOUT PRIOR CONSENT OF THE COMPANY 159 VEHICLE RENTAL LLP

RETURN OF VEHICLE. THE HIRER/DRIVER IS REQUIRED TO SIGN IN THE COLUMN * SINGAPORE OF HIRER / DRIVER * FAILING WHICH THE DAY AND TIME INSERTED BELOW SHALL DEEMED TO BE THE DAY AND TIME THE VEHICLE IS RETURNED TO 159 VEHICLE RENTAL LLP AND THE SAME SHALL BE ACCEPTED AS CONCLUSIVE EVIDENCE OF THE SAME AND SHALL NOT BE CHALLENGED OR QUESTIONED ON ANY ACCOUNT WHATSOEVER.

DATE IN	TIME IN	MILEAGE	CHECKED BY	REMARKS	SIGNATURE OF HIRER/DRIVER
13/10	1.15 PM		Beckham	Rear door? OK	

Alpha Car Services Pte Ltd

ALPHA

Blk C, Kaki Bukit Ave 6 #01-59, Kaki Bukit Autobay, Singapore 417883

Tel: 6509 8258 Email: alphacarservices@hotmail.com

ROC No. 201717633Z

**Chiam Garden Landscape &
Construction Pte Ltd**

(200000676Z)

C/O. BLK C Kaki Bukit Avenue 6

#01-59 Autobay @ Kaki Bukit

Singapore 417883

INVOICE

Date: 19/11/2018

Vehicle No: GBD 1786P

Make/Model: Nissan Cabstar 3.0

Chassis/Engine No: ZD30338479K

Acc. Date: 07/10/2018

Claim No.: 1810-0178 IC (GBD 1786P)ONG.

Ref Policy No.: DMCVSN3044961803

	Amount S\$
Inclusive of Supplying Parts and labour, Panel beating and spray painting	9,600.00
Repairs Costs	9,600.00

SGD NINE THOUSAND AND SIX HUNDRED ONLY.



ALPHA CAR SERVICES PTE LTD

ALPHA



**SINGAPORE
POLICE FORCE**



G/20190517/2043

1 of 3

POLICE REPORT (NP299)

Report No. G/20190517/2043

Police Station Of Origin
Tampines N.P.C
6 Tampines Avenue 4 SINGAPORE 529682
Tel No: 1800-5871999


Date/Time Report Made 17/05/2019 12:40	Vide Report No.	Station Diary No. 43
Name Of Informant SUBRAMANIYAN PUSHPARAJU	Address C/O 519 OLD CHOACHU KANG #09-167 SUNGEI TENGAH LODGE SINGAPORE	
ID Type / ID No. FIN NO / G6948496X	Contact No. Home/Office	Mobile 83455966
Nationality INDIAN	Email Address	
Occupation ELECTRICIAN	Sex Male	Age 34
Institution/School Name	Date of Birth 07/04/1985	Race Indian
Date/Time Of Incident 30/04/2019 00:00	Location Of Incident KRANJI EXPRESSWAY SINGAPORE	

Brief details.

On 07/10/2018 , at about 9:45am , I was involved in an accident with another lorry GBD1786P while I was driving Company's lorry (YN8201P). At that point of time , I was alone and do not have any passengers on board. The weather was Sunny, dry road surface and traffic volume was moderate. I was driving along KJE Slip Road towards Choa Chu Kang Way at about 10 to 20km/hr at that point of time. As I was at the slip road and making a check for any oncoming vehicles , a lorry (GBD1786P) in front of me had suddenly came to a complete stop despite the lorry had already went out of the give way line as such , my lorry had collided onto the rear of the lorry (GBD1786P). After the accident had occurred , we had

Signature Of Officer Recording The Report: G / Staff Sgt CHAN DE MING	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 17/05/2019 12:40
Officer In-Charge Of Case: G / Bedok Police Divisional Investigation Branch / Insp IBNU QAYYIM BIN NAWAWI Contact No.: 62440000	Classification Of Case:

Authentication Stamp





exchanged particulars. There is no in-car camera recording in my company's lorry. No ambulance or traffic police had attended to us as well as there is no one injured. I had taken several photograph of the incident too, I had also noticed that there was a front passenger and a driver in the lorry (GBD1786P). After the accident , a supervisor and a car service staff (Alpha Car Services Pte Ltd , namely Derrick Lim , HP: 82889809) had came down to incident location. Derrick Lim had told me not to worry and told me that I can go off. As I think that it was a minor accident, I did not inform my company on the matter as well.

On 30/04/2019, my company namely ISO Landscape located at "8 Changi North Street 1" had received a lawyer letter from "Actus Legal LLP" on claiming damages on lorry amounting to SGD\$12680.35/- due to the accident that occurred between my company lorry and other party lorry. We had send an appeal letter as the claim amount was too much.


On 15/05/2019 , my company had received medical claim from a lawyer company (AL&T) for two company(Chiam Garden Landscape Construction Pte Ltd) workers namely Mondol Sapon (Passenger), and Ng Bak Seng (S0182005B , Driver) with the claim amount of SGD\$18333.50/- and SGD\$18359.99 respectively. However , my project administrator namely Ng Hwee Yen (HP: 92308469) had realized that the location of accident stated on both the medical claim lawyer letter were different.

On 16/05/2019 , my company received another letter to inform me that the company was not agreeable to the settlement offer but the amount of claim for the lorry damages had decreased to SGD\$11480.35/-.

I am lodging this police report as I believe there is false claim and my company have inform my insurance

Signature Of Officer Recording The Report: G / Staff Sgt CHAN DE MING	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 17/05/2019 12:40
Officer In-Charge Of Case: G / Bedok Police Divisional Investigation Branch / Insp IBNU QAYYIM BIN NAWAWI Contact No.: 62440000	Classification Of Case:

Authentication Stamp





**SINGAPORE
POLICE FORCE**



G/20190517/2043

3 of 3

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. G/20190517/2043

company on the matter as well.

Signature Of Officer Recording The Report:

G / Staff Sgt CHAN DE MING

Signature Of Informant:

Signature Of Interpreter:
Not applicable


Date/Time:
17/05/2019 12:40

Officer In-Charge Of Case:
G / Bedok Police Divisional Investigation Branch /
Insp IBNU QAYYIM BIN NAWAWI
Contact No.: 62440000

Classification Of Case:

Authentication Stamp

 <p>SINGAPORE POLICE FORCE</p>	
<p>_____ SIGNATURE</p>	



SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:



Driver's Signature 8/10/18
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

I WAS TRAVELLING FROM OLD CHOA CHU KANG SLIP RD TWDS CHOA CHU KANG WAY ON THE LEFT LANE OF A2-LANES RD. AFTER I PASSED THE ZEBRA CROSSING I LOOK UP FOR ONCOMING VEH ON THE RIGHT SIDE OF THE MAIN ROAD. SUDDENLY INFRT OF MY VEH STOP AFTER HIS VEH OUT FROM THE GIVEWAY LINE, I HAVE NOT ENOUGH TIME TO REACT AND MY VEH HIT ONTO THE REAR PORTION OF VEH B.



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/10/2018 12:29
Date Of Accident	07/10/2018 09:45
Exact Location Of Accident	KJE SLIP ROAD TOWRS CCK WAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBD1786P
Insured/Policyholder	
Name Of Registered Owner	M/S CHIAM GARDEN LANDSCAPE & CONSTRUCTION PTE LTD
Co Reg No	200000676Z
Email Address	CHIAMGARDEN@LIVE.COM
Mobile Phone No	(LOCAL) +65-92379788
Alternative Phone No	OFFICE-92379788

Vehicle Particulars

Manufacturer	NISSAN
Model	CABSTAR-3.0 5M/T ABS 2DR 2WD EURO 5 (A)

Exact Purpose for which vehicle was being used at time of accident	TO WORK
--	---------

Are you claiming under your own insurance policy for repair to your vehicle?	NO
--	----

If No, Please state action to be taken	THIRD PARTY
--	-------------

Vehicle Category	GOODS VEHICLE
------------------	---------------

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCVSN3044961803
Cover Note Number	

Driver

Name of Driver	NG BAK SENG
NRIC No	S0182005B
Date Of Birth	13/06/1952
Occupation	OUTDOOR
Date Of Driving Pass	20/10/1972
Driving Experience	45 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96336657
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address BLK 118 YISHUN RING ROAD #02-659
 Postcode 760118
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1
 NAME: : MONDOL SAPON
 GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

AS PER SKETCH PLAN ATTACHED. ***ADDENDUM - AMEND PASSENGER'S NAME FROM MONDOC SAPON TO MONDOL SAPON*** ***ADDENDUM - AMEND VEHICLE REG NO FROM XE9903A TO YN8201P***

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YN8201P
 Vehicle Make/Model/Colour LORRY
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	NG BAK SENG
Approximate Age	66
Injuries Sustain	
Injured person in which vehicle?	GBD1786P
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	BLK 118 YISHUN RING #02-659
Postcode	760118

DETAILS OF INJURED PERSON 2

Name	MONDOL SAPON
Approximate Age	30
Injuries Sustain	
Injured person in which vehicle?	GBD1786P
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to reassess policy liability.
 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time: 8/10/18 11:00



Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



VEH A : GBD 1786D
 VEH B : XE 9903 A-

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was getting out into the slip rd turning into C-c-lc way. As I was about to turn a big truck hit into the rear of my veh. Causing my veh to surge forward. I myself and my pass had neck and back pain due to the accident.

DECLARATION

I/We declare the foregoing details are true in every respect.

Policyholder's Signature

Date & Time:
 8/10/18
 11-00



Driver's Signature

(If driver is not the policyholder)
 Date & Time:

[Handwritten signature]

Reporting Centre Signature

Name:
 NRIC/PIH No.:





中国太平保險(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Co. Reg. No. 200302394E

NR300/C
R 3H
AN0420A
Cov. Type: C

MOTOR COMMERCIAL VEHICLE

CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 188)
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1987
Road Transport Act, 1987 (Malaysia)
Motor Vehicles (Third-Party Risks) Rules, 1999 (Malaysia)

ORIGINAL

CERTIFICATE No.	2PKVdr3044861803	Engine No : 2D30338479x CHRB01JWLS2F2420851762
1. Index Mark and Registration Number of Vehicle	QNL726P	AUTOGRAFE
2. Name of Policy Holder	M/S OGDAN GARDEN LANDSCAPE & CONSTRUCTION PTE LTD	
3. Effective date of the Commencement of Insurance for the purposes of the Regulations, Ordinance or Enactment	18 July 2018	EXCESS SECT 1 \$500.00 EX ON WINDSCREEN \$300.00
4. Date of Expiry of Insurance	15 July 2019	
5. Persons or Classes of Persons entitled to drive*	Any person who is driving on the policyholder's order or with their permission. Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor vehicle.	
6. Limitations as to use†	(1) Use in connection with the policyholder's business. (2) Use for the carriage of passengers (other than for hire or reward) in connection with the policyholder's business. (3) Use for social, domestic or pleasure purposes. The policy does not cover: (1) use for hire or reward or racing, pace-making, reliability trial or speed testing. (2) use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.	


HERE PURCHASED BY: HIYACHI CAPITAL SINGAPORE PTE LTD AS IF OWNER
*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 188) and Section 95 of the Road Transport Act 1987 (Malaysia), are not to be included under these headings.

I/We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 188) and Part IV of the Road Transport Act, 1987 (Malaysia).


Please see reverse

For CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Issued By:  THONGREX INVESTMENT SERVICES PTE LTD
Authorized Officer


Authorized Signatory

Driver



AMENDED SKETCH PLAN Pg. 1

GENERAL INSURANCE ASSOCIATION RECORDS MANAGEMENT CENTRE

GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
5 Raffles Quay #15-02 Singapore 048520
Tel (65) 6224 0010 Fax (65) 6224 0090
Operating Hours: Monday to Friday, 09:00 - 17:00
USN: S66092299 / GST Reg. No.: M49962726

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No: MCCA 18/30/40-01 Vehicle Registration No: G8D 1786 P
Name (as shown in NRIC): Chian Garden Landscape & Construction Pte Ltd NRIC/FIN/Passport No: 3000006762
Address: 2 Tampines Road Singapore (535071)
Contact (Tel): Mobile No: 9237 9788
Email Address: chianmgarden@live.com
Date of Accident: 07/10/2018 Time of Accident: 9:45 am
Place of Accident: KJE Slip Road towards CCK way.
Insurance Company: China Taiping Insurance (Singapore) Pte Ltd.

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

Amend Other Vehicle Reg No From XE 9903A to YN 8201P.

Policyholder / Driver's Signature
Date: 11/10/18
[Signature]



Reporting Centre Personnel's Signature
Name: Selby
NRIC/FIN No.: 51842
Date: 11/10/18
[Signature]



GENERAL INSURANCE ASSOCIATION
RECORDS MANAGEMENT CENTRE

GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
6 Raffles Quay #23-00 Singapore 048580
Tel (65) 6224 0010 Fax (65) 6224 0030
Operating Hours: Monday to Friday, 09:00 - 17:00
UEN: S66220220 / 017 Reg. No.: M40017788

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No: MCCA1810/40-01 Vehicle Registration No: G80 1786 P
NAME (as shown in NRIC): Chiam Garden Landscape & Construction Pte Ltd NRIC/FIN/Passport No: 30000676 Z
(*Vehicle-Driver / Vehicle Owner) (*) Please delete as appropriate
Address: 82 Tampines Road Singapore: 535071
Contact (Tel): _____ Mobile No.: 9337 9788
Email Address: chiamgarden@live.com
Date of Accident: 07/10/2018 Time of Accident: 9:45 am
Place of Accident: KJE Slip Road towards cck way.
Insurance Company: China Taiping Insurance (Singapore) Pte Ltd.

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

Amend Other Vehicle Reg No From XE 9903A to YN 8201P.

Policyholder / Driver's Signature

Date: 11/10/18

[Signature]



Reporting Centre Personnel's Signature

Name: Stacy
NRIC/FIN No.: 5184Z

Date: 11/10/18



[Signature]



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
8 Raffles Quay #12-00 Singapore 048580
Tel (65) 6224 0050 Fax (65) 6224 0050
Operating Hours : Monday to Friday, 09:00 - 17:00
MEN: 66880206 / GST Reg. No.: M40002735

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MCCA18130140 Vehicle Registration No: GBD 1786 P
Name (as shown in NRIC) : M2 CHIANG GARDEN LANDSCAPE & CONSTRUCTION P/L NRIC/FIN/Passport No : 2000 00676Z
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
Address : _____ Singapore ()
Contact (Tel) : _____ Mobile No. : 92379728
Email Address : chiangarden@live.com
Date of Accident : 07/10/2018 Time of Accident : 09:45 am
Place of Accident : KJE Slip Road Towards CCK way
Insurance Company: China Taiping Insurance

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

Amend passenger's Name from Mondoc Japan to
MONDOL SAPEH

Policyholder / Driver's Signature
Date:


Reporting Centre Personnel's Signature
Name: Seky
NRIC/FIN No.:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/10/2018 10:36
Date Of Accident	07/10/2018 09:45
Exact Location Of Accident	OLD CHOA CHU KANG RD SLIP RD TO CHOA CHU KANG WAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YN8201P
Insured/Policyholder	
Name Of Registered Owner	ISO-INTEGRATED M&E PTE LTD
Co Reg No	-
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-92717589

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	FUSO
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCVSN3054361801
Cover Note Number	

Driver

Name of Driver	SUBRAMANIYAN PUSHPARAJU
Passport No/FIN	G6948496X
Date Of Birth	07/04/1985
Occupation	OUTDOOR
Date Of Driving Pass	11/05/2018
Driving Experience	0 YEAR AND 4 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-83455966
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	8 CHANGI NORTH STREET
Postcode	498829
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBD1786P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	NG BAK SENG
NRIC/Passport Number	S0182005B
Contact Number	81718572
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (a) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time


Driver's Signature
(If driver is not the policyholder)
Date & Time


GIA Centre Personnel's Signature
Name
NRIC/TIN No.

Individual Statement

I WAS TRAVELLING FROM OLD CHOA CHU KANG SLIP RD TWDS CHOA CHU KANG WAY ON THE LEFT LANE OF A2-LANES RD. AFTER I PASSED THE ZEBRA CROSSING I LOOK UP FOR ONCOMING VEH ON THE RIGHT SIDE OF THE MAIN ROAD. SUDDENLY INFRT OF MY VEH STOP AFTER HIS VEH OUT FROM THE GIVEWAY LINE. I HAVE NOT ENOUGH TIME TO REACT AND MY VEH HIT ONTO THE REAR PORTION OF VEH B.

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Identification Card

REPUBLIC OF SINGAPORE DRIVING LICENCE

IC Number: **G6948496X**

SUBRAMANYAN PUSHPARAJU

DOB: 07 Apr 1983

Issue Date: 11 May 2010

Valid Till: 20052023

IC002-0017



WORK PERMIT
Department of Foreign Manpower Act (Chapter 114)
Republic of Singapore

Employer: **K&I AUTOMATED WARE PTE. LTD.**

Name: **SUBRAMANYAN PUSHPARAJU**

IC Number: **G6948496X**

Employment Sector: **CONSTRUCTION**

Age: **28**

Passport No: **87-24-1648**

Multiple Journey Visa Issued:

Valid Till: **2015-04-30**

IC002-0017



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

Class	Vehicle Class	Effective Date
Class 2F	Motorcycles - 200 cc	21 May 2010
Class 3F	Motor cars with variable engine capacity with 7 passenger seats or less	11 May 2010



VISIT PASS
Immigration Registration

Name: **SUBRAMANYAN PUSHPARAJU**

IC Number: **G6948496X**

Date of Birth: **07-04-1983**

Nationality: **INDIAN**

Multiple Journey Visa Issued:

Valid Till: **2015-04-30**

IC002-0017





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
RAY LOUIS LAW CORPORATION		Ref : CS3/CTI19013446/Gqd3e2-1	
101 UPPER CROSS STREET #06-05 PEOPLE'S PARK CENTRE SINGAPORE 058357 058357		Date : 08-10-2019	
		Code : L164	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	YN 8201P	Veh. Inspected	GBD 1786P
Policy No.	DMCVSN3054361801	Coverage (\$)	0.00
Claim No.	SNM18D04837C02	Excess (\$)	0.00
Assign From	ZHONG HSIEN	Assign Date	30/07/2019
2. Vehicle Particulars & Condition			
Make & Model	NISSAN CABSTAR	c.c	2953
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JN1SC2F24Z0855762	Colour	BLUE
Odometer	70245	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195 R15	BRIDGESTONE	5 mm
L/H Front Tyre	195 R15	BRIDGESTONE	5 mm
R/H Rear Tyre	155 R13	CONDOR	5/5 mm
L/H Rear Tyre	155 R13	CONDOR	5/5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	07/10/2018	Inspection Date	15/10/2018
Survey held at	ALPHA CAR SERVICES PTE LTD BLK C, KAKI BUKIT AVE 6 #01-59 KAKI BUKIT AUTOBAY SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBD 1786P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR TAILGATE	DAMAGED	1,939.10	1,399.70
2	REAR TAILGATE LOCK HINGES	DAMAGED	297.00	119.00
1	REAR TAILGATE "NISSAN" STICKER	NECESSARY	105.80	105.80
2	REAR TAILGATE STOPPER BRACKETS	SERVICEABLE	327.20	-
2	REAR TAILGATE STOPPER RUBBERS	SERVICEABLE	85.00	-
2	REAR TAILLAMPS	N/S CRACKED / O/S SERVICEABLE	915.60	225.00
1	REAR NUMBER PLATE PANEL	SERVICEABLE	89.50	-
1	REAR FLOOR PANEL	SERVICEABLE	1,538.00	-
2	REAR SIDE GATES	TO REPAIR SEE LABOUR	4,403.80	-
1	FRONT N/S DOOR REAR PILLAR	TO REPAIR SEE LABOUR	970.00	-
	LESS 10% DISCOUNT		-1,067.10	-184.95
			9,603.90	1,664.55
SPECIAL NETT ITEMS				
1	REAR TAILGATE "70KM/H" STICKER (SN)	NECESSARY	25.00	10.00
1	REAR TAILGATE "6PAX" STICKER (SN)	NECESSARY	25.00	10.00
1	REAR NUMBER PLATE (SN)	SERVICEABLE	45.00	-
1	SET REAR REVERSE SENSOR (SN)	DAMAGED	350.00	200.00
			445.00	220.00
LABOUR				
	TO REMOVE, REFIT, REPLACED DAMAGED LAMPS AND CHECK UP REAR ELECTRICAL WIRING.		80.00	30.00
	TO REMOVE AND REFIT REAR REVERSE SENSOR.		120.00	40.00
	TO APPLY UNDERCOATING ON REPAIRED AND REPLACED PANEL.	NOT NECESSARY	200.00	-
	TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS, REPAIR INCLUDING CUT AND WELD; RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR SIDE GATES AND FRONT N/S DOOR REAR PILLAR.		1,800.00	600.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RESPRAY PAINTING INCLUDE POLISHING AND WAXING ON THE CHANGED BODY PARTS, REPAIRED PORTIONS WHERE CONSISTENT TO THE ACCIDENT.	NOT NECESSARY	1,600.00	500.00
	TO STRAIGHTEN REAR CHASSIS FRAME MEMBER AND RE-ALIGN CHASSIS FRAME.		800.00	-
			4,600.00	1,170.00
GRAND TOTAL			14,648.90	3,054.55
RECOMMENDED COST OF LUMP SUM REPAIRS				2,450.00

Report Ref No. CS3/CT119013446/Gqd3e2-1

MARKET VALUE: \$36,000.00(EST)-LTA REIMBURSEMENT VALUE: \$7,895.00=NETT VALUE: \$28,105.00

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.