



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

RAY LOUIS LAW CORPORATION

Ref : CS3/CTI18018623/Gqd3e2-1

101 UPPER CROSS STREET #06-05 PEOPLE'S
PARK CENTRE SINGAPORE 058357 058357

Date : 08-10-2019



Code : L164

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YN 8201P	Veh. Inspected	GBD 1786P
Policy No.	DMCVSN3054361801	Coverage (\$)	0.00
Claim No.	SNM18D04837C02	Excess (\$)	0.00
Assign From	ZHONG HSIEN	Assign Date	30/07/2019

2. Vehicle Particulars & Condition

Make & Model	NISSAN CABSTAR	c.c	2953
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JN1SC2F24Z0855762	Colour	BLUE
Odometer	70245	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15	BRIDGESTONE	5 mm
L/H Front Tyre	195 R15	BRIDGESTONE	5 mm
R/H Rear Tyre	155 R13 (D)	CONDOR	5/5 mm
L/H Rear Tyre	155 R13 (D)	CONDOR	5/5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	07/10/2018	Inspection Date	15/10/2018
Survey held at	ALPHA CAR SERVICES PTE LTD BLK C, KAKI BUKIT AVE 6 #01-59 KAKI BUKIT AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**