

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC3/MSG 1901+663/USF302

MSIG/

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

CIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

Res.: Yes or No

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

have under of folder

24/10/18 2/5 #1500 confirmed with Alan + 7% = 1605

Reval 7-10 per day 100 = 300

Search Fee 2.00 = TOTAL #1907

25/10/19 - called insured to explain of car but didn't answer @ 1811 (NAZ).

C \$ 2.870.30 Red- 66%

RECEIVED NOV 2019

Date/Time, File Pass to?

☐

Preli. Report

Days Of Repair:

3

1) Typist

☒

Final Report

Resurvey No. of Trip:

2

Survey Fee:

Date/Time, File Return to?

Transportation:

2)

Add Fee:

☐

Site Insp (\$

) \$ + RS \$

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

)

Report Format :

Lump Sum / I.B.I. (\$ 1,500/- LIS)

TOTAL

150
11
161

Veh No: SMH 6732 Yr Regn: 10.16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal.

L/Bal.

D.O.I.

Rear n/s

mm

mm

mm

mm

mm

mm

mm

mm

mm

mm

mm

mm

mm

mm

mm

mm

mm

mm

mm

mm

mm

mm

mm

mm

mm

mm

mm

mm

mm

mm

mm

**DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA:
05/10/2019, SLH 673Z (TP VEHICLE), SJW 5434J (OI VEHICLE)**

Shirley Hiew (LKK Auto)

Wed 9/10/2019 5:25 PM

To: motorsurvey@sg.msig-asia.com <motorsurvey@sg.msig-asia.com>

Cc: SUR <sur@lkkauto.com>

 1 attachments (734 KB)

TP GIA REPORT.pdf,

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SLH 673Z at M/s: FASTECH AUTO PTE LTD, 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883 on 08/10/2019

Enclosed herewith a copy of TP's GIA report and estimated cost of repair will forward to you shortly.

Meanwhile, kindly provide us the claim reference number for our necessary action.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	471Z
Vehicle Details	
Vehicle No.:	SLH673Z
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Oct 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	ELANTRA AD 1.6 GLS AT
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	G4FGGU219154
Chassis No.:	KMHD841CMHU238356
Maximum Power Output:	93.8 kW (125 bhp)
Open Market Value:	\$13,177.00
Original Registration Date:	24 Oct 2016
First Registration Date:	24 Oct 2016
Transfer Count:	0
Actual ARF Paid:	\$13,177.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Oct 2026
PARF Rebate Amount:	\$9,882.00
Intended COE Rebate Details	
COE Expiry Date:	23 Oct 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,991.00
COE Rebate Amount:	\$35,899.00
Total Rebate Amount:	\$45,781.00

The information contained herein is correct as at 08 Oct 2019

OK

sgCARMART.COM

Login Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Nice Car. Maserati GranTurismo S MC Sport Line 4.7A.



Selling Cheap.
Direct Owner StarAd

KA-HUP

VALUE FOR MONEY
VALUE FOR TIME
A PEACE OF MIND

HOTLINE: 6741 9997 [VIEW OUR CARS](#)

Browse by Category






◀ Back (1 2) Next ▶

Sort by Date Posted 20 results/page

26 vehicles

Elantra

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Elantra		Any	Any	2016	Any	Any	Any	Available
	Hyundai	Elantra 1.6A GLS	\$60,800	\$7,450 /yr	30-Dec-2016	1,591 cc	61,000 km	Sedan	Available
2.28% Interest Rate. 1 Owner Only. Flexible Bank/In House Loan Packages Available. High PARF. 5 Years Agent Warranty With Komoco... Pure Motors Pte Ltd Posted: 06-Oct-2019 Tags: 2016 Hyundai Elantra, 2016 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai									
	Hyundai	Elantra 1.6A GLS	\$56,600	\$7,880 /yr	20-Feb-2016	1,591 cc	45,900 km	Sedan	Available
Free Car Grooming Before Delivery. New Paintwork. Serviced And Still Under Warranty From Agent! With Low Mileage. Value Buy! Loan... Posted: 05-Oct-2019 Tags: 2016 Hyundai Elantra, 2016 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai									
	Hyundai	Elantra 1.6A GLS	\$58,800	\$7,780 /yr	27-Jul-2016	1,591 cc	70,000 km	Sedan	Available
Vehicle Still Under Warranty By Komoco Until To July 2021, Free Titanium Glass Coating Worth \$888 Come With 3 Years Warranty And 3... Accendore Autolution Pte Ltd Posted: 05-Oct-2019 Tags: 2016 Hyundai Elantra, 2016 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai									
	Hyundai	Elantra 1.6A Elite	\$59,800	\$8,330 /yr	11-Jan-2016	1,591 cc	72,315 km	Sedan	Available
1 Owner, Elite Model High Specifications With Higher PARF Value, Low Mileage Done, Agent Komoco Maintained Engine Benefitted Next... Benefit Auto Enterprise Pte Ltd Posted: 04-Oct-2019 Tags: 2016 Hyundai Elantra, 2016 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai									
	BC Racing V1 Coilover BC (V1) Coilovers available for Hyundai. (Fully adjustable in terms of height and damping! (30-Levels) More info about this product								
	Hyundai	Elantra 1.6A GLS	\$61,668	\$8,000 /yr	28-Sep-2016	1,591 cc	45,845 km	Sedan	Available
Hyundai Komoco Unit. Fully Agent Maintained. One Owner. Beige With Black Interior. Comes With Auspicious Number Of 3188. Spacious... Inchcape Pre-Owned Posted: 03-Oct-2019 Tags: 2016 Hyundai Elantra, 2016 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai									
	Hyundai	Elantra 1.6A GLS Elite	\$58,800	\$7,720 /yr	06-Apr-2016	1,591 cc	44,895 km	Sedan	Available
Only 1 Previous Owner! Highest Specs Elite Model With Ventilated Memory Electric Seats/Lane Departure Sensing. Low Mileage Done! G... Creative Auto Posted: 02-Oct-2019 Tags: 2016 Hyundai Elantra, 2016 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai									
	Hyundai	Elantra 1.6A GLS S	\$62,000	\$7,870 /yr	25-Oct-2016	1,591 cc	33,300 km	Sedan	Available
First Owner. Komoco Warranty Until 2021. Low Mileage. Road Tax Paid Until 24 April 2020. Vehicle Inspection For 2019/2020 Completed... Posted: 02-Oct-2019 Tags: 2016 Hyundai Elantra, 2016 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai									
	Hyundai	Elantra 1.6A GLS	\$59,800	\$8,180 /yr	15-Apr-2016	1,591 cc	63,000 km	Sedan	Available
Accredited Company! Accident Free, Low Mileage Done, Low Interest 1.99%, STA Evaluation Are Welcome, Fully Maintained/Warranty By... Fu Yip Motor Trading Posted: 02-Oct-2019									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/10/2019 09:40
Date Of Accident	05/10/2019 18:10
Exact Location Of Accident	ECP F1 CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLH673Z
Insured/Policyholder	
Name Of Registered Owner	ANG RONG JUN NICHOLAS
NRIC No	S8719471Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98781813
Alternative Phone No	OFFICE-98781813

Vehicle Particulars

Manufacturer	HYUNDAI
Model	ELANTRA
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	B 28843521 QMX
Cover Note Number	

Driver

Name of Driver	ANG RONG JUN NICHOLAS
NRIC No	S8719471Z
Date Of Birth	05/07/1987
Occupation	INDOOR
Date Of Driving Pass	18/07/2008
Driving Experience	11 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98781813
Fax Number	
Contact Number	OFFICE-98781813
EMail Address	NOEMAIL

Address	6 WOODLANDS DR #03-18
Postcode	738209
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	
	NAME: : CLARK TIMOTHY JAMES
	GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJW5434J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(if driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN



A: SH 673Z

B: SJW 5434J.

ECP F1 Carpark.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 05/10/19 at about 6:11pm. I was stationary to look for carpark lot. Suddenly vehicle A hit my rear. When he was reversing from the car carpark lot.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

FASTECH AUTO PTE LTD
BLK 1 KAKI BUKIT AVE 6
#01-46/48/50 AUTOBAY
SINGAPORE 417883

Not Allowed
1/5 1500
3 day.

SLH 673Z

1PC	REAR BUMPER	489.24
1PC	REAR BUMPER SIDE RETAINER N/S	
1PC	REAR BUMPER REFLECTOR N/S	38.50
1SET	REAR BUMPER CLIPS	
1PC	REAR BUMPER REINFORCEMENT	328.20
1PC	REAR BUMPER LOWER GARNISH	213.00
1SET	REAR BUMPER REVERSE SENSOR	
1SET	REAR END PANEL	

Accepting/	\$688.20
11	\$66.50 X
sur	\$121.00
11	\$48.00
11	\$422.20
11	\$366.50
11	\$280.00 2005.2
11	\$517.90 X
	\$2,510.30

20%

TO CHECK WIRING
TO DISMANTLE & REPAIRING REVERSE SENSOR
TO DISMANTLE & REFIX CUSHION UPHOLSTERY
TO SPRAY RUST PROOFING
LABOUR FOR PANEL BEATING & REPLACING PARTS
TO PUTTY & SPRAY PAINTING

	\$50.00 20
	\$80.00 50
11	\$120.00 X
11	\$50.00 X
	\$680.00 320
	\$880.00 400
TOTAL	\$4,370.30

770

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-1116.94
P-883.55
S.N-200.00
L-790.00
1883.49

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Oct 2019		10 Oct 2019 11:45 Edit Adj Rpt	S\$1,500.00 Edit Estimates	S\$1,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	HELEN MARY CLARK, ID: G6311461N	
Main Claimant:	ANG RONG JUN NICHOLAS, ID: S8719471Z	
Vehicle Reg. No.:	SLH673Z	Date of Loss: 05/10/2019 18:00 - :59 [35 Months and 11 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 608049	Policy/Cover Note No.: 27339335AMM (Comprehensive) Coverage: 01/07/2012 - 29/09/2020
Vehicle Reg. No. (Insured):	SJW5434J	Policy No. (Claimant):
		Excess:
Repairer:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, 417883 Kaki Bukit - Tel: 67465405	
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Imm.Advice due 11/10/2019]	
Driver/Custodian (Insured):	CLARK TIMOTHY JAMES (), NRIC: G6311472W Email:	
Adj Asg. Remarks:	Direct Survey by LKK Auto Consultants on 08/10/2019.	

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		












































ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													












Claim Documents

*SLH673Z (608049)
[SJW5434J]
TP
ANG RONG JUN NICHOLAS
Oct 5 2019 6:00PM
[HELEN MARY CLARK]
Fastech Auto Pte Ltd

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#)

View [View in Browser](#)

Photos/Images			3 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/11/19 09:14	General View	 Load JPG	<input checked="" type="checkbox"/>
2	01/11/19 09:14	General View	 Load JPG	<input checked="" type="checkbox"/>
3	01/11/19 09:14	General View	 Load JPG	<input checked="" type="checkbox"/>
4	01/11/19 09:14	General View	 Load JPG	<input checked="" type="checkbox"/>
5	01/11/19 09:14	General View	 Load JPG	<input checked="" type="checkbox"/>
6	01/11/19 09:14	General View	 Load JPG	<input checked="" type="checkbox"/>
7	01/11/19 09:14	General View	 Load JPG	<input checked="" type="checkbox"/>
8	01/11/19 09:14	General View	 Load JPG	<input checked="" type="checkbox"/>
9	01/11/19 09:14	General View	 Load JPG	<input checked="" type="checkbox"/>
10	01/11/19 09:14	General View	 Load JPG	<input checked="" type="checkbox"/>
11	01/11/19 09:14	General View	 Load JPG	<input checked="" type="checkbox"/>
12	01/11/19 09:14	General View	 Load JPG	<input checked="" type="checkbox"/>
13	01/11/19 09:14	General View	 Load JPG	<input checked="" type="checkbox"/>
14	01/11/19 09:14	General View	 Load JPG	<input checked="" type="checkbox"/>
15	01/11/19 09:14	General View	 Load JPG	<input checked="" type="checkbox"/>
16	01/11/19 09:14	General View	 Load JPG	<input checked="" type="checkbox"/>
17	01/11/19 09:14	General View	 Load JPG	<input checked="" type="checkbox"/>
18	01/11/19 09:14	General View	 Load JPG	<input checked="" type="checkbox"/>
19	01/11/19 09:14	General View	 Load JPG	<input checked="" type="checkbox"/>
20	01/11/19 09:14	General View	 Load JPG	<input checked="" type="checkbox"/>
21	01/11/19 09:14	General View	 Load JPG	<input checked="" type="checkbox"/>
22	01/11/19 09:14	General View	 Load JPG	<input checked="" type="checkbox"/>
23	01/11/19 09:14	General View	 Load JPG	<input checked="" type="checkbox"/>
24	01/11/19 09:14	General View	 Load JPG	<input checked="" type="checkbox"/>
25	01/11/19 09:14	General View	 Load JPG	<input checked="" type="checkbox"/>
26	01/11/19 09:14	General View	 Load JPG	<input checked="" type="checkbox"/>
27	01/11/19 09:14	General View	 Load JPG	<input checked="" type="checkbox"/>
28	01/11/19 09:14	General View	 Load JPG	<input checked="" type="checkbox"/>
29	01/11/19 09:14	General View	 Load JPG	<input checked="" type="checkbox"/>
30	01/11/19 09:14	General View	 Load JPG	<input checked="" type="checkbox"/>
31	01/11/19 09:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
32	01/11/19 09:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
33	01/11/19 09:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
34	01/11/19 09:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
35	01/11/19 09:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	01/11/19 09:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	01/11/19 09:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	01/11/19 09:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	01/11/19 09:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	01/11/19 09:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	01/11/19 09:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	01/11/19 09:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	01/11/19 09:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	01/11/19 09:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	01/11/19 09:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	01/11/19 09:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	01/11/19 09:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	01/11/19 09:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	01/11/19 09:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	01/11/19 09:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	01/11/19 09:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	10/10/19 11:15	DIRECT SURVEY BY LKK DONE ON 08/10/2019	 Load PDF	
2	10/10/19 11:15	OI Accident Report	 Load PDF	
3	10/10/19 11:15	TP SLH673Z E-REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG19017663/USF3E2

Date: 01/11/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 27339335AMM
Claimant
Vehicle No : SLH673Z **Insured Vehicle No :** SJW5434J
Date of Loss: 05/10/2019 **Nature of Claim:** TP **Claim No:** 608049

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLH673Z**
 Make & Model: HYUNDAI ELANTRA, 1.6 (A) Engine No: G4FGGU219154
 Reg. Date: 24/10/2016 (Man. Year: 2016) Chassis No: KMHD841CMHU238356
 Colour: White Odometer: 75132 km
 Engine Capacity: 1591 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Nexen 6 mm Rear Left Side: Nexen 6 mm
 Front Right Side: Nexen 6 mm Rear Right Side: Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,510.30	1,093.55	1,416.75	56.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,860.00	790.00	1,070.00	57.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,370.30	1,883.55	2,486.75	56.90
Approved Total (Overridden) (S\$)		1,500.00		
(S\$)	4,370.30	1,500.00	2,870.30	65.68
+ GST 7.00/7.00% (S\$)	305.92	105.00	200.92	65.68
Nett Amount (S\$)	4,676.22	1,605.00	3,071.22	65.68

INSPECTION

Date of Assignment: 10/10/2019
 Date Inspected: 08/10/2019 Inspected At: Fastech Auto Pte Ltd (HQ)
 1 Kaki Bukit Ave 6, #01-46/48/50
 Autobay
 Singapore 417883
 Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Nov 2019)
Parts:	143	HYUNDAI ELANTRA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLH673Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deep Cut / Deformed	688.20 F	*489.24 FL
2	1		*REAR BUMPER SIDE RETAINER N/S	Not Necessary	66.50 F	*- FL
3	1		*REAR BUMPER REFLECTOR N/S	Scratched	121.00 F	*38.50 FL
4	1		*SET REAR BUMPER CLIPS	Necessary	48.00 F	*48.00 FL
5	1		*REAR BUMPER REINFORCEMENT	Bent	422.20 F	*328.20 FL
6	1		*REAR BUMPER LOWER GARNISH	Grazed	366.50 F	*213.00 FL
7	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
8	1		*SET REAR END PANEL	Repair	517.90 F	*- FL
					Sub Total (S\$)	2,510.30 1,316.94
					- List Item Discount on L Items 0.00/20.00% (S\$)	0.00 223.39
					Total Parts (S\$)	2,510.30 1,093.55

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REFIX REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	0.00
4	TO SPRAY RUST PROOFING	New	50.00	0.00
5	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	680.00	320.00
6	TO PUTTY & SPRAY PAINTING	New	880.00	400.00
Gross Labour Cost (\$\$)			1,860.00	790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >