

ASS. REC. BY:

REF: CS3/ CT19 017669/QC f303

Special Instruction:

Survivor: Sun Pin

ASSIGNMENT (Office)From (Person): Chung Bron Sen of CTL Date/Time: 8.10.19 10.00 a.m

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SMM 9463R Insured: SGK 1949Rat Workshop m/s 365 Automotive Tel: 9169 0825of 205 Kaki Bukit Rd 4 #01-55 SynergyPolicy No: DMH CSN 192394 19000 Claim No: SMM 1915704658

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 2.10.2019  
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 8.10.19 10.16 a.m Person Contacted: Pei Jie H.O.D. Endorsement: \_\_\_\_\_Vehicle: IN/OUT

Date/Time	Action/Instruction ( X ) Estimate
8/10/19 11:26 a.m	Confirmed with Pei Jie 365 Automotive b Apex motoring is same wheel.
	SMM 9463R - X
	SGK 1949R - CC3 / AIG 09 000 502 / CAJ DOA - 01/01/2019
	Dismantle: 9/10/2019
	After repair: 14/10/2019.

Merimen

AGS REC. BY: Sun Pin

REF: CT1

PR 5

## ASSIGNMENT

From: Date: 8.10.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMM 9463R

at Workshop m/s 365 Automotive

of 25 Kaki Bukit Rd 4 #01-53 synergy

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

up

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: SMM 9463 R Yr Regn: 19/JUL/2019

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Noah Hybrid C.C. 1797

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 14455 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: ZWR800396260

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15

R: 195/65 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6

mm

R/Bal. 6

mm

L/Bal. 6

mm

L/Bal. 6

mm

D.O.A. 02/10/2019

D.O.I. 08/10/2019

Survey held at

365 Automotive.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front Right.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

PR 5 Case.

112,000

MV: 120,000

PV: 60,604

NV: 54,391 51,391

112,000

Repair Range: 4K-5K

Repair Days: 4 day

RECEIVED 17 OCT 2019

16/10/2019

Date/Time, File Pass to?

: Preli. Report

1)

: Final Report

Date/Time, File Return to?

2)

Rep. Format:

PR 5

Lump Sum / T.B.C.

Days Of Repair: 4

Resurvey No. of Trip: 2

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Wheel end (\$)

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

190

190

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Oct 2019		08 Oct 2019 10:04 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

#### CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	
Main Claimant: <b>ADVANCE CR PTE LTD</b> , Co. Reg. No.: 201320997M	
Vehicle Reg. No.:	<b>SMM9463R</b>
Date of Loss:	02/10/2019 20:00 - :59
Claim Type:	<b>TP / SNM19D204658C02</b>
Policy/Cover Note No.:	DMHCSN19239419000
Vehicle Reg. No. (Insured):	<b>SGK1949R</b>
Policy No. (Claimant):	B29130960MCX
Excess:	S\$0.00
Repairer: <b>Apex Motoring ( )</b> 25 Kaki Bukit Road 4, #01-55 Synergy @ KB, 417800 Kaki Bukit - Tel:	
Handling Insurer: <b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]	
Claimant's Insurer: <b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888	
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... <b>[Final Rpt due 17/10/2019]</b>	

#### ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

#### ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**Summer Lee (LKK Auto)**

---

**From:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Sent:** Tuesday, 8 October, 2019 10:00 AM  
**To:** peijie@expresscar.com.sg  
**Cc:** assignments  
**Subject:** RE: OUR REF: SNM19D204658-SGK1949R-CBS - FW: SMM9463R PRS FW: From "  
"(Fax Message NO.2421)

WITHOUT PREJUDICE  
SAVE AS TO COSTS

Dear Sir,

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

Chong Boon Sen  
Claims Executive  
Department

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | FB: [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | WeChat: 太平狮城 Taiping SG 3 Anson  
Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

-----Original Message-----

From: peijie@expresscar.com.sg [mailto:peijie@expresscar.com.sg]  
Sent: Friday, October 4, 2019 7:11 PM  
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
Subject: Re: OUR REF: SNM19D204658-SGK1949R-CBS - FW: SMM9463R PRS FW: From " "(Fax Message NO.2421)

Dear Sir/Madam,

We do not agree to your list of surveyor.  
Kindly refer below for our list of surveyor :

- 1) Teo Hoon Tong – Kelvin Automotive Appraising Services
- 2) Chang Fuh Keong, Dave – Sincere Appraisal Services
- 3) Ho Joo Loong, Danny – HJL Auto Appraiser Services

- 4) Lee Kok Weng – Lee Automobile Appraisers Services
- 5) Hong Shiyuan – Kelvin Automotive Appraising Services
- 6) Ong Ah Keng, Kent – KTO Automobile Assessors
- 7) Ong Poh Meng – Aeon Auto Consultants LLP
- 8) Philip Foo – Presicion Appraisal Services
- 9) Thor Teck Soon, David – JAS Appraisal Services

Thanks.

---  
 Best Regards,  
 Peijie  
 82 Lorong 23 Geylang  
 #03-06 ATRIX  
 S(388409)  
 DID: 91690825

On 2019-10-04 16:19, Chong Boon Sen wrote:

- > Without prejudice
- > Dear Sir,
- > LKK
- >
- > STA
- > LBS
- >
- >
- > Chong Boon Sen
- > Claims Executive
- > Department
- >
- > China Taiping Insurance (Singapore) Pte. Ltd.
- > 3 Anson Road #16-00 Springleaf Tower Singapore 079909
- > DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033
- >
- > W: [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | FB: [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/)
- > | WeChat: 太平獅城 Taiping SG 3 Anson Road #16-00 Springleaf Tower
- > Singapore 079909
- > DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033
- >
- >
- > -----Original Message-----
- > From: Claims Dept of CTI
- > Sent: Friday, October 4, 2019 4:07 PM
- > To: Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)>; Alfred Toh
- > <[alfred.toh@sg.cntaiping.com](mailto:alfred.toh@sg.cntaiping.com)>; Chee So Chow
- > <[sochow.chee@sg.cntaiping.com](mailto:sochow.chee@sg.cntaiping.com)>; PEIJIE@EXPRESSCAR.COM.SG
- > Subject: OUR REF: SNM19D204658-SGK1949R-CBS - FW: SMM9463R PRS FW:
- > From " "(Fax Message NO.2421)
- >
- > Dear Boon Sen,
- >
- > Please conduct PRS for SMM9463R.
- >
- > Note : officer in charge – Boon Sen 63896171.
- >

> Regards,

> Claims Department

> China Taiping Insurance (Singapore) Pte. Ltd.

> 3 Anson Road #15-00 Springleaf Tower Singapore 079909

> T: (65) 63896116 | F: (65) 62247175

> W: [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | FB: [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/)

> | WeChat: 太平獅城 Taiping SG

> Disclaimer: This e-mail and any files transmitted with it is intended  
> only for the named recipients and may contain confidential  
> information. Any unauthorized disclosure, use or dissemination of this  
> message, either in whole or partial, is prohibited. If you are not the  
> intended recipient, please notify the sender immediately. Please  
> delete the e-mail and any copies of it thereafter.

> -----Original Message-----

> From: RC6004F-15A-CL@sg.cntaiping.com

> [mailto:RC6004F-15A-CL@sg.cntaiping.com]

> Sent: Friday, October 04, 2019 11:34 AM

> To: FA-X5575C-16A-CL

> Subject: From " "(Fax Message NO.2421)

> This E-mail was sent from "RC6004F-15A-CL" (MP C6004ex).

> Queries to: RC6004F-15A-CL@sg.cntaiping.com

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	997M
Vehicle Details	
Vehicle No.:	SMM9463R
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Oct 2019
Vehicle Make:	TOYOTA
Vehicle Model:	NOAH HYBRID 7-SEATER 1.8X CVT
Primary Colour:	Black
Manufacturing Year:	2019
Engine No.:	2ZR0E01701
Chassis No.:	ZWR800396260
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$33,888.00
Original Registration Date:	19 Jul 2019 ✓
First Registration Date:	19 Jul 2019
Transfer Count:	0
Actual ARF Paid:	\$29,444.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Jul 2029
PARF Rebate Amount:	\$22,083.00
Intended COE Rebate Details	
COE Expiry Date:	18 Jul 2029
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$39,406.00
COE Rebate Amount:	\$38,526.00
<b>Total Rebate Amount:</b>	<b>\$60,609.00</b>

The information contained herein is correct as at 08 Oct 2019

OK

New Car \$132K

QMI ToughGuard Paint  
Protection Coating3rd Generation  
Volkswagen Touran

Toyota Noah Price Range Depreciation 2019 Vehicle Type

Advanced  
Search

Home » Used Cars » TTS Eurocars » Toyota Noah Hybrid 1.8A X

## Toyota Noah Hybrid 1.8A X

Overview

Financial

Accessories

Similar

Research

Photos

Map



<b>Price</b>	<b>\$123,988</b>	<b>Fuel Type</b>	Petrol-Electric
<b>Depreciation</b> ⓘ	<b>\$11,290 /yr</b> View models with similar depre	<b>Reg Date</b>	05-Jul-2019 (9yrs 8mths 26days COE left)
<b>Mileage</b>	50 km	<b>Manufactured</b> ⓘ	2018
<b>Road Tax</b> ⓘ	N.A.	<b>Transmission</b>	Auto
<b>Dereg Value</b> ⓘ	\$54,105 as of today (change)	<b>OMV</b> ⓘ	\$32,830
<b>COE</b> ⓘ	\$34,000	<b>ARF</b> ⓘ	\$27,962
<b>Engine Cap</b>	1,797 cc	<b>No. of Owners</b> ⓘ	1
<b>Curb Weight</b> ⓘ	1,610 kg		
<b>Type of Vehicle</b>	MPV		

## Features

Airbags, ABS, Reliable And Fuel Efficient 1.8L 4 Cylinder 16V DOHC Engine, Hybrid Producing 134 Bhp, E-CVT Transmission, Toyota Safety Sense. View specs of the Toyota Noah

## Accessories

Smart Entry System, Steering Switch, Dual Powered Sliding Door With One Touch Switch, Rear Auto Air Conditioner, Hybrid System Indicator.

## Description

Best Affordable MPV. 5 Years Warranty Provided, Loan With Low Installment Options! Cheapest In The Market, A Deal Not To Be Missed! 35 Years In Business! Our Warranty Provided In-House!

## Category

PARF Car, Almost New Car, Low Mileage Car, Hybrid Cars

## Status

Available

## Resources



## Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



## Car Valuation - Free

Find out the market value of your existing car for free. Get started



Click on the point to view the vehicle

Shortlist

Compare

Add note

Report Error

More Actions

## Seller Information

<b>Company</b>	TTS Eurocars	
	» dealer's pricelist	
	» 64 vehs sold   96 vehs available	
<b>Address</b>	383 Sin Ming Drive	
	Search cars nearby this location	
<b>Office No</b>	68422222	
<b>Contact Person(s)</b>	Andy Sim	92327999
	Brandon	92277709

Posted on: 08-Sep-2019 | Last updated on: 09-Sep-2019

U Compare

» more Financial info



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	03/10/2019 18:15
Date Of Accident	02/10/2019 20:50
Exact Location Of Accident	BUKIT BATOK DRIVING CENTRE CARPARK
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMM9463R
<b>Insured/Policyholder</b>	
Name Of Registered Owner	ADVANCE CR PTE LTD
Co Reg No	201320997M
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90274902
Alternative Phone No	OFFICE-90274902

### Vehicle Particulars

Manufacturer	TOYOTA
Model	NOAH
Exact Purpose for which vehicle was being used at time of accident	PRIVATE HIRER USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	B29130960MCX
Cover Note Number	

### Driver

Name of Driver	KHAIRUL SHAH BIN KAMARUDDIN SHAH
NRIC No	S7805756D
Date Of Birth	07/03/1978
Occupation	OUTDOOR
Date Of Driving Pass	12/09/2000
Driving Experience	19 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90274902
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	APT BLK 370 BUKIT BATOK ST 31 #03-217
Postcode	650370
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	HONG KAH NORTH NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 370 BUKIT BATOK STREET 31 , POSTCODE: 650370 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-5679999 - FAX NO: 65652508
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH OWNER
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGK1949R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### DETAILS OF INJURED PERSON 1

Name	KHAIRUL SHAH BIN KAMARUDDIN SHAH
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SMM9463R
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	APT BLK 370 BUKIT BATOK STREET 31 #03-217
Postcode	650370

## Sketch Plan


### SKETCH PLAN


#### IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to renege policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


  
Policyholder's Signature  
Date & Time: 02/10/2019  
10:30am

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 03/10/2019  
10:30am

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

### Sketch Plan #2

### SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature \_\_\_\_\_

Date & Time: 03/10/19  
10:30am

Driver's Signature \_\_\_\_\_

(If driver is not the policyholder)  
Date & Time: 03/10/19  
10:30 am

Reporting Centre Personnel's Signature

Name: \_\_\_\_\_  
NRIC/FIN No.: \_\_\_\_\_



**SINGAPORE  
POLICE FORCE**



J/20191003/2050

1 of 2

**POLICE REPORT (NP299)**

Report No. J/20191003/2050

Police Station Of Origin  
Hong Kah North NPP  
370 Bukit Batok Street 31 #01-201  
SINGAPORE 650370  
Tel No: 1800-5679999


Date/Time Report Made 03/10/2019 13:14	Vide Report No.	Station Diary No. 15
Name Of Informant KHAIRUL SHAH BIN KAMARUDDIN SHAH	Address APT BLK 370 BUKIT BATOK STREET 31 #03-217 SINGAPORE 650370	
ID Type / ID No. NRIC NO / S7805756D	Contact No. Home/Office Mobile 90274902	
Nationality SINGAPORE CITIZEN	Email Address	
Occupation GRAB DRIVER	Sex Male	Age 41
Institution/School Name	Date of Birth 07/03/1978	Race Malay
Date/Time Of Incident 02/10/2019 20:50	Location Of Incident 815 BUKIT BATOK WEST AVENUE 5 BUKIT BATOK DRIVING TEST CENTRE SINGAPORE 659085	

**Brief details.**

I am the driver of Reg: SMM9463R, on 02/10/2019 at about 2050hrs, I was at Bukit Batok Driving center dropping of a passenger. While I was at the round about inside the driving center waiting for my turn to drop off my passenger at the drop off point, another vehicle Reg: SGK1949R was in front of my vehicle, I was waiting him to move so that I could proceed. Suddenly vehicle Reg: SGK1949R Reverse and collided my vehicle right front bumper. After the accident I exchanged particular with the driver of SGK1949R and left. However I felt discomfort the next day so I went to see a doctor and was given 3 days of medical

Signature Of Officer Recording The Report: J / Sgt 2 JACKY ONG CHUN HENG	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 03/10/2019 13:14
Officer In-Charge Of Case: J / Bukit Batok N.P.C / Staff Sgt S VIKNESHVARAN S/O SUBRAMANIAM Contact No.:	Classification Of Case:

Authentication Stamp



**SINGAPORE  
POLICE FORCE**

J/20191003/2050




2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. J/20191003/2050

leave. My Vehicle suffered damages on the front right bumper and I am unable to open my vehicle driver side door fully after the accident. This report is for insurance claim purposes.

Signature Of Officer Recording The Report: J / Sgt 2 JACKY ONG CHUN HENG 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 03/10/2019 13:14
Officer In-Charge Of Case: J / Bukit Batok N.P.C / Staff Sgt S VIKNESHVARAN S/O SUBRAMANIAM Contact No.:	Classification Of Case:
Authentication Stamp 	

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Oct 2019		08 Oct 2019 10:04 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured: -, Co. Reg. No.: -									
Main Claimant: <b>ADVANCE CR PTE LTD</b> , Co. Reg. No.: 201320997M									
Vehicle Reg. No.: <b>SMM9463R</b>		Date of Loss: 02/10/2019 20:00 - :59 [2 Months and 13 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP / SNM19D204658C02</b>		Policy/Cover Note No.: DMHCSN19239419000							
Vehicle Reg. No. (Insured): <b>SGK1949R</b>		Policy No. (Claimant): B29130960MCX							
		Excess: S\$0.00							
Repairer: <b>Apex Motoring ()</b> 25 Kaki Bukit Road 4, #01-55 Synergy @ KB, 417800 Kaki Bukit - Tel:									
Handling Insurer: <b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]									
Claimant's Insurer: <b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>OI SUN PIN</b> ] ... [Final Rpt due 17/10/2019]									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

\*SMM9463R (SNM19D204658C02)

[SGK1949R]

TP

























































ADVANCE CR PTE LTD

























































Oct 2 2019 8:00PM


























[-]

Apex Motoring
















Upload Documents			Upload Photos			Compose New Letter			View <span>View in Browser</span>		
Assessment Reports								1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)						Thumbnail		Print	
1	03/10/19 18:19	Accident Statement							Load HTM		
Photos/Images								3 per page		<input checked="" type="checkbox"/>	
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)						Thumbnail		Print	
1	03/10/19 18:19	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
2	03/10/19 18:19	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
3	03/10/19 18:19	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
4	03/10/19 18:19	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
5	03/10/19 18:19	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
6	03/10/19 18:19	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
7	03/10/19 18:19	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
8	03/10/19 18:19	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
9	03/10/19 18:19	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
10	03/10/19 18:19	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail		Print	
1	15/10/19 18:56	General View							Load JPG	<input checked="" type="checkbox"/>	
2	15/10/19 18:56	General View							Load JPG	<input checked="" type="checkbox"/>	
3	15/10/19 18:56	General View							Load JPG	<input checked="" type="checkbox"/>	
4	15/10/19 18:56	General View							Load JPG	<input checked="" type="checkbox"/>	
5	15/10/19 18:56	General View							Load JPG	<input checked="" type="checkbox"/>	
6	15/10/19 18:56	General View							Load JPG	<input checked="" type="checkbox"/>	
7	15/10/19 18:56	General View							Load JPG	<input checked="" type="checkbox"/>	
8	15/10/19 18:56	General View							Load JPG	<input checked="" type="checkbox"/>	
9	15/10/19 18:56	General View							Load JPG	<input checked="" type="checkbox"/>	
10	15/10/19 18:56	General View							Load JPG	<input checked="" type="checkbox"/>	
11	15/10/19 18:56	General View							Load JPG	<input checked="" type="checkbox"/>	
12	15/10/19 18:56	General View							Load JPG	<input checked="" type="checkbox"/>	
13	15/10/19 18:56	General View							Load JPG	<input checked="" type="checkbox"/>	
14	15/10/19 18:56	General View							Load JPG	<input checked="" type="checkbox"/>	
15	15/10/19 18:56	General View							Load JPG	<input checked="" type="checkbox"/>	
16	15/10/19 18:56	General View							Load JPG	<input checked="" type="checkbox"/>	
17	15/10/19 18:56	General View							Load JPG	<input checked="" type="checkbox"/>	
18	15/10/19 18:56	General View							Load JPG	<input checked="" type="checkbox"/>	
19	15/10/19 18:56	General View							Load JPG	<input checked="" type="checkbox"/>	
20	15/10/19 18:56	General View							Load JPG	<input checked="" type="checkbox"/>	
21	15/10/19 18:56	General View							Load JPG	<input checked="" type="checkbox"/>	
22	15/10/19 18:56	General View							Load JPG	<input checked="" type="checkbox"/>	
23	15/10/19 18:56	General View							Load JPG	<input checked="" type="checkbox"/>	
24	15/10/19 18:56	General View							Load JPG	<input checked="" type="checkbox"/>	
25	15/10/19 18:56	General View							Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	Thumbnail	Print
26	15/10/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
27	15/10/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
28	15/10/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
29	15/10/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
30	15/10/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
31	15/10/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
32	15/10/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
33	15/10/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
34	15/10/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
35	15/10/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
36	15/10/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
37	15/10/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
38	15/10/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
39	15/10/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
40	15/10/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
41	15/10/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
42	15/10/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
43	15/10/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
44	15/10/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
45	15/10/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
46	15/10/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
47	15/10/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
48	15/10/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
49	15/10/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
50	15/10/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
51	15/10/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
52	15/10/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
53	15/10/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
54	15/10/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
55	15/10/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
56	15/10/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
57	15/10/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
58	15/10/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
59	15/10/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
60	15/10/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
61	15/10/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
62	15/10/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
63	15/10/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
64	15/10/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
65	15/10/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
66	15/10/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
67	15/10/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
68	15/10/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
69	15/10/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
70	15/10/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
71	15/10/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
72	15/10/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
73	15/10/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
74	15/10/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
75	15/10/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
76	15/10/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
77	15/10/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
78	15/10/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
79	15/10/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
80	15/10/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
81	15/10/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	Thumbnail	Print
82	15/10/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
83	15/10/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
84	15/10/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
85	15/10/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
86	15/10/19 18:56	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
87	15/10/19 18:57	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
88	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
89	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
90	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
91	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
92	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
93	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
94	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
95	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
96	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
97	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
98	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
99	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
100	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
101	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
102	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
103	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
104	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
105	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
106	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
107	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
108	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
109	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
110	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
111	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
112	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
113	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
114	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
115	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
116	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
117	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
118	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
119	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
120	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
121	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
122	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
123	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
124	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
125	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
126	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
127	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
128	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
129	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
130	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
131	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
132	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
133	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
134	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
135	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
136	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
137	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	Thumbnail	Print
138	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
139	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
140	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
141	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
142	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
143	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
144	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
145	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
146	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
147	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
148	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
149	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
150	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
151	15/10/19 18:58	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
152	16/10/19 08:49	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
153	16/10/19 08:49	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
154	16/10/19 08:49	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
155	16/10/19 08:49	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
156	16/10/19 08:49	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
157	16/10/19 08:49	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
158	16/10/19 08:49	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	03/10/19 18:18	Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	03/10/19 18:18	Sketch Plan #2 [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	03/10/19 18:18	POLICE REPORT [Linked Accident Report Documents]	 Load TIF	
4	03/10/19 18:18	POLICE REPORT [Linked Accident Report Documents]	 Load TIF	

## Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	03/10/19 18:19	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	03/10/19 18:19	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	03/10/19 18:19	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	03/10/19 18:19	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	03/10/19 18:19	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	03/10/19 18:19	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	03/10/19 18:19	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	03/10/19 18:19	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	03/10/19 18:19	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	03/10/19 18:19	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	03/10/19 18:19	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	03/10/19 18:18	Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	03/10/19 18:18	Sketch Plan #2	 Load JPG	<input checked="" type="checkbox"/>
3	03/10/19 18:18	POLICE REPORT	 Load TIF	
4	03/10/19 18:18	POLICE REPORT	 Load TIF	

Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	<a href="#">Reset</a>	<a href="#">Save</a>	<a href="#">Print</a>
There are no document checklists configured.			

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:** ☐ Handling Insurer  
Note: Remarks are private unless you show it to other parties.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT119017669/QCF3E2

Date: 23/10/2019

### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSN19239419000

Claimant Vehicle No: SMM9463R Insured Vehicle No: SGK1949R

Date of Loss: 02/10/2019 Nature of Claim: TP Claim No: SNM19D204658C02

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMM9463R

Make & Model: TOYOTA NOAH HYBRID, 1.8 X CVT (A) Engine No: 2ZR0E01701

Reg. Date: 19/07/2019 (Man. Year: 2019) Chassis No: ZWR800396260

Colour: Black Odometer: 14455 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15

Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 08/10/2019

Date Inspected: 08/10/2019 Inspected At:

Apex Motoring  
25 Kaki Bukit Road 4, #01-55 Synergy  
@ KB  
Singapore 417800

Estimated Period of Repair: 4.0 days

Adjuster: OI SUN PIN

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 -\$5,000.00

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 22 Oct 2019)
<b>Parts:</b>	M1-MPV	TOYOTA NOAH HYBRID 1.8 X CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMM9463R)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >