

ASS. REC. BY:

REF: CS/EG19017674UVf302

Special Instruction:

Surveyor: MARCUS

ASSIGNMENT (Office)

From (Person): Pauline Soh

of Ergo

Date/Time: 8.10.19 10:30.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJM 8569 L

Insured: GBB 8551 P

at Workshop m/s Fastech Auto

Tel: 6746 5405

of 1 Kati Bukit Ave 6 #101-46

Policy No:

Claim No: CDMC9 19001876

Sum Insured:

Excess:

Make of Veh:

D.O.A 6.10.19

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 8.10.19 10:50.m

Person Contacted: Jason

H.O.D. Endorsement:

Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SJM 8569 L -x
	GBB 8551 P -x
9/10/19	Informed Pauline pending workshop est by merimen
31/10/19	Send preli revised via merimen

Merimen

08/11/13) wof

A.S.S. REC. BY: MAR 14/5

REF:

SRV

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / QD RES / EVA / INV / MV
 To inspect Vehicle No: SYM R569C
 at Workshop m/s: R.
 of: GAB RTRIP
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: #414
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Sean: _____ Consistent? : Yes or No
 Est. Repairs: 5 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

6442
 Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SYM R569C Yr Regn: 10 09
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or LA
 Make: Honda / Fit opc cc 1339
 Colour: white A/C: Insured / Std / NI / NA
 Sp. Reading: 68761 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: GE6 11 42820
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Order / Jammed / Leaked / Burnt or
 Brakes: Order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 195/55 R 15
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front	<u>6</u>	mm	Rear	<u>6</u>	mm
R/Bal.	<u>6</u>	mm	R/Bal.	<u>6</u>	mm
L/Bal.	<u>6</u>	mm	L/Bal.	<u>6</u>	mm
D.O.A.	<u>6/10/19</u>		D.O.L.	<u>8/10/19</u>	

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

LHM 29394

30/10/19 4545500 confirmed with Alen. (Red 8856.30, 609)

RECEIVED 3 OCT 2019

Date/Time, File Pass to?

☐ : Prel. Report
☐ : Final Report

Days Of Repair: 5

Resurvey No. of Trip: 3

Survey Fee: 390
 Transportation:

Add Fee: ☐ : Site Insp (\$ _____) \$ + RS _____
☐ : Interview (\$ _____) Photos
☐ : Tech. Invs (\$ _____) Others
☐ : Weekend (\$ _____)

Report Format: merimen

Lump Sum / I.B.I: (\$ 5500/2)

TOTAL

<u>390</u>
<u>11</u>
<u>361</u>

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	(Not Notified) Edit Reg		08 Oct 2019 00:00 Edit Adj Rpt		Last:IA 31 Oct 2019 11:08		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:			
Main Claimant:	-		
Vehicle Reg. No.:	SJM8569L	Date of Loss:	06/10/2019 00:00 - :59
Claim Type:	TP / CDMCG19001876	Policy/Cover Note No.:	
Vehicle Reg. No. (Insured):	GBB8551P	Policy No. (Claimant):	
		Excess:	
Repairer:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, 417883 Kaki Bukit - Tel: 67465405		
Handling Insurer:	ERGO Insurance Pte. Ltd. (HQ) - Tel: 6829 9199 ... [Handled by Ivy Yong - 6829 9197]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 17/10/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:	ERGO Insurance Pte. Ltd. 5 Temasek Boulevard #04-01 Suntec Tower Five Singapore 038985	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
-----	---	-------	---

Attn: Ivy Yong Date: 31 Oct 2019

Preliminary Advice

Insured Vehicle No	: GBB8551P	Accident Date	: 06/10/2019
TP Vehicle No	: SJM8569L	Assignment Date	: 08/10/2019
Make	: HONDA ACCORD	Est. Duration of Repair	: 5
Date of Inspection	: 8/10/2019		
Inspection At	: FASTECH AUTO PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,356.30
Revised Amount	:S\$	5,500.00 (LUMP SUM)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,500.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :The above survey was conducted on a 'Without Prejudice' basis.

View Sent Message

This mail is associated with :

***SJM8569L**
[GBB8551P]

TP

Oct 5 2019 12:00AM

Fastech Auto Pte Ltd

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 09/10/2019 12:45 PM.
To pauline.soh@ergo.com.sg
Subject TP SURVEY SJM 8569L

Dear Pauline,

Please be informed that we have inspected the vehicle SJM 8569L on 8/10/2019.

We are pending estimate from repairer.

Best Regards,
Veron Chen

DOCUMENTS SUMMARY

There are no documents.

Nivitha (LKK Auto)

From: ERGO Insurance Pte. Ltd. (Claims Department) <claims@ergo.com.sg>
Sent: Tuesday, 8 October 2019 10:33 AM
To: Lina Pang; Nancy Lam; Ivy Yong; Phoebe Xie; Admin-D (LKKAuto (admin-d@lkkauto.com)); Admin A (admin-a@lkkauto.com); Mei Kwan (LKKAuto (Meikwan@lkkauto.com))
Cc: Jenny Law; Jason
Subject: RE: Claims ref no. (P) CDMCG19001876 Request for PRS : SJM8569L DOA:06/10/2019

Hi LKK,

Please conduct this survey request.
(Note: Survey vehicle only)

Kindly inform us if you are not able to attend it.

***** NOTE:** Please assist to quote our claims ref no. as the subject matter, when forwarding the Preliminary Reports / Survey Reports.

Thank you

Date Classification : Confidential, C3

Warmest Regards,
Pauline Soh
ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-05 Suntec Tower Five
Singapore 038985
DID : +65 8829 9194
pauline.soh@ergo.com.sg

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.



Disclaimer: This message and its attachments are confidential, intended only for the named addressee, and may be privileged. If you are not the intended recipient, you should not disclose, distribute, copy or use this communication. If you are not the intended recipient, please notify the sender by return email and delete this message. By opening any attachment to this message, you agree to accept the risk that it may contain a virus or damaging code, and you agree that ERGO Insurance Pte Ltd. will not be liable for any loss or damage thereby caused.

From: Lina Pang [mailto:Lina.pang@fastechauto.com.sg]
Sent: Tuesday, October 08, 2019 10:25 AM
To: ERGO Insurance Pte. Ltd. (Claims Department); Nancy Lam; Ivy Yong; Phoebe Xie; Pauline Soh
Cc: Jenny Law; Jason
Subject: RE: Claims ref no. (P) CDMCG19001876 Request for PRS : SJM8569L DOA:06/10/2019

Without Prejudice

Dear Pauline,

We will like to select LKK Auto Consultants Pte Ltd.

Thank you,

Best Regards

Lina

Fastech Auto Pte Ltd

1 Kaki Bukit Ave 6

#01-46/48/50 Autobay

Singapore 417883

Tel: 67465405 Fax: 67458520

From: ERGO Insurance Pte. Ltd. (Claims Department) [<mailto:claims@ergo.com.sg>]

Sent: Tuesday, October 8, 2019 10:15 AM

To: Nancy Lam <nancy.lam@fastechauto.com.sg>; Ivy Yong <ivy.yong@ergo.com.sg>; Phoebe Xie <phoebe.xie@ergo.com.sg>; Pauline Soh <pauline.soh@ergo.com.sg>

Cc: Lina Pang <Lina.pang@fastechauto.com.sg>; Jenny Law <jenny.law@fastechauto.com.sg>

Subject: RE: Claims ref no. (P) CDMCG19001876 Request for PRS : SJM8569L DOA:06/10/2019

Dear Jason,

Please refer to our list of surveyors

1	AIS	Automobile Inspection Services Pte Ltd
2	FTA	FormTeam Consultancy Pte Ltd
3	IAS	Infiniti Appraisal Service
4	JPk	JP Knights Pte Ltd
5	LBS	L.B.S Auto Consultants Pte Ltd
6	LKK	LKK Auto Consultants Pte Ltd
7	PS	Priority Services
8	VAC	Vicom Ltd
9	AJAX	AJAX Inspection Services Pte Ltd
10	QRM	Quantum Risk Management (S) Pte Ltd
11	AA	Appraisal Associate

Date Classification : Confidential, C3

Warmest Regards,

Pauline Soh

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-05 Suntec Tower Five

Singapore 038985

DID.: +65 6829 9194

pauline.soh@ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.



Disclaimer: This message and its attachments are confidential, intended only for the named addressee, and may be privileged. If you are not the intended recipient, you should not disclose, distribute, copy or use this communication. If you are not the intended recipient, please notify the sender by return email and delete this message. By opening any attachment to this message, you agree to accept the risk that it may contain a virus or damaging code, and you agree that ERGO Insurance Pte Ltd. will not be liable for any loss or damage thereby caused.

From: Nancy Lam [<mailto:nancy.lam@fastechauto.com.sg>]
Sent: Monday, October 07, 2019 1:23 PM
To: ERGO Insurance Pte. Ltd. (Claims Department)
Cc: Lina Pang; Jenny Law
Subject: Request for PRS : SJM8569L DOA:06/10/2019

WITHOUT PREJUDICE

Hi Sir/Madam,

My client claiming your insured GBB8551P.

Please kindly arrange PRS for SJM8569L.

Date of accident 06.10.2019.

In accordance to APPENDIX C Pre-action Protocol for Non-Injury Motor Accident Cases of PRACTICE DIRECTIONS

AMENDMENT NO. 1 OF 2016 paragraph 2.3, you are require to provide a list of at least 10 motor surveyors within 2 days of the notice.

Regards,
Jason Tang
Fastech Auto Pte Ltd
Tel: 6746 5405
Fax: 6745 8520

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	644D
Vehicle Details	
Vehicle No.:	SJM8569L
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Oct 2019
Vehicle Make:	HONDA
Vehicle Model:	FIT 1.3G A
Primary Colour:	White
Manufacturing Year:	2009
Engine No.:	L13A4155861
Chassis No.:	GE61142820
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$15,029.00
Original Registration Date:	11 Oct 2009
First Registration Date:	11 Oct 2009
Transfer Count:	3
Actual ARF Paid:	\$14,230.00
OPC Cash Rebate Details	
OPC Cash Rebate Eligibility:	No
OPC Cash Rebate Eligibility Expiry Date:	-
OPC Cash Rebate Amount:	-
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Oct 2019
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Sep 2029
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$29,485.00
COE Rebate Amount:	\$29,394.00
Total Rebate Amount:	\$29,394.00

The information contained herein is correct as at 07 Oct 2019

SGCARMART.COM

Login

Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

YOUR NEW BMW AWAITS WITH CARS@EXPO DEALS

Find out more



fit

Price Range

Depreciation

> 10 year

Vehicle Type

Submit

Advanced Search

Home » Used Cars » Zenith Automobile » Honda Fit 1.3A G (COE till 05/2029)

Honda Fit 1.3A G (COE till 05/2029)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Price

\$41,800

Depreciation

\$4,330 /yr

Reg Date

26-Jun-2009
(9yrs 7mths 24days COE left)

Mileage

141,000 km (13.7k /yr)

Manufactured

2009

Road Tax

\$590 /yr

Transmission

Auto

Dereg Value

\$26,923 as of today (change)

OMV

\$13,745

COE

\$27,886

ARF

\$13,745

Engine Cap

1,339 cc

Power

73.0 kW (97 bhp)

Curb Weight

1,010 kg

No. of Owners

5

Type of Vehicle

Hatchback

Features

1.3L I-VTEC Engine, Smooth 5 Speed CVT Transmissions, 2 SRS Airbags, ABS, Key Immobilizer, Knockdown Rear Seats. View specs of the Honda Fit (2008-2013)

Accessories

Leather Seats, Sports Rims, Audio Player, Reverse Sensors, Retractable Side Mirrors.

Description

\$791x84 Month. With Insurance. Well Maintained By Previous Owner! Low Fuel Consumption And Low Maintenance Cost! Smooth And Responsive Engine! Flexible Bank/In House Loan Available! Trade In Most Welcome! Don't Miss!

Category

COE Car

Status

Available

Resources

 Car Valuation - Free

Find out the market value of your existing car for free. [Get started](#)

 Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. [Find out more](#)







Location Map

Shortlist

Compare

Add note

Report Error

More Actions

Seller Information

Company

Zenith Automobile

• dealer's pricelist

• 23 vehs sold | 23 vehs available

Address

1 Bukit Batok Crescent #02-54

Search cars nearby this location

Location

WCEGA Plaza

Office No

66848884

Contact Person(s)

George 88088825

Simon 98197237

https://www.sgcarmart.com/used_cars/info.php?ID=831220&DL=1238

07-Oct-19

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 07/10/2019 09:57
Date Of Accident 06/10/2019 15:45
Exact Location Of Accident SLIP ROAD OF TOA PAYOH LORONG 2 > PIE
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJM8569L
Insured/Policyholder
Name Of Registered Owner FOO SAK MENG
NRIC No S6823644D
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-93858788
Alternative Phone No OTHERS-93858788

Vehicle Particulars

Manufacturer HONDA
Model FIT-1.3 G (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken. THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number 5083351524-02
Cover Note Number 25/09/2019 - 10/10/2020

Driver

Name of Driver FOO SAK MENG
NRIC No S6823644D
Date Of Birth 16/06/1968
Occupation INDOOR
Date Of Driving Pass 07/05/1990
Driving Experience 29 YEARS AND 4 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-93858788
Fax Number
Contact Number OTHERS-93858788
Email Address NOEMAIL

Address BLK163 SIMEI ROAD
 Postcode #02-384
 520163
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance?
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/claiming accident claims assistance NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, Against whom?

ON THE STATED DATE & TIME, I STATIONARY THE SAID LOCATION TO CHECKING THE TRAFFIC FLOW. OUT OF SUDDEN, I FELT AN IMPACT FROM BEHIND AND NOTICED THAT VEHICLE B (GBB8551P) WAS COLLIDED ONTO MY REAR PORTION OF VEHICLE.

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBB8551P
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

IMPORTANT NOTICE
 1. Please report accident to
 2. This form must be
 3. Information
 4.

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIX Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in ensuring, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel
Name:
In-Center No.:



Sketch Plan 

SKETCH PLAN



Surf 1500 of the PLYMOUTH LG 2, Pie

Vol A - 5348569L

Doc E 6882551P

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER CIA REPORT

You had been advised by workshop that in the event that you wish to claim against your own policy (OD claim), there is a Fourteen (14) days clause whereby the claim must be made within the stipulated time-frame from the day of occurrence.

Reporting Only

Claim OO

Claim TP

Claim OD/TP at other workshop

We declare the foregoing particulars are true in every respect.

Policyholder's Signature Date & Place

Reporting Center Personnel
NAME _____
PHONE/EXT. No. _____





GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
4 Kallies Quay #18-00 Singapore 348560
Tel (65) 6224 0010 Fax (65) 6224 0030
Operating Hours: Monday to Friday, 09:00 - 17:00
URL: 1443300390 / GST Reg. No.: M400017793

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No: MMW119132181 Vehicle Registration No: 5JH 8569L
Name (as shown in NRIC): FOO JAY NENG NRIC/FIN/Passport No: S 68 236440
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
Address: BLK 162 SUNEI 2000 402-384 SC530163 Singapore (53063)
Contact (Tel): _____ Mobile No: 97858788
Email Address: _____
Date of Accident: 06-10-2019 Time of Accident: 15:45
Place of Accident: SLIP ROAD OF TPA PATCH LORONG 2 > PIE
Insurance Company: NTUC Income Insurance Co-operative Ltd

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

I WOULD LIKE CHANGED TO THIRD PARTY CLAIM
INSTEAD OF REPORTING ONLY.

[Signature]
Policyholder / Driver's Signature
Date: _____

[Signature]
Reporting Centre Personnel's Signature
Name: _____
NRIC/Fin No: _____
Date: _____



FASTECH AUTO PTE LTD
BLK1 KAKI BUKIT AVE 6
#01-46,48,50 AUTOBAY
SINGAPORE 417883

VEHICLE NO: SJM 8569L

QTY	PARTICULAR
1 PCS	REAR WINDSCREEN MOULDING
1 PCS	TAILGATE
1 PCS	TAILGATE 'FIT' EMBLEM
1 PCS	TAILGATE INNER LOCK
1 PCS	TAILGATE INNER TRIM BOARD
1 PCS	TAILGATE WEATHERSTRIP
1 PCS	REAR BUMPER
2 PCS	REAR BUMPER SIDE REATINERS @\$30.50
1 SET	REAR BUMPER CLIPS
1 PCS	REAR BUMPER BRACKET
1 PCS	REAR END PANEL
1 PCS	REAR END PANEL TOP GARNISH
2 PCS	TAILLAMPS @\$399.00
1 PCS	TAILLAMP HOUSING PANEL N/S
1 PCS	REAR FENDER
1 PCS	REAR FENDER INNER TRIM
1 PCS	REAR FENDER UNDER SPLASHSHIELD
1 PCS	REAR AIR VENT
1 PCS	REAR FLOOR PANEL
1 PCS	REAR FLOOR PANEL tools sponge

S.NETT

1 SET	REAR WHEEL HOUSING PANEL SOUND PROOF INSULATOR
1 SET	REAR FLOOR PANEL SOUND PROOF INSULATOR
1 PCS	REAR WINDSCREEN SEALANT
1 PCS	REAR LICENCE PLATE
1 SET	TAILGATE CARBON STICKER
1 PCS	TAILGATE REVERSE CAMERA
1 SET	REAR BUMPER REVERSE SENSOR
1 SET	REAR BUMPER LOWER SKIRTING
1 PCS	REAR FENDER GLASS SEALANT
1 PCS	REAR END PANEL SEALANT

LABOUR CHARGES

TO CHECK WIRING
TO DISMANTLE & REPLACING REVERSE SENSOR
TO DISMANTLE & REFIX REAR WINDSCREEN
TO TRANSFER TAILGATE MECHANISM
TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTREY
TO DISMANTLE & REFIX REAR QUARTER GLASS
TO DISMANTLE & REFIX REAR EXHAUST
TO SPRAY RUST PROOFING
LABOUR FOR PANEL BEATING & REPLACING PARTS
TO PUTTY & SPRAY PAINTING

not Authorised
L/K
8/10/19
L/S @ 5500
Teleph. After repair
Sdy.

Submittal

re	\$68.10	—
Set/Buc	\$845.20	—
re	\$45.00	—
W/Shift	\$209.60	—
re	\$388.20	X
re	\$166.80	—
re	\$645.50	—
re	\$61.00	IPC
re	\$39.00	—
re	\$145.00	X
re	\$366.00	—
re	\$219.00	—
re	\$798.00	IPC
re	\$288.50	—
re	\$911.20	X
re	\$388.50	—
re	\$66.80	X
re	\$45.00	X
re	\$911.00	X
re	\$388.90	—
	\$6,996.30	

re	\$650.00	200 S.N
re	\$800.00	300 S.N
re	\$50.00	40 S.N
re	\$50.00	X
re	\$220.00	X
re	\$380.00	X
re	\$280.00	200 S.N
re	\$1,200.00	800 S.N
re	\$50.00	X
re	\$50.00	—

	\$80.00	20
	\$80.00	50
	\$150.00	120
	\$100.00	60
	\$120.00	80
	\$100.00	X
	\$100.00	X
	\$120.00	80
	\$1,280.00	800
	\$1,500.00	1100
TOTAL	\$14,356.30	

P-3729.90
20%
2983.92

S.N 1590
L-2310
6883.92
5207

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Nov 2019 17:06 Edit Reg		08 Oct 2019 00:00 Edit Adj Rpt	S\$5,500.00 Edit Estimates	S\$5,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: -, Co. Reg. No.: -									
Main Claimant: -									
Vehicle Reg. No.: SJM8569L		Date of Loss: 06/10/2019 00:00 - :59 [119 Months and 25 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / CDMCG19001876		Policy/Cover Note No.:							
Vehicle Reg. No. (Insured): GBB8551P		Policy No. (Claimant):							
		Excess:							
Repairer: Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, 417883 Kaki Bukit - Tel: 67465405									
Handling Insurer: ERGO Insurance Pte, Ltd. (HQ) - Tel: 6829 9199 ... [Handled by Ivy Yong - 6829 9197]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 17/10/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJM8569L (CDMCG19001876)
[GBB8551P]

TP

-
Oct 6 2019 12:00AM

[-]

Fastech Auto Pte Ltd

Upload Documents | Upload Photos | Compose New Letter

View View in Browser

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	31/10/19 11:08	Adjuster Immediate Advice	 Load HTM	☒
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	31/10/19 11:01	General View	 Load JPG	☒
2	31/10/19 11:01	General View	 Load JPG	☒
3	31/10/19 11:01	General View	 Load JPG	☒
4	31/10/19 11:01	General View	 Load JPG	☒
5	31/10/19 11:01	General View	 Load JPG	☒
6	31/10/19 11:01	General View	 Load JPG	☒
7	31/10/19 11:01	General View	 Load JPG	☒
8	31/10/19 11:01	General View	 Load JPG	☒
9	31/10/19 11:01	General View	 Load JPG	☒
10	31/10/19 11:01	General View	 Load JPG	☒
11	31/10/19 11:01	General View	 Load JPG	☒
12	31/10/19 11:01	General View	 Load JPG	☒
13	31/10/19 11:01	General View	 Load JPG	☒
14	31/10/19 11:01	General View	 Load JPG	☒
15	31/10/19 11:01	General View	 Load JPG	☒
16	31/10/19 11:01	General View	 Load JPG	☒
17	31/10/19 11:01	General View	 Load JPG	☒
18	31/10/19 11:01	General View	 Load JPG	☒
19	31/10/19 11:01	General View	 Load JPG	☒
20	31/10/19 11:01	General View	 Load JPG	☒
21	31/10/19 11:01	General View	 Load JPG	☒
22	31/10/19 11:01	General View	 Load JPG	☒
23	31/10/19 11:01	General View	 Load JPG	☒
24	31/10/19 11:01	General View	 Load JPG	☒
25	31/10/19 11:01	General View	 Load JPG	☒
26	31/10/19 11:01	General View	 Load JPG	☒
27	31/10/19 11:01	General View	 Load JPG	☒
28	31/10/19 11:01	General View	 Load JPG	☒
29	31/10/19 11:01	General View	 Load JPG	☒
30	31/10/19 11:01	General View	 Load JPG	☒
31	31/10/19 11:01	General View	 Load JPG	☒
32	31/10/19 11:01	General View	 Load JPG	☒
33	31/10/19 11:01	General View	 Load JPG	☒
34	31/10/19 11:01	General View	 Load JPG	☒
35	31/10/19 11:01	General View	 Load JPG	☒
36	31/10/19 11:01	General View	 Load JPG	☒
37	31/10/19 11:01	General View	 Load JPG	☒
38	31/10/19 11:01	General View	 Load JPG	☒
39	31/10/19 11:01	General View	 Load JPG	☒
40	31/10/19 11:01	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				☒
41	31/10/19 11:01	General View		☒
42	31/10/19 11:01	General View		☒
43	31/10/19 11:01	General View		☒
44	31/10/19 11:01	General View		☒
45	31/10/19 11:01	General View		☒
46	31/10/19 11:01	General View		☒
47	31/10/19 11:01	Reinspection Photo		☒
48	31/10/19 11:01	Reinspection Photo		☒
49	31/10/19 11:01	Reinspection Photo		☒
50	31/10/19 11:01	Reinspection Photo		☒
51	31/10/19 11:01	Reinspection Photo		☒
52	31/10/19 11:01	Reinspection Photo		☒
53	31/10/19 11:01	Reinspection Photo		☒
54	31/10/19 11:01	Reinspection Photo		☒
55	31/10/19 11:01	Reinspection Photo		☒
56	31/10/19 11:01	Reinspection Photo		☒
57	31/10/19 11:01	Reinspection Photo		☒
58	31/10/19 11:01	Reinspection Photo		☒
59	31/10/19 11:01	Reinspection Photo		☒
60	31/10/19 11:01	Reinspection Photo		☒
61	31/10/19 11:01	Reinspection Photo		☒
62	31/10/19 11:01	Reinspection Photo		☒
63	31/10/19 11:01	Reinspection Photo		☒
64	31/10/19 11:01	Reinspection Photo		☒
65	31/10/19 11:01	Reinspection Photo		☒
66	31/10/19 11:01	Reinspection Photo		☒
67	31/10/19 11:01	Reinspection Photo		☒
68	31/10/19 11:01	Reinspection Photo		☒
69	31/10/19 11:01	Reinspection Photo		☒
70	31/10/19 11:01	Reinspection Photo		☒
71	31/10/19 11:01	Reinspection Photo		☒
72	31/10/19 11:01	Reinspection Photo		☒
73	31/10/19 11:01	Reinspection Photo		☒
74	31/10/19 11:01	Reinspection Photo		☒
75	31/10/19 11:01	Reinspection Photo		☒
76	31/10/19 11:01	Reinspection Photo		☒
77	31/10/19 11:01	Reinspection Photo		☒
78	31/10/19 11:01	Reinspection Photo		☒
79	31/10/19 11:01	Reinspection Photo		☒
80	31/10/19 11:01	Reinspection Photo		☒
81	31/10/19 11:01	Reinspection Photo		☒
82	31/10/19 11:01	Reinspection Photo		☒
83	31/10/19 11:02	Reinspection Photo		☒
84	31/10/19 11:02	Reinspection Photo		☒
85	31/10/19 11:02	Reinspection Photo		☒
86	31/10/19 11:02	Reinspection Photo		☒
87	31/10/19 11:02	Reinspection Photo		☒
88	31/10/19 11:02	Reinspection Photo		☒
89	31/10/19 11:02	Reinspection Photo		☒
90	31/10/19 11:02	Reinspection Photo		☒
91	31/10/19 11:02	Reinspection Photo		☒
92	31/10/19 11:02	Reinspection Photo		☒
93	31/10/19 11:02	Reinspection Photo		☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI19017673/UVF3E2

Date: 01/11/2019

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant

Vehicle No : SJM8569L

Insured Vehicle No : GBB8551P

Date of Loss: 06/10/2019

Nature of Claim:

TP

Claim No: CDMCG19001876

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJM8569L

Make & Model: HONDA FIT, 1.3 G (A)

Engine No: L13A4155861

Reg. Date: 11/10/2009 (Man. Year: 2009)

Chassis No: GE61142820

Colour: White

Odometer: 68761 km

Engine Capacity: 1339 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55 R15

Rear Tyre Size:

195/55 R15

Front Left Side: Michelin 6 mm

Rear Left Side:

Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side:

Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,726.30	4,573.92	6,152.38	57.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,630.00	2,310.00	1,320.00	36.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,356.30	6,883.92	7,472.38	52.05
Approved Total (Overridden) (S\$)		5,500.00		
(S\$)	14,356.30	5,500.00	8,856.30	61.69
+ GST 7.00/7.00% (S\$)	1,004.94	385.00	619.94	61.69
Nett Amount (S\$)	15,361.24	5,885.00	9,476.24	61.69

INSPECTION

Date of Assignment: 08/10/2019

Date Inspected: 08/10/2019 Inspected At:

Fastech Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #01-46/48/50
Autobay
Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Nov 2019)
Parts:	144	HONDA FIT 1.3 G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJM8569L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	68.10 F	*68.10 FL
2	1		*TAILGATE	Bent / Buckled	845.20 F	*845.20 FL
3	1		*TAILGATE FIT EMBLEM	Necessary	45.00 F	*45.00 FL
4	1		*TAILGATE INNER LOCK	Dented / Shorted	209.60 F	*209.60 FL
5	1		*TAILGATE INNER TRIM BOARD	Not Necessary	388.20 F	*- FL
6	1		*TAILGATE WEATHERSTRIP	Twisted	166.80 F	*166.80 FL
7	1		*REAR BUMPER	Distorted	645.50 F	*493.70 FL
8	1		*REAR BUMPER SIDE RETAINERS	N/S Bent	61.00 F	*30.50 FL
9	1		*SET REAR BUMPER CLIPS	Necessary	39.00 F	*39.00 FL
10	1		*REAR BUMPER BRACKET	No such part	145.00 F	*- FL
11	1		*REAR END PANEL	Dented / Bent	366.00 F	*296.60 FL
12	1		*REAR END PANEL TOP GARNISH	Twisted	219.00 F	*184.20 FL
13	1		*TAILLAMPS	N/S Cracked	798.00 F	*285.30 FL
14	1		*TAILLAMP HOUSING PANEL N/S	Dented / Bent	288.50 F	*288.50 FL
15	1		*REAR FENDER	Repair	911.20 F	*- FL
16	1		*REAR FENDER INNER TRIM	Deformed / Torn	388.50 F	*388.50 FL
17	1		*REAR FENDER UNDER SPLASHSHIELD	Not Necessary	66.80 F	*- FL
18	1		*REAR AIR VENT	Not Necessary	45.00 F	*- FL
19	1		*REAR FLOOR PANEL	Repair	911.00 F	*- FL
20	1		*REAR FLOOR PANEL TOOLS SPONGE	Torn	388.90 F	*388.90 FL
21	1		*SET REAR WHEEL HOUSING PANEL SOUND PROOF INSULATOR	Necessary	650.00 FS	*200.00 FS
22	1		*SET REAR FLOOR PANEL SOUND PROOF INSULATOR	Necessary	800.00 FS	*300.00 FS
23	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
24	1		*REAR LICENSE PLATE	Not Necessary	50.00 FS	*- FS
25	1		*SET TAILGATE CARBON STICKER	Not Necessary	220.00 FS	*- FS
26	1		*TAILGATE REVERSE CAMERA	Serviceable	380.00 FS	*- FS
27	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
28	1		*SET REAR BUMPER LOWER SKIRTING	Cracked	1,200.00 FS	*800.00 FS
29	1		*REAR FENDER GLASS SEALANT	Not Necessary	50.00 FS	*- FS
30	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 10,726.30 5,319.90
 - List Item Discount on L Items 0.00/20.00% (\$\$) 0.00 745.98

Total Parts (\$\$) 10,726.30 4,573.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	80.00	20.00
2	TO DISMANTLE & REPLACING REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	120.00
4	TO TRANSFER TAILGATE MECHANISM	New	100.00	60.00
5	TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTREY	New	120.00	80.00
6	TO DISMANTLE & REFIX REAR QUARTER GLASS	New	100.00	0.00
7	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	0.00
8	TO SPRAY RUST PROOFING	New	120.00	80.00
9	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	1,280.00	800.00
10	TO PUTTY & SPRAY PAINTING	New	1,500.00	1,100.00
Gross Labour Cost (\$\$)			3,630.00	2,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >