99/03/2002 ASS. REC. BY:	REF: CS	SPF 19017624/ As	F307 Special Instruction:
From (Person)	Adnay As Haseul Ferhon Rahmat of	SSIGNMENT (Office	Date/Time: 8.10.19 11.414.m
Estimated Cos OD TP WS	st:st-TP RES / OD RES / EVA / IN	Bill to:	
at Workshop i	hicle No: SJJ 5095B m/s Kang (av Repairum Bukit In 6 407-0	h Authbau	Insured: Qx 5998 Tel: 6747 7636
Policy No:			AEMD/105/009/2019/09&
Sum Insured: Make of Veh: (Client's Record		Excess:	D.O.A. 5.10. 2019
CA / REV /	REP. / REV 24 HRS		H.O.D Endorsement: Vehicle IN OUT
Date/Time	Action/Instruction (✓)	Estimate	
	Q X 529 P-X		Do Not Finalise

ASSIGNMENT

From: Date:	Veh No: 5JJ5085B Yr Regn: 2008 Sept
Estimated Cost:	Type: M.Cap/ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make: Toyola Altis c.c 1598
at Workshop m/s	Colour Black - A/C: Insured / Std / NI / NA
of	Sp.Reading 3+88+0 T/Radio: Insured / Std / NI / NA
nsured:	Eng/No:
Policy No.	C/No: MR053ZEE106117418
Claims No.	Gen. Cond: Good/ Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Morder/ Jammed / Leaked / Burnt or
(Client's Record)	Brake: (Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil/S/Rim) STD A/Rim or
	Tyre Size: F: 205/35 R16
(Policy Condition)	R: 205/55/216/
Remark: The veh had commenced its N/S 0/S	
repair at the time of inspection.	TOYO/YOKO or
Bal, or Market Value:	Front Rear
DAC Accident Rport: Consistent? : Yes or No	R/Bal. OG mm R/Bal. OG mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 06 mm L/Bal. 06 mm
Est. Repairs: days Res.: Yes or No	D.O.A. D.O.I. 08/10/19,
Lum Sum: % 3 Val.: Yes or No	Survey held at Kony
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / OU	
Date:Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction TP SPF	10E Evalua 31/08/23
27/11/19 Submit LIS \$ 8,150/- C	10 Expiry: 31/08/23. 2 / Lays (weekends - 2 day) = 15da 2%)
(\$3,745.00 Red - 3	2%)
MV: 26K	Reprir Range : 7.516 - 8:515
PV: 13.3K	7 0
Nett: 12.7k.	- 0 = 1/4 = 0 0 0 10 10 10 10 10 10 10 10 10 10 10
R	ECEIVED 2 7 NOV 2019
Date/Time, File Pass to? 27/11/19 1) Typic+ : Final Report	Days Of Repair: 9 Resurvey No. of Trip: Survey Fee: 770
Date/Time, File Return to?	Transportation:
Add F	
	: Interview (\$) Photos
Report Format:	: Tech, Invs (3) Others
Jump Sup / I.B. K. (\$ 8,150/- 45	:Weelend (\$
	1018T >M

Summer Lee (LKK Auto)

From:

Hafizul Farhan RAHMAT (SPF) < Hafizul_Farhan_RAHMAT@spf.gov.sg>

Sent:

Tuesday, 8 October, 2019 11:41 AM assignments; SUR; Admin-D (LKKAuto)

To: Cc:

Frankie THAY (SPF); Cui Fen ENG (SPF)

Subject:

Pre-repair survey of SJJ5085B; (vs QX529P on 05.10.2019)

Attachments:

GIA-SJJ5085B.pdf

Message Classification: Unclassified

Our ref: AEMD/105/009/2019/098

Hi,

Kindly conduct pre-repair survey for SJJ5085B at

Kang Car Repairers Pte Ltd 1 Kaki Bukit Ave 6 #02-06 Autobay@Kaki Bukit Singapore 417883

Contact: Sharon, Tel: 67477636

Thank you.

Best Regards,

Hafizul Farhan Bin Rahmat AEMD / PLD Singapore Police Force DID: (65) 6478 4840 | FAX: (65) 6478 4848



WARNING "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC	
Owner ID:	672D	
Vehicle Details		
Vehicle No.:	SJJ5085B	
Vehicle to be Exported:	Yes	
Intended Deregistration Date:	09 Oct 2019	
Vehicle Make:	TOYOTA	
Vehicle Model:	COROLLA ALTIS 1.6 AUTO	
Primary Colour:	Black	
Manufacturing Year:	2008	
Engine No.:	3ZZ4791885	
Chassis No.:	MR053ZEE106117418	
Maximum Power Output:	80.0 kW (107 bhp)	
Open Market Value:	\$16,777.00	
Original Registration Date:	17 Sep 2008	
First Registration Date:	17 Sep 2008	
Transfer Count:	0	
Actual ARF Paid:	\$16,777.00	
Intended PARF Rebate Details	X Control of the Cont	
PARF Eligibility:	Forfeited	
PARF Eligibility Expiry Date:	•	
PARF Rebate Amount:	\$0.00	
Intended COE Rebate Details		S EL ST
COE Expiry Date:	31 Aug 2023	
COE Category:	A - Car (1600cc & below)	
COE Period(Years):	5	
PQP Paid:	\$17,099.00	
COE Rebate Amount:	\$13,311.00	
Total Rebate Amount: Message	\$13,311.00	

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 09 Oct 2019

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles


Forum

Resources









Compare [4]

Toyota Corolla Altis 1.6A (COE \$28,500 till 03/2024)

\$6,440 /yr

13-Mar-2009

1,598 cc

Sedan

Available

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

	ACCIDENT STATEMENT
Date Of Report	07/10/2019 15:27
Date Of Accident	05/10/2019 17:10
Exact Location Of Accident	JURONG TOWN HALL RD TWDS SCIENCE CENTRE
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE

	D	ETA	LS O	F OW	N VEH	ICLE
--	---	-----	------	------	-------	------

Vehicle Registration Number SJJ5085B

Insured/Policyholder

Name Of Registered Owner CHONG CHU SIM

NRIC No S7002672D

Email Address LEON.FIRSTEP@GMAIL.COM

Mobile Phone No (LOCAL) +65-98216180

Alternative Phone No OFFICE-98216180

Vehicle Particulars

Manufacturer TOYOTA

Model COROLLA ALTIS-1.6 (A)

Exact Purpose for which vehicle was being used at

time of accident

HIRE & REWARD

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE HIRE

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number 5101781421-01

Cover Note Number

Driver

Name of Driver CHONG CHU SIM
NRIC No S7002672D

Date Of Birth 02/01/1970
Occupation OUTDOOR
Date Of Driving Pass 12/12/1994

Driving Experience 24 YEARS AND 9 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-98216180

Fax Number

Contact Number OFFICE-98216180

EMail Address LEON.FIRSTEP@GMAIL.COM

Address

BLK 115 EDGEFIELD PLAINS #11-350

Postcode

820115

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle) involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

2

Passenger 1

NAME:

: UNKOWN

GENDER:

: FEMALE

Details of Police Action

Was the accident reported to the police?

YES

Police Station Name

If Yes, Please state which Police Station

Police Station Address

ROAD: 21A TEBING LANE, POSTCODE: 828837, COUNTRY:

SINGAPORE

Police Station Contact

TEL NO: - FAX NO:

PUNGGOL N.P.C

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

SEE ATTACHED POLICE RPEORT NO: T/20191005/2129

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

QX529P

Vehicle Make/Model/Colour

Details Of Properties

VEHICLE B GOVERNMENT

Vehicle Category Name of Driver

NRIC/Passport Number

Contact Number

Address

Page 2 of 23

Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

01/10/19 1360 hrs

Driver's Signature

(If driver is not the policyholder)

Date & Time: 07/10/19 12001

Reporting Centre Personnel's Signature Name:

NRIC/FIN No .:

SKETCH PLAN

Science & Jung Town Hall Rd



A: SJJ 5085B B: QX 529P.

See	attached	Police	Report	NoT	/20191005/2129
			1		· ·
	111				
		1			
ARATION					1
eclare the	foregoing particulars ar	e true in every res	spect.		1
WILL		1111			
AND.		The			
noider's Sign	ature	Driver's Signature		Re	porting Centre Personnel's Signature
Time:	12.1	(If driver is not the	policyholder)		ime:
0/19	1300 hrs	Date & Time: ,	19 1300h	NR	RIC/FIN No.:





Police Station Of Origin: Punggol N.P.C 21A Tebing Lane SINGAPORE 828837 Tel No: 1800-6049999 1 of 3 Report No. T/20191005/2129

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 05/10/2019 22:01			Vide Report No.:	Station Diary No.: 89		
Informa	int's Partic	ulars				
Name of Informant: CHONG CHU SIM			Address: APT BLK 115 EDGEFIELD PLAINS #11-350 SINGAPORE 820115			
ID Type / ID No.: NRIC NO / S7002672D Nationality: SINGAPORE CITIZEN			Contact No.: Home/Office: Mobile: 98216180 Email:			
Sex: Age: Date of Birth: Male 49 02/01/1970		Type of Informant: Driver				
Race: Chinese			Language: English	Institution / School Name:		
Occupation: GRAB DRIVER			Driving Licence Informa Class: 3	tion: Date of Expiry:		

Type of	Non-Injury	Drink	Date/Time of		Type of Location:	
Accident:	Police Vehicle	Drive:	Accident:		T-Junction	
Accident.		No	05/10/2019 17:10			
JURONG TO	WN HALL ROAD WN HALL ROAD Town Hall road at the t	hird lane towards So	ience Centre			
Weather:		Road Surface:			Road Speed Limit:	
Clear		Dry	Dry			
Traffic Flow:		Traffic Control:		Traffic Volume:		
Dual Carriage	Way	Traffic Light - Wo	Traffic Light - Working		Moderate	
Type of Collisi Between Movi	on: ng Vehicles - Head To	Rear	-		one conveyed by ulance:	

Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenge
QX529P	Car	ТОУОТА	COROLLA ALTIS 1.6 AUTO	White	Seriously Damaged	1
SJJ5085B	Car	ТОУОТА	COROLLA ALTIS 1.6 AUTO	Black	Seriously Damaged	1

Details of Vehicle Insurance	
Vehicle No. Insurance Company Insurance No Effective I	xpiry Date





Police Station Of Origin: Punggol N.P.C 21A Tebing Lane SINGAPORE 828837 Tel No: 1800-6049999 2 of 3 Report No. T/20191005/2129

CONTINUATION OF REPORT

Details of Vehicle Insurance						
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date		
SJJ5085B	NTUC Income Insurance Co-Operative Limited	5101781421-01	17/09/2019	16/09/2020		

Brief Details.

On 05/10/2019 at about 1710hrs, I was driving my vehicle SJJ5085B along Jurong Town Hall road at the third lane towards science centre. I was driving at a slow speed on the road and there was a vehicle SJQ5124K in front of my vehicle. The vehicle SJQ5124K make a brake as there was a bus filtering towards the third lane.

I also applied brake but still moving slowly but subsequently I felt an impact from the rear of my vehicle and I quickly stepped on my brake. I then stationary stopped my vehicle. I then check with my passenger if she is alright and she informed me that she is alright. I then stepped out of my vehicle to make a check. I discovered that I had an accident with a police vehicle QX529P.

I spoke to the police officer who drove the vehicle what happened however he informed me nothing. He only requested for my particulars. The other police officer came over and asked me if I am alright. I told him that I felt numbness at the back of my head area.

After a while, the traffic police came and took the police officer particulars and my particulars. I asked for the driver particulars however he asked me to speak to the traffic police. I asked the traffic police and he informed me not to worry and they will investigate. We took photos of the scene.

I have an in-build car camera in my vehicle viewing the front and the accident footage was captured. I send the accident footage into my mobile phone. I then showed the accident footages to the traffic police and he recorded it by using a mobile phone. The traffic police gave me a case card D/20191005/0096. The traffic police then advise me to lodge a traffic accident report.

I was unable to drive my vehicle anymore. I called Grab and informed about the matter. Grab then find another driver to fetch my passenger. I called my insurance about the matter too and they arrange a tow truck came and took over my vehicle.





Police Station Of Origin: Punggol N.P.C 21A Tebing Lane SINGAPORE 828837 Tel No: 1800-6049999

3 of 3 Report No. T/20191005/2129

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report	t: Signature Of Informant:
Sgt 2 IVIN ONG HONG CHUAN	
Signature Of Interpreter: Not applicable	Date/Time
Tot applicable	05/10/2019 22:01
Officer In Charge Of Case:	Classification Of Case:
TP / DDGVT / SI VILTON HIA WEE SIANG	
Contact No.: 65476228	SN 085
Authentication Stamp	Signature:
NP168	
S'n-	rapore Police Force

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883 TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg GST:201300201N

M/S: SINGAPORE POLICE FORCE

AUTOMOTIVE ENGINEERING & MGT DIVISION

POLICE LOGISTICS DEPT, 1 MOUNT PLEASANT

BLK 8 OLD POLICE ACADEMY, SE 298333

ATTN: Motor Claim Department

Shir ley

Estimate No:

EST1900333

Date:

08 Oct 2019

Veh Reg No:

SJJ5085B

Make/Model:

TOYOTA ALTIS 1.6

AUTO

Chasis No:

MR053ZEE106117418

Reg. Date:

17/09/2008

Your Ref No:

QX529P

Accident Date: TP Veh Reg No:

Claim Type:

05/10/2019 QX529P

Third Party

Estimate Repair Cost to Vehicle No :SJJ5085B

Quantity		Description	List Price	Amoun
			<u>SS</u>	<u>SS</u>
		List Price		
	1 PC	BOOT LID Dertld	667.60	
2	1 PC	BOOT LID LOGO	52.10	
	1 PC	BOOTLID "1.6" EMBLEM	32.40	
	1 PC	BOOTLID "COROLLA" EMBLEM 2	42.30 -	
	1 PC	BOOT LID "ALTIS" EMBLEM	44.20	
	1 PC	BOOT LID LAMP LH Cut	267.20	
	2 PCS	BOOT LID HINGE ALL	180.40	۲.
8	1 PC	BOOT LID LOCK Pod	196.50	
9	1 PC	BOOT LID LOCK CHECKER Au	39.10	
10	1 PC	BOOTLID TRIM XVI W	159.10	
11	4 PCS	BOOTLID STOPPER MG	24.00	
12	1 PC	BOOT LID LAMP LH INNER COVER MG	34.20	t .
13	1 PC	REAR FENDER LH Distorte	1,029.70	
14	1 PC	REAR FENDER INNER TRIM LH COMPLETE	334.20	V
15	1 PC	REAR FENDER LOWER INNER PANEL RH DISCLE	266.30	
16	1 PC	REAR WINDSCREEN RUBBER	75.60 ~	
17	1 PC	REAR FENDER LH HOUSING INNER TRIM	175.90 -	+
18	1 PC	REAR FENDER VENTILATION COVER LH	124.70	
19	1 PC	REAR FENDER MUDFLAP LH	39.70	
20	1 PC	REAR DOOR LH Brelched.	1082-10	2/
21	1 PC	REAR DOOR LOCK LH	424.70	
22	1 PC	REAR DOOR LOCK CHECKER LH MY	29.50	
23	1 PC	REAR DOOR RUBBER LH	175.80 -	
24	1 PC	REAR DOOR PROTECTOR LH	66.20	1
25	1 PC	REAR DOOR PROTECTOR MOULDING LH GAY L	22.20	-
26	1 PC	REAR DOOR OUTER MOULDING LH	131.20	P
27	1 PC	REAR DOOR FRAME BLACK STICKER LH	64.30 -	
28	1 PC	TAIL LAMP LH Could	360.90	
29	1 PC	TAIL LAMP PANEL LH DISLL	89.30	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883 TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg GST:201300201N

M/S: SINGAPORE POLICE FORCE

ATTN: Motor Claim Department

AUTOMOTIVE ENGINEERING & MGT DIVISION

POLICE LOGISTICS DEPT, 1 MOUNT PLEASANT

BLK 8 OLD POLICE ACADEMY, SE 298333

Veh Reg No: SJJ5085B

Make/Model: TOYOTA ALTIS 1.6

AUTO

Chasis No:

Estimate No:

Date:

MR053ZEE106117418

Reg. Date: Third Party

Your Ref No:

17/09/2008

QX529P

EST1900333

08 Oct 2019

Accident Date: TP Veh Reg No:

Claim Type:

05/10/2019 QX529P

Estimate Repair Cost to Vehicle No :SJJ5085B

	Quantity	Description	List Price Amount
		2011	<u>SS</u> <u>SS</u>
30	1 PC	REAR PANEL Distil	552.20
31	1 PC	REAR PANEL TRIM Det C	185.30
32	1 PC	SPARE TYRE COVER ton REAR BUMPER Distle	348.10
33	1 PC		499.70
34	1 PC	REAR BUMPER REINFORCEMENT	117.50
35	1 PC	REAR BUMPER SPONGE - LH	81.40
36	2 PCS	REAR BUMPER BRACKET LH Bet	165.60 82.80
37	2 PCS	REAR BUMPER SIDE RETAINER HH HL	153.60 76.80
38	2 PCS	REAR BUMPER RETAINER (SMALL) LH ~~	79.40 39.70
39	2 PCS	FRT BUMPER SIDE RETAINER (BELOW TAIL LAMP) LH Com-	
40	1 PC	REAR BUMPER REFLECTOR - LH	33.90
			8.217.20 2592.50
		Less 25%	<u>2.054.30</u> 6.163.00
		Special Net	6444.37
41	1 PC	BOOTLID TRIM CLIPS LU L	48.00 ←
42	1 SET	REAR FENDER INNER TRIM CLIPS LH NUC	48.00-30
43	1 SET	REAR FENDER INNER TRIM CLIPS RH X4 ~	48.00
44	1 PC	REAR WINDSCREEN SEAL 2	60.00 30
45	1 PC	REAR WINDSCREEN SEALANT	60.00 30
46	1 SET	REAR FENDER MUDFLAP CLIPS LH NGC 1(30	20.00
47	1 SET	REAR PANEL TRIM CLIPS	40.00 /3
48	1 PC	REAR BUMPER SPOILER Distant	Z50.00
49	1 SET	REAR BUMPER CLIPS MC	48.00 30
50	4 PCS	REAR BUMPER LOWER SPOILER BRACKET Best	100.00 50
51	1 SET	REVERSE SENSORS Dend	250.00 200
			1.472.00 1.472.00
		Labour	
52	1	TO CHECK WIRING	50.00 30
53	Ī	TO REMOVE AND REFIT REAR WINDSCREEN	120.00
1000	7		

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883 TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg GST:201300201N

M/S: SINGAPORE POLICE FORCE

ATTN: Motor Claim Department

AUTOMOTIVE ENGINEERING & MGT DIVISION

POLICE LOGISTICS DEPT, 1 MOUNT PLEASANT

BLK 8 OLD POLICE ACADEMY, SE 298333

Estimate No:

EST1900333

Date:

08 Oct 2019

Veh Reg No:

SJJ5085B

Make/Model:

TOYOTA ALTIS 1.6

AUTO

Chasis No:

MR053ZEE106117418

Claim Type: Accident Date: Third Party

05/10/2019

Reg. Date:

17/09/2008

Your Ref No:

OX529P

TP Veh Reg No: QX529P

Estimate Repair Cost to Vehicle No :SJJ5085B

	Quantity	Description	List Pr	ice Amount
54 55 56 57 58 59 60	1 1 1 1 1 1	TO REMOVE AND REFIT SEAT CUSHION TO REMOVE AND REFIT PETROL TANK TO REMOVE AND REFIT REVERSE SENSOR TO SPRAY UNDERSEAL (REAR) TO SPRAY PAINTING TO REMOVE AND REFIT DOOR GLASS TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR	180: .80: 150:	
		CUTTING/WELDING WORKS.	4.260.	00 4.260.00
		12126-42	Total	S\$ 11,895.00
			ST @ 7%	832.65
		Total Amoun	nt Payable	S\$ 12,727.65

TOTAL: SINGAPORE DOLLAR TWELVE THOUSAND SEVEN HUNDRED TWENTY SEVEN AND CENTS SIXTY FIVE ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Internation	onale Des Experts En Automobi	ile			
AUTOMOTIVE ENGIN	AUTOMOTIVE ENGINEERING & MGT DIVISION Ref : CS/SPF19017684/Asf3e2					
FORCE) 1 MOUNT PL POLICE ACADEMYSII		Date: 05-12-2019 Code: SPF				
ATTN : HAFIZUL FARI	2 7/22 00/2 1/20/21/01 2/2		Principal Company			
1.	QX 529P	:- THIRD PARTY CLAIM	SJJ 5085B			
Insured Veh.	QX 529P	Veh. Inspected	0.00			
Policy No.	AEMD/105/009/2019/098	Coverage (\$)	0.00			
Claim No.	HAFIZUL FARHAN RAHMAT	Excess (\$) Assign Date	08/10/2019			
Assign From			00/10/2019			
2.	TOYOTA ALTIS	culars & Condition	1598			
Make & Model	10101111110	c.c	2008			
Engine No.	HIDDEN MR053ZEE106117418	Year of Reg.	BLACK			
Chassis No.	348840		IN ORDER			
Odometer Brakes	IN ORDER	Steering Modification	SPORTS RIM			
General	GOOD	Modification	SPORTS KIIVI			
3.		ions of Tyres				
3.	Size	Make	Balance			
R/H Front Tyre	205/55 R16	PIRELLI	6 mm			
L/H Front Tyre	205/55 R16	PIRELLI	6 mm			
R/H Rear Tyre	205/55 R16	PIRELLI	6 mm			
L/H Rear Tyre	205/55 R16	PIRELLI	6 mm			
4.		on of Damages				
The same of the sa	STAINED DAMAGES AT THE RE					
DAMAGES SEE D	FTAII S					
5.		I Information				
Accident Date	05/10/2019	Inspection Date	08/10/2019			
Survey held at	KANG CAR REPAIRERS PTE L					
	NO.1 KAKI BUKIT AVE 6 #02-06 AUTOBAY @ KAKI BUKIT SINGAPORE 417883					
5a.	R	emarks				
	ON WAS CONDUCTED ON A"WIT CE TO YOUR INSTRUCTIONS, W					
5b.	Estimate	Days of Repair				
ESTIMATED NOR	ESTIMATED NORMAL PERIOD FOR REPAIR: 9 Working Days					



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJJ 5085B

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BOOT LID	DENTED	667.60	667.60
1	BOOT LID LOGO	NECESSARY	52.10	52.10
1	BOOTLID "1.6" EMBLEM	NECESSARY	32.40	32.40
1	BOOTLID "COROLLA" EMBLEM	NECESSARY	42.30	42.30
1	BOOT LID "ALTIS" EMBLEM	NECESSARY	44.20	44.20
1	BOOT LID LAMP LH	CUT	267.20	267.20
2	BOOT LID HINGE	NOT NECESSARY	180.40	-
1	BOOT LID LOCK	DAMAGED	196.50	196.50
1	BOOT LID LOCK CHECKER	NOT NECESSARY	39.10	-
1	BOOTLID TRIM	NOT NECESSARY	159.10	-
4	BOOTLID STOPPER	NOT NECESSARY	24.00	-
1	BOOT LID LAMP LH INNER COVER	NOT NECESSARY	34.20	-
1	REAR FENDER LH	DISTORTED	1,029.70	1,029.70
1	REAR FENDER INNER TRIM LH	CRUMPLED	334.20	334.20
1	REAR FENDER LOWER INNER PANEL RH	DISTORTED	266.30	266.30
1	REAR WINDSCREEN RUBBER	NECESSARY	75.60	75.60
1	REAR FENDER LH HOUSING INNER TRIM	NOT NECESSARY	175.90	-
1	REAR FENDER VENTILATION COVER LH	CRACKED	124.70	124.70
1	REAR FENDER MUDFLAP LH	NOT NECESSARY	39.70	-
1	REAR DOOR LH	BUCKLED	1,082.10	1,082.10
1	REAR DOOR LOCK LH	DAMAGED	424.70	424.70
1	REAR DOOR LOCK CHECKER LH	NOT NECESSARY	29.50	-
1	REAR DOOR RUBBER LH	NOT NECESSARY	175.80	-
1	REAR DOOR PROTECTOR LH	NOT NECESSARY	66.20	-
1	REAR DOOR PROTECTOR MOULDING LH	NOT NECESSARY	22.20	-
1	REAR DOOR OUTER MOULDING LH	NOT NECESSARY	131.20	-
1	REAR DOOR FRAME BLACK STICKER LH	NECESSARY	64.30	64.30
1	TAIL LAMP LH	CRACKED	360.90	360.90
1	TAIL LAMP PANEL LH	DISTORTED	89.30	89.30
1	REAR PANEL	DISTORTED	552.20	552.20
1	REAR PANEL TRIM	DEFORMED	185.30	185.30

Report Ref No. CS/SPF19017684/Asf3e2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	SPARE TYRE COVER	TORN	348.10	348.10
1	REAR BUMPER	DISTORTED	499.70	499.70
1	REAR BUMPER REINFORCEMENT	BENT	117.50	117.50
1	REAR BUMPER SPONGE - LH	CRACKED	81.40	81.40
2	REAR BUMPER BRACKET	N/S BENT	165.60	82.80
2	REAR BUMPER SIDE RETAINER	N/S NECESSARY	153.60	76.80
2	REAR BUMPER RETAINER (SMALL)	N/S NECESSARY	79.40	39.70
2	FRT BUMPER SIDE RETAINER (BELOW TAIL LAMP)	N/S CRACKED	144.40	72.20
1	REAR BUMPER REFLECTOR - LH	CRACKED	33.90	33.90
	LESS 25% DISCOUNT		-2,148.13	-1,810.93
			6,444.37	5,432.77
	SPECIAL NETT ITEMS			
1	BOOTLID TRIM CLIPS (SN)	NOT NECESSARY	48.00	-
1	SET REAR FENDER INNER TRIM CLIPS LH (SN)	NECESSARY	48.00	30.00
1	SET REAR FENDER INNER TRIM CLIPS RH (SN)	NOT NECESSARY	48.00	-
1	REAR WINDSCREEN SEAL (SN)	NECESSARY	60.00	30.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	60.00	30.00
1	SET REAR FENDER MUDFLAP CLIPS LH (SN)	NOT NECESSARY	20.00	-
1	SET REAR PANEL TRIM CLIPS (SN)	NECESSARY	40.00	10.00
1	REAR BUMPER SPOILER (SN)	DISTORTED	750.00	750.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	48.00	30.00
4	REAR BUMPER LOWER SPOILER BRACKET (SN)	BENT	100.00	50.00
1	SET REVERSE SENSORS (SN)	DAMAGED	250.00	200.00
			1,472.00	1,130.00
	LABOUR			
	TO CHECK WIRING.		50.00	30.00
	TO REMOVE AND REFIT REAR WINDSCREEN.		120.00	120.00
	TO REMOVE AND REFIT SEAT CUSHION.		200.00	150.00
	TO REMOVE AND REFIT PETROL TANK.		180.00	80.00
	TO REMOVE AND REFIT REVERSE SENSOR.		80.00	50.00
	TO SPRAY UNDERSEAL.		150.00	120.00
	(REAR) TO SPRAY PAINTING.		1,600.00	1,500.00

Report Ref No. CS/SPF19017684/Asf3e2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO REMOVE AND REFIT DOOR FITTINGS.		80.00	80.00
	TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING / WELDING WORKS.		1,800.00	1,500.00
			4,260.00	3,630.00
	GRAND TOTAL		12,176.37	10,192.77

RECOMMENDED COST OF LUMP SUM REPAIRS		8,150.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/SPF19017684/Asf3e2

NOTES: THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$7,500-\$8,500

RECOMMENDED REPAIR DAYS: 11

WEEKEND: 4 TOTAL DAYS: 15



ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.