

INSURANCE

INS. CASE OWNER:

Sundari

CC 4/III/1901 7717, A 9/17/19

LKK:
IDAC:

Surveyor:

Addan

DOI:

ASSIGNMENT

7/10/19

Date / Time:

7/10/19

Registered in Merimen:

7/10/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHH 22532

Name of Insured:

LTPL

Insured Tel No.:

HP:

Excess Sec II : \$5

D.O.A:

5/10/19

Is driver the owner? (YES / NO)

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Only Sam Hui 18 years

Driver Tel No.:

(VA: YES / NO)

Claim No.:

Policy No.:

Make / Model:

HM 1000

Place of Accident:

upp 4th floor East 1 Expo BR

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

% Final ? Yes / No

GR 811K



INSRS:
WSP:
Tel:
Liability:
RMKS:

SD
CNR CARE



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time		STAGE	DATE/ PIC
	GR 811K	Non-Reporting Itr (1st):	
	SHH 22532	Non-Reporting Itr (2nd):	
		Non-Reporting Itr (Final):	
		Notification Itr (if non-pickup):	
		Call OI:	
		After call Itr to OI:	
		Documentation Check List: Handler	Typist
		Notification Itr (if non-pickup)	
		After call Itr to OI:	
		Authorisation To Act:	
		Release Voucher:	
		Final Repair Bill:	
		Car Rental Invoice:	
		Towing Invoice:	
		LTA / GIA:	
		Medical Bill:	
		PIR:	
		Mandate/Reject Instruction:	
		LOD:	
		Payment Breakdown Form:	
		Post-Repair Photos:	
		Others:	

PRELIMINARY ADVICE	Date/Time:	Sent By:	Confirm with:	Confirm by:
Repair Cost:	\$5	(days) Reduction:	%	Email ☐ Call ☐
FINAL SETTLEMENT	Date/Time:	Confirm with:	Email ☐ Call ☐	
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No.:	7	If NO or B 28, Ass. Lia:
Repair Cost:	\$5			
Loss of Rental (LOR):	\$5	(days)		
Loss of Use (LOU):	\$5	(5 x days)		
Loss of Income (LOI):	\$5	(5 x days)		
LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐				[Tick only one]
GIA/LTA Search	\$5			
Medical:	\$5			
Disbursement:	\$5	(e.g. Tow/ Independent)		
Legal Cost:	\$5			
Total:	\$5	Global Sum \$5:		
FINAL PAYMENT	Date/Time:	Confirm with:	Email ☐ Call ☐	
Payee 1:	\$5	Name 1:		
Payee 2: (Strike if N.A.)	\$5	Name 2:		
Payee 3: (Strike if N.A.)	\$5	Name 3:		

COPY SENT
27/1/2020

- 1) Claim status: Normal/Reject/Private Settle
- 2) Report Format: WP 4/1/19
- 3) Survey fee:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop n/s _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: GK811K Yr Regn: 2004 Nov
 Type: M.Car / M.Cycle / Bus / Van / Car / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Dyna c.c. 2986
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp Reading: 296923 T/Radio: Insured / Std / NI / NA

Eng/No: _____
 C/No: JTFUF34Y703002996

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 155 R14C

R: 155 R12C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or CST Tires.

Front	Rear
R/Bal. <u>06</u> mm	R/Bal. <u>06</u> mm
L/Bal. <u>06</u> mm	L/Bal. <u>06</u> mm
D.O.A. _____	D.O.I. <u>07/10/19</u>

Survey held at S-D

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front o/s.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP III.</u>
	<u>MV : 25k</u>
	<u>PV : 12.8k</u>
	<u>Nett. 12.2k -</u>

COE Expiry : 31/08/24.

Date/Time, File Pass to? ☐ : Prel. Report

if ☐ : Final Report

Date/Time, File Return to?

3.

Report Format: _____

Group Gen / AB: _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp. (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Insp (\$ _____)

☐ : Misc. exp (\$ _____)

Survey Fee: _____

Transportation: _____

3 + RS. _____

Phone: _____

Other: _____

TOTAL

S.D CAR CARE CENTRE

Blk 2, Kaki Bukit Avenue 2, #01-29, (Kaki Bukit AutoHub), Singapore 417921

H/P: 9616 1359 (Ah Boon) / 9650 7403 (Ah Boy)

Tel: 6749 6155 / 6745 5102 / Fax: 6742 9003

TPM
Cecilia

Vehicle number: GK811K

Vehicle Made & Model: TOYOTA DYNA

Qty	List Items	Amount \$
1	Front bumper <i>Distorted</i>	521.60 ✓
1	Front corner panel - RH <i>Distorted</i>	321.60 ✓
1	Front corner moulding - RH <i>3 new</i>	199.62 ✗
1	Front corner garnish - RH	287.43 ✗
1	Front cab panel <i>3 new</i>	1,265.60 ✗
1	Front cab panel logo	89.95 ✓
1	Front cab panel emblem "DYNA" <i>new</i>	86.90 ✓
1	Front door - RH <i>Distorted</i>	1,658.60 ✓
1	Front door side mirror <i>lt</i>	281.90 ✓
1	Front door outer handle <i>new</i>	161.20 ✗
1	Front door glass outer moulding <i>new</i>	141.60 ✗
1	Front door glass run channel <i>3 new</i>	155.90 ✗
1	Front door glass guide <i>new</i>	110.65 ✗
1	Front door glass regulator <i>damaged</i>	281.60 ✓
1	Front door glass regulator motor <i>new</i>	481.90 ✗
1	Front door inner lock <i>Jammed</i>	581.65 ✓
1	Front door inner trim board <i>cracked</i>	761.90 ✓
1	Front door insulation <i>new</i>	130.20 ✗
1	Front door w/strip <i>lt</i>	141.60 ✓
1	Front door seal <i>new</i>	112.30 ✓
1	Front door checker <i>damaged</i>	89.95 ✓
2	Front door hinges @ 115 <i>Bent</i>	230.00 ✓
1	Front door pillar - RH - Outer <i>Distorted</i>	711.52 ✓
1	Front door pillar - RH - Inner <i>Repis</i>	695.50 ✗
1	Front door rear pillar <i>Repis</i>	581.90 ✗
1	Front headlamp assy <i>cracked</i>	704.35 ✓
1	Front grille <i>cracked</i>	487.31 ✓
1	Front wheel guard - RH <i>new</i>	286.90 ✗
1	Front wheel arch panel - RH <i>Buckled</i>	441.59 ✓
1	Front wheel arch panel moulding <i>lt</i>	121.30 ✓
1	Front wheel arch panel garnish <i>deformed</i>	186.90 ✓

Vehicle number: GK811K

Vehicle Made & Model: TOYOTA DYNA

1	Front windscreen rubber <i>Not New</i>	287.92	x
1	Front step garnish - RH <i>Distorted</i>	312.60	✓
1	Front shock absorber - RH <i>Bent</i>	221.30	✓
1	Front steering rack link assy <i>Not New</i>	1,126.50	x
1	Front steering box universal joint <i>Bent</i>	481.30	✓
1	Front axle beam <i>Not New</i>	2,885.90	x
1	Front knuckle arm <i>Bent</i>	861.90	✓
1	Front wheel hub bearing <i>Damaged</i>	551.60	✓
1	Brake air chamber - RH <i>Not New</i>	281.30	x
Sub-total		19,321.24	
Less 25%		4,830.31	
Total List		14,490.93	

1007337
755502

Special Nett Items

1	Front wheel rim <i>Not</i>	280.00	250
1	Front tyre <i>Not New</i>	260.00	x
1	R.O.V sticker <i>New</i>	45.00	30
Total Special Nett		585.00	

280

Labour charges

To check front electrical wiring	120.00	30
Towing charges	150.00	60
To respray undercoating	150.00	80
To remove, refix front interior trims to assist repair	120.00	80
To remove, refix front undercarriage	450.00	280
To remove, refix front windscreen	150.00	x
To remove, refix front dashboard	350.00	220
To check wheel alignment	120.00	80
To respray painting and etc	1,500.00	1000
Panel beating, cut, weld remove & replacing above parts	2,000.00	1400
Total Labour	5,110.00	

3230

Let Auto Consultation Services Ltd.
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Total: 11065.02
L/S: 8.81c 12 Day

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$ 20,185.93

Acknowledged by Repairer
Signature:
Date:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Details	
Owner ID Type:	Company
Owner ID:	964G
Vehicle Details	
Vehicle No.:	GK811K
Vehicle to be Exported:	Yes
Intended Deregistration Date:	07 Oct 2019
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 D
Primary Colour:	Silver
Manufacturing Year:	2004
Engine No.:	5L5500495
Chassis No.:	JTFUF34Y703002996
Maximum Power Output:	-
Open Market Value:	\$23,715.00
Original Registration Date:	26 Nov 2004
First Registration Date:	26 Nov 2004
Transfer Count:	2
Actual ARF Paid:	\$1,186.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Aug 2024
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$13,055.00
COE Rebate Amount:	\$12,788.00
Total Rebate Amount:	\$12,788.00

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 07 Oct 2019

OK



We're revving up our celebrations for our first-year milestone





Post an Advertisement
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

 Post an Ad
  Advertiser Login
  Ways of Selling

New 5 Years Renewal Coe Toyota Wish 1.8A



2.88% P.A. \$0 Admin, \$0 Down, Monthly From \$688, 2 Years Warranty Engine
 (CV Drive Pte Ltd StarAd)





**VALUE FOR MONEY
VALUE FOR TIME
A PEACE OF MIND**

HOTLINE: 6741 9997

[View Our Cars](#)

Browse by Category   Save Search  Print

Back (1 2 3) Next =

Sort by Date Posted  20 results/page 

55 vehicles

Search  Advanced Search  Search  View All

Search Selection: dyna Any Any > 10 year(s) old Any Any Any Available



☐ **Toyota Dyna 150 3.0M (COE till 05/2024)**

Fuel Type: Diesel

Don't Miss! Class 3 Box Lorry! New 5 Years COE! Cheapest In The Market! No Need To Repair! New 6 Months Road Tax! Box Height (6 1/2 Feet), Excellent Condition With 2 Sliding Door, Price Still Can Negotiable, Call Before Viewing.

 Posted: 11-Sep-2019  Tag: 2002 Toyota Dyna, 2007 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota



☐ **Toyota Dyna 150 3.0M (COE till 06/2023)**

Fuel Type: Diesel

Last 3 Days For This Amazing Deal Till This Fri. Here Is The Best Budget Ever Had For Newly Start-Up Company Or Short Term Usage. Selling At Dealer Price! Comes With Full Length Cabin Height Canopy. Monthly As Low As \$488. Wait No More Now And Contact Us Fast!

Bell Auto Pte Ltd

 Posted: 02-Oct-2019  Tag: 2005 Toyota Dyna, 2004 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota



☐ **Toyota Dyna 150 3.0M (New 5-yr COE)**

Fuel Type: Diesel

6.5 Feet Box With Power Tailgate. New Paintwork. Excellent Condition. Doorstep Viewing Can Be Arranged For Test Drive. Hurry Call Now!

Net Link Partners Pte Ltd

 Posted: 09-Oct-2019  Tag: 2005 Toyota Dyna, 2005 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota



☐ **Toyota Dyna 150 3.0M (COE till 12/2021)**

Fuel Type: Diesel

\$10,880 COE Rebate After Usage! Free 6 Months Road Tax And Inspection!, Value For Money, High Trade In And High Loan Possible! Call Now For An No Obligations Discussion! Door Step Viewing Possible!

Net Link Partners Pte Ltd

 Posted: 28-Sep-2019  Tag: 2006 Toyota Dyna, 2006 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota

GET YOUR COE RENEWAL LOAN

Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.



☐ **Toyota Dyna 100 3.0M (COE till 04/2022)**

Fuel Type: Diesel

Best Assurance! 1 Year Warranty! Lowest Pricing In Market! Flexible Bank/In House Up To 100% Loan \$14,998 Mthly Instalment \$557. New Paintwork And Leather Seats, Smooth Engine And Gear Box. Regular Maintained. Just Change Gearbox No Repairs Needed! Selling...

CarQuotz Singapore

 Posted: 01-Oct-2019  Tag: 2007 Toyota Dyna, 2007 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota



☐ **Toyota Dyna 150 3.0M (COE till 05/2022)**

Fuel Type: Diesel

Frozen Fridge Truck. Save At Least 6k Purchasing The Fridge, engine Tip Top Condition, Able To Access Into Multi-storey Carpark, In House Loan Available. Don't Hesitate Call Now To View And Test Drive

 Compare

Summer Lee (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Monday, 7 October, 2019 3:41 PM
To: ct-admin@visionlawllc.com; 'jactan@visionlawllc.com'; 'sur@lkkauto.com'; Admin-D (LKKAuto)
Cc: Sundari Nagarajan - III
Subject: RE: PRE-REPAIR INSPECTION FOR VEHICLE NO. GK811K (Accident involving GK811K and SHA2253Z on 05.10.2019)
Attachments: 0240_001.pdf

Dear Sir / Mdm,

Please conduct a survey on TP vehicle GK811K and let us have your report urgently.

This claim will be handled by Ms Sundari.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street, #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

P: Ah Boy
T: 4.04 p.m.
V: lu
E: ✓

From: Motor Claim - III
Sent: 07 October, 2019 1:40 PM
To: 'ct-admin@visionlawllc.com' <ct-admin@visionlawllc.com>; 'jactan@visionlawllc.com' <jactan@visionlawllc.com>
Subject: PRE-REPAIR INSPECTION FOR VEHICLE NO. GK811K (Accident involving GK811K and SHA2253Z on 05.10.2019)

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext – 248

From: ct-admin@visionlawllc.com [<mailto:ct-admin@visionlawllc.com>]
Sent: 07 October, 2019 12:05 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: Scan Image

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.
It may contain confidential and/or legally privileged information.
If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.
Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.
Print this email only if it is absolutely necessary and help in preservation of environment.
India International Insurance Pte Ltd.
Registration No. 198703792-K

VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths
Agents for Trade Marks
(Incorporated with limited liability)

ERIC NG CHING BOON
WONG KENG LEONG RAYHEE
AUDREY WONG SU-JEEN
PAUL YAP TAI SAN
ANJALLI D'O MUNIANDY
ANG KIM NOI DEANE
RAVENDRA KRISHNASAMY
TAN YINGXUAN, SELWYN
CHEONG YUNSHU, CLARISSA
SONIA LIM WEI LEE

Unique Entity Number :200721148H
✓ **HEAD OFFICE:** 133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413

Branch: 490 Toa Payoh Lorong 6
#03-11 HDB Hub
Singapore 310490

✓ HEAD OFFICE

TEL : (65) 65342811 (Hunting)
FAX ✓ : (65) 65358802 (General)
: (65) 65355905 (Litigation)
E-mail : jactan@visionlawllc.com

BRANCH

TEL : 65 63580703
FAX : 65 63580448 (Conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE- KINDLY REPLY TO HEAD OFFICE FOR THIS MATTER

Our Ref: AM.Jt.Ins.S119.41765.19 (sj)
Your Ref: SHA 2253 Z

07 October 2019

INDIA INTERNATIONAL INSURANCE PTE LTD
64 Cecil Street
#04/#05 IOB Building
Singapore 049711
Attention: Motor Claims Department

BY FAX: 6224 4174

motorclaim@iii.com.sg

Dear Sirs,

ACCIDENT INVOLVING GK 811 K & SHA 2253 Z ON 05 OCTOBER 2019 ALONG JUNCTION OF UPPER CHANGI ROAD EAST & EXPO DRIVE AT ABOUT 1130 HOURS (NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES)

We refer to your email 07 October 2019 of even date informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment of LKK Auto Consultant Pte Ltd as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

Venue: S.D. Car Care Centre
Blk 2 Kaki Bukit Avenue 2
#01-29
Singapore 417921
Contact Person: Ah Boy 6749-6155/6745-5102

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully

ANJALLI M
(HEAD OFFICE)

FOR SURVEYOR

Please initial here after completion of pre-repair inspection.
Thank you.

1st Survey on _____
Appointed surveyor
(Name & Signature)

2nd Survey on _____
Appointed surveyor
(Name & Signature)

3rd Survey on _____
Appointed Surveyor
(Name & signature)

cc: GK 811 K – by fax only : 6742-9003 only

NB.: Any settlement of offer is on the express condition that this settlement is in respect of our client's claim for property-related damages only and shall not preclude our client from claiming injury-related damages arising from this accident.

CONFIDENTIALITY
THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

...CLAIM SUBFOLDER...(Pending for Survey Report)

WP

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Oct 2019 Edit Reg		07 Oct 2019 00:00 Edit Adj Rpt	S\$8,800.00 Edit Estimates	S\$8,800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R								
Main Claimant:	CHILLI API CATERING PTE LTD, Co. Reg. No.: 200208964G								
Vehicle Reg. No.:	GK811K	Date of Loss:	05/10/2019 11:00 - :59 [178 Months and 9 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT19100108	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHA2253Z	Policy No. (Claimant):	5086459533-02						
		Excess:							
Repairer:	S.d. Car Care Centre (HQ) BLK 2 KAKI BUKIT AVENUE 2 #01-29, 417921 Kaki Bukit - Tel:								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sundari Nagarajan - 6347 6071]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 17/10/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- III_SG (21/01/2020): Alert - Adj Mandate Maintained - GK811K - Claim Handler: Sundari Nagarajan - III_SG (11/11/2019): Alert - Adj Mandate Maintained - GK811K - Claim Handler: Sundari Nagarajan									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GK811K (MCT19100108)
[SHA2253Z]
TP
CHILLI API CATERING PTE LTD
Oct 5 2019 11:00AM
[COMFORT TRANSPORTATION PTE LTD]
S.d. Car Care Centre

Upload Documents			Upload Photos		Compose New Letter		View View in Browser	
Video							1 per page	☒
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print			
1	11/11/19 14:03	Video - Accident-IV			Load MP4			
Photos/Images							3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print			
1	08/11/19 09:43	General View			Load JPG		☒	
2	08/11/19 09:43	General View			Load JPG		☒	
3	08/11/19 09:43	General View			Load JPG		☒	
4	08/11/19 09:43	General View			Load JPG		☒	
5	08/11/19 09:43	General View			Load JPG		☒	
6	08/11/19 09:43	General View			Load JPG		☒	
7	08/11/19 09:43	General View			Load JPG		☒	
8	08/11/19 09:43	General View			Load JPG		☒	
9	08/11/19 09:43	General View			Load JPG		☒	
10	08/11/19 09:43	General View			Load JPG		☒	
11	08/11/19 09:43	General View			Load JPG		☒	
12	08/11/19 09:43	General View			Load JPG		☒	
13	08/11/19 09:43	General View			Load JPG		☒	
14	08/11/19 09:43	General View			Load JPG		☒	
15	08/11/19 09:43	General View			Load JPG		☒	
16	08/11/19 09:43	General View			Load JPG		☒	
17	08/11/19 09:43	General View			Load JPG		☒	
18	08/11/19 09:43	General View			Load JPG		☒	
19	08/11/19 09:43	General View			Load JPG		☒	
20	08/11/19 09:43	General View			Load JPG		☒	
21	08/11/19 09:43	General View			Load JPG		☒	
22	08/11/19 09:43	General View			Load JPG		☒	
23	08/11/19 09:43	General View			Load JPG		☒	
24	08/11/19 09:43	General View			Load JPG		☒	
25	08/11/19 09:43	General View			Load JPG		☒	
26	08/11/19 09:43	General View			Load JPG		☒	
27	08/11/19 09:43	General View			Load JPG		☒	
28	08/11/19 09:43	General View			Load JPG		☒	
29	08/11/19 09:43	General View			Load JPG		☒	
30	08/11/19 09:43	General View			Load JPG		☒	
31	08/11/19 09:43	General View			Load JPG		☒	
32	08/11/19 09:43	General View			Load JPG		☒	
33	08/11/19 09:43	General View			Load JPG		☒	
34	08/11/19 09:43	General View			Load JPG		☒	
35	08/11/19 09:43	General View			Load JPG		☒	
36	08/11/19 09:43	General View			Load JPG		☒	
37	08/11/19 09:43	General View			Load JPG		☒	
38	08/11/19 09:43	General View			Load JPG		☒	
39	08/11/19 09:43	General View			Load JPG		☒	
40	08/11/19 09:43	Reinspection Photo			Load JPG		☒	

Video			1 per page	☒
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
				☒
41	08/11/19 09:43	Reinspection Photo	 Load JPG	☒
42	08/11/19 09:43	Reinspection Photo	 Load JPG	☒
43	08/11/19 09:43	Reinspection Photo	 Load JPG	☒
44	08/11/19 09:43	Reinspection Photo	 Load JPG	☒
45	08/11/19 09:43	Reinspection Photo	 Load JPG	☒
46	08/11/19 09:43	Reinspection Photo	 Load JPG	☒
47	08/11/19 09:43	Reinspection Photo	 Load JPG	☒
48	08/11/19 09:43	Reinspection Photo	 Load JPG	☒
49	08/11/19 09:43	Reinspection Photo	 Load JPG	☒
50	08/11/19 09:43	Reinspection Photo	 Load JPG	☒
51	08/11/19 09:43	Reinspection Photo	 Load JPG	☒
52	08/11/19 09:43	Reinspection Photo	 Load JPG	☒
53	08/11/19 09:43	Reinspection Photo	 Load JPG	☒
54	08/11/19 09:43	Reinspection Photo	 Load JPG	☒
55	08/11/19 09:43	Reinspection Photo	 Load JPG	☒
56	08/11/19 09:43	Reinspection Photo	 Load JPG	☒
57	08/11/19 09:43	Reinspection Photo	 Load JPG	☒
58	08/11/19 09:43	Reinspection Photo	 Load JPG	☒
59	08/11/19 09:43	Reinspection Photo	 Load JPG	☒
60	08/11/19 09:43	Reinspection Photo	 Load JPG	☒
61	08/11/19 09:43	Reinspection Photo	 Load JPG	☒
62	08/11/19 09:43	Reinspection Photo	 Load JPG	☒
63	08/11/19 09:43	Reinspection Photo	 Load JPG	☒
64	08/11/19 09:43	Reinspection Photo	 Load JPG	☒
65	08/11/19 09:43	Reinspection Photo	 Load JPG	☒
66	08/11/19 09:43	Reinspection Photo	 Load JPG	☒
67	08/11/19 09:43	Reinspection Photo	 Load JPG	☒
68	08/11/19 09:43	Reinspection Photo	 Load JPG	☒
69	08/11/19 09:43	Reinspection Photo	 Load JPG	☒
70	08/11/19 09:43	Reinspection Photo	 Load JPG	☒
71	08/11/19 09:43	Reinspection Photo	 Load JPG	☒
72	08/11/19 09:43	Reinspection Photo	 Load JPG	☒
73	08/11/19 09:43	Reinspection Photo	 Load JPG	☒
74	08/11/19 09:43	Reinspection Photo	 Load JPG	☒
75	08/11/19 09:43	Reinspection Photo	 Load JPG	☒
76	08/11/19 09:43	Reinspection Photo	 Load JPG	☒
77	02/12/19 10:00	Reinspection Photo	 Load JPG	☒
78	02/12/19 10:00	Reinspection Photo	 Load JPG	☒
79	02/12/19 10:00	Reinspection Photo	 Load JPG	☒
80	02/12/19 10:00	Reinspection Photo	 Load JPG	☒
81	02/12/19 10:00	Reinspection Photo	 Load JPG	☒
82	02/12/19 10:00	Reinspection Photo	 Load JPG	☒
83	02/12/19 10:00	Reinspection Photo	 Load JPG	☒
84	02/12/19 10:00	Reinspection Photo	 Load JPG	☒
85	02/12/19 10:00	Reinspection Photo	 Load JPG	☒
86	02/12/19 10:00	Reinspection Photo	 Load JPG	☒
87	02/12/19 10:00	Reinspection Photo	 Load JPG	☒
88	02/12/19 10:00	Reinspection Photo	 Load JPG	☒
89	02/12/19 10:00	Reinspection Photo	 Load JPG	☒
90	02/12/19 10:00	Reinspection Photo	 Load JPG	☒
91	02/12/19 10:00	Reinspection Photo	 Load JPG	☒
92	02/12/19 10:00	Reinspection Photo	 Load JPG	☒
93	02/12/19 10:00	Reinspection Photo	 Load JPG	☒
94	02/12/19 10:00	Reinspection Photo	 Load JPG	☒
95	02/12/19 10:00	Reinspection Photo	 Load JPG	☒

Video				1 per page	☒
No	Finalized On		India International Insurance Pte Ltd (HQ)	Thumbnail	Print
Documentation				1 per page	☒
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/10/19 15:18	EMAIL FROM III DO 07102019			Load PDF
2	08/10/19 15:18	NOTICE			Load PDF
3	08/10/19 17:05	TP GIA REPORT			Load PDF
No	Finalized On		India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	09/10/19 08:59	Singapore Accident Statement			Load PDF
2	20/01/20 19:05	Letter of Demand from Third Party TPD LOD FROM VISION LAW LLC (GR811K)			Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19017717/AGS3Q2

Date: 23/01/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
 Claimant: GK811K Insured Vehicle No: SHA2253Z
 Vehicle No: GK811K Date of Loss: 05/10/2019 Nature of Claim: TP Claim No: MCT19100108

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GK811K
 Make & Model: TOYOTA DYNA 1.5T, 3.0 (A) Engine No: 5L5500495
 Reg. Date: 26/11/2004 (Man. Year: 2004) Chassis No: JTFUF34Y703002996
 Colour: Silver Odometer: 296923 km
 Engine Capacity: 2986 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R14C Rear Tyre Size: 155 R12C
 Front Left Side: CST TIRE 6 mm Rear Left Side: CST TIRE 6 mm
 Front Right Side: CST TIRE 6 mm Rear Right Side: CST TIRE 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,075.93	7,828.28	7,247.65	48.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,110.00	3,230.00	1,880.00	36.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,185.93	11,058.28	9,127.65	45.22
Approved Total (Overridden) (S\$)		8,800.00		
Nett Amount (S\$)	20,185.93	8,800.00	11,385.93	56.41
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 07/10/2019
 Date Inspected: 07/10/2019 Inspected At: S.d. Car Care Centre (HQ)
 BLK 2 KAKI BUKIT AVENUE 2 #01-29
 Singapore 417921
 Estimated Period of Repair: 12.0 days

Adjuster: ADRIAN LING

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 22 Jan 2020)	
Parts:	N/A	TOYOTA DYNA 1.5T 3.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GK811K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	521.60 FL	*521.60 FL
2	1		*FRONT CORNER PANEL -RH	Distorted	321.60 FL	*321.60 FL
3	1		*FRONT CORNER MOULDING -RH	Not Necessary	199.62 FL	*- FL
4	1		*FRONT CORNER GARNISH -RH	Not Necessary	287.43 FL	*- FL
5	1		*FRONT CAB PANEL	Not Necessary	1,265.60 FL	*- FL
6	1		*FRONT CAB PANEL LOGO	Not Necessary	89.95 FL	*- FL
7	1		*FRONT CAB PANEL EMBLEM DYNA	Not Necessary	86.90 FL	*- FL
8	1		*FRONT DOOR -RH	Distorted	1,658.60 FL	*1,658.60 FL
9	1		*FRONT DOR SIDE MIRROR	Cut	281.90 FL	*281.90 FL
10	1		*FRONT DOOR OUTER HANDLE	Not Necessary	161.20 FL	*- FL
11	1		*FRONT DOOR GLASS OUTER MOULDING	Not Necessary	141.60 FL	*- FL
12	1		*FRONT DOOR GLASS RUN CHANNEL	Not Necessary	155.90 FL	*- FL
13	1		*FRONT DOOR GLASS GUIDE	Not Necessary	110.65 FL	*- FL
14	1		*FRONT DOOR GLASS REGULATOR	Damaged	281.60 FL	*281.60 FL
15	1		*FRONT DOOR GLASS REGULATOR MOTOR	Not Necessary	481.90 FL	*- FL
16	1		*FRONT DOOR INNER LOCK	Jammed	581.65 FL	*581.65 FL
17	1		*FRONT DOOR INNER TRIM BOARD	Cracked	761.90 FL	*761.90 FL
18	1		*FRONT DOOR INSULATION	Not Necessary	130.20 FL	*- FL
19	1		*FRONT DOOR W/STRIP	Cut	141.60 FL	*141.60 FL
20	1		*FRONT DOOR SEAL	Necessary	112.30 FL	*112.30 FL
21	1		*FRONT DOOR CHECKER	Damaged	89.95 FL	*89.95 FL
22	2		*FRONT DOOR HINGES	Bent	230.00 FL	*230.00 FL
23	1		*FRONT DOOR PILLAR -RH -OUTER	Distorted	711.52 FL	*711.52 FL
24	1		*FRONT DOOR PILLAR -RH -INNER	Repair	695.50 FL	*- FL
25	1		*FRONT DOOR REAR PILLAR	Repair	581.90 FL	*- FL
26	1		*FRONT HEADLAMP ASSY	Cracked	704.35 FL	*704.35 FL
27	1		*FRONT GRILLE	Cracked	487.31 FL	*487.31 FL
28	1		*FRONT WHEEL GUARD -RH	Not Necessary	286.90 FL	*- FL
29	1		*FRONT WHEEL ARCH PANEL -RH	Buckled	441.59 FL	*441.59 FL
30	1		*FRONT WHEEL ARCH PANEL MOULDING	Cut	121.30 FL	*121.30 FL
31	1		*FRONT WHEEL ARCH PANEL GARNISH	Deformed	186.90 FL	*186.90 FL
32	1		*FRONT WINDSCREEN RUBBER	Not Necessary	287.92 FL	*- FL
33	1		*FRONT STEP GARNISH -RH	Distorted	312.60 FL	*312.60 FL
34	1		*FRONT SHOCK ABSORBER -RH	Bent	221.30 FL	*221.30 FL
35	1		*FRONT STEERING RABK LINK ASSY	Not Necessary	1,126.50 FL	*- FL
36	1		*FRONT STEERING BOX UNIVERSAL JOINT	Bent	481.30 FL	*481.30 FL
37	1		*FRONT AXLE BEAM	Not Necessary	2,885.90 FL	*- FL
38	1		*FRONT KNUCKLE ARM	Bent	861.90 FL	*861.90 FL
39	1		*FRONT WHEEL HUB BEARING	Damaged	551.60 FL	*551.60 FL
40	1		*BRAKE AIR CHAMBER -RH	Not Necessary	281.30 FL	*- FL
41	1		*FRONT WHEEL RIM	Cut	280.00 FS	*250.00 FS
42	1		*FRONT TYRE	Not Necessary	260.00 FS	*- FS
43	1		*R.O.V STICKER	Necessary	45.00 FS	*30.00 FS

F=Franchise part. S=SpccNett. L=ListItemDisc

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Sub Total (S\$)	19,906.24	10,344.37
				- List Item Discount on L Items 25.00/25.00% (S\$)	4,830.31	2,516.09
				Total Parts (S\$)	15,075.93	7,828.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK FRONT ELECTRICAL WIRING	New	120.00	30.00
2	TOWING CHARGES	New	150.00	60.00
3	TO RESPRAY UNDERCOATING	New	150.00	80.00
4	TO REMOVE,REFIX FRONT INTERIOR TRIMS TO ASSIST REPAIR	New	120.00	80.00
5	TO REMOVE,REFIX FRONT UNDERCARRIAGE	New	450.00	280.00
6	TO REMOVE,REFIX FRONT WINDSCREEN	New	150.00	0.00
7	TO REMOVE,REFIX FRONT DASHBOARD	New	350.00	220.00
8	TO CHECK WHEEL ALIGNMENT	New	120.00	80.00
9	TO RESPRAY PAINTING AND ETC	New	1,500.00	1,000.00
10	PANEL BEATING ,CUT,WELD REMOVE & REPLACING ABOVE PARTS	New	2,000.00	1,400.00
Gross Labour Cost (\$\$)			5,110.00	3,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >