

ASS. REC. BY:

REF:

es/INC19017730/Kqd3n2

Special Instructions:

Surveyor: KennedyASSIGNMENT (Office)From (Person): Theresa Vimala of INCDate/Time: 8/10/19 @ 10:04am.

Estimated Cost: _____ Bill to: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SMK 2182HInsured: YP 82202at Workshop in/s Complete VMSTel: 6455 0012of 176 An Ming Drive #03-14

Policy No: _____

Claim No: M1/1065698-001

Sum Insured: _____

Excess: _____

Make of Veh:

(* Licen's Record)

D.O.A. 6/10/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 10:17am @ 8/10/19Person Contacted: Ji HuiVehicle IN / OUT

Date/Time

Action/Instruction

Johnny / ✓

SMK 2182H-Xyp 82202-X17/10 11Pm @ 335d. 365d email & confirm (Red @ 3880.56, 54%)

ASS. REC. BY:

REF: 1NCL

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: 3/24 Person Contacted: _____ Vehicle: IN / OUT

Veh No: SMK 21824 Yr Regn: 06, 09

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Aventure cc 1591

Colour: M. Maroon AC: Insured / Std / NI / NA

Sp. Reading: 152333 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KM110U41BR96774378

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / Rlm or

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: 3 mm Rear: 7 mm

R/Bal: 3 mm L/Bal: 7 mm

D.O.A. 6/10/19 D.O.I. 8/10/19

Survey held at 11:30

Des. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 File pass to

RECEIVED 25 OCT 2019

Date/Time, File Pass to?

☐ : Prell. Report☐ : Final Report

1) 24/10 11:30

Date/Time, File Return to?

Days Of Repair: 4

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S - RS - SI

Furnish

Others

TOTAL

250

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Report Format :

Lump Sum / L.B.I. (\$)

TP

3350

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Theresa Vimala D/O Balagangadharan [mailto:thrsvim.bala@income.com.sg]

Sent: Tuesday, 8 October 2019 10:04 AM

To: assignments <assignments@lkkauto.com>; Catherine Chong (LKK Auto) <admin-d@lkkauto.com>

Cc: Teng Ken Leong <kenleong.teng@income.com.sg>; Thio Tse Kiat <tsekiat.thio@income.com.sg>; Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>

Subject: RE: TP CASES FARMED OUT TO LKK ON 08/10/2019

Dear LKK,

Please assist to survey the following vehicles as per Tse Kiat's instruction :-

SN	OIC	Claim No.	Survey Date	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	CHRYSLLIS	MT/1065646-002	8/10/2019	SMH465X	CAR TIMES AUTOLUTION PTE LTD	160 SIN MING DRIVE #02-04 AUTOCITY	Yuki Peck / 64715111		5JQ9148R	1/10	
2	CYNDIE YONG	MT/1065698-001	8/10/2019	SMK2182H	COMPLETE VMS PTE LTD	176 SIN MING DRIVE #03-14 SIN MING AUTOCARE SINGAPORE 575721	Chiu S. L. / 6455 0012		YP8220Z	6/10	
3	JEFF LIN	MT/1065519-002	8/10/2019	SLL8018S	EM-1 AUTO PTE. LTD.	BLK 8 #01-68 SIN MING INDUSTRIAL EST SECTOR C SINGAPORE 575643	Chia Sin Muk / 9666 6556		SIV7242M	5/10	

4	JARED	MT/1065564-002	8/10/2019	SCQ95B	LEONG AUTO PTE LTD	160 SIN MING DRIVE #02-13 SIN MING AUTOCITY	Daniel Tan/Cady Lee / 9692 4113	SGV8018Z	5/10	
5	HELENA TAN	MT/1065715-001	8/10/2019	SIZ1046G	TEAM AUTOPRO PTE LTD	BLK 160 SIN MING DRIVE #01-14 SINGAPORE 575722	Eric Lee / 8269 9999	SGV9761D	5/10	

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

With Regards

Theresa Vimala
Senior Administrator
Motor Insurance
T +65 6430 7898
www.income.com.sg

income
made different



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers

in with you

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/10/2019 15:09
Date Of Accident	06/10/2019 12:20
Exact Location Of Accident	WOODLANDS ST 31 OUTSIDE FUCHUN COMMUNITY CENTRE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMK2182H
Insured/Policyholder	
Name Of Registered Owner	AUTOGRAND PTE LTD
Co Reg No	201621171M
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-84436190

Vehicle Particulars

Manufacturer	HYUNDAI
Model	AVANTE
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5109472572
Cover Note Number	

Driver

Name of Driver	MARTADZA BIN MOHAMED
NRIC No	S1786170J
Date Of Birth	04/02/1967
Occupation	OUTDOOR
Date Of Driving Pass	31/08/1998
Driving Experience	21 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-84436190
Fax Number	
Contact Number	
Email Address	TAZZMOHD@YAHOO.COM.SG

Address	BLK 316D PUNGGOL WAY #11-685
Postcode	824316
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : NA GENDER: : MALE
Passenger 2	NAME: : NA GENDER: : MALE
Passenger 3	NAME: : NA GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED (VEHICLE B REVERSED AND HIT ONTO VEHICLE A)

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YP8220Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	ISKANDER BIN JUMAAT
NRIC/Passport Number	S1775651F

Contact Number

90691445

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I have just drove my veh A and parked behind veh B (1 metre away) to alight my passengers. As they are alighting, veh B suddenly start reversing. As upon seeing the situation, I immediately honked at him but he still continued and collided into the front of my stationary vehicle A.

He admitted his fault and we exchange particulars. I am filing this report for insurance claim purposes.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/YIN No.:



Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

AUTOGRAND PTE LTD
21 TOH GUAN ROAD EAST, #07-02
TOH GUAN CENTRE SINGAPORE 608609

Attention : THE OWNER
Contact : 91457171

Estimate : ES006809

Date : 07/10/2019
Vehicle Num. : SMK2182H
Make/Model : HYUNDAI HD AVANTE 1.6A-2009
Chassis/Eng# : KMHU41BR9U774378/G4FC9U6635
Accident Date : 06/10/2019
Claim No. :
Reference :
Policy No. :

Not Noted
11 Sep 87
Repair After Rain
4 days

S/N Quantity Particular Unit Price Amount S\$

1.	1	LIST ITEMS :		
2.	1	FRONT BONNET		1,855.40 ✓
3.	1	BONNET LOCK		64.80 ✓
4.	1	RADIATOR GRILLE		386.00 ✓
5.	1	GRILLE LOGO		48.00 ✓
6.	1	FRONT SUPPORT PANEL		891.30 ?
7.	2	HEADLAMP	480.00	960.00
8.	1	FRONT BUMPER		511.40 X?
9.	1	FRONT BUMPER REINFORCEMENT		282.80 ✓
10.	1	FRONT BUMPER SPONGE		126.60 ✓
11.	1	AIR CON CONDENSER		990.90 ?
		BONNET RUBBER SEAL		121.00 ✓

List TotalS\$: 6,238.20
20.00% Discount S\$: 1,247.64
4,990.56

LABOUR :
REMOVE & REINSTALL AIRCON CONDENSER & REFILL GAS 180.00 ?
RUST PROOFING TREATMENT 100.00 301
CHANGE HEAD LAMP AND CHECK LIGHTING 80.00 201
SPRAY PAINT DAMAGED AREA AFFECTED 400 980.00
TO CUT OFF FRONT SUPPORT PANEL, KNOCK AND STRAIGHTEN
FRONT CHASSIS FRAME AND CHANGE ALL NECESSARY PARTS 900.00 ?
Labour Total S\$: 2,240.00

SingDollars : Seven Thousand Two Hundred Thirty & Cents Fifty-Six Only

Total S\$: 7,230.56
=====

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun

LRC Auto Centre hereby notice
the Repaired of the following:
• To restore vehicle to factory painting
• Parts prices are in factory price
• Third party repair (not a "Without Prejudice" item)
• No third party claim is allowed
• Repaired work must be completed and
in accordance with the relevant law and standards Company

Acknowledged by Repaired
Signature:
Date:



kg

COMPLETE VMS PTE LTD The Premier One-Stop Vehicle Accident Claims Centre
176 Sin Ming Drive, #03-14, Sin Ming Autocare Complex, Singapore 575127
(Tel) 6455 0012 (Fax) 6554 0012 (Web) www.completevms.com.sg

Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

AUTOGRAND PTE LTD
21 TOH GUAN ROAD EAST, #07-02
TOH GUAN CENTRE SINGAPORE 608609

Estimate : ES006809

Attention : THE OWNER
Contact : 91457171

Date : 07/10/2019
Vehicle Num. : SMK2182H
Make/Model : HYUNDAI HD AVANTE 1.6A-2009
Chassis/Eng# : KMHU41BR9U774378/G4FC9U6635
Accident Date : 06/10/2019
Claim No. :
Reference :
Policy No. :

Not Notarised
3350
C/Sy @ 3650h
Penny After Rain

S/N Quantity Particular Unit Price Amount S\$

1.	1	LIST ITEMS :			
2.	1	FRONT BONNET	1108.	B	1,855.40 ✓
3.	1	BONNET LOCK		nit	64.80 —
4.	1	RADIATOR GRILLE		cm	386.00 —
5.	1	GRILLE LOGO		ru	48.00 —
6.	1	FRONT SUPPORT PANEL	791.30	Bu	891.30 2 ✓
7.	2	HEADLAMP		480.00	960.00 ✓
8.	1	FRONT BUMPER		11	511.40 X 2
9.	1	FRONT BUMPER REINFORCEMENT		1	282.80 ✓
10.	1	FRONT BUMPER SPONGE	876.00	5	126.60 1
11.	1	AIR CON CONDENSER		Pu	990.90 2 ✓
		BONNET RUBBER SEAL		Drill	121.00 ✓

List Total S\$:
20.00% Discount S\$:

6,238.20
1,247.64
4,990.56

LABOUR :
REMOVE & REINSTALL AIRCON CONDENSER & REFILL GAS
RUST PROOFING TREATMENT
CHANGE HEAD LAMP AND CHECK LIGHTING
SPRAY PAINT DAMAGED AREA AFFECTED
TO CUT OFF FRONT SUPPORT PANEL, KNOCK AND STRAIGHTEN
FRONT CHASSIS FRAME AND CHANGE ALL NECESSARY PARTS

100l 180.00 ?
100.00 30l
80.00 20l
400l 980.00
540l 900.00 ?

Labour Total S\$:

2,240.00

SingDollars : Seven Thousand Two Hundred Thirty & Cents Fifty-Six Only

Total S\$: 7,230.56

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT				
NTUC INCOME INSURANCE CO-OPERATIVE LTD		Ref: CS/INC19017730/Kqd3n2		
73 BRAS BASAH ROAD		Date: 25-10-2019		
#05-01 NTUC TRADE UNION HOUSESINGAPORE				
189556				
ATTN: CYNDIE YONG		Code: INC		
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh. YP 8220Z	Veh. Inspected	SMK 2182H	
	Policy No.	Coverage (\$)	0.00	
	Claim No. MT/1065698-001	Excess (\$)	0.00	
	Assign From THERESA VIMALA	Assign Date	08/10/2019	
2. Vehicle Particulars & Condition				
	Make & Model HYUNDAI AVANTE (A)	c.c	1591	
	Engine No. HIDDEN	Year of Reg.	2009	
	Chassis No. KMH DU41BR9U774378	Colour	METALLIC MAROON	
	Odometer 152333 KM	Steering	IN ORDER	
	Brakes IN ORDER	Modification	STANDARD ALLOY RIM	
	General GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
	R/H Front Tyre 195/65 R15	MICHELIN	3 mm	
	L/H Front Tyre 195/65 R15	MICHELIN	3 mm	
	R/H Rear Tyre 195/65 R15	MICHELIN	7 mm	
	L/H Rear Tyre 195/65 R15	MICHELIN	7 mm	
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date 06/10/2019	Inspect Date / Time	08/10/2019 (11:30 AM)	
	Survey held at COMPLETE VMS PTE LTD BLK 176 SIN MING DRIVE #03-14 SIN MING AUTOCARE COMPLEX SINGAPORE 575721			
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days			



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMK 2182H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BONNET	BENT	1,855.40	1,108.00
1	BONNET LOCK	DISTORTED	64.80	64.80
1	RADIATOR GRILLE	CRACKED	386.00	386.00
1	GRILLE LOGO	NECESSARY	48.00	48.00
1	FRONT SUPPORT PANEL	BUCKLED	891.30	791.30
2	HEADLAMP @\$480.00	O/S MTG CRACKED / N/S SERVICEABLE	960.00	480.00
1	FRONT BUMPER	TO REPAIR SEE LABOUR	511.40	-
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	282.80	-
1	FRONT BUMPER SPONGE	SERVICEABLE	126.60	-
1	AIR CON CONDENSER	PUNCTURE	990.90	876.00
1	BONNET RUBBER SEAL	DISTORTED / CUT	121.00	121.00
	LESS 20% DISCOUNT		-1,247.64	-775.02
			4,990.56	3,100.08
LABOUR				
	REMOVE & REINSTALL AIRCON CONDENSER & REFILL GAS.		180.00	100.00
	RUST PROOFING TREATMENT.		100.00	30.00
	CHANGE HEAD LAMP AND CHECK LIGHTING.		80.00	20.00
	SPRAY PAINT DAMAGED AREA AFFECTED.		980.00	400.00
	TO CUT OFF FRONT SUPPORT PANEL,KNOCK AND STRAIGHTEN FRONT CHASSIS FRAME AND CHANGE ALL NECESSARY PARTS,INCLUSIVE OF THE REPAIR OF FRONT BUMPER AND FRONT BUMPER REINFORCEMENT.		900.00	540.00
			2,240.00	1,090.00
GRAND TOTAL			7,230.56	4,190.08
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				3,350.00

Report Ref No. CS/INC19017730/Kqd3n2



Report Ref No. CS/INC19017730/Kqd3n2

KONG SENG CHEONG

Licensed Appraiser

A handwritten signature in black ink, appearing to be 'K.K. LAU'.

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.