

22/03/2001

ASS. REC. BY:

REF:

08/INC/19017739/Bgd302

Special Instruction:

Surveyor:

Mthm

ASSIGNMENT (Office)

From (Person):

Theresa Timule

of

INC

Date/Time:

10:04am @ 5/10/19

Estimated Cost:

Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJZ 1046G

Insured:

SGV 9761D

at Workshop m/s

Team Autopro

Tel:

62581955

of

160 Sin Ming Drive # 01-14

Policy No:

Claim No:

MT/1065715-001

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

5/10/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:43am @ 5/10/19

Person Contacted:

peach

Vehicle IN / OUT

Date/Time	Action/Instruction	Initials
	SJZ1046G-NBA/AIG/19017624/Y	DIA: 5/10/2019
	SGV 9761D-NBA/AIG/19017624/Y	DOA: 5/10/2019

REF: INC

A/S. REC. BY:

ASSIGNMENT

From:

Date:

8/10/19

Estimated Cost:

OE / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SJZ 1046G

at Workshop m/s

Team Autopro

of

160 Sin Ming Drive # 01-14

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{up}

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SJZ 1046G

Yr Regn:

27/10/2009

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Kia Picanto

c.c 1086

Colour:

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading:

77574

T/Radio:

Insured / Std / NI / NA

Eng/No:

GAHGAP014989

C/No:

KNABK513LAT082173

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / 8/Rim / STD A/Rim or

Tyre Size:

F: 165/50/15

R: 165/50/15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Kumho

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

5/10/19

D.O.I.

8/10/19

0216pm

Survey held at

Team Autopro

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Range - 3000/2 - 4000/2

RECEIVED 25 OCT 2019

NV 2077/2

10/10/19

with 5 repair days Team Autopro

HS 4450/2

Finalized with w/s on Wed, 8:39pm @ NV 2050/2

MV 8000/2

PV 5,723/2

2050

Team Autopro

Team Autopro

NV 2077/2

24/10/19

9/10/19

C.Ren \$10133.06, 83%¹⁰

Date/Time, File Pass to?



Preli. Report

24/10 typist



Final Report

Date/Time, File Return to?

Days Of Repair:

5

Resurvey No. of Trip:

1

Survey Fee:

250

Transportation:

S + RS. SI

Photos

Others

TOTAL

250

2)

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Report Format:

TP

Lump Sum / L.P. (\$)

2050

Nivitha (LKK Auto)

From: Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>
Sent: Tuesday, 8 October 2019 11:55 AM
To: Admin-D (LKKAuto); assignments
Cc: SUR; Theresa Vimala D/O Balagangadharan
Subject: RE: TP CASES FARMED OUT TO LKK ON 08/10/2019

Hi LKK, here is the list of the OIC details etc....

With Regards

Theresa Vimala
Senior Administrator
Motor Insurance
T +65 6430 7898
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at Income.com.sg/careers

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Tuesday, 8 October 2019 11:02 AM
To: Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>; assignments <assignments@lkkauto.com>
Cc: Teng Ken Leong <kenleong.teng@income.com.sg>; Thio Tse Kiat <tsekiat.thio@income.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: TP CASES FARMED OUT TO LKK ON 08/10/2019

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Theresa Vimala D/O Balagangadharan [mailto:thrsvim.bala@income.com.sg]

Sent: Tuesday, 8 October 2019 10:04 AM

To: assignments <assignments@lkkauto.com>; Catherine Chong (LKK Auto) <admin-d@lkkauto.com>

Cc: Teng Ken Leong <kenleong.teng@income.com.sg>; Thio Tse Kiat <tsekiat.thio@income.com.sg>; Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>

Subject: RE: TP CASES FARMED OUT TO LKK ON 08/10/2019

Dear LKK,

Please assist to survey the following vehicles as per Tse Kiat's instruction :-

SN	OIC	Claim No.	Survey Date	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	CHRYLLIS	MT/1065646-002	8/10/2019	SMH465X	CAR TIMES AUTOLUTION PTE LTD	160 SIN MING DRIVE #02-04 AUTOCITY	Yuki Peck / 64715111		SIQ9148R	1/10	
2	CYNDIE YONG	MT/1065698-001	8/10/2019	SMK2182H	COMPLETE VMS PTE LTD	176 SIN MING DRIVE #03-14 SIN MING AUTOCARE SINGAPORE 575721	Chiu S. L. / 6455 0012		YP8220Z	6/10	
3	JEFF LIN	MT/1065519-002	8/10/2019	SLL8018S	EM-1 AUTO PTE. LTD.	BLK 8 #01-68 SIN MING INDUSTRIAL EST SECTOR C SINGAPORE 575643	Chia Sin Muk / 9666 6556		SIV7242M	5/10	

4	JARED	MT/1065564-002	8/10/2019	SCQ95B	LEONG AUTO PTE LTD	160 SIN MING DRIVE #02-13 SIN MING AUTO CITY	Daniel Tan/Cady Lee / 9692 4113	SGV8018Z	5/10	
5	HELENA TAN	MT/1065715-001	8/10/2019	SIZ1046G	TEAM AUTOPRO PTE LTD	BLK 160 SIN MING DRIVE #01-14 SINGAPORE 575722	Eric Lee / 8269 9999	SGV9761D	5/10	

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

With Regards

Theresa Vimala
Senior Administrator
Motor Insurance
T +65 6430 7898
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at Income.com.sg/careers

in with you

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.



This email has been checked for viruses by AVG antivirus software.

www.avg.com

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

TG Lim (LKK Auto)

From: Team Auto <tap.finalization@gmail.com>
Sent: Wednesday, 23 October, 2019 8:39 PM
To: TG Lim (LKK Auto)
Subject: Re: SLU1663C - FINALIZE AMOUNT AND AFTER PAINT
Attachments: WhatsApp Image 2019-09-24 at 10.11.07 AM.jpeg; WhatsApp Image 2019-09-24 at 10.12.11 AM.jpeg; WhatsApp Image 2019-09-24 at 10.11.23 AM.jpeg; WhatsApp Image 2019-09-24 at 10.11.45 AM.jpeg; WhatsApp Image 2019-09-24 at 10.10.59 AM.jpeg; WhatsApp Image 2019-09-24 at 10.12.50 AM.jpeg; WhatsApp Image 2019-09-24 at 10.13.13 AM.jpeg; WhatsApp Image 2019-09-24 at 10.13.02 AM.jpeg; 20191012_140719_resized.jpg; 20191012_140726_resized.jpg; 20191012_140717_resized.jpg; 20191012_140728.jpg; 20191012_140711_resized.jpg; 20191012_140738_resized.jpg; 20191012_140743_resized.jpg; 20191012_140747_resized.jpg; 20191012_140733.jpg; 20191012_140757_resized.jpg; 20191012_140805_resized.jpg; 20191012_140801_resized.jpg; WhatsApp Image 2019-10-12 at 9.35.37 AM.jpeg; WhatsApp Image 2019-10-12 at 9.36.30 AM.jpeg; WhatsApp Image 2019-10-12 at 9.36.35 AM.jpeg; 20191015_174651_resized.jpg; 20191015_174705_resized.jpg; 20191015_174635_resized.jpg; 20191015_174709_resized.jpg; 20191015_174637_resized.jpg; 20191015_174656_resized.jpg; 20191015_174710_resized.jpg; 20191015_174717_resized.jpg; 20191015_174725_resized.jpg; 20191015_174722_resized.jpg

Dear Mr Lim,

Without Prejudice

Thank You for assisting as the SJE for all the subject vehicle.

We are pleased to confirm our acceptance to your proposed of COR for

Vehicle Number	Finalised Amount	Repair Days
1 GBJ 5820R	\$10,000.00	10
2 GBB 5113R	\$3050.00	7
3 SJR 1046G	\$2050.00	5

Kindly advise OIC and reference number (if any) for our submission of LOD.

Enclosed herewith after-repair photos fyn.

Thank you.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	945H
Vehicle Details	
Vehicle No.:	SJZ1046G
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Oct 2019
Vehicle Make:	KIA
Vehicle Model:	PICANTO 1.1EX MT 2WD 5DR
Primary Colour:	Blue
Manufacturing Year:	2010
Engine No.:	G4HGAP014989
Chassis No.:	KNABK513LAT982173
Maximum Power Output:	47.1 kW (63 bhp)
Open Market Value:	\$7,840.00
Original Registration Date:	27 Oct 2010
First Registration Date:	27 Oct 2010
Transfer Count:	0
Actual ARF Paid:	\$7,840.00
OPC Cash Rebate Details	
OPC Cash Rebate Eligibility:	No
OPC Cash Rebate Eligibility Expiry Date:	-
OPC Cash Rebate Amount:	-
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Oct 2020
PARF Rebate Amount:	\$4,312.00
Intended COE Rebate Details	
COE Expiry Date:	26 Oct 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$15,415.00
COE Rebate Amount:	\$1,611.00
Total Rebate Amount:	\$5,923.00

The information contained herein is correct as at 09 Oct 2019

OK

COE left 1yr

MV 8,000/2
PV 5,923/2
NV 2,077/2

Tarim bin
9/10/12

Used Cars ([//www.oneshift.com/used_cars/index.php](http://www.oneshift.com/used_cars/index.php))

› Kia Listings (listings.php?make=Kia&model=Picanto&year_from=10&year_to=) › Kia Picanto 1.1

[GO BACK](#)[SHOW FILTER](#)[ADVANCED SEARCH \(\[//www.oneshift.com/used_cars/advanced_search.php\]\(http://www.oneshift.com/used_cars/advanced_search.php\)\)](http://www.oneshift.com/used_cars/advanced_search.php)

Overview



Kia Picanto 1.1 ([listings.php?po_carname=Kia Picanto 1.1](http://listings.php?po_carname=Kia%20Picanto%201.1))

\$5,388

Be the first of your friends to like this.



Print Ad ([//www.oneshift.com/used_cars/ads_detail_print.php?adid=242958&print=1](http://www.oneshift.com/used_cars/ads_detail_print.php?adid=242958&print=1))

Selling Price **\$5,388**

Availability **Available**

Reg Date **19 Jan 2009 8 mths left**

COE  **\$5,001**

OMV  **\$7,553**

Depreciation	 -
Road Tax	 \$486
Transmission	Manual
Engine Cap	1,086 cc
Mileage	150,000 km

Description

Accident Free, Very Well Maintain, Driven By A Teacher.

Features

Fuel Efficient 1.1 L 4 Cylinder Inline SOHC Engine, Smooth 5 Speed Manual Transmission, Power Steering, Nice Interior, Fuel Consumption Low, Power Window Audio Player
Knockdown Rear Seat
Solar Film.

Fuel Type	Petrol
No. of Owners	2
Car Type	Hatch (listings.php?cartype=Hatch)
Car Category	PARF Car (listings.php?category=PARF+Car)
Colour	-
Ad Posted	18 Sep 2019

Upfront Payment

Transfer Fee:

\$25

Down Payment

\$1,616 (30% of Car Price)

1st Installment

\$428.43

Total Upfront Payment:

\$2,069.83

Calculate Car Loan (http://www.oneshift.com/used_cars/car-loan.php?adid=242958)

Email: sm@idac.com.sg

Tel no: 6555 6888 Fax no: 6454 3279

Personal Particulars of Owner & Driver (Vehicle A)

Date of Accident: 05/10/2019 (dd/mm/yy) Time of Accident: 20 50 (24-HR-FORMAT)
Vehicle No.: SJZ 1046 G Vehicle Make & Model: KIA PICANTO 1.1EX MT 2WD 5DR
Exact location of Accident: BLK 178 EDGEFIELD PLAINS SERVICE ROAD
Policyholder's Name / IC No.: TAN KOK CHYE S1780945H
Driver's Name / IC No.: TAN KOK CHYE S1780945H (As Above) ☐
Driver's Contact No.: 8121 3901 Company Contact No.: _____
Driver's Address: 178 EDGEFIELD PLAINS #05-224 S820178
Insurance Company: AIG Email address (if any): _____

Relationship between Owner & Driver: OWNER

or Others specify: _____

What do you wish to claim? (Please TICK one only)

☐ Own Insurance / ☒ Other Vehicle (The one you want to claim against) / ☐ Reporting (For Record Purpose)

**Exact purpose for which the vehicle
Was being used at time of accident?**

Occupation (nature of job) ☒ Indoor/ ☐ Outdoor

☒ Private use / ☐ Work purpose

No. of Passengers (Including Driver): 02

Passenger Name : NANCY LEE JIA YI

Gender : Female

Passenger Name : _____

Gender : _____

Weather condition & Road conditions? (On the day of accident)

☒ Clear & Dry / ☐ Raining & Wet / ☐ After-Rain & Wet / ☐ Drizzling & Wet / Others: _____

Was there any video captured by your Car Camera? ☐ Yes / ☒ No

Any Injuries: ☒ Yes / ☐ No (If YES) Injured Person's Name: NANCY LEE JIA YI

Injuries Sustain: HEAD & FACE Injured Person in Which Vehicle: SJZ1046G

Police Report filed: ☒ Yes / ☐ No (If YES) Which Police Station: _____

The Other Party(s) Details:

1. Driver's Name / IC No.: _____ Vehicle No: SGV 9761D

Driver's Contact No.: _____ Insurance Company (If any): _____

2. Driver's Name / IC No.: _____ Vehicle No: _____


Driver's Contact No.: _____ Insurance Company (If any): _____

*Independent Witness (If Any): _____ Contact No: _____

Preferred Workshop Name: _____ Contact No: _____

*If no proper documents are produced, IDAC should not file the report. Information will be discarded after one week.

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

refer to police report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SJZ1046G	AIG ASIA PACIFIC INSURANCE PTE. LTD.	2100234242-08	27/10/2018	26/10/2019

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Passenger				
Name	NANCY LEE JIA YI		ID No.	S7972444J
Related Vehicle	SJZ1046G (Car)		Contact No.	81279859
Hospital/Clinic	SENGKANG GENERAL HOSPITAL PTE. LTD.		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	05/10/2019		Date Discharge	05/10/2019
No. of Days granted Medical Leave		03	Degree of Injury	Slight
Driver				
Name	TAN KOK CHYE		ID No.	S1780945H
Related Vehicle	NIL		Contact No.	81213901
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave		NIL	Degree of Injury	NIL

Brief Details.

On 05/10/2019 at about 2050hrs, I was driving my vehicle SJZ1046G along Blk 178 Edgefield Plains at the service road. I drove down the slope and turn right towards the carpark.

Suddenly, I felt an impact from the right portion of my vehicle. I stationary stopped my vehicle and made a check on my wife. My wife informed me that she suffered bleeding at her forehead area. I then stepped out of my vehicle and discovered that I got an accident with vehicle SGV9761D. But the vehicle driver of SGV9761D reversed and parked back his vehicle and his vehicle front light is not on. I took photos of the scene, damages of my vehicle and damages of vehicle SGV9761D.

I went to speak to the driver of SGV9761D and he told me that he wanted to private settlement. I told him that how to private settlement the matter as he had already moved his vehicle without taking any photos of the accident and is his fault already and he claims that is my fault for hitting against his vehicle as I am driving too fast and he got an in-build car camera. As such I told him that I am not driving fast and I told him that I have the right of way and he should let me proceed first. He then tells me that he will call traffic



**SINGAPORE
POLICE FORCE**



T/20191006/2004

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

3 of 4

Report No. T/20191006/2004

CONTINUATION OF REPORT

police. As such I agree with him and he called for traffic police. I then exchanged my particulars with the driver.

I called my eldest daughter and inform about the matter and she came down to scene. Ambulance came shortly and render medical assistance to my wife. My wife was then conveyed to Sengkang General Hospital accompanied by my eldest daughter. My youngest daughter also came to the scene shortly.

After a while, there are vehicles behind my vehicle honking indicating that they wanted to drive into the carpark as such I have no choice and drove my vehicle into the carpark and parked my vehicle. After parking my vehicle, I went back to the accident location.

I checked with the driver if the traffic police are coming. However, the driver told me that the traffic police might not be coming. As such, I told him that we can settle the matter via insurance claim as he denied is his wrong and I am rushing to send my wife to hospital and he agreed. When I was about to leave, the traffic police came.

The traffic police took particulars from me and the driver of SGV9761D. The traffic police then asked me to drive out my vehicle to let them have a look which I did so. The traffic police then gave me a case card F/20191005/0194 and asked me to lodge a traffic accident report. I then drove my vehicle to Sengkang General Hospital to check on my wife.

My youngest daughter told me that she overheard the driver of SGV9761D telling the traffic police that that I was driving very fast around the speed of 60mph which is ridiculous. At the speed of 60mph and was turning right, my vehicle will already overturn.

Team AutoPro Pte Ltd 160 Sin Ming Dr, #02-12 Sin Ming AutoCity Singapore 575722

Tel: 8269-9999 Email: estimate.tap@gmail.com/teamautopl@gmail.com

SJE :

Date of Survey :

Date of ReSurvey:

Contacts :

After-Paint:

Vehicle Nos : **SJZ 1046 G**

Made : KIA

Model : Picanto

Chassis No :

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount:

Working Day:

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Front door <i>SVC X</i>	1	\$ 729.00	\$ 729.00
2	Front door protector <i>SVC X</i>	1	\$ 81.50	\$ 81.50
3	Bonnet <i>SVC X</i>	1	\$ 978.00	\$ 978.00
4	Front fender <i>RH DD ✓</i>	1	\$ 567.00	\$ 281.50 567.00
5	Front fender inner shield <i>BR ✓</i>	1	\$ 106.00	\$ 70.00 106.00
6	Headlamp Rh <i>CUT ✓</i>	1	\$ 897.60	\$ 330.00 897.60
7	Front shock absorber <i>{ ? DDV</i>	1	\$ 426.00	\$ 426.00 267.90 <i>P</i>
8	Front lower arm <i>{ ? DDV</i>	1	\$ 289.00	\$ 289.00 266.70
9	Front knuckle arm <i>{ ?</i>	1	\$ 347.60	\$ 347.60
10	Front knuckle arm bearing <i>{ ? NDMX</i>	1	\$ 164.20	\$ 164.20
11	Front bumper <i>DD ✓</i>	1	\$ 816.00	\$ 816.00 322.00
12	Front bumper side retainer <i>NECV</i>	1	\$ 106.00	\$ 106.00 60.00
13	Front bumper inner sponge <i>? BR ✓</i>	1	\$ 135.00	\$ 135.00 102.00
14	Front bumper reinforcement <i>? DDV</i>	1	\$ 189.70	\$ 189.70 145.00
15	Front bumper fog lamp <i>CUT ✓</i>	1	\$ 267.30	\$ 267.30 145.00
16	Front bumper grille <i>? } NDM</i>	1	\$ 189.00	\$ 189.00
17	Front grille <i>? } NDM</i>	1	\$ 95.60	\$ 95.60
18	Front support panel <i>? BR ✓</i>	1	\$ 768.90	\$ 768.90 562.00

Parts Sub Total : \$ 2552.10 7,153.40

10%

Discount \$ 255.21 715.34

PARTS TOTAL : \$ 2296.89 6,438.06

KV 2077

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Front fender inner shield clips <i>NECV</i>	1	\$ 50.00	\$ 30.00 50.00
2	Front bumper clips <i>NECV</i>	1	\$ 50.00	\$ 30.00 50.00
3	Front bumper side retainer clips <i>NA X</i>	1	\$ 50.00	\$ -50.00
4	Front bumper grille clips <i>upper NDMX</i> <i>NECV</i>	1	\$ 50.00	\$ -50.00
5	Front grille clips <i>lower</i> <i>NECV</i>	1	\$ 50.00	\$ -50.00
6	Front number plate with garnish <i>SVC X</i>	1	\$ 80.00	\$ 80.00
7	Front tyre <i>SVC X</i>	1	\$ 325.00	\$ -325.00
8	Front alloy rim <i>local retain</i>	1	\$ 800.00	\$ 200.00 800.00
9	Aircon compressor fluid <i>SVC X</i>	1	\$ 80.00	\$ -80.00
SPECIAL NETT TOTAL :				\$ 260.00 1,535.00

Nos.	LABOUR	S\$
1	To Panel Beating & Straighten Accident Areas	\$ 1000.00 1,500.00
2	To R&R Undercarriage Components (Brake Pad, Caliper & ETC)	\$ 120.00
3	To R&R Undercarriage Parts (Lower Arms, Absorber, Steering Rack & ETC)	\$ 120.00
4	To Check Wiring & Reconnect All Electrical System	\$ 30.00 100.00
5	To Apply Rust Proofing On Accident Affected Areas	\$ 60.00 150.00
6	To Putty & Respray Accident Affected Damage Areas	\$ 600.00 1,500.00
7	Wheel Alignment	\$ 60.00 -120.00
8	To Align Front Chassis alignment	\$ 300.00
9	Mount workbench	\$ 300.00
LABOUR TOTAL :		\$ 1830.00 4,210.00

PARTS TOTAL : \$ 6,438.06
 SPECIAL NETT TOTAL : \$ 1,535.00
 LABOUR TOTAL : \$ 4,210.00
 GRAND TOTAL : \$ 12,183.06

10/1/19
 Telling him
 1445 hrs
 ? photo
 Repair days ? 5

12624 66

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

SJE :

Date of Survey :

Date of ReSurvey:

Contacts :

After-Paint:

Vehicle Nos : **SJZ 1046 G**

Made KIA

Model Picanto

Chassis No :

Supplementary Report

* AGREED Cost Of Repair and Repair Day/s with SJE *

Amount:

Working Day:

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Washer tank <i>DD ✓</i>	1	\$ 264.00	\$ 67.00 264.00
2	Washer tank fluid <i>NECV ✓</i>	1	\$ 60.00	\$ 10.00 60.00
Amt				\$ 77.00 324.00
Discount(10.00%)				\$ 7.70 32.40
Subtotal				\$ 69.30 291.60

Nos.	LABOUR	S\$
1	R&R washer tank	\$ 30.00 150.00
2		\$ -
3		\$ -
LABOUR TOTAL :		\$ 30.00 150.00
TOTAL:		\$ 99.30 441.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Parts ⁷² 2296.89 + 69.30 = 2366.19
 SN 260.00
 Labour 1830.00 + 30.00 = 1860.00
 4486.19

4/3 4.450/2

[Signature]
 10/10/19

[Signature]
 10/10/19



Kia : Morning/Picanto : 2004-11 (SA)
Thrust Line Alignment

Front : Left

Actual	Before	Specified Range
-1°02'	-1°02'	-0°30' 0°30'
2°50'	2°50'	2°13' 3°13'
-0°11'	-0°10'	-0°05' 0°05'
8°26'	8°26'	12°30' 13°30'
7°24'	7°24'	12°00' 14°00'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-2°22'	-2°23'	-0°30' 0°30'
0°52'	0°52'	2°13' 3°13'
-0°27'	-0°27'	-0°05' 0°05'
13°35'	13°35'	12°30' 13°30'
11°12'	11°12'	12°00' 14°00'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
1°21'	1°21'	
1°58'	1°58'	
-5°09'	-5°09'	
-0°38'	-0°38'	-0°09' 0°09'

Rear : Left

Actual	Before	Specified Range
-1°19'	-1°19'	-1°30' -0°30'
-0°46'	-0°46'	0°05' 0°14'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-0°45'	-0°46'	-1°30' -0°30'
0°05'	0°05'	0°05' 0°14'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
-0°34'	-0°34'	
-0°41'	-0°41'	0°09' 0°28'
-0°26'	-0°26'	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT				
NTUC INCOME INSURANCE CO-OPERATIVE LTD		Ref: CS/INC19017739/Bqd3e2		
73 BRAS BASAH ROAD		Date: 25-10-2019		
#05-01 NTUC TRADE UNION HOUSESINGAPORE				
189556				
ATTN: HELENA TAN		Code: INC		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGV 9761D	Veh. Inspected	SJZ 1046G	
Policy No.		Coverage (\$)	0.00	
Claim No.	MT/1065715-001	Excess (\$)	0.00	
Assign From	THERESA VIMALA	Assign Date	08/10/2019	
2. Vehicle Particulars & Condition				
Make & Model	KIA PICANTO	c.c	1086	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	KNABK513LAT982173	Colour	BLUE	
Odometer	77574 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	POOR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	165/50 R15	KUMHO	5 mm	
L/H Front Tyre	165/50 R15	KUMHO	5 mm	
R/H Rear Tyre	165/50 R15	KUMHO	5 mm	
L/H Rear Tyre	165/50 R15	KUMHO	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	05/10/2019	Inspect Date / Time	08/10/2019 (02:26 PM)	
Survey held at	160 SIN MING DRIVE #01-14			
Repairer	TEAM AUTOPRO PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJZ 1046G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT DOOR	SERVICEABLE	729.00	-
1	FRONT DOOR PROTECTOR	SERVICEABLE	81.50	-
1	FRONT FENDER RH	DENTED	567.00	281.50
1	FRONT FENDER INNER SHIELD	BROKEN	106.00	70.00
1	HEADLAMP RH	CUT	897.60	330.00
1	FRONT SHOCK ABSORBER	DENTED	426.00	267.90
1	FRONT LOWER ARM	DENTED	289.00	266.70
1	FRONT KNUCKLE ARM	NO DAMAGED	347.60	-
1	FRONT KNUCKLE ARM BEARING	NO DAMAGED	164.20	-
1	FRONT BUMPER	DENTED	816.00	322.00
1	FRONT BUMPER SIDE RETAINER	NECESSARY	106.00	60.00
1	FRONT BUMPER INNER SPONGE	BROKEN	135.00	102.00
1	FRONT BUMPER REINFORCEMENT	DENTED	189.70	145.00
1	FRONT BUMPER FOG LAMP	CUT	267.30	145.00
1	FRONT BUMPER GRILLE	NO DAMAGED	189.00	-
1	FRONT GRILLE	NO DAMAGED	95.60	-
1	FRONT SUPPORT PANEL	BROKEN	768.90	562.00
1	BONNET	SERVICEABLE	978.00	-
1	WASHER TANK (ADDITIONAL)	DENTED	264.00	67.00
1	WASHER TANK FLUID (ADDITIONAL)	NECESSARY	60.00	10.00
	LESS 10% DISCOUNT		-747.74	-262.91
			6,729.66	2,366.19
SPECIAL NETT ITEMS				
1	FRONT FENDER INNER SHIELD CLIPS (SN)	NECESSARY	50.00	30.00
1	FRONT BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
1	FRONT BUMPER SIDE RETAINER CLIPS (SN)	NO APPLICATION	50.00	-
1	FRONT BUMPER GRILLE CLIPS (SN)	NO DAMAGED	50.00	-
1	FRONT GRILLE CLIPS (SN)	NO DAMAGED	50.00	-
1	FRONT NUMBER PLATE WITH GARNISH (SN)	SERVICEABLE	80.00	-
1	FRONT TYRE (SN)	SERVICEABLE	325.00	-

Report Ref No. CS/INC19017739/Bqd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT ALLOY RIM (SN) (LOCAL REPAIR)	SCRATCHED	800.00	200.00
1	AIRCON COMPRESSOR FLUID (SN)	SERVICEABLE	80.00	-
			1,535.00	260.00
	LABOUR			
	TO PANEL BEATING & STRAIGHTEN ACCIDENT AREAS.		1,500.00	1,000.00
	TO R&R UNDERCARRIAGE COMPONENTS (BRAKE PAD, CALIPER & ETC). }		120.00	80.00
	TO R&R UNDERCARRIAGE PARTS (LOWER ARMS, ABSORBER, STEERING RACK & ETC). }		120.00	-
	TO CHECK WIRING & RECONNECT ALL ELECTRICAL SYSTEM.		100.00	30.00
	TO APPLY RUST PROOFING ON ACCIDENT AFFECTED AREAS.		150.00	60.00
	TO PUTTY & RESPRAY ACCIDENT AFFECTED DAMAGE AREAS.		1,500.00	600.00
	WHEEL ALIGNMENT.		120.00	60.00
	TO ALIGN FRONT CHASSIS ALIGNMENT.	NOT NECESSARY	300.00	-
	MOUNT WORKBENCH.	NOT NECESSARY	300.00	-
	R&R WASHER TANK. (ADDITIONAL)		150.00	30.00
			4,360.00	1,860.00
GRAND TOTAL			12,624.66	4,486.19
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				2,050.00

Report Ref No. CS/INC19017739/Bqd3e2

LIM TEOW GUAN

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.