

VOLKSWAGEN CENTRE SINGAPORE

17 Tuas Avenue
Singapore 639176
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page 1/1

Company
AIG ASIA PACIFIC INSURANCE P/L
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Customer Details:
Mr
ANG
CHING AI
710 ANG MO KIO AVENUE 8
#05-2617
Singapore 560710

Document no.
Document date
Customer no.
Customer GST-ID
Dealer
Job order number
Job order date
Service Advisor
08-10-2019
5211043795
201009404M
39999
2019002254/ 1
07-10-2019
PEARLYN CHEONG

License plate	Model code	First registration	VIN	Model	Mileage
SCG881B	3G24JZ	22-10-2018	WVWZZZ3CZKE003687	Passat Comfortline 1.8 TSI 132kW DSG	1

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	Diagnostic and Programming	1	pcs.	480.00	#1	480.00	513.60
3G0807217K GRU	Cover For Bumper Primed <i>de</i>	1	pcs.	1,393.26	#1	1,393.26	1,490.79
3G0998493	1 Set Sensor Brackets <i>re</i>	1	pcs.	39.84	#1	39.84	42.63
D 822150A1	Bonding Agent For Plastic <i>re</i>	1	pcs.	56.90	#1	56.90	60.88
D 180KU2A1	2k-Plastic Adhesive <i>re</i>	1	pcs.	74.29	#1	74.29	79.49
	LABOUR	3	pcs.	840.00	#1 <i>840</i>	2,520.00	2,696.40
	Spray Painting	3	pcs.	800.00	#1 <i>800</i>	2,400.00	2,568.00

Quotation valid till 14-10-2019

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	480.00	6,484.29	7%	487.50	6,964.29	7,451.79
Total	480.00	6,484.29		487.50	6,964.29	7,451.79

Customer

Service Advisor

-----VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).-----

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resul
Ap 90010068
3 days
09/10/19 @ 1400
Resurvey before paint