

228013002

ASS. REC. BY:

REF: CS3/CT119017765/HCB⁵⁷

Special Instruction:

Surveyor: Hock Ann

ASSIGNMENT (Office)

Menimen
From (Person): Irene Tay

of CT1

Date/Time: 8/10/19 @ 3:48pm

Estimated Cost: _____ Bill to: _____

OD / ~~IT~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJL 3018Z

Insured: SLK 6779Y

at Workshop n/s: A- Tee Automotive

Tel: 9062 6924

of 1 Kalei Bkt Ave 6 # 02-11 Autobay

Policy No: DMPCCN 30231319000

Claim No: SNM9D202698C02

Sum Insured: _____ Excess: _____

D.O.A. 5/10/2019

Make of Veh:
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 9:29am @ 9/10

Person Contacted: James

Vehicle IN / OUT

Date/Time	Action/Instruction	Estimated (X)	Insp: 8 Kalei Bkct Ave 4 # 04-20
	SJL 3018Z - NA	AIG 19017648	Z4 DOA: 5/10/2019
	SLK 6779Y - X		
	Dismantle: 10/10/2019.		
	After repair: 16/10/2019		

ASSIGNMENT

From: Date: 9/10/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SJL 3018Z
at Workshop m/s: A-tec Automotive
of: 8kaki Bukit Ave 4 # 04-20 premier

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

X	
N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{lap}

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SJL 3018Z Yr Regn: 21/11/2008

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: H. city LX 1.5 c.c. 1497

Colour: Gray A/C: Insured / Std / NI / NA

Sp. Reading: 215416 km T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MRHGM 26709P020052

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Moti: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55/R16

R: 205/55/R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front	<u>Assemble</u>	Rear	<u>Toyo</u>
R/Bal.	5 mm	R/Bal.	5 mm
L/Bal.	5 mm	L/Bal.	5 mm
D.O.A.	5/10/19	D.O.I.	9/10/19

Survey held at: A-tec Auto

Des. of Damages: Frnt Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

SJL 3018Z NON Estimate (PRS) case

RECEIVED 23 OCT 2019

MV - 19500

PV - 12156

NV - 7300

Range → 2-3k

refer Days → 4 day

* NON completed

waiting after paint photo &

17/10/2019

Date/Time, File Pass to?

: Preli. Report

Days Of Repair: 4

1)

: Final Report

Resurvey No. of Trip: 2

Date/Time, File Return to?

Survey Fee:

2)

Add Fee: : Site Insp (\$

Transportation:

: Interview (\$

\$ + RS, \$

: Tech. Insp (\$

Photo

: Wheel and (\$

Other:

Report Format: PRS

Lump Sum / L.B. (\$

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Oct 2019		08 Oct 2019 15:48 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	YUE SI HUI, ID: S8102441C [Created by insurer]		
Main Claimant:	FRESH CARS PTE LTD, Co. Reg. No.: 201608540Z		
Vehicle Reg. No.:	SJL3018Z	Date of Loss:	05/10/2019 18:00 - :59 [130 Months and 14 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D204698C02	Policy/Cover Note No.:	DMPCSN30231319000
Vehicle Reg. No. (Insured):	SLK6779Y	Policy No. (Claimant):	999994039
Repairer:	A-tec Automotive Pte Ltd (KAKI BUKIT) 1 KAKI BUKIT AVE 6 #02-11 AUTOBAY, 417883 Kaki Bukit - Tel: 90626929/97103383	Excess:	S\$0.00
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 17/10/2019]		
Driver/Custodian (Insured):	YUE SI HUI (38 / Male), NRIC: S8102441C Email:		

ASSOCIATED MAIL RECEIVED

There are no mail for this case. [View All](#) [Compose Case Mail](#)

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/10/2019 19:02
Date Of Accident	05/10/2019 18:55
Exact Location Of Accident	LORNIE RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJL3018Z
Insured/Policyholder	
Name Of Registered Owner	FRESH CARS PTE LTD
Co Reg No	201608540Z
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-89999999
Vehicle Particulars	
Manufacturer	HONDA
Model	HONDA CITY LX 1.5 I-VTEC AUTO
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	999994039
Cover Note Number	
Driver	
Name of Driver	TOH CHEE MING
NRIC No	S8022079J
Date Of Birth	24/07/1980
Occupation	OUTDOOR
Date Of Driving Pass	07/09/2013
Driving Experience	6 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92722722
Fax Number	
Contact Number	OFFICE-92722722
Email Address	NOEMAIL

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	TOH CHEE MING
Approximate Age	
Injuries Sustain	BODY
Injured person in which vehicle?	SJL3018Z
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	540Z
Vehicle Details	
Vehicle No.:	SJL3018Z
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Oct 2019
Vehicle Make:	HONDA
Vehicle Model:	HONDA CITY LX 1.5 I-VTEC AUTO
Primary Colour:	Grey
Manufacturing Year:	2008
Engine No.:	L15A71800168
Chassis No.:	MRHGM26709P020052
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$19,462.00
Original Registration Date:	21 Nov 2008
First Registration Date:	21 Nov 2008
Transfer Count:	3
Actual ARF Paid:	\$19,462.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	20 Nov 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$14,835.00
COE Rebate Amount:	\$12,156.00
Total Rebate Amount:	\$12,156.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 15 Oct 2019

OK

Enquire Vehicle Transfer Fee

Vehicle Details

Vehicle No: SJL3018Z	
Make / Model HONDA / HONDA CITY LX 1.5 I-VTEC AUTO	
Vehicle Type: Z10 - Private Hire (Chauffeur) Motor Car	Vehicle Attachment 1: No Attachment
Vehicle Scheme: Normal	Chassis No.: MRHGM26709P020052
Propellant: Petrol	Engine No.: L15A71800168
Motor No.: -	Engine Capacity: 1497 cc
Power Rating: -	Maximum Power Output: 88.0 kW (118 bhp)
Maximum Laden Weight: 1480 kg	Unladen Weight: 1150 kg
Year Of Manufacture: 2008	Original Registration Date: 21 Nov 2008
Lifespan Expiry Date: -	COE Category: A - Car (1600cc & below)
PQP Paid: \$14,835.00	COE Expiry Date: 20 Nov 2023
Road Tax Expiry Date: 20 Nov 2019	PARF Eligibility Expiry Date: -
Inspection Due Date: 20 Nov 2019	Intended Transfer Date: 15 Oct 2019
CO2 Emission: -	CEV/VES Rebate Utilised Amount: -
CO Emission: -	HC Emission: -
NOx Emission: -	PM Emission: -

Fees To Be Paid For Transfer

Transfer Fees	
Road Tax Renewal - 6 months (21 Nov 2019 to 20 May 2020)	\$25.00
Road Tax Renewal - 12 months (21 Nov 2019 to 20 Nov 2020)	\$411.00
	\$821.00

Message

The fees above do not include any late road tax fees, which apply if road tax or lay-up has expired. You can use the digital service Enquire Road Tax Payable to check if there are any late road tax fees. Any road tax that has been paid for the vehicle will be transferred to the next owner. Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

Print

Save as PDF

Copy as Text

DOA = 5/10/19

MV - 19500
PV - 12156
MV - 7300

3 year 11 months
5000 yr
5000 in = 416
= 15000 + 4576
= 19576

OK →

- New Cars
- Used Cars
- Sell My Car
- Directory
- Products
- Insurance
- Articles
- Forum
- Resources

Honda City Price Range Depreciation 2009 Vehicle Type

Home Used Cars SmartCars Boutique Pte Ltd Honda City 1.5A VTEC (COE till 08/2024)

Honda City 1.5A VTEC (COE till 08/2024)

Overview Financial Insurance Accessories Similar Research Photos Map



Price	\$26,800	Reg Date	13-Aug-2009 (4yrs 5mths 28days COE left)
Depreciation	\$5,550 /yr	Manufactured	2008
Mileage	131,235 km (12.9k /yr)	Transmission	Auto
Road Tax	\$684 /yr	OMV	\$19,389
Derag Value	\$14,166 as of today (thru/yr)	ARF	\$19,389
COE	\$14,664	Power	88.0 kW (118 bhp)
Engine Cap	1,497 cc	No. of Owners	5
Curb Weight	1,150 kg		

Type of Vehicle Mid-Size Sedan

Features

Powerful And Fuel Efficient 4 Cylinders 16 Valves I-VTEC Engine, 118 Bhp, Responsive 5-Speed Auto Transmission, Paddle Shifters, ABS, SRS Airbags. View specs of the Honda City (2008-2014)

Accessories

Original Leather Upholstery Seats, Factory Fitted Audio System, Fog Lamps, Solar Film, Reverse Sensors.

Description

Pass Owners Transfer Account Manager As Usage Within Company. Full Loan Available! Beautifully Maintained Inside Out. Responsive Throttle And Smooth Gearbox. 100% Accident-Free. Trade-In Welcome. Various Loan Schemes To Suit Your Budget. Booking Fee Excluded. Call Or Drop By For A No-Obligation Discussion On Test Drive Or Financial Matters.

Category

COE Car, Premium Ad Car

Status

Available

Resources

Car Valuation - Free. Find out the market value of your existing car for free. Get started

Vehicle Evaluation. Afraid of lemons? Request to have this car evaluated professionally. Find out more

Printed on: 13-Oct-2019 | Last Updated on: 15-Oct-2019

Upfront Payment

Transfer Fee	\$25	Maximum 30% Loan
Down Payment	\$5,040 (change)	
1st Instalment	\$368	Based on 4,200 Service side
Insurance	\$1,116 onwards	Not at fault! No upfront payment required! (Get a quote) Quote assumes a standard profile. Call a quote for exact figure.
Total Upfront Payment	\$9,569	Check with seller for exact figure



Show/Hide Report Error Compare Add to My Favorites

Supplier Information

Company SmartCars Boutique Pte Ltd
 • 80% in stock
 • 62 units sold | 37 units available

Address 61 Ubi Avenue 2 #03-19
 Search for nearby this location

Location Automobile Magnet

Office No 6740082

Contact Person(s) Kenny 9080958
 Cary 9082309

USED CARS NEW CARS PROFILE

Products and Services

BUY & SELL
Your APPRECIATION & UNIQUE Vehicle No.

THE BIGGEST PLAYER
with the most reliable and consistent for sale!

★★★★

The Largest Car No. Plate market in SG

LED Skull Plate

Honda 2014 LED Skull Plate

Protect The Door Sill From Damages

Kenon HID Light (With Silver Ballast)

Protect Original Petrol Pump Wear & Tear.

SBE 59 G FOR SALE

Bibbed Carplate for Sale

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Oct 2019		08 Oct 2019 15:48 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	YUE SI HUI, ID: S8102441C	
Main Claimant:	FRESH CARS PTE LTD, Co. Reg. No.: 201608540Z	
Vehicle Reg. No.:	SJL3018Z	Date of Loss: 05/10/2019 18:00 - :59 [130 Months and 14 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D204698C02	Policy/Cover Note No.: DMPCSN30231319000
Vehicle Reg. No. (Insured):	SLK6779Y	Policy No. (Claimant): 999994039
		Excess: S\$0.00
Repairer:	A-tec Automotive Pte Ltd (KAKI BUKIT) 1 KAKI BUKIT AVE 6 #02-11 AUTOBAY, 417883 Kaki Bukit - Tel: 90626929/97103383	
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]	
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 17/10/2019]	
Driver/Custodian (Insured):	YUE SI HUI (38 / Male) , NRIC: S8102441C Email:	

ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
There are no mail for this case.			

ALL ASSOCIATED TASKS		View All	Search Tasks	Create New Task	Complete				
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJL3018Z (SNM19D204698C02)**
[SLK6779Y]

TP

FRESH CARS PTE LTD

Oct 5 2019 6:00PM

[YUE SI HUI]

A-tec Automotive Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser ▼
Assessment Reports			1 per page <input type="checkbox"/> <input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail <input type="checkbox"/> Print <input type="checkbox"/>
1	07/10/19 19:11	Accident Statement	<input checked="" type="checkbox"/> <input type="checkbox"/>
Photos/Images			3 per page <input type="checkbox"/> <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail <input type="checkbox"/> Print <input type="checkbox"/>
1	15/10/19 18:10	Chassis Number	<input checked="" type="checkbox"/> <input type="checkbox"/>
2	15/10/19 18:10	Odometer Reading	<input checked="" type="checkbox"/> <input type="checkbox"/>
3	15/10/19 18:10	General View	<input checked="" type="checkbox"/> <input type="checkbox"/>
4	15/10/19 18:10	General View	<input checked="" type="checkbox"/> <input type="checkbox"/>
5	15/10/19 18:10	General View	<input checked="" type="checkbox"/> <input type="checkbox"/>
6	15/10/19 18:10	General View	<input checked="" type="checkbox"/> <input type="checkbox"/>
7	15/10/19 18:10	General View	<input checked="" type="checkbox"/> <input type="checkbox"/>
8	15/10/19 18:10	General View	<input checked="" type="checkbox"/> <input type="checkbox"/>
9	15/10/19 18:10	General View	<input checked="" type="checkbox"/> <input type="checkbox"/>
10	15/10/19 18:11	General View	<input checked="" type="checkbox"/> <input type="checkbox"/>
11	15/10/19 18:11	General View	<input checked="" type="checkbox"/> <input type="checkbox"/>
12	15/10/19 18:11	General View	<input checked="" type="checkbox"/> <input type="checkbox"/>
13	15/10/19 18:11	General View	<input checked="" type="checkbox"/> <input type="checkbox"/>
14	15/10/19 18:11	General View	<input checked="" type="checkbox"/> <input type="checkbox"/>
15	15/10/19 18:11	General View	<input checked="" type="checkbox"/> <input type="checkbox"/>
16	15/10/19 18:11	General View	<input checked="" type="checkbox"/> <input type="checkbox"/>
17	15/10/19 18:11	General View	<input checked="" type="checkbox"/> <input type="checkbox"/>
18	15/10/19 18:11	General View	<input checked="" type="checkbox"/> <input type="checkbox"/>
19	15/10/19 18:11	General View	<input checked="" type="checkbox"/> <input type="checkbox"/>
20	15/10/19 18:11	General View	<input checked="" type="checkbox"/> <input type="checkbox"/>
21	15/10/19 18:11	General View	<input checked="" type="checkbox"/> <input type="checkbox"/>
22	15/10/19 18:11	General View	<input checked="" type="checkbox"/> <input type="checkbox"/>
23	15/10/19 18:11	General View	<input checked="" type="checkbox"/> <input type="checkbox"/>
24	15/10/19 18:11	General View	<input checked="" type="checkbox"/> <input type="checkbox"/>
25	15/10/19 18:11	General View	<input checked="" type="checkbox"/> <input type="checkbox"/>
26	15/10/19 18:11	General View	<input checked="" type="checkbox"/> <input type="checkbox"/>
27	15/10/19 18:11	General View	<input checked="" type="checkbox"/> <input type="checkbox"/>
28	15/10/19 18:11	General View	<input checked="" type="checkbox"/> <input type="checkbox"/>
29	15/10/19 18:11	General View	<input checked="" type="checkbox"/> <input type="checkbox"/>
30	15/10/19 18:11	General View	<input checked="" type="checkbox"/> <input type="checkbox"/>
31	15/10/19 18:11	General View	<input checked="" type="checkbox"/> <input type="checkbox"/>
32	15/10/19 18:11	General View	<input checked="" type="checkbox"/> <input type="checkbox"/>
33	15/10/19 18:11	General View	<input checked="" type="checkbox"/> <input type="checkbox"/>
34	15/10/19 18:11	General View	<input checked="" type="checkbox"/> <input type="checkbox"/>
35	15/10/19 18:11	General View	<input checked="" type="checkbox"/> <input type="checkbox"/>
36	15/10/19 18:11	General View	<input checked="" type="checkbox"/> <input type="checkbox"/>
37	15/10/19 18:11	General View	<input checked="" type="checkbox"/> <input type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
38	15/10/19 18:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	15/10/19 18:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	15/10/19 18:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	15/10/19 18:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	15/10/19 18:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	15/10/19 18:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	15/10/19 18:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	15/10/19 18:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	15/10/19 18:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	15/10/19 18:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	15/10/19 18:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	15/10/19 18:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	15/10/19 18:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	15/10/19 18:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	15/10/19 18:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	15/10/19 18:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	15/10/19 18:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	15/10/19 18:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	15/10/19 18:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	15/10/19 18:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	15/10/19 18:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	15/10/19 18:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	15/10/19 18:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	15/10/19 18:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	15/10/19 18:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	15/10/19 18:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	15/10/19 18:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	15/10/19 18:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	15/10/19 18:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	15/10/19 18:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	15/10/19 18:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	15/10/19 18:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	15/10/19 18:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	15/10/19 18:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	15/10/19 18:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	15/10/19 18:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	15/10/19 18:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	15/10/19 18:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	15/10/19 18:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	15/10/19 18:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	15/10/19 18:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	15/10/19 18:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	15/10/19 18:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	15/10/19 18:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	15/10/19 18:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	15/10/19 18:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	15/10/19 18:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	15/10/19 18:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	15/10/19 18:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	15/10/19 18:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	15/10/19 18:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	15/10/19 18:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	15/10/19 18:13	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
91	15/10/19 18:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	15/10/19 18:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	15/10/19 18:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	15/10/19 18:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	15/10/19 18:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	15/10/19 18:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	15/10/19 18:13	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	15/10/19 18:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	17/10/19 09:10	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
100	17/10/19 09:10	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
101	17/10/19 09:10	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
102	17/10/19 09:10	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
103	17/10/19 09:10	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
104	17/10/19 09:10	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
105	17/10/19 09:10	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
106	17/10/19 09:10	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
107	17/10/19 09:10	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
108	17/10/19 09:10	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
109	17/10/19 09:10	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
110	17/10/19 09:10	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
111	17/10/19 09:10	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
112	17/10/19 09:10	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
113	17/10/19 09:10	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
114	17/10/19 09:10	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
115	17/10/19 09:10	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
116	17/10/19 09:10	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
117	17/10/19 09:10	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
118	17/10/19 09:10	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
119	17/10/19 09:10	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
120	17/10/19 09:10	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	08/10/19 15:48	INSD SLK6779Y GIA REPORT	 Load PDF	
2	08/10/19 15:48	PRS	 Load PDF	

Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	National Assessment Centre Services (Ubi)	1 per page	<input checked="" type="checkbox"/>
1	07/10/19 19:11	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	07/10/19 19:10	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	07/10/19 19:10	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	07/10/19 19:10	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	07/10/19 19:10	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	07/10/19 19:10	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	07/10/19 19:10	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	07/10/19 19:10	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	07/10/19 19:10	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	07/10/19 19:10	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
10	07/10/19 19:10	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	07/10/19 19:10	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	07/10/19 19:08	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	07/10/19 19:08	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST

There are no document checklists configured.

[Reset](#)
[Save](#)
[Print](#)

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19017765/HCF3S2
Date: 25/10/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSN30231319000
 Claimant Vehicle No: SJL3018Z Insured Vehicle No: SLK6779Y
 Date of Loss: 05/10/2019 Nature of Claim: TP Claim No: SNM19D204698C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJL3018Z**
 Make & Model: HONDA CITY, 1.5 LX (A) Engine No: L15A71800168
 Reg. Date: 21/11/2008 (Man. Year: 2008) Chassis No: MRHGM26709P020052
 Colour: Grey Odometer: 215416 km
 Engine Capacity: 1497 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16
 Front Left Side: Bridgestone 5 mm Rear Left Side: Toyo 5 mm
 Front Right Side: Bridgestone 5 mm Rear Right Side: Toyo 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 08/10/2019
 Date Inspected: 09/10/2019 Inspected At: A-tec Automotive Pte Ltd (KAKI BUKIT)
 1 KAKI BUKIT AVE 6 #02-11 AUTOBAY
 Singapore 417883
 Estimated Period of Repair: 4.0 days

Adjuster: LEE HOCK ANN

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

10/25/2019

Adjuster Report

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 - \$3,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 25 Oct 2019)
Parts: 143	HONDA CITY 1.5 LX (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJL3018Z)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >