

ASS. REC. BY:

REF:

TMI/CC3/TMI1907785/KVf3N2

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: M / S / Rim / STD / Rim or

Tyre Size:

F: Giti

R: GY

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

File pass to

SHD 5778R - CS/MXG/19010415/KVf3N2

SLS 1343L - X

20A - 03/06/2019

RECEIVED 07 NOV 2019

9/10/19

Email GIA to TMI and preli revised

6/11

3421.05 to Summit Confirmed by email (Ref 30,538.33, 9090)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trlp:

Survey Fee:

Transportation:

S + FS, SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format:

Lump Sum / I.B.I. (\$

250

11

261



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 URAVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: PLEASE ADVISED

Our ref: CC3/TMI19017785/Kvf3

Date :9/10/2019

The Motor Claims Department
M/S TOKIO MARINE INSURANCE SINGAPORE LTD

Dear Sir/Madam,


PRELIMINARY ADVICE OF VEHICLE NO. SHD 5778R

Please be informed that we had conducted the inspection of the above mentioned vehicle on 8/10/2019 at the premises of M/ TRANS-CAB AUTO SERVICES PTE TLD and have the following to report:-

Workshop Estimate Amount	: S\$33,959.38
Revised Estimate Amount	: S\$3,421.05
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear o/s portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

Kenneth Kong
Licensed Appraiser

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Oct 2019		09 Oct 2019 13:32 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	LOW YING HAN, ID: S8336314B			
Main Claimant:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K			
Vehicle Reg. No.:	SHD5778R	Date of Loss:	04/10/2019 18:00 - :59	
Claim Type:	TP / M1907853	Policy/Cover Note No.:	MT106893 (Comprehensive) Coverage: 11/09/2019 - 10/09/2020	
Vehicle Reg. No. (Insured):	SLS1343L	Policy No. (Claimant):	VFX/P1680520	
		Excess:	S\$0.00	
Repairer:	Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel: 62876666			
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Ng Kwai Kay Francis]			
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 18/10/2019]			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 9 October 2019 12:02 PM
To: SUR; motorclaims@tokiomarine.com.sg
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP -TRANS-CAB AUTO SERVICES PTE LTD, DOA:4/10/2018, SHD 5778R (TP VEHICLE), SLS 1343L (OI VEHICLE)
Attachments: EST.pdf; GIA.pdf; POLICE REPORT.pdf; PRELI REVISED.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SHD 5778R at M/s: TRANS-CAB AUTO SERVICES PTE LTD, NO.2 ANG MO KIO ST 63 SINGAPORE 569111 on 8/10/2019

Enclosed herewith a copy of TP's GIA report,police report ,estimated cost of repair and preliminary revised.

Kindly create claim in merimen for our necessary action.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Veron Chen (LKKAuto)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Wednesday, 6 November 2019 3:34 PM
To: Veron Chen (LKKAuto)
Cc: jasminetan@transcab.com.sg; SUR
Subject: FW: SHD 5778R-DOA: 4/10/19 -- AAD1910-046
Attachments: EST.pdf

Hi Veron

Amount confirmed \$ 3,421.05 (before GST).

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**

TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63
Singapore 569111
Tel: 6287 6666 Fax: 6287 7764

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]
Sent: Wednesday, 6 November, 2019 11:08 AM
To: Ng Wai Yin <waiyin.ng@transcab.com.sg>; SUR <sur@lkkauto.com>
Cc: jasminetan@transcab.com.sg
Subject: SHD 5778R-DOA: 4/10/19

Dear Wai Yin,

WITHOUT PREJUDICE

Finalize amount \$3421.05 @ 2.5 days.

Best Regards,
Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



This email has been checked for viruses by AVG antivirus software.
www.avg.com

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	878K
Vehicle Details	
Vehicle No.:	SHD5778R
Vehicle to be Exported:	Yes
Intended Deregistration Date:	07 Oct 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS 5DR HATCHBACK (AUTO)
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	2ZR2B92770
Chassis No.:	JTDKB3FU703078577
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,605.00
Original Registration Date:	19 Dec 2018
First Registration Date:	19 Dec 2018
Transfer Count:	0
Actual ARF Paid:	\$14,247.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Dec 2026
PARF Rebate Amount:	\$10,685.00
Intended COE Rebate Details	
COE Expiry Date:	18 Dec 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$22,057.00
COE Rebate Amount:	\$17,645.00
Total Rebate Amount:	\$28,330.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 07 Oct 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/10/2019 10:29
Date Of Accident	04/10/2019 19:00
Exact Location Of Accident	PUNGGOL ROAD FLYOVER AFTER EXITING FROM TPE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD5778R
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS-1.8 HYBRID CVT (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VFX/P1680520
Cover Note Number	

Driver

Name of Driver	SYED MASHOR BIN SYED ABU BAKAR
NRIC No	S2171340F
Date Of Birth	11/05/1958
Occupation	OUTDOOR
Date Of Driving Pass	13/08/1985
Driving Experience	34 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-98171760
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	BLK 123 BEDOK RESERVOIR ROAD #02-1003
Postcode	470123
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : LOW YING HAN GENDER: : FEMALE
Passenger 2	NAME: : UNKNOWN CHILD GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TAMPINES NORTH NPP
Police Station Address	ROAD: 461 TAMPINES ST 44 #01-56 , POSTCODE: 520461 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT T/20191005/2090

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO WITH TRAFFIC POLICE
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLS1343L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR

Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name LOW YING HAN
Approximate Age
Injuries Sustain
Injured person in which vehicle? SHD5778R
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? YES
Address
Postcode

DETAILS OF INJURED PERSON 2

Name SYED MASHOR BIN SYED ABU BAKAR
Approximate Age
Injuries Sustain
Injured person in which vehicle? SHD5778R
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:




Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report T/2019 1005 / 2090

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____



SINGAPORE POLICE FORCE



T/20191005/2090

1 of 3

Police Station Of Origin:
Tampines North NPP
461 Tampines Street 44 #01-56 SINGAPORE
520461
Tel No: 1800-7818999

Report No. T/20191005/2090

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 05/10/2019 17:39		Vide Report No.: E/20191004/0154		Station Diary No.: 20	
Informant's Particulars					
Name of Informant: SYED MASHOR BIN SYED ABU BAKAR			Address: APT BLK 123 BEDOK RESERVOIR ROAD #02-1003 SINGAPORE 470123		
ID Type / ID No.: NRIC NO / S2171340F			Contact No.: Home/Office: Mobile: 98171760		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 61	Date of Birth: 11/05/1958	Type of Informant: Driver		
Race: Malay			Language:		Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: 2B,3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 04/10/2019 19:00	Type of Location: X-Junction
Location: Junction of Road 1 and Road 2 FLYOVER AFTER EXITING FROM THE Block 461 Tampines St 44 SENGKANG EAST DRIVE #01-56 Singapore 520461 PUNGGOL ROAD Tel: 1800-7818999				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Dual Carriage Way		Traffic Control: Traffic Light - Working		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHD5778R	M/Taxi					2
SLS1343L	Car				Slightly Damaged	1

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



SINGAPORE POLICE FORCE



T/20191005/2090

2 of 3

Police Station Of Origin:
Tampines North NPP
461 Tampines Street 44 #01-56 SINGAPORE
520461
Tel No: 1800-7818999

Report No. T/20191005/2090

CONTINUATION OF REPORT

Driver			
Name	SYED MASHOR BIN SYED ABU BAKAR	ID No.	S2171340F
Related Vehicle	SHD5778R (M/Taxi)	Contact No.	98171760
Hospital/Clinic	NEPTUNE HEALTHCARE MEDICAL & SURGERY	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	05/10/2019	Date Discharge	NIL
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Driver			
Name	low Ying Han	ID No.	S83363314B
Related Vehicle	SLS1343L (Car)	Contact No.	96579940
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 04/10/2019 @ 1900hrs, I was driving my Taxi with two passengers on board along Punggol Way flyover after exiting from TPE when I was hit by another car while making a right turn. The driver apologized and admitted to his fault as he said that he was rushing. E/20191004/0154.

My Taxi sustained dents and scratches on its rear boot. While the other car sustained damages to its front portion of the car.

I have an in car camera and had already handed over the SD Car to the Traffic police Officer.

I sustained pain on my back and was given 3 days MC.



**SINGAPORE
POLICE FORCE**



T/20191005/2090

3 of 3

Police Station Of Origin:
Tampines North NPP
461 Tampines Street 44 #01-56 SINGAPORE
520461
Tel No: 1800-7818999

Report No. T/20191005/2090

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

G /

Sr Staff Sgt MOHAMMAD ABDULGHANI BIN
MOHD ADNAN

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIT /

Sgt 2 PHUA TIAK YEE

Contact No.: 65472077

Authentication Stamp

NP168

Signature Of Informant:

Date/Time:

05/10/2019 17:39

Classification Of Case:



SINGAPORE
POLICE FORCE

SIGNATURE

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5778R**AAD1910-046***Not Authored
Penalty B4 point**83421.05*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

08 OCT 2019

SHD 5778R

JTDKB3FU703078577

TOYOTA

PRIUS

4.10.19

TOKIO MARINE

19/12/2018

		PART		LIST	
1	1	REAR BUMPER	\$	<i>B</i> 442.60	✓
2	1	REAR BUMPER RE-INFORCEMENT	\$	<i>B</i> 332.70	✓
3	1	REAR BUMPER TOWING COVER	\$	<i>na</i> 15.40	✓
4	1	REAR BUMPER UNDER COVER (BLACK)	\$	<i>cm</i> 576.30	✓
5	1	REAR BUMPER SIDE RETAINER LH	\$	<i>sl</i> 116.50	X
6	1	REAR BUMPER SIDE RETAINER RH	\$	<i>cm</i> 117.70	✓
7	1	REAR TAILGATE	\$	<i>R</i> 1,147.80	} X
8	1	REAR TAILGATE OUTER GARNISH	\$	<i>R</i> 925.60	
9	1	ANTENNA, ELECTRICAL KEY	\$	<i>sl</i> 72.00	
10	1	COVER, REAR COMBINATION LAMP, RH	\$	<i>sl</i> 64.50	
11	1	COVER, REAR COMBINATION LAMP, RH	\$	<i>sl</i> 64.50	
12	1	GARNISH, BACK DOOR SIDE, LH	\$	<i>sl</i> 95.60	
13	1	GARNISH, BACK DOOR SIDE, RH	\$	<i>sl</i> 95.60	
14	1	MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER RH	\$	<i>sl</i> 56.50	
15	1	MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER LH	\$	<i>sl</i> 56.50	
16	1	BOARD ASSY, BACK DOOR TRIM	\$	<i>sl</i> 259.20	
17	1	PANEL ASSY, BACK DOOR TRIM, UPPER	\$	<i>sl</i> 52.10	
18	1	REAR TAILGATE WEATHERSTRIP	\$	<i>sl</i> 372.30	
19	1	PANEL SUB-ASSY, BODY LOWER BACK	\$	<i>R</i> 650.30	} X
20	1	TAILLAMP LOWER RH	\$	<i>cm</i> 502.00	
21	1	TAILLAMP UPPER RH	\$	<i>cm</i> 451.80	✓
22	1	REAR BUMPER SIDE RH	\$	<i>ndy cm</i> 123.70	✓
23	1	REAR BUMPER SIDE LH	\$	<i>sl</i> 123.70	X
24	1	TAILLAMP LOWER LH	\$	<i>sl</i> 502.00	X
25	1	TAILLAMP UPPER LH	\$	<i>sl</i> 443.30	X
26	1	REAR FENDER RH	\$	<i>R</i> 854.80	X
27	1	LINER, REAR WHEEL HOUSE, RH	\$	<i>R</i> 139.80	X

Trans-cab Auto Services Pte Ltd**AAD1910-046**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5778R

28	1	BOARD, BACK DOOR TRIM	\$	SH	225.20	}
29	1	PANEL ASSY, DECK TRIM SIDE, RH	\$	SH	355.90	
30	1	PANEL ASSY, DECK TRIM SIDE, LH	\$	SH	355.90	
31	1	PANEL, QUARTER WHEEL HOUSE, OUTER RH	\$	SH	296.20	
32	1	COVER, FLOOR UNDER, NO.1	\$	SH	175.10	
33	1	COVER, FLOOR UNDER, NO.2	\$	SH	241.90	
34	1	COVER, REAR FLOOR	\$	SH	229.90	
35	1	PAN, REAR FLOOR	\$	SH	583.40	
36	1	EXTENSION, REAR FLOOR SIDE PANEL, RH	\$	SH	78.30	
37	1	EXTENSION, REAR FLOOR PAN TO QUARTER PANEL, RH	\$	SH	196.50	
38	1	PIPE ASSY, EXHAUST, TAIL	\$	SH	1,655.40	
39	1	SUPPORT, EXHAUST PIPE, NO.4	\$	SH	49.10	
40	1	SUPPORT, EXHAUST PIPE, NO.5	\$	SH	49.10	
41	1	GASKET, EXHAUST PIPE	\$	SH	99.60	
42	1	TROUGH, BACK DOOR OPENING, RH	\$	SH	103.40	
TOTAL			\$		13,349.70	
25%			\$		3,337.43	
			\$		10,012.28	

Special Nett

1	1SET	PARKING AID	\$	SH	700.00	X
2	1SET	REAR BUMPER CLIP	\$	SH	66.00	✓
3	2	REAR WINDSCREEN SEALANT	\$	SH	80.00	X
4	1	WINDSCREEN MOULDING	\$	SH	100.00	X
5	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	SH	100.00	X
6	1	REAR TAILGATE TOYOTA LOGO	\$	SH	47.00	✓
7	1	REAR TAILGATE WORDING 'PRIUS'	\$	SH	52.90	✓
8	1	REAR TAILGATE WORDING 'HYBRID'	\$	SH	53.50	✓
9	1	REAR TAILGATE STICKER 'TRANS-CAB'	\$	SH	80.00	3012
10	1	REAR TAILGATE STICKER '6555-3333'	\$	SH	80.00	3012
11	1	REAR BUMPER PROTECTOR	\$	SH	100.00	4012
12	1	REAR WHEEL RIM	\$	SH	1,570.55	X
13	1	REAR WHEEL RIM COVER	\$	SH	175.80	X
14	1	SPARE WHEEL RIM	\$	SH	1,570.55	X
15	1	SPARE WHEEL RIM COVER	\$	SH	175.80	X
16	1SET	FENDER WHEELARCH REAR RH CLIP	\$	SH	35.00	X

Trans-cab Auto Services Pte Ltd**AAD1910-046**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5778R

17	1	REAR TYRE 195/65/15	\$	<i>nn</i>	350.00	X
TOTAL			\$		5,337.10	
TOTAL PARTS			\$		15,349.38	

LABOUR

To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	<i>nn</i>	170.00	X
To Rust-Proofing Of The Affected Areas.	\$	<i>nn</i>	170.00	X
Putty And Spray Painting Of The Affected Portion.	\$		7,500.00	<i>6601</i>
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	<i>nn</i>	170.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		7,500.00	<i>4001</i>
To reinstall rear bumper parking sensor.	\$		170.00	<i>501</i>
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	<i>nn</i>	170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$		170.00	<i>501</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i>	220.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>nn</i>	380.00	X
To supply and re-do rear luggage floor panel insulation padding.	\$	<i>nn</i>	380.00	X

Trans-cab Auto Services Pte Ltd**AAD1910-046**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5778R

To transfer of tire, rim and on wheel balancing.	\$	170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	X
To repair and realign rear exhaust pipe.	\$	170.00	X
TOTAL	\$	18,610.00	
Over All Total	\$	33,959.38	

(PART-BY-PART) Repair Days~~25 Days~~

2 1/2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting.
- To display damaged part(s) during resurvey.
- Parts prices are subject to confirmation.
- Third party survey is on a "Without Prejudice" basis.
- No illegal modification(s) is allowed.
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company.

Acknowledged by Repairer:

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI19017785/KVF3N2

Date: 14/11/2019

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MT106893
Claimant Vehicle No :	SHD5778R	Insured Vehicle No :	SLS1343L
Date of Loss:	04/10/2019	Nature of Claim:	TP
		Claim No:	M1907853

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD5778R	Engine No:	2ZR2B92770
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Chassis No:	JTDKB3FU703078577
Reg. Date:	19/12/2018 (Man. Year: 2018)	Odometer:	63239 km
Colour:	Metallic White/Red		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	Giti 9 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Giti 9 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,349.37	2,241.05	13,108.32	85.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	18,610.00	1,180.00	17,430.00	93.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	33,959.37	3,421.05	30,538.32	89.93
+ GST 7.00/7.00% (S\$)	2,377.16	239.47	2,137.69	89.93
Nett Amount (S\$)	36,336.53	3,660.52	32,676.01	89.93

INSPECTION

Date of Assignment: 09/10/2019

Date Inspected: 08/10/2019 Inspected At:

Trans-cab Auto Services Pte Ltd (Ang Mo Kio)
2, Ang Mo Kio Street 63
Singapore 569111

Estimated Period of Repair: 2.5 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Nov 2019)
Parts:	144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD5778R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	442.60 FL	*442.60 FL
2	1		*REAR BUMPER RE-INFORCEMENT	Bent	332.70 FL	*332.70 FL
3	1		*REAR BUMPER TOWING COVER	Dented	15.40 FL	*15.40 FL
4	1		*REAR BUMPER UNDER COVER (BLACK)	Cracked	576.30 FL	*576.30 FL
5	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	116.50 FL	*- FL
6	1		*REAR BUMPER SIDE RETAINER RH	Cracked	117.70 FL	*117.70 FL
7	1		*REAR TAILGATE	Repair	1,147.80 FL	*- FL
8	1		*REAR TAILGATE OUTER GARNISH	Repair	925.60 FL	*- FL
9	1		*ANTENNA,ELECTRICAL KEY	Serviceable	72.00 FL	*- FL
10	1		*COVER,REAR COMBINATION LAMP,RH	Serviceable	64.50 FL	*- FL
11	1		*COVER,REAR COMBINATION LAMP,RH	Serviceable	64.50 FL	*- FL
12	1		*GARNISH,BACK DOOR SIDE,LH	Serviceable	95.60 FL	*- FL
13	1		*GARNISH,BACK DOOR SIDE,RH	Serviceable	95.60 FL	*- FL
14	1		*MOULDING,BACK DOOR OUTSIDE GARNISH,LOWER RH	Serviceable	56.50 FL	*- FL
15	1		*MOULDING,BACK DOOR OUTSIDE GARNISH,LOWER LH	Serviceable	56.50 FL	*- FL
16	1		*BOARD ASSY,BACK DOOR TRIM	Serviceable	259.20 FL	*- FL
17	1		*PANEL ASSY,BACK DOOR TRIM,UPPER	Serviceable	52.10 FL	*- FL
18	1		*REAR TAILGATE WEATHERSTRIP	Serviceable	372.30 FL	*- FL
19	1		*PANEL SUB-ASSY,BODY LOWER BACK	Repair	650.30 FL	*- FL
20	1		*TAILLAMP LOWER RH	Cracked	502.00 FL	*502.00 FL
21	1		*TAILLAMP UPPER RH	Cracked	451.80 FL	*451.80 FL
22	1		*REAR BUMPER SIDE RH	Mtg Cracked	123.70 FL	*123.70 FL
23	1		*REAR BUMPER SIDE LH	Serviceable	123.70 FL	*- FL
24	1		*TAILLAMP LOWER LH	Serviceable	502.00 FL	*- FL
25	1		*TAILLAMP UPPER LH	Serviceable	443.30 FL	*- FL
26	1		*REAR FENDER RH	Repair	854.80 FL	*- FL
27	1		*LINER,REAR WHEEL HOUSE,RH	Repair	139.80 FL	*- FL
28	1		*BOARD,BACK DOOR TRIM	Serviceable	225.20 FL	*- FL
29	1		*PANEL ASSY,DECK TRIM SIDE,RH	Serviceable	355.90 FL	*- FL
30	1		*PANEL ASSY,DECK TRIM SIDE,LH	Serviceable	355.90 FL	*- FL
31	1		*PANEL QUARTER WHEEL HOUSE,OUTER RH	Repair	296.20 FL	*- FL
32	1		*COVER,FLOOR UNDER,NO 1	Serviceable	175.10 FL	*- FL
33	1		*COVER,FLOOR UNDER,NO 2	Serviceable	241.90 FL	*- FL
34	1		*COVER,REAR FLOOR	Serviceable	229.90 FL	*- FL
35	1		*PANEL,REAR FLOOR	Repair	583.40 FL	*- FL
36	1		*EXTENSION,REAR FLOOR SIDE PANEL RH	Repair	78.30 FL	*- FL
37	1		*EXTENSION,REAR FLOOR PAN TO QUARTER PANEL,RH	Repair	196.50 FL	*- FL
38	1		*PIPE ASSY,EXHAUST,TAIL	Repair	1,655.40 FL	*- FL
39	1		*SUPPORT,EXHAUST PIPE,NO 4	Serviceable	49.10 FL	*- FL
40	1		*SUPPORT,EXHAUST PIPE,NO 5	Serviceable	49.10 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
41	1		*GASKET,EXHAUST PIPE	Serviceable	99.60 FL	*- FL
42	1		*TROUGH,BACK DOOR OPENING,RH	Serviceable	103.40 FL	*- FL
43	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
44	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
45	2		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
46	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS
47	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
48	1		*REAR TAILGATE TOYOTA LOGO	Necessary	47.00 FS	*47.00 FS
49	1		*REAR TAILGATE WORDING PRIUS	Necessary	52.90 FS	*52.90 FS
50	1		*REAR TAILGATE WORDING HYBRID	Necessary	53.50 FS	*53.50 FS
51	1		*REAR TAILGATE STICKER TRANC-CAB	Necessary	80.00 FS	*30.00 FS
52	1		*REAR TAILGATE STICKER 6555-3333	Necessary	80.00 FS	*30.00 FS
53	1		*REAR BUMPER PROTECTOR	Necessary	100.00 FS	*40.00 FS
54	1		*REAR WHEEL RIM	Serviceable	1,570.55 FS	*- FS
55	1		*REAR WHEEL RIM COVER	Serviceable	175.80 FS	*- FS
56	1		*SPARE WHEEL RIM	Serviceable	1,570.55 FS	*- FS
57	1		*SPARE WHEEL RIM COVER	Serviceable	175.80 FS	*- FS
58	1		*SET FENDER WHEELARCH REAR RH CLIP	Not Necessary	35.00 FS	*- FS
59	1		*REAR TYRE 195/65/15	Serviceable	350.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 18,686.80 2,881.60
 - List Item Discount on L Items 25.00/25.00% (\$\$) 3,337.43 640.55

Total Parts (\$\$) 15,349.37 2,241.05

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TRANSFER OF TAILGATE FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
2	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	7,500.00	660.00
4	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
5	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	7,500.00	400.00
6	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	50.00
7	TO TRANSFER OF REAR WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	0.00
8	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	50.00
9	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
10	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
11	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING	New	380.00	0.00
12	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING	New	170.00	0.00
13	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
14	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
15	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR	New	380.00	0.00
16	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR	New	380.00	0.00
17	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	0.00
18	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
Gross Labour Cost (\$\$)			18,610.00	1,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >