

ASSIGNMENT

Surveyor:

MARCUS

DOI:

10/10/19

Date / Time: 09/10/2019

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. : YN 1426D

Claim No. : 19/19/19/VC05/022486

Name of Insured :

DYNAMAX CONTRACTORS P/L

Policy No. :

Insured Tel No. :

HP:

Make / Model :

Excess Sec II :SS

D.O.A : 09/09/19 10:20

Place of Accident : MBS MICE OFFICE

Is driver the owner?

(YES / NO)

Nature of Accident :

If NO, Driver Name / Age :

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Driver Tel No. :

(V/L: YES / NO)

Insured Liability : %

Final ? Yes / No

GBH 9248C



INSRS: WSP: ETHOZ (T)

Tel:

Liability:

RMKS:



INSRS: WSP:

Tel:

Liability:

RMKS:



INSRS: WSP:

Tel:

Liability:

RMKS:



INSRS: WSP:

Tel:

Liability:

RMKS:

Date/ Time	GBH 9248C - X	YN 1426D - X	STAGE	DATE / PIC
			Non-Reporting ltr (1st):	
			Non-Reporting ltr (2nd):	
			Non-Reporting ltr (Final):	
			Notification ltr (if non-pickup):	
			Call OI:	
			After call ltr to OI:	
			Documentation Check List: Handler	Typist
			Notification ltr (if non-pickup):	
			After call ltr to OI:	
			Authorisation To Act:	
			Release Voucher:	
			Final Repair Bill:	
			Car Rental Invoice:	
			Towing Invoice:	
			LTA / GIA :	
			Medical Bill:	
			PIR:	
			Mandate/Reject Instruction:	
			LOD	
			Payment Breakdown Form:	
			Post-Repair Photos:	
			Others:	

PRELIMINARY ADVICE	Date/Time:	Sent By:	Confirm by:
FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost:	SS (days) Reduction:	%	Email ☐ Call ☐
FINAL SETTLEMENT	Date/Time: 13/2/2020	Confirm with: Joyce	Email ☒ Call ☐
Final Liability:	% 100 (Agreed / Assessed) BOLA S/N No. : NIL		If NO or B 28, Ass. Lia :
Repair Cost: (w/ 41)	SS 2407.50		
Loss of Rental (LOR):	SS (days)		
Loss of Use (LOU):	SS 300.00 (\$ 100 x 3 days)		
Loss of Income (LOI):	SS (\$ x days)		
LOR only ☐ LOU only ☐	LOR + LOU ☐ LOR + LOI ☐ [Tick only one]		
GIA/LTA Search	SS 2.00		
Medical:	SS -		
Disbursement:	SS - (e.g. Tow/ Independent)		
Legal Cost	SS -		
Total:	SS 2709.50	Global Sum SS:	
FINAL PAYMENT	Date/Time:	Confirm with:	Email ☐ Call ☐
Payee 1:	SS 2709.50	Name 1: Ethoz Group Ltd	
Payee 2: (Strike if N.A.)	SS	Name 2:	
Payee 3: (Strike if N.A.)	SS	Name 3:	

COPY SENT 26/02/2020

1) Claim status: Normal/Reject/Private Settle
2) Report Format: TP
3) Survey fee: 4400

Ref: **IPC**

ASSIGNMENT

From: _____ Date: **10/10/19**

Estimated Cost: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: **GBH 9248C**

at Workshop m/s: **Ethoz**

of: **22 Tampines St. 92**

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: **Morning**

OIC: **Jimmy**

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: **\$56k.**

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / BR Seen: **1** Consistent? : Yes or No

Est. Repairs: **3** days Res. Yes or No

Lum Sum: **20** % 3 Val: Yes or No

CA / REV / REP. / 24 HRS **sup** **531H**

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **GBH 9248C** Yr Regn: **11 / 18**

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or: **(M)**

Make: **Toyota hiace** cc: **2982**

Colour: **white** A/C: Insured / Std / NI / NA

Sp Reading: **37062** T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **JTFH T02 P 500246330**

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: ☒ M / S/Rim / STD A/Rim or

Tyre Size: F: **195 R15**

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or **OHTSU**

Front: **6** mm Rear: **6** mm

R/Bal: **6** mm L/Bal: **6** mm

D.O.A: **9/9/19** D.O.I: **10/10/19**

Survey held at: _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S R/L

The U/C / Chassis frame / Body Structure affected due to collision.

N/S	O/S

Date / Time Action / Instruction

27A 24791

11/10/19 2/5 @ 2250 contact with AH Kai
(Red \$4035.02 / 64%)

Date/Time, File Pass in?

☐ : Prelim. Report
☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RE = \$ _____

Phone: _____

Other: _____

TOTAL

Add Fee:

☐ Site Insp \$
☐ Interview \$
☐ Tech. Insp \$
☐ Wheel end \$

Report Format: _____

Lump Sum / P.P. \$ _____



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: 19/19/19/VC05/022486

Date: 09/10/2019

Our ref: CC4/LPC19017809/Uda3

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

GBH 9248C


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 07/10/2019 at the premises of M/s Ethoz Group Ltd - Tampines and have the following to report:-

Workshop Estimate Amount	: S\$	6,285.02
Revised Estimate Amount	: S\$	2,250.00
"Check" Items Amount	: S\$	-
Total (Including Check Items)	: S\$	2,250.00
Market Value	: S\$	- (est.)
LTA Reimbursement Value	: S\$	- (est.)
Nett Value	: S\$	- (est.)

Description of Damage:

The vehicle sustained damages at the
N/S Front Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 3.0 days

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

sgCARMART.COM

Login

Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources



ALL-NEW

Mercedes-Benz GLE450 AMG

Premium Plus

TEST DRIVE TODAY!

☎ 6250 6696 / 9637 5329



Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Renewal Coe Honda Stream 1.8A



2.58% P.A. \$0 Admin, \$2800

Down Monthly From \$598, 2

Years Warranty Engine

GV Credit Pte Ltd StarAd

Think One Automobile

NEW & USED

COMMERCIAL VEHICLES



Browse by Category

Sort by Date Posted

20 results/page

13 vehicles

Toyota Hiace

Advanced Search

Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Toyota Hiace		Any	Any	2018	Any	Any	Any	Available
	Toyota Hiace	3.0A	\$67,800	\$7,430 /yr	22-Nov-2018	2,982 cc	-	Van	Available
Fuel Type: Diesel Newly Registered! Totally Legit, GST/ARF/COE All In! Toyota Hiace 4 Doors Auto Diesel. Borneo Motors 3 Years Or 100k Km Warranty! C... ABWIN (1994) Pte Ltd Posted: 10-Oct-2019 Tags: 2018 Toyota Hiace, 2018 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota									
	Toyota Hiace	3.0M DX	-	N.A	02-Apr-2018	2,982 cc	37,488 km	Van	Available
Fuel Type: Diesel Auction Closing Time: 16th Oct 2019 at 11:00 PM With Key. This Vehicle Is Non GST Chargeable, Kindly Download The Non GST Chargeable Tender Form At This Link: https://goo.gl/FBnt... Posted: 10-Oct-2019 Tags: 2018 Toyota Hiace, 2018 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota									
	Toyota Hiace	3.0M	-	N.A	26-Sep-2018	2,982 cc	-	Van	Available
Fuel Type: Diesel Auction Closing Time: 16th Oct 2019 at 05:00 PM GST Registered. Tender Applicable To Business Entities Only. Road Tax Due Date 25 Sep 2019. Renewal Amount S\$100.00, Total Rebat... Posted: 09-Oct-2019 Tags: 2018 Toyota Hiace, 2018 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota									
	Toyota Hiace	3.0A DX	\$61,500	\$7,310 /yr	07-Mar-2018	2,982 cc	-	Van	Available
Fuel Type: Diesel Still Under Warranty, Well Taken Care By Fussy Owner And Still Looks And Feels New. Posted: 09-Oct-2019 Tags: 2018 Toyota Hiace, 2018 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota									
	Precise Auto Service - Specialist for Toyota Car repair, servicing & maintenance Your Trusted Car Workshop, a one-stop car workshop specialising in Japanese cars. More info about this shop								
	Toyota Hiace	Commuter 2.8A	\$80,800	\$8,910 /yr	01-Nov-2018	2,754 cc	-	Bus	Available
Fuel Type: Diesel (Hiace Commuter With Front Sensing) Lots Of Safety Features! Come With Lots Of Accessories, High Loan With Low Interest Rate, High... Posted: 09-Oct-2019 Tags: 2018 Toyota Hiace, 2018 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota									
	Toyota Hiace	3.0M	\$58,800	\$6,730 /yr	02-Jul-2018	2,982 cc	30,000 km	Van	Available
Fuel Type: Diesel Agent Unit. Posted: 02-Oct-2019 Tags: 2018 Toyota Hiace, 2018 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota									
	Toyota Hiace	Commuter 3.0A High Roof	\$82,800	\$9,020 /yr	12-Dec-2018	2,982 cc	6,000 km	Bus	Available
Fuel Type: Diesel Compare									

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	531H
Vehicle Details	
Vehicle No.:	GBH9248C
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Oct 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE VAN TURBO 5DR MT
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	1KD2831546
Chassis No.:	JTFHT02P500246330
Maximum Power Output:	-
Open Market Value:	\$28,136.00
Original Registration Date:	05 Nov 2018
First Registration Date:	05 Nov 2018
Transfer Count:	0
Actual ARF Paid:	\$1,407.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	04 Nov 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$27,341.00
COE Rebate Amount:	\$24,791.00
Total Rebate Amount:	\$24,791.00

The information contained herein is correct as at 10 Oct 2019

OK

PLEASE ARRANGE TO SURVEY
VEHICLE AT 22 TAMPINES ST 92 (S
528876)

Jimmy Goh KI
CLAIM DEPARTMENT
DID : 66547618
FAX :

KKK: J.A 12

Date : 09/10/2019
To : LONPAC INSURANCE BHD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : D17MTHCVE000063 Accident Date : 09/09/2019
Vehicle No : GBH-9248-C Make & Model : TOYOTA HIACE 3.0 TURBO VAN G (M) EURO

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
-----	-------------	-------------------	---------------

List Item

1	BONNET	983.40	X
1	BONNET LOGO	102.50	
1	CORNEL PANEL LH	291.20	
1	FRONT HEADLAMP LH	843.40	
1	FRONT DOOR LH	1,925.60	X
1	FRONT DOOR HINGE LH(UPPER)	121.20	X
1	FRONT DOOR HINGE LH(LOWER)	121.20	X
1	FRONT DOOR CHECKER LH	190.60	X
1	SIDE MIRROR LH	1,253.40	

not Alund

KKK
h/s 2250
327

10/10/19

Whip Ahn

P-2258.50

252
P-1692.37
S.N-340.00
L-800.00

2832.27
207
2625

Date : 09/10/2019
To : LONPAC INSURANCE BHD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
: SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : D17MTHCVE000063 Accident Date : 09/09/2019
Vehicle No : GBH-9248-C Make & Model : TOYOTA HIACE 3.0 TURBO VAN G (M) EURO

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	SIDE MIRROR GLASS LH	17 214.20	X
	Sub Total	6046.70	
	Discount 25% On Parts	(1511.67)	
	<u>Special Nett Item</u>		
1	BONNET ADVERTISEMENT STICKER <i>6 door sticker</i>	<i>net</i> 320.00	<i>✓</i>
1	FRONT DOOR LH ADVERTISEMENT STICKER	<i>net</i> 20.00	<i>✓</i>
	Sub Total	340.00	
	<u>Labour & Misc</u>		
	LABOUR TO FACILITATE REPAIR	550.00	<i>300</i>
	LABOUR TO SPRAY PAINT AFFECTED AREAS	750.00	<i>400</i>

Date : 09/10/2019
To : LONPAC INSURANCE BHD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D17MTHCVE000063 Accident Date : 09/09/2019
Vehicle No : GBH-9248-C Make & Model : TOYOTA HIACE 3.0 TURBO VAN G (M) EURO

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	30.00	20
	TO REMOVE & REFIT FRONT DOOR COMPONENT	11 80.00	X
	Sub Total	1410.00	



Remarks:

SUB TOTAL

GST 7.0 % 439.95

TOTAL 6,724.98

Surveyor's name: _____

Principal's name: ETHOZ Group Ltd

Survey Date & Time: _____


Summer Lee (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Wednesday, 9 October, 2019 1:02 PM
To: Jimmy Goh; MT_Claim_SG; assignments; Admin-D (LKKAuto)
Cc: Ng Boon Kai; Suhelmi Bin Suharman
Subject: RE: Survey for vehicle No : GBH9248C TP Claim Our Ref: 19/19/19/VC05/022486
Attachments: GBH9248G AGAINSTYN1426D.PDF

Dear Nivitha

Please arrange survey.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse
Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



From: Jimmy Goh [mailto:jimmy.gohkl@ethozgroup.com]
Sent: Wednesday, 9 October 2019 11:36 AM
To: MT_Claim_SG
Cc: Ng Boon Kai; Suhelmi Bin Suharman
Subject: Survey for vehicle No : GBH9248C TP Claim

Hi Motor Claims,

Appreciate if you could arrange survey for the above mentioned vehicle. (Vehicle in workshop)

Your insured : YN1426D

DOA : 09/09/2019

Thanks


Best Regards,
Jimmy Goh
Motor Claims Operations

ETHOZ
ETHOZ GROUP LTD

22 Tampines Street 92 Singapore 528876

DID:6654 7618 | Fax:6654 7648

Website: www.ethozgroup.com



Disclaimer: This message may contain confidential information intended only for the use of the addressee named above. If you are not the intended recipient of this message you are hereby notified that any use, dissemination, distribution or reproduction of this message is prohibited. If you received this message by mistake, please notify the sender by reply email immediately. Please conduct your own virus checks before opening any attachment as ETHOZ Group does not guarantee the integrity of this email or attached files has been maintained nor this communication is free of viruses, interceptions or interference. Any views expressed in this message are those of the individual sender and may not necessarily reflect the views of ETHOZ Group. ETHOZ Group shall not be responsible nor liable for the improper and incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system.

Mei Kwan (LKKAUTO)


From: ONG LI LI <llong@lonpac.com>
Sent: Monday, 6 January, 2020 3:19 PM
To: Mei Kwan (LKKAUTO)
Cc: MT_Claim_SG; Jia Le (LKK Auto); Admin A
Subject: RE: Survey for vehicle No : GBH9248C TP Claim Our Ref: 19/19/19/VC05/022486 [External General]
Attachments: SAS2728275.PDF
Categories: HMK

Lonpac External - General

Dear Mei Kwan

Please see attached for our Insured's GIA report.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse
Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: ONG LI LI
Sent: Friday, 6 December 2019 4:47 PM
To: 'Mei Kwan (LKKAUTO)'
Cc: MT_Claim_SG; Jia Le (LKK Auto); Admin A
Subject: RE: Survey for vehicle No : GBH9248C TP Claim Our Ref: 19/19/19/VC05/022486 [External General]

Lonpac External - General

Dear Mei Kwan

Our Insured has still not reported the accident.

We are following up on this matter.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse
Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Mei Kwan (LKKAuto) [<mailto:Meikwan@lkkauto.com>]
Sent: Thursday, 7 November 2019 1:13 PM
To: ONG LI LI
Cc: MT_Claim_SG; Jia Le (LKK Auto); Admin A
Subject: RE: Survey for vehicle No : GBH9248C TP Claim Our Ref: 19/19/19/VC05/022486

LPC ref: 19/19/19/VC05/022486
LKK REF: CC4/LPC19017809/Uda3

Dear Sir / Madam,

We refer to the above matter.

Kindly advise whether insured has reported. If so, kindly let us have a copy of insured's accident report for our necessary action.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)


From: ONG LI LI <long@lonpac.com>
Sent: Friday, 25 October, 2019 2:28 PM
To: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Cc: MT_Claim_SG <mt_claim@lonpac.com>; Jia Le (LKK Auto) <JiaLe@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: Survey for vehicle No : GBH9248C TP Claim Our Ref: 19/19/19/VC05/022486

Dear Mei Kwan

Our Insured has not reported the accident to us.

We are still following up.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse
Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



From: Mei Kwan (LKKAuto) [<mailto:Meikwan@lkkauto.com>]
Sent: Friday, 25 October 2019 11:48 AM
To: ONG LI LI
Cc: MT_Claim_SG; Jia Le (LKK Auto); Admin A
Subject: RE: Survey for vehicle No : GBH9248C TP Claim Our Ref: 19/19/19/VC05/022486

<admin-a@lkkauto.com>

Subject: RE: Survey for vehicle No : GBH9248C TP Claim Our Ref: 19/19/19/VC05/022486

Dear Mei Kwan

Our Insured has not reported the accident to us yet.

Regards,


Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse

Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



From: Mei Kwan (LKKAuto) [<mailto:Meikwan@lkkauto.com>]

Sent: Thursday, 10 October 2019 7:57 PM

To: ONG LI LI

Cc: MT_Claim_SG; Jia Le (LKK Auto); Admin A

Subject: RE: Survey for vehicle No : GBH9248C TP Claim Our Ref: 19/19/19/VC05/022486

LPC ref: 19/19/19/VC05/022486

LKK REF: CC4/LPC19017809/Uda3

Dear Sir / Madam,

We refer to the above matter.

Kindly let us have a copy of insured's accident report for our necessary action.

Please take note that the case handler in-charge is Jia Le and she can be contacted at DID: 6749 5792.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>

Sent: Wednesday, 9 October, 2019 5:29 PM

To: 'ONG LI LI' <long@lonpac.com>; assignments <assignments@lkkauto.com>

Cc: 'MT_Claim_SG' <mt_claim@lonpac.com>; Admin A <admin-a@lkkauto.com>

Subject: RE: Survey for vehicle No : GBH9248C TP Claim Our Ref: 19/19/19/VC05/022486

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,
Jimmy Goh
Motor Claims Operations

ETHOZ
ETHOZ GROUP LTD


22 Tampines Street 92 Singapore 528876

DID:6654 7618 | Fax:6654 7648

Website: www.ethozgroup.com



Disclaimer: This message may contain confidential information intended only for the use of the addressee named above. If you are not the intended recipient of this message you are hereby notified that any use, dissemination, distribution or reproduction of this message is prohibited. If you received this message by mistake, please notify the sender by reply email immediately. Please conduct your own virus checks before opening any attachment as ETHOZ Group does not guarantee the integrity of this email or attached files has been maintained nor this communication is free of viruses, interceptions or interference. Any views expressed in this message are those of the individual sender and may not necessarily reflect the views of ETHOZ Group. ETHOZ Group shall not be responsible nor liable for the improper and incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system.



This email has been checked for viruses by AVG antivirus software.
www.avg.com



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC19017809/Uda3n2

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 26-02-2020



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YN 1426D	Veh. Inspected	GBH 9248C
Policy No.	Z19VC05001698	Coverage (\$)	0.00
Claim No.	19/19/19/VC05/022486	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	09/10/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HIACE (M)	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	JTFHT02P500246330	Colour	WHITE
Odometer	37062	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15	OHTSU	6 mm
L/H Front Tyre	195 R15	OHTSU	6 mm
R/H Rear Tyre	195 R15	OHTSU	6 mm
L/H Rear Tyre	195 R15	OHTSU	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	09/09/2019	Inspection Date	10/10/2019
Survey held at	ETHOZ GROUP LTD 22 TAMPINES STREET 92 SINGAPORE 528876		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBH 9248C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BONNET	TO REPAIR SEE LABOUR	983.40	-
1	BONNET LOGO	NECESSARY	102.50	68.80
1	CORNEL PANEL LH	BADLY DENTED	291.20	291.20
1	FRONT HEADLAMP LH	SCRATCHED	843.40	843.40
1	FRONT DOOR LH	TO REPAIR SEE LABOUR	1,925.60	-
1	FRONT DOOR HINGE LH (UPPER)	NOT NECESSARY	121.20	-
1	FRONT DOOR HINGE LH (LOWER)	NOT NECESSARY	121.20	-
1	FRONT DOOR CHECKER LH	NOT NECESSARY	190.60	-
1	SIDE MIRROR LH	CUT	1,253.40	1,053.10
1	SIDE MIRROR GLASS LH	NOT NECESSARY	214.20	-
	LESS 25% DISCOUNT		-1,511.68	-564.13
			4,535.02	1,692.37
	<u>SPECIAL NETT ITEMS</u>			
1	BONNET ADVERTISEMENT STICKER & DOOR STICKER (SN)	NECESSARY	320.00	320.00
1	FRONT DOOR LH ADVERTISEMENT STICKER (SN)	NECESSARY	20.00	20.00
			340.00	340.00
	<u>LABOUR</u>			
	LABOUR TO FACILITATE REPAIR.INCLUSIVE OF THE REPAIR OF BONNET AND FRONT DOOR LH.		550.00	300.00
	LABOUR TO SPRAY PAINT AFFECTED AREAS.		750.00	480.00
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS.		30.00	20.00
	TO REMOVE & REFIT FRONT DOOR COMPONENT.	NOT NECESSARY	80.00	-
	-		-	-
	-		-	-
	-		-	-
			1,410.00	800.00
	GRAND TOTAL		6,285.02	2,832.37

Report Ref No. CC4/LPC19017809/Uda3n2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,250.00
---	--	--	----------

Report Ref No. CC4/LPC19017809/Uda3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.