

ASS. REC. BY:

REF:

03/SMO/19017836/Hcd36h

Special Instruction:

Surveyor: Hock Ann

ASSIGNMENT (Office)

From (Person): Anoh Pui Lung

of

SMO

Date/Time:

9/10/19 @ 11:30 am

Estimated Cost:

Bill to:

OD - TP - WS - TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJS 8630K

Insured:

SKR 81242

at Workshop m/s

Mylar Consultant

Tel:

9858 6006

of

53 ubi Ave 1 # 01-33

Policy No:

D19MTPV0101793

Claim No:

CMTD1904726

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

6/10/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12:17pm @ 9/10/19

Person Contacted:

Kai ling

Vehicle IN OUT

Date/Time

Action/Instruction

Tehmoll ✓

SJS 8630K - NA / INC 19017579/24

JVA: 6/10/2019

SKR 81242 - X

PRS case

17/10 2:30pm

Niritha spoken to Kai ling, they confirm this is PRS case.  
They had engaged independent surveyor.

ASS. REG. BY:

H. ANN

REF:

SMO

PRS

## ASSIGNMENT

From:

Date:

9/10/2019

Estimated Cost:

OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV

To Inspect Vehicle No:

SJS 8630K

at Workshop m/s

MyCar Consultant

of

53 ubi Avenue 1 # 01-33

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

251K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

80

days

Res.: Yes or No

Lum Sum:

10

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

mp

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SJS 8630K

Yr Regn:

11/09/2009

Type: ☒ M.Car ☐ M.Cycle ☐ Bus ☐ Van ☐ Lorry ☐ Taxi ☐ Prime Mover ☐

Truck / Trailer or

Make:

PERODUA MYVI 1.6 AT

C.C. 1298

Colour:

Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

104490km

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

PM2M3015002316536

Gen. Cond: ☒ Good ☐ Fair ☐ Poor ☐ BurntSteering: ☒ Inorder ☐ Jammed ☐ Leaked ☐ Burnt orBrake: ☒ Inorder ☐ Jammed ☐ Leaked ☐ Burnt orModi: Nil ☒ S/Rim ☐ STD A/Rim or

Tyre Size:

F:

175/65/R14

R:

175/65/R14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

5

mm

Rear

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

6/10/19

D.O.I.

9/10/19

'Survey held at

my car con

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Bismah survey: 10/10/19

After paina: 11/10/19

MV - 25000

PV - 14369

NV - 10600

Submit PRS.

repair days - 4/10/19

Range - 3-4K

# SJS 8630K 110V

Ex-emplar (PRS) case

RECEIVED 2 OCT 2019

15/10/2019

Date/Time, File Pass to?



: Preli. Report

1) 27/10/2019



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Insp (\$)



: Weekend (\$)

Survey Fee:

Transportation:

S + PRS \$1

Photos

Other:

TOTAL

100

60

60

11

231

Report Form:

PRS.

Lump Sum / U/C: \$

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Oct 2019		09 Oct 2019 11:31 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

#### CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	LUM KEE KONG, ID: S1496289A, Tel: +6596668568			
Main Claimant:	HUANG XIONG JIE			
Vehicle Reg. No.:	SJS8630K	Date of Loss:	06/10/2019 17:00 - :59	
Claim Type:	TP / CMTD1904726	Policy/Cover Note No.:	D19MTPV01011793 (Comprehensive)	
Vehicle Reg. No. (Insured):	SKR8124Z	Policy No. (Claimant):		
		Excess:		
Repairer:	My Car Consultant Pte Ltd (Ubi) 53 Ubi Ave 1, #01-33, Paya Ubi Industrial Park, 408934 Ubi - Tel:			
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 18/10/2019]			
Driver/Custodian (Insured):	LUM KOK FAI ANDY (), NRIC: S9225645F, Tel: +6591709821 Email: -			

#### ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

#### ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	751I
Vehicle Details	
Vehicle No.:	SJS8630K
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Oct 2019
Vehicle Make:	PERODUA
Vehicle Model:	MYVI EZI 1.3L AT 2WD 5DR
Primary Colour:	Grey
Manufacturing Year:	2009
Engine No.:	E11B41P
Chassis No.:	PM2M301S002316536
Maximum Power Output:	64.0 kW (85 bhp)
Open Market Value:	\$8,553.00
Original Registration Date:	11 Sep 2009
First Registration Date:	11 Sep 2009
Transfer Count:	2
Actual ARF Paid:	\$8,553.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Aug 2024
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$14,664.00
COE Rebate Amount:	\$14,309.00
<b>Total Rebate Amount:</b>	<b>\$14,309.00</b>
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 14 Oct 2019

OK

## Enquire Vehicle Transfer Fee

### Vehicle Details

Vehicle No.  
SJS8630K

Make / Model  
PERODUA / MYVI EZI 1.3LAT 2WD SDR

Vehicle Type:  
Z10 - Private Hire (Chauffeur) Motor Car

Vehicle Scheme:  
Normal

Propellant:  
Petrol

Motor No.:  
-

Power Rating:  
-

Maximum Laden Weight:  
1015 kg

Year Of Manufacture:  
2009

Lifespan Expiry Date:  
-

PQP Paid:  
\$14,664.00

Road Tax Expiry Date:  
10 Mar 2020

Inspection Due Date:  
10 Sep 2020

CO2 Emission:  
-

CO Emission:  
-

NOx Emission:  
-

Vehicle Attachment 1:  
No Attachment

Chassis No.:  
PM2M301S002316536

Engine No.:  
E11B41P

Engine Capacity:  
1298 cc

Maximum Power Output:  
64.0 kW (85 bhp)

Unladen Weight:  
955 kg

Original Registration Date:  
11 Sep 2009

COE Category:  
A - Car (1600cc & below)

COE Expiry Date:  
31 Aug 2024

PARF Eligibility Expiry Date:  
-

Intended Transfer Date:  
14 Oct 2019

CEV/VES Rebate Utilised Amount:  
-

HC Emission:  
-

PM Emission:  
-

### Fees To Be Paid For Transfer

Transfer Fees

\$25.00

### Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

DOA - 6/10/19

Print

OK →

Save as PDF

Copy as Text

MV - 25000  
PV - 14309  
NV - 10600  
MV - 2512

- New Cars
- Used Cars
- Sell My Car
- Directory
- Products
- Insurance
- Articles
- Forum
- Resources



Perodua Myvi Price Range Depreciation 2010 Vehicle Type

Advanced Search

Home » Used Cars » Ocean Motoring » Perodua Myvi 1.3A EZI (New 5-yr COE)

## Perodua Myvi 1.3A EZI (New 5-yr COE)

Overview Financial Insurance Accessories Similar Research Photos Map

Price	\$28,800		
Depreciation	\$5,750 /yr	Reg Date	22-Jan-2010 (5yrs COE left)
Mileage	94,000 km (9.7k /yr)	Manufactured	2009
Road Tax	\$566 /yr	Transmission	Auto
Dereg Value	N.A.	OMV	\$8,286
COE	N.A.	ARF	\$8,286
Engine Cap	1,298 cc	Power	54.0 kW (85 bhp)
Curb Weight	955 kg	No. of Owners	1
Type of Vehicle	Hatchback		



Shortlist Compare Add note  
Report Error More Actions

### Features

View specs of the Perodua Myvi (2009-2015)

### Description

1 Owner, Low Mileage Done At 94000km, Service By Autobacs, Neat And Clean Interior, Bank Or In-House Loan Available, Test Drive Welcome.

### Category

COE Car, Low Mileage Car

### Status

Available

### Resources



Car Valuation - Free  
Find out the market value of your existing car for free. Get started



Vehicle Evaluation  
Afraid of lemons? Request to have this car evaluated professionally. Find out more

### Seller Information

Company	Ocean Motoring
	• dealer's picket • 8 vehs sold   7 vehs available
Address	210 Turf Club Road Lot C19A Search cars nearby this location
Location	Car Mall @ The Grandstand
Contact Person(s)	Jason 90489293 Chan 90021531

Posted on: 13-Oct-2019 | Last Updated on: 13-Oct-2019

### Upfront Payment

• more Financial info

Transfer Fee	\$25	
Down Payment	\$8,640 (change)	Maximum 70% Loan
1st Instalment	\$399	Based on 3.75% interest rate
Insurance	\$941 onwards Not at fault? No upfront payment required! (Get a quote) Quoted amounts is standard profile. "Get a quote" for exact figure.	
Total Upfront Payment	\$10,005	Check with seller for exact figure



### Products and Services

• View All



For all your leasing and rental needs.



Door Visor



Scuff Plate



TA Car Mat

Compare



Bitrid Carplate for Sale

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	07/10/2019 12:15
Date Of Accident	06/10/2019 17:30
Exact Location Of Accident	CTE (AYE) AFTER YIO CHU KANG RD EXIT
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJS8630K
<b>Insured/Policyholder</b>	
Name Of Registered Owner	HUANG XIONG JIE
NRIC No	S85347511
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96945472
Alternative Phone No	OFFICE-96945472

### Vehicle Particulars

Manufacturer	PERODUA
Model	MYVI EZI 1.3L AT 2WD 5DR
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5111681974
Cover Note Number	

### Driver

Name of Driver	HUANG XIONGJIE
NRIC No	S85347511
Date Of Birth	17/11/1985
Occupation	OUTDOOR
Date Of Driving Pass	12/03/2007
Driving Experience	12 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96945472
Fax Number	
Contact Number	OFFICE-96945472
EMail Address	NOEMAIL

Address	BLK 24 HOUGANG AVENUE 3 #05-422
Postcode	530024
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : LIM KAI YING GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ - SINGAPORE CITY
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO POLICE REPORT - T/20191006/7014.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLB1913G
Vehicle Make/Model/Colour	TOYOTA HARRIER
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	



Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SKR8124Z  
Vehicle Make/Model/Colour NISSAN SYLPHY  
Details Of Properties  
Vehicle Category PRIVATE CAR  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

#### DETAILS OF INJURED PERSON 1

Name HUANG XIONGJIE  
Approximate Age  
Injuries Sustain BODY  
Injured person in which vehicle? SJS8630K  
Were seat belts worn? YES  
Was this injured conveyed to hospital by ambulance? NO  
Address  
Postcode

#### DETAILS OF INJURED PERSON 2

Name LIM KAI YING  
Approximate Age  
Injuries Sustain BODY  
Injured person in which vehicle? SJS8630K  
Were seat belts worn? YES  
Was this injured conveyed to hospital by ambulance? NO  
Address  
Postcode

## Accident Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Dealer.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to cancel its policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false report may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be situated outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (a) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Person's Signature  
Name:  
NRIC/FIN No.:

# Accident Sketch Plan

SKETCH PLAN

Vehicle A  
- JJS 8630K

Vehicle B  
- SLB 1913G

Vehicle C  
- SEE 8124Z

CTE  
TOWARDS AYB  
AFTER YIO CHU  
PANG  
EXIT

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO POLICE REPORT

## DECLARATION

I/We declare the foregoing particulars are true in every particular.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Person's Signature  
Name:  
NRIC/PIN No.:

# Police Report



**SINGAPORE  
POLICE FORCE**



T/20191006/7014

1 of 3

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

Report No. T/20191006/7014

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 06/10/2019 21:21		Vide Report No.:		Station Diary No.:	
<b>Informant's Particulars</b>					
Name of Informant: HUANG XIONGJIE			Address: APT BLK 24 HOUGANG AVENUE 3 #05-422 SINGAPORE 530024		
ID Type / ID No.: NRIC NO / S85347511			Contact No.: Home/Office:		Mobile: 96945472
Nationality: SINGAPORE CITIZEN			Email: stanley.huang.xiongjie@gmail.com		
Sex: Male	Age: 33	Date of Birth: 17/11/1985	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Operations officer (except transport operations)			Driving Licence Information: Class: 3		Date of Expiry:

<b>General Information of the Accident</b>				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 06/10/2019 17:30	Type of Location: Bend
Location: SELETAR EXPRESSWAY				
Weather: After rain		Road Surface: Wet		Road Speed Limit: 80 Km/h
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJS8630K	Car	PERODUA	MYVI EZI 1.3L AT 2WD 5DR	Blue	Seriously Damaged	1
SKR8124Z	Car					0
SLB1913G	Car					0

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date

Scanned by CamScanner

## Police Report



**SINGAPORE  
POLICE FORCE**



T/20191006/7014

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408665  
Tel No: 65470000

2 of 3

Report No: T/20191006/7014

## CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
SJS5630K	NTUC Income Insurance Co-Operative Limited	5111681974	07/02/2019	06/02/2020

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Passenger			
Name	LIM KAI YING	ID No.	S8984556D
Related Vehicle	SJS5630K (Car)	Contact No.	NIL
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	06/10/2019	Date Discharge	06/10/2019
No. of Days granted Medical Leave	06	Degree of Injury	Slight
Driver			
Name	HUANG XIONGJIE	ID No.	S8534751I
Related Vehicle	SJS5630K (Car)	Contact No.	96945472
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	06/10/2019	Date Discharge	06/10/2019
No. of Days granted Medical Leave	05	Degree of Injury	Slight

## Brief Details.

On the stated date and time, I was travelling along CTE towards AYE after Yio Chu Kang Road exit on Lane 1. Suddenly the vehicle in front of me slow down and stopped. I follow suit. All of sudden I felt a one huge impact from the rear, followed by another second impact. I alighted from my vehicle and realise that vehicle SLB1913G has collided onto my rear and swerve to lane 2 (1st impact). Then vehicle SKR8124Z collided directly on my rear (2nd impact) causing severe damages to my vehicle. I wish to state that my wife Lim Kai Ying (S8984556D) is in the car with me. Both me & her felt pain and discomfort after the accident and consulted a doctor at Mount Alvernia hospital. She was subsequently referred to KK women's and children hospital as she is pregnant. I'm given 5 days mc and my wife is given 6 days mc.

Police Report



**SINGAPORE  
POLICE FORCE**

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000



T/20191006/7014

3 of 3

Report No. T/20191006/7014

**CONTINUATION OF REPORT**

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:  
Not applicable

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:  
TP / TPHQ /  
WONG SIEU LUI  
Contact No.: 65476151

Authentication Stamp  
NP168

Signature Of Informant:  
The identity of the person making this report has  
been authenticated by SingPass. No signature is  
required.

Date/Time:  
06/10/2019 21:21

Classification Of Case:

Scanned by CamScanner

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Oct 2019		09 Oct 2019 11:31 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>






























Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured: <b>LUM KEE KONG</b> , ID: S1496289A, Tel: +6596668568									
Main Claimant: <b>HUANG XIONG JIE</b>									
Vehicle Reg. No.: <b>SJS8630K</b>		Date of Loss: 06/10/2019 17:00 - :59 [120 Months and 25 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP / CMTD1904726</b>		Policy/Cover Note No.: D19MTPV01011793 (Comprehensive)							
Vehicle Reg. No. (Insured): <b>SKR8124Z</b>		Policy No. (Claimant):							
		Excess:							
Repairer: <b>My Car Consultant Pte Ltd (Ubi)</b> 53 Ubi Ave 1, #01-33, Paya Ubi Industrial Park, 408934 Ubi - Tel:									
Handling Insurer: <b>Sompo Insurance Singapore Pte. Ltd. (HQ)</b> - Tel: 6461 6555 ... [Handled by <b>GNOH PAU LOONG</b> - 63295217]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>LEE HOCK ANN</b> ] ... [Final Rpt due 18/10/2019]									
Driver/Custodian (Insured): LUM KOK FAI ANDY (), NRIC: S9225645F, Tel: +6591709821 Email:									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SJS8630K (CMTD1904726)  
[SKR8124Z]  
TP  
HUANG XIONG JIE  
Oct 6 2019 5:00PM  
[LUM KEE KONG]  
My Car Consultant Pte Ltd

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/10/19 08:27	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
2	15/10/19 08:28	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
3	15/10/19 08:29	General View	Load JPG	<input checked="" type="checkbox"/>
4	15/10/19 08:29	General View	Load JPG	<input checked="" type="checkbox"/>
5	15/10/19 08:29	General View	Load JPG	<input checked="" type="checkbox"/>
6	15/10/19 08:29	General View	Load JPG	<input checked="" type="checkbox"/>
7	15/10/19 08:29	General View	Load JPG	<input checked="" type="checkbox"/>
8	15/10/19 08:29	General View	Load JPG	<input checked="" type="checkbox"/>
9	15/10/19 08:29	General View	Load JPG	<input checked="" type="checkbox"/>
10	15/10/19 08:29	General View	Load JPG	<input checked="" type="checkbox"/>
11	15/10/19 08:29	General View	Load JPG	<input checked="" type="checkbox"/>
12	15/10/19 08:29	General View	Load JPG	<input checked="" type="checkbox"/>
13	15/10/19 08:29	General View	Load JPG	<input checked="" type="checkbox"/>
14	15/10/19 08:29	General View	Load JPG	<input checked="" type="checkbox"/>
15	15/10/19 08:29	General View	Load JPG	<input checked="" type="checkbox"/>
16	15/10/19 08:29	General View	Load JPG	<input checked="" type="checkbox"/>
17	15/10/19 08:29	General View	Load JPG	<input checked="" type="checkbox"/>
18	15/10/19 08:29	General View	Load JPG	<input checked="" type="checkbox"/>
19	15/10/19 08:29	General View	Load JPG	<input checked="" type="checkbox"/>
20	15/10/19 08:29	General View	Load JPG	<input checked="" type="checkbox"/>
21	15/10/19 08:29	General View	Load JPG	<input checked="" type="checkbox"/>
22	15/10/19 08:29	General View	Load JPG	<input checked="" type="checkbox"/>
23	15/10/19 08:29	General View	Load JPG	<input checked="" type="checkbox"/>
24	15/10/19 08:29	General View	Load JPG	<input checked="" type="checkbox"/>
25	15/10/19 08:29	General View	Load JPG	<input checked="" type="checkbox"/>
26	15/10/19 08:29	General View	Load JPG	<input checked="" type="checkbox"/>
27	15/10/19 08:29	General View	Load JPG	<input checked="" type="checkbox"/>
28	15/10/19 08:29	General View	Load JPG	<input checked="" type="checkbox"/>
29	15/10/19 08:29	General View	Load JPG	<input checked="" type="checkbox"/>
30	15/10/19 08:29	General View	Load JPG	<input checked="" type="checkbox"/>
31	15/10/19 08:29	General View	Load JPG	<input checked="" type="checkbox"/>
32	15/10/19 08:29	General View	Load JPG	<input checked="" type="checkbox"/>
33	15/10/19 08:29	General View	Load JPG	<input checked="" type="checkbox"/>
34	15/10/19 08:29	General View	Load JPG	<input checked="" type="checkbox"/>
35	15/10/19 08:29	General View	Load JPG	<input checked="" type="checkbox"/>
36	15/10/19 08:33	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
37	15/10/19 08:33	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
38	15/10/19 08:33	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
39	15/10/19 08:33	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
40	15/10/19 08:33	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
41	15/10/19 08:33	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
42	15/10/19 08:33	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
43	15/10/19 08:33	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>



Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	15/10/19 08:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	15/10/19 08:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	15/10/19 08:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	15/10/19 08:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	15/10/19 08:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	15/10/19 08:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	15/10/19 08:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	15/10/19 08:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	15/10/19 08:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	15/10/19 08:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	15/10/19 08:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	15/10/19 08:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	15/10/19 08:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	15/10/19 08:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	15/10/19 08:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	15/10/19 08:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	15/10/19 08:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	15/10/19 08:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	15/10/19 08:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	15/10/19 08:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	15/10/19 08:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	15/10/19 08:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	15/10/19 08:36	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
67	15/10/19 08:36	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
68	15/10/19 08:36	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
69	15/10/19 08:36	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
70	15/10/19 08:36	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	09/10/19 11:33	Pre-Repair Survey--MY CAR CONSULTANT ACK/AGREE LKK	 Load PDF	
2	09/10/19 11:33	Third Party E-filed GIA report	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/SMO19017836/HCD3E2

Date: 23/10/2019

## REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D19MTPV01011793
Claimant Vehicle No :	SJS8630K	Insured Vehicle No :	SKR8124Z
Date of Loss:	06/10/2019	Nature of Claim:	TP
		Claim No:	CMTD1904726

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	<b>SJS8630K</b>		
Make & Model:	PERODUA MYVI, 1.3 EZI AT 2WD 5DR (A)	Engine No:	E11B41P
Reg. Date:	11/09/2009 (Man. Year: 2009)	Chassis No:	PM2M301S002316536
Colour:	Grey	Odometer:	104490 km
Engine Capacity:	1298 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	175/65 R14	Rear Tyre Size:	175/65 R14
Front Left Side:	Firenza 5 mm	Rear Left Side:	Firenza 5 mm
Front Right Side:	Firenza 5 mm	Rear Right Side:	Firenza 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment:	09/10/2019	
Date Inspected:	09/10/2019 Inspected At:	My Car Consultant Pte Ltd (Ubi) 53 Ubi Ave 1, #01-33, Paya Ubi Industrial Park Singapore 408934
Estimated Period of Repair:	4.0 days	

Adjuster: LEE HOCK ANN

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 - \$4,000.00

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 23 Oct 2019)

**Parts:** 144      PERODUA MYVI 1.3 EZI AT 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SJS8630K)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >