

Access:

A.C. REP. BY:

REP: CS/AWA19017841/Kad3n2

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Hew Lee Fong

of AWAC

Date/Time: 9/10/19 @ 10:52am

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHD 587GR

Insured: FBQ 3021 G

at Workshop n/s - trans-cab

Tel: 62876666

of No. 2 Amk St. 63

Policy No: AVFMSBD000591904

Claim No: NSV1900501/SG

Sum Insured:

Excess:

Make of Veh:

D.O.A. 6/10/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 11:21am @ 9/10/19

Person Contacted: zhewei

Vehicle IN/OUT

Date/Time	Action/Instruction
	Initial <input checked="" type="checkbox"/>
	SHD 587GR - CS / AWA19017841 / Kad3n2
	FBQ 3021 G - X

D.O.A. 15/9/2019

ASS. REC. BY:

REF: /HWB/CS/AWA 19017841/kq d3

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s: Trans Cab

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Vsh: _____

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 1.31 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: S1405876R Yr Regn: 01, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry (Taxi) Prime Mover /

Truck / Traller or

Make: Toyota Prius cc 1798

Colour M.P. White 1st A/C: Insured / Std / NI / NA

Sp. Reading 117912 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKB3FU803079270

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/R/Im / STD / R/Im or

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Pailun

Front

Rear

R/Bal. 9 mm

R/Bal. 9 mm

L/Bal. 9 mm

L/Bal. 9 mm

D.O.A. 6/10/19


D.O.I. 24/3/2020

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

C/S 1st

The U/C / Chassis frame / Body Structure affected due to collision.



RECEIVED 26 MAR 2020

Date/Time, File Pass to?

26/3/2020

: Prel. Report

: Final Report

Date/Time, File Return to?

Days Of Repair: 4

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S - RS - SI

Fuel

Others

TOTAL

250

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech Invs (\$)

: Weekend (\$)

Report Format :

Lump Sum / I.B.I: (\$)

Nivitha (LKK Auto)

From: Hew, Lee Fong <LeeFong.Hew@awac.com> on behalf of Motorsurvey <Motorsurvey@awac.com>
Sent: Wednesday, 9 October 2019 10:52 AM
To: 'assignments@lkkauto.com'
Cc: 'Candy Kong'; 'Zhe Wei'; 'sur@lkkauto.com'
Subject: TP Survey assignment for SHD5876R DOA: 06.10.2019 Our ref: NSV1900501/SG

The above captioned accident refers.

Pursuant to the Practice Directions Amendment No. 1 of 2016 which was effective on 1 April 2016, we like to advise that the third party claimant and us **do have** consensus in the appointment of **Mr Kenneth Kong** as the Single Joint Expert to conduct the pre-repair survey of the third party claimant's vehicle.

Please conduct "THIRD PARTY" survey on without prejudice basis. The information as are follows:

3 rd Party Vehicle	:	SHD 5876 R
Insured Vehicle	:	FBQ 3021 G
Policy Number	:	AVFMSB0000591904
Name of Workshop	:	TRANS-CAB AUTO SERVICES PTE LTD
Contact Number	:	6287 6666
Person to Contact	:	MR KEK ZHEWEI
Estimated Cost of repairs	:	\$ 19,983.00

Regards,
Claims Division

Copy to TRANS-CAB AUTO SERVICES PTE LTD (Your Ref: SHD5876R) via Email.

Note -

- (x)
1. This is to keep you informed that we have appointed surveyors to conduct inspection to your client's damaged vehicle on a without prejudice basis.
 2. **Please keep our motor surveyor and us informed so as to enable the surveyor to conduct a post repair inspection once your client's vehicle has been repaired and before returning the repaired vehicle to your customer.**
 3. Please quantify your client's claim with all relevant supporting documents once your client's vehicle has been repaired.
 4. Please do not construe this appointment of surveyor and our above request as an admission of liability.

The information contained in this e-mail and any attachments hereto is confidential. If you are not the intended recipient, you must not use or disseminate any of this information. If you have received this e-mail in error, please immediately notify the sender by reply e-mail and permanently delete the original e-mail

(and any attachments hereto) and any copies or printouts thereof. Although this e-mail and any attachments hereto are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by Allied World Assurance Company Holdings, Ltd or its subsidiaries or affiliates, either jointly or severally, for any loss or damage arising in any way from its use.

Shiau Chan (LKKAuto)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Wednesday, 25 March 2020 3:33 PM
To: Shiau Chan (LKKAuto)
Cc: 'claims'
Subject: FW: TP VEHICLE SHD 5876R (DOA: 06/10/2019) -- AAD1910-040
Attachments: SHD5876 EST.pdf

Without prejudice

Dear Shiau Chan

Amount confirmed \$ 2,814.01 (before GST).

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**

TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63
Singapore 569111
Tel: 6287 6666 Fax: 6287 7764

From: Shiau Chan (LKKAuto) [mailto:siewsc@lkkauto.com]
Sent: Wednesday, 25 March, 2020 1:59 PM
To: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Subject: RE: TP VEHICLE SHD 5876R (DOA: 06/10/2019) -- AAD1910-040

Dear Wai Yin,

As per your requested.

Best Regards,
Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Wednesday, 25 March 2020 1:32 PM
To: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Subject: RE: TP VEHICLE SHD 5876R (DOA: 06/10/2019) -- AAD1910-040

Without prejudice

Dear Shiau Chan

I can't find the estimate marking, can forward me a copy? ->_->

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**

TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63
Singapore 569111
Tel: 6287 6666 Fax: 6287 7764

From: Shiau Chan (LKKAuto) [<mailto:siewsc@lkkauto.com>]
Sent: Wednesday, 25 March, 2020 12:09 PM
To: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Subject: TP VEHICLE SHD 5876R (DOA: 06/10/2019)


Dear Wai Yin,

WITHOUT PREJUDICE

Based on our surveyor's marking estimate, the calculation of repair cost will be at final fig \$2,814.01 before GST and 4 repair days.

Kindly check.

Best Regards,
Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



This email has been checked for viruses by AVG antivirus software.
www.avg.com

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	878K
Vehicle Details	
Vehicle No.:	SHD5876R
Vehicle to be Exported:	Yes
Intended Deregistration Date:	07 Oct 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS 5DR HATCHBACK (AUTO)
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	2ZR2B99847
Chassis No.:	JTDKB3FU803079270
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,605.00
Original Registration Date:	17 Jan 2019
First Registration Date:	17 Jan 2019
Transfer Count:	0
Actual ARF Paid:	\$14,247.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Jan 2027
PARF Rebate Amount:	\$10,685.00
Intended COE Rebate Details	
COE Expiry Date:	16 Jan 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$20,838.00
COE Rebate Amount:	\$16,670.00
Total Rebate Amount:	\$27,355.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 07 Oct 2019.

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/10/2019 08:55
Date Of Accident	06/10/2019 03:00
Exact Location Of Accident	YUNG HO ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD5876R
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS-1.8 HYBRID CVT (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VFX/P1680520
Cover Note Number	

Driver

Name of Driver	NEO TIANG JEE
NRIC No	S0157828F
Date Of Birth	25/09/1952
Occupation	OUTDOOR
Date Of Driving Pass	13/04/1977
Driving Experience	42 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98979390
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	13C LIM TUA TOW ROAD
Postcode	547736
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	JURONG NPP
Police Station Address:	ROAD: 158 YUNG LOH ROAD #01-58 , POSTCODE: 610158 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT T/20191006/2067

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBQ3021G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	



No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Zhang

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report T/20191026/2067.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Zhai
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Police Station Of Origin:
Jurong NPP
158 Yung Loh Road #01-58 SINGAPORE
610158
Tel No: 1800-2659999

Report No. T/20191006/2067

CONTINUATION OF REPORT

Driver			
Name	NEO TIANG JEE	ID No.	S0157828F
Related Vehicle	SHD5876R (Car)	Contact No.	98979390
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3,4 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 6/10/19, around 0300hrs, I was driving V1) SHD5876R along Yung Ho Rd, travelling at the right most lane. Subsequently, V2) FBQ3021G, squeezed in on V1's right and in the process, side swiped V1 and caused damage to V1's rear right portion, above the rear right tyre. Initially V2 did not stop even after I sounded my horn thus I followed V2 into Taman Jurong McDonalds, and stopped V2. The rider of V2 said that it was not his responsibility as it was a rental, refused to exchange particulars and asked me to go to the McDonalds office. I then proceeded to do so, and was advised by the duty manager of Taman Jurong Superbowl Mcdonalds, Ainum, to lodge a report.



**SINGAPORE
POLICE FORCE**



T/20191006/2067

Police Station Of Origin:
Jurong NPP
158 Yung Loh Road #01-58 SINGAPORE
610158
Tel No: 1800-2659999

3 of 3

Report No. T/20191006/2067


CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: J / Staff Sgt MUHAMMAD ZHARIF BIN ZAINUDIN
Signature Of Interpreter: Not applicable
Officer In Charge Of Case: TP / HRT / Sr Staff Sgt TAN JEOK LENG Contact No.: 65476144

Signature Of Informant: 
Date/Time: 06/10/2019 13:28
Classification Of Case:

SN 124



Signature : _____

Singapore Police Force

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5876R

AAD1910-040

*NOT Notified
Return by paint
8 2 8 1 4 0 1*

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model: *24 MAR 2020*
Date of Accident :
Third Party Insurer :
Date of Registration :

SHD 5876R
JTDKB3FU803079270
TOYOTA
PRIUS
6.10.19
Allied
17/1/2019

PART		LIST	
1	1	MOULDING ASSY, BODY ROCKER PANEL, RH	\$ <i>Sm</i> 594.80 X
2	1	REAR FENDER RH	\$ <i>R</i> 854.80 ✓
3	1	REAR FENDER LINER	\$ <i>Sm</i> 139.80
4	1	REAR BUMPER	\$ <i>R</i> 442.60
5	1	REAR BUMPER RE-INFORCEMENT	\$ <i>R</i> 332.70
6	1	REAR BUMPER TOWING COVER	\$ <i>Sm</i> 15.40
7	1	REAR BUMPER UNDER COVER (BLACK)	\$ <i>Sm</i> 576.30
8	1	REAR BUMPER SIDE RETAINER RH	\$ <i>Sm</i> 117.70
9	1	TAILLAMP LOWER RH	\$ <i>Sm</i> 502.00
10	1	TAILLAMP UPPER RH	\$ <i>Sm</i> 451.80
11	1	REAR BUMPER SIDE RH	\$ <i>Sm</i> 123.70
12	1	REAR TAILGATE	\$ <i>R</i> 1,147.80
13	1	PANEL SUB-ASSY, REAR DOOR, RH	\$ <i>R</i> 1,281.70
14	1	LOCK ASSY, REAR DOOR W/MOTOR, RH	\$ <i>Sm</i> 561.90
TOTAL		\$ 7,143.00	
25%		\$ 1,785.75	
		\$ 5,357.25	

Special Nett

1	1	REAR DOOR STICKER '6555-3333'	\$ <i>na</i> 80.00 X
2	1	REAR RIGHT WHEEL RIM <i>→ 256</i>	\$ <i>Ad</i> 1,570.55 ✓
3	1	REAR RIGHT WHEEL RIM COVER	\$ <i>Sm</i> 175.80 X
4	1	SET PARKING AID	\$ <i>Sm</i> 700.00 X
5	1	SET REAR BUMPER CLIP	\$ <i>na</i> 66.00 X
6	1	REAR BUMPER PROTECTOR	\$ <i>Sm</i> 100.00 X
7	2	REAR WINDSCREEN SEALANT	\$ <i>na</i> 80.00 <i>30sm</i>
8	1	WINDSCREEN MOULDING	\$ <i>na</i> 100.00 X

Trans-cab Auto Services Pte Ltd

AAD1910-040

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5876R

9	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i>	100.00	X
10	1	REAR TAILGATE TOYOTA LOGO	\$	<i>na</i>	47.00	X
11	1	REAR TAILGATE WORDING 'PRIUS'	\$	<i>na</i>	52.90	X
12	1	REAR TAILGATE WORDING 'HYBRID'	\$	<i>na</i>	53.50	X
13	1	REAR TAILGATE STICKER 'TRANS-CAB'	\$	<i>na</i>	80.00	X
14	1	REAR TAILGATE STICKER '6555-3333'	\$	<i>na</i>	80.00	X
TOTAL			\$		3,285.75	

TOTAL PARTS	\$	8,643.00
--------------------	-----------	-----------------

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	4,500.00	<i>2201</i>
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	<i>na</i> 170.00	X
To transfer of tire, rim and on wheel balancing.	\$	170.00	<i>201</i>
To check steering geometry and computer wheel alignment	\$	220.00	X
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	170.00	X
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	170.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,500.00	<i>6001</i>
To transfer of Rear Fender fittings, attachments and perform water seepage test.	\$	170.00	<i>* 801</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>na</i> 380.00	X

Trans-cab Auto Services Pte Ltd

AAD1910-040

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5876R

To Check Electrical Lighting Concerned.	\$	170.00	15/
To reinstall rear bumper parking sensor.	\$	~ 170.00	X
To Rust-Proofing Of The Affected Areas.	\$	170.00	30/
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	~ 380.00	X
TOTAL	\$	11,340.00	
Over All Total	\$	19,983.00	

(PART-BY-PART) Repair Days **15 DAYS**

4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To reserve behaviour spray painting
- To display damaged part(s) during reserve
- Parts price are subject to confirmation
- Third party survey is on a "without Prejudice" basis
- No illegal modification is allowed
- Supplementary work must be reviewed and is subject to 1st approval from insurance Company

Acknowledged by Repairer:
Signature:
Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ALLIED WORLD ASSURANCE COMPANY LTD		Ref : CS/AWA19017841/Kqd3n2	
(SINGAPORE BRANCH) 60 ANSON ROAD #08-01 (8th FLOOR) MAPLETREE ANSON SINGAPORE 079914		Date : 30-03-2020	
		Code : AWA	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	FBQ 3021G	Veh. Inspected	SHD 5876R
Policy No.	AVFMSB0000591904	Coverage (\$)	0.00
Claim No.	NSV1900501/SG	Excess (\$)	0.00
Assign From	HEW LEE FONG	Assign Date	09/10/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA PRIUS (A)	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	JTDKB3FU803079270	Colour	M.P.WHITE / RED
Odometer	117912	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	SAILUN	9 mm
L/H Front Tyre	195/65 R15	SAILUN	9 mm
R/H Rear Tyre	195/65 R15	SAILUN	9 mm
L/H Rear Tyre	195/65 R15	SAILUN	9 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	06/10/2019	Inspection Date	24/03/2020
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607196-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 5876R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	MOULDING ASSY,BODY ROCKER PANEL,RH	SERVICEABLE	594.80	-
1	REAR FENDER RH	BENT	854.80	854.80
1	REAR FENDER LINER	SERVICEABLE	139.80	-
1	REAR BUMPER	TO REPAIR SEE LABOUR	442.60	-
1	REAR BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	332.70	-
1	REAR BUMPER TOWING COVER	SERVICEABLE	15.40	-
1	REAR BUMPER UNDER COVER (BLACK)	SERVICEABLE	576.30	-
1	REAR BUMPER SIDE RETAINER RH	SERVICEABLE	117.70	-
1	TAILLAMP LOWER RH	SERVICEABLE	502.00	-
1	TAILLAMP UPPER RH	SERVICEABLE	451.80	-
1	REAR BUMPER SIDE RH	SERVICEABLE	123.70	-
1	REAR TAILGATE	TO REPAIR SEE LABOUR	1,147.80	-
1	PANEL SUB-ASSY,REAR DOOR,RH	TO REPAIR SEE LABOUR	1,281.70	-
1	LOCK ASSY,REAR DOOR W/MOTOR,RH	SERVICEABLE	561.90	-
	LESS 25% DISCOUNT		-1,785.75	-213.70
			5,357.25	641.10
1	REAR RIGHT WHEEL RIM	DENTED	1,570.55	1,570.55
	LESS 25% DISCOUNT		-	-392.64
			1,570.55	1,177.91
SPECIAL NETT ITEMS				
1	REAR DOOR STICKER "6555-3333" (SN)	NOT NECESSARY	80.00	-
1	SET PARKING AID (SN)	SERVICEABLE	700.00	-
1	SET REAR BUMPER CLIP (SN)	NOT NECESSARY	66.00	-
1	REAR BUMPER PROTECTOR (SN)	SERVICEABLE	100.00	-
2	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	30.00
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
1	REAR TAILGATE TOYOTA LOGO (SN)	NOT NECESSARY	47.00	-
1	REAR TAILGATE WORDING "PRIUS" (SN)	NOT NECESSARY	52.90	-

Report Ref No. CS/AWA19017841/Kqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR TAILGATE WORDING "HYBRID" (SN)	NOT NECESSARY	53.50	-
1	REAR TAILGATE STICKER "TRANS-CAB" (SN)	NOT NECESSARY	80.00	-
1	REAR TAILGATE STICKER "6555-3333" (SN)	NOT NECESSARY	80.00	-
1	REAR RIGHT WHEEL RIM COVER (SN)	SERVICEABLE	175.80	-
			1,715.20	30.00
	LABOUR			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		4,500.00	220.00
	TO TRANSFER OF TAILGATE FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.		170.00	20.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR.	NOT NECESSARY	170.00	-
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF REAR BUMPER, REAR BUMPER REINFORCEMENT, REAR TAILGATE AND PANEL SUB-ASSY, REAR DOOR, RH.		4,500.00	600.00
	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		170.00	80.00
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	15.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.	NOT NECESSARY	170.00	-
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	30.00
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	-		-	-
	-		-	-
	-		-	-
			11,340.00	965.00
	GRAND TOTAL		19,983.00	2,814.01

Report Ref No. CS/AWA19017841/Kqd3n2



RECOMMENDED COST OF REPAIRS			2,814.01
-----------------------------	--	--	----------

Report Ref No. CS/AWA19017841/Kqd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.