

ASS. REC. BY:

Steve

REF:

ALG

12848/10

## ASSIGNMENT

From:

Date:

09/12/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SL2 2540R

at Workshop m/s

Performance Motors

of

303 Alexandra Road

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SL2 2540R

Yr Regn:

27/4/18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 1160

C.C

1496

Colour

Orange

A/C:

Insured / Std / NI / NA

Sp.Reading

48667

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WBA1V72000V945462

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/40ZR18

R:

"

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

7/12/19

D.O.I.

9/12/19

Survey held at

Performance

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

M/V-90K

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Report Format:

Lump Sum / L.B.I. (\$)

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Week end (\$)

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	771H
<b>Vehicle Details</b>	
Vehicle No.:	SLZ2540R
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Dec 2019
Vehicle Make:	B.M.W.
Vehicle Model:	116D 5DR LED EU6
Primary Colour:	Orange
Manufacturing Year:	2018
Engine No.:	39375245B37D15A
Chassis No.:	WBA1V72000V945462
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$28,248.00
Original Registration Date:	27 Apr 2018
First Registration Date:	27 Apr 2018
Transfer Count:	1
Actual ARF Paid:	\$31,548.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Apr 2028
PARF Rebate Amount:	\$23,661.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	26 Apr 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$37,000.00
COE Rebate Amount:	\$31,008.00
<b>Total Rebate Amount:</b>	<b>\$54,669.00</b>

The information contained herein is correct as at 09 Dec 2019

OK