

ASS. REC. BY:

REF:

TM1/CC3/TM1 19017871/K+f3n2

ASSIGNMENT

From:

Date:

Estimated Cost:

QD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 / File pass to

1/1/19 8/1730/ (Red: 22918.30 / 92%) confirm with Wai Yim
SHC 5350 X - CC3/FC15005668/E96E3 DOA - 23/11/2014
SLK 8123B - X

RECEIVED 22 OCT 2019

11/10 Sent email to TOKIO preli advise, Air, Police report and estimate

Date/Time, File Pass to?



: Preli. Report

1) 22/10/19



: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trlp:

Survey Fee:

Transportation:

S - RS - SI

Fixing

Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Report Format:

Lump Sum / I.B.I. (\$

261



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: -

Date: 11/10/2019

Our Ref: CS/LPC19010968/R1td3

The Motor Claims Department
TOKIO MARINE INSURANCE SINGAPORE LTD

Dear Sirs/Mdm


PRELIMINARY ADVICE OF VEHICLE NO. SHC 5350K.

Please be informed that we had conducted the inspection of the above-mentioned vehicle on 09/10/2019 at the premises of M/s Trans Cab and have the following to report: -

Workshop Estimate Amount	: S\$ 24,668.30
Revised Estimate Amount	: S\$ 2,167.72
"Check" Items Amount	: S\$ 0.00
Market Value	: S\$
LTA Reimbursement Value	: S\$ -
Nett Value	: S\$ -

Description of Damage:

The vehicle sustained damages at the n/s front portion.



Repair days: 2

Comments/ Present Status:

Damages Consistent.

Yours faithfully
Rasul
Automotive Assessor

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Friday, 11 October 2019 3:46 PM
To: 'motorclaims@tokiomarine.com.sg'
Cc: SUR
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP -TRANS-CAB AUTO SERVICES PTE LTD, DOA: 1/10/2019, SHC 5350X (TP VEHICLE), SLK 8123B (OI VEHICLE)
Attachments: POLICE REPORT.pdf; GIA REPORT.pdf; ESTIMATE.pdf; PRELI ADVISED OF SHC 5350X.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SHC 5350R at M/s: TRANS-CAB AUTO SERVICES PTE LTD, NO.2 ANG MO KIO ST 63 SINGAPORE 569111 on 9/10/2019

Enclosed herewith a copy of TP's GIA report, police report ,estimated cost of repair and preliminary revised.

Kindly create claim in merimen for our necessary action.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Denise Tay (LKKAUTO)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Tuesday, 22 October 2019 11:51 AM
To: Denise Tay (LKKAUTO)
Subject: FW: SHC 5350X / TOKIO / DOA: 01/10/2019 -- AAD1910-011
Attachments: estimate.pdf

Hi Denise

Amount confirmed \$ 1,750 (before GST).

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**

TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63
Singapore 569111
Tel: 6287 6666 Fax: 6287 7764

From: Denise Tay (LKKAUTO) [mailto:denisetay@lkkauto.com]
Sent: Monday, 21 October, 2019 2:49 PM
To: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Subject: SHC 5350X / TOKIO / DOA: 01/10/2019

Dear Wai Yin,

Offer lump sum \$1750, 2days

Please check and confirm.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



This email has been checked for viruses by AVG antivirus software.
www.avg.com

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	878K
Vehicle Details	
Vehicle No.:	SHC5350X
Vehicle to be Exported:	Yes
Intended Deregistration Date:	02 Oct 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C001987
Chassis No.:	VF1ABL15AUC279368
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	30 Sep 2014
First Registration Date:	30 Sep 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Sep 2022
PARF Rebate Amount:	\$8,748.00
Intended COE Rebate Details	
COE Expiry Date:	29 Sep 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$50,704.00
COE Rebate Amount:	\$18,961.00
Total Rebate Amount:	\$27,709.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 02 Oct 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/10/2019 10:15
Date Of Accident	01/10/2019 07:30
Exact Location Of Accident	BENCOOLEN STREET X MIDDLE ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC5350X
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666

Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 D DCI (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VFX/P1680520
Cover Note Number	

Driver

Name of Driver	YEO CHUI BOK
NRIC No	S1367948G
Date Of Birth	11/08/1959
Occupation	OUTDOOR
Date Of Driving Pass	24/06/2013
Driving Experience	6 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-88121942
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	BLK 8 NORTH BRIDGE ROAD #05-4126
Postcode	190008
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	ROCHER N.P.C
Police Station Address	ROAD: 11 KAMPONG KAPOR ROAD , POSTCODE: 208678 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2949999 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT T/20191001/2202

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLK8123B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Middle Road

Bancroft Street

Bancroft Street X Middle Road

A: SHL 535AX

B: SLK 8123 B

Refer to Police Report T/20191601/2202.

I/We declare the foregoing particulars are true in every respect.

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20191001/2202

Police Station Of Origin:
Rochor N.P.C
11 Kampong Kapur Road SINGAPORE
208678
Tel No: 1800-2949999

1 of 3

Report No. T/20191001/2202

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 01/10/2019 20:45	Vide Report No.:	Station Diary No.: 135
--	------------------	---------------------------

Informant's Particulars

Name of Informant: YEO CHUI BOK			Address: APT BLK 8 NORTH BRIDGE ROAD #05-4126 SINGAPORE 190008		
ID Type / ID No.: NRIC NO / S1367948G			Contact No.: Home/Office: Mobile: 88121942		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 60	Date of Birth: 11/08/1959	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 01/10/2019 07:30	Type of Location: X-Junction
Location: Along Road 1 Traveling Toward Road 2 BENCOOLEN STREET MIDDLE ROAD Along Bencoolen St turning left towards Middle Road.				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHC5350X	Car	RENAULT	Latitude	Red	Slightly Damaged	0
SLK8123B	Car	TOYOTA	Vellfire	Black	Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20191001/2202

2 of 3

Police Station Of Origin:

Rochor N.P.C

11 Kampong Kapor Road SINGAPORE

208678

Tel No: 1800-2949999

Report No. T/20191001/2202

CONTINUATION OF REPORT

Driver			
Name	YEO CHUI BOK	ID No.	S1367948G
Related Vehicle	SHC5350X (Car)	Contact No.	88121942
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 01/10/2019 at about 0730hrs, I was driving my taxi (SHC5350X) along Bencoolen St. I was travelling on the left most lane. As I was approaching the junction of Bencoolen St and Middle Road, the said traffic light was green. As such I slowed down to make a left turn. While I was making a left turn, a car on my right was also making a left turn. While making the turn, the said car rear left bumper scrape onto my front right bumper. As such parked our vehicles on the leftmost lane of Middle Road.

Both of us alight from our vehicles and we spoke to each other. Initially we wanted to solve the matter privately. However, I deemed that it is best that we made a police report regarding the matter. Both of us took pictures of the damages. The car (SLK8123B) suffered minor scratches on the rear left bumper. My car suffered a few scratches on the front right bumper.

I am not injured. I am lodging this report for my own record purpose to inform my taxi company regarding the matter.



**SINGAPORE
POLICE FORCE**



T/20191001/2202

3 of 3

Police Station Of Origin:
Rochor N.P.C
11 Kampong Kapor Road SINGAPORE
208678
Tel No: 1800-2949999

Report No. T/20191001/2202

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

A /

Sgt 2 MOHAMAD SHAFUDIN BIN KADER

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

01/10/2019 20:45

Officer In Charge Of Case:

TP / GIA /

Staff Sgt WONG SIEU LUI

Contact No.: 65476151

Classification Of Case:

Authentication Stamp

NP168

SINGAPORE

FORCE

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5350X**AAD1910-011***Not Authored
L/Snp 81750k*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

09 OCT 2019

SHC 5350X

VF1ABL15AUC279368

RENAULT

LATITUDE

1.10.19

TOKIO MARINE

30/9/2014

PART

1	BUMPER COVER FRT
1	BUMPER SPOILER FRT
1	BUMPER ABSORBER FRT
1	BUMPER RETAINER FRT RH
1	BUMPER SUPPORT FRT
1	BUMPER UNDERTRAY FRT
1	BUMPER GRILLE LOWER FRT
1	BUMPER FOG LAMP GRILLE RH
1	BUMPER BEAM FRT
1	HEADLAMP RH
1	HEADLAMP PANEL FRT RH
1	FENDER PANEL FRT RH
1	WHEELARCH FRT RH
1	FENDER BRACKET LOWER RH
1	FENDER INSULATOR RH
1	TOW COVER FRT
1	FRONT BRACE PANEL
1	RADIATOR GRILLE
1	RADIATOR GRILLE BADGE 'RENAULT'
1	RADIATOR GRILLE FRAME
1	FRAME FULL SUPPORT PANEL
1	FRAME FULL SUPPORT BRACKET
1	BONNET
1	BONNET INSULATOR

LIST

\$	<i>mg cm</i>	747.20	✓
\$	<i>SL</i>	344.70	}
\$	<i>SL</i>	394.68	
\$	<i>SL</i>	101.40	
\$	<i>SL</i>	10.70	
\$	<i>SL</i>	292.50	
\$	<i>SL</i>	147.00	}
\$	<i>SL</i>	207.21	
\$	<i>SL</i>	663.70	}
\$	<i>SL</i>	743.60	
\$	<i>SL</i>	128.30	}
\$	<i>SL</i>	437.10	
\$	<i>SL</i>	191.40	
\$	<i>SL</i>	11.80	
\$	<i>SL</i>	66.30	
\$	<i>SL</i>	60.90	
\$	<i>SL</i>	177.22	}
\$	<i>SL</i>	969.90	
\$	<i>SL</i>	225.36	
\$	<i>SL</i>	686.00	
\$	<i>SL</i>	592.70	}
\$	<i>SL</i>	41.60	
\$	<i>SL</i>	1,312.70	
\$	<i>SL</i>	294.30	

Trans-cab Auto Services Pte Ltd**AAD1910-011**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5350X

1	BONNET STRUT RH	\$	53.30	}	X
1	BONNET HINGE RH	\$	237.40		
1	BONNET LOCK	\$	152.80		
1	BONNET CABLE	\$	55.20		
1	BONNET CABLE COVER	\$	80.60		
1	BONNET SEAL OUTER	\$	83.20		
1	BONNET SEAL INNER	\$	70.10		
1	WIPER RESERVOIR MOTOR	\$	82.60		
1	WIPER RESERVOIR	\$	179.60		
1	WIPER RESERVOIR NECK	\$	29.30		
TOTAL		\$	9,872.37		
10%		\$	987.24		
		\$	8,885.13		

Special Nett

1	BUMPER CLIP FRT	\$	66.00	}	X
1	BUMPER BRACKET CLIP FRT RH	\$	12.00		
1	BUMPER SUPPORT CLIP FRT RH	\$	10.50		
1	BUMPER GRILLE LOWER CLIP	\$	69.00		
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	70.00		
2	FRAME FULL SUPPORT PANEL NUT	\$	20.00		
2	FRAME FULL SUPPORT PANEL STUD	\$	30.00		
1	WHEELARCH CLIP FRT RH	\$	30.50		
1	FRONT RIGHT TYRE	\$	300.00		
1	FRONT RIGHT TYRE RIM	\$	380.00		
1SET	Front licence plate with holder	\$	80.00		
1SET	RADIATOR GRILLE SCREW	\$	16.00		
1SET	RADIATOR GRILLE FRAME CLIP	\$	52.00		
2	BONNET CABLE CLIP L70Y	\$	6.31		
2	BONNET CABLE COVER SCREW L70Y	\$	10.85		
TOTAL		\$	1,153.17		
TOTAL PARTS		\$	10,038.30		

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5350X**AAD1910-011****LABOUR**

Putty and spray painting of the affected portion.	\$	6,000.00	4401
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	6,000.00	3001
To rust-proofing of the affected areas.	\$	170.00	X
To transfer of front fender fittings, attachment and perform water seepage test.	\$	380.00	X
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	380.00	X
To check steering geometry and computer wheel alignment	\$	220.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	380.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	X
To transfer of tire, rim and on wheel balancing.	\$	170.00	X
TOTAL	\$	14,630.00	

Over All Total \$ 24,668.30**LUMP SUM (REPAIR DAY)****20 DAYS**
2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to our quotation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI19017871/KTF3N2

Date: 29/10/2019

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MJ001711
Claimant Vehicle No :	SHC5350X	Insured Vehicle No :	SLK8123B
Date of Loss:	01/10/2019	Nature of Claim:	TP
		Claim No:	M1907713

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC5350X	Engine No:	M9R8839C001987
Make & Model:	RENAULT LATITUDE, 2.0 D dCi (A)	Chassis No:	VF1ABL15AUC279368
Reg. Date:	30/09/2014 (Man. Year: 2014)	Odometer:	544476 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Sailun 9 mm	Rear Left Side:	Sailun 9 mm
Front Right Side:	Sailun 9 mm	Rear Right Side:	Sailun 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,038.29	1,407.72	8,630.57	85.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,630.00	760.00	13,870.00	94.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,668.29	2,167.72	22,500.57	91.21
Approved Total (Overridden) (S\$)		1,750.00		
(S\$)	24,668.29	1,750.00	22,918.29	92.91
+ GST 7.00/7.00% (S\$)	1,726.78	122.50	1,604.28	92.91
Nett Amount (S\$)	26,395.07	1,872.50	24,522.57	92.91

INSPECTION

Date of Assignment: 11/10/2019

Date Inspected: 09/10/2019 Inspected At:

Trans Cab Auto Services Pte Ltd - Amk (HQ)
No 2 Ang Mo Kio St 63
Singapore 569111

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 25 Oct 2019)
Parts: 143	RENAULT LATITUDE 2.0 D dCi (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHC5350X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER FRT	Mtg Cracked	747.20 FL	*747.20 FL
2	1		*BUMPER SPOILER FRT	Serviceable	344.70 FL	*- FL
3	1		*BUMPER ABSORBER FRT	Serviceable	394.68 FL	*- FL
4	1		*BUMPER RETAINER FRT RH	Serviceable	101.40 FL	*- FL
5	1		*BUMPER SUPPORT FRT	Serviceable	10.70 FL	*- FL
6	1		*BUMPER UNDERTRAY FRT	Serviceable	292.50 FL	*- FL
7	1		*BUMPER GRILLE LOWER FRT	Serviceable	147.00 FL	*- FL
8	1		*BUMPER FOG LAMP GRILLE RH	Serviceable	207.21 FL	*- FL
9	1		*BUMPER BEAM FRT	Repair	663.70 FL	*- FL
10	1		*HEADLAMP RH	Cut	743.60 FL	*743.60 FL
11	1		*HEADLAMP PANEL FRT RH	Repair	128.30 FL	*- FL
12	1		*FENDER PANEL FRT RH	Repair	437.10 FL	*- FL
13	1		*WHEELARCH FRT RH	Serviceable	191.40 FL	*- FL
14	1		*FENDER BRACKET LOWER RH	Serviceable	11.80 FL	*- FL
15	1		*FENDER INSULATOR RH	Serviceable	66.30 FL	*- FL
16	1		*TOW COVER FRT	Serviceable	60.90 FL	*- FL
17	1		*FRONT BRACE PANEL	Repair	177.22 FL	*- FL
18	1		*RADIATOR GRILLE	Serviceable	969.90 FL	*- FL
19	1		*RADIATOR GRILLE BADGE RENAULT	Serviceable	225.36 FL	*- FL
20	1		*RADIATOR GRILLE FRAME	Serviceable	686.00 FL	*- FL
21	1		*FRAME FULL SUPPORT PANEL	Serviceable	592.70 FL	*- FL
22	1		*FRAME FULL SUPPORT BRACKET	Serviceable	41.60 FL	*- FL
23	1		*BONNET	Repair	1,312.70 FL	*- FL
24	1		*BONNET INSULATOR	Serviceable	294.30 FL	*- FL
25	1		*BONNET STRUT RH	Serviceable	53.30 FL	*- FL
26	1		*BONNET HINGE RH	Repair	237.40 FL	*- FL
27	1		*BONNET LOCK	Repair	152.80 FL	*- FL
28	1		*BONNET CABLE	Serviceable	55.20 FL	*- FL
29	1		*BONNET CABLE COVER	Serviceable	80.60 FL	*- FL
30	1		*BONNET SEAL OUTER	Serviceable	83.20 FL	*- FL
31	1		*BONNET SEAL INNER	Serviceable	70.10 FL	*- FL
32	1		*WIPER RESERVOIR MOTOR	Serviceable	82.60 FL	*- FL
33	1		*WIPER RESERVOIR	Serviceable	179.60 FL	*- FL
34	1		*WIPER RESERVOIR NECK	Serviceable	29.30 FL	*- FL
35	1		*BUMPER CLIP FRT	Necessary	66.00 FS	*66.00 FS
36	1		*BUMPER BRACKET CLIP FRT RH	Not Necessary	12.00 FS	*- FS
37	1		*BUMPER SUPPORT CLIP FRT RH	Not Necessary	10.50 FS	*- FS
38	1		*BUMPER GRILLE LOWER CLIP	Not Necessary	69.00 FS	*- FS
39	1		*SET FRAME FULL SUPPORT PANEL CLIP	Not Necessary	70.00 FS	*- FS
40	2		*FRAME FULL SUPPORT PANEL NUT	Not Necessary	20.00 FS	*- FS
41	2		*FRAME FULL SUPPORT PANEL STUD	Not Necessary	30.00 FS	*- FS
42	1		*WHEELARCH CLIP FRT RH	Not Necessary	30.50 FS	*- FS
43	1		*FRONT RIGHT TYRE	Serviceable	300.00 FS	*- FS
44	1		*FRONT RIGHT TYRE RIM	Serviceable	380.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	1		*SET FRONT LICENCE PLATE WITH HOLDER	Serviceable	80.00 FS	*- FS
46	1		*SET RADIATOR GRILLE SCREW	Serviceable	16.00 FS	*- FS
47	1		*SET RADIATOR GRILLE FRAME CLIP	Not Necessary	52.00 FS	*- FS
48	2		*BONNET CABLE CLIP L70Y	Not Necessary	6.31 FS	*- FS
49	2		*BONNET CABLE COVER SCREW L70Y	Not Necessary	10.85 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					11,025.53	1,556.80
- List Item Discount on L Items 10.00/10.00% (\$\$)					987.24	149.08
Total Parts (\$\$)					10,038.29	1,407.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	6,000.00	440.00
2	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	6,000.00	300.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
4	TO TRANSFER OF FRONT FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
5	TO TRANSFER OF BONNET FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
6	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
7	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
8	TO TRANSFER OF FRONT BUMPER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
9	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	0.00
10	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR	New	380.00	0.00
11	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	170.00	0.00
Gross Labour Cost (S\$)			14,630.00	760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >