

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/TP/9017872/UGD302

ASSIGNMENT

From:

Date:

Estimated Cost:

OD TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SKR 2672C

at Workshop m/s

Bul

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

49

IDAC Accident Report:

Consistent? : Yes or No

CA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Syris Inu-Dep

Date / Time

Action / Instruction

Ajax nru LA 39693 Rep 9k.

1/5 @ 4500 (Per @ 4563.47, 50%)

RECEIVED 16 OCT 2019

Date/Time, File Pass to?

1) 16/10/2019

Date/Time, File Return to?

2)

☐ : Preli. Report☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

) S + RS, SI

) Photos

) Others

)

TOTAL

Report Format:

Lump Sum / I.B.A. (\$

7p

4500

170
50
50
66
80
416

Veh No: SKR 2672C

Yr Regn: 11 / 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

Make:

Volkswagen Golf c.c 1395

Colour:

silver

A/C: Insured / Std / NI / NA

Sp. Reading

1.75958

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WVWZZZAUZFWO81136

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225 / 40 ZR 18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MID / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

R/Bal.

mm

Rear

6

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

4/10/19

D.O.I.

8/10/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum



golf

Price Range ▼

Depreciation ▼

2014 ▼

Vehicle Type ▼



Home » Used Cars » Auto Empire Pte Ltd » Volkswagen Golf 1.4A TSI

Volkswagen Golf 1.4A TSI

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Price \$48,800

Depreciation ⓘ

\$9,010 /yr

View models with similar depre

Reg Date

28-Nov-2014

(5yrs 1mth 17days COE left)

Mileage

85,000 km (17.5k /yr)

Manufactured ⓘ

2014

Road Tax ⓘ

\$624 /yr

Transmission

Auto

Dereg Value ⓘ

\$37,089 as of today (change)

OMV ⓘ

\$19,226

COE ⓘ

\$64,900

ARF ⓘ

\$5,000

Engine Cap

1,395 cc

Power

90.0 kW (120 bhp)

Curb Weight ⓘ

1,249 kg

No. of Owners ⓘ

1

Type of Vehicle

Hatchback

Features

Responsive 1.4L TSI Engine, Steering Control. Auto Headlamps. Rain Sensors. Electric Brake/Brake Hold. View specs of the Volkswagen Golf (2012)

Accessories

Sports Rims, Premium Leather Upholstery, Factory Fitted Audio System. Retractable Side Mirrors With Indicators, Bluetooth.

Description

1 Owner, Low Mileage, Comes With Warranty And 1 Year Servicing Package, Call Now For Viewing.

Category

PARF Car

Status

Available


Re: [Compare](#)

https://www.sgcarmart.com/used_cars/info.php?ID=854333&DL=3559



Location Map

Price Chart



Click on the point to view the i

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

2-HR
FREE
WEEKDAY PARKING

Spend \$30 to qualify
NOW TILL 15 NOV 2019
 [MON - FRI, 6PM - 10PM]

[CLICK TO FIND OUT MORE](#)

golf

Price Range ▼

Depreciation ▼

2014 ▼

Vehicle Type ▼


[Home](#) » [Used Cars](#) » [VMG Auto Pte Ltd](#) » [Volkswagen Golf 1.4A TSI](#)

Volkswagen Golf 1.4A TSI

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Price \$50,800

Depreciation ? \$9,590 /yr
 View models with similar depre

Reg Date 23-Oct-2014
 (5yrs 12days COE left)

Mileage 55,806 km (11.2k /yr)

Manufactured ? 2014

Road Tax ? \$624 /yr

Transmission Auto

Dereg Value ? \$35,935 as of today (change)

OMV ? \$19,226

COE ? \$63,880

ARF ? \$5,000

Engine Cap 1,395 cc

Power 90.0 kW (120 bhp)

Curb Weight ? 1,249 kg

No. of Owners ? 2

Type of Vehicle Hatchback

Features

Combined With The Frugal Nature Of The Responsive 1.4-Litre TSI Engine. 120 BHP With Auto Headlamps And Rain Sensor. View specs of the Volkswagen Golf (2012)

Accessories

As Per Standard Factory Features With 17" Sports Rims. Leather Seats. Factory Fitted Audio System.

Description

Hot Hatch In Da House. One Year Warranty And One Year Free Service Upon Purchase. Classy Silver On Black. Immaculate Condition With Zero Mods. Viewing Is Most Welcome. Price Still Negotiable. Thank You.

Category

PARF Car


Status

Available

 Re: [Compare](#)
https://www.sgcarmart.com/used_cars/info.php?ID=859935&DL=3219


Location Map

Price Chart



Click on the point to view the

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	386G
Vehicle Details	
Vehicle No.:	SKQ2672C
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Oct 2019
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	GOLF A7 1.4 TSI AT 5G13GZ SR HID
Primary Colour:	Silver
Manufacturing Year:	2014
Engine No.:	CXS221946
Chassis No.:	WVWZZZAUZFW081136
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$22,709.00
Original Registration Date:	17 Nov 2014
First Registration Date:	17 Nov 2014
Transfer Count:	1
Actual ARF Paid:	\$8,793.00 <i>4396</i>
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Nov 2024
PARF Rebate Amount:	\$6,594.00
Intended COE Rebate Details	
COE Expiry Date:	16 Nov 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$64,900.00
COE Rebate Amount:	\$33,099.00
Total Rebate Amount:	\$39,693.00

The information contained herein is correct as at 10 Oct 2019

OK

MDA219131417 / Progressive Car Care Pte Ltd - HQ
 ENTRY DATE & TIME: 04/10/2019 12:30
 SUBMITTED BY: Lily Lim

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at this centre and to copies of the report being made available as/when/where.

ACCIDENT STATEMENT

Date Of Report 04/10/2019 12:30
 Date Of Accident 04/10/2019 07:10
 Exact Location Of Accident CHOA CHU KANG DR FILTER LANE TO KJE
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SKQ2672C
 Insured/Policyholder
 Name Of Registered Owner ONG WEI MIN SHERMAN
 NRIC No S9128386G
 Email Address WEIMINONG@YAHOO.COM.SG
 Mobile Phone No (LOCAL) +65-97392300
 Alternative Phone No OTHERS-97392300
 Vehicle Particulars
 Manufacturer VOLKSWAGEN
 Model GOLF
 Exact Purpose for which vehicle was being used at time of accident
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category PRIVATE CAR
 Insurance Company
 Name of Insurance Company DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number MT700422109
 Cover Note Number
 Driver
 Name of Driver ONG WEI MIN SHERMAN
 NRIC No S9128386G
 Date Of Birth 02/08/1991
 Occupation INDOOR
 Date Of Driving Pass 01/10/2010
 Driving Experience 9 YEARS AND 0 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-97392300
 Fax Number
 Contact Number OTHERS-97392300
 Email Address WEIMINONG@YAHOO.COM.SG

Address BLK 754 CHOA CHU KANG NORTH 5 #10-221
 Postcode 680754
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 Vehicle -
 Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1 NAME : PAX 1
 GENDER : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHED STATEMENT RECORD BY LILY - PROGRESSIVE CAR CARE PTE LTD 67415336

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SGB4633D
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the Centre and to copies of the report being made available insofar as:
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (forms) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Shen
Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature]
Reporting Centre Personnel's Signature
Name:
NIC/FIN No.:

4/10/19

Sketch Plan #2

SKETCH PLAN



Vehicle
A - SKR2672C
B - SGB4633D

Legend
Vehicle
Motorcycle

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Was in the filter lane at Et Chm Chukang Dr going into KJE. There were 2 cars in front of me. They proceeded to move off and I'm the 1st car of the queue. Was stationary at the point of impact.

DECLARATION

I/We declare the foregoing particulars are true in every respect.
Please be advised that your insurer may have a fourteen (14) days clause whereby the claim against your policy must be made within the stipulated timeframe from the day of occurrence. Kindly check your policy for more details.

[Signature]
Policyholder's Signature
Date & Time:

[Signature]
Driver's Signature
(if driver is not the policyholder)
Date & Time:

[Signature]
Reporting Centre Personnel's Signature
Name:
NASC/FIN No.:

4/10/19.



BLUWEL AUTOMOTIVE SERVICE PTE LTD

Workshop: 1 Kaki Bukit Ave 6 (Unit B) #01-28
 (Unit C) #01-28-53/55 Singapore 417883
 Hp: 9755 2088 Tel: 6745 2088 Fax: 6841 2088
 Website: www.bluwel.com.sg Email: bluwel2088@yahoo.com.sg
 Co. Reg. No.: 200704951N
 GST Reg. No.: 200704951N

not Allowed
 after
 1/5 @ 4500
 5 day.

SK22672C

	Rear bumper	20/02	1080.14	/
	Rear bumper lower skirt	22/02/11	485.00	/
1 set	Rear bumper clips	neu	45.00	/
	Rear bumper reinforcement	30/01	572.31	/
	Rear bumper tow cover	11	33.00	X
2 pcs	Rear bumper side retainers @ 34.57	11	69.02	X
	Tailgate	12	1450.00	X
	Tailgate weatherstrip	su	191.00	X
2 pcs	Tail lamps @ 345.00	one	690.00	/
2	Rear bumper PDC sensors @ 215.00	shorted	430.00	/
	Rear end panel	20/02/11	730.00	/
	Rear end panel top garnish	su	178.00	X
		102	5953.47	4032.45
S. Netff				
	Rear licence plate w/holder	30/01	50.00	40
	Rear end panel sealant	neu	50.00	/
	Rear windscreen sealant	11	50.00	X
	To check wiring		80.00	- 30
	To Dismantle & replacing pdc sensor		80.00	- 50
	To dismantle & refix rear windscreen	11	120.00	- X
	To spray rust proofing		80.00	- 30
	To dismantle & refix cushion upholstery		120.00	- 80
	labour for panel beating & replacing parts		980.00	- 750
	To putty & spray painting		1500.00	- 1000
			TOTAL	9063.47
				5259.10
				4577



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
BLUWEL AUTOMOTIVE SERVICE PTE LTD		Ref : CS/TP19017872/Uqd3n2	
BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE)SINGAPORE 417883		Date : 16-10-2019	
ON BEHALF OF ONG WEI MIN SHERMAN		Code : TP149	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	Veh. Inspected		SKQ 2672C
Policy No.	Coverage (\$)		0.00
Claim No.	Excess (\$)		0.00
Assign From	Assign Date		08/10/2019
2. Vehicle Particulars & Condition			
Make & Model	VOLKSWAGEN GOLF (A)	c.c	1395
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	WVWZZZAUZFW081136	Colour	SILVER
Odometer	175958	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/40 ZR18	MICHELIN	6 mm
L/H Front Tyre	225/40 ZR18	MICHELIN	6 mm
R/H Rear Tyre	225/40 ZR18	MICHELIN	6 mm
L/H Rear Tyre	225/40 ZR18	MICHELIN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	04/10/2019	Inspection Date	08/10/2019
Survey held at	BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKQ 2672C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DENTED / DEFORMED	1,080.14	1,080.14
1	REAR BUMPER LOWER SKIRT	DEFORMED / TORN	485.00	485.00
1	SET REAR BUMPER CLIPS	NECESSARY	45.00	45.00
1	REAR BUMPER REINFORCEMENT	BENT	572.31	572.31
1	REAR BUMPER TOW COVER	NOT NECESSARY	33.00	-
2	REAR BUMPER SIDE RETAINERS @\$34.51	NOT NECESSARY	69.02	-
1	TAILGATE	TO REPAIR SEE LABOUR	1,450.00	-
1	TAILGATE WEATHERSTRIP	SERVICEABLE	191.00	-
2	TAILLAMPS @\$345.00	CRACKED	690.00	690.00
2	REAR BUMPER PDC SENSORS @\$215.00	SHORTED	430.00	430.00
1	REAR END PANEL	DENTED / BENT	730.00	730.00
1	REAR END PANEL TOP GARNISH	SERVICEABLE	178.00	-
	LESS 10% DISCOUNT		-	-403.25
			5,953.47	3,629.20
SPECIAL NETT ITEMS				
1	REAR LICENCE PLATE W/HOLDER (SN)	BENT	50.00	40.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	50.00	50.00
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	50.00	-
			150.00	90.00
LABOUR				
	TO CHECK WIRING.		80.00	30.00
	TO DISMANTLE & REPLACING PDC SENSOR.		80.00	50.00
	TO DISMANTLE & REFIX REAR WINDSCREEN.	NOT NECESSARY	120.00	-
	TO SPRAY RUST PROOFING.		80.00	30.00
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY.		120.00	80.00
	LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF TAILGATE.		980.00	750.00
	TO PUTTY & SPRAY PAINTING.		1,500.00	1,000.00
			2,960.00	1,940.00
GRAND TOTAL			9,063.47	5,659.20

Report Ref No. CS/TP19017872/Uqd3n2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,500.00
---	--	--	----------

Report Ref No. CS/TP19017872/Uqd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.