













SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Occupation

Gender

Date Of Driving Pass

Driving Experience

Mobile Number

Fax Number

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

	ACCIDENT STATEMENT
Date Of Report	05/10/2018 16:35
Date Of Accident	03/10/2018 16:25
Exact Location Of Accident	PIE TOWARDS CHANGI
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SKP308Z
Insured/Policyholder	
Name Of Registered Owner	HON SIN YEA, SAMANTHA
NRIC No	S8900334B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93261711
Alternative Phone No	OTHERS-NOPHONE
Vehicle Particulars	
Manufacturer	BMW
Model	3351 A
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
f No, Please state action to be taken	
/ehicle Category	PRIVATE CAR
nsurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5093096153-01
Cover Note Number	
Driver	
Name of Driver	TANG KAI LOON, NICHOLAS
NRIC No	S8228994A
Date Of Birth	31/08/1982
	11122222

INDOOR

MALE

05/10/2012

5 YEARS AND 11 MONTHS

(LOCAL) +65-82008343

Address BLK 539 BUKIT BATOK ST 52 #08-577

Postcode 650539

Was driver an employee of the Insured's Company NO

If No. Relationship of the Driver with the Insured SPOUSE

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident CHAIN COLLISION

Weather Conditions CLEAR Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? YES

Was any injured conveyed to hospital by NO

ambulance?

YES Was any other material or property damaged?

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name TRAFFIC POLICE DIVISION HQ - SINGAPORE CITY

NO

NO

ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: Police Station Address

SINGAPORE

Police Station Contact TEL NO: 65470000 - FAX NO:

Was notice of intended Prosecution given?

If Yes, against whom?

Circumstances of Accident

refer to police report.

Attachment(s)

Are accident photos available for attachment? YES Was there any video captured by Car Camera? NO NO

Was there any audio recorded?

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLQ137H

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR Name of Driver TAN LIAN HIANG NRIC/Passport Number S0186833J

Contact Number

Address

Postcode

Insurance Company Name

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SLT7853L

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category Name of Driver

PRIVATE CAR LIM JIUNN YUAN

NRIC/Passport Number

S1475780E

Contact Number

Address Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

SGS773U

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number

SLL3570X

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 5

Vehicle Registration Number

WWJ7899

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

TANG KAI LOON NICHOLAS

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SKP308Z

Were seat belts wom?

Was this injured conveyed to hospital by

ambulance?

Address

Postcode

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for Investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers", the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (III) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - [IV] administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (II) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:

Oriver's Signature (If driver is not the policyholder) Date & Time: Reporting Centre Personne

SIN

s Signature

NRIC/FIN No.:

Police Report Pg. 1





T/20181004/2140

Police Station Of Origin: Traffic Police Division HQ 10 Ubi Avenue 3 SINGAPORE 408865

Report No. T/20181004/2140

Tel No: 65470000

REPORT OF A	TRAFFIC	ACCIDENT
-------------	---------	----------

Date/Time Report Made: 04/10/2018 17:41		Made:	Vide Report No.:	Station Diary No.:	
Informa	nt's Partic	ulars			
Name of Informant: TANG KAI LOON, NICHOLAS			Address: APT BLK 539 BUKIT BATOK STREET 52 #08-577 GUILIN BREEZE SINGAPORE 650539		
NRIC NO National	ID Type / ID No.: NRIC NO / S8228994A Nationality: SINGAPORE CITIZEN		Contact No.: Home/Office: Email:	Mobile: 82008343	
Sex: Male	Age: 36	Date of Birth: 31/08/1982	Type of Informant:		
Race: Chinese		1	Language: Institution / School Na		
The second secon	Occupation: MANAGER		Driving Licence Information: Class: 3 Date of Expiry:		

Type of Accident:	Injury Conveyed By Ambu	ulance	Drink Drive: No	Date/Time of Accident: 03/10/2018 16:2	15	Type of Location Straight Road
Location: Along Road 1 PAN ISLAND PIE (AP) 18K	EXPRESSWAY					
Weather: Clear		Road	Surface:		Roa	d Speed Limit:
Traffic Flow: Traffic		Traffic Control: Not Controlled		Traffic Volume: Heavy		
One Way		14010	OTTE SHOW		1100	vy

Details of V	ehicle Invo	lved			The Island	
Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenger
SGS773U	Car	BMW	520I 2.0L AT D/AB 2WD 4DR GAS/D NAV	Blue	Slightly Damaged	0
SKP308Z	Car	BMW	335I A	Black	Slightly	0
SLL3570X	Car	MAZDA	MAZDA3 4- DOOR SEDAN 1.5L SP.6EAT	Blue	Slightly Damaged	0

Police Report Pg. 2



T/201B1004/2140

Police Station Of Origin: Traffic Police Division HQ 10 Ubi Avenue 3 SINGAPORE 408865 2 of 3 Report No. T/20181004/2140

Tel No: 65470000

CONTINUATION OF REPORT

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SLQ137H	Car	MERCEDES BENZ	A200 FL STYLE (R17 HLG)	Silver	Slightly Damaged	0
SLT7853L	Car	KIA	NIRÓ HYBRID 1.6 GDI DCT SUNROOF	Brown	Slightly Damaged	0
WWJ7899	Car				Slightly Damaged	0

Brief Details.

ON THE ABOVE MENTIONED DATE TIME AND LOCATION
I WAS TRAVELLING ALONG THE SAID LOCATION. THE VEHICLES ARE AS FOLLOWS (IN CHOROLOGICAL ORDER; A1 (SGS773U), A2(SLT7853L), B1 (SKP308Z), A3(SLQ137H), A4(SLL3570X), B2(WWJ7899). I AM B1, I NOTICE THE VEHICLE INFRONT OF ME A2 DID A SUDDEN BRAKE. IN ORDER NOT TO MAKE THINGS WORST, I APPLIED BRAKE AS WELL. AT THAT MOMENT, MY VEHICLE ONLY HAD A SLIGHT CONTACT WITH THE REAR. HOWEVER, THE VEHICLE AT MY REAR A3, WAS UNABLE TO BRAKE ON TIME AND COLLIDED ONTO MY REAR. THE MOMENTUM CAUSED BY THE A3 MADE MY VEHICLE WORSEN THE DAMAGES MADE TO THE VEHICLE INFRONT OF ME. SUBSEQUENTLY, A4 COLLIDED ONTO A3 AND B2 COLLIDED ONTO A4. WE GOT OFF AND EXCHANGE PARTICULARS. I WAS ADMITTED TO MOUNT ELIZABETH HOSPITAL FOR FUTHER MEDICAL TREATMENT AND WAS GIVEN 5 DAYS MC.

THE PARTICULARS ARE AS FOLLOWS:

NAME: LIM JIUNN YUAN (A2)

NRIC: \$1475780E

NAME: TAN LIAN HIANG (A3)

NRIC: S0186833J

Police Report Pg. 3





Police Station Of Origin: Traffic Police Division HQ 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000 3 of 3 Report No. T/20181004/2140

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Repor TP / NG JIN SHENG	t: Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 04/10/2018 17:41
Officer In Charge Of Case: TP / GIT / Sr Staff Sgt RAZIZ BIN TAHAR Contact No.: 65476200	Classification Of Case:
Authentication Stamp NP168 Sugnatur	

Medical Certificate Pg. 1



MC NO: PNH-2018-018084

MEDICAL CERTIFICATE

NAME: TANG, KAI LOON NICHOLAS

Identification No: S8228994A

THIS IS TO CERTIFY THAT THE ABOVE IS UNFIT FOR DUTY FOR A PERIOD OF 5 DAYS FROM 03-Oct-2018 TO 07-Oct-2018

TYPE OF MEDICAL LEAVE GRANTED: HOSPITALIZATION LEAVE

ADMITTED ON 03-Oct-2018

DISCHARGED ON: 04-Oct-2018

DATE

SIGNATURE, NAME (IN BLOCK LETTERS) AND DESIGNATION

04-Oct-2018

Wong , Siong Sung

13693z

This certificate is not valid for absence from court or other judicial proceedings unless specifically stated*










Accident Photo





Accident Photo











Addendum Sheet



GENTRAL INSURANCE ASSOCIATION OF SINGAPORS RECEIVED MANAGEMENT CENTRS

Charles San 202 St Inguistra 1982 St Inc. 202 St Inc. 202 St Inguistra 1982 St Inguistra 1982 St Inc. 202 St Inc.

IMPORTANT NOTE: Please outmit the completed Addervium form to the patter Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A)	PARTICULARS OF PER	ISON MAKING THE AMENDMENTS		
	Original Report for	MFA118129447	Vehicle Augustration No. SNP MRZ	_
	Name to describe the control	TANG KALLOON, NICHOLAS	THE CHARLEST STATE OF THE PARTY	
	(*Vehicle Driver / Ve	hicks Owner) (*) Please delete as ap	propriate	
	Address			3
	Contact (Tel)		Mobile No.	
	Email Address			
	Date of Accident	63/16/2618	Time of Accident 14:25	
	Place of Accident	711 DOWARDS CHASGE		
	Insurance Company	NELS INCOME INSCRINCE O	D-OPERATIVE LTD	
	ADDITION IN THE PARTY	MATION / AMENDMENTS		
	make the following a	RD PARTY" TO OWN DAMA	and would like to include additional information of	-
	0			
	15/10/20	Signalura ol &	Reporting Contre Personnel's Signature Speed	



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Intern	ationale Des Experts En Auton	nobile
AIG ASIA PACIFIC IN	NSURANCE PTE LTD	Ref : CS3/AlG18018	217/Ayd3e2-1
78 SHENTON WAY # CHARTIS BUILDING SINGAPORE 079120 ATTN : MAVIS CHEV		Date: 21-10-2019 Code: AJG	
WILLIAM SALAK SARA SARA SARAKAN SARAKA	olicy Particulars :- THIRD P.	54000 198	Y INSPECTION)
Insured Veh.	SLL 3570X	Veh. Inspected	SLQ 137H
Policy No.	2100503147-01	Coverage (\$)	0.00
Claim No.	1234823063SG	Excess (\$)	0.00
Assign From	MAVIS CHEW	Assign Date	09/10/2019
2.	Vehicle Pa	rticulars & Condition	
Make & Model	MERCEDES BENZ A200	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WDD1760432J489142	Colour	SILVER
Odometer	19236	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3.	Con	ditions of Tyres	
	Size	Make	Balance
R/H Front Tyre	225/45 R17	BRIDGESTONE	6 mm
L/H Front Tyre	225/45 R17	BRIDGESTONE	6 mm
R/H Rear Tyre	225/45 R17	BRIDGESTONE	6 mm
L/H Rear Tyre	225/45 R17	BRIDGESTONE	6 mm
4.	Descri	ption of Damages	
WINESSEM/ASSIGNA	HAD COMPLETED ITS REPAIR I	WORKS.	
5.		eral Information	
Accident Date	03/10/2018	Inspection Date	17/10/2019
Survey held a	PRECISE AUTO SERVICE	*	
	NO.1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883		
5a.		Remarks	
	TION WAS CONDUCTED ON A" NCE TO YOUR INSTRUCTIONS		
5b.	Estima	ate Days of Repair	

14 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR:



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 137H

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER FASCIA	REPLACED	1,240.22	1,240.22
2	FRONT BUMPER SIDE RETAINER	REPLACED	70.00	70.00
1	FRONT BUMPER LOWER AIR GRILLE	REPLACED	128.00	128.00
- 1	FRONT BUMPER LOWER CHROME MOULDING	REPLACED	168.58	168.58
1	FRONT BUMPER REINFORCEMENT	REPLACED	285.65	285.68
2	FRONT BUMPER REINFORCEMENT BRACKET	REPLACED	268.88	268.88
1	FRONT BUMPER SPONGE	REPLACED	108.48	108.48
1	FRONT BUMPER EMBLEM	REPLACED	55.10	55.10
1	FRONT BUMPER TOW HOOK COVER	REPLACED	50.00	50.00
16	FRONT BUMPER CLIP	REPLACED	128.00	50.00
4	FRONT BUMPER PDC SENSOR	REPLACED (2PCS ONLY)	637.36	318.68
4	FRONT BUMPER PDC SENSOR HOLDER	SERVICEABLE	117.60	1
1	FRONT BUMPER PDC SENSOR WIRE HARNESS	SERVICEABLE	184.95	
1	FRONT BUMPER RADAR SENSOR	REPLACED	631.85	631.8
1	FRONT BUMPER RADAR SENSOR BRACKET	REPLACED	39.15	39.1
2	FRONT BUMPER BRACKET	REPLACED	120.00	120.0
1	FRONT BUMPER LOWER COVER	REPLACED	228.23	228.2
8	FRONT BUMPER LOWER COVER CLIP	REPLACED	64.00	20.0
2	FRONT BUMPER LOWER COVER BRACKET	SERVICEABLE	136.32	
2	FRONT BUMPER FOG LAMP COVER GARNISH	SERVICEABLE	86.22	
1	FRONT GRILLE - OUTER	REPLACED	440.00	440.0
1	FRONT GRILLE - INNER	REPLACED	198.00	198.0
1	FRONT GRILLE OUTER GARNISH	REPLACED	292.45	292.4
1	FRONT GRILLE LOGO EMBLEM	REPLACED	122.74	122.7
- 1	FRONT GRILLE LOGO EMBLEM GARNISH	REPLACED	66.44	66.4
2	FRONT GRILLE CHROME	REPLACED	133.82	133.8
6	FRONT GRILLE CLIP	REPLACED	48.00	48.0
1	FRONT NUMBER PLATE PLINTH	REPLACED	58.66	58.6
2	HEADLAMP	REPLACED	1,569.88	1,569.8
2	HEADLAMP BRACKET	SERVICEABLE	242.96	

Report Ref No. CS3/AIG18018217/Ayd3e2-1



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	FRONT SUPPORT PANEL	REPLACED	596.97	596.97
2	FRONT SUPPORT PANEL SIDE AIR GRILLE GARNISH	REPLACED	84.22	84.22
1	FRONT TURBO INTERCOOLER	REPLACED	784.65	784.65
1	FRONT TURBO INTERCOOLER AIR GRILLE GARNISH	SERVICEABLE	98.11	
2	FRONT TURBO INTERCOOLER BRACKET	SERVICEABLE	29.20	14
-1	AIRCOND CONDENSOR	REPLACED	1,018.64	1,018.64
2	AIRCOND CONDENSOR SIDE AIR GRILLE GARNISH	REPLACED	223.48	223.48
1	RADIATOR ASSY	REPLACED	789.99	789.99
2	RADIATOR TOP MOUNTING	REPLACED	34.28	34.28
2	RADIATOR TOP MOUNTING CLIP	REPLACED	16.00	16.00
2	RADIATOR LOWER BRACKET	SERVICEABLE	100.00	10
1	RADIATOR COOLING FAN ASSY	REPLACED	703.26	703.26
-1	RADIATOR FILLER PIPE	SERVICEABLE	197.11	13
1	FRONT BONNET LOCK	SERVICEABLE	114.02	9
1	FRONT BONNET LOCK SENSOR SWITCH ASSY	SERVICEABLE	168.11	2
9	FRONT AIR CLEANER INLET DUCT	REPLACED	139.16	139.16
2	FRONT HORN ASSY	SERVICEABLE	220.00	3
9	TAILGATE ASSY	REPLACED	1,538.11	1,538.1
1	TAILGATE WEATHERSTRIP	REPLACED	168.16	168.16
2	TAILGATE RUBBER STOPPER	SERVICEABLE	23.60	19
1	TAILGATE UPPER LOCK	REPLACED	190.00	190.00
-11	TAILGATE LOWER LOCK STRIKER	NOT NECESSARY	66.81	53
1	TAILGATE INNER TRIMBOARD	REPLACED	363.11	363,11
- 1	TAILGATE LOWER EDGE TRIMBOARD	REPLACED	488.16	488.16
2	TAILGATE DAMPER	SERVICEABLE	580.00	
1	TAILGATE LOGO EMBLEM	REPLACED	48.00	48.00
1	TAILGATE A200 EMBLEM	REPLACED	60:00	60.00
14	REAR WINDSCREEN GLASS CLIP	REPLACED	112.00	50,0
2	TAILLAMP	REPLACED	1,075.98	1,075.9
2	TAILLAMP CLIP	REPLACED	16.00	16.00
11	REAR BUMPER ASSY	REPLACED	1,175.04	1,175.0
2	REAR BUMPER SIDE RETAINER	REPLACED	70.22	70.23
2	REAR BUMPER SIDE ATTACHMENT	REPLACED	58.32	58.33

Report Ref No. CS3/AIG18018217/Ayd3e2-1



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	REAR BUMPER CENTRE RETAINER	REPLACED	96.31	96.31
31	REAR BUMPER REINFORCEMENT	REPLACED	417.32	417.32
1	REAR BUMPER TOW HOOK COVER	REPLACED	60.00	60.00
6	REAR BUMPER PDC SENSOR	REPLACED (2PCS ONLY)	1,304.40	434.80
6	REAR BUMPER PDC SENSOR HOLDER	REPLACED	108.66	108.66
1	REAR BUMPER PDC SENSOR WIRE HARNESS	SERVICEABLE	279.11	
-1	REAR BUMPER LOWER DIFFUSER	REPLACED	290.00	290.00
2	REAR BUMPER LOWER BRACKET	REPLACED	96.28	96.28
10	REAR BUMPER CLIP	REPLACED	80.00	30.00
1	REAR END PANEL	REPAIRED SEE LABOUR	777.41	
1	REAR END PANEL TOP TRIM	REPLACED	199.68	199.68
4	REAR END PANEL TOP TRIM CLIP	REPLACED	32.00	10.00
1	REAR EXHAUST SILENCER	REPAIRED SEE LABOUR	1,296.48	54
1	REAR EXHAUST SILENCER HEAT SHIELD	REPLACED	88.17	88.17
2	REAR EXHAUST SILENCER MOUNTING	SERVICEABLE	79.32	1.5
	LESS 10% DISCOUNT		-	-1,823.58
			24,477.39	16,412.20
	SPECIAL NETT ITEMS			
1	TAILGATE C&C EMBLEM (SN)	REPLACED	58.00	58.00
1	SET REAR WINDSCREEN GLASS REPLACEMENT KIT (SN)	REPLACED	185.00	185.00
2	TAILLAMP SEALANT (SN)	REPLACED	100.00	40.00
1	FRONT NUMBER PLATE (EMBOSS) (SN)	REPLACED	29.00	29.00
1	FRONT NUMBER PLATE CASING (SN)	REPLACED	45.00	30.00
			417.00	342.00
	LABOUR			
	TO PROVIDE TOWING SERVICE USING "KING DOLLY".		120.00	110.00
	TO REMOVE / REFIT FRONT AND REAR WIRE HARNESS, ALL RELATED CONNECTORS, CHECK PROPER FUNCTION, FOCUS HEADLIGHTS.		180.00	150.00
	TO APPLY UNDERSEAL AND RUST-PROOFING ON THE AFFECTED AREAS.		280.00	60.00

Report Ref No. CS3/AIG18018217/Ayd3e2-1



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO REMOVE / REFIT BOOT GARNISHES, SPEAKERS, INTERIOR GARNISHES, CARPETS WHERE NECESSARY.		180.00	80.00
	TO PERFORM DIAGNOSTIC CHECKS ON CONTROL UNITS. RESET TO FACTORY SPECIFICATIONS.		380.00	150.00
	TO REMOVE / REFIT REAR WINDSCREEN GLASS.		180.00	120.00
	TO REMOVE / REFIT EXHAUST ASSEMBLY AND COOLING FAN ASSY WITH ALL ATTACHMENTS. BRACKETS AND HOLDERS.		280.00	80.00
	TO REMOVE / RENEW AIR-CON CONDENSER WITH ALL NECESSARY PIPES AND HOSES. VACUUM AND REPLENISH COOLING AGENT. CHECK FOR PROPER FUNCTION.		250.00	60.00
	TO REMOVE / RENEW RADIATOR ASSEMBLY WITH ALL CONNECTING HOSES. REPLENISH COOLING AGENT AND CHECK FOR PROPER FUNCTION (INCLUDE COOLANT).		250.00	60.00
	TO SET VEHICLE ON CHASSIS ALIGNMENT BENCH, INCLUSIVE OF ALL NECESSARY PREPARATORY WORKS.	NOT NECESSARY	380.00	8
	TO TRANSFER TAILGATE MECHANISMS WITH MOTOR ASSEMBLY AND ALL ATTACHMENTS.		250.00	80.00
	TO REMOVE / REFIX ENGINE FRONT TURBO INTERCOOLER. CHECK FUNCTION.		120.00	50.00
	TO SPRAY PAINT FRONT BUMPER FASCIA, FRONT MAIN GRILLE, FRONT BONNET, BOTH FRONT FENDERS, REAR BUMPER FASCIA, REAR END PANEL, REAR TRUNK LID. BOTH REAR FENDERS AND ETCS., INCLUSIVE OF PREPARATORY WORKS AND PAINTNG MATERIALS.		2,800.00	1,500.00
	TO REMOVE ALL DAMAGED PARTS WITH ALL NECESSARY COMPONENTS / ATTACHMENTS. TO APPLY HOT-WORKS WHERE NECESSARY, STRAIGHTEN CHASSIS MEMBERS, REPAIR / RESHAPE DENTED BODY PANELS, IN ACCORDANCE WITH FACTORY SPECIFICATIONS. REPLACE DAMAGED PARTS, REFIT AND ALIGN INTO POSITION. REFIT ALL NECESSARY COMPONENTS / ATTACHMENTS. INCLUSIVE OF THE REPAIR OF REAR END PANEL AND REAR EXHAUST SILENCER.		3,000.00	2,000.00
			8,650.00	4,500.00
	GRAND TOTAL		33,544.39	21,254.20



Page No.:5 of 5

RECOMMENDED COST OF LUMP SUM REPAIRS	17,000.00
(TO ITS PRE-ACCIDENT CONDITION)	
(AMOUNT AGREED AND ACCEPTED BY	
REPAIRER)	

Report Ref No. CS3/AIG18018217/Ayd3e2-1



ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatspeyer, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report in whole or in part, does so at his or her own risk.