

23000001

ASS. REC. BY:

REP: cslcr119017804/Rvd301

Special Instruction:

Supervisor: Rasul

ASSIGNMENT (Office)

Merimen

From (Person): chong Boon Sen

of CTI

Date/Time: 10/10/19 @ 9:45am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKN 9549X

Insured:

at Workshop n/s

Sng Ah Tee

Tel: 6268 6183

of Bldg 3 Pioneer Road North #01-18

Policy No: DMPCS N3034951804

Claim No: SNM19D204664

Sum Insured:

Excess: JBA 0

Make of Veh:

D.O.A. 3/10/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10:48am @ 10/10/19

Person Contacted:

Samantha

Vehicle: IN / OUT

Date/Time	Action/Instruction
	Validated ✓
	SKN 9549X - CS 3 / CTI 119017832 / Ccds
	SM: 210/2019

11/10/19	@ 9:23am Spoken to Janice, able to repair the vehicle at \$1200
11/10/19	@ 11:44am Samantha said she will check & call back
11/10/19	@ 4:34pm offer Darren LS \$4000, will check & call back
11/10/19	Revert via merimen, pending repair cost from repairer

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD TP WS TP RES OD RES EVA INV MV
 To Inspect Vehicle No: SKN 9549X
 at Workshop n/s SNH AH TEE
 of PIONEER ROAD NORTH
 Insured: CTI
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: TBA
 (Client's Record)
 Make of Veh: _____

Veh No: SKN 9549X Yr Regn: 2010/OCT
 Type: M.Car M.Cycle Bus Van Lorry Taxi Prime Mover /
 Truck / Trailer or _____
 Make: VOLVO S60 2.0 AT c.c. 1999
 Colour: RED A/C: Insured / Std / NI / NA
 Sp. Reading: 110870 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: 4U1FS 445BB 200 4992
 Gen. Cond: Good Fair Poor Burnt
 Steering: In order Jammed Leaked Burnt or _____
 Brake: In order Jammed Leaked Burnt or _____
 Modl: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 215/50R17
 R: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 27K 30K
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lim Sum: _____ % 3 Val.: Yes or No
 CA REV REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA M/C OHTSU / PIR / SUMI /
 TOYO / YOKO or _____

<u>Front</u>		<u>Rear</u>
R/Bal. <u>6</u> mm		R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm		L/Bal. <u>6</u> mm
D.O.A. <u>03/10/19</u>		D.O.I. <u>10/10/19</u>

Survey held at SNH AH TEE
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
FRONT O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
16/10/19	Recd email from Samantha unable to repair the limit amount
16/10/19	Revert vehicle TLH by merimen
16/10/19	Submit uneconomical TLH - mv: \$30K (EST) LTA: \$25,780 NV: \$4220
RECEIVED 16 OCT 2019	

Date/Time, File Pass to? : Prel. Report
 : Final Report
 1) _____
 Date/Time, File Return to?

Days Of Repair: _____

Resurvey No. of Trip: _____

1) 16/10 - typist

Add Fee: : Site Insp (\$) _____
 : Interview (\$) _____
 : Tech. Insp (\$) _____
 : Wheel end (\$) _____

Survey Fee:	<u>270</u>
Transportation:	_____
S + RS: \$	_____
Photos	_____
Other	_____
TOTAL	<u>270</u>

Report Format: _____

Lump Sum / E/B: _____

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Oct 2019 Sendback Est	08 Oct 2019 16:22 S\$15,098.55	10 Oct 2019 09:45 Assign				New Assignment Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	KOO YOON SEONG, ID: S2693102I, Tel: +6591519283, Email: KOOYOONSEONG@YAHOO.COM.SG		
Vehicle Reg. No.:	SKN9549X	Date of Loss:	03/10/2019 07:00 - :59 [107 Months and 8 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / SNM19D204664-SKN9549X-CBS	Policy/Cover Note No.:	DMPCSN3034951804 (Comprehensive) Coverage: 25/10/2018 - 24/10/2019
		Excess:	S\$0.00
Repairer:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18, 628457 Pioneer - Tel: 6268 6183		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 21/10/2019]		
Driver/Custodian:	KOO YOON SEONG (66 / Male) , NRIC: S2693102I, Tel: +6591519283 Email: KOOYOONSEONG@YAHOO.COM.SG		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:196607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8905 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd. 3 Anson Road #16-00 Springleaf Tower Singapore 079909	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Chong Boon Sen	Date: 16 Oct 2019

Preliminary Advice

Vehicle No	: SKN9549X	Accident Date	: 03/10/2019
Make	: VOLVO S60	Policy No.	: DMPCSN3034951804
Assignment Date	: 10/10/2019	Excess	: S\$0.00
Date of Inspection	: 10/10/2019	Est. Duration of Repair	: 9.00
Inspection At	: SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER) BLK 3 PIONEER ROAD NORTH, #01-18 SINGAPORE 628457		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,098.55
Revised Amount	:S\$	10,427.55
Check Items (Estimated)	:S\$	3,031.00
Total	:S\$	13,458.55
Lump Sum Repair	:S\$	
Total Loss Consideration		
New for Old Value	:S\$	
Pre-Accident Value	:S\$	30,000.00
COE / PARF Rebate	:S\$	25,780.00
Salvage Value	:S\$	
Margin for Repair	:S\$	4,220.00

Remarks

- The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- Other comments :

Veron Chen (LKKAUTO)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Wednesday, 16 October 2019 3:02 PM
To: SAMANTHA TAN; Veron Chen (LKKAUTO)
Cc: darren@sngahtee.com; assignments; Denise Tay (LKKAUTO)
Subject: RE: OD CALIM SKN9549X / DATE OF ACCIDENT: 3.10.09

Dear Samantha,

Thank you for your update.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: SAMANTHA TAN [mailto:sam@sngahtee.com]
Sent: Wednesday, October 16, 2019 2:56 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; veronchen@lkkauto.com
Cc: darren@sngahtee.com; 'assignments' <assignments@lkkauto.com>; 'Denise Tay (LKKAUTO)' <denisetay@lkkauto.com>
Subject: RE: OD CALIM SKN9549X / DATE OF ACCIDENT: 3.10.09

Hi All,

We are unable to repair with the limit amount.

Thank you.

Best Regards

Samantha Tan | sam@sngahtee.com

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD | BLK 3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457
TEL: 62686183 (4LINES) | FAX: 62681429 | Find us at <http://www.sngahtee.com>



From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Wednesday, 16 October 2019 12:00 PM
To: SAMANTHA TAN <sam@sngahtee.com>
Cc: darren@sngahtee.com; assignments <assignments@lkkauto.com>; Denise Tay (LKKAUTO) <denisetay@lkkauto.com>
Subject: RE: OD CALIM SKN9549X / DATE OF ACCIDENT: 3.10.09

Dear all,

Just following up if can repair or not?

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Chong Boon Sen
Sent: Monday, October 14, 2019 8:56 AM
To: 'SAMANTHA TAN' <sam@sngahtee.com>
Cc: darren@sngahtee.com; 'assignments' <assignments@lkkauto.com>; 'Denise Tay (LKKAuto)' <denisetay@lkkauto.com>
Subject: OD CALIM SKN9549X / DATE OF ACCIDENTI 3.10.09

Dear all,

Just following up on CTL/OD claim.

Understood from LKK last week Sng Ah Tee is checking on vehicle can be repaired?

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Veron Chen (LKKAuto)

From: SAMANTHA TAN <sam@sngahtee.com>
Sent: Wednesday, 16 October 2019 2:56 PM
To: 'Chong Boon Sen'; Veron Chen (LKKAuto)
Cc: darren@sngahtee.com; assignments; Denise Tay (LKKAuto)
Subject: RE: OD CALIM SKN9549X / DATE OF ACCIDENT: 3.10.09

Hi All,

We are unable to repair with the limit amount.

Thank you.

Best Regards

Samantha Tan | sam@sngahtee.com

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD | BLK 3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457
TEL: 62686183 (4LINES) | FAX: 62681429 | Find us at <http://www.sngahtee.com>



From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Wednesday, 16 October 2019 12:00 PM
To: SAMANTHA TAN <sam@sngahtee.com>
Cc: darren@sngahtee.com; assignments <assignments@lkkauto.com>; Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Subject: RE: OD CALIM SKN9549X / DATE OF ACCIDENTI 3.10.09

Dear all,

Just following up if can repair or not?

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Chong Boon Sen
Sent: Monday, October 14, 2019 8:56 AM
To: 'SAMANTHA TAN' <sam@sngahtee.com>
Cc: darren@sngahtee.com; 'assignments' <assignments@lkkauto.com>; 'Denise Tay (LKKAuto)'

<denisetay@lkkauto.com>

Subject: OD CALIM SKN9549X / DATE OF ACCIDENTI 3.10.09

Dear all,

Just following up on CTL/OD claim:

Understood from LKK last week Sng Ah Tee is checking on vehicle can be repaired?

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd. 3 Anson Road #16-00 Springleaf Tower Singapore 079909	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Chong Boon Sen	Date: 11 Oct 2019

Preliminary Advice

Vehicle No	: SKN9549X	Accident Date	: 03/10/2019
Make	: VOLVO S60	Policy No.	: DMPCSN3034951804
Assignment Date	: 10/10/2019	Excess	: S\$0.00
Date of Inspection	: 10/10/2019	Est. Duration of Repair	: 9.00
Inspection At	: SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER) BLK 3 PIONEER ROAD NORTH, #01-18 SINGAPORE 628457		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,098.55
Revised Amount	:S\$	10,427.55
Check Items (Estimated)	:S\$	3,031.00
Total	:S\$	13,458.55
Lump Sum Repair (ESTIMATED)	:S\$	10,750.00
Total Loss Consideration		
New for Old Value	:S\$	
Pre-Accident Value	:S\$	30,000.00
COE / PARF Rebate	:S\$	25,780.00
Salvage Value	:S\$	
Margin for Repair	:S\$	4,220.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : PENDING REPAIR COST FROM REPAIRER

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1021
Vehicle Details	
Vehicle No.:	5KN9549X
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Oct 2019
Vehicle Make:	VOLVO
Vehicle Model:	S60 2.0T AT ABS AIRBAG 2WD
Primary Colour:	Red
Manufacturing Year:	2010
Engine No.:	B4204T6202076
Chassis No.:	YV1F5445BB2004592
Maximum Power Output:	149.0 kW (199 bhp)
Open Market Value:	\$38,444.00
Original Registration Date:	25 Oct 2010
First Registration Date:	25 Oct 2010
Transfer Count:	1
Actual ARF Paid:	\$38,444.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Oct 2020
PARF Rebate Amount:	\$21,144.00
Intended COE Rebate Details	
COE Expiry Date:	24 Oct 2020
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$44,001.00
COE Rebate Amount:	\$4,636.00
Total Rebate Amount:	\$25,780.00

The information contained herein is correct as at 03 Oct 2019

OK

27,000

25,780

1,222

1 - 0.7
30,000

11,410



Volvo S60 Price Range Depreciation 2010 Vehicle Type

Advanced Search

Home » Used Cars » Dynamic Motoring » Volvo S60 2.0T

Volvo S60 2.0T

Overview Financial Insurance Accessories Similar Research Photos Map



Price	\$31,800	Reg Date	22-Dec-2010 (1yr 2mths 10days COE left)
Depreciation	\$11,410 /yr <small>View models with similar depre</small>	Manufactured	2010
Mileage	134,700 km (15.3k /yr)	Transmission	Auto
Road Tax	\$1,212 /yr	OMV	\$36,284
Dereg Value	\$25,929 as of today (change)	ARF	\$36,284
COE	\$49,890	Power	149.0 kW (199 bhp)
Engine Cap	1,999 cc	No. of Owners	2
Curb Weight	1,592 kg		

Type of Vehicle Luxury Sedan

Features

Powerful Inline 4 Cylinder Direct Injection Turbocharged Engine, 6 Speed Power Shift Gearbox, Keyless Push Start, Electric And Memory Seats, ABS View. View specs of the Volvo S60 (2010-2014)

Accessories

Premium Leather Seats, Multi Function Steering, Cruise Control, Electric Memory Seat.

Description

(100% Loan Available) Offer Bank Interest Rate From 1.98%. Best Value Buy! Tuned By Polestar Volvo Agent. Stylish Swedish Sports Sedan! Tops In Safety Ratings. Very Responsive, Superb Drive & Handling! Best For Short Terms, Very Well Maintained. White On Luxurious Brown Interior. Trade In Welcome. Free Servicing At Our Authorized Workshop. Immediate Viewing At Our Showroom Ready. Call Us Today.

Category

PARF Car

Status

Available

Resources



Vehicle Evaluation
Afraid of lemons? Request to have this car evaluated professionally. Find out more



Car Valuation - Free
Find out the market value of your existing car for free. Get started



Shortlist Report Error Compare More Actions Add note

Seller Information

Company	Dynamic Motoring dealer's pricelist 41 vech sold 42 vech available	
Address	8 Kaki Bukit Avenue 4 #04-25/26/27 <small>Search cars nearby this location</small>	
Location	Premier @ Kaki Bukit	
Website	www.dynamicmotoring.com.sg	
Office No	63866020	
Contact Person(s)	Dickson Adrian Jacky	82888567 88123478 97477375

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/10/2019 10:11
Date Of Accident	03/10/2019 07:30
Exact Location Of Accident	CLEMENTI AVE 6 BEF CLEMENTI LOOP JUNCTION
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKN9549X
Insured/Policyholder	
Name Of Registered Owner	KOO YOON SEONG
NRIC No	S2693102I
Email Address	KOOYOONSEONG@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-91519283
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	VOLVO
Model	S60-2.0 T (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN3034951804
Cover Note Number	

Driver

Name of Driver	KOO YOON SEONG
NRIC No	S2693102I
Date Of Birth	05/11/1952
Occupation	INDOOR
Date Of Driving Pass	31/12/1990
Driving Experience	28 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91519283
Fax Number	
Contact Number	OFFICE-NOPHONE
EMail Address	KOOYOONSEONG@YAHOO.COM.SG

Address	311C CLEMENTI AVE 4 #13-193
Postcode	123311
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 03/10/2019 AT AROUND 0730HRS, I WAS TRAVELLING ALONG CLEMENTI AVE 6. WHILE DRIVING ALONG THE ROAD THE TRAFFIC IS HEAVY AND I ON MY LANE STRAIGHT AND VEHICLE B WAS IN FRONT ME AND FILTER TO RIGHT LANE, BUT HE MAKE A HARD JAMMED BRAKE WHEN HE HAD ALREADY MOVE OUT TO THE RIGHT AND BY THE TIME I APPLY MY BRAKE ITS ALREADY TOO LATE AND CAUSED ME HIT ONTO HIS REAR LEFT PORTION. AFTER THE ACCIDENT I WENT DOWN TO CHECK AND FOUND THAT IT ALSO INVOLVED WITH VEHICLE C.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBH9155L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	RAIMMIE BIN ROHANI
NRIC/Passport Number	S7601490F
Contact Number	86206510
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SMN5261C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	THANG KOK WEI JOHN
NRIC/Passport Number	S7935500C
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

I AM AWARED THAT MY INSURER MAY HAVE A 14 DAYS TIMEFRAME FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY. I WILL CHECK MY POLICY FOR MORE DETAILS.

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Accident Circumstance.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Claim own policy
 Claim third party
 Claim OD / TP at other works hop
 For record purpose

Policy No. DMPSCW203495104
Insurer Gina Veh.No. SKW9549X



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sng Ah Tee Motor Pte Ltd
Blk 3 Pioneer Road North, #01-18,
628457

Insurer Reference:
Repairer Reference: SKN9549X-OD-CHINA
Date calculated: 08/10/2019 3:12 PM

Full Report
Registration: SKN9549X
Printed: 08/10/2019 3:12 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	DARREN SNG	Currency:	SGD
Claim Reference:		Date of Incident:	03/10/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	VOLVO
Model:	S 60 (F)
Sub Model:	BASE MODEL
Model Sheet Number:	41 32 01
Registration:	SKN9549X
VIN number:	YV1FS445BB2004592
Odometer:	

Model Specs

FROM VIN 002840	AUTO AIR CON	KEYLESS ENTRY	ILLUMINATED MIRROR
AUDIO SYS HIGH PERFO	AUTO DIPPING MIRROR	LEATHER SHIFT ROD	LEATHER SEATS
ELECTRIC LEFT SEAT	WDW CHANNEL CHROMED	RAIN SENSOR	ANTI THEFT ALARM
INT MIRROR AUTODIP	FRT BRAKE DISC 16"	REAR PARKING SYSTEM	2.0 LTR 149KW
FRONT DRIVE	POWERSHIFT	CRUISE CONTROL	TYRES 235/45 WR 17
WHEELS 8J X 17 ALLOY	TWO COAT METALLIC	PREPARE OFF VEHICLE	

Vehicle Condition


Vehicle Status

Pre-Accident Damage:

Date of Inspection:

Damage Areas

All
Underbody



Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
80203-0	R + R FRONT PANEL INCLUDES: R + R FRONT BUMPER		19.0	79.80
86170-2)	R + R FR/BUMPER ATTACHED PARTS		8.0	33.60
81110-3ZAX	R + R FRONT LOWER CROSSMEMBER		3.0	12.60
89702-2	RENEW FR NUMBER PLATE (REMOVED)		1.0	4.20
35203-2)	R + R LEFT HEADLAMP		1.0	4.20
35203-2)	R + R RIGHT HEADLAMP		1.0	4.20
35202-2	ADJUST HEADLAMPS		1.0	4.20
82311-3)	RENEW RADIATOR GRILLE		3.0	12.60
82151-2	RENEW BONNET INCLUDES: R + R BONNET, CONVERT ATTACHED PARTS, RENEW IF NECESSARY		6.0	25.20
82131-2	ADJUST BONNET		3.0	12.60
82111-2)	REMOVE AND REFIT L/BONNET LOCK		2.0	8.40
82112-2)	REMOVE AND REFIT R/BONNET LOCK		1.0	4.20
82116-2)	R + R BONNET CABLE		6.0	25.20
82125-2)	RENEW BONNET HOOK		1.0	4.20
82114-2)	R + R LEFT BONNET HINGE		1.0	4.20
82114-2)	R + R RIGHT BONNET HINGE		1.0	4.20
80201-0)	RIGHT FRONT WING R + R INCLUDES: R/F WHEELHOUSE COVER, R/SILL PANEL COVER, R/A-PILLAR COVER REMOVE AND REFIT		6.0	25.20
31115-3	R + R BATTERY		1.0	4.20
87003-2	DRAIN + REFILL AIR CONDITIONING		8.0	33.60
26118-2	R + R OVERFLOW TANK		3.0	12.60
26104-2)	R + R RADIATOR		5.0	21.00
26121-3	R + R L/RADIATOR BRACKET		1.0	4.20

Code	Description	WU	Price SGD
26121-3	R + R R/RADIATOR BRACKET	1.0	4.20
87408-2)	R + R CONDENSER	5.0	21.00
NO NUMBER	R + R RADIATOR FILLER HOSE	3.0	12.60
21581-2	R + R DRIVE BELT	2.0	8.40
86310-2	R + R FRONT LOWER AIR GUIDE	1.0	4.20
64534-2	R + R OIL TANK POWER STEERING	3.0	12.60
77061-2	R + R RIGHT FRONT WHEEL	1.0	4.20
64531-2)	R + R RETURN HOSE	7.0	29.40
64518-2)	R + R POWER STEERING PUMP	5.0	21.00
64525-2)	R + R COOLING PIPE POWER STEERING	6.0	25.20
Labour Cost		Hrs	WU
Panel / Mechanical Labour		11.60	116.0
Total of Labour			487.20

Paint

Code	Description - TWO COAT METALLIC	WU	Price SGD
Paint Work		Time Basis 10 WU/h	
SYSTEM AZT			
	BONNET NEW PART PAINTING	26.0	
	R/F WING NEW PART PAINTING	9.0	
	FRT LWR CROSSMEMBER SURFACE PAINT	4.0	
	FRONT BUMPER NEW PART PAINT K1R	14.0	
	FRT TOWING EYE COVER NEW PART PAINT K1R	3.0	
	L/F WING SURFACE PAINT	5.0	
	RIGHT FRONT DOOR SURFACE PAINT	8.0	

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	85.66
0742	R/F WING NEW PART PAINTING	17.03
1001	FRT LWR CROSSMEMBER SURFACE PAINT	2.99
0283	FRONT BUMPER NEW PART PAINT K1R	68.39
0303	FRT TOWING EYE COVER NEW PART PAINT K1R	0.49
0741	L/F WING SURFACE PAINT	8.22
1482	RIGHT FRONT DOOR SURFACE PAINT	21.17

Labour Cost - Paint

	Hrs	WU	Price SGD
Factor			
Time Paint		69.0	
Preparation Main Work Metal	2.50	25.0	105.00
Preparation Comp. Work Plastic	0.50	5.0	21.00
Total	10 WU/h	9.90	415.80

Material Cost - Paint

New Part Painting	102.69
New Part Painting - Plastic K1R	68.88
Surface-/Blend Paint	32.38
Material-constant Metal Preparation	28.60
Material-constant Plastic	9.00
Total	241.55

Spare Parts

				prices as at 2001-01-01
Code	Description	Part Number	Supplier	Price SGD
0257	FRONT NUMBER PLATE	KNPL3	scu /	35.00
0283	FRONT BUMPER	39802501	TKW /	1,500.00
0303	FRT TOWING EYE COVER	39802519	MU /	45.00
0326	R/F BUMPER BRACKET	31323426	neu /	45.00
0378	R/F BUMPER COVER	31294130	scu /	55.00
0396	R/F LWR BUMPER TRIM	31283097	X SVC	30.00
0410	GRILLE	30795039	gra /	500.00
0444	R/F AIR DUCT	30796467	.	95.00
0471	BONNET	31335350	buu /	1,700.00
0475	L/BONNET HINGE	31385812	?	80.00
0476	R/BONNET HINGE	31385813	BT /	80.00
0481	BONNET INSULATION	30715826	de /	500.00
0494	SAFETY LATCH	31425791	bt /	85.00
0497	L/F BONNET STRUT	31278769	?	115.00
0498	R/F BONNET STRUT	31278769	?	115.00
0500	BONNET CABLE	31385848	cut /	70.00
0503	L/BONNET LOCK	31425975	bt /	120.00
0504	R/BONNET LOCK	31371016	bt /	120.00
0561	LEFT HEADLAMP ASSY	31383068	pro /	650.00
0562	RIGHT HEADLAMP ASSY	31383069	?	700.00
0696	R/DAY RUNNING LAMP	31278558	gra /	140.00
0742	R/F WING	31352074	bt /	600.00
0842	R/F WHEELHOUSE COVER	31497105	requir	190.00
1001	FRT LWR CROSSMEMBER	31349058	?	900.00
1017	FRONT PANEL	31283053	pro /	900.00
4465	CONDENSER	31332027	bt /	800.00
7461	POWER PUMP EXCH	36001204	scu X scu	800.00
7479	POWER STRG OIL TANK	30680756	gra /	80.00
7480	P/STRG COOLING COIL	31302549	X scu	600.00
7485	STRG INLET PIPE	31201112	bt /	300.00
7755	L/UPP RADIATOR BRKT	30723366	?	85.00
7756	R/UPP RADIATOR BRKT	30723367	?	85.00
7760	RADIATOR EXCH	31368082	gra /	600.00
7769	L/RADIATOR BRACKET	31261931	?	68.00
7770	R/RADIATOR BRACKET	31261932	?	68.00
7774	EXPANSION TANK HOSE	31202747	cut /	78.00
7787	EXPANSION TANK	31200321	de /	80.00
7789	ELECTRIC FAN	31368867	.	720.00
9974	POWER STEERING OIL	NO NUMBER	neu /	70.00

f: OEM Parts
n: Non-OEM Parts
u: Used parts

Savings	0.00
Subtotal	13,804.00
Fixed Sundry Parts Price	100.00

Total **13,904.00**

Extras

Code	Description	Price SGD
1000	TOP UP AIRCON GAS -	30 50.00*
	Total Extras	50.00

Final Calculation

	SGD	SGD
Parts	13,804.00	
Fixed Sundry Parts Price	100.00	
Total Parts		13,904.00
Labour Time Base 10 WU/h		
Total 116.0 WU X 42.00 SGD/h	487.20	
Total of Labour		487.20
Total Of Extras		50.00
Paint Work Time Base 10 WU/h		
Labour Cost 99.0 WU X 42.00 SGD/h	415.80	
Material Cost	241.55	
Total Paint Including Material		657.35
Repair Cost Excludes GST		15,098.55
GST (+7.0%)		1,056.90
Repair Cost Included GST		16,155.45

Comments

- * - USER SUPPLIED DATA
- NN - NO MANUFACTURERS CODE EXISTS
-) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

LRK Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No original modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorised by Repairer
Signature:
Date:

Rasul
Hp 90010068
9 days
L/S
10/10/19 @ 1700
EXCESS: TBA
Revert
Resurvey after repair

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Oct 2019 Sendback Est	08 Oct 2019 18:22 \$15,098.55	10 Oct 2019 09:45 Edit Adj Rpt	\$10,427.55 Edit Estimates	\$10,427.55 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: KOO YOON SEONG , ID: S2693102I, Tel: +6591519283, Email: KOOYOONSEONG@YAHOO.COM.SG									
Vehicle Reg. No.:	SKN9549X	Date of Loss:	03/10/2019 07:00 - :59 [107 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / SNM19D204664-SKN9549X-CBS	Policy/Cover Note No.:	DMPCSN3034951804 (Comprehensive) Coverage: 25/10/2018 - 24/10/2019						
		Excess:	\$0.00						
Repairer:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Bldg 3 Pioneer Road North, #01-18, 628457 Pioneer - Tel: 6268 6183								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 21/10/2019]								
Driver/Custodian:	KOO YOON SEONG (66 / Male), NRIC: S2693102I, Tel: +6591519283 Email: KOOYOONSEONG@YAHOO.COM.SG								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• CHINA_TAIPING (16/10/2019): Alert - Adj Mandate Maintained - SKN9549X - Claim Handler: Chong Boon Sen									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SKN9549X (SNM19D204664-SKN9549X-CBS)

OD

Oct 3 2019 7:00AM

[KOO YOON SEONG]

Sng Ah Tee Motor & Panel Service Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View	View in Browser
Video										
1 per page <input type="checkbox"/>										
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)		Thumbnail	Print					
1	03/10/19 15:29	Video - Accident [Linked Accident Report Documents]	1	Load MP4						
Assessment Reports										
1 per page <input type="checkbox"/>										
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)		Thumbnail	Print					
1	03/10/19 15:32	Accident Statement	1	Load HTM						
2	08/10/19 18:22	Repairer Estimates	1	Load HTM						
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	11/10/19 17:18	Adjuster Immediate Advice	1	Load HTM						
2	15/10/19 15:22	Adjuster Immediate Advice	1	Load HTM						
Photos/Images										
1 per page <input type="checkbox"/>										
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)		Thumbnail	Print					
1	03/10/19 15:28	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>					
2	03/10/19 15:28	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>					
3	03/10/19 15:28	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>					
4	03/10/19 15:28	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>					
5	03/10/19 15:28	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>					
6	03/10/19 15:28	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>					
7	03/10/19 15:28	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>					
8	03/10/19 15:28	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>					
9	03/10/19 15:28	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>					
10	03/10/19 15:28	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>					
11	03/10/19 15:28	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>					
12	03/10/19 15:28	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>					
13	03/10/19 15:28	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>					
14	03/10/19 15:28	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>					
15	03/10/19 15:28	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>					
16	03/10/19 15:28	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>					
17	03/10/19 15:28	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>					
18	03/10/19 15:28	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>					
19	03/10/19 15:28	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>					
20	03/10/19 15:28	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>					
21	03/10/19 15:28	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>					
22	03/10/19 15:28	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>					
23	03/10/19 15:28	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	11/10/19 10:22	General View	1	Load PDF						
Documentation										

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	03/10/19 15:32	Sketch Plan [Linked Accident Report Documents]	Load TIF	
2	08/10/19 15:37	CI,IC,DL	Load TIF	
3	08/10/19 15:37	AUDATEX	Load PDF	
4	08/10/19 15:37	E-filed GIA report	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/10/19 10:22	MARK ESTIMATE	Load PDF	

Linked Accident Report Documents

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	03/10/19 15:29	Video - Accident	Load MP4	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	03/10/19 15:32	Accident Statement	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	03/10/19 15:28	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	03/10/19 15:28	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	03/10/19 15:28	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	03/10/19 15:28	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	03/10/19 15:28	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	03/10/19 15:28	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	03/10/19 15:28	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	03/10/19 15:28	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	03/10/19 15:28	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
10	03/10/19 15:28	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
11	03/10/19 15:28	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
12	03/10/19 15:28	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
13	03/10/19 15:28	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
14	03/10/19 15:28	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
15	03/10/19 15:28	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
16	03/10/19 15:28	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
17	03/10/19 15:28	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
18	03/10/19 15:28	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
19	03/10/19 15:28	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
20	03/10/19 15:28	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
21	03/10/19 15:28	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
22	03/10/19 15:28	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
23	03/10/19 15:28	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	03/10/19 15:32	Sketch Plan	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Repairer Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CT119017884/R1VD3E2

Date: 16/10/2019

REFERENCE

Insured/Claimant:	KOO YOON SEONG	Policy No:	DMPCSN3034951804	Claim No:	SNM19D204664-SKN9549X-CBS
Date of Loss:	03/10/2019	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKN9549X	Engine No:	B4204T6202076
Make & Model:	VOLVO S60, 2.0 T (A)	Chassis No:	YV1FS445BB2004592
Reg. Date:	25/10/2010 (Man, Year: 2010)	Odometer:	110870 km
Colour:	Red		
Engine Capacity:	1999 cc		
Market Value/New Car Price:	S\$30,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/50 R17	Rear Tyre Size:	215/50 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth.

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,904.00	9,253.00	4,651.00	33.45
Miscellaneous Items	50.00	30.00	20.00	40.00
Paintwork Materials	241.55	241.55	0.00	0.00
Labour	487.20	487.20	0.00	0.00
Paintwork Labour	415.80	415.80	0.00	0.00
Towing	0.00	0.00	0.00	
Gross Total (S\$)	15,098.55	10,427.55	4,671.00	30.94
+ GST 7.00/0.00% (S\$)	1,056.90	0.00	1,056.90	100.00
Nett Amount (S\$)	16,155.45	10,427.55	5,727.90	35.45

INSPECTION

Date of Assignment:	10/10/2019 Present Location:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)
Date Inspected:	10/10/2019 Inspected At:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18 Singapore 628457
Estimated Period of Repair:	0.0 days	

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(EXCLUDE CHECK ITEMS S\$3,031.00 NETT)

TOTAL LOSS ASPECT

Market Value :	\$30,000.00
OMV :	\$38,444.00
PARF Rebate (1) :	\$21,144.00
Quota Premium Paid :	\$44,001.00
COE Rebate (2) :	\$4,636.00
Total Rebate (1) + (2) = :	\$25,780.00

The total amount incurred will be Market Value \$30,000.00 minus Total Rebate \$25,780.00 = \$4,220.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 16 Oct 2019)
Parts: 143	VOLVO S60 2.0 T (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKN9549X)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SPARE PARTS		13,904.00 F	*9,253.00 F
					Total Parts (S\$)	13,904.00
						9,253.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Materials				
1	1	TOTAL PAINT / MATERIAL	241.55	241.55
Miscellaneous Items				
2	1	SPARE PARTS SPECIAL NETT	50.00	30.00
Sub Total (S\$)			291.55	271.55

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	TOTAL PAINTWORK	New	415.80	415.80
Labour Items				
2	TOTAL PANEL / MECHANICAL	New	487.20	487.20
Gross Labour Cost (S\$)			903.00	903.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >