

ASS. REC. BY:

REF: CS/MSG19017888/Uad3/12 Special Instruction:

Sinear: Marcus

ASSIGNMENT (Office)

From (Person):

Meximen Irene Tan

of

MSGDate/Time: 9/10/19 @ 4.5pm

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SBU 72H

Insured:

SGV 230D

at Workshop m/s

Zoom Autowerks

Tel:

9450 7920

of

130 Bedok Reservoir Road

Policy No:

1000871705

Claim No:

231 867

Sum Insured:

Excess:

Make of Vch:

(Client's Record)

D.O.A. 6/10/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10.17am @ 10/10/19

Person Contacted:

Vehicle IN/OUT

Date/Time

Action/Instruction

Is done? ☒SBU 72H - NA / AIG 19017645 / 24DOA: 6/10/19SGV 230D - NA / AIG 19017645 / 24DOA: 6/10/201911/10/19 @11.20am informed Irene, we are pending estimate from repairer16/10/19 @11.17am revised to Irene Tan via Meximen.

(08/11/13) wef
ASS. REC. BY: *Marius*

REF:

MS14

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: *SBU 72H*
at Workshop m/s: *room*
of _____
Insured: _____
Policy No.: _____
Claims No.: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: *37*
IDAC Accident Rpt: Consistent? : Yes or No
GIA / PR Seen: Consistent? : Yes or No
Est. Repairs: *2* days Res.: Yes or No
Lum Sum: *20* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Date / Time Action / Instruction *Dep 12th 1911 Ant.*
only minor LRA 2750g

15/10/19 confirmed L/S \$ 1050 with Elin (LRA \$ 8908.56, 89%)

RECEIVED 17 OCT 2019

Veh No: *SBU 72H* Yr Regn: *6 11*
Type: *Car* / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or *LA*
Make: *Volkswagen Scirocco* c.c. *1984*
Colour: *white* A/C: Insured / Std / NI / NA
Sp. Reading: *76181* T/Radio: Insured / Std / NI / NA
Eng/No: _____

C/No: *WVWZZZ13ZBV011951*
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: *235/35R19*
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front: *6* mm Rear: *6* mm
R/Bal. *6* mm L/Bal. *6* mm
D.O.A. *6/10/19* D.O.I. *10/10/19*
Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
O/S Ant.
The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to? ☐ : Preli. Report
12/10 1911 Ant ☐ : Final Report

Days Of Repair: *2*
Resurvey No. of Trip: *1* Survey Fee: _____
Transportation: _____

Date/Time, File Return to? _____
Add Fee: ☐ : Site Insp (\$ _____) \$ + R.S. \$ _____
☐ : Interview (\$ _____) Photos
☐ : Tech. Invs (\$ _____) Others
☐ : Weekend (\$ _____)
Report Format: *MER-TP*
Lump Sum / I.B.I. (\$) *1050*

TOTAL

150
11
161

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 16 Oct 2019

Preliminary Advice

Insured Vehicle No	: SGV230D	Accident Date	: 06/10/2019
TP Vehicle No	: SBU72H	Assignment Date	: 09/10/2019
Make	: VOLKSWAGEN SCIROCCO	Est. Duration of Repair	: 2.00
Date of Inspection	: 10/10/2019		
Inspection At	: ZOOM AUTOWERKS PTE LTD (BEDOK) 130 BEDOK RESERVOIR ROAD, #08-1339 SINGAPORE 470130		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,958.56
Revised Amount	:S\$	1,316.86
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,316.86

Lump Sum Repair	:S\$	1,050.00
-----------------	------	----------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Oct 2019		09 Oct 2019 16:45 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	Chua Geok Lan, ID: S1462254C, Tel: +6597391698, Email: chuageoklan@mpuni.com.sg		
Main Claimant:	TERENCE HO HIN NGEE, ID: S1472907J		
Vehicle Reg. No.:	SBU72H	Date of Loss:	06/10/2019 21:00 - :59 [99 Months and 22 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 231867	Policy/Cover Note No.:	1000871705 (Comprehensive) Coverage: 21/12/2018 - 20/12/2019
Vehicle Reg. No. (Insured):	SGV230D	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Zoom Autowerks Pte Ltd (Bedok) 130 Bedok Reservoir Road, #08-1339, 470130 Eunos - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 10/10/2019]		
Driver/Custodian (Insured):	Poh Tze Hui, Uraiana (), NRIC: S8901569C, Tel: +6598769786 Email:		
Adj Asg. Remarks:	on WP. Liab: clear. Agree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: Elin Cai @ 9450 7920.		

ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAuto)

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Friday, 11 October 2019 11:20 AM
To: do-not-reply@merimen.com
Cc: SUR
Subject: TP VEHICLE SBU 72H (YOUR REF: 231867)

This mail is associated with :

***SBU72H (231867)**
[SGV230D]

TP

TERENCE HO HIN NGEE

Oct 6 2019 9:00PM

[Chua Geok Lan]

Zoom Autowerks Pte Ltd

Dear Irene,

Please be informed that we have inspected the vehicle SBU 72H on 10/10/2019.

We are pending for estimate from repairer.

Thanks & Regards,

Shiau Chan (Ms)
LKK Auto Consultants Pte Ltd
Tel: 6256 3561

This is an auto-generated email. Do not reply to this email.

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)



AVG

This email has been checked for viruses by AVG antivirus software.
www.avg.com

**2-HR
FREE
WEEKDAY PARKING**



**Spend \$30 to qualify
NOW TILL 15 NOV 2019**
[MON - FRI, 6PM - 10PM]

CLICK TO FIND OUT MORE

Post an Advertisement

Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Mercedes-Benz S-Class S63 Coupe AMG 4MATIC At \$59...



One And Only Unit In Market!
Immaculate Condition!
StarAd

▪ Free VICOM evaluation
▪ Free grooming and 6 months maintenance
▪ In-house workshop ensures quality
▪ Member of SVTA and hire purchase
▪ 100% deposit refund for unapproved

YONG LEE SENG

Post an Ad

Advertiser Login

Ways of Selling

Browse by Category

« Back (1 2) Next »

Sort by Date Posted

21 vehicles

Scirocco

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh T
Search Selection	Scirocco		Any	Any	2011	Any	Any	/
	Volkswagen Scirocco 1.4A TSI		\$31,888	\$8,830 /yr	05-Dec-2011	1,390 cc	180,000 km	Sf
Lowest Depreciation In The Market! 6 Months Gearbox Warranty From Monster Tune! Do Not Miss This Best Value Scirocco Deal. Super Smooth Drive! Test To Believe. Loan Available. Trade In Welcome, Call/SMS/WhatsApp For A Viewing And Test Drive Now!								
Posted: 10-Oct-2019			Tags: 2011 Volkswagen Scirocco, 2011 volkswagen scirocco, Volkswagen Scirocco, volkswagen scirocco, Volkswagen, Scirocco, scirocco, Used Volkswagen					
	Volkswagen Scirocco R 2.0A		\$41,800	\$18,180 /yr	09-Feb-2011	1,984 cc	-	Sf
Well Maintained, Owner's Consignment! Owner Selling Due To Upgrading! Cleanest And Problem Free Unit. Healthy Engine And Gearbox, No Repairs Or Wear And Tear To Be Done. Come View To Believe It's Condition. No Messy Modifications, Fully Legal And Not A Dekitted...								
Tan Wei Auto Pte Ltd			Posted: 09-Oct-2019					
			Tags: 2011 Volkswagen Scirocco, 2011 volkswagen scirocco, Volkswagen Scirocco, volkswagen scirocco, Volkswagen, Scirocco, scirocco, Used Volkswagen					
	Volkswagen Scirocco 1.4A TSI		\$24,800	\$9,500 /yr	21-Jan-2011	1,390 cc	70,000 km	Sf
Low Mileage Unit! Pre-Owned By An Expatriate For Weekend Use Only. Selling Due To Returning To Home Country. Vehicle Extremely Well Maintained By Ex-Owner. No Repairs Needed And Good Driving Condition Guaranteed. Purchase Comes With 6 Months Warranty A...								
Posted: 07-Oct-2019			Tags: 2011 Volkswagen Scirocco, 2011 volkswagen scirocco, Volkswagen Scirocco, volkswagen scirocco, Volkswagen, Scirocco, scirocco, Used Volkswagen					
	Volkswagen Scirocco 2.0A TSI		\$31,888	\$12,690 /yr	11-Jan-2011	1,984 cc	143,000 km	Sf
Lowest Depreciation! Reasonably Price And Very Rare Unit With Low Mileage Done! Cover Just Change Gearbox And Mechatronic Unit And Many More. 100% Loan Approval Rate. Pristine Showroom Condition With No Chassis Or Structural Damage. STA/Agent Evaluation Welc...								
Posted: 05-Oct-2019			Tags: 2011 Volkswagen Scirocco, 2011 volkswagen scirocco, Volkswagen Scirocco, volkswagen scirocco, Volkswagen, Scirocco, scirocco, Used Volkswagen					

**GET YOUR
COE
RENEWAL
LOAN**

Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and approval in 2 days without effort! Enquire today.

Volkswagen Scirocco 1.4A TSI **\$56,888** **\$5,680 /yr** **11-Jan-2011** **1,390 cc** - Sf
v 10-yr COE)

Compare

ears Coe! Stock & Tip Top Conditions! Various Loan Packages Avail! Trade In Welcome! Hurry Down To View This Beauty! Call

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	907J
Vehicle Details	
Vehicle No.:	SBU72H
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Oct 2019
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	SCIROCCO 2.0L AT TSI 1379V3
Primary Colour:	White
Manufacturing Year:	2010
Engine No.:	CCZ091429
Chassis No.:	WVWZZZ13ZBV011951
Maximum Power Output:	155.0 kW (207 bhp)
Open Market Value:	\$30,860.00
Original Registration Date:	14 Jun 2011
First Registration Date:	14 Jun 2011
Transfer Count:	3
Actual ARF Paid:	\$30,860.00 15430
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Jun 2021
PARF Rebate Amount:	\$16,973.00
Intended COE Rebate Details	
COE Expiry Date:	13 Jun 2021
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$63,000.00
COE Rebate Amount:	\$10,535.00
Total Rebate Amount:	\$27,508.00

The information contained herein is correct as at 11 Oct 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/10/2019 17:47
Date Of Accident	06/10/2019 21:35
Exact Location Of Accident	95 FRANKEL AVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SBU72H
Insured/Policyholder	
Name Of Registered Owner	TERENCE HO HIN NGEE
NRIC No	S1472907J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98330253
Alternative Phone No	OFFICE-98330253

Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	SCIROCCO 2.0L AT TSI 1379V3
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1700060103-01
Cover Note Number	

Driver

Name of Driver	HO REN JIE, TROY
NRIC No	S9233709Z
Date Of Birth	14/09/1992
Occupation	INDOOR
Date Of Driving Pass	14/09/2011
Driving Experience	8 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98330253
Fax Number	
Contact Number	OFFICE-98330253
Email Address	NOEMAIL

Address 37B JERVOIS ROAD
 Postcode 249022
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured CHILDREN
 Vehicle Registration Number of Driver's Own Vehicle -
 Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance?
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 0

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SGV230D
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number 98769786
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver) 1

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:


Accident Sketch Plan

SKETCH PLAN

VEHICLE A: SBU 72 H

VEHICLE B: SGV 230 D

[45 Frankel Ave]



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date & time, I, vehicle 'A', SBU 72 H, was stationary on the stated venue. As I was outside 45 Frankel Avenue, vehicle 'B', SGV 230 D, collided onto my vehicle's light portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NAIC/PIN No.:

Scanned by CamScanner



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road, Eunos Spring
#08-1339 Singapore 470130
Tel: 9450 7920
zoomautowerks@gmail.com

Car Number: SBU72H

Date: 09/10/2019

Model: VOLKSWAGEN SCIROCCO

Damaged Area: (Front Right Side Damaged)

Repairer Estimation Cost of Repair :

Supplementary may be included during the cost of repair :

not Affected
2/5 \$1050
10/10/19
2 day
light. After repair

Parts / Material :

	Quantity			
1 Front Bumper	1/c	7011	\$ 1,625.00	X
2 Front Bumper Side Bracket RH	17		\$ 94.60	X
3 Front Bumper Retainer RH	17		\$ 92.00	X
4 Front Bumper Clips	\$6.00 X 10pcs	17	\$ 60.00	X
5 Front Headlamp Assy RH	17		\$ 1,722.60	X
6 Front Headlamp Bracket RH	17		\$ 80.20	X
7 Front Fender Inner Shield	17		\$ 284.00	X
8 Front Fender Inner Shield Clips	\$6.00 X 10pcs	17	\$ 60.00	X
9 Front RH Wing Mirror Assy	885-40	CRP/Day	908.00	✓
10 Front RH Door Outer Glass Moulding	17		\$ 214.00	X
11 Right Rocker Garnish	17		\$ 498.00	X
12 Right Rocker Garnish Clips	\$6.00 X 10pcs	17	\$ 60.00	X
13 Front RH Fender - Repair	17		\$ -	X
14 Front RH Door - Repair	17		\$ -	X
Parts :			\$ 5,698.40	
Less Parts 10% :			\$ 569.84	
Total Parts :			\$ 5,128.56	

Special Net Items :

Front RH Sport RIM

Front RH Tyre

17	\$ 1,280.00	X
17	\$ 550.00	X
Total S/N Parts :		\$ 1,830.00

Labour :

To Remove & Renew Front RH Affected Accident Areas

To Putty, Spray Paint on Front RH Affected Accident Areas

To Check & Re-Connect all electrical wiring

To Conduct Computerised Wheel Alignment

To Remove & Renew Front RH RIM & Tyre

To Re-Programme & Reset Diagnostic

To Rust Proof Affected Areas

\$	1,200.00	200
\$	1,100.00	300
\$	50.00	20
\$	200.00	X
\$	100.00	X
\$	250.00	X
\$	100.00	X
Total Labour : \$		3,000.00

2. 885-40
102
1-79686
1-520.00

TOTAL PARTS :	\$ 5,128.56
TOTAL SPECIAL NET ITEM:	\$ 1,830.00
TOTAL LABOUR :	\$ 3,000.00
TOTAL REPAIR COST :	<u>\$9,958.56</u>

DATE OF SURVEY / INSPECTED:

RECOMMENDED PART BY PART / LUMP SUM :

RECOMMENDED NUMBER OF DAYS :

SURVEY BY / SURVEYOR FIRM :

RE-SURVEY DISMANTLE PARTS / BEFORE PAINT / AFTER PAINT :

FINALISED AMOUNT :

Let Auto Consultants hence notify the Repairs of the following:

- * Repairs to be done after spray painting
- * Repairs to be done part(s) during survey
- * Repairs to be done after survey
- * Repairs to be done after "No Fault Prejudice" tests
- * Repairs to be done after survey
- * Repairs to be done after survey

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19017888/UQD3N2

Date: 17/10/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1000871705
Claimant Vehicle No :	SBU72H	Insured Vehicle No :	SGV230D
Date of Loss:	06/10/2019	Nature of Claim:	TP
		Claim No:	231867

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBU72H	Engine No:	CCZ091429
Make & Model:	VOLKSWAGEN SCIROCCO, 2.0 TSI (A)	Chassis No:	WVWZZZ13ZBV011951
Reg. Date:	14/06/2011 (Man. Year: 2010)	Odometer:	76181 km
Colour:	White		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/35 R19	Rear Tyre Size:	235/35 R19
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	6,958.56	796.86	6,161.70	88.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,000.00	520.00	2,480.00	82.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,958.56	1,316.86	8,641.70	86.78
Approved Total (Overridden) (S\$)		1,050.00		
Nett Amount (S\$)	9,958.56	1,050.00	8,908.56	89.46

INSPECTION

Date of Assignment:	09/10/2019	
Date Inspected:	10/10/2019	Inspected At:
		Zoom Autowerks Pte Ltd (Bedok)
		130 Bedok Reservoir Road, #08-1339
		Singapore 470130

Estimated Period of Repair: 2.0 days**Adjuster:** MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Oct 2019)
Parts:	144	VOLKSWAGEN SCIROCCO 2.0 TSI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBU72H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (TORN)	Not Consistent With The Impact	1,625.00 FL	*- FL
2	1		*FRONT BUMPER SIDE BRACKET RH	Not Necessary	94.60 FL	*- FL
3	1		*FRONT BUMPER RETAINER RH	Not Necessary	92.00 FL	*- FL
4	10		*FRONT BUMPER CLIPS	Not Necessary	60.00 FL	*- FL
5	1		*FRONT HEADLAMP ASSY RH	Not Necessary	1,722.60 FL	*- FL
6	1		*FRONT HEADLAMP BRACKET RH	Not Necessary	80.20 FL	*- FL
7	1		*FRONT FENDER INNER SHIELD	Not Necessary	284.00 FL	*- FL
8	10		*FRONT FENDER INNER SHIELD CLIPS	Not Necessary	60.00 FL	*- FL
9	1		*FRONT RH WING MIRROR ASSY	Cracked/Damaged	908.00 FL	*885.40 FL
10	1		*FRONT RH DOOR OUTER GLASS MOULDING	Not Necessary	214.00 FL	*- FL
11	1		*RIGHT ROCKER GARNISH	Not Necessary	498.00 FL	*- FL
12	10		*RIGHT ROCKER GARNISH CLIPS	Not Necessary	60.00 FL	*- FL
13	1		*FRONT RH FENDER (NPA)	Not Necessary	0.00 FL	*- FL
14	1		*FRONT RH DOOR (NPA)	Repair	0.00 FL	*- FL
15	1		*FRONT RH SPORT RIM	Not Necessary	1,280.00 FS	*- FS
16	1		*FRONT RH TYRE	Not Necessary	550.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,528.40	885.40
- List Item Discount on L Items 10.00/10.00% (\$\$)	569.84	88.54
Total Parts (\$\$)	6,958.56	796.86

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & RENEW FRONT RH AFFECTED ACCIDENT AREAS	New	1,200.00	200.00
2	TO PUTTY, SPRAY PAINT ON FRONT RH AFFECTED ACCIDENT AREAS	New	1,100.00	300.00
3	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING	New	50.00	20.00
4	TO CONDUCT COMPUTERISED WHEEL ALIGNMENT	New	200.00	0.00
5	TO REMOVE & RENEW FRONT RH RIM & TYRE	New	100.00	0.00
6	TO RE-PROGRAMME & RESET DIAGNOSTIC	New	250.00	0.00
7	TO RUST PROOF AFFECTED AREAS	New	100.00	0.00
Gross Labour Cost (S\$)			3,000.00	520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >