- MASAGI	Adran Assignmen	1489/ Aq NT (Office)	
From (Person	Tan kah Leong or CT	11	Date/Time: 10.10-19 3.16pm
Estimated Go	9	Bill to:	
To haped Ve	S/TP RES / OD RES / EVA / INV / MV / CS shiele No: SJ C 7356T	N.	Insured: YN 9450E Tel: 8285 7623
at Workshop	m/s Shing 4 Lai		Tel: 8285 7623
of 2 taki	Bull + hue 2 +101-36		
Policy No:	DMCNSN 19370919000	Claim No:	5NM190204763 co2
Sum Insured:		Excess:	
Make of Veh			D.O.A. 9,10. 2019
(Client's Recer	"wp"		
CA / REV	KEP, / REV 24 HRS		H.O.D. Swiorseneut:
Date/Time:	0.10.19 3.35p.m Person Confected:	Ah Hock	Vehicle IN JOUT
Date/Time	Action/Instruction (V) Estimate		
	SJ C TISELT - NATING 19011	0.07/24	DOA-041101 2019
	YN 94505 -NATING 190 14 811		DOA - 09/ 10/ 2019

ASSIGNMENT

From Date	WHITE SJC7356T, WRANG 2008 Feb
Estimated Cost	Type ACD/ McCycle / Bus / Van / Lorry / Taxl / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Paspect Vehicle No.	Male: Toyota Vios- cc 1497
at Workshop m/s	Make: Toyota Vios- cc 1497 Colour Vivile AC: Insured/Std/NI/NA
of .	Sp.Reading /4/063 T/Radio: Insured / Std / NI / NA
nsured	Eng/No:
olicy No.	CANO: MROSSHY9305052253
Jaims No.	Gen. Cond Good Fair / Poor / Burnt
um insured: Excess:	Steering: Inatuer / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
take of Veh:	Modi: Nil SIRim I STD A/Rim or
	Tyre Size: F: 195/LoR15 .
(Policy Condition)	R: 185/60R15.
	BS / DUN / EXNOVA / GY / FS / LIZA (MIC) OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO / YOKO ar
Sal. or Market Value:	Front Rear
DAC Accident Rport: Consistent? : Yes or No	R/Bal. 06 mm R/Bal. 66 mm
GIA PR Seen: Consistent? : Yes or No	L/Bal 06 mm L/Bal 06 mm
est Repairs: 1 days Res.: Yes or No	D.O.A. D.O.I. 10/10/19.
um Sum % 3 Val.: Yes or No	Survey held at Sheny Li Lai .
CA / REV / REP. / 24 HRS	Des, of Damages : Frt / Rear / DIS / N/S / U/C / Rooftop or
Vehicle: IN / C	DUT
Date Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision
Date / Time Action / Instruction	COE Expiry: 26/02/23
Tr Chin.	COL Expirity. 5 7-57-5
MY : 221C	2019
PV: 14.314 RE	CEIVED 0 2 DEC 2019
Nett, 7.7k.	
7100	
760	
	Days Of Repair: 7
Date/Title: File Page 10/ : Prell. Report	Days Of Repair: 7 Resurvey No. of Trip: Survey Fee.
: Prell. Report	
: Prell. Report : Final Report	Resurvey No. of Trip: Survey Fee.
: Prell. Report : Final Report	Resurvey No. of Trip: Survey Fee. Transposition
Date/Time. File Parts to/ : Prell. Report : Final Report Cost/Time. File Ratem to/	Resurvey No. of Trip: Survey Fee. Transposition: Fig.: Site hisp. (5)3-859

Summer Lee (LKK Auto)

From: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>

Sent: Thursday, 10 October, 2019 3:16 PM

To: ct-admin@visionlawllc.com; sllshenglilai@gmail.com; assignments

Subject: RE: Scan Image Attachments: 0670_001.pdf

WITHOUT PREJUDICE

Dear Sirs.

We refer to your attached letter dated 10.10.2019.

We will be assigning M/s LKK Auto Consultants to survey your client's vehicle on a without prejudice basis.

Aside to LKK,

Please refer to the attachment & proceed to survey the third party vehicle.

Thank you.

Regards

Tan Kah Leong

Assistant Executive Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sq.cntaiping.com | FB: www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: ct-admin@visionlawllc.com [mailto:ct-admin@visionlawllc.com]

Sent: Thursday, October 10, 2019 3:07 PM

To: claimdept@sg.cntaiping.com; Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; sllshenglilai@gmail.com

Subject: Scan Image

ISION LAW L

Advocates & Solicitors - Notary Public - Commissioner for Oaths Agents for Trade Marks

EKIC NG CHENG BOON WONG KENG LEDNG RAYNEY AUDREY WOND SU-ISSEN PAUL VAP TAI SAM ANJALLI DIO MUNIANDY AND KIM NOI DIANE BAYENDRA KRESHNASAMY TAN YINGNIAN, BELWYH CHEONG YUNBUL CLARISSA SONIA LIM WIII LEII

(Incorporated with limited liability) Unique Entity Number :200721148H HEAD OFFICE: 133 New Bridge Road #18-01/02 Chinatown Point Singapore 059413

Branch: 490 Toa Payoh Lorong 6 #03-11 HDB Hub Singapore 310490

VHEAD OFFICE TEL : (65) 65342

TEL : (65) 65342811 (Hunting) FAX ✓ : (65) 65356802 (General) (65) 65355905 (Litigation)

E-mail : jactan@visionlawlic.com

BRANCH

TEL: 65 63580703 FAX: 65 63580448 (Conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE-KINDLY REPLY TO HEAD OFFICE FOR THIS MATTER

Our Ref:

AM.jt.lns.S125,111801.19 (sj)

Your Ref:

SNM19D204763C02

10 October 2019

CHINA TAIPING INSURANCE (S'PORE) PTE LTD

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Attention: Motor Claims Department

Dear Sirs.

BY FAX: 6224 7175

email:claimsdept@sg.cntaiping.com email: kahleong.tan@sg.cntaiping.com

ACCIDENT INVOLVING SJC 7356 T & YN 9450 E ON 09 OCTOBER 2019 ALONG 113 EUNOS AVENUE 3 AT ABOUT 0900 HOURS (NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES)

We refer to your fax 10 October 2019 of even date informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment of Adrian Ling as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

Venue:

Sheng Li Lai

2 Kaki Bukit Avenue 2

#01-36 Kaki Bukit Auto Hub 2

Singapore 417921

Contact Person:

Ah Hock: 8285-7623

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully

ANJAVI I M (HEAD OFFICE) FOR SURVEYOR

Please initial here after completion of pre-repair inspection.

Thank you.

1st Survey on

Appointed surveyor

(Name & Signature)

2nd Survey on

Appointed surveyor

(Name & Signature)

3rd Survey on

Appointed Surveyor


(Name & signature)

cc: SJC 7356 T - By Email: sllshenglilai@gmail.com only

NB.: Any settlement of offer is on the express condition that this settlement is in respect of our client's claim for property-related damages only and shall not preclude our client from claiming injury-related damages arising from this accident.

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error piezze contact us immediately by telephone so that we can arrange for its



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company	
Owner ID:	234C	
Rubialis Ferallis		
Vehicle No.:	SJC7356T	
Vehicle to be Exported:	Yes	
Intended Deregistration Date:	11 Oct 2019	
Vehicle Make:	TOYOTA	
Vehicle Model:	VIOSEAUTO	
Primary Colour:	White	
Manufacturing Year:	2008	
Engine No.:	1NZX709599	
Chassis No.:	MR053HY9305052253	
Maximum Power Output:	80.0 kW (107 bhp)	
Open Market Value:	\$12,498.00	
Original Registration Date:	27 Feb 2008	
First Registration Date:	27 Feb 2008	
Transfer Count:	1	
Actual ARF Paid:	\$13.748.00	
Interiorea PARTE REDITO DISCOUR		
PARF Eligibility:	Forfeited	
PARF Eligibility Expiry Date:	*	
PARF Rebate Amount:	\$0.00	
International Research Details	74 F-1- 2022	
COE Expiry Date:	26 Feb 2023	
COE Category:	A - Car (1600cc & below)	
COE Period(Years):	.5	
PQP Paid:	\$21,061.00	
COE Rebate Amount:	\$14,228.00	
Total Rebate Amount:	\$14,228.00	

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 11 Oct 2019

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

ACCIDENT STATEMEN	Į
-------------------	---

 Date Of Report
 09/10/2019 12:41

 Date Of Accident
 09/10/2019 09:00

 Exact Location Of Accident
 113 EUNOS AVE 3

 Country/State of Loss
 SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJC7356T

Insured/Policyholder

Name Of Registered Owner 7 CAR RENTAL & SERVICES PTE LTD

Co Reg No 201619234C Email Address NOEMAIL

Mobile Phone No

Alternative Phone No OFFICE-89999999

Vehicle Particulars

Manufacturer TOYOTA

Model VIOS E AUTO

Exact Purpose for which vehicle was being used at

time of accident

WORKING

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number 5112118167

Cover Note Number

Driver

 Name of Driver
 WOG CHI CHOY

 NRIC No
 \$9525593J

 Date Of Birth
 18/07/1995

 Occupation
 OUTDOOR

 Date Of Driving Pass
 19/09/2018

Driving Experience 1 YEAR AND 0 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-97348206

Fax Number

Contact Number OFFICE-97348206

EMail Address NOEMAIL

Address

BLK 346 TAMPINES STREET 33

#09-380

Postcode

520346

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

SIDE SWIPE

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle)

2

involved in the accident

NO

Was any body injured in the Accident? Was any injured conveyed to hospital by

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

Details of Police Action

Was the accident reported to the police?

NO

If Yes Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

ON STATED DATE AND TIME, I WAS TRAVELLING ALONG THE STATED VENUE. I NOTICED THAT VEHICLE B PROCEEDED TO STOP ON RIGHT SIDE. SUDDENLY VEHICLE B SWERVE TOWARDS THE LEFT AND HIT ONTO MY VEHICLE RIGHT PORTION.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

VIDEO FOOTAGE WITH DRIVER

Was there any audio recorded?

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

YN9450E

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)
Passenger 1

NAME:

GENDER:

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of
 the report being made available aforesaid.
- 8 Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (iii) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents/including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time: Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signatur

Name:

NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN	The second second	THE RESIDENCE OF THE RE
		T225522 4 A
	→ <u>[M</u>]	B > AH dinso E
ESCRIBE CIRCUMSTANCE	S OF THE ACCIDENT	
ECLARATION We decide the foregoing par	oculars are true in every respect.	
	56	
olicyholic State Stare late & Time:	Driver's Signature (if driver is not the policyholder) Date & Time:	Reporting Centre Personnel's Signature Name: NRIC/FIN No.:

SHENG LI LAI

Kaki Bukit Auto Hub 2 Kaki Bukit Ave 2 #01-36 Singapore 417921

TEL: 6842 0302 FAX: 6746 0295 H/P: 91

H/P: 9111 9222

TP China Xiao Chun,

Vehicle No.: SJC 7356T Model: TOYOTA VIOS

QTY	List Price:		Prices \$
1	Rear door- RH Distorted		1126.50
1	Rear door protector pelaned		106.20
1	Rear door protector moulding of ward		45.21
1	Rear door outer handle		136.20
1	Rear door glass outer moulding Defined		121.60
1	Rear door glass guide PNE NE		112.30 /
1	Rear door glass run channel		156.30 ×
1	Rear door glass regulator		260.90
1	Rear door glass regulator motor H Nu		481.60 T
1	Rear door inner lock Jamed		341.55
1	Rear door insulation Here		120.30 X
1	Rear door inner board		761.90 *
1	Rear door 1/4 glass rubber New		86.90
1	Rear door checker		68.60 +
2	Rear door hinges @ 61.50 New		123.00 +
1	Rear door w/strip &		126.60 /
1	Rear fender-RH Distorted		899.60
1	Rear fender inner panel Page		641.50 X
1	Rear shock absorber 3		341.66
1	Rear axle beam		1899.50 +
1	Rear wheel hub bearing- RH Hu	3 371 36	481.90 /
1	Rear windscreen moulding		120.10
1	Front door-RH Pais	2528.52	1281.50 +
1	Front door protector moulding		109.71
1	Front door protector moulding		81.50 +
		_	10032.63
		Less 25%	(2508.16)
		Subtotal	7524.47

Vehicle No.: SJC 7356T

Special Nett Items	5:
--------------------	----

1	Rear sport wheel Cut		-450.00-380
1	Rear tyre At New		250.00 🗡
1 Set	Rear windscreen sealant New	Life Com Co	80.00-60
1 Set	F/R door visor	1050	280.00 60
1 Set	Side sill panel skirt Defond		800:00 500
		Subtotal	1860.00
	Labour Charges:		
	To remove, refix R/windscreen		180.00-120
	To remove, refix R/interior trims to assist repair		120.00 80
	To remove, refix R/undercarriage	1840	300.00 ×
	To check wheel alignment		120.00 80
	To respray undercoating		120:00 60
	To respray painting and etc		1200.00 800
	Panel beating, cut, weld, remove and replacing above	e parts	1200:00 700
		Subtotal	3240.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$

12624.47

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before after spray painting
- . To asplay damaged part(s) during resurvey
- . Parts prices are subject to confirmation
- * Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary tem(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 5418.52 1/s: 43K. 07 Days.

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/CTI19017889/AQF3N2

Date:

02/12/2019

REFERENCE

Handling Insurer: China Taiping Insurance

(Singapore) Pte. Ltd.

Policy No:

DMCVSN19370919000

Claimant Vehicle No :

SJC7356T

Insured Vehicle No :

YN9450E

Date of Loss:

09/10/2019

Nature of Claim:

TP

Claim No:

SNM19D204763C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SJC7356T

Make & Model: Reg. Date: TOYOTA VIOS, 1.5 E (A)

27/02/2008 (Man. Year: 2008)

Engine No: Chassis No: Odometer: 1NZX709599 MR053HY9305052253

141063 km

Colour:

White 1497 cc

Engine Capacity: Market Value/New Car

Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable): Yes Engine Modification: Yes Footbrake (Serviceable): No Pre-accident Condition: Yes

Handbrake (Serviceable): CONDITION OF TYRES

Front Tyre Size: Front Left Side: 195/60R15

Rear Tyre Size:

195/60R15

Front Right Side:

Michelin 6 mm

Rear Left Side: Rear Right Side: Michelin 6 mm Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS Parts	Repairer's 9,384.47 0.00	Adjuster's 3,578.52 0.00	5,805.95 0.00	Diff % 61.87
Miscellaneous Items Labour	3,240.00 0.00	1,840.00	1,400.00	43.21
Paintwork Labour Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$) Approved Total (Overridden) (S\$)	12,624.47	5,418.52 4,300.00	7,205.95	57.08
Nett Amount (S\$)	12 624 47	4.300.00	8.324.47	65.94

INSPECTION

Date of Assignment:

10/10/2019

Date Inspected:

10/10/2019 Inspected At:

Sheng Li Lai (KAKI BUKIT)

NO. 2 KAKI BUKIT AVE 2, # 01-36 AUTOHUB KAKI BUKIT

Singapore 417921

Estimated Period of Repair:

7.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Referen	ce	
Part Source	: MRM-SG	Version: 1.0 (Last Synchronised: 02 Dec 2019)
Parts:	143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted,	no print-code for SJC7356T)
Validity:		es are valid only if they contain the print code (above) on all estimate pages, running page the END OF ESTIMATES marker on the last estimate page
Further Info	: Items/values n	ot in reference catalogue are prefixed with an asterisk *.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR-RH	Distorted	1,126.50 FL	*1,126.50 FL
2	1		*REAR DOOR PROTECTOR	Deformed	106.20 FL	*106.20 FL
3	1		*REAR DOOR PROTECTOR MOULDING	Deformed	45.21 FL	*45.21 FL
4	1		*REAR DOOR OUTER HANDLE	Damaged	136.20 FL	*136.20 FL
5	1		*REAR DOOR GLASS OUTER MOULDING	Deformed	121.60 FL	*121.60 FL
6	1		*REAR DOOR GLASS GUIDE	Not Necessary	112.30 FL	*-FL
7	1		*REAR DOOR GLASS RUN CHANNEL	Not Necessary	156.30 FL	*-FL
8	1		*REAR DOOR GLASS REGULATOR	Damaged	260.90 FL	*260.90 FL
9	1		*REAR DOOR GLASS REGULATOR MOTOR	Not Necessary	481.60 FL	*-FL
10	1		*REAR DOOR INNER LOCK	Jammed	341.55 FL	*341.55 FL
11	1		*REAR DOOR INSULATION	Not Necessary	120.30 FL	*-FL
12	1		*REAR DOOR INNER BOARD	Not Necessary	761.90 FL	*-FL
13	1		*REAR DOOR 1/4 GLASS RUBBER	Necessary	86.90 FL	*86.90 FL
14	1		*REAR DOOR CHECKER	Not Necessary	68.60 FL	*-FL
15	2		*REAR DOOR HINGES	Not Necessary	123.00 FL	*-FL
16	1		*REAR DOOR W/STRIP	Cut	126.60 FL	*126.60 FL
17	1		*REAR FENDER-RH	Distorted	899.60 FL	*899.60 FL
18	1		*REAR FENDER INNER PANEL	Repair	641.50 FL	*-FL
19	1		*REAR SHOCK ABSORBER	Not Necessary	341.66 FL	*-FL
20	1		*REAR AXLE BEAM	Not Necessary	1,899.50 FL	*-FL
21	1		*REAR WHEEL HUB BEARING-RH	Not Necessary	481.90 FL	*-FL
22	1		*REAR WINDSCREEN MOULDING	Necessary	120.10 FL	*120.10 FL
23	1		*FRONT DOOR-RH	Repair	1,281.50 FL	*-FL
24	1		*FRONT DOOR PROTECTOR	Not Necessary	109.71 FL	*-FL
25	1		*FRONT DOOR PROTECTOR MOULDING	Not Necessary	81.50 FL	*-FL
26	1		*REAR SPORT WHEEL	Cut	450.00 FS	*380.00 FS
27	1		*REAR TYRE	Not Necessary	250.00 FS	*-FS
28	1		*SET REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS
29	1		*SET F/R DOOR VISOR	Necessary	280.00 FS	*60.00 FS
30	1		*SET SIDE SILL PANEL SKIRT	Deformed	800.00 FS	*550.00 FS
F=Fra	mchise	part. S=SpcN	Nett. L=ListItemDisc.			
				Sub Total (S\$)	11,892.63	4,421.36
			- List Item Discount on L Items	25.00/25.00% (S\$)	2,508.16	842.84
				Total Parts (S\$)	9,384.47	3,578.52

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=g... 2/12/2019

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

Particulars	Lab.Type	Repairer's	Amount
ır Items			
TO REMOVE, REFIX R/WINDSCREEN	New	180.00	120.00
그리고 하는 사람들은 사람들은 보고 기계보다는 것이 되었다. 사람들은 그들은 그 가는 사람들은 사람들은 중요를 보고 있다면 살아보다는 것이다.	New	120.00	80.00
TO REMOVE, REFIX R/UNDERCARRIAGE	New	300.00	0.00
TO CHECK WHEEL ALIGNMENT	New	120.00	80.00
TO RESPRAY UNDERCOATING	New	120.00	60.00
TO RESPRAY PAINTING AND ETC	New	1,200.00	800.00
	New	1,200.00	700.00
Gross Labour	Cost (S\$)	3,240.00	1,840.00
	Particulars IT Items TO REMOVE, REFIX R/WINDSCREEN TO REMOVE, REFIX R/INTERIOR TRIMS TO ASSIST REPAIR TO REMOVE, REFIX R/UNDERCARRIAGE TO CHECK WHEEL ALIGNMENT TO RESPRAY UNDERCOATING TO RESPRAY PAINTING AND ETC PANEL BEATING, CUT, WELD, REMOVE AND REPLACING ABOVE PARTS Gross Labour	TO REMOVE, REFIX R/WINDSCREEN New TO REMOVE, REFIX R/INTERIOR TRIMS TO ASSIST New REPAIR TO REMOVE, REFIX R/UNDERCARRIAGE New TO CHECK WHEEL ALIGNMENT New TO RESPRAY UNDERCOATING New TO RESPRAY PAINTING AND ETC New PANEL BEATING, CUT, WELD, REMOVE AND REPLACING New	TO REMOVE, REFIX R/WINDSCREEN New 180.00 TO REMOVE, REFIX R/INTERIOR TRIMS TO ASSIST New 120.00 REPAIR TO REMOVE, REFIX R/UNDERCARRIAGE New 300.00 TO CHECK WHEEL ALIGNMENT New 120.00 TO RESPRAY UNDERCOATING New 120.00 TO RESPRAY PAINTING AND ETC New 1,200.00 PANEL BEATING, CUT, WELD, REMOVE AND REPLACING New 1,200.00 ABOVE PARTS

< END OF ESTIMATES >