

ASS. REC. BY:

REF: CS/CTI/001792/Hq d3d

Special Instruction:

Survey: Hock Ann

ASSIGNMENT (Office)

Member: Menthen

From (Person): Org chin kiat

of CTI

Date/Time: 10/10/2019 @ 4:02pm

Estimated Cost:

Bill to:

OD (TP) WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SML 6182 B

Insured: YM 86 M

at Workshop n/s: Ngialk Motor

Tel: 9850 2253

of No. 10 Kaki Bukit Road 2 # 03-36

Policy No: DMCVSN19152919000

Claim No: SNM19D204539C02

Sum Insured:

Excess:

Make of Veic:  
(Client's Record)

D.O.A. 21/09/2019

CA / REV / REP. / REV 24 HRS

11/10/2019

H.O.D. Endorsement:

Date/Time: 4:51pm @ 10/10/19

Person Contacted:

Mr. Kuan

Vehicle: IN/OUT

| Date/Time | Action/Instruction                  |
|-----------|-------------------------------------|
|           | <u>SML 6182B - X</u>                |
|           | <u>YM 86M - NJS/INC0900400/1141</u> |
|           | <u>2019: 02/01/2009</u>             |
|           |                                     |
|           |                                     |
|           |                                     |

Inspected by HANN at CTI

**ASSIGNMENT**

From: \_\_\_\_\_ Date: 11/10/19  
 Estimated Cost: \_\_\_\_\_  
 OD  TP WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: SML 6182B  
 at Workshop with: Ngiam Motor  
 of: No. 10 Kaki Bukit Road 2 #03-36  
 Insured: First East Centre  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: Before 12pm  
Mr. Kueing 9850 2253  
at estimate.  
 (Policy Condition)  
 Remark: The veh had commenced its  
repair at the time of inspection.  
 Bal. or Market Value: \$70K  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repairs: 5 days Res: Yes or No  
 Lump Sum: \_\_\_\_\_ % 3 Val: Yes or No  
PIP  
CA / REV / REP. / 24 HRS <sup>up</sup>  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT

Veh No: SML 6182B VI Regn: 29/05/2019  
 Type:  M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: H. AD AVANTE (GAS) CC 1591  
 Colour: Gray AC: Insured / Std / NI / NA  
 Sp. Reading: 4339 km T/Radio: Insured / Std / NI / NA  
 Eng No: \_\_\_\_\_  
 C/Nr: KMH084 / CMK4910019  
 Gen. Cond:  Good / Fair / Poor / Burnt  
 Steering:  Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake:  Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modi: Nil  S/Rim / STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: 205/55/R16  
 R: 205/55/R16  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Kumho → (at and for same)  
 Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
 R/Bal: 7 mm R/Bal: 7 mm  
 L/Bal: 7 mm L/Bal: 7 mm  
 D.O.A: 21/9/17 D.O.I: 11/10/19  
 Survey held at: Ngiam Motor  
 Des. of Damages: Frnt / Rear /  O/S / N/S / UIC / Rooftop or \_\_\_\_\_  
 The UIC / Chassis frame / Body Structure affected due to collision.

|     |     |
|-----|-----|
| N/S | O/S |
|     |     |

| Date / Time | Action / Instruction   |
|-------------|--|
|             | * SML 6182B Finished P/Parts amount \$4703.28 * SML 6182B No |
|             | Agree by workshop no. chiu H. amount have finished           |
|             | Let to 2607.68, 96% workshop required work                   |
|             | MV - 71000 do p/p repair                                     |
|             | PV - 37005   |
|             | NV - 33900   |
|             | MV - 70-7/1K   |

RECEIVED 28 NOV 2019

Date/Time, File Pass to?  : Prel. Report  
 : Final Report

Days Of Repair: 5  
 Resurvey No. of Trip: 1

Artd Fee:  Site Insp 1\$  
 Interview 1\$  
 Tech. Insp 1\$  
 Wheel stud 1\$

|                 |            |
|-----------------|------------|
| Survey Fee:     | <u>770</u> |
| Transportation: |            |
| S + P.S. S:     |            |
| Folio:          |            |
| Other:          |            |
| Total:          | <u>770</u> |

Report Format: MER-TP  
 Total Sum / AB: 4703.28

## Hock Ann (LKK Auto)

---

**From:** Hock Ann (LKK Auto)  
**Sent:** Tuesday, 26 November, 2019 8:39 AM  
**To:** weekwanchia@yahoo.com  
**Cc:** Shiau Chan (LKKAuto)  
**Subject:** RE: SML 6182B FINALIZED EXTIMATE CALCULATE UPDATED 22.11.2019

**'WITHOUT PREJUDICE'**  
**SAVE AS TO COSTS**

Dear mr chia ,

Good day, o.k will be process base on finalized total amount COR \$ 4703.28 P / PARTS and DOR 5 days close.

Noted: All finalized document > LOA ,LOD,DV,LTA need send to CHINA TAIPING INSURANCE claims dept.

Thanks.

Best Regards,

**Hock Ann** | Assistant Automotive Assessor

**LKK Auto Consultants**

Phone: 6741 3061 | Email: [HockAnn@lkkauto.com](mailto:HockAnn@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** WeeKwan Chia [mailto:weekwanchia@yahoo.com]  
**Sent:** Monday, 25 November, 2019 7:51 AM  
**To:** Hock Ann (LKK Auto); WEEKWANCHIA@YAHOO.COM  
**Cc:** Shiau Chan (LKKAuto)  
**Subject:** RE: SML 6182B FINALIZED EXTIMATE CALCULATE UPDATED 22.11.2019

Ok confirmed COR at S\$ 4,703.28  
& DOR at 5days.

Thank you.

Sent from Yahoo Mail on Android

On Fri, 22 Nov 2019 at 9:02, Hock Ann (LKK Auto)  
<[HockAnn@lkkauto.com](mailto:HockAnn@lkkauto.com)> wrote:

'WITHOUT PREJUDICE'

*SAVE AS TO COSTS*

Dear mr chia,

Good day , Kindly attached refer vehicle SML 6182B HYUNDAI AD AVANTE 1.6 GLS finalized updated calculate adjustment estimate on 22.11.2019 .

management auditor after checking price update offer below amount to you,

COR - \$ 4703.28

DOR – 5 DAYS

Please refer adjustment updated total P/PARTS repair amount \$ 4703.28 if agree total P/PARTS amount and repair days, will be to close case.

Please to updated email back asap.

Thanks.

Best Regards,

**Hock Ann** | Assistant Automotive Assessor

**LKK Auto Consultants**

Phone: 6741 3061 | Email: [HockAnn@lkkauto.com](mailto:HockAnn@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## ...CLAIM SUBFOLDER...(New Assignment)

| CLAIM SUBFOLDER TRACKING |             |               |  |         |               |             |  |
|--------------------------|-------------|---------------|--|---------|---------------|-------------|--|
| Case                     | Notified    | Est Submitted | Adj Assigned                                   | Adj Rpt | Adj Submitted | Ins Auth'ed | Status   |
| Main                     | 10 Oct 2019 |               | 10 Oct 2019<br>16:02<br><a href="#">Assign</a> |         |               |             | <b>New Assignment</b><br><a href="#">Cancel Case</a> |

|      |           |               |           |                          |
|------|-----------|---------------|-----------|--------------------------|
| Main | Reference | Claim Details | Documents | <a href="#">Show All</a> |
|------|-----------|---------------|-----------|--------------------------|

| CLAIM SUBFOLDER DETAILS     |  |                        |   | [Created by insurer] |
|-----------------------------|--|------------------------|---|----------------------|
| Insured:                    | M CITY RENTAL, Co. Reg. No.: 53110235A   |                        |   |                      |
| Main Claimant:              | TAN SIEW KIANG, ID: S0085535I  |                        |   |                      |
| Vehicle Reg. No.:           | SML6182B   | Date of Loss:          | 21/09/2019 19:00 - :59<br>[3 Months and 23 Days From LTA Reg Date (Man Yr)] |                      |
| Claim Type:                 | TP / SNM19D204539C02   | Policy/Cover Note No.: | DMCVSN19152919000   |                      |
| Vehicle Reg. No. (Insured): | YM86M  | Policy No. (Claimant): | CN046708  |                      |
|                             |  | Excess:                | S\$0.00   |                      |
| Repairer:                   | Ngiak Motor Works - Kaki Bukit (HQ) NO.10 KAKI BUKIT ROAD 2, #03-36 FIRST EAST CENTRE, 417868 Kaki Bukit - Tel: 98502253 |                        |   |                      |
| Handling Insurer:           | China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]                       |                        |   |                      |
| Claimant's Insurer:         | AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288  |                        |   |                      |
| Adjuster:                   | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 21/10/2019]  |                        |   |                      |
| Driver/Custodian (Insured): | CHAN KERNG TONG (40 / Male), NRIC: S7838181G Email:  |                        |   |                      |
| Adj Asg. Remarks:           | please assign Mr Kenneth Kong for SJE. thank you.  |                        |   |                      |

| ASSOCIATED MAIL RECEIVED         | <a href="#">View All</a> | <a href="#">Compose Case Mail</a> |
|----------------------------------|--------------------------|-----------------------------------|
| There are no mail for this case. |                          |                                   |

| ALL ASSOCIATED TASKS |          |      |            |         |         |             |              | <a href="#">View All</a> | <a href="#">Search Tasks</a> | <a href="#">Create New Task</a> | <a href="#">Complete</a> |
|----------------------|----------|------|------------|---------|---------|-------------|--------------|--------------------------|------------------------------|---------------------------------|--------------------------|
| Due Date             | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On               | Done?                        |                                 |                          |
| No results.          |          |      |            |         |         |             |              |                          |                              |                                 |                          |

# NGIAK MOTOR WORKS

No. 10, Kaki Bukit Road 2, First East Centre, #03 - 36, Singapore 417868  
Fax : 6636 - 2832 / Email : weekwanchia@yahoo.com

Date :- 8 / 10 / 2019

Motor Claims Department

BY FAX :- China Tailoring Insurance (S) Pte. Ltd  
6224 - 7175

Dear Sir,

**NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION  
WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF  
PRE-ACTION PROTOCOL FOR NIMA CASES**

We have been appointed by the Owner to repair his/her motor vehicle  
No. SML 6182B on 21-9-19 with another vehicle  
No. YM 86M <sup>at</sup> along B/814 Tampines St. 81

Please be informed that the said vehicle can be inspected at:-  
open car - Park

Contact

Workshop : **NGIAK MOTOR WORKS**

**BY HAND**

First East Centre, #03 - 36

No. 10, Kaki Bukit Road 2, Singapore 417868

Contact

Fax : **6636 - 2832**

Person : **Mr. Kwan / 9850 - 2253**

Email : **weekwanchia@yahoo.com**

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Holiday. We will commence repairs thereafter without further reference to you.

Yours faithfully,

**Wu LLC - Law Firm - Tony Gn**

Our Ref : 19 - G 489

COPY

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Particulars     |                                      |
|-------------------------------|--------------------------------------|
| Owner ID Type:                | Singapore NRIC                       |
| Owner ID:                     | 535I                                 |
| Vehicle Details               |                                      |
| Vehicle No.:                  | SML6182B                             |
| Vehicle to be Exported:       | No                                   |
| Intended Deregistration Date: | 14 Oct 2019                          |
| Vehicle Make:                 | HYUNDAI                              |
| Vehicle Model:                | AD AVANTE 1.6 GLS (A) S              |
| Primary Colour:               | Grey                                 |
| Manufacturing Year:           | 2019                                 |
| Engine No.:                   | G4FGKU146290                         |
| Chassis No.:                  | KMHD841CMKU910019                    |
| Maximum Power Output:         | 93.8 kW (125 bhp)                    |
| Open Market Value:            | \$14,706.00                          |
| Original Registration Date:   | 29 May 2019                          |
| First Registration Date:      | 29 May 2019                          |
| Transfer Count:               | 0                                    |
| Actual ARF Paid:              | \$14,706.00                          |
| Intended PARF Rebate Details  |                                      |
| PARF Eligibility:             | Yes                                  |
| PARF Eligibility Expiry Date: | 28 May 2029                          |
| PARF Rebate Amount:           | \$11,029.00                          |
| Intended COE Rebate Details   |                                      |
| COE Expiry Date:              | 28 May 2029                          |
| COE Category:                 | A - Car up to 1600cc & 97kW (130bhp) |
| COE Period(Years):            | 10                                   |
| QP Paid:                      | \$27,000.00                          |
| COE Rebate Amount:            | \$25,976.00                          |
| <b>Total Rebate Amount:</b>   | <b>\$37,005.00</b>                   |

The information contained herein is correct as at 14 Oct 2019

OOA = 21/9/2019

OK

Bulmer - 9yr 8 months

MV - 71000  
PV - 37005  
NV - 33900

new car price 87999  
less 15%  
3 yr

---

74799

MV - 70-71k

## Enquire Vehicle Transfer Fee

### Vehicle Details

Vehicle No.  
**SML6182B**

Make / Model  
**HYUNDAI / AD AVANTE 1.6 GLS (A) S**

Vehicle Type:  
**P10 - Passenger Motor Car**

Vehicle Scheme:  
**Normal**

Propellant:  
**Petrol**

Motor No.:  
-

Power Rating:  
-

Maximum Laden Weight:  
**1800 kg**

Year Of Manufacture:  
**2019**

Lifespan Expiry Date:  
-

Quota Premium:  
**\$27,000.00**

Road Tax Expiry Date:  
**28 Nov 2019**

Inspection Due Date:  
**28 May 2022**

CO2 Emission:  
**152.00 (g/km)**

CO Emission:  
**0.268410 (g/km)**

NOx Emission:  
**0.008170 (g/km)**

Vehicle Attachment 1:  
**No Attachment**

Chassis No.:  
**KMHD841CMKU910019**

Engine No.:  
**G4FGKU146290**

Engine Capacity:  
**1591 cc**

Maximum Power Output:  
**93.8 kW (125 bhp)**

Unladen Weight:  
**1345 kg**

Original Registration Date:  
**29 May 2019**

COE Category:  
**A - Car up to 1600cc & 97kW (130bhp)**

COE Expiry Date:  
**28 May 2029**

PARF Eligibility Expiry Date:  
**28 May 2029**

Intended Transfer Date:  
**14 Oct 2019**

CEV/VES Rebate Utilised Amount:  
-

HC Emission:  
**0.023310 (g/km)**

PM Emission:  
**0.300000 (mg/km)**

### Fees To Be Paid For Transfer

|   |            |
|---|------------|
| Transfer Fees   | \$25.00    |
| Road Tax Renewal - 6 months (29 Nov 2019 to 28 May 2020)  | \$369.00   |
| Road Tax Renewal - 12 months (29 Nov 2019 to 28 Nov 2020) | \$738.00   |
| Levy  | \$4,759.00 |

### Message

The fees above do not include any late road tax fees, which apply if road tax or lay-up has expired. You can use the digital service Enquire Road Tax Payable to check if there are any late road tax fees.

Any road tax that has been paid for the vehicle will be transferred to the next owner.

- Specs
- Photos
- Similar
- Accessories
- News

[Add to Shortlist](#)
[Submit a Review](#)
[Report Error](#)
[Share](#)



USER RATINGS: (11 reviews)

Details

|                    |  |
|--------------------|--|
| <b>Distributor</b> | Romoco Motors  |
| <b>Model</b>       | 9473888  |
| <b>Built in</b>    | Korea (Introduced 2018)  |
| <b>Production</b>  | Hyundai Avante (2018-2019)   |
| <b>Price list</b>  | 11-City Price list <a href="#">Select Another Date</a>   |
| <b>Promotion</b>   | <b>Avante 1.8 at \$77,889. Visit us today to find out more about our extended promotions and decide which will be your top pick.</b> |

[View all other promotions](#)
[Download Brochure](#)
[Add to Shortlist](#)

| Model         | Price      | Registration | Fuel Economy | Power | Transmission | Optional Extras  |
|---------------|------------|--------------|--------------|-------|--------------|------------------|
| 1.8 (A)       | \$82,389 A | \$7,700 /yr  | 14.8km/L     | 128Hp | 6-speed (A)  | Spice   Features |
| 1.8 S (A)     | \$87,889 A | \$8,100 /yr  | 14.8km/L     | 128Hp | 6-speed (A)  | Spice   Features |
| 1.8 Elite (A) | \$94,999 A | \$8,600 /yr  | 14.8km/L     | 128Hp | 6-speed (A)  | Spice   Features |

Price updated 13-Oct-2019



Hyundai Avante

4.3 stars - based on 11 reviews

Photos & Reviews



- [Placeholder for photo]

View All 83 Hyundai Avante Photos

Facelift - Hyundai Avante 1.8 S (A)

21 Jan 2019 | Hyundai Motors

Refreshed, futuristic, well-priced and easy to live with, the facelifted Hyundai Avante 3 will appeal to many buyers.



CONSUMER REVIEWS

Comparing to KIA Cerato brother

Compared to the Kia Cerato, this is more value for money while the Cerato is more of looks rather than value. For example, the cheapest variant of both cars have a huge difference in terms of specs. The Cerato barely offers anything and other get a free upgrade to both.

Read More »

2018 Hyundai Avante

We wish to extend our sincere thanks and appreciation to Romoco Management and the sales team for the wonderful services rendered during our recent new Hyundai Avante purchase. On 22nd July 2018, I went to Romoco showroom together with my wife and relative to...

Read More »

Be aware 2 reviews received 3 MCP points when you submit a review

View All 13 Consumer Reviews

Specs for Hyundai Avante



Compare ( 0 )



Hyundai Avante

Price Range

Depreciation

2019

Vehicle Type



Home » Used Cars » Direct Owners » Hyundai Avante 1.6A GLS

## Hyundai Avante 1.6A GLS

Overview

Financial

Accessories

Similar

Research

Photos

Map

DIRECT

|                        |   |                        |  |
|------------------------|---|------------------------|--|
| <b>Price</b>           | <b>\$71,800</b>                               | <b>Reg Date</b>        | 24-Apr-2019<br>(9yrs 6mths 9days COE left) |
| <b>Depreciation</b> ⓘ  | \$6,880 /yr<br>View models with similar depre | <b>Manufactured</b> ⓘ  | 2019                                       |
| <b>Mileage</b>         | 3,500 km                                      | <b>Transmission</b>    | Auto                                       |
| <b>Road Tax</b> ⓘ      | \$738 /yr                                     | <b>OMV</b> ⓘ           | \$12,538                                   |
| <b>Dereg Value</b> ⓘ   | \$37,196 as of today (change)                 | <b>ARF</b> ⓘ           | \$12,538                                   |
| <b>COE</b> ⓘ           | \$29,159                                      | <b>Power</b>           | 93.8 kW (125 bhp)                          |
| <b>Engine Cap</b>      | 1,591 cc                                      | <b>No. of Owners</b> ⓘ | 1  |
| <b>Curb Weight</b> ⓘ   | 1,345 kg                                      |                        |  |
| <b>Type of Vehicle</b> | Mid-Sized Sedan                               |                        |  |

## Features

1.6 Liter. 125Bhp. 6 Speed Auto. 6 Airbags. Rear Aircon. View specs of the Hyundai Elantra (2016-2018)

## Accessories

15" Rims. Leather Seats. Original Audio Set With Apple/Android Play, Bluetooth. Front/Rear Recorder Cam. Auto Head Lights. Auto Wiper/3M Solar.

## Description

Brand New Condition. Extremely Low Mileage Of 3,500km. 5 Years Factory Warranty. Trade In And Finance Available.

## Category

PARF Car, Direct Owner Sale, Almost New Car, Low Mileage Car

## Status

Available

## Resources



## Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more




## Car Valuation - Free

Find out the market value of your existing car for free. Get started

100% I  
PAPER &  
SUPPORT  
BOTH BI  
& SELLE

## Price Chart



Click on the point to view the vehicle

Shortlist

Compare

Add nc

Report Error

More Actions

## Seller Information

|                          |                |
|--------------------------|----------------|
| <b>Contact Person(s)</b> | Ms Ho          |
| <b>Contact No.</b>       | 97978799       |
| <b>Enquiry</b>           | Contact Seller |

## ESSENTIAL TRANSACTION FORMS

- » Indemnity form
- » Sales agreement
- » Receipt
- » Hand-over form

Posted on: 08-Oct-2019 | Last Updated on: 10-Oct-2019

Upf Compare

» more Financial info

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |                                 |
|----------------------------|---------------------------------|
| Date Of Report             | 24/09/2019 18:11                |
| Date Of Accident           | 21/09/2019 19:00                |
| Exact Location Of Accident | 814 TAMPINES ST 81 OPEN CARAPRK |
| Country/State of Loss      | SINGAPORE                       |

### DETAILS OF OWN VEHICLE

|                             |                      |
|-----------------------------|----------------------|
| Vehicle Registration Number | SML6182B             |
| <b>Insured/Policyholder</b> |                      |
| Name Of Registered Owner    | TAN SIEW KIANG       |
| NRIC No                     | S0085535I            |
| Email Address               | MELVYNSEET@GMAIL.COM |
| Mobile Phone No             | (LOCAL) +65-98506202 |
| Alternative Phone No        | OFFICE-98506202      |

### Vehicle Particulars

|  |                         |
|--|-------------------------|
| Manufacturer   | HYUNDAI                 |
| Model  | AD AVANTE 1.6 GLS (A) S |
| Exact Purpose for which vehicle was being used at time of accident           |                         |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO                      |
| If No, Please state action to be taken                                       | THIRD PARTY             |
| Vehicle Category   | PRIVATE CAR             |

### Insurance Company

|                           |                       |
|---------------------------|-----------------------|
| Name of Insurance Company | AXA INSURANCE PTE LTD |
| Type Of Coverage          | COMPREHENSIVE         |
| Fleet Policy              | NO                    |
| Policy Number             | CN046708              |
| Cover Note Number         | 24/05/2019-23/05/2020 |

### Driver

|                      |                      |
|----------------------|----------------------|
| Name of Driver       | SEET MELVYN JONHAN   |
| NRIC No              | S7618700B            |
| Date Of Birth        | 22/06/1976           |
| Occupation           | INDOOR               |
| Date Of Driving Pass | 23/07/2011           |
| Driving Experience   | 8 YEARS AND 1 MONTH  |
| Gender               | MALE                 |
| Mobile Number        | (LOCAL) +65-96949602 |
| Fax Number           |                      |
| Contact Number       |                      |
| Email Address        | NOEMAIL              |

|   |                            |
|---|----------------------------|
| Address   | 27 TAMPINES ST 86<br>01-25 |
| Postcode  | 528570                     |
| Was driver an employee of the Insured's Company     | NO                         |
| If No, Relationship of the Driver with the Insured  | CHILDREN                   |
| Vehicle Registration Number of Driver's Own Vehicle | -<br>-<br>-                |
| Insurance Company of Driver's Own Vehicle           | -<br>-<br>-                |

#### General Information of the Accident

|                    |   |
|--------------------|---|
| Type Of Accident   | HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED |
| Weather Conditions | CLEAR   |
| Road Surface       | DRY   |

#### Other Information

|   |                                       |
|---|---------------------------------------|
| Was any foreign vehicle involved in this accident?  | NO                                    |
| Number of vehicles (including own vehicle) involved in the accident                         | 2                                     |
| Was any body injured in the Accident?   | NO                                    |
| Was any injured conveyed to hospital by ambulance?  | NO                                    |
| Was any other material or property damaged?   | YES                                   |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO                                    |
| Number of Passengers (Including Driver)   | 2                                     |
| Passenger 1   | NAME: : ONG WENLI<br>GENDER: : FEMALE |

#### Details of Police Action

|   |    |
|---|----|
| Was the accident reported to the police?  | NO |
| If Yes, Please state which Police Station |    |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom?                     |    |

#### Circumstances of Accident

REFER TO SKETCH PLAN

#### Attachment(s)

|   |     |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera?   | NO  |
| Was there any audio recorded?                 | NO  |

#### DETAILS OF OTHER VEHICLE PROPERTY 1

|                             |                    |
|-----------------------------|--------------------|
| Vehicle Registration Number | YM85M              |
| Vehicle Make/Model/Colour   | MINICAB            |
| Details Of Properties       |                    |
| Vehicle Category            | COMMERCIAL VEHICLE |
| Name of Driver              | CHAN KERNG TONG    |
| NRIC/Passport Number        | S7838181G          |
| Contact Number              | 94550711           |
| Address                     |                    |
| Postcode                    |                    |
| Insurance Company Name      |                    |
| Nature Of Damage            |                    |

No. Of Passenger (Including Driver)

## Sketch Plan Pg. 1

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ["GIA"] may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

24/09/2019

Driver's Signature

(If driver is not the policyholder)

Date & Time:

24/09/2019


Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My car was parked next to 3rd party car.  
 He drove out and turned too early, his under carriage scraped the front right side of my car.

|  |                                 |
|--|---------------------------------|
| You had been advised by workshop that in the event that you wish to claim against your own policy (OD claim), there is a <b>Fourteen (14) days clause</b> whereby the claim must be made within the stipulated timeframe from the day of occurrence. | Reporting Only                  |
|  | Claim OD                        |
|  | Claim TP                        |
|  | Claim OD / TP at other workshop |

DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
 Policyholder Signature  
 Date & Time:  
 24/09/2019

  
 Driver's Signature  
 (if driver is not the policyholder)  
 Date & Time:  
 24/04/2019

  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:



**POLICYHOLDER ACKNOWLEDGEMENT FORM**

Date: 24/09/2019 To: Owner of Vehicle Number: SML 6182B

The following has been advised to you via your workshop: Sulu Bros through their staff.



Please tick the applicable box if you had been advised on any of the following

- You had been advised by the workshop that in the case that you wish to claim against your own policy, there is a Fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurrence.
- You had been advised by the workshop on the liability and merits of the case accordingly.
- You had been advised by the workshop on the claims procedure for the type of claim that you will be making due to this accident.
  - > if fire damage and you claim under your own insurance, any applicable excess will be waived. However, there will be no recovery prospect and NCD will be affected.
  - > if fire damage and you are claiming against the Third Party, your NCD will not be affected. However, the recovery is not guaranteed, and AXA will not be held responsible.
- There will be delay to your vehicle repair due to the unavailability of spare parts locally and there is no other option except to import it from overseas.
- There will be no cancellation/withdrawal of the Own Damage claim once the order of spare parts have been placed. If you wish to cancel/withdraw the claim, you shall bear all costs, expenses &/or related charges incurred directly &/or indirectly to the procurement of the spare parts.
- The estimated waiting time for the spare parts to arrive is \_\_\_\_\_ The estimated arrival time does not include the repair period.
- You will be driving the vehicle out despite being advised by the workshop mechanic/ personnel that the vehicle may not be road worthy.
- For vehicles below three (3) years old or under warranty with a local distributor, your insurance company will use only original parts to repair your vehicle.
 

For vehicles above three (3) years old and no longer under warranty with a local distributor, your insurance company will be carrying out repairs where any damaged part that can be repaired will be repaired and any part that needs to be replaced will be replaced using **any combination** of original parts and/or original equipment manufacturer (OEM) parts and/or second-hand parts.
- You had been advised by the workshop of the Twelve (12) months warranty for Own Damage repairs on workmanship related to the accident.
- For vehicles that are under warranty with a local distributor, you have been advised by the workshop to check with your local distributor on any effect to your warranty prior to making this Own Damage claim.
- Others claim 3rd party & own liability

Signed and acknowledged by:

Mil

Name and signature of policyholder/ authorized driver\* and company stamp (where applicable)

\*authorized driver to either the named drivers as per motor insurance policy or in the case of commercial vehicles, permitted drivers who are permitted to drive the insured vehicle.



Name and signature of workshop personnel including company stamp

[Signature]

# NGIAK MOTOR WORKS

MAILING ADDRESS: BLK 6, GHIM MOH ROAD #10-194

SINGAPORE 270006

H/P: 9850 2253

Reg. No. 207300/00C

Date 9th Oct 2019

Quotation SHL 61823 Hyundai Avante S

S#

|          |     |   |   |                   |                  |     |
|----------|-----|---|---|-------------------|------------------|-----|
| 1        | Pc  | Front bonnet                                | ✓ B+  | 1,195.30          | ✓                |     |
| 1        | Set | Front bonnet insulator clips                | ✓ acc   | 30.00             | ✓                |     |
| 1        | Pc  | Front RH fender                             | ✓ B+  | 620.90            | ✓                |     |
| X        | 1   | Pc  | Front RH fender - top plastic garnish <sup>with Hand by R/H</sup> | ✓ SVC             | <del>50.00</del> | X X |
| 1        | Pc  | Front RH fender - nose shield               | ✓ CRA   | 128.00            | ✓                |     |
| 1        | Set | Front RH fender nose shield clips           | ✓ acc   | 20.00             |                  |     |
| 1        | Pc  | Front RH headlamp                           | ✓ CRA   | 1,430.60          | ✓                |     |
| X        | 1   | Pc  | Front RH headlamp top rubber <sup>with Hand by R/H</sup>          | ✓ acc             | <del>42.00</del> | X X |
| 1        | Pc  | Front RH headlamp lower bracket             | ✓ B+  | 75.00             | ✓ ✓              |     |
| 1        | Pc  | Front bumper                                | ✓ cut   | 649.30            | ✓                |     |
| 1        | Pc  | Front bumper - Tow cover                    | ✓ MS  | 29.20             | ✓                |     |
| 1        | Pc  | Front bumper - RH side retainer             | ✓ CRA   | 43.10             | ✓                |     |
| 1        | Pc  | Front bumper - inner sponge                 | ✓ CRA   | 149.50            | ✓                |     |
| 1        | Pc  | Front bumper - nose beam                    | X SVC   | <del>186.30</del> | X                |     |
| 1        | Set | Front bumper - clips                        | ✓ acc   | 45.00             |                  |     |
| 1        | Pc  | Front bumper - RH signal lamp assy          | ✓ CRA   | 230.70            | ✓                |     |
| 1        | Pc  | Front bumper - RH signal lamp air duct      | ✓ CRA   | 67.40             | ✓                |     |
| 1        | Pc  | Front bumper - RH signal lamp lower garnish | X SVC   | <del>138.60</del> | X                |     |
| 1        | Pc  | Front bumper - RH side holder               | ✓ CRA   | 63.30             | ✓                |     |
| 1        | Pc  | Front bumper - bottom garnish               | X SVC   | 100.20            | X                |     |
| 1        | Pc  | Front grille                                | ✓ CRA   | 538.00            | ✓                |     |
|          |     |   |   | 5,834.40          |                  |     |
| Less 10% |     |   |   | 583.44            |                  |     |
| C/fd     |     |   |   | 5,250.96          |                  |     |

# NGIAK MOTOR WORKS

MAILING ADDRESS: BLK 6, GHIM MOH ROAD #10-194

SINGAPORE 270006

H/P: 9850 2253

Reg. No. 207300/00C

b / fd                      SIB  
5,250.96

Labour -

|                          |        |                     |          |
|--------------------------|--------|---------------------|----------|
| ① To pass headlights     |        | <del>600.00</del>   | 30       |
| ② Computerised resetting |        | <del>1,000.00</del> | 30       |
| ③ Panel beating          | 7 days | <del>9,000.00</del> | 500      |
| ④ Spray painting         | 2.5 pl | <del>1,500.00</del> | 650      |
| Total                    |        |                     | 7,310.96 |

work stop required 1/10/19  
8531188  
H. Ann  
before painting

17 days  
knowing before paint  
check into must  
make ANN @ full auto car

Selay 14/10/19  
455pm  
H. Ann before paint H  
Ann U plf repair  
8531188  
455pm before paint  
make before paint

weekwan chia 9@yahoo.com

chia

# NGIAK MOTOR WORKS

MAILING ADDRESS: BLK 6, GHIM MOH ROAD #10-194

SINGAPORE 270006

H/P: 9850 2253

Reg. No. 207300/00C

Date: 9th Oct 2019

Quotation: SML 61 B 2 B Hyundai Avante S

|   | S\$                          |
|---|------------------------------|
| 1 Pc. Front bonnet ✓ BT   | <del>1,195.30</del> 970.80 ✓ |
| 1 Set Front bonnet insulator clips ✓ acc  | <del>30.00</del> 15 ✓        |
| 1 Pc. Front RH fender ✓ BT  | <del>620.70</del> 520.19 ✓   |
| 1 Pc. Front RH fender top plastic garnish <sup>with Head up RH</sup> ✓ <del>SVC</del> | <del>52.00</del>             |
| 1 Pc. Front RH fender inner shield ✓ CRA  | <del>128.70</del> 87.80 ✓    |
| 1 Set Front RH fender inner shield clips ✓ acc  | <del>20.00</del> 10 ✓        |
| 1 Pc. Front RH headlamp ✓ CRA   | <del>430.60</del> 1100.50 ✓  |
| 1 Pc. Front RH headlamp top rubber <sup>with Head up RH</sup> ✓ acc                   | <del>42.90</del>             |
| 1 Pc. Front RH headlamp lower bracket ✓ BT  | <del>75.50</del> 32.80 ✓     |
| 1 Pc. Front bumper ✓ cut  | <del>649.55</del> 520.60 ✓   |
| 1 Pc. Front bumper TOW cover ✓ acc  | <del>29.00</del> 20 ✓        |
| 1 Pc. Front bumper RH side retainer ✓ CRA   | <del>42.10</del> 30.20 ✓     |
| 1 Pc. Front bumper inner sponge ✓ CRA   | <del>149.50</del> 117.70 ✓   |
| 1 Pc. Front bumper inner beam X SVC   | <del>188.30</del>            |
| 1 Set Front bumper clips ✓ acc  | <del>45.00</del> 15 ✓        |
| 1 Pc. Front bumper RH signal lamp assy. ✓ CRA   | <del>230.70</del> 165.80 ✓   |
| 1 Pc. Front bumper RH signal lamp air duct ✓ CRA                                      | <del>67.40</del> 45 ✓        |
| 1 Pc. Front bumper RH signal lamp lower garnish X SVC                                 | <del>139.60</del>            |
| 1 Pc. Front bumper RH side holder ✓ CRA   | <del>63.30</del> 41.80 ✓     |
| 1 Pc. Front bumper bottom garnish X SVC   | <del>100.20</del>            |
| 1 Pc. Front grille ✓ CRA  | <del>538.70</del> 460.20 ✓   |
|   | 5,834.40                     |
| Less <sup>20%</sup> <del>10%</del>  | 583.44                       |
| C/fd  | 5,250.96                     |

# NGIAK MOTOR WORKS

MAILING ADDRESS: BLK 6, GHIM MOH ROAD #10-194

SINGAPORE 270006

H/P: 9850 2253

Reg. No. 207300/00C

S\$  
b / fd      5,250.96

Labour :-

|                          |                     |      |
|--------------------------|---------------------|------|
| ① To focus headlight     | <del>600.00</del>   | 30V  |
| ② Computerised resetting | <del>1,400.00</del> | 50V  |
| ③ Panel beating          | <del>900.00</del>   | 600V |
| ④ Spray painting         | <del>1,000.00</del> | 700V |

Total :      7,310.96

*[Signature]*  
14/10/19

workshop required PIP repair  
85311883  
H-ANN

without prejudice  
11/10/19

14/12/19  
6155P  
H-ANN  
Resurvey before part  
PIP repair  
85311883 #

parts = 4154.10

parts Dis = 20%

3323.28

labour = 1380

4703.28

12.10pm  
Resurvey before paint  
check item must  
take photo  
Hock ANN @ 11/11/19

5/11/19

Total Amount = \$4703.28 #

PIP →

|  |
|--|
| <p><b>LKK Auto Consultants</b> hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>• To resurvey before/after spray painting</li> <li>• To display damaged part(s) during resurvey</li> <li>• Parts prices are subject to confirmation</li> <li>• Third party survey is on a "Without Prejudice" basis</li> <li>• No illegal modification(s) is allowed</li> <li>• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer<br/>Signature: _____<br/>Date: _____</p> |
|--|

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

| CLAIM SUBFOLDER TRACKING |             |               |  |  |  |            |   |
|--------------------------|-------------|---------------|--|--|--|------------|---|
| Case                     | Notified    | Est Submitted | Adj Assigned   | Adj Rpt  | Adj Submitted                                  | Ins Auth'd | Status  |
| Main                     | 10 Oct 2019 |               | 10 Oct 2019<br>16:02<br><a href="#">Edit Adj Rpt</a> | <b>S\$4,703.28</b><br><a href="#">Edit Estimates</a> | <b>S\$4,703.28</b><br><a href="#">View Rpt</a> |            | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

| Main  | Reference   | Claim Details          | Documents   | Show All                 |                                   |             |              |            |       |
|---|---|------------------------|---|--------------------------|-----------------------------------|-------------|--------------|------------|-------|
| <b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>  |   |                        |   |                          |                                   |             |              |            |       |
| Insured:  | <b>M CITY RENTAL</b> , Co. Reg. No.: 53110235A  |                        |   |                          |                                   |             |              |            |       |
| Main Claimant:  | <b>TAN SIEW KIANG</b> , ID: S00855351   |                        |   |                          |                                   |             |              |            |       |
| Vehicle Reg. No.:   | <b>SML6182B</b>   | Date of Loss:          | 21/09/2019 19:00 - :59<br>[3 Months and 23 Days From LTA Reg Date (Man Yr)] |                          |                                   |             |              |            |       |
| Claim Type:   | <b>TP / SNM19D204539C02</b>   | Policy/Cover Note No.: | DMCVSN19152919000   |                          |                                   |             |              |            |       |
| Vehicle Reg. No. (Insured):   | <b>YMB6M</b>  | Policy No. (Claimant): | CN046708  |                          |                                   |             |              |            |       |
|   |   | Excess:                | S\$0.00   |                          |                                   |             |              |            |       |
| Repairer:   | <b>Ngiak Motor Works - Kaki Bukit (HQ)</b> NO.10 KAKI BUKIT ROAD 2, #03-36 FIRST EAST CENTRE, 417868 Kaki Bukit - Tel: 96502253 |                        |   |                          |                                   |             |              |            |       |
| Handling Insurer:   | <b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Ong Chin Kiat</b> ]               |                        |   |                          |                                   |             |              |            |       |
| Claimant's Insurer:   | <b>AXA Insurance Pte Ltd (HQ)</b> - Tel: 6338 7288  |                        |   |                          |                                   |             |              |            |       |
| Adjuster:   | <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>LEE HOCK ANN</b> ] ... [Final Rpt due 21/10/2019]  |                        |   |                          |                                   |             |              |            |       |
| Driver/Custodian (Insured):   | CHAN KERNG TONG (40 / Male) , NRJC: 57838181G Email:  |                        |   |                          |                                   |             |              |            |       |
| Adj Asg. Remarks:   | please assign Mr Kenneth Kong for SJE. thank you.   |                        |   |                          |                                   |             |              |            |       |
| <b>ASSOCIATED MAIL RECEIVED</b>   |   |                        |   | <a href="#">View All</a> | <a href="#">Compose Case Mail</a> |             |              |            |       |
| There are no mail for this case.  |   |                        |   |                          |                                   |             |              |            |       |
| <b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span> |   |                        |   |                          |                                   |             |              |            |       |
| Due Date  | Priority  | Type                   | Task Group  | Subject                  | Handler                           | Assigned By | Completed On | Created On | Done? |
| No results.   |   |                        |   |                          |                                   |             |              |            |       |

## Claim Documents

\*SML6182B (SNM19D204539C02)  
[YM86M]  
TP  
TAN SIEW KIANG  
Sep 21 2019 7:00PM  
[M CITY RENTAL]  
Ngiak Motor Works - Kaki Bukit

| Upload Documents          |                 |                                     | Upload Photos |  | Compose New Letter   |                                     | View       | View in Browser                     |
|---------------------------|-----------------|-------------------------------------|---------------|--|--|-------------------------------------|------------|-------------------------------------|
| <b>Assessment Reports</b> |                 |                                     |               |  |  |                                     | 1 per page | <input checked="" type="checkbox"/> |
| No                        | Finalized On    | ETHOZ Protect Pte Ltd (Bukit Batok) |               |  | Thumbnail  | Print                               |            |                                     |
| 1                         | 24/09/19 18:30  | Accident Statement                  |               |  |  Load HTM   |                                     |            |                                     |
| <b>Photos/Images</b>      |                 |                                     |               |  |  |                                     | 3 per page | <input checked="" type="checkbox"/> |
| No                        | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)   |               |  | Thumbnail  | Print                               |            |                                     |
| 1                         | 14/10/19 09:15  | Chassis Number                      |               |  |  Load JPG   | <input checked="" type="checkbox"/> |            |                                     |
| 2                         | 14/10/19 09:16  | Odometer Reading                    |               |  |  Load JPG   | <input checked="" type="checkbox"/> |            |                                     |
| 3                         | 14/10/19 09:16  | General View                        |               |  |  Load JPG   | <input checked="" type="checkbox"/> |            |                                     |
| 4                         | 14/10/19 09:16  | General View                        |               |  |  Load JPG   | <input checked="" type="checkbox"/> |            |                                     |
| 5                         | 14/10/19 09:16  | General View                        |               |  |  Load JPG   | <input checked="" type="checkbox"/> |            |                                     |
| 6                         | 14/10/19 09:16  | General View                        |               |  |  Load JPG   | <input checked="" type="checkbox"/> |            |                                     |
| 7                         | 14/10/19 09:16  | General View                        |               |  |  Load JPG   | <input checked="" type="checkbox"/> |            |                                     |
| 8                         | 14/10/19 09:16  | General View                        |               |  |  Load JPG  | <input checked="" type="checkbox"/> |            |                                     |
| 9                         | 14/10/19 09:16  | General View                        |               |  |  Load JPG | <input checked="" type="checkbox"/> |            |                                     |
| 10                        | 14/10/19 09:16  | General View                        |               |  |  Load JPG | <input checked="" type="checkbox"/> |            |                                     |
| 11                        | 14/10/19 09:16  | General View                        |               |  |  Load JPG | <input checked="" type="checkbox"/> |            |                                     |
| 12                        | 14/10/19 09:16  | General View                        |               |  |  Load JPG | <input checked="" type="checkbox"/> |            |                                     |
| 13                        | 14/10/19 09:16  | General View                        |               |  |  Load JPG | <input checked="" type="checkbox"/> |            |                                     |
| 14                        | 14/10/19 09:16  | General View                        |               |  |  Load JPG | <input checked="" type="checkbox"/> |            |                                     |
| 15                        | 14/10/19 09:16  | General View                        |               |  |  Load JPG | <input checked="" type="checkbox"/> |            |                                     |
| 16                        | 14/10/19 09:17  | General View                        |               |  |  Load JPG | <input checked="" type="checkbox"/> |            |                                     |
| 17                        | 14/10/19 09:17  | General View                        |               |  |  Load JPG | <input checked="" type="checkbox"/> |            |                                     |
| 18                        | 14/10/19 09:17  | General View                        |               |  |  Load JPG | <input checked="" type="checkbox"/> |            |                                     |
| 19                        | 14/10/19 09:17  | General View                        |               |  |  Load JPG | <input checked="" type="checkbox"/> |            |                                     |
| 20                        | 14/10/19 09:17  | General View                        |               |  |  Load JPG | <input checked="" type="checkbox"/> |            |                                     |
| 21                        | 14/10/19 09:17  | General View                        |               |  |  Load JPG | <input checked="" type="checkbox"/> |            |                                     |
| 22                        | 14/10/19 09:17  | General View                        |               |  |  Load JPG | <input checked="" type="checkbox"/> |            |                                     |
| 23                        | 14/10/19 09:17  | General View                        |               |  |  Load JPG | <input checked="" type="checkbox"/> |            |                                     |
| 24                        | 14/10/19 09:17  | General View                        |               |  |  Load JPG | <input checked="" type="checkbox"/> |            |                                     |
| 25                        | 14/10/19 09:17  | General View                        |               |  |  Load JPG | <input checked="" type="checkbox"/> |            |                                     |
| 26                        | 14/10/19 09:17  | General View                        |               |  |  Load JPG | <input checked="" type="checkbox"/> |            |                                     |
| 27                        | 14/10/19 09:17  | General View                        |               |  |  Load JPG | <input checked="" type="checkbox"/> |            |                                     |
| 28                        | 14/10/19 09:17  | General View                        |               |  |  Load JPG | <input checked="" type="checkbox"/> |            |                                     |
| 29                        | 14/10/19 09:17  | General View                        |               |  |  Load JPG | <input checked="" type="checkbox"/> |            |                                     |
| 30                        | 14/10/19 09:17  | General View                        |               |  |  Load JPG | <input checked="" type="checkbox"/> |            |                                     |
| 31                        | 14/10/19 09:17  | General View                        |               |  |  Load JPG | <input checked="" type="checkbox"/> |            |                                     |
| 32                        | 14/10/19 09:17  | General View                        |               |  |  Load JPG | <input checked="" type="checkbox"/> |            |                                     |
| 33                        | 14/10/19 09:17  | General View                        |               |  |  Load JPG | <input checked="" type="checkbox"/> |            |                                     |
| 34                        | 14/10/19 09:17  | General View                        |               |  |  Load JPG | <input checked="" type="checkbox"/> |            |                                     |
| 35                        | 14/10/19 09:17  | General View                        |               |  |  Load JPG | <input checked="" type="checkbox"/> |            |                                     |
| 36                        | 14/10/19 09:18  | General View                        |               |  |  Load JPG | <input checked="" type="checkbox"/> |            |                                     |
| 37                        | 14/10/19 09:18  | General View                        |               |  |  Load JPG | <input checked="" type="checkbox"/> |            |                                     |
| 38                        | 14/10/19 09:18  | General View                        |               |  |  Load JPG | <input checked="" type="checkbox"/> |            |                                     |
| 39                        | 14/10/19 09:18  | General View                        |               |  |  Load JPG | <input checked="" type="checkbox"/> |            |                                     |
| 40                        | 14/10/19 09:18  | General View                        |               |  |  Load JPG | <input checked="" type="checkbox"/> |            |                                     |

| Assessment Reports |                |                                     | 1 per page   | <input checked="" type="checkbox"/> |
|--------------------|----------------|-------------------------------------|--|-------------------------------------|
| No                 | Finalized On   | ETHOZ Protect Pte Ltd (Bukit Batok) | Thumbnail  | Print                               |
|                    |                |                                     |  | <input checked="" type="checkbox"/> |
| 41                 | 14/10/19 09:18 | General View                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 42                 | 14/10/19 09:18 | General View                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 43                 | 14/10/19 09:18 | General View                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 44                 | 14/10/19 09:18 | General View                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 45                 | 14/10/19 09:18 | General View                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 46                 | 14/10/19 09:18 | General View                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 47                 | 14/10/19 09:18 | General View                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 48                 | 14/10/19 09:18 | General View                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 49                 | 14/10/19 09:18 | General View                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 50                 | 14/10/19 09:18 | General View                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 51                 | 14/10/19 09:18 | General View                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 52                 | 14/10/19 09:18 | General View                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 53                 | 14/10/19 09:18 | General View                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 54                 | 14/10/19 09:18 | General View                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 55                 | 14/10/19 09:18 | General View                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 56                 | 14/10/19 09:18 | General View                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 57                 | 14/10/19 09:18 | General View                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 58                 | 14/10/19 09:18 | General View                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 59                 | 14/10/19 09:18 | General View                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 60                 | 14/10/19 09:18 | General View                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 61                 | 14/10/19 09:18 | General View                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 62                 | 14/10/19 09:18 | General View                        |  Load JPG  | <input checked="" type="checkbox"/> |
| 63                 | 14/10/19 09:18 | General View                        |  Load JPG | <input checked="" type="checkbox"/> |
| 64                 | 14/10/19 09:18 | General View                        |  Load JPG | <input checked="" type="checkbox"/> |
| 65                 | 24/10/19 13:40 | Reinspection Photo                  |  Load JPG | <input checked="" type="checkbox"/> |
| 66                 | 24/10/19 13:40 | Reinspection Photo                  |  Load JPG | <input checked="" type="checkbox"/> |
| 67                 | 24/10/19 13:40 | Reinspection Photo                  |  Load JPG | <input checked="" type="checkbox"/> |
| 68                 | 24/10/19 13:40 | Reinspection Photo                  |  Load JPG | <input checked="" type="checkbox"/> |
| 69                 | 24/10/19 13:40 | Reinspection Photo                  |  Load JPG | <input checked="" type="checkbox"/> |
| 70                 | 24/10/19 13:40 | Reinspection Photo                  |  Load JPG | <input checked="" type="checkbox"/> |
| 71                 | 24/10/19 13:40 | Reinspection Photo                  |  Load JPG | <input checked="" type="checkbox"/> |
| 72                 | 24/10/19 13:40 | Reinspection Photo                  |  Load JPG | <input checked="" type="checkbox"/> |
| 73                 | 24/10/19 13:40 | Reinspection Photo                  |  Load JPG | <input checked="" type="checkbox"/> |
| 74                 | 24/10/19 13:41 | Reinspection Photo                  |  Load JPG | <input checked="" type="checkbox"/> |
| 75                 | 24/10/19 13:41 | Reinspection Photo                  |  Load JPG | <input checked="" type="checkbox"/> |
| 76                 | 24/10/19 13:41 | Reinspection Photo                  |  Load JPG | <input checked="" type="checkbox"/> |
| 77                 | 24/10/19 13:41 | Reinspection Photo                  |  Load JPG | <input checked="" type="checkbox"/> |
| 78                 | 24/10/19 13:41 | Reinspection Photo                  |  Load JPG | <input checked="" type="checkbox"/> |
| 79                 | 24/10/19 13:41 | Reinspection Photo                  |  Load JPG | <input checked="" type="checkbox"/> |
| 80                 | 24/10/19 13:41 | Reinspection Photo                  |  Load JPG | <input checked="" type="checkbox"/> |
| 81                 | 24/10/19 13:41 | Reinspection Photo                  |  Load JPG | <input checked="" type="checkbox"/> |
| 82                 | 24/10/19 13:41 | Reinspection Photo                  |  Load JPG | <input checked="" type="checkbox"/> |
| 83                 | 24/10/19 13:41 | Reinspection Photo                  |  Load JPG | <input checked="" type="checkbox"/> |
| 84                 | 24/10/19 13:41 | Reinspection Photo                  |  Load JPG | <input checked="" type="checkbox"/> |
| 85                 | 24/10/19 13:41 | Reinspection Photo                  |  Load JPG | <input checked="" type="checkbox"/> |
| 86                 | 24/10/19 13:41 | Reinspection Photo                  |  Load JPG | <input checked="" type="checkbox"/> |
| 87                 | 24/10/19 13:41 | Reinspection Photo                  |  Load JPG | <input checked="" type="checkbox"/> |
| 88                 | 24/10/19 13:41 | Reinspection Photo                  |  Load JPG | <input checked="" type="checkbox"/> |
| 89                 | 24/10/19 13:41 | Reinspection Photo                  |  Load JPG | <input checked="" type="checkbox"/> |
| 90                 | 24/10/19 13:41 | Reinspection Photo                  |  Load JPG | <input checked="" type="checkbox"/> |
| 91                 | 24/10/19 13:41 | Reinspection Photo                  |  Load JPG | <input checked="" type="checkbox"/> |
| 92                 | 24/10/19 13:41 | Reinspection Photo                  |  Load JPG | <input checked="" type="checkbox"/> |
| 93                 | 24/10/19 13:41 | Reinspection Photo                  |  Load JPG | <input checked="" type="checkbox"/> |
| 94                 | 24/10/19 13:41 | Reinspection Photo                  |  Load JPG | <input checked="" type="checkbox"/> |
| 95                 | 24/10/19 13:41 | Reinspection Photo                  |  Load JPG | <input checked="" type="checkbox"/> |

| Assessment Reports |                |  | 1 per page | <input checked="" type="checkbox"/> |
|--------------------|----------------|--|------------|-------------------------------------|
| No                 | Finalized On   | ETHOZ Protect Pte Ltd (Bukit Batok)                | Thumbnail  | Print                               |
| 96                 | 24/10/19 13:41 | Reinspection Photo                                 |            | <input checked="" type="checkbox"/> |
| 97                 | 24/10/19 13:41 | Reinspection Photo                                 |            | <input checked="" type="checkbox"/> |
| 98                 | 24/10/19 13:41 | Reinspection Photo                                 |            | <input checked="" type="checkbox"/> |
| 99                 | 24/10/19 13:41 | Reinspection Photo                                 |            | <input checked="" type="checkbox"/> |
| 100                | 24/10/19 13:41 | Reinspection Photo                                 |            | <input checked="" type="checkbox"/> |
| 101                | 24/10/19 13:41 | Reinspection Photo                                 |            | <input checked="" type="checkbox"/> |
| 102                | 24/10/19 13:41 | Reinspection Photo                                 |            | <input checked="" type="checkbox"/> |
| 103                | 24/10/19 13:41 | Reinspection Photo                                 |            | <input checked="" type="checkbox"/> |
| 104                | 24/10/19 13:42 | Reinspection Photo                                 |            | <input checked="" type="checkbox"/> |
| 105                | 24/10/19 13:42 | Reinspection Photo                                 |            | <input checked="" type="checkbox"/> |
| 106                | 24/10/19 13:42 | Reinspection Photo                                 |            | <input checked="" type="checkbox"/> |
| 107                | 24/10/19 13:42 | Reinspection Photo                                 |            | <input checked="" type="checkbox"/> |
| 108                | 24/10/19 13:42 | Reinspection Photo                                 |            | <input checked="" type="checkbox"/> |
| 109                | 24/10/19 13:42 | Reinspection Photo                                 |            | <input checked="" type="checkbox"/> |
| 110                | 24/10/19 13:42 | Reinspection Photo                                 |            | <input checked="" type="checkbox"/> |
| 111                | 24/10/19 13:42 | Reinspection Photo                                 |            | <input checked="" type="checkbox"/> |
| 112                | 24/10/19 13:42 | Reinspection Photo                                 |            | <input checked="" type="checkbox"/> |
| 113                | 24/10/19 13:42 | Reinspection Photo                                 |            | <input checked="" type="checkbox"/> |
| 114                | 24/10/19 13:42 | Reinspection Photo                                 |            | <input checked="" type="checkbox"/> |
| 115                | 24/10/19 13:42 | Reinspection Photo                                 |            | <input checked="" type="checkbox"/> |
| 116                | 24/10/19 13:42 | Reinspection Photo                                 |            | <input checked="" type="checkbox"/> |
| 117                | 24/10/19 13:42 | Reinspection Photo                                 |            | <input checked="" type="checkbox"/> |
| 118                | 24/10/19 13:42 | Reinspection Photo                                 |            | <input checked="" type="checkbox"/> |
| 119                | 24/10/19 13:42 | Reinspection Photo                                 |            | <input checked="" type="checkbox"/> |
| 120                | 24/10/19 13:42 | Reinspection Photo                                 |            | <input checked="" type="checkbox"/> |
| 121                | 24/10/19 13:42 | Reinspection Photo                                 |            | <input checked="" type="checkbox"/> |
| 122                | 24/10/19 13:42 | Reinspection Photo                                 |            | <input checked="" type="checkbox"/> |
| 123                | 24/10/19 13:42 | Reinspection Photo                                 |            | <input checked="" type="checkbox"/> |
| 124                | 24/10/19 13:42 | Reinspection Photo                                 |            | <input checked="" type="checkbox"/> |
| 125                | 24/10/19 13:42 | Reinspection Photo                                 |            | <input checked="" type="checkbox"/> |
| 126                | 24/10/19 13:42 | Reinspection Photo                                 |            | <input checked="" type="checkbox"/> |
| 127                | 24/10/19 13:42 | Reinspection Photo                                 |            | <input checked="" type="checkbox"/> |
| 128                | 24/10/19 13:43 | After Repair Photo                                 |            | <input checked="" type="checkbox"/> |
| 129                | 24/10/19 13:43 | After Repair Photo                                 |            | <input checked="" type="checkbox"/> |
| 130                | 24/10/19 13:43 | After Repair Photo                                 |            | <input checked="" type="checkbox"/> |
| 131                | 24/10/19 13:43 | After Repair Photo                                 |            | <input checked="" type="checkbox"/> |
| 132                | 24/10/19 13:43 | After Repair Photo                                 |            | <input checked="" type="checkbox"/> |
| Documentation      |                |  | 1 per page | <input checked="" type="checkbox"/> |
| No                 | Finalized On   | China Taiping Insurance (Singapore) Pte. Ltd. (HQ) | Thumbnail  | Print                               |
| 1                  | 10/10/19 15:21 | INSD YMB6M GIA REPORT                              |            | <input checked="" type="checkbox"/> |
| 2                  | 10/10/19 15:21 | pri  |            | <input checked="" type="checkbox"/> |

### Linked Accident Report Documents

| Assessment Reports |                |                                     | 1 per page | <input checked="" type="checkbox"/> |
|--------------------|----------------|-------------------------------------|------------|-------------------------------------|
| No                 | Finalized On   | ETHOZ Protect Pte Ltd (Bukit Batok) | Thumbnail  | Print                               |
| 1                  | 24/09/19 18:30 | Accident Statement                  |            | <input checked="" type="checkbox"/> |
| Photos/Images      |                |                                     | 3 per page | <input checked="" type="checkbox"/> |
| No                 | Finalized On   | ETHOZ Protect Pte Ltd (Bukit Batok) | Thumbnail  | Print                               |
| 1                  | 24/09/19 18:22 | Accident Photo                      |            | <input checked="" type="checkbox"/> |
| 2                  | 24/09/19 18:22 | Accident Photo                      |            | <input checked="" type="checkbox"/> |
| 3                  | 24/09/19 18:22 | Accident Photo                      |            | <input checked="" type="checkbox"/> |
| 4                  | 24/09/19 18:22 | Accident Photo                      |            | <input checked="" type="checkbox"/> |
| 5                  | 24/09/19 18:22 | Accident Photo                      |            | <input checked="" type="checkbox"/> |

| Assessment Reports |                |                                     | 1 per page | <input checked="" type="checkbox"/> |
|--------------------|----------------|-------------------------------------|------------|-------------------------------------|
| No                 | Finalized On   | ETHOZ Protect Pte Ltd (Bukit Batok) | Thumbnail  | Print                               |
| 6                  | 24/09/19 18:22 | Accident Photo                      |            | <input checked="" type="checkbox"/> |
| 7                  | 24/09/19 18:22 | Accident Photo                      |            | <input checked="" type="checkbox"/> |
| 8                  | 24/09/19 18:22 | Accident Photo                      |            | <input checked="" type="checkbox"/> |
| 9                  | 24/09/19 18:22 | Accident Photo                      |            | <input checked="" type="checkbox"/> |
| 10                 | 24/09/19 18:22 | Accident Photo                      |            | <input checked="" type="checkbox"/> |
| 11                 | 24/09/19 18:22 | Accident Photo                      |            | <input checked="" type="checkbox"/> |
| 12                 | 24/09/19 18:22 | Accident Photo                      |            | <input checked="" type="checkbox"/> |
| Documentation      |                |                                     | 1 per page | <input checked="" type="checkbox"/> |
| No                 | Finalized On   | ETHOZ Protect Pte Ltd (Bukit Batok) | Thumbnail  | Print                               |
| 1                  | 24/09/19 18:30 | Sketch Plan                         |            | <input type="checkbox"/>            |
| 2                  | 24/09/19 18:30 | AXA                                 |            | <input checked="" type="checkbox"/> |

## Documents Checklist

| DOCUMENTS CHECKLIST  | Reset | Save | Print |
|--|-------|------|-------|
| There are no document checklists configured.   |       |      |       |
| <b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b><br><div style="border: 1px solid black; height: 40px; width: 100%;"></div>        |       |      |       |
| <b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer<br><small>Note: Remarks are private unless you show it to other parties.</small> |       |      |       |

## LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CT119017921/HQD3E2

**Date:** 29/11/2019

#### REFERENCE

|                       |   |                      |                   |
|-----------------------|---|----------------------|-------------------|
| Handling Insurer:     | China Taiping Insurance (Singapore) Pte. Ltd. | Policy No:           | DMCVSN19152919000 |
| Claimant Vehicle No : | SML6182B                                      | Insured Vehicle No : | YM86M             |
| Date of Loss:         | 21/09/2019                                    | Nature of Claim:     | TP                |
|                       |   | Claim No:            | SNM19D204539C02   |

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SML6182B</b>                   | Engine No:  | G4FGKU146290      |
| Make & Model:               | HYUNDAI AD AVANTE, 1.6 GLS S (A)  | Chassis No: | KMHD841CMKU910019 |
| Reg. Date:                  | 29/05/2019 (Man. Year: 2019)      | Odometer:   | 4839 km           |
| Colour:                     | Grey                              |             |                   |
| Engine Capacity:            | 1591 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

#### CONDITION OF TYRES

|                   |            |                  |            |
|-------------------|------------|------------------|------------|
| Front Tyre Size:  | 205/55 R16 | Rear Tyre Size:  | 205/55 R16 |
| Front Left Side:  | Kumho 7 mm | Rear Left Side:  | Kumho 7 mm |
| Front Right Side: | Kumho 7 mm | Rear Right Side: | Kumho 7 mm |

*The above values represent the remaining tyre treads depth*

| COST OF CLAIMS           | Repairer's      | Adjuster's      | Difference      | Diff %       |
|--------------------------|-----------------|-----------------|-----------------|--------------|
| Parts                    | 5,250.96        | 3,323.28        | 1,927.68        | 36.71        |
| Miscellaneous Items      | 0.00            | 0.00            | 0.00            |              |
| Labour                   | 2,060.00        | 1,380.00        | 680.00          | 33.01        |
| Paintwork Labour         | 0.00            | 0.00            | 0.00            |              |
| Towing                   | 0.00            | 0.00            | 0.00            |              |
| <b>Nett Amount (S\$)</b> | <b>7,310.96</b> | <b>4,703.28</b> | <b>2,607.68</b> | <b>35.67</b> |

#### INSPECTION

|                             |                          |   |
|-----------------------------|--------------------------|---|
| Date of Assignment:         | 10/10/2019               |   |
| Date Inspected:             | 11/10/2019 Inspected At: | Ngiak Motor Works - Kaki Bukit (HQ)<br>NO.10 KAKI BUKIT ROAD 2, #03-36<br>FIRST EAST CENTRE<br>Singapore 417868 |
| Estimated Period of Repair: | 5.0 days                 |   |

**Adjuster:** LEE HOCK ANN

**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

|   |  |
|---|--|
| <b>Reference</b>  |  |
| <b>Part Source:</b> MRM-SG  | Version: 1.0 (Last Synchronised: 29 Nov 2019)  |
| <b>Parts:</b> 143   | HYUNDAI AD AVANTE 1.6 GLS S (A) (Catalogue:Merimen Singapore 1.0)  |
| <b>Labour:</b> Repairer's   | (Price-denominated Standard List)  |
| <b>Print Code:</b>  | (Unsubmitted, no print-code for SML6182B)  |
| <b>Validity:</b>  | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| <b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *. |  |

## Recommended Parts

| No. | Qty | Part No. Particulars                       | Condition   | Repairer's  | Amount       |
|-----|-----|--|-------------|-------------|--------------|
| 1   | 1   | *FRONT BONNET                              | Bent        | 1,195.30 FL | *970.80 FL   |
| 2   | 1   | *SET FRONT BONNET INSULATOR CLIPS          | Necessary   | 30.00 FL    | *15.00 FL    |
| 3   | 1   | *FRONT RH FENDER                           | Bent        | 620.90 FL   | *520.90 FL   |
| 4   | 1   | *FRONT RH FENDER INNER SHIELD              | Cracked     | 128.10 FL   | *87.80 FL    |
| 5   | 1   | *SET FRONT RH FENDER INNER SHIELD CLIPS    | Necessary   | 20.00 FL    | *10.00 FL    |
| 6   | 1   | *FRONT RH HEADLAMP}                        | Cracked     | 1,430.60 FL | *1,100.50 FL |
| 7   | 1   | *FRONT RH FENDER TOP PLASTIC GARNISH}      |             | 50.40 FL    | *- FL        |
| 8   | 1   | *FRONT RH HEADLAMP TOP RUBBER}             |             | 42.90 FL    | *- FL        |
| 9   | 1   | *FRONT RH HEADLAMP LOWER BRACKET           | Bent        | 75.30 FL    | *32.80 FL    |
| 10  | 1   | *FRONT BUMPER                              | Cut         | 649.50 FL   | *520.60 FL   |
| 11  | 1   | *FRONT BUMPER TOP COVER                    | Missing     | 29.20 FL    | *20.00 FL    |
| 12  | 1   | *FRONT BUMPER RH SIDE RETAINER             | Crushed     | 43.10 FL    | *30.20 FL    |
| 13  | 1   | *FRONT BUMPER INNER SPONGE                 | Cracked     | 149.50 FL   | *117.70 FL   |
| 14  | 1   | *FRONT BUMPER INNER BEAM                   | Serviceable | 186.30 FL   | *- FL        |
| 15  | 1   | *SET FRONT BUMPER CLIPS                    | Necessary   | 45.00 FL    | *15.00 FL    |
| 16  | 1   | *FRONT BUMPER RH SIGNAL LAMP ASSY          | Cracked     | 230.70 FL   | *165.80 FL   |
| 17  | 1   | *FRONT BUMPER RH SIGNAL LAMP AIR DUCT      | Crushed     | 67.40 FL    | *45.00 FL    |
| 18  | 1   | *FRONT BUMPER RH SIGNAL LAMP LOWER GARNISH | Serviceable | 138.60 FL   | *- FL        |
| 19  | 1   | *FRONT BUMPER RH SIDE HOLDER               | Crushed     | 63.30 FL    | *41.80 FL    |
| 20  | 1   | *FRONT BUMPER BOTTOM GARNISH               | Serviceable | 100.20 FL   | *- FL        |
| 21  | 1   | *FRONT GRILLE                              | Cracked     | 538.10 FL   | *460.20 FL   |

F=Franchise part. L=ListItemDisc.

|   |                 |                 |
|---|-----------------|-----------------|
| <b>Sub Total (S\$)</b>                                    | <b>5,834.40</b> | <b>4,154.10</b> |
| <b>- List Item Discount on L Items 10.00/20.00% (S\$)</b> | <b>583.44</b>   | <b>830.82</b>   |
| <b>Total Parts (S\$)</b>                                  | <b>5,250.96</b> | <b>3,323.28</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars             | Lab.Type | Repairer's      | Amount          |
|--------------------------------|-------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>            |                         |          |                 |                 |
| 1                              | TO FOCUS HEADLIGHT.     | New      | 60.00           | 30.00           |
| 2                              | COMPUTERISED RESETTING. | New      | 100.00          | 50.00           |
| 3                              | PANEL BEATING.          | New      | 900.00          | 600.00          |
| 4                              | SPRAY PAINTING.         | New      | 1,000.00        | 700.00          |
| <b>Gross Labour Cost (S\$)</b> |                         |          | <b>2,060.00</b> | <b>1,380.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >