

ASSIGNMENT

MUMIN

From:

Date:

Veh No:

SLX 2543T

Yr Regn: 2018 / MARC

Estimated Cost:

Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

☒ OD / ☐ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

To Inspect Vehicle No: SLX 2543T

Make: AUDI A3 SPORTBACK 1.0 TFSI c.c. 999

at Workshop m/s PREMIUM

Colour: BLUE

A/C: Insured / Std / NI / NA

of 281, MEXAMOR RD

Sp. Reading 16938

T/Radio: Insured / Std / NI / NA

Insured: AIG

Eng/No:

Policy No. 1800029147-01

C/No: WAN 2228V 2JA 084431

Claims No.

Gen. Cond: Good / ☒ Fair / ☐ Poor / ☐ Burnt

Sum Insured:

Excess:

TBA \$600

Steering: ☒ Order / ☐ Jammed / ☐ Leaked / ☐ Burnt or


(Client's Record)

Brake: ☒ Order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Make of Veh:

Mod: Nil / ☒ S/Rim / ☐ STD A/Rim or

(Policy Condition)



Remark: The veh had commenced its repair at the time of inspection.

Tyre Size:

F:

205/55R16

R:

1

☒ BS / ☐ DUN / ☐ EXNOVA / ☐ GY / ☐ FS / ☐ LIZA / ☐ MIC / ☐ OHTSU / ☐ PIR / ☐ SUMI /

TOYO / YOKO or

Bal. or Market Value:

90K

Front

Rear

IDAC Accident Rpt: Consistent? : Yes or No

R/Bal. 6 mm

R/Bal. 6 mm

GIA / PR Seen: Consistent? : Yes or No

L/Bal. 6 mm

L/Bal. 6 mm

Est. Repairs: days Res.: Yes or No

D.O.A. 04/10/19

D.O.I. 10/10/19

Lum Sum: % 3 Val.: Yes or No

Survey held at

PREMIUM

CA / ☒ REV / ☐ REP. / 24 HRSDes. of Damages: ☒ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

Vehicle: IN / OUT

Date:

Person Contacted:

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

SLX 2543T - NBA / INC 19017615 / Y

Date: 11/10/2019

14/10/19 @ 15:30 pm Muzed PA to AIG via mmm.

14/10/19 @ 15:33 pm mandate request authorise repair to AIG via mmm.

15/10/19 @ 17:23 pm informed CIA to George Cooper via and 1

15/10/19 @ 17:07 pm mandate approved by Victor Koh via mmm

Resu! Continued P/P \$4,328.40 @ 3 days with Boss. (\$4,424.60 Red-51%)

Date/Time, File Pass to?

10/02/20



Prel. Report

Days Of Repair: 3

RECEIVED 10 FEB 2020

1) Type



Final Report

Resurvey No. of Trip: 1

Survey Fee:

Date/Time, File Return to?

Transportation:

2)

Add Fee:



Site Insp (\$

S + RS \$1

200



Interview (\$

Photos

11



Tech. Invs (\$

Others



Weekend (\$

TOTAL

211

Report Format:

Lump Sum P/P \$4,328.40

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 14 Oct 2019

Preliminary Advice

Vehicle No	: SLX2543T	Accident Date	: 04/10/2019
Make	: AUDI A3 SPORTBACK	Policy No.	:
Assignment Date	: 14/10/2019	Excess	: S\$0.00
Date of Inspection	: 10/10/2019	Est. Duration of Repair	: 3 days
Inspection At	: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,753.00
Revised Amount	:S\$	4,787.00
Check Items (Estimated)	:S\$	2,411.00
Total	:S\$	7,198.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	90,000.00
COE / PARF Rebate	:S\$	50,412.00
Salvage Value	:S\$	
Margin for Repair	:S\$	39,588.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Tuesday, 31 December 2019 10:59 am
To: Boo seng yak
Cc: Adrian Ling (LKKAuto); SUR; Carrine Leong; Chang Chee Sing;
jiayee.yap@premiumauto.com.sg
Subject: RE: FINAL REVISION - SLX2543T - OD AIG - SURVEYED 10 OCT 19 - RASUL

Dear Mr. Boo,

Confirmed final fig \$ 4,328.40 @ 3 days of repairs before excess \$ 600/- & GST.

Kindly expedite the discharge voucher and tax invoice to us for close case.

"Best Wishes for Merry Christmas & Happy New Year 2020"

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Thursday, 26 December 2019 6:04 pm
To: Adrian Ling (LKKAuto) <adrianling@lkkauto.com>; Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; Chang Chee Sing <claims@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg
Subject: FINAL REVISION - SLX2543T - OD AIG - SURVEYED 10 OCT 19 - RASUL

Hi Adrian and all,

Revised estimate is attached. Photographs was mailed to SUR on 7 Nov 19.

Please confirm repair cost of \$4328.40 @ 3 days.

Your early closure is well appreciated.

Best regards - jb

Re: OD CLAIMS FOR SLX 2543 T

Shirley Hiew (LKK Auto)

Tue 15/10/2019 5:23 PM

To: 'Claims' <claims@premiumauto.com.sg>

Cc: SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>

 1 attachments (419 KB)

ESTIMATE.pdf;

Hi George,

As instructed by our client, please proceed to repair the insured vehicle **SLX 2543T (Excess \$ 600/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte LtdPhone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>**Sent:** Monday, 14 October 2019 11:11 AM**To:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>; 'Claims' <claims@premiumauto.com.sg>**Cc:** SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>**Subject:** RE: OD CLAIMS FOR SLX 2543 T

Dear George,

Kindly assist on urgent basis.

Best Regards

G.NIVITHA**LKK Auto Consultants Pte Ltd**Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***SLX2543T (4955207607SG)**

OD

Oct 4 2019 7:55PM

[KAREN LEO SU -WYN]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on **15/10/2019 17:07 PM**.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$4787.00) - SLX2543T - Claim Handler: Mithoo Singh, Aashweenjeet Kaur

Approved:4787.00:Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	850D
Vehicle Details	
Vehicle No.:	SLX2543T
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Oct 2019
Vehicle Make:	AUDI
Vehicle Model:	A3 SPORTBACK 1.0 TFSI S TRONIC (LED)
Primary Colour:	Blue
Manufacturing Year:	2018
Engine No.:	CHZ667962
Chassis No.:	WAUZZZ8V2JA084431
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$24,163.00
Original Registration Date:	21 Mar 2018
First Registration Date:	21 Mar 2018
Transfer Count:	0
Actual ARF Paid:	\$25,829.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Mar 2028
PARF Rebate Amount:	\$19,371.00
Intended COE Rebate Details	
COE Expiry Date:	20 Mar 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$36,810.00
COE Rebate Amount:	\$31,041.00
Total Rebate Amount:	\$50,412.00

The information contained herein is correct as at 14 Oct 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/10/2019 17:08
Date Of Accident	04/10/2019 19:55
Exact Location Of Accident	SLIP ROAD FROM BRADDELL ROAD TURNING BISHAN ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLX2543T
-----------------------------	----------

Insured/Policyholder

Name Of Registered Owner	KAREN LEO SU -WYN
NRIC No	S7237850D
Email Address	KLEOSW13@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98591393
Alternative Phone No	OFFICE-64661803

Vehicle Particulars

Manufacturer	AUDI
Model	A3 SB 1.0 TFSI
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	KAREN LEO SU -WYN
NRIC No	S7237850D
Date Of Birth	13/10/1972
Occupation	INDOOR
Date Of Driving Pass	19/12/1990
Driving Experience	28 YEARS AND 9 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-98591393
Fax Number	
Contact Number	OFFICE-64661803
Email Address	KLEOSW13@GMAIL.COM

Address	57A CORONATION RD WEST
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

WAS AT THE SLIP ROAD FROM BRADDEL ROAD TURNING INTO BISHAN ROAD. I SAW THE CAR IN FRONT MOVE OFF SO I STARTED MOVING OFF TOO. HOWEVER, HE SUDDENLY BRAKED AND I BUMPED INTO HIM FROM BEHIND.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJJ7448A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Resolving Centre Personnel's Signature
Name: Wong Sze Han
NRIC/IN No: C92487103X

 - SJS 7448A
 - SLX 2543T

was at the slip road from Boddleford turning onto Birtch Road. I ~~then~~ saw the car in front ~~move~~ move off so I started moving off too. However, he suddenly braked and I bumped into his bonnet behind.

I/We declare the foregoing particulars are true in every respect.

Reporting Centre Personnel's Signature
Name: Wendy Elizabeth Smith, George
NRIC/ID No.: G2987426

Accident Photo





CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : KAREN LEO SU-WYNN
Period of Insurance : 21 Mar 2019 To 30 Mar 2020
Engine No. : CHZ667962
Chassis No. : WAUZZZ8V2JA064431

Vehicle No. : SLX2543T
Policy No. : 1800029147-01
Endorsement No. :
Issued Date : 14 Feb 2019

ABOUT THE COVER

Make/Model : AUDI A3 Sportback 1.0 TFSI S tronic
Engine Capacity/Tonnage : 999.00 CC
Driver Restriction : NA
Person or Classes of Persons Entitled to Drive* :
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2018
Insuring with COE/PARF : Yes

4) The Policyholder
To Any other person who is driving on the Policyholder's order or with written permission.
This Policy will indemnify the Policyholder or any authorized driver only if he/she meets the specified age condition.
You have to pay an additional sum of \$0.00 for "Young and/or inexperienced Driver Cover" (TYICDP) if you are or Your Authorized Driver (named or unnamed) is under the age of 20 and/or has less than 2 years driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, business and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, deer driving, assembly line or speed testing, the carriage of goods other than parcels in connection with any trade or business or use for any purpose in connection with motor trade.

Loss of Use: 1500hrs - 2000hrs Optional

* Limitations imposed irrespective by Section 8 of the Motor Vehicle (Third Party Risk and Compensation) Act (Cap. 196) and Section 95 of the Road Transport Act, 1987 (Singapore), are not to be included under these headings.

EXCESS

Section 1
Fire - \$0 Own Damage - \$800 Theft - \$0 Flood Cover - \$0

Section 2
Property Damage - \$0

Windscreen - \$100

Named Driver and Excess (where applicable)

KAREN LEO SU-WYNN - \$800 (Own Damage)

APPROVED REPORTING CENTRE/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1 Audi Customer Service Centre, 100 To Ubi Road, Singapore 408602

For other Approved Reporting Centres/Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6248 1000. Alternatively, you may refer to AIG website www.aig.com.sg or AIG Asia Mobile App. Simply search and download "AIG 24hr Hotline & Garage Find".

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: MayBank

Please verify clearly that the policy to which this Certificate of Insurance refers is issued in accordance with the provisions of the Motor Vehicle (Third Party Risk and Compensation) Act (Cap. 196), Part 95 of the Road Transport Act, 1987 (Singapore) and Motor Vehicle (Third Party Risk and Compensation) Regulations (S. 196 (2006)).

0504125259

PREMIUM LEADING - JPHS

201 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159055

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.


AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

AIG Asia Pacific Insurance Pte. Ltd.

To: Sherrin May 907-10 AIG Building 10001101 Tel: 65 6410 2000 | www.aig.com.sg

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

WIP : 15260

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1220/2019/NS
Date	:	09-Oct-19

Vehicle NOT IN workshop. Please arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Ms Karen Leo Su-Wyn
Address	:	57A Coronation Road West Singapore 269271
Telephone	:	98591393
Type of Claim	:	Own Damage Claims
Policy No.	:	
Vehicle No	:	SLX 2543 T
Model Code	:	A3 SPORTBACK 1.0 TF
Model / Year	:	21-03-18
Engine No	:	CHZ 667962
Chassis No	:	WAUZZZ8V2JA084431
Mileage	:	
Date In	:	
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	04-Oct-19
Place of Accident	:	Slip Rd From Bradell Rd Turning To Bishan Rd

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLX 2543 T

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	
2	To dismantle and renew front bumper. Re-organise crash management components. Reinstall all parts removed.	\$ 1,050.00 500	
3	To respray front bumper.	\$ 900.00 550	
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: <u>\$ 2,502.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 2543 T

S/N	Parts Description		Damaged Parts & Prices	
			S/Nett	Remarks
1	FRONT BUMPER <i>cr</i>	\$	1,698.00	✓ 1358.40
2	FRONT BUMPER FIXING PARTS ? <i>X</i> <i>su</i>	\$	170.00	X
3	FRONT BUMPER GUIDE SECTION - LH / RH ? <i>X</i> <i>su</i>	2 \$	70.00	X
4	FRONT BUMPER GRILLE - CENTRE <i>cr</i>	\$	146.00	✓ 116.40
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE ? <i>X</i> <i>su</i>	\$	270.00	X
6	FRONT BUMPER CLOSING ELEMENT - LH / RH ? <i>X</i> <i>su</i>	2 \$	540.00	X
7	RADIATOR GRILLE <i>scr</i>	\$	1,301.00	✓ 1,040.80
8	RADIATOR GRILLE CLOSING ELEMENT ? <i>cr</i>	\$	174.00	✓ 138.80
9	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>X</i> <i>su</i>	2 \$	342.00	
10	FRONT BUMPER SIDE REINFORCEMENT BEAM ? <i>X</i> <i>su</i>	\$	660.00	X
11	FRONT BUMPER FOAM FILLER PIECE ? <i>X</i> <i>su</i>	\$	172.00	X
12	FRONT BUMPER COVER <i>X</i> <i>su</i>	\$	111.00	
13	AIRCON STICKER <i>nu</i>	NEC \$	7.00	✓ 5.12
14	CAUTION SIGN STICKER <i>nu</i>	NEC \$	13.00	✓ 9.76
15	SIGNAL HORN - RH LOW TONE <i>X</i> <i>su</i>	\$	182.00	
16	RADIATOR AIR GUIDE LH / RH ? <i>cr</i>	1pc \$	44.00	✓ 17.12 (1pc)
17	RADIATOR AIR GUIDE - UPPER CENTRE ? <i>X</i> <i>su</i>	\$	11.00	X
18	FRONT NO PLATE <i>st</i>	S/N \$	40.00	
19	SUNDRIES ? <i>X</i> <i>su</i>	\$	300.00	X
TOTAL SPARE PARTS		:	\$ 6,251.00	
TOTAL LABOUR CHARGES			\$ 2,502.00	
GRAND TOTAL			\$ 8,753.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

:

:

:

:

:

:


16/10/19
Rasul - Hp 90010068
16/10/19 @ 1010
3 days
EXCESS: TBA
Rental
Resury before paint

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be submitted and
is subject to final approval from LKK Auto Consultants

Acknowledged by Repairer
Signature:
Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

WIP : 15260

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1220/2019/NS
Date : 9-Oct-19

Vehicle NOT IN workshop. Please arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian, Rasul

3 days - ok - jb - 26 Dec 19

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Karen Leo Su-Wyn
Address : 57A Coronation Road West
Singapore 269271
Telephone : 98591393
Type of Claim : Own Damage Claims
Policy No. :
Vehicle No : **SLX 2543 T**
Model Code : A3 SPORTBACK 1.0 TF
Model / Year : 21/3/2018
Engine No : CHZ 667962
Chassis No : WAUZZZ8V2JA084431
Mileage :
Date In :
Estimated By : Johnny Boo / Allan Wu
Accident Date : 4-Oct-19
Place of Accident : Slip Rd From Bradell Rd Turning To Bishan Rd

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLX 2543 T

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N	\$ 360.00	\$ 360.00
2	To dismantle and renew front bumper. Re-organise crash management components. Reinstall all parts removed.		\$ 1,050.00	\$ 500.00
3	To respray front bumper.		\$ 900.00	\$ 550.00
4	To carry out diagnostic check.	S/N	\$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	<u>\$ 2,502.00</u>	<u>\$ 1,602.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SLX 2543 T**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER	\$ 1,698.00	\$ 1,358.40
2	FRONT BUMPER FIXING PARTS	\$ 170.00	
3	FRONT BUMPER GUIDE SECTION - LH / rh	2 \$ 70.00	
4	FRONT BUMPER GRILLE - CENTRE	\$ 146.00	\$ 116.40
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$ 270.00	
6	FRONT BUMPER CLOSING ELEMENT - LH / RH	2 \$ 540.00	
7	RADIATOR GRILLE	\$ 1,301.00	\$ 1,040.80
8	RADIATOR GRILLE CLOSING ELEMENT	\$ 174.00	\$ 138.80
9	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2 \$ 342.00	
10	FRONT BUMPER SIDE REINFORCEMENT BEAM	\$ 660.00	
11	FRONT BUMPER FOAM FILLER PIECE	\$ 172.00	
12	FRONT BUMPER COVER	\$ 111.00	
13	AIRCON STICKER	NEC \$ 7.00	\$ 5.12
14	CAUTION SIGN STICKER	NEC \$ 13.00	\$ 9.76
15	SIGNAL HORN - RH LOW TONE	\$ 182.00	
16	RADIATOR AIR GUIDE - LH / RH	2 \$ 44.00	\$ 17.12
17	RADIATOR AIR GUIDE - UPPER CENTRE	\$ 11.00	
18	FRONT NO PLATE	S/N \$ 40.00	\$ 40.00
19	SUNDRIES	\$ 300.00	
	TOTAL SPARE PARTS	\$ 6,251.00	\$ 2,726.40
	TOTAL LABOUR CHARGES	\$ 2,502.00	\$ 1,602.00
	GRAND TOTAL	\$ 8,753.00	\$ 4,328.40

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLX 2543 T

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/1220/2019/NH

30TH JAN 2020

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SLX 2543 T, Audi A3 SB 1.0 TFSI.

With reference to the above-mentioned vehicle, no. **SLX 2543 T**, claimant, **Ms. Karen Leo Su-Wyn**, please find the related document per attached.

1. A copy of the Original invoice no. 85014779 – S\$ 3,989.39.
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encl
AIG – SLX 2543 T

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 16:12

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014779 Date: 29/01/2020 Order: SLX2543T Term: 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
Regn No: SLX2543T (V 37051)	Regn Date: 21/03/2018	Mileage: 17748
Model: A3 SPORTSBACK 1.0 TFSI 8VFANG	Chassis: WAUZZZ8V2JA084431	Engine: CHZ 667962
WIP No.: 15260 Dept: U		
You have been assisted by :- UB-Tony Foong (33)		

		Details	Qty	Unit Price	Amount
S	SUBLET	M: TO SUPPLY VEHICLE NUMBER PLATE.	40.00	1.00	40.00
Q	EXC	M: 8888 Insurance Excess/Liability	-600.00	1.00	-600.00
S	BODYWORK	M: TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNES FOR HEADLIGHT,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	360.00	1.00	360.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER. REORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	500.00	1.00	500.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER	550.00	1.00	550.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	A8V0807065R GRU	COVER	Less 020%	1.00	1698.00
X	A8V3807647B 9B9	GRILLE	Less 020%	1.00	145.50
X	A8V3853651AA3F2	GRILLE	Less 020%	1.00	1301.00
X	A8V3853949	PLATE(LAST) AP	Less 020%	1.00	173.50
X	A8V0010515A	STICKER	Less 020%	1.00	6.40
X	A8K0010520A	STICKER	Less 020%	1.00	12.20
X	A8V0121283K	AIR DUCT AP	Less 020%	1.00	21.40

Parts 2,686.40
Labour 0.00
Sublet 1,642.00
Menus 0.00
Lubricant 0.00

Sub-Total 3,728.40

7% GST 260.99

Grand Total 3,989.39



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SLX 2543 T

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/1220/2019/TG
08 November 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

total pages

RE: CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A3 SPORTBACK 1.0 TF
Vehicle Chassis No. : WAUZZZ8V2JA084431
Vehicle Regn No. : SLX 2543 T
Vehicle Mileage : 17748 KM
Vehicle Owner : Ms. Karen Leo Su-Wyn
Certificate No : 1800029147-01
Own Damage Excess : S\$ 642.00 (Inclusive 7% GST)
Accident Date : 04/10/2019
Place : Slip Road from Braddel Road Turning Bishan Road
Repair Cost : \$ 3989.39
WIP No. : 15260
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : Karen
Time : 18.35pm.
Date : 8/11/2019.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Oct 2019		14 Oct 2019 14:42 Edit Adj Rpt	S\$4,328.40 Edit Estimates	S\$4,328.40 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: KAREN LEO SU -WYN , ID: S7237850D, Tel: +6598591393, Email: KLEOSW13@GMAIL.COM									
Vehicle Reg. No.: SLX2543T		Date of Loss: 04/10/2019 19:00 - :59 [18 Months and 13 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / 4955207607SG		Policy/Cover Note No.: (Comprehensive) Excess: S\$600.00							
Repairer: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Mithoo Singh, Aashweenjeet Kaur Aashweenjeetkaur.Mithoosingh@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 23/10/2019]									
Driver/Custodian: KAREN LEO SU -WYN (46 / Female) , NRIC: S7237850D, Tel: +6598591393 Email: KLEOSW13@GMAIL.COM									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (15/10/2019): Alert - Adj Mandate Approved (S\$4787.00) - SLX2543T - Claim Handler: Mithoo Sing... - AIG_SG (15/10/2019): SLX2543T / OD / 04/10/2019 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLX2543T (4955207607SG)

OD

Oct 4 2019 7:55PM

[KAREN LEO SU -WYN]

Premium Automobiles Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio				View View In Browser	
Assessment Reports				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	14/10/19 15:30	Adjuster Immediate Advice	1	Load HTM	
Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	14/10/19 15:32	General View	1	Load JPG	☒
2	14/10/19 15:32	General View	1	Load JPG	☒
3	14/10/19 15:32	General View	1	Load JPG	☒
4	14/10/19 15:32	General View	1	Load JPG	☒
5	14/10/19 15:32	General View	1	Load JPG	☒
6	14/10/19 15:32	General View	1	Load JPG	☒
7	14/10/19 15:32	General View	1	Load JPG	☒
8	14/10/19 15:32	General View	1	Load JPG	☒
9	14/10/19 15:32	General View	1	Load JPG	☒
10	14/10/19 15:32	General View	1	Load JPG	☒
11	14/10/19 15:32	General View	1	Load JPG	☒
12	14/10/19 15:32	General View	1	Load JPG	☒
13	14/10/19 15:32	General View	1	Load JPG	☒
14	14/10/19 15:32	General View	1	Load JPG	☒
15	14/10/19 15:32	General View	1	Load JPG	☒
16	14/10/19 15:32	General View	1	Load JPG	☒
17	14/10/19 15:32	General View	1	Load JPG	☒
18	14/10/19 15:32	General View	1	Load JPG	☒
19	14/10/19 15:32	General View	1	Load JPG	☒
20	14/10/19 15:32	General View	1	Load JPG	☒
21	31/12/19 10:56	Reinspection Photo	1	Load JPG	☒
22	31/12/19 10:56	Reinspection Photo	1	Load JPG	☒
23	31/12/19 10:56	Reinspection Photo	1	Load JPG	☒
24	31/12/19 10:56	Reinspection Photo	1	Load JPG	☒
25	31/12/19 10:56	Reinspection Photo	1	Load JPG	☒
26	31/12/19 10:56	Reinspection Photo	1	Load JPG	☒
27	31/12/19 10:56	Reinspection Photo	1	Load JPG	☒
28	31/12/19 10:56	Reinspection Photo	1	Load JPG	☒
29	31/12/19 10:57	Reinspection Photo	1	Load JPG	☒
30	31/12/19 10:57	Reinspection Photo	1	Load JPG	☒
31	31/12/19 10:57	Reinspection Photo	1	Load JPG	☒
Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	14/10/19 15:31	SLX 2543T GIA.pdf 396.54 KB	1	Load PDF	
2	14/10/19 15:31	ESTIMATE.pdf	1	Load PDF	
3	14/10/19 15:31	CI.pdf	1	Load PDF	
4	14/10/19 15:31	DRIVING.pdf	1	Load PDF	
5	31/12/19 10:57	ESTIMATE MARKED.pdf	1	Load PDF	
6	10/02/20 16:19	WORKSHOP INVOICE	1	Load PDF	

Assessment Reports			1 per page ▼	✓
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
7	10/02/20 16:20	DISCHARGE VOUCHER	 Load PDF	

Linked Accident Report Documents

Assessment Reports			View	View in Browser ▼	1 per page ▼	✓
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print		
1	06/12/19 18:55	Accident Statement	 Load HTM			
2	06/12/19 18:56	Accident Statement	 Load HTM			
3	06/12/19 18:56	Accident Statement	 Load HTM			
4	06/12/19 18:57	Accident Statement	 Load HTM			
Photos/Images			3 per page ▼	✓		
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print		
1	05/10/19 17:26	Accident Photo	 Load JPG	✓		
2	05/10/19 17:26	Accident Photo	 Load JPG	✓		
3	05/10/19 17:26	Accident Photo	 Load JPG	✓		
4	05/10/19 17:26	Accident Photo	 Load JPG	✓		
5	05/10/19 17:26	Accident Photo	 Load JPG	✓		
6	05/10/19 17:26	Accident Photo	 Load JPG	✓		
7	05/10/19 17:26	Accident Photo	 Load JPG	✓		
Documentation			1 per page ▼	✓		
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print		
1	05/10/19 17:29	Sketch Plan	 Load JPG	✓		
2	05/10/19 17:29	Sketch Plan #2	 Load JPG	✓		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
 Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19017932/R1SD3N2

Date: 10/02/2020

REFERENCE

Insured/Claimant: KAREN LEO SU -WYN
Date of Loss: 04/10/2019

Policy No:
Nature of Claim: OD Claim No: 4955207607SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLX2543T
Make & Model: AUDI A3 SPORTBACK, 999cc TFSI S TRONIC (LED) (A)
Reg. Date: 21/03/2018 (Man. Year: 2018)
Colour: Blue
Engine Capacity: 999 cc
Market Value/New Car Price: S\$90,000.00
Sum Insured (S\$): **Market Value/New Car Price**

Engine No: CHZ667962
Chassis No: WAUZZZ8V2JA084431
Odometer: 16938 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,251.00	2,726.40	3,524.60	56.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,502.00	1,602.00	900.00	35.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,753.00	4,328.40	4,424.60	50.55
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	8,153.00	3,728.40	4,424.60	54.27
+ GST 7.00/7.00% (S\$)	570.71	260.99	309.72	54.27
Nett Amount (S\$)	8,723.71	3,989.39	4,734.32	54.27

INSPECTION

Date of Assignment: 14/10/2019

Date Inspected: 10/10/2019 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	1,698.00 FS	*1,358.40 FS
2	1		*FRONT BUMPER FIXING PARTS	Serviceable	170.00 FS	*- FS
3	2		*FRONT BUMPER GUIDE SECTION-LH/RH	Serviceable	70.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE-CENTRE	Cracked	146.00 FS	*116.40 FS
5	1		*FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE	Serviceable	270.00 FS	*- FS
6	2		*FRONT BUMPER CLOSING ELEMENT-LH/RH	Serviceable	540.00 FS	*- FS
7	1		*RADIATOR GRILLE	Scratched	1,301.00 FS	*1,040.80 FS
8	1		*RADIATOR GRILLE CLOSING ELEMENT	Cracked	174.00 FS	*138.80 FS
9	2		*FRONT BUMPER AIR GUIDE GRILLE-LH/RH	Serviceable	342.00 FS	*- FS
10	1		*FRONT BUMPER FOAM FILLER PIECE	Serviceable	172.00 FS	*- FS
11	1		*FRONT BUMPER COVER	Serviceable	111.00 FS	*- FS
12	1		*AIRCON STICKER	Necessary	7.00 FS	*5.12 FS
13	1		*CAUTION SIGN STICKER	Necessary	13.00 FS	*9.76 FS
14	1		*SIGNAL HORN-RH LOW TONE	Serviceable	182.00 FS	*- FS
15	1		*RADIATOR AIR GUIDE-LH/RH	N/s Cracked	44.00 FS	*17.12 FS
16	1		*RADIATOR AIR GUIDE-UPPER CENTRE	Serviceable	11.00 FS	*- FS
17	1		*FRONT NO PLATE	Bent	40.00 FS	*40.00 FS
18	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
19	1		*FRONT BUMPER SIDE REINFORCEMENT BEAM	Serviceable	660.00 FS	*- FS
Total Parts (S\$)					6,251.00	2,726.40

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	1,050.00	500.00
3	TO RESPRAY FRONT BUMPER	New	900.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			2,502.00	1,602.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >