

ASS. REC. BY:

REF: CS3/SM99017953/Hqf362 Special Instruction:

Surveyor: HOE Ann

ASSIGNMENT (Office)

From (Person): Thelma Choo

of SMO

Date/Time: 11.10.19 12.42pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No: SGV 5506B

Insured: SLJ 4719P

at Workshop m/s The mechanics

Tel: 91193959

of 205 Kaki Bukit Road 4 #05-85

Policy No:

Claim No: CMTD 1904744

Sum Insured:

Excess:

Make of Veh:

D.O.A. 9.10.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 11.10.19 1.42pm

Person Contacted: Ah xian

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate Inspection: 8 Kaki Bukit Ave 4 #02-47 Premier
	SGV 5506B - X
	SLJ 4719P - X
	Disassemble photo: 16/10/19
	Submit PRS.

ASSIGNED BY: HANN

Ref: 500

PR3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s The mechanics pte Ltd

of 8 Rali But. QVR 4 #02-49

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res: Yes or No

Lum Sum: 25 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

SGV 5506B

Yr Regn:

19/06/2019

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

T. VIOS E

c.c

1197

Colour:

Red

A/C: Insured / Std / NI / NA

Sp. Reading

323735

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MR053HY 7305005714

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 185/60/R15

R: 185/60/R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front and Rear -> (Firestone A)

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

9/10/19

D.O.I.

11/10/19

Survey held at

The mechanics pte Ltd

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

2-3K

* SGV 5506B / NON

Range -> 4.5-7.5k

Estimate (PR3)

repair days -> 4

case H

MU - 17300

PV - 13528

NV - 3700

RECEIVED 21 OCT 2019

17/10/2019

OverTime, File Pass to?



: Prel. Report

21/10/2019



: Final Report

OverTime, File Return to?

2

Request For Road:

Excess Paid / R.B.:

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Insp (\$



: Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Pinus

Colours

TOTAL

100
60
11
171

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Oct 2019		11 Oct 2019 12:42 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	ETHOZ GROUP LTD, Co. Reg. No.: 198104531H		
Main Claimant:	JDPH, Co. Reg. No.: 53368449L		
Vehicle Reg. No.:	SGV5506B	Date of Loss:	09/10/2019 18:00 - :59
Claim Type:	TP / CMTD1904794	Policy/Cover Note No.:	D19MTRENTD000075 (Third Party Only)
Vehicle Reg. No. (Insured):	SLJ4719P	Policy No. (Claimant):	5093508729-01 (DRIVO CLASSIC)
		Excess:	
Repairer:	The Mechanics Pte Ltd (HQ) 25 KAKI BUKIT ROAD 4, #05-85 SYNERGY@KB, 417800 Kaki Bukit - Tel:		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Thelma Choo - 6322 4681]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 22/10/2019]		
Adj Asg. Remarks:	PTC- BAO BAO 91193959		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	449L
Vehicle Details	
Vehicle No.:	SGV5506B
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Oct 2019
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS E AUTO
Primary Colour:	Red
Manufacturing Year:	2007
Engine No.:	1NZX557067
Chassis No.:	MR053HY9305005714
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$12,607.00
Original Registration Date:	19 Jun 2007
First Registration Date:	19 Jun 2007
Transfer Count:	3
Actual ARF Paid:	\$13,868.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	18 Jun 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$25,313.00
COE Rebate Amount:	\$13,528.00
Total Rebate Amount:	\$13,528.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 16 Oct 2019

OK

Enquire Vehicle Transfer Fee

Vehicle Details

Vehicle No:
SGV5506B

Make / Model:
TOYOTA / VIOS E AUTO

Vehicle Type:
Z10 - Private Hire (Chauffeur) Motor Car

Vehicle Scheme:
Normal

Propellant:
Petrol

Motor No.:
-

Power Rating:
-

Maximum Laden Weight:
1505 kg

Year Of Manufacture:
2007

Lifespan Expiry Date:
-

PQP Paid:
\$25,313.00

Road Tax Expiry Date:
18 Dec 2019

Inspection Due Date:
18 Jun 2020

CO2 Emission:
-

CO Emission:
-

NOx Emission:
-

Vehicle Attachment 1:
No Attachment

Chassis No.:
MR053HY9305005714

Engine No.:
1N2X557067

Engine Capacity:
1497 cc

Maximum Power Output:
80.0 kW (107 bhp)

Unladen Weight:
1095 kg

Original Registration Date:
19 Jun 2007

COE Category:
A - Car (1600cc & below)

COE Expiry Date:
18 Jun 2022

PARF Eligibility Expiry Date:
-

Intended Transfer Date:
16 Oct 2019

CEV/VES Rebate Utilised Amount:
-

HC Emission:
-

PM Emission:
-

Fees To Be Paid For Transfer

Transfer Fees	\$25.00
Road Tax Renewal - 6 months (19 Dec 2019 to 18 Jun 2020)	\$445.00
Road Tax Renewal - 12 months (19 Dec 2019 to 18 Dec 2020)	\$924.00

Message

The fees above do not include any late road tax fees, which apply if road tax or lay-up has expired. You can use the digital service Enquire Road Tax Payable to check if there are any late road tax fees. Any road tax that has been paid for the vehicle will be transferred to the next owner. Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

Print

Save as PDF

Copy as Text

DOA = 9/10/19
MV - 17300
PV - 13528
NV - 3700

Balance - 2 yr 8 month
Dep - 6500 yr
6500 4m = 541 month
13000 + 4328
= 17328

OK +

- New Cars
- Used Cars
- Sell My Car
- Directory
- Products
- Insurance
- Articles
 - Car Reviews
 - Car Advice
 - Car News
 - Car Features
- Forum
- Resources

Spend \$30 to qualify
NOW TILL 15 NOV 2019
[MON - FRI, 6PM - 10PM]

CLICK TO FIND OUT MORE

toyota vios

Price Range ▼

Depreciation ▼

Year Reg ▼

Vehicle Type ▼



Advanced Search

Home » Used Cars » Trust Motor Trading » Toyota Vios 1.5A E (COE till 06/2022)

Toyota Vios 1.5A E (COE till 06/2022)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Price \$19,800

Depreciation ⓘ ~~\$2,390~~ /yrReg Date 21-Jun-2007
(2yrs 8mths 4days COE left)

Mileage 145,000 km (11.8k /yr)

Manufactured ⓘ 2007

Road Tax ⓘ \$821 /yr

Transmission Auto

Dereg Value ⓘ \$13,565 as of today (change)

OMV ⓘ \$12,878

COE ⓘ \$25,313

ARF ⓘ \$14,166

Engine Cap 1,497 cc

Power 80.0 kW (107 bhp)

Curb Weight ⓘ 1,095 kg

No. of Owners ⓘ 1

Type of Vehicle Mid-Sized Sedan

Features

Responsive And Fuel Efficient 1.5L DOHC VVTi 16 Valve Engine Coupled With 4 Speed Auto Transmission, ABS, Dual Airbags View specs of the Toyota Vios (2007-2013)

Accessories

Factory Fitted Original Audio Player, Leather Seats, Sports Rims, Retractable Side Mirrors With Indicators.

Description

1st Owner Unit. Vehicle In Superbly Tip Top Condition. Flexible Loan And 100% Available With Low Interest Rate. Call Now To Viewing The Car By Today.

Category

COE Car

St Compare



Location Map

Shortlist

Compare

Add note

Report Error

More Actions

Seller Information

Company

Trust Motor Trading

• dealer's pricelist

• 25 vehs sold | 18 vehs available

Address

73 Mackenzie Road Lot 17 & 18

Search cars nearby this location

Location

Mackenzie Used Car Centre

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/10/2019 14:49
Date Of Accident	09/10/2019 18:10
Exact Location Of Accident	STEVEN ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGV5506B
Insured/Policyholder	
Name Of Registered Owner	JDPH
Co Reg No	53368449L
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91699667
Alternative Phone No	OFFICE-91699667

Vehicle Particulars

Manufacturer	TOYOTA
Model	VIOS
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5093508729-01 (DRIVO CLASSIC)
Cover Note Number	

Driver

Name of Driver	DIANA GOH GEK NEO
NRIC No	S1527967B
Date Of Birth	11/08/1962
Occupation	OUTDOOR
Date Of Driving Pass	25/08/1983
Driving Experience	36 YEARS AND 1 MONTH
Gender	FEMALE
Mobile Number	(LOCAL) +65-91699667
Fax Number	
Contact Number	OTHERS-91699667
Email Address	NOEMAIL

Address	BLK 513B #05-365 YISHUN STREET 51
Postcode	762513
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TECK GHEE NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 321 ANG MO KIO STREET 31 , POSTCODE: 560321 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4599999 - FAX NO: 64574478
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT NO. T/20191010/2079 ATTACHED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLJ4719P
Vehicle Make/Model/Colour	MAZDA
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	DIANA GOH GEK NEO
Approximate Age	
Injuries Sustain	REFER TO POLICE REPORT
Injured person in which vehicle?	SGV5506B
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

[Signature]

Driver's Signature
(If driver is not the policyholder)
Date & Time:

10 OCT 2019




Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

A - 5GV5506B
B - SLJ4719P

DOA - 9/10/19



ANDERSON ROAD

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

This image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. There is no handwriting or other markings on the paper.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

10 OCT 2019



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:





**SINGAPORE
POLICE FORCE**



T/20191010/2079

1 of 4

Police Station Of Origin:
Teck Ghee NPP
321 Ang Mo Kio Street 31 SINGAPORE
560321
Tel No: 1800-4599999

Report No. T/20191010/2079

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 10/10/2019 14:06		Vide Report No.:		Station Diary No.: 24	
Informant's Particulars					
Name of Informant: DIANA GOH GEK NEO			Address: APT BLK 513B YISHUN STREET 51 #05-365 SINGAPORE 762513		
ID Type / ID No.: NRIC NO / S1527967B			Contact No.: Home/Office: Mobile: 91699667		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Female	Age: 57	Date of Birth: 11/08/1962	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: GRAB DRIVER			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 09/10/2019 18:10	Type of Location: Straight Road
Location: Along Road 1 Traveling Toward Road 2 STEVENS ROAD ANDERSON ROAD NEAR TRAFFIC LIGHT, BEFORE YELLOW BOX				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Traffic Light - Working	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SGV5506B	Car	TOYOTA	VIOS E AUTO	Red	Slightly Damaged	0
SLJ4719P	Car	MAZDA	MAZDA3 4- DOOR SEDAN 1.5L SP.6EAT	Grey	Slightly Damaged	1



**SINGAPORE
POLICE FORCE**



T/20191010/2079

Police Station Of Origin:
Teck Ghee NPP
321 Ang Mo Kio Street 31 SINGAPORE
560321
Tel No: 1800-4599999

2 of 4

Report No. T/20191010/2079

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	DIANA GOH GEK NEO	ID No.	S1527967B
Related Vehicle	SGV5506B (Car)	Contact No.	91699667
Hospital/Clinic	PLATINUM MEDICAL CLINIC & SURGERY PTE LTD	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Other Person Involved			
Name	Unknown	ID No.	NIL
Related Vehicle	SLJ4719P (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 09/10/19 at about 1810hrs, I was driving my car bearing registration number SGV5506B along Stevens Rd towards Anderson Rd.

As it was red light, my car was stationary near the traffic light junction. I was the second car behind the yellow box.

As the green arrow turning right was on, the car in front of me had moved off. Just as I was about to move off, the car bearing registration number SLJ4719P behind me suddenly collided to the rear of my car.

I came out of my car and checked on the damages of my car. We exchanged particulars, took photos and left the scene.

No one was injured at that point. No ambulance or traffic police came down to scene. No government property was damaged.

I have an in built camera in my car however it was not working.

I felt pain to my neck after the accident. I went to see a doctor at Platinum Medical Clinic & Surgery Pte Ltd at Blk 513 Yishun St 51 #01-03 and was given 3 days of MC from 10/10/19 to 12/10/19.



**SINGAPORE
POLICE FORCE**



T/20191010/2079

Police Station Of Origin:
Teck Ghee NPP
321 Ang Mo Kio Street 31 SINGAPORE
560321
Tel No: 1800-4599999

3 of 4

Report No. T/20191010/2079

CONTINUATION OF REPORT

I will be reporting this accident to my insurance company for claims.



**SINGAPORE
POLICE FORCE**



T/20191010/2079

4 of 4

Police Station Of Origin:
Teck Ghee NPP
321 Ang Mo Kio Street 31 SINGAPORE
560321
Tel No: 1800-4599999

Report No. T/20191010/2079

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

F /

Sgt 2 KIAM JIN HUAT

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

10/10/2019 14:06

Officer In Charge Of Case:

TP / AEIT /

SI MOHAMAD ZULFAZDLI BIN ABDULLAH


Contact No.: 65476204

Classification Of Case:

Authentication Stamp

NP168

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Driving License



Accident Photo



Accident Photo



Accident Photo












































...CLAIM SUBFOLDER...(Pending for Survey Report)
























































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Oct 2019		11 Oct 2019 12:42 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case





Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	ETHOZ GROUP LTD, Co. Reg. No.: 198104531H								
Main Claimant:	JDPH, Co. Reg. No.: 53368449L								
Vehicle Reg. No.:	SGV5506B	Date of Loss:	09/10/2019 18:00 - :59 [147 Months and 20 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / CMTD1904794	Policy/Cover Note No.:	D19MTRENTD00075 (Third Party Only)						
Vehicle Reg. No. (Insured):	SLJ4719P	Policy No. (Claimant):	5093508729-01 (DRIVO CLASSIC)						
		Excess:							
Repairer:	The Mechanics Pte Ltd (HQ) 25 KAKI BUKIT ROAD 4, #05-85 SYNERGY@KB, 417800 Kaki Bukit - Tel:								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Thelma Choo - 6322 4681]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 22/10/2019]								
Adj Asg. Remarks:	PTC- BAO BAO 91193959								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents
















*SGV5506B (CMTD1904794)
[SLJ4719P]
TP
JDPH
Oct 9 2019 6:00PM
[ETHOZ GROUP LTD]
The Mechanics Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Assessment Reports									1 per page		<input checked="" type="checkbox"/>
No	Finalized On	VAC (Sin Ming)							Thumbnail	Print	
1	10/10/19 15:09	Accident Statement							 Load HTM		
Photos/Images									3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	16/10/19 15:16	Chassis Number							 Load JPG	<input checked="" type="checkbox"/>	
2	16/10/19 15:17	Odometer Reading							 Load JPG	<input checked="" type="checkbox"/>	
3	16/10/19 15:17	General View							 Load JPG	<input checked="" type="checkbox"/>	
4	16/10/19 15:17	General View							 Load JPG	<input checked="" type="checkbox"/>	
5	16/10/19 15:17	General View							 Load JPG	<input checked="" type="checkbox"/>	
6	16/10/19 15:17	General View							 Load JPG	<input checked="" type="checkbox"/>	
7	16/10/19 15:17	General View							 Load JPG	<input checked="" type="checkbox"/>	
8	16/10/19 15:17	General View							 Load JPG	<input checked="" type="checkbox"/>	
9	16/10/19 15:17	General View							 Load JPG	<input checked="" type="checkbox"/>	
10	16/10/19 15:17	General View							 Load JPG	<input checked="" type="checkbox"/>	
11	16/10/19 15:17	General View							 Load JPG	<input checked="" type="checkbox"/>	
12	16/10/19 15:18	General View							 Load JPG	<input checked="" type="checkbox"/>	
13	16/10/19 15:18	General View							 Load JPG	<input checked="" type="checkbox"/>	
14	16/10/19 15:18	General View							 Load JPG	<input checked="" type="checkbox"/>	
15	16/10/19 15:18	General View							 Load JPG	<input checked="" type="checkbox"/>	
16	16/10/19 15:18	General View							 Load JPG	<input checked="" type="checkbox"/>	
17	16/10/19 15:18	General View							 Load JPG	<input checked="" type="checkbox"/>	
18	16/10/19 15:18	General View							 Load JPG	<input checked="" type="checkbox"/>	
19	16/10/19 15:18	General View							 Load JPG	<input checked="" type="checkbox"/>	
20	16/10/19 15:18	General View							 Load JPG	<input checked="" type="checkbox"/>	
21	16/10/19 15:18	General View							 Load JPG	<input checked="" type="checkbox"/>	
22	16/10/19 15:18	General View							 Load JPG	<input checked="" type="checkbox"/>	
23	16/10/19 15:18	General View							 Load JPG	<input checked="" type="checkbox"/>	
24	16/10/19 15:18	General View							 Load JPG	<input checked="" type="checkbox"/>	
25	16/10/19 15:18	General View							 Load JPG	<input checked="" type="checkbox"/>	
26	16/10/19 15:18	General View							 Load JPG	<input checked="" type="checkbox"/>	
27	16/10/19 15:18	General View							 Load JPG	<input checked="" type="checkbox"/>	
28	16/10/19 15:18	General View							 Load JPG	<input checked="" type="checkbox"/>	
29	16/10/19 15:18	General View							 Load JPG	<input checked="" type="checkbox"/>	
30	16/10/19 15:18	General View							 Load JPG	<input checked="" type="checkbox"/>	
31	16/10/19 15:18	General View							 Load JPG	<input checked="" type="checkbox"/>	
32	16/10/19 15:18	General View							 Load JPG	<input checked="" type="checkbox"/>	
33	16/10/19 15:18	General View							 Load JPG	<input checked="" type="checkbox"/>	
34	16/10/19 15:18	General View							 Load JPG	<input checked="" type="checkbox"/>	
35	16/10/19 15:18	General View							 Load JPG	<input checked="" type="checkbox"/>	
36	16/10/19 15:18	General View							 Load JPG	<input checked="" type="checkbox"/>	
37	16/10/19 15:18	General View							 Load JPG	<input checked="" type="checkbox"/>	
38	16/10/19 15:18	General View							 Load JPG	<input checked="" type="checkbox"/>	
39	16/10/19 15:18	General View							 Load JPG	<input checked="" type="checkbox"/>	
40	16/10/19 15:18	General View							 Load JPG		

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No.	Finalized On	VAC (Sin Ming)		Thumbnail	Print
					<input checked="" type="checkbox"/>
41	16/10/19 15:18	General View		Load JPG	<input checked="" type="checkbox"/>
42	16/10/19 15:18	General View		Load JPG	<input checked="" type="checkbox"/>
43	16/10/19 15:19	General View		Load JPG	<input checked="" type="checkbox"/>
44	16/10/19 15:19	General View		Load JPG	<input checked="" type="checkbox"/>
45	16/10/19 15:19	General View		Load JPG	<input checked="" type="checkbox"/>
46	16/10/19 15:19	General View		Load JPG	<input checked="" type="checkbox"/>
47	16/10/19 15:19	General View		Load JPG	<input checked="" type="checkbox"/>
48	16/10/19 15:19	General View		Load JPG	<input checked="" type="checkbox"/>
49	16/10/19 15:19	General View		Load JPG	<input checked="" type="checkbox"/>
50	16/10/19 15:19	General View		Load JPG	<input checked="" type="checkbox"/>
51	16/10/19 15:19	General View		Load JPG	<input checked="" type="checkbox"/>
52	16/10/19 15:19	General View		Load JPG	<input checked="" type="checkbox"/>
53	16/10/19 15:19	General View		Load JPG	<input checked="" type="checkbox"/>
54	16/10/19 15:19	General View		Load JPG	<input checked="" type="checkbox"/>
55	16/10/19 15:19	General View		Load JPG	<input checked="" type="checkbox"/>
56	16/10/19 15:19	General View		Load JPG	<input checked="" type="checkbox"/>
57	16/10/19 15:19	General View		Load JPG	<input checked="" type="checkbox"/>
58	16/10/19 15:19	General View		Load JPG	<input checked="" type="checkbox"/>
59	16/10/19 15:19	General View		Load JPG	<input checked="" type="checkbox"/>
60	16/10/19 15:19	General View		Load JPG	<input checked="" type="checkbox"/>
61	16/10/19 15:26	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
62	16/10/19 15:26	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
63	16/10/19 15:26	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
64	16/10/19 15:26	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
65	16/10/19 15:26	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
66	16/10/19 15:26	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
67	16/10/19 15:26	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
68	16/10/19 15:26	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
69	16/10/19 15:26	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
70	16/10/19 15:26	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
71	16/10/19 15:26	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
72	16/10/19 15:26	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
73	16/10/19 15:26	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
74	16/10/19 15:26	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
75	16/10/19 15:26	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
76	16/10/19 15:26	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
77	16/10/19 15:26	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
78	16/10/19 15:26	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
79	16/10/19 15:26	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
80	16/10/19 15:26	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
81	16/10/19 15:26	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
82	16/10/19 15:26	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
83	16/10/19 15:26	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
84	16/10/19 15:26	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
85	16/10/19 15:26	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
86	16/10/19 15:26	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
87	16/10/19 15:26	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
88	16/10/19 15:26	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
89	16/10/19 15:26	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
90	16/10/19 15:26	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
91	16/10/19 15:26	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
92	16/10/19 15:26	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
93	16/10/19 15:26	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
94	16/10/19 15:26	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
95	16/10/19 15:26	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Sin Ming)	Thumbnail	Print
96	16/10/19 15:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	16/10/19 15:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	16/10/19 15:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	11/10/19 12:43	Pre-Repair Survey-R S SOLOMON ACK/ASSIGN LKK	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Sin Ming)	Thumbnail	Print
1	10/10/19 15:09	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Sin Ming)	Thumbnail	Print
1	10/10/19 15:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	10/10/19 15:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	10/10/19 15:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	10/10/19 15:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	10/10/19 15:07	Driving License	 Load JPG	<input checked="" type="checkbox"/>
6	10/10/19 15:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	10/10/19 15:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	10/10/19 15:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Sin Ming)	Thumbnail	Print
1	10/10/19 15:03	Sketch Plan	 Load TIF	
2	10/10/19 15:03	Sketch Plan #2	 Load TIF	
3	10/10/19 15:03	Sketch Plan #3	 Load TIF	
4	10/10/19 15:03	Sketch Plan #4	 Load TIF	
5	10/10/19 15:03	Sketch Plan #5	 Load TIF	
6	10/10/19 15:03	Sketch Plan #6	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/SMO19017953/HQF3E2
Date: 22/10/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D19MTRENT000075
Claimant Vehicle No :	SGV5506B	Insured Vehicle No :	SLJ4719P
Date of Loss:	09/10/2019	Nature of Claim:	TP
		Claim No:	CMTD1904794

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGV5506B	Engine No:	1NZX557067
Make & Model:	TOYOTA VIOS, 1.5 (A)	Chassis No:	MR053HY9305005714
Reg. Date:	19/06/2007 (Man. Year: 2007)	Odometer:	323735 km
Colour:	Red		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Firenza 5 mm	Rear Left Side:	Firenza 5 mm
Front Right Side:	Firenza 5 mm	Rear Right Side:	Firenza 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	11/10/2019	
Date Inspected:	11/10/2019 Inspected At:	The Mechanics Pte Ltd (HQ) 25 KAKI BUKIT ROAD 4, #05-85 SYNERGY@KB Singapore 417800
Estimated Period of Repair:	4.0 days	

Adjuster: LEE HOCK ANN

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 - \$3,000.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Oct 2019)
Parts:	143	TOYOTA VIOS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGV5506B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >