

ASS. REC. BY:

REP: CS/CTI19017958/04302

Special Instruction:

Surveyor: Marcus

ASSIGNMENT (Office)

From (Person): Tan Kah Leong of CTI Date/Time: 11/10/19 @ 12:41pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / M

To Inspect Vehicle No: SMN 5261C Insured: GBH 9155L

at Workshop n/s Focus Auto Tel: 6886 9097

of 1 Kaki Bukit Ave 6 # 02-50 Autobay

Policy No: DMCVSN18349518000 Claim No: SNM19D204680

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 3/10/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement: _____

Date/Time: 12:50pm 11/10/19 Person Contacted: Jenny Vehicle-IN/OUT: (OUT)

Date/Time	Action/Instruction
	Estimated (✓)
	GBH 9155L - CS3/CTI19017822/1E4/5 DOA: 03/10/2019
	SMN 5261C: X

Nivitha (LKK Auto)

From: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Sent: Friday, 11 October 2019 12:14 PM
To: claims@focusauto.com.sg; assignments
Subject: RE: OUR REF: SNM19D204680-GBH9155L-TKL- PRE REPAIR SURVEY - SMN 5261 C & GBH 9155 L ACCIDENT ON 03/10/19

WITHOUT PREJUDICE

Dear Jenny,

We refer to your email dated 11.10.2019.

We will be assigning M/s LKK Auto Consultants to survey your client's vehicle on a without prejudice basis.

Aside to LKK,

Please refer to the email below & proceed to survey the third party vehicle.

Thank you.

Regards

Tan Kah Leong

Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: claims@focusauto.com.sg [mailto:claims@focusauto.com.sg]

Sent: Friday, October 11, 2019 12:11 PM

To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>

Subject: OUR REF: SNM19D204680-GBH9155L-TKL- PRE REPAIR SURVEY - SMN 5261 C & GBH 9155 L ACCIDENT ON 03/10/19

Dear Kah Leong

We would like to appoint Marcus Chua from LKK for the survey.

Thank you

Best Regards

Jenny Koh

On 2019-10-11 12:06, Tan Kah Leong wrote:

Without Prejudice

Dear Sirs,

Please see attached and let us know if you agree with SJE.

Thank you.

Regards

Tan Kah Leong

Assistant Executive

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI

Sent: Friday, October 11, 2019 11:59 AM

To: claims@focusauto.com.sg; Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>

Subject: OUR REF: SNM19D204680-GBH9155L-TKL- PRE REPAIR SURVEY - SMN5261C & GBH9155L ACCIDENT ON 03/10/19

Dear Kah Leong,

Please conduct PRS for SMN5261C.

Note : officer in charge – Kah Leong 63896193.

Regards,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

T: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: claims@focusauto.com.sg [mailto:claims@focusauto.com.sg]

Sent: Wednesday, 9 October, 2019 5:13 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: PRE REPAIR SURVEY - SMN5261C & GBH9155L ACCIDENT ON 03/10/19

Dear Officer In-Charge,

Good Day,

Please sent surveyor to arrange the surveyor down to our workshop as below.

We are instructed by our client to notify you of a road traffic accident on 03/10/19 at about 0730 hours at Clementi Avenue 6 involving our client's SMN5261C and GBH9155L driven by your insurer or your insured's authorized driver at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client / we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle without further reference to you.

Please be informed that the said vehicle can be inspected at :

Name of workshop : FOCUS AUTO PTE LTD

Address : No. 1 Kaki Bukit Avenue 6

Autobay #02-50

Singapore 417883

Telephone No.: 6886 9097

Best Regards

Aidah

--

Focus Auto Pte Ltd

No. 1 Kaki Bukit Avenue 6

#02-50 AutoBay Singapore 417883

Tel: 6886 9097 Fax: 6481 9095

Office Hours : Mon ~ Sat, 0900 ~ 1800

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

--

Focus Auto Pte Ltd

No. 1 Kaki Bukit Avenue 6

#02-50 AutoBay Singapore 417883

Tel: 6886 9097 Fax: 6481 9095

Office Hours : Mon ~ Sat, 0900 ~ 1800

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	430G
Vehicle Details	
Vehicle No.:	SMN5261C
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Oct 2019
Vehicle Make:	HONDA
Vehicle Model:	FREED HYBRID 1.5G AUTO
Primary Colour:	Grey
Manufacturing Year:	2019
Engine No.:	LEB5633062
Chassis No.:	GB71093688
Maximum Power Output:	101.0 kW (135 bhp)
Open Market Value:	\$26,067.00
Original Registration Date:	15 Aug 2019
First Registration Date:	15 Aug 2019
Transfer Count:	0
Actual ARF Paid:	\$18,494.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Aug 2029
PARF Rebate Amount:	\$13,870.00
Intended COE Rebate Details	
COE Expiry Date:	14 Aug 2029
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$40,001.00
COE Rebate Amount:	\$39,334.00
Total Rebate Amount:	\$53,204.00

The information contained herein is correct as at 14 Oct 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/10/2019 17:23
Date Of Accident	03/10/2019 07:30
Exact Location Of Accident	ALONG CLEMENTI AVENUE 6
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMN5261C
Insured/Policyholder	
Name Of Registered Owner	TW PREMIUM AUTOMOBILE PTE LTD
Co Reg No	201320430G
Email Address	INFO@TECKWEI.COM.SG
Mobile Phone No	(LOCAL) +65-88589186
Alternative Phone No	OFFICE-64650030

Vehicle Particulars

Manufacturer	HONDA
Model	FREED HYBRID-1.5 G (A)
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5111894346
Cover Note Number	15/08/2019 - 14/08/2020

Driver

Name of Driver	THANG KOK WEI JOHN
NRIC No	S7935500C
Date Of Birth	29/11/1979
Occupation	OUTDOOR
Date Of Driving Pass	13/03/2012
Driving Experience	7 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-88589186
Fax Number	
Contact Number	
Email Address	JOHNTHANG1979@GMAIL.COM

Address BLK 807C CHOA CHU KANG AVENUE 1 #02-540
 Postcode S683807
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 3
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1 NAME: : PASSENGER
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name CLEMENTI POLICE DIVISIONAL HQ (D DIVISION)
 Police Station Address ROAD: 20 CLEMENTI AVENUE 5 , POSTCODE: 129858 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 1800-7740000 - FAX NO: 67741705
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO POLICE REPORT ATTACHED.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBH9155L
 Vehicle Make/Model/Colour NA
 Details Of Properties NA
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver RAIMMIE BIN ROHANI
 NRIC/Passport Number
 Contact Number 86206510

Address	NA
	NA
Postcode	NA
Insurance Company Name	
Nature Of Damage	NA
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SKN9549X
Vehicle Make/Model/Colour	NA
Details Of Properties	NA
Vehicle Category	PRIVATE CAR
Name of Driver	KOO YOON SEONG
NRIC/Passport Number	
Contact Number	NA
Address	NA
	NA
Postcode	NA
Insurance Company Name	
Nature Of Damage	NA
No. Of Passenger (Including Driver)	


DETAILS OF INJURED PERSON 1

Name	THANG KOK WEI JOHN
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SMN5261C
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Accident Sketch Plan Pg. 1

SKETCH PLAN

Clemente Avenue G



A : SMN 5261 L
 B : GBH 9155 R
 C : SKW 9549 X

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report No. 3.D / 2019/003/7017

Insurance Co:	NTUC
Vehicle No:	SMN 5261 L
Date of Accident:	3/10/2019
<input type="checkbox"/> Reporting Only <input type="checkbox"/> Own Damage Claim <input checked="" type="checkbox"/> Third Party Claim	

Workshop: Progressive Auto

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

Police Report Pg. 1



**SINGAPORE
POLICE FORCE**



D/20191003/7017

1 of 2

POLICE REPORT (NP299)

Report No. D/20191003/7017

Police Station Of Origin
Clementi Division HQ
20 Clementi Avenue 5 SINGAPORE 129858
Tel No:1800-7740000

Date/Time Report Made 03/10/2019 14:35	Vide Report No.	Station Diary No.
Name Of Informant THANG KOK WEI JOHN	Address APT BLK 807C CHO A CHU KANG AVENUE 1 #02-540 SINGAPORE 683807	
ID Type / ID No. NRIC NO / S7935500C	Contact No. Home/Office:	Mobile: 88589186
Nationality SINGAPORE CITIZEN	Email Address johnthang1979@gmail.com	
Occupation PRIVATE HIRE DRIVER	Sex Male	Age 39
Institution/School Name	Date of Birth 29/11/1979	Race Chinese
Date/Time Of Incident 03/10/2019 07:30	Location Of Incident CLEMENTI AVENUE 6	

Brief details.

On the above mentioned date and time, I was travelling along Clementi Ave 6 towards AYE in my vehicle SMN5261C. There was 1 passenger on board of my vehicle. Vehicle in front of me came to a stop and I followed suit. Suddenly, I felt a huge impact from the rear of my vehicle. I got down and realised that I was involved in a chain collision involving 2 other vehicles. Order of vehicles as follows:

- 1 - SMN5261C (My Vehicle)
- 2 - GBH9155L (Red Ninja Van)
- 3 - SKN9549X (Red Volvo)

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 03/10/2019 14:35
Officer In-Charge Of Case:	Classification Of Case:

Authentication Stamp

Police Report Pg. 1



**SINGAPORE
POLICE FORCE**



D/20191003/7017

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. D/20191003/7017

We exchanged particulars and left the scene. After about 3 hours, I started to feel soreness on my neck, shoulders and back areas. As such, I proceeded to visit my family doctor at Unihealth 24-Hr Clinic Toa Payoh. I am lodging this report as I was given 5 days MC.

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 03/10/2019 14:35
Officer In-Charge Of Case:	Classification Of Case:

Authentication Stamp

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50

AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6886 9095 Email: claims@focusauto.com.sg

GST:200712509E RCB NO:201004495R

*Not Allowed
here
2/50 2200
The phc Attorney
3dy.
14/10/19*

M/S : CHINA TAIPING

Estimate No: EST0001023

Date: 12 Oct 2019

Policy No:

Veh Reg No: **SMN5261C**

Make/Model: HONDA FREED

Chassis No: GB71093688

Engine No: LEB5633062

Reg. Date: 15/08/2019

ATTN: Motor Claim Department

Your Ref No: SMN5261C HONDA FREED

Claim Type: Third Party

Accident Date: 03/10/2019

Estimate Repair Cost to Vehicle No :SMN5261C

PAGE:1/2

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
List Price				
1 Rear Boot <i>500/500 96790</i>	1,460.50	1 PC	1,460.50	
2 Rear Boot Lock <i>11</i>	181.60	1 PC	181.60	X
3 Rear Boot Rubber <i>11</i>	185.00	1 PC	185.00	X
4 Rear Boot Emblem (Freed) <i>rec</i>	47.10	1 PC	47.10	
5 Rear Boot Emblem (Hybrid) <i>rec</i>	48.20	1 PC	48.20	
6 Rear Boot Centre Moulding <i>11</i>	287.30	1 PC	287.30	X
7 Rear Boot Reflector <i>11</i>	384.20	1 PC	384.20	X
8 Rear Bumper <i>10/10</i>	690.30	1 PC	690.30	
9 Rear Bumper Side Retainer <i>11</i>	28.00	2 PC	56.00	X
10 Rear Bumper Lower Clips <i>rec</i>	5.50	4 PC	22.00	X
11 Rear End Panel <i>R</i>	523.20	1 PC	523.20	X
			3,885.40	
	Less 10%		388.54	3,496.86
Special Net				
12 Rear Windscreen <i>sealant rec</i>	60.00	1 PC	60.00	40
13 Rear Bumper Sensor <i>shock</i>	300.00	1 SET	300.00	200
			360.00	360.00
Labour				
14 Panel Beating	950.00	1 PC	950.00	300
15 Check Wiring	60.00	1 PC	60.00	20
16 Rust Proofing	60.00	1 PC	60.00	30
17 To Remove & Refit Rear Windscreen	160.00	1 PC	160.00	120
18 To Remove & Replace Bumper Sensor	80.00	1 PC	80.00	50

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50

AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6886 9095 Email: claims@focusauto.com.sg

GST:200712509E RCB NO:201004495R

M/S : CHINA TAIPING

Estimate No:EST0001023

Date: 12 Oct 2019

Policy No:

Veh Reg No: **SMN5261C**

Make/Model: HONDA FREED

Chassis No: GB71093688

Engine No: LEB5633062

Reg. Date: 15/08/2019

ATTN:Motor Claim Department

Your Ref No: SMN5261C HONDA FREED

Claim Type: Third Party

Accident Date: 03/10/2019

Estimate Repair Cost to Vehicle No :SMN5261C

PAGE:1/2

Description	U/Price	Quantity	List Price	Amount
List Price			<u>S\$</u>	<u>S\$</u>

19 To Spray Painting

850.00

1 PC

850.00

600

2,160.00 2,160.00

Total S\$ 6,016.86

TOTAL: SINGAPORE DOLLAR SIX THOUSAND SIXTEEN AND CENTS EIGHTY SIX ONLY

For FOCUS AUTO PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To respray before/after spray painting
- To underlay damaged part(s) during respray
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No third modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

AUTHORISED SIGNATURE

P-1775-50
202
P-1420-40
S.N-240.00
L-1120-00
2780-40
202
27243

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19017958/UTD3N2

Date: 16/10/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN18349518000		
Claimant Vehicle No :	SMN5261C	Insured Vehicle No :	GBH9155L		
Date of Loss:	03/10/2019	Nature of Claim:	TP	Claim No:	SNM19D204680C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMN5261C		
Make & Model:	HONDA FREED HYBRID, 1.5 G (A)	Engine No:	LEB5633062
Reg. Date:	15/08/2019 (Man. Year: 2019)	Chassis No:	GB71093688
Colour:	Grey	Odometer:	16498 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/65R15	Rear Tyre Size:	185/65R15
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %	
Parts	3,856.86	1,660.40	2,196.46	56.95	
Miscellaneous Items	0.00	0.00	0.00		
Labour	2,160.00	1,120.00	1,040.00	48.15	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
Calculated Gross Total (S\$)	6,016.86	2,780.40	3,236.46	53.79	
Approved Total (Overridden) (S\$)		2,200.00			
	(S\$)	6,016.86	2,200.00	3,816.86	63.44
+ GST 7.00/7.00% (S\$)	421.18	154.00	267.18	63.44	
Nett Amount (S\$)	6,438.04	2,354.00	4,084.04	63.44	

INSPECTION

Date of Assignment:	15/10/2019		
Date Inspected:	14/10/2019	Inspected At:	Focus Auto Pte Ltd (Kaki Bukit) NO 1 KAKI BUKIT AVE 6(AUTOBAY) #02-50 Singapore 417883
Estimated Period of Repair:	3.0 days		

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 16 Oct 2019)
Parts: M1-MPV	HONDA FREED HYBRID 1.5 G (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMN5261C)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Badly Dented/Bent	1,460.50 FL	*967.90 FL
2	1		*REAR BOOT LOCK	Not Necessary	181.60 FL	*- FL
3	1		*REAR BOOT RUBBER	Not Necessary	185.00 FL	*- FL
4	1		*REAR BOOT EMBLEM (FREED)	Necessary	47.10 FL	*47.10 FL
5	1		*REAR BOOT EMBLEM (HYBRID)	Necessary	48.20 FL	*48.20 FL
6	1		*REAR BOOT CENTRE MOULDING	Not Necessary	287.30 FL	*- FL
7	1		*REAR BOOT REFLECTOR	Not Necessary	384.20 FL	*- FL
8	1		*REAR BUMPER	Dented/Deformed	690.30 FL	*690.30 FL
9	2		*REAR BUMPER SIDE RETAINER	Not Necessary	56.00 FL	*- FL
10	4		*REAR BUMPER LOWER CLIPSE	Necessary	22.00 FL	*22.00 FL
11	1		*REAR END PANEL	Repair	523.20 FL	*- FL
12	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
13	1		*SET REAR BUMPER SENSOR	Shorted	300.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,245.40	2,015.50
- List Item Discount on L Items 10.00/20.00% (\$\$)	388.54	355.10
Total Parts (\$\$)	3,856.86	1,660.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	950.00	300.00
2	CHECK WIRING	New	60.00	20.00
3	RUST PROOFING	New	60.00	30.00
4	TO REMOVE & REFIT REAR WINDSCREEN	New	160.00	120.00
5	TO REMOVE & REPLACE BUMPER SENSOR	New	80.00	50.00
6	TO SPRAY PAINTING	New	850.00	600.00
Gross Labour Cost (\$\$)			2,160.00	1,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >