

ASS. REC. BY:

REF:

053/SMO/9017973/Hcd302

Special Instruction:

Survey: Huck AmASSIGNMENT (Office)

Meimien

From (Person): Huang Shiang Yi

of

SMO

Date/Time:

11/10/2019 @ 2.20pm

Estimated Cost:

Bill to:

OD TP WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJW 861S

Insured:

SLD 1933M

at Workshop m/s

My Car Consultant

Tel:

88668832

of

53 Ubi Ave 1 # 01-33

Policy No:

D19MTPV01008026

Claim No:

CMTD1904778

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

8/10/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

3.53pm 11/10/19

Person Contacted:

Hui Qin

Vehicle IN/OUT

Date/Time

Action/Instruction

Fchm/ll (X)

SJW 861S - X

SLD 1933M - X

Dismantle: 15/10/2019

After repair: 16/10/2019

ASS. REC. BY: H. Ann

REF: SMO

ASSIGNMENT

From:

Date:

15/10/19

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

SJW 8615

at Workshop m/s

my car consultant

of

53 ubi Avenue 1# 01-33

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

XX	
N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS up

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SJW 8615

Yr Regn:

16/04/2007

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

H. CRV AT

c.c

2354

Colour:

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

304772 km

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JHLRE 48507C 204811

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 235/60/R18

R:

235/60/R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Fut and Rur → (PIR)

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

8/10/19

D.O.I.

15/10/19

Survey held at

my car con

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

range → 2.5-3.5 km SJW 8615 NON

repair Days → 3

Estimate (PRS)

Case #

MV - 47000 RECEIVED 25 OCT 2019
PV - 38999
NV - 8000

Signature
24/10/2019

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

2

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Insp (\$)

☐

: Weekend (\$)

Survey Fee:

100

Transportation:

60

3 + RS, SI

60

Photos

Others

11

TOTAL

231

Report Format:

PRS.

Lump Sum / L.B.I: (\$)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Oct 2019		11 Oct 2019 14:20 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	CHONG LIANG HIAN, ID: S1472664J		
Main Claimant:	NG HWEE HENG DAVIS, ID: S7230066A		
Vehicle Reg. No.:	SJW861S	Date of Loss:	08/10/2019 18:00 - :59
Claim Type:	TP / CMTD1904778	Policy/Cover Note No.:	D19MTPV01008026 (Comprehensive)
Vehicle Reg. No. (Insured):	SLD1933M	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	My Car Consultant - Ubi (HQ) 53 Paya Ubi Industrial Park, #01-33, 408934 Ubi - Tel:		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Hwang Shiang Yi - 6329 5205]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 22/10/2019]		
Driver/Custodian (Insured):	TAN LAY GIN (), NRIC: S1665922C, Tel: +6592346326 Email: -		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	066A
Vehicle Details	
Vehicle No.:	SJW861S
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Oct 2019
Vehicle Make:	HONDA
Vehicle Model:	HONDA CRV 2.4L AT
Primary Colour:	Black
Manufacturing Year:	2007
Engine No.:	K24Z11758506
Chassis No.:	JHLRE48507C204811
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$28,433.00
Original Registration Date:	16 Apr 2007
First Registration Date:	16 Apr 2007
Transfer Count:	2
Actual ARF Paid:	\$31,277.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	15 Apr 2027
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$52,008.00
COE Rebate Amount:	\$38,999.00
Total Rebate Amount:	\$38,999.00

The information contained herein is correct as at 16 Oct 2019

OK

7.5

Enquire Vehicle Transfer Fee

Vehicle Details

Vehicle No. SJW861S	
Make / Model HONDA / HONDA CRV 2.4L AT	
Vehicle Type : P11 - Passenger Station Wagon/Jeep/Land Rover	Vehicle Attachment 1 : With Sun Roof
Vehicle Scheme : Normal	Chassis No. : JHLRE48507C204811
Propellant : Petrol	Engine No. : K24Z11758506
Motor No. : -	Engine Capacity : 2354 cc
Power Rating : -	Maximum Power Output : 125.0 kW (167 bhp)
Maximum Laden Weight : 2060 kg	Unladen Weight : 1605 kg
Year Of Manufacture : 2007	Original Registration Date : 16 Apr 2007
Lifespan Expiry Date : -	COE Category : B - Car (1601cc & above)
PQP Paid : \$52,008.00	COE Expiry Date : 15 Apr 2027
Road Tax Expiry Date : 15 Apr 2020	PARF Eligibility Expiry Date : -
Inspection Due Date : 15 Apr 2020	Intended Transfer Date : 16 Oct 2019
CO2 Emission : -	CEV/VES Rebate Utilised Amount : -
CO Emission : -	HC Emission : -
NOx Emission : -	PM Emission : -

Fees To Be Paid For Transfer

Transfer Fees	\$25.00
---------------	---------

Print

Save as PDF

Copy as Text

OK →

- New Cars
- Used Cars
- Sell My Car
- Directory
- Products
- Insurance
- Articles
- Forum
- Resources



CONNECTING CAR BUYERS & SELLERS.
We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)



[Home](#) > [Used Cars](#) > [Direct Owners](#) > [Honda CR-V 2.0A \(COE till 09/2028\)](#)

[Honda CR-V 2.0A](#)

[Price Range](#)

[Depreciation](#)

[Year Reg](#)

[Vehicle Type](#)

[Advanced Search](#)

*can't not find and H-CRV 2.4
renew COE
use of return model*

[Honda CR-V 2.0A \(COE till 09/2028\)](#)

[Overview](#)
[Financial](#)
[Insurance](#)
[Accessories](#)
[Similar](#)
[Research](#)
[Photos](#)
[Map](#)

Price \$51,000

Depreciation \$5,720 /yr

Mileage 118,000 km (10.6k /yr)

Road Tax \$1,331 /yr

Dereg Value \$29,783 as of today (change)

COE \$33,377

Engine Cap 1,997 cc

Curb Weight 1,540 kg

Type of Vehicle SUV

Reg Date 18-Sep-2008
(8yrs 10mths 30days COE left)

Manufactured 2008

Transmission Auto

OHV \$24,652

ARF \$24,652

Power 110.0 kW (147 bhp)

No. of Owners 3

Features
Engine With I-VTEC Engine, 5 Speed Auto Transmission, Dual SRS Airbags, ABS, Dual Climatic Aircon Controls, Auto Headlights, Cruise Control. View specs of the Honda CR-V (2007-2012)


Accessories
Leather Seats, Fog Lamps, Side Steps, Retractable Mirrors, Solar Films, Electric Driver Seat, Audio System With Steering Control.


Description
Female Driver And Direct Owner, Regularly Servicing At Workshop, Great For Family, Please Whatsapp To Arrange For Test Drive. Last Serviced Car On 12-June-2019, Cat B Vehicle.








Category
COE Car, Direct Owner Sale

Status
Available


Resources

 **Car Valuation - Free**
Find out the market value of your existing car for free. Get started

 **Vehicle Evaluation**
Afraid of lemons? Request to have this car evaluated professionally. Find out more

100% FREE PAPERWORK SUPPORT FOR BOTH BUYER & SELLER

 Preferred Viewing Area

[Shortlist](#) [Compare](#) [Add note](#)

[Report Error](#) [More Actions](#)


Seller Information


Contact Person(s) Jess

Contact No. 84481782

ESSENTIAL TRANSACTION FORMS

- Indemnity form
- Receipt
- Ownership Transfer
- Sales agreement
- Hand-over form

 GET HELP WITH PAPERWORK

 SGCARMART CONNECT

sgCarMart Connect handles your transaction paperwork - send us your completed Sales Agreement, and we'll help with Car Loans, Insurance, Payments & Ownership Transfer, FREE for all sgCarMart Advertised Vehicles.

[Upload your Sales Agreement](#)

[Read our 8 Step Guide for Direct Buyers & Sellers](#)

Posted on: 01-Oct-2019 | Last Updated on: 14-Oct-2019

Upfront Payment

Transfer Fee	\$25	
Down Payment	\$15,300 (change)	Maximum 70% Loan
1st Instalment	\$537	Based on 3.79% interest rate
Insurance	\$707 onwards (Get a quote)	Extra 15% Off for MINDEF, MHA & POGIS policyholders
		Quote assumes a standard profile. "Get a quote" for exact figure.
Total Upfront Payment	\$16,569	Check with seller for exact figure

View Financial Info



Tags: Honda CR-V, honda CRV, 2008 Honda CR-V, 2008 honda CRV, Honda, CR-V, CRV, Used Honda

Recommended for you

1-6 of 18



What is VEP and how do you register for it



Updated Honda Civic continues to impress



BMW 3 Series is all the car you ever need



Honda teases image of the new Jazz



Car number plates and what they stand for



How much Mileage Adjustment will a dealer adjust?

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/10/2019 16:30
Date Of Accident	08/10/2019 18:50
Exact Location Of Accident	PAYA LEBAR SQUARE CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJW861S
Insured/Policyholder	
Name Of Registered Owner	NG HWEE HENG, DAVIS
NRIC No	S7230066A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91017779
Alternative Phone No	OTHERS-96326600

Vehicle Particulars

Manufacturer	HONDA
Model	CR-V-2.4 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA496748
Cover Note Number	

Driver

Name of Driver	TANG CHEE PENG
NRIC No	S7505621D
Date Of Birth	03/02/1975
Occupation	INDOOR
Date Of Driving Pass	18/01/2000
Driving Experience	19 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96326600
Fax Number	
Contact Number	
EMail Address	JOHN@GTT.COM.SG

Address	BLK 273C COMPASSVALE LINK #15-160 SINGAPORE
Postcode	543273
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	FRIEND
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : PAX 1 GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE ATTACH STATEMENT RECORDED BY PEI WEN - PROGRESSIVE CAR CARE PTE LTD TEL 6741 5336

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLD1933M (Toyota wish)
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TAN LAY GIN
NRIC/Passport Number	S1665922C
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

Nô. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

4:16pm
9/10/19

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	09 Oct 2019		11 Oct 2019 14:20 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	CHONG LIANG HIAN, ID: S1472664	
Main Claimant:	NG HWEE HENG DAVIS, ID: S7230066A	
Vehicle Reg. No.:	SJW861S	Date of Loss: 08/10/2019 18:00 - :59 [149 Months and 22 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / CMTD1904778	Policy/Cover Note No.: D19MTPV01008026 (Comprehensive)
Vehicle Reg. No. (Insured):	SLD1933M	Policy No. (Claimant):
		Excess: S\$0.00
Repairer:	My Car Consultant - Ubi (HQ) 53 Paya Ubi Industrial Park, #01-33, 408934 Ubi - Tel:	
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Hwang Shiang Yi - 6329 5205]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 22/10/2019]	
Driver/Custodian (Insured):	TAN LAY GIN (), NRIC: S1665922C, Tel: +6592346326 Email:	












































ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		









































ALL ASSOCIATED TASKS		View All	Search Tasks	Create New Task	Complete				
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJW861S (CMTD1904778)
[SLD1933M]

TP
NG HWEE HENG DAVIS
Oct 8 2019 6:00PM
[CHONG LIANG HIAN]
My Car Consultant - Ubi

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/10/19 18:47	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
2	17/10/19 18:48	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
3	17/10/19 18:48	General View	 Load JPG	<input checked="" type="checkbox"/>
4	17/10/19 18:48	General View	 Load JPG	<input checked="" type="checkbox"/>
5	17/10/19 18:48	General View	 Load JPG	<input checked="" type="checkbox"/>
6	17/10/19 18:48	General View	 Load JPG	<input checked="" type="checkbox"/>
7	17/10/19 18:48	General View	 Load JPG	<input checked="" type="checkbox"/>
8	17/10/19 18:48	General View	 Load JPG	<input checked="" type="checkbox"/>
9	17/10/19 18:48	General View	 Load JPG	<input checked="" type="checkbox"/>
10	17/10/19 18:48	General View	 Load JPG	<input checked="" type="checkbox"/>
11	17/10/19 18:48	General View	 Load JPG	<input checked="" type="checkbox"/>
12	17/10/19 18:48	General View	 Load JPG	<input checked="" type="checkbox"/>
13	17/10/19 18:48	General View	 Load JPG	<input checked="" type="checkbox"/>
14	17/10/19 18:48	General View	 Load JPG	<input checked="" type="checkbox"/>
15	17/10/19 18:48	General View	 Load JPG	<input checked="" type="checkbox"/>
16	17/10/19 18:48	General View	 Load JPG	<input checked="" type="checkbox"/>
17	17/10/19 18:48	General View	 Load JPG	<input checked="" type="checkbox"/>
18	17/10/19 18:48	General View	 Load JPG	<input checked="" type="checkbox"/>
19	17/10/19 18:49	General View	 Load JPG	<input checked="" type="checkbox"/>
20	17/10/19 18:49	General View	 Load JPG	<input checked="" type="checkbox"/>
21	17/10/19 18:49	General View	 Load JPG	<input checked="" type="checkbox"/>
22	17/10/19 18:49	General View	 Load JPG	<input checked="" type="checkbox"/>
23	17/10/19 18:49	General View	 Load JPG	<input checked="" type="checkbox"/>
24	17/10/19 18:49	General View	 Load JPG	<input checked="" type="checkbox"/>
25	17/10/19 18:49	General View	 Load JPG	<input checked="" type="checkbox"/>
26	17/10/19 18:49	General View	 Load JPG	<input checked="" type="checkbox"/>
27	17/10/19 18:49	General View	 Load JPG	<input checked="" type="checkbox"/>
28	17/10/19 18:49	General View	 Load JPG	<input checked="" type="checkbox"/>
29	17/10/19 18:49	General View	 Load JPG	<input checked="" type="checkbox"/>
30	17/10/19 18:49	General View	 Load JPG	<input checked="" type="checkbox"/>
31	17/10/19 18:49	General View	 Load JPG	<input checked="" type="checkbox"/>
32	17/10/19 18:49	General View	 Load JPG	<input checked="" type="checkbox"/>
33	17/10/19 18:49	General View	 Load JPG	<input checked="" type="checkbox"/>
34	17/10/19 18:49	General View	 Load JPG	<input checked="" type="checkbox"/>
35	17/10/19 18:49	General View	 Load JPG	<input checked="" type="checkbox"/>
36	17/10/19 18:49	General View	 Load JPG	<input checked="" type="checkbox"/>
37	17/10/19 18:49	General View	 Load JPG	<input checked="" type="checkbox"/>
38	17/10/19 18:49	General View	 Load JPG	<input checked="" type="checkbox"/>
39	17/10/19 18:49	General View	 Load JPG	<input checked="" type="checkbox"/>
40	17/10/19 18:49	General View	 Load JPG	<input checked="" type="checkbox"/>
41	17/10/19 18:49	General View	 Load JPG	<input checked="" type="checkbox"/>
42	17/10/19 18:49	General View	 Load JPG	<input checked="" type="checkbox"/>
43	17/10/19 18:49	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	17/10/19 18:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	17/10/19 18:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	17/10/19 18:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	17/10/19 18:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	17/10/19 18:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	17/10/19 18:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	17/10/19 18:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	17/10/19 18:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	17/10/19 18:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	17/10/19 18:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	17/10/19 18:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	17/10/19 18:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	17/10/19 18:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	17/10/19 18:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	17/10/19 18:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	17/10/19 18:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	17/10/19 18:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	17/10/19 18:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	17/10/19 18:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	17/10/19 18:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	17/10/19 18:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	17/10/19 18:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	17/10/19 18:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	17/10/19 18:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	17/10/19 18:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	17/10/19 18:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	17/10/19 18:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	17/10/19 18:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	17/10/19 18:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	17/10/19 18:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	17/10/19 18:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	17/10/19 18:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	17/10/19 18:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	17/10/19 18:51	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
78	17/10/19 18:51	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
79	17/10/19 18:51	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
80	17/10/19 18:51	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
81	17/10/19 18:51	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	11/10/19 14:22	Pre-Repair Survey-MY CAR CONSULTANT ACK/ASSIGN LKK	 Load PDF	
2	11/10/19 14:26	Third Party E-filed GIA report	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/SMO19017973/HCD3E2

Date: 30/10/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D19MTPV01008026
Claimant Vehicle No :	SJW861S	Insured Vehicle No :	SLD1933M
Date of Loss:	08/10/2019	Nature of Claim:	TP
		Claim No:	CMTD1904778

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJW861S	Engine No:	K24Z11758506
Make & Model:	HONDA CR-V, 2.0 L AT (A)	Chassis No:	JHLRE48507C204811
Reg. Date:	16/04/2007 (Man. Year: 2007)	Odometer:	304772 km
Colour:	Black		
Engine Capacity:	2354 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/60 R18	Rear Tyre Size:	235/60 R18
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	Pirelli 5 mm	Rear Right Side:	Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	11/10/2019	
Date Inspected:	15/10/2019	Inspected At: My Car Consultant - Ubi (HQ) 53 Paya Ubi Industrial Park, #01-33 Singapore 408934
Estimated Period of Repair:	3.0 days	

Adjuster: LEE HOCK ANN

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,500.00 - \$3,500.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Oct 2019)
Parts:	M1-SUV	HONDA CR-V 2.0 L AT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJW861S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >