

INS. CASE OWNER:


CC3/CTI19017983/K1ka3

LKK:

IDAC:

ASSIGNMENTSurveyor: **KALVIN**DOI: **10/10/2019**Date / Time : **10/10/2019**

Registered in Merimen: _____

Pre-assign / CCU / FTEInsured Vehicle No. : **SLJ 5150Y**

Claim No. : _____

Name of Insured : _____

Policy No. : _____

Insured Tel No. : _____ HP: _____

Make / Model : _____

Excess Sec II :S\$ _____ D.O.A : **09/10/19 18:45**Place of Accident : **SLIP ROAD FROM BUANGKOK GREEN TO HOUGANG ST 11**

Is driver the owner? (YES / NO) Nature of Accident : _____

If NO, Driver Name / Age : _____

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. : _____ (V/L: YES / NO)

Insured Liability : % **Final ? Yes / No****SHC 626J**INSRS:
WSP: **CDGE LOYANG**
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/ Time				
	SHC 626J - CS/FCI19011055/Kvd3n2; DOA: 19/06/2019	STAGE	DATE / PIC	
	- CC4/ASM18003327/K1hb3q2; DOA: 19/02/18	Non-Reporting ltr (1st):		
	- CS/FCI15003302/R1qbu2; DOA: 22/2/15	Non-Reporting ltr (2nd):		
	SLJ 5150Y - X	Non-Reporting ltr (Final):		
		Notification ltr (if non-pickup):		
		Call OI:		
		After call ltr to OI:		
		Documentation Check List:	Handler	Typist
		Notification ltr (if non-pickup)	☐	☐
		After call ltr to OI:	☐	☐
		Authorisation To Act:	☐	☐
		Release Voucher:	☐	☐
		Final Repair Bill:	☐	☐
		Car Rental Invoice:	☐	☐
		Towing Invoice	☐	☐
		LTA / GIA :	☐	☐
		Medical Bill:	☐	☐
		PIR:	☐	☐
		Mandate/Reject Instruction:	☐	☐
		LOD	☐	☐
		Payment Breakdown Form:	☐	☐
PRELIMINARY ADVICE	Date/Time:	Sent By:	Post-Repair Photos:	☐
			Others:	☐
FINALIZATION	Date/Time:	Confirm with:	Confirm by:	
Repair Cost:	S\$	(days) Reduction:	%	Email ☐ Call ☐
FINAL SETTLEMENT	Date/Time:	Confirm with	Email ☐ Call ☐	
Final Liability:	%	(Agreed / Assessed) BOLA S/N No. :	If NO or B 28, Ass. Lia :	
Repair Cost:	S\$			
Loss of Rental (LOR):	S\$	(days)		
Loss of Use (LOU):	S\$	(\$ x days)		
Loss of Income (LOI):	S\$	(\$ x days)		
LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐	[Tick only one]			
GIA/LTA Search	S\$			
Medical:	S\$		1) Claim status: Normal/Reject/Private Settle	
Disbursement:	S\$	(e.g. Tow/ Independent)	2) Report Format:	
Legal Cost	S\$		3) Survey fee:	
Total:	S\$	Global Sum S\$:		
FINAL PAYMENT	Date/Time:	Confirm with:	Email ☐ Call ☐	
Payee 1:	S\$	Name 1:		
Payee 2: (Strike if N.A.)	S\$	Name 2:		
Payee 3: (Strike if N.A.)	S\$	Name 3:		

(08/11/3)

Surveyor: KalvinREF: 1

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Insp'd Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHC 626J Yr Regn: 25 Oct, 2012

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Santa Fe c.c. 1900Colour: Yellow A/C: Insured / Std / NI / NASp. Reading: 185 785 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHET41UMCA83618

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size: F: 215 / 65R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or HankookFront 2 mm Rear 2 mmR/Bal. 2 mm R/Bal. 2 mmL/Bal. 2 mm L/Bal. 2 mmD.O.A. 9/10/19 D.O.I. 10/10/19Survey held at C/DHE (Loyang)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

CTI
4

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)

S + RS \$ _____

Photos

Team: ARC Repair TP(CFSO)1

JOB CARD

Sales Order:

JC NO.: 305340317

OMER	REGN NO.: SHC 626J	MILEAGE
S CITYCAB PTE LTD	MAKE: HYUNDAI	FUEL
OMER NO. 7010070	MODEL SONATA	E.....1/2.....F
ESS 383 SIN MING DRIVE	DATE/TIME IN	10.10.2019 10:35
Singapore SINGAPORE 575717	YR OF MANU	TARGET DATE
65551188 (R) (P)	25.10.2012	
	CHASSIS CODE	COMPLETION DATE/TIME:
	KMHET41VMCA831018	


JUNT CARD NO.

JOB DESCRIPTION

Accident Date: 09.10.2019

NATURE: 3P 09.10.19

S/NO LABOR CODE DESCRIPTION



KED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

lo.: SHC 626J JU CHINA

Vehicle No.: SHC 626J

Service Advisor

Signature/Date

Name of Service Advisor

Date

urned to Service Reception upon collection

To be kept by Security Guard

China - 14
19 11:33 LDM

DATE 10/10/2019 11:33

MODEL : HYUNDAI SONATA

Page 1 of 1

KCN

COMFORTDELGRO ENGINEERING

Our Job Ref No 305340317
Date : 12/10/19

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK
Attn : KALVIN
: SHC 626J

Fax :

305333809 09/10/19

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: CHINA --- SLJ5150Y
###
2. The finalized amount shall be:

(a) Spare Parts after List discount		\$0.00
(b) Labour Charges	###	\$440.00
Total for Part-By-Part Repair Cost	###	\$440.00
(c.) Lumpsum Repair (if applicable)		
Total for Lumpsum repair cost after Less: <u>20%</u>		
Final Lumpsum Repair cost		

3. Estimated normal period for repairs: 2 working days

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : JUMANI
Tel : 6214 8315
Fax : 65468156

Signature : 
Name : Kalvin
Date : 14/10/19

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 11.10.2019

Time: 17:36:54

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS : CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 305340317
REGN NO : SHC 626J
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : SONATA
DATE OF REGN : 25.10.2012
DATE/TIME IN : 10.10.2019 10:35
ACCIDENT DATE : 09.10.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

SUB-TOTAL : 0.00

JOB NATURE

0000 PB	PANEL BEATING	240.00
0001 SP	SPRAYPAINT CHARGE	200.00

SUB-TOTAL : 440.00

TOTAL : 440.00

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :