

/SS. REC. BY:

REF: CS/CT219018014/Agf30

Special Instruction:

Surveyor: Adrian

ASSIGNMENT (Office)

From (Person): Ong Chin Kiat

of CTI

Date/Time: 11.10.19 17.12pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJZ 4512H

Insured: SKJ 7800D

at Workshop m/s Kang Car Repairs

Tel: 67472636

of NO 1 Kaki Bukit Ave 6 A 02-06

Policy No: DMTPSV16139419033

Claim No: SNM 19D 20478702

Sum Insured:

Excess:

Make of Veh:

D.O.A. 10.10.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 14.10.19 9.05am

Person Contacted:

Jeffrey

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SKJ 7800D : X

SJZ 4512H : X

US \$1300, 3 days (red \$1122.61, 46%)

ASSIGNMENT

Veh No: SJ2451217 Yr Regn: 2010 Nov

Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: Toyota Vios C.C. 1497

Colour silver A/C: Insured / Std / NI / NA

Sp. Reading 213810. T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MR053HY9305173.70

Gen. Cond: Good Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi : Nil / (S/Rim) / STD A/Rim or

Tyre Size: F: 185/60 R15

R: 185/60 R15

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO

Front

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 14/10/19.

Survey held at Keny

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

Front o/s.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP China.
	RECEIVED 10 DEC 2019
	MV : 19K
	PV : 10.5K
	Nett: 8.5K

Days Of Repair: 3

Resurvey No. of Trip:

Survey Fee: 200

Transportation:

Add Fee: : Site Insp (\$

 Interview (15)

Tech. Invs. 48

☐ Weekend (3)

3	$S + PS$	SI
---	----------	----

Figure

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Oct 2019		11 Oct 2019 17:12 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All																				
CLAIM SUBFOLDER DETAILS		[Created by insurer]																						
Insured:	ST AUTOMOBILE PTE LTD, Co. Reg. No.: 201605341M																							
Main Claimant:	COMFORTDELGRO DRIVING CENTRE PTE LTD, Co. Reg. No.: 199601882C																							
Vehicle Reg. No.:	SJZ4512H	Date of Loss:	10/10/2019 11:00 - :59 [106 Months and 15 Days From LTA Reg Date (Man Yr)]																					
Claim Type:	TP / SNM19D204787C02	Policy/Cover Note No.:	DMTPSN16139419033																					
Vehicle Reg. No. (Insured):	SKJ7800D	Policy No. (Claimant):	M489523																					
		Excess:	S\$0.00																					
Repairer:	Kang Car Repairers Pte Ltd (HQ) No 1 Kaki Bukit Ave 6, #02-06 AutoBay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67477636																							
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]																							
Claimant's Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100																							
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 22/10/2019]																							
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail																						
There are no mail for this case.																								
<div> ALL ASSOCIATED TASKS </div> <div> View All Search Tasks Create New Task Complete </div> <table border="1"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	882C
Vehicle Details	
Vehicle No.:	SJZ4512H
Vehicle to be Exported:	Yes
Intended Deregistration Date:	14 Oct 2019
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS E AUTO
Primary Colour:	Silver
Manufacturing Year:	2010
Engine No.:	1NZY126269
Chassis No.:	MR053HY9305175790
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$12,306.00
Original Registration Date:	25 Nov 2010
First Registration Date:	25 Nov 2010
Transfer Count:	0
Actual ARF Paid:	\$12,306.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Nov 2020
PARF Rebate Amount:	\$6,768.00
Intended COE Rebate Details	
COE Expiry Date:	24 Nov 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$33,132.00
COE Rebate Amount:	\$3,681.00
Total Rebate Amount:	\$10,449.00

The information contained herein is correct as at 14 Oct 2019

OK



☐ Toyota Vios 1.5A G

\$15,800

N.A

22-Mar-2010

1,497 cc

97,000 km

Sedan

Available



100% Loan Available, We Only Select The Best Unit To Sell. All Our Car Come With Trade In Welcomed. Buy With A Peace Of Mind As Car Is In Fantastic Condition. Hurry, Call For Availability Or Viewing Appointment.

1axis

★ Posted: 08-Oct-2019 Tags: 2010 Toyota Vios, 2010 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota



☐ Toyota Vios 1.5A E (New 5-yr COE)

\$29,800

\$5,950 /yr

20-Apr-2010

1,497 cc

96,000 km

Sedan

Available

100% Loan Available, We Only Select The Best Unit To Sell. All Our Car Come With Trade In Welcomed. Buy With A Peace Of Mind As Car Is In Fantastic Condition. Hurry, Call For Availability Or Viewing Appointment.

1axis

★ Posted: 06-Oct-2019 Tags: 2010 Toyota Vios, 2010 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota



☐ Toyota Vios 1.5A E

\$15,800

\$15,770 /yr

25-May-2010

1,497 cc

-

Sedan

Available

High Loan! High Trade In! Popular Car Suitable For COE Renewal! Make Use Of The Low COE Prices! Call Now!

★ Posted: 11-Oct-2019 Tags: 2010 Toyota Vios, 2010 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota



Find the right car through consignment.

Purchase pre-loved, owner consigned cars at affordable prices through our dedicated consignment agents. Arrange a test drive today.

Find out more!



☐ Toyota Vios 1.5A E

\$18,000

\$12,790 /yr

17-Sep-2010

1,497 cc

89,000 km

Sedan

Available

1 Female Owner (2nd Owner Due To Temporary Transfer). Fully Maintained By Toyota Authorized Agent With Service Record Book. Accident Free. Very Well Maintained. Genuine Low Mileage. Easy Maintenance And Very Good Fuel Consumption. Call For Viewing!

★ Posted: 18-Aug-2019 Tags: 2010 Toyota Vios, 2010 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota

Save this search criteria, to get email alerts whenever a match is found.

Save Search

Make ▼ Model ▼ Price ▼ Depreciation ▼ Reg Date ▼ Eng Cap ▼ Mileage ▼ Veh Type ▼ Status ▼

For old advertisements, view Expired ads

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used vios, vios Singapore, used vios Singapore, used vios, used vehicles Singapore or even buy used vios Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow [sgCarMart.com](#)



[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

SHORTLISTED HISTORY

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/10/2019 14:10
Date Of Accident	10/10/2019 11:35
Exact Location Of Accident	UBI RD 4
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJZ4512H
-----------------------------	----------

Insured/Policyholder

Name Of Registered Owner	COMFORTDELGRO DRIVING CENTRE PTE LTD
Co Reg No	199601882C
Email Address	DARYLTAN@CDC.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-67401636

Vehicle Particulars

Manufacturer	TOYOTA
Model	VIOS-1.5 E (A)
Exact Purpose for which vehicle was being used at time of accident	TRAINING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	M489523
Cover Note Number	

Driver

Name of Driver	CHAN YAN LING CHELSA
NRIC No	S9042240E
Date Of Birth	06/11/1990
Occupation	OUTDOOR
Date Of Driving Pass	10/10/2019
Driving Experience	0 YEAR AND 0 MONTH
Gender	FEMALE
Mobile Number	(LOCAL) +65-96408089
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 203E COMPASSVALE RD #09-69
Postcode	545203
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - LEARNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : ALLAN TAN SIEW CHYE
	GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

CAR 249 WAS TURNING INTO THE SIDE ROAD TO UBI RD 4. I SIGNALLED RIGHT AND WHEN ABOUT TO TURN INTO THE LANE, SKJ7800D WAS DRIVING AT A FAST SPEED AND WENT AGAINST THE FLOW OF TRAFFIC TO OVERTAKE US. AS A RESULT, OUR RIGHT SIDE BUMPER OF CAR 249 WAS HIT BY CAR'S LEFT REAR BUMPER. NO ONE WAS INJURED. AS SKJ7800D SHIFTED THE CAR- NO PICTURE WAS TAKEN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

Details of Witness 1

Name	ALLAN TAN SIEW CHYE
Phone Number	91292069
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKJ7800D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	SUZANNE ONG SOK CHENG
NRIC/Passport Number	S7001020H

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by Interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any inquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

MountDelGro Driving Centre Pte Ltd


205 Ubi Ave 4
Singapore 408805

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Car 249, was turning into the side road to Ubi Rd. 4.

I signalled right and when about to turn into the lane, SKJ7800D was driving at a fast speed and went against the flow of traffic to overtake us.

As a result, our right side bumper of Car 249 was hit by car's left rear bumper.

No one was injured.

(As SKJ7800D shifted the car - no picture was taken.)

DECLARATION

I/we declare the foregoing particulars are true in every respect.

205 Ubi Ave 4
Singapore 408805

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S: CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 10/10/2019
TP Veh Reg No: SKJ7800D

Estimate No: EST1900337
Date: 11 Oct 2019

Veh Reg No: SJZ4512H
Make/Model: TOYOTA VIOSE AUTO
Chasis No: MR053HY9305175790
Reg. Date: 25/11/2010
Your Ref No: SKJ7800D

Estimate Repair Cost to Vehicle No :SJZ4512H

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
	List Price		
1	1 PC FRT BUMPER <i>Reformed</i>	487.30 ✓	
2	1 PC FRT BUMPER SIDE RETAINER RH <i>new</i>	54.80 ✓	
3	1 PC FRT FOG LAMP COVER RH <i>new</i>	85.80 x	
4	1 PC HEADLAMP RH <i>Replaced</i>	585.30 ✓	
5	1 PC FRT FENDER 'VVTI' EMBLEM <i>new</i>	43.60 ✓	
		1,256.80	
	Less 25%	314.20	942.61
	Special Net		
6	1 SET FRT BUMPER CLIPS <i>new</i>	40.00 ✓	
7	2 PCS "L" PLATE BRACKET <i>new</i>	70.00 x	
8	1 SET FRT FENDER COWLING CLIPS RH <i>new</i>	40.00 x	
		150.00	150.00
	Labour		
9	1 TO CHECK WIRING	50.00 30	
10	1 TO SPRAY UNDERSEAL	80.00 x	
11	1 (FRONT) TO SPRAY PAINTING	600.00 350	
12	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	600.00 300	
		1,330.00	1,330.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian L
L/S 14/10/19.
03 Days
Total: 1600.75
L/S: 1.3K

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 10/10/2019
TP Veh Reg No: SKJ7800D

Estimate No: EST1900337
Date: 11 Oct 2019

Veh Reg No: SJZ4512H
Make/Model: TOYOTA VIOSE AUTO
Chasis No: MR053HY9305175790
Reg. Date: 25/11/2010
Your Ref No: SKJ7800D


Estimate Repair Cost to Vehicle No :SJZ4512H

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
	Total		S\$ 2,422.61
	Add GST @ 7%		169.58
	Total Amount Payable		<u>S\$ 2,592.19</u>

TOTAL: SINGAPORE DOLLAR TWO THOUSAND FIVE HUNDRED NINETY TWO AND CENTS NINETEEN ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd



AUTHORISED SIGNATURE

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Oct 2019		11 Oct 2019 17:12 Edit Adj Rpt	\$1,300.00 Edit Estimates	\$1,300.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	ST AUTOMOBILE PTE LTD, Co. Reg. No.: 201605341M		
Main Claimant:	COMFORTDELGRO DRIVING CENTRE PTE LTD, Co. Reg. No.: 199601882C		
Vehicle Reg. No.:	SJZ4512H	Date of Loss:	10/10/2019 11:00 - :59 [106 Months and 15 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D204787C02	Policy/Cover Note No.:	DMTPSN16139419033
Vehicle Reg. No. (Insured):	SKJ7800D	Policy No. (Claimant):	M489523
		Excess:	\$0.00
Repairer:	Kang Car Repairers Pte Ltd (HQ) No 1 Kaki Bukit Ave 6, #02-06 AutoBay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67477636		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]		
Claimant's Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 22/10/2019]		
ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
There are no mail for this case.			
ALL ASSOCIATED TASKS		View All	Search Tasks
		Create New Task	Complete
Due Date	Priority	Type	Task Group
			Subject
			Handler
			Assigned By
			Completed On
			Created On
			Done?
No results.			

Claim Documents

*SJZ4512H (SNM19D204787C02)
[SKJ7800D]

TP

COMFORTDELGRO DRIVING CENTRE PTE LTD

Oct 10 2019 11:00AM


[ST AUTOMOBILE PTE LTD]

Kang Car Repairers Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kang Car Repairers Pte Ltd (HQ)		Thumbnail	Print
1	11/10/19 14:34	Accident Statement		Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	10/12/19 11:24	General View		Load JPG	<input checked="" type="checkbox"/>
2	10/12/19 11:24	Chassis Number		Load JPG	<input checked="" type="checkbox"/>
3	10/12/19 11:24	General View		Load JPG	<input checked="" type="checkbox"/>
4	10/12/19 11:24	General View		Load JPG	<input checked="" type="checkbox"/>
5	10/12/19 11:24	General View		Load JPG	<input checked="" type="checkbox"/>
6	10/12/19 11:24	General View		Load JPG	<input checked="" type="checkbox"/>
7	10/12/19 11:24	General View		Load JPG	<input checked="" type="checkbox"/>
8	10/12/19 11:24	General View		Load JPG	<input checked="" type="checkbox"/>
9	10/12/19 11:24	General View		Load JPG	<input checked="" type="checkbox"/>
10	10/12/19 11:24	General View		Load JPG	<input checked="" type="checkbox"/>
11	10/12/19 11:24	General View		Load JPG	<input checked="" type="checkbox"/>
12	10/12/19 11:24	General View		Load JPG	<input checked="" type="checkbox"/>
13	10/12/19 11:24	General View		Load JPG	<input checked="" type="checkbox"/>
14	10/12/19 11:24	General View		Load JPG	<input checked="" type="checkbox"/>
15	10/12/19 11:25	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
16	10/12/19 11:25	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
17	10/12/19 11:25	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
18	10/12/19 11:25	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
19	10/12/19 11:25	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	11/10/19 17:12	Estimate		Load PDF	
2	11/10/19 17:13	Insd GIA report		Load PDF	

Linked Accident Report Documents

				View View in Browser	
Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kang Car Repairers Pte Ltd (HQ)		Thumbnail	Print
1	11/10/19 14:34	Accident Statement		Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kang Car Repairers Pte Ltd (HQ)		Thumbnail	Print
1	11/10/19 14:29	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
2	11/10/19 14:29	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
3	11/10/19 14:29	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
4	11/10/19 14:29	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
5	11/10/19 14:29	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
6	11/10/19 14:29	Accident Photo		Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kang Car Repairers Pte Ltd (HQ)	Thumbnail	Print
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kang Car Repairers Pte Ltd (HQ)	Thumbnail	Print
1	11/10/19 14:29	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

^v

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19018014/AQF3E2

Date: 19/12/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMTPSN16139419033

Claimant
Vehicle No : SJZ4512HInsured
Vehicle No : SKJ7800D

Date of Loss: 10/10/2019

Nature of Claim: TP

Claim
No: SNM19D204787C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJZ4512H

Make & Model: TOYOTA VIOS, 1.5 E (A)

Engine No: 1NZY126269

Reg. Date: 25/11/2010 (Man. Year: 2010)

Chassis No: MR053HY9305175790

Colour: Silver

Odometer: 213810 km

Engine Capacity: 1497 cc

Market Value/New Car

N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15

Rear Tyre Size: 185/60 R15

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,092.60	968.25	124.35	11.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,330.00	680.00	650.00	48.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,422.60	1,648.25	774.35	31.96
Approved Total (Overridden) (S\$)		1,300.00		
(S\$)	2,422.60	1,300.00	1,122.60	46.34
+ GST 7.00/7.00% (S\$)	169.58	91.00	78.58	46.34
Nett Amount (S\$)	2,592.18	1,391.00	1,201.18	46.34

INSPECTION

Date of Assignment: 11/10/2019

Date Inspected: 14/10/2019 Inspected At:

Kang Car Repairers Pte Ltd (HQ)
No 1 Kaki Bukit Ave 6, #02-06
AutoBay@Kaki Bukit
Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Dec 2019)
Parts:	143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJZ4512H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Deformed	487.30 FL	*487.30 FL
2	1		*FRT BUMPER SIDE RETAINER RH	Necessary	54.80 FL	*54.80 FL
3	1		*FRT FOG LAMP COVER RH	Not Necessary	85.80 FL	*- FL
4	1		*HEADLAMP RH	Cracked	585.30 FL	*585.30 FL
5	1		*FRT FENDER VVTI EMBLEM	Necessary	43.60 FL	*43.60 FL
6	1		*SET FRT BUMPER CLIPS	Necessary	40.00 FS	*40.00 FS
7	2		*L PLATE BRACKET	Necessary	70.00 FS	*50.00 FS
8	1		*SET FRT FENDER COWLING CLIPS RH	Not Necessary	40.00 FS	*- FS
					Sub Total (\$\$)	1,406.80 1,261.00
					- List Item Discount on L Items 25.00/25.00% (\$\$)	314.20 292.75
					Total Parts (\$\$)	1,092.60 968.25

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	50.00	30.00
2	TO SPRAY UNDERSEAL	New	80.00	0.00
3	(FRONT) TO SPRAY PAINTING	New	600.00	350.00
4	TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING / WELDING WORKS	New	600.00	300.00
Gross Labour Cost (\$\$)			1,330.00	680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >