

22/03/2002

CS3/MSG19013095/RTB302-1

ASS. REC. BY:

REF: CS3/MSG19013095/RTB302-1 Special Instruction:

Surveyor: Rasu ASSIGNMENT (Office) 15.10.2019

Merum

From (Person): Pauline Tham of MSI9 Date/Time: 24.7.19 16:23/24

Estimated Cost: _____ Bill to: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJB 4940H Insured: SGH 3266E

at Workshop m/s Gek Song Paint Tel: 96605755

of 10 Buroh Street #08-22

Policy No: 27413149 Claim No: 600489

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 18.7.19

(Client's Record)

CA / REV / REP. / REV 24 HRS mp' 30.7.2019 H.O.D. Endorsement: _____

Date/Time: 25.7.19 9:07 a.m Person Contacted: Gek Song Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SJB 4940H - X
	SGH 3266E - X
	After repair: 2/8/2019.
	Part by part \$1520, 3 days
	CRed: 2270; (60%)

[Signature]
16/10/2019

16/10 - File pass to typist

RECEIVED 17 OCT 2019

Surveyor *Rasul*

REF: MS19

ASSIGNMENT

From: _____ Date: 30.7.2019

Veh No: SLB 4940H Yr Regn: Jun / 11

Estimated Cost: _____

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or _____

To Inspect Vehicle No: SLB 4940H

Make: MERCEDES BENZ c.c 1796

at Workshop n/s Ghee Sing Paint
of 10 Buroh street #08-22

Colour: GRAY A/C: Insured / Std / NI / NA

Sp. Reading: 74047 T/Radio: Insured / Std / NI / NA

Insured: _____

Eng/No: _____

Policy No: _____

C/No: W002120482A 318 580

Claims No: _____

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured: _____ Excess: _____

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh: After 10.30 a.m

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Tyre Size: F: 245 / 45 ZR17

R: 7

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Bal. or Market Value: 61K

Front Rear

IDAC Accident Rpt: _____ Consistent?: Yes or No

R/Bal. 6 mm R/Bal. 6 mm

GIA / PR Seen: _____ Consistent?: Yes or No

L/Bal. 6 mm L/Bal. 6 mm

Est. Repairs: _____ days Res.: Yes or No

D.O.A. 18/07/19 D.O.I. 30/07/19

Lum Sum: _____ % 3 Val.: Yes or No

Survey held at GHEE SING PAINT

CA / REV / REP. / 24 HRS *mp'*

Des. of Damages: Frt / Rear / O/S / NIS / U/C / Rooftop or
O/S REAR

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	NO GIA
	Range only
	Range - 4,000 - 5,000
	Repair Day - 5 days. <i>[Signature]</i>
	10/9/2019

Date/Time, File Pass to? : Preli. Report
 : Final Report

Days Of Repair: 5
Resurvey No. of Trip: 1

Survey Fee:	120
Transportation:	
S + RS, St	
Photos	
Others	11
TOTAL	131

Date/Time, File Return to?
1)
2)

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

Report Format: PRS
Lump Sum / I.B.I.: (\$)

Celine Fong (LKKAuto)

From: Pauline Tham <pauline_tham@sg.msig-asia.com>
Sent: Tuesday, 15 October 2019 10:33 AM
To: SUR
Cc: Denise Tay (LKKAuto); Veron Chen (LKKAuto); Bryan Ang (LKKAuto)
Subject: Urgent paper survey for SLB4940H - DOA 18/7/2019, Oref : 600489

Dear Sir

Please assist on urgent paper survey as we have received WOS.

Thanks for help.

Pauline Tham
Senior Executive, Claims Services, Motor
D: +65 6594 2545 | F: +65 6225 7402 | pauline_tham@sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	908F
Vehicle Details	
Vehicle No.:	SLB4940H
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Aug 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E 200CGI
Primary Colour:	Silver
Manufacturing Year:	2011
Engine No.:	27186030200056
Chassis No.:	WDD2120482A398580
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$51,151.00
Original Registration Date:	30 Jun 2011
First Registration Date:	30 Jun 2011
Transfer Count:	2
Actual ARF Paid:	\$51,151.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Jun 2021
PARF Rebate Amount:	\$28,133.00
Intended COE Rebate Details	
COE Expiry Date:	29 Jun 2021
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$67,700.00
COE Rebate Amount:	\$12,919.00
Total Rebate Amount:	\$41,052.00

The information contained herein is correct as at 02 Aug 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/07/2019 11:21
Date Of Accident	18/07/2019 18:10
Exact Location Of Accident	ALOG JALAN BUKIT HO SWEE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLB4940H
Insured/Policyholder	
Name Of Registered Owner	NG BEE LIAN
NRIC No	S1503908F
Email Address	BEEBUZZZZ@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-97481068
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	E200-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2019-00009955
Cover Note Number	

Driver

Name of Driver	KONG WEI REN
NRIC No	S9026979H
Date Of Birth	29/07/1990
Occupation	INDOOR
Date Of Driving Pass	27/03/2009
Driving Experience	10 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96681509
Fax Number	
Contact Number	OFFICE-NOPHONE
EEmail Address	BEEBUZZZZ@HOTMAIL.COM

Address	BLK 30 TANGLIN HALT ROAD #08-154
Postcode	140030
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	SUBMIT TO FWD DIRECTLY
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGH3266E
Vehicle Make/Model/Colour	NISSAN
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	YU YO JEN
NRIC/Passport Number	
Contact Number	9762 7247 / 9368 1065
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN

VEHICLE NO: SLB4940H
ACCIDENT DATE: 18/07/2019 @ 18:10

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
(d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
(e) the information so collected under (d) above may be shared / disclosed:
(i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
(ii) for complying with requirements under any regulations, laws or court orders.

NOTE: DO NOTE THAT YOU MAY HAVE A 14-DAYS TIMEFRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE REFER TO YOUR POLICY FOR MORE INFORMATION.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

19 July 2019, 9am



Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I (~~was~~ ^{KONG WEI REN}) was driving vehicle (SLB4940H) in my lane when ~~the~~ ~~oncoming~~ vehicle SGH 3266E was driving towards my lane and hit the right side of my vehicle.

~~From~~ just before the moment of impact, I saw the driver in ~~SGH~~ SGH 3266E was looking down and not straight at the road (see frame of video provided).

Also, in the video, it is very obvious the vehicle SGH3266E was not driving straight (he had ample space on the left) but at an angle towards my vehicle.

The accident happened along Jalan Bukit Ho Swee, in front of block 34

OWN DAMAGE () 3RD PARTY CLAIM () REPORTING ONLY () OWN WORKSHOP ()

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

[Handwritten Signature] 19 July 2019, 9am
CHARN' CUSTOMERS CRAFT

PRECISION APPRAISAL SERVICES

Insurance Loss Assessors/ Adjusters Cargo Surveyors & Licensed Appraisers

227 Simei St 4 #06-42 Singapore 520227 Fax: 64444886 Company Registration No. 53139926E



AUTOMOBILE INSPECTION REPORT

To:
NG BEE LIAN
C/O 10 BUROH STREET #08-22 West
Connect Building Singapore 627564

INSURANCE DETAILS

Insured : -
Policy No. / Claim No. : -
Sum Insured : -
Excess Clause : -
Windscreen Coverage : -
Type of Claims : Third Party Claims
Third Party Insurer : -
Third Party Policy No. : -

REFERENCE

Assigned By : As above
Accident Date : 18 July 2019
Assignment Date : 30 July 2019
Inspection Date : 30 July 2019
Our Reference No. : PAS/GS/190803/TP

Inspection Report Date : 05 August 2019

GHEE SENG PAINT SPRAYING WORKS

Inspection Address :

10 BUROH STREET #08-22 West Connect
Building Singapore 627564

PARTICULARS OF VEHICLE

Registration No. : SLB 4940 H
Make/Model : MERCEDES BENZ E 200CGI
Yr of Manuf/Regn : 2011
Carrying Capacity : 4 Seater
Chassis No. : WDD2120482A398580
Engine No. : 27186030200056
Colour : Metallic Silver
Class : Passenger (Private)

Mileage : 74047 Km/h
Radio/Cassette : Fitted
CD Disc Player : Fitted
Air Conditioner : Fitted
Clock : Fitted
Seat Belt : Fitted
Wing Mirror : Fitted
Other Accessories : Fitted

PRE-ACCIDENT CONDITION (Static Check Only)

Body Work : Good
Paint Work : Good
Handbrake : Serviceable
Footbrake : Serviceable
Steering : Serviceable
Any Apparent : None
Eng Modifications

VEHICLE VALUE

Market Value : -
Wreck Value (Part) : -

TYRE SIZE & CONDITION

Front N/s Size : 245/45ZR17 80 %
Make : MICHELIN
Rear N/s Size : 245/45ZR17 80 %
Make : MICHELIN
Spare Size : 245/45ZR17 80 %
Make : MICHELIN

Front O/s Size : 245/45ZR17 80 %
Make : MICHELIN
Rear O/s Size : 245/45ZR17 80 %
Make : MICHELIN
Spare Size :
Make :
Jack & Tools : Intact/Missing

Type of Wheel Rims: ALLOY

Note: The above percentage % represent the estimated remaining tyre threads.

PRECISION APPRAISAL SERVICES

Insurance Loss Assessors/Adjusters Cargo Surveyors & Licensed Appraisers




VEHICLE REGISTRATION NO. : SLB 4940 H

APPENDIX A

POINT OF IMPACT

Direction of impact/damage marked (→) (X)

The vehicle sustained impact along its Rear O/s Portion. (see Diagram D)



GENERAL DESCRIPTION OF DAMAGES

Parts damaged were :

The rear o/s door and wheel rim, rear o/s fender and wheel arch, rear bumper were dented.

ADJUSTMENTS & RECOMMENDATIONS

A static inspection was carried out on 30/07/2019 & our report is here with enclosed for your perusal. The Repairs Estimate submitted by M/s GHEE SENG PAINT SPRAYING WORKS as per attached Appraisal Schedule have been revised and scrutinised thoroughly by us & in our opinion, we consider it to be fair and reasonable. The repairer has agreed to effect repairs to the owners satisfaction & to roadworthy condition on an agreed Lump Sum Repair Basis of \$ 3,800.00 after deducting the Policy Excess Clause of \$ NA. As instructed, we have not authorised any of the repairs on your behalf.

	Repairer's		Our	
	Estimate	Amount	Revised	Amount
Spares Parts	7621	78	2931	38
Towing Charges	-		-	
PB Labour Charges	980	00	800	00
Others Misc	480	00	360	00
Charges Paintwork	800	00	680	00
Total	\$ 9881	78	\$ 4771	38

Under normal circumstances, the duration of repairs should not exceed Two (02) days excluding Pre -Repair Inspection (PRI) / Pre - Repair Survey (PRS) waiting time frame & Public Holidays

Attached photographs taken during inspection Twenty - Three (23) Photographs.

SPECIAL REMARKS

1. The inspection was conducted on a 'without prejudice' basis
2. On 01/08/2019, we examined the repaired vehicle.

Yours Faithfully,

T F N G PHILIP FOO
A C I I C A E, A M I M I
A I A M E, A M S A E - A
Licensed Appraiser/Adjuster

Inspection Report Date: 05 August 2019

VEHICLE REGN NO : SLB 4940 H
 OUR REFERENCE : PAS/GS/190803/TP
 INSPECTION REPORT DATE : 5-Aug-19

APPRAISEMENT SCHEDULE

CONTINUATION SHEET NO : 1

S/No	Qty	Parts / Labour Descriptions	Remarks / Condition	Repairer's Estimate Amount \$ cts	Recommendation / Revised Amount \$ cts
		<u>PARTS SUPPLY - NETT ITEMS</u>			
1	1pc	Rear o/s door	Badly dented	2279.00	2279.00 R
2	1pc	Rear o/s fender	Badly dented	2297.70	Repair
3	1pc	Rear o/s wheel rim (Original)	Dented/Warped	978.08	978.08 500 500
4	1pc	Rear bumper	Badly dented	2067.00	Repair
				<u>7621.78</u>	<u>3257.08</u>
		Less:10% discount	500	-	<u>325.70</u>
				7621.78	2931.38
		<u>LABOUR & MISC. CHARGES</u>			
1		Remove the necessary affected parts, straighten rear o/s fender and wheel arch, repair rear bumper and replace parts		980.00	800.00 300
2		Putty and spraypaint on all affected parts		800.00	600 680.00
3		Check electrical		100.00	X 80.00
4		Remove and refit rear o/s door parts	500 1020	150.00	X 120.00
5		Reset wheel alignment	1520	100.00	60 80.00
6		Tuff Kote		100.00	40 60.00
7		Remove and refit rear o/s wheel rim and balancing	3 days P/P	30.00	20.00
		Note: Recommended lump sum repair at \$3,800.00nett.			<u>1020</u>
SUB / GRAND TOTAL				9881.78	4771.38

PRECISION APPRAISAL SERVICES



LIST OF DISBURSEMENTS*MC/MC 15311/2019**As at 15.10.2019***I. Disbursements not subject to GST**Stamp fees:-

1) Writ of Summons	\$	106.60	
2) Statement of Claim	\$	11.80	
3) Notice of Discontinuance (anticipated)	\$	16.60	
			Sub-total \$ 135.00

Other fees:-

4) Survey fees	\$	443.00	
5) GIA search and document fees	\$	29.00	
6) GIA insurer enquiry	\$	2.00	
7) LTA search fee	\$	10.00	
8) ACRA search fee	\$	10.00	
			Sub-total \$ 494.00

II. Disbursements subject to GST

9) Postage, Xerox and other incidentals	\$	150.00	
10) 7% GST on Item 9	\$	10.50	
			Sub-total \$ 160.50
			GRAND TOTAL \$ 789.50

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Jul 2019		24 Jul 2019 16:23 Edit Adj Rpt	S\$1,520.00 Edit Estimates	S\$1,520.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	Dainan Tech (S) Pte Ltd , Co. Reg. No.: 198102767H								
Main Claimant:	NG BEE LIAN , ID: S1503908F								
Vehicle Reg. No.:	SLB4940H	Date of Loss:	18/07/2019 18:00 - :59 [96 Months and 18 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 600489	Policy/Cover Note No.:	27413149 (Comprehensive) Coverage: 07/12/2018 - 06/12/2019						
Vehicle Reg. No. (Insured):	SGH3266E	Policy No. (Claimant):							
Repairer:	Ghee Seng Paint Spraying Works - Buroh (HQ) 10 BUROH STREET, #08-22 WEST CONNECT BUILDING, 627564 Pioneer - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 17/10/2019]								
Driver/Customer (Insured):	YU YO-JEN (54 / Male) , NRIC: S2191852J Email:								
Adj Asg. Remarks:	on WP Liab: Dispute. Lawyer disagree on SJE - assign LKK. Contact: Mr. Gan Gek Song (h/p: 9660 5755 tel: 6268 9640)								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> MSIG_SG (15/10/2019): Report Send Back Alerts - SLB4940H (TP) 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLB4940H (600489)
[SGH3266E]
TP
NG BEE LIAN
Jul 18 2019 6:00PM
[Dainan Tech (S) Pte Ltd]
Ghee Seng Paint Spraying Works - Buroh

Upload Documents		Upload Photos	Compose New Letter	View View in Browser
Video				1 per page <input type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	15/10/19 10:29	Video - Accident	Load MP4	<input type="checkbox"/>
Photos/Images				3 per page <input type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/08/19 17:01	General View	Load JPG	<input checked="" type="checkbox"/>
2	02/08/19 17:01	General View	Load JPG	<input checked="" type="checkbox"/>
3	02/08/19 17:01	General View	Load JPG	<input checked="" type="checkbox"/>
4	02/08/19 17:01	General View	Load JPG	<input checked="" type="checkbox"/>
5	02/08/19 17:01	General View	Load JPG	<input checked="" type="checkbox"/>
6	02/08/19 17:01	General View	Load JPG	<input checked="" type="checkbox"/>
7	02/08/19 17:01	General View	Load JPG	<input checked="" type="checkbox"/>
8	02/08/19 17:01	General View	Load JPG	<input checked="" type="checkbox"/>
9	02/08/19 17:01	General View	Load JPG	<input checked="" type="checkbox"/>
10	02/08/19 17:01	General View	Load JPG	<input checked="" type="checkbox"/>
11	02/08/19 17:01	General View	Load JPG	<input checked="" type="checkbox"/>
12	02/08/19 17:01	General View	Load JPG	<input checked="" type="checkbox"/>
13	02/08/19 17:01	General View	Load JPG	<input checked="" type="checkbox"/>
14	02/08/19 17:01	General View	Load JPG	<input checked="" type="checkbox"/>
15	02/08/19 17:01	General View	Load JPG	<input checked="" type="checkbox"/>
16	02/08/19 17:01	General View	Load JPG	<input checked="" type="checkbox"/>
17	02/08/19 17:01	General View	Load JPG	<input checked="" type="checkbox"/>
18	02/08/19 17:01	General View	Load JPG	<input checked="" type="checkbox"/>
19	02/08/19 17:01	General View	Load JPG	<input checked="" type="checkbox"/>
20	02/08/19 17:01	General View	Load JPG	<input checked="" type="checkbox"/>
21	02/08/19 17:01	General View	Load JPG	<input checked="" type="checkbox"/>
22	02/08/19 17:01	General View	Load JPG	<input checked="" type="checkbox"/>
23	02/08/19 17:13	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
24	02/08/19 17:13	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
25	02/08/19 17:13	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
26	02/08/19 17:13	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
27	02/08/19 17:13	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
28	02/08/19 17:13	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
29	02/08/19 17:13	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
30	02/08/19 17:13	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
31	02/08/19 17:13	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
32	02/08/19 17:13	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
33	02/08/19 17:13	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
34	02/08/19 17:13	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
35	02/08/19 17:13	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
36	02/08/19 17:13	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page <input type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	22/07/19 09:53	OI Accident Report	Load PDF	<input type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail Print
2	22/07/19 09:53	TP SLB4940H E-REPORT		Load PDF
3	24/07/19 14:02	Disagree on SJE		Load PDF
4	24/07/19 14:02	Workshop details		Load PDF
5	14/08/19 18:08	Survey Report		Load PDF
6	14/08/19 18:08	Survey Photos		Load PDF
7	15/10/19 10:15	lists of disbursement		Load PDF
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	17/10/19 09:58	PRS Invoice		Load PDF
2	17/10/19 09:58	Colour Photo		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/MSG19013095/R1TF3E2-1**Date:** 17/10/2019REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	27413149
Claimant	Insured Vehicle No :	SGH3266E
Vehicle No : SLB4940H	Nature of Claim:	TP
Date of Loss: 18/07/2019	Claim No:	600489

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLB4940H	Engine No:	27186030200056
Make & Model:	MERCEDES-BENZ E200, 2.0 (A)	Chassis No:	WDD2120482A398580
Reg. Date:	30/06/2011 (Man. Year: 2011)	Odometer:	74047 km
Colour:	Grey	Engine Capacity:	1796 cc
Market Value/New Car Price:	N/A	Sum Insured (S\$):	Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45Z R17	Rear Tyre Size:	245/45Z R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,621.78	500.00	7,121.78	93.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,260.00	1,020.00	1,240.00	54.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	9,881.78	1,520.00	8,361.78	84.62

INSPECTION

Date of Assignment:	24/07/2019
Date Inspected:	30/07/2019 Inspected At:
	Ghee Seng Paint Spraying Works - Buroh (HQ) 10 BUROH STREET, #08-22 WEST CONNECT BUILDING Singapore 627564

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 17 Oct 2019)
Parts: 143	MERCEDES-BENZ E200 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLB4940H)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR O/S DOOR	Repair	2,279.00 F	*- FN
2	1		*REAR O/S FENDER	Repair	2,297.70 F	*- FN
3	1		*REAR BUMPER	Repair	2,067.00 F	*- FN
4	1		*REAR O/S WHEEL RIM (ORIGINAL)	Dented/Warped	978.08 FS	*500.00 FS
Sub Total (S\$)					7,621.78	500.00
- Nett Item Discount on N Items 0.00/10.00% (S\$)					0.00	0.00
Total Parts (S\$)					7,621.78	500.00

F=Franchise part. S=SpcNett. N=NettItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE THE NECESSARY AFFECTED PARTS,STRAIGHTEN REAR O/S FENDER AND WHEEL ARCH,REPAIR REAR BUMPER AND REPLACE PARTS	New	980.00	300.00
2	PUTTY AND SPRAYPAINT ON ALL AFFECTED PARTS	New	800.00	600.00
3	CHECK ELECTRICAL	New	100.00	0.00
4	REMOVE AND REFIT REAR O/S DOOR PARTS	New	150.00	0.00
5	RESET WHEEL ALIGNMENT	New	100.00	60.00
6	TUFF KOTE	New	100.00	40.00
7	REMOVE AND REFIT REAR O/S WHEEL RIM	New	30.00	20.00
Gross Labour Cost (\$\$)			2,260.00	1,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >