

ASS. REC. BY:

REF: CS/CT1 19018140 / Uqf302

Special Instruction:

Surveior: Marcus

## ASSIGNMENT (Office)

From (Person): Tan Kah Leong

of

CT1

Date/Time: 15.10.19 8.46 a.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FY 81922

Insured:

GBJ 8038M

at Workshop m/a

Gofia Motor

Tel:

67527740

of 1 Kaki Bukit Ave 6 #02-62 Autobay

Policy No:

DMCVSN30640519000

Claim No:

SYM19D204836C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 11.10.2019

CA / REV / REP. / REV 24 HRS

Date/Time:

15/10/19 9.15 a.m

Person Contacted:

Lee Lee

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

GBJ 8038M X

FY 81922 X

17/10/19

Submit Unconformal Total Loss report.

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

days

Res: Yes or No

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

2019/10/19 Bal 3m/s

100 uncl / 12-1-2020

15/10/19

400

197

203

inform

Submit TOTAL 1055

MR 700 MVB 400 TOTAL 1055

RECEIVED 1 OCT 2019

Date/Time, File Pass to?

1) 12/10/19

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

3 + RS \$

Photo:

Others:

TOTAL

Add Fee:

Site Insp (\$

Interview (\$

Tech. Invs (\$

Weekend (\$

770

770

MR 700 / TL 400

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Oct 2019		15 Oct 2019 10:45 Assign				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:									
Main Claimant: <b>M2M TECHNOLOGIES PTE LTD</b> , Co. Reg. No.: 200309950K									
Vehicle Reg. No.: <b>FY8192Z</b> Date of Loss: 11/10/2019 07:00 - :59									
Claim Type: <b>TP / SNM19D204836C02</b> Policy/Cover Note No.: DMCVSN30640519000									
Vehicle Reg. No. (Insured): <b>GBJ8038M</b> Policy No. (Claimant): 5090866144-02									
Excess: S\$500.00									
Repairer: <b>Erofia Motor Trading Pte Ltd (KAKI BUKIT)</b> 1 KAKI BUKIT AVE 6 #02-62, 417883 Kaki Bukit - Tel:									
Handling Insurer: <b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Tan Kah Leong</b> - 63896193]									
Claimant's Insurer: <b>NTUC Income Insurance Co-operative Ltd (HQ)</b> - Tel:									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... <b>[Final Rpt due 24/10/2019]</b>									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;">View All Compose Case Mail</span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;">View All Search Tasks Create New Task Complete</span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Summer Lee (LKK Auto)

---

**From:** Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>  
**Sent:** Tuesday, 15 October, 2019 8:46 AM  
**To:** erofia@singnet.com.sg; assignments  
**Subject:** RE: OUR REF: SNM19D204836-GBJ8038M-TKL-request pre-repair inspection for accident involving GBJ8038M and FY8192Z on 11 October 2019

WITHOUT PREJUDICE

Dear LeeLee,

We refer to your email dated 14.10.2019.

We will be assigning M/s LKK Auto Consultants to survey your client's vehicle on a without prejudice basis.

Aside to LKK,

Please refer to the email below & proceed to survey the third party vehicle.

Thank you.

Regards

**Tan Kah Leong**  
Assistant Executive  
Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**  
3 Anson Road #15-00 Springleaf Tower Singapore 079909  
DID: (65) 6389 6193 | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/)

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

---

**From:** Erofia Motor - LeeLee Tan [mailto:erofia@singnet.com.sg]  
**Sent:** Monday, October 14, 2019 7:04 PM  
**To:** Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>  
**Subject:** RE: OUR REF: SNM19D204836-GBJ8038M-TKL-request pre-repair inspection for accident involving GBJ8038M and FY8192Z on 11 October 2019

Without Prejudice

Dear Mr Tan

Could you kindly arrange Marcus Chua

Thank you

Regards  
LeeLee Tan  
Erofia Motor Trading Pte Ltd

Tel: 67527740  
Fax: 67528669

**From:** Tan Kah Leong [<mailto:KahLeong.Tan@sg.cntaiping.com>]  
**Sent:** 14 October, 2019 5:48 PM  
**To:** [erofia@singnet.com.sg](mailto:erofia@singnet.com.sg)  
**Subject:** RE: OUR REF: SNM19D204836-GBJ8038M-TKL-request pre-repair inspection for accident involving GBJ8038M and FY8192Z on 11 October 2019

Without Prejudice

Dear LeeLee,

Please see attached and let us know if you agree with SJE.

Thank you.

Regards

**Tan Kah Leong**  
Assistant Executive  
Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**  
3 Anson Road #15-00 Springleaf Tower Singapore 079909  
DID: (65) 6389 6193 | F: (65) 6222 1033

W: [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | FB: [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/)

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

**From:** Claims Dept of CTI  
**Sent:** Monday, October 14, 2019 5:43 PM  
**To:** Tan Kah Leong <[KahLeong.Tan@sg.cntaiping.com](mailto:KahLeong.Tan@sg.cntaiping.com)>; Alfred Toh <[alfred.toh@sg.cntaiping.com](mailto:alfred.toh@sg.cntaiping.com)>; Chee So Chow <[sochow.chee@sg.cntaiping.com](mailto:sochow.chee@sg.cntaiping.com)>; [erofia@singnet.com.sg](mailto:erofia@singnet.com.sg)  
**Subject:** OUR REF: SNM19D204836-GBJ8038M-TKL-request pre-repair inspection for accident involving GBJ8038M and FY8192Z on 11 October 2019

Dear Kah Leong,

Please conduct PRS for FY8192Z.

Note: officer in charge – Kah Leong 63896193.

Thank you

Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**  
3 Anson Road #15-00 Springleaf Tower Singapore 079909  
DID: (65) 63896116 | F: (65) 62247175

W: [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | FB: [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | WeChat: 太平獅城 Taiping SG

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

**From:** Erofia Motor - LeeLee Tan [mailto:erofia@singnet.com.sg]

**Sent:** Monday, October 14, 2019 2:22 PM

**To:** Claims Dept of CTI

**Subject:** request pre-repair inspection for accident involving GBJ8038M and FY8192Z on 11 October 2019

Dear Sir

Attached necessary documents for your arrangement of pre-repair inspection for our client's

Motorcycle No: FY8192Z

Workshop:

Erofia Motor Trading Pte Ltd

1 Kaki Bukit Avenue 6 #02-62

AutoBay @ Kaki Bukit

Singapore 417883

Tel: 67527740

Thank You

Regards

LeeLee Tan

Erofia Motor Trading Pte Ltd

Tel: 67527740

Fax: 67528669



Virus-free. [www.avg.com](http://www.avg.com)

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

# EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

[erofia@singnet.com.sg](mailto:erofia@singnet.com.sg)

Co. Reg No. 201202259N

Name : M2M Technologies Pte Ltd

Accident Date : 11-Oct-19

Vehicle No : FY8192Z

Vehicle Model : Yamaha YBR125

## Estimate Repair Cost

Qty	Description List Items	Amount S(\$)
-----	---------------------------	--------------

Total loss  
Beyond repair of S\$2,500.00

\$ 900.00

\$ 900.00

Dollars: Nine Hundred only

EROFIA MOTOR TRADING PTE LTD

Not Approved  
Total 1085  
15/10/19  
Tel. 62553581

LKK Auto Consultants hence notify  
the Receiver of the following:

- 1. Damages incurred after spray painting
- 2. Damages incurred parts during delivery
- 3. Damages incurred to confirmation
- 4. Damages incurred to a "General Purpose" work
- 5. Damages incurred to a "General Purpose" work
- 6. Damages incurred to a "General Purpose" work
- 7. Damages incurred to a "General Purpose" work
- 8. Damages incurred to a "General Purpose" work
- 9. Damages incurred to a "General Purpose" work
- 10. Damages incurred to a "General Purpose" work

Approved by Receiver

Signature

Date

**Enquire Vehicle & Owner Information ( Vehicle No. GBJ8038M As At 11 Oct 2019 / 07:35:00 )****Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: EROFIA

Current Owner Details

FY 8192 E

Owner ID Type: Company

Owner ID: 200313006C

Owner Name: DIGO CORPORATION PTE. LTD.

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 54

Registered Street Name: SENOKO ROAD

Registered Unit No.: -

Registered Building Name: WOODLANDS EAST INDUSTRIAL ESTA

Registered Postal Code: 758118

**Current Vehicle Details**

Vehicle No.: GBJ8038M

Make Description/Model: MITSUBISHI / CANTER FEA01BR2SDEK (CBU)

Insurance Company Name: CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD





**SINGAPORE  
POLICE FORCE**



T/20191011/2031

Police Station Of Origin:  
Bukit Batok N.P.C  
21 Bukit Batok East Avenue 4 SINGAPORE  
659840  
Tel No: 1800-6659999

1 of 3

Report No. T/20191011/2031

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 11/10/2019 11:38	Vide Report No.:	Station Diary No.: 48
--	------------------	--------------------------

**Informant's Particulars**

Name of Informant: RAMACHANDRAN RAJKUMAR			Address:	
ID Type / ID No.: FIN NO / G2970890N			Contact No.: Home/Office:	Mobile: 83141850
Nationality: INDIAN			Email:	97591965
Sex: Male	Age: 24	Date of Birth: 10/05/1995	Type of Informant: Driver	
Race: Others			Language: English	Institution / School Name:
Occupation: CONSTRUCTION WORKER			Driving Licence Information: Class:	Date of Expiry:

**General Information of the Accident**

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 11/10/2019 07:35	Type of Location: X-Junction
Location:  BRICKLAND ROAD  Along Brickland Rd towards Bukit Batok				
Weather: Clear	Road Surface: Dry	Road Speed Limit:		
Traffic Flow: Dual Carriage Way	Traffic Control: Traffic Light - Working	Traffic Volume: Light		
Type of Collision: Between Moving Vehicles - Head To Rear	Anyone conveyed by ambulance: No			

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FY8192Z	Motorcycle				Slightly Damaged	1
GBJ8038M	Lorry				Slightly Damaged	5

**Details of Person Involved**

Any Pedestrian Involved: No		
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA	



**SINGAPORE  
POLICE FORCE**



T/20191011/2031

2 of 3

Report No. T/20191011/2031

Police Station Of Origin:  
Bukit Batok N.P.C  
21 Bukit Batok East Avenue 4 SINGAPORE  
659840  
Tel No: 1800-6659999

**CONTINUATION OF REPORT**

<b>Passenger</b>			
Name	PALANIVEL VELMURUGAN	ID No.	G2999940L
Related Vehicle	FY8192Z (Motorcycle)	Contact No.	82891483
Hospital/Clinic	ONECARE CLINIC BUKIT GOMBAK	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	11/10/2019	Date Discharge	NIL
No. of Days granted Medical Leave	03	Degree of Injury	Slight
<b>Driver</b>			
Name	RAMACHANDRAN RAJKUMAR	ID No.	G2970890N
Related Vehicle	FY8192Z (Motorcycle)	Contact No.	83141850
Hospital/Clinic	ONECARE CLINIC BUKIT GOMBAK	Class of Driving Licence & Expiry Date	Class: 2B,3C Date of Expiry: NIL
Date Treatment	11/10/2019	Date Discharge	NIL
No. of Days granted Medical Leave	03	Degree of Injury	Slight
<b>Witness</b>			
Name	Irisappan Thileepkumar	ID No.	G7370459L
Related Vehicle	GBJ8038M (Lorry)	Contact No.	96114415
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On the 11/10/2019, at around 0735hrs, I was riding my vehicle V1) FY8192Z along Brickland Rd towards Bukit Batok. At the cross junction, I braked as the traffic light was amber and turning red. However, a lorry namely V2) GBJ8038M with driver A1) Irisappan Thileepkumar, FIN G7370459L did not manage to stop in time and collided with the rear of my bike. As a result, I lost my balance and skidded off towards the left and landed on my left elbow. My passenger namely A2) Palanivel Velmurugan, FIN G2999940L also lost his balance and landed on his left hand which suffered some scratches.



**SINGAPORE  
POLICE FORCE**



T/20191011/2031

Police Station Of Origin:  
Bukit Batok N.P.C  
21 Bukit Batok East Avenue 4 SINGAPORE  
659840  
Tel No: 1800-6659999

3 of 3

Report No. T/20191011/2031

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J /

YAP WEI XUAN

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / AEIT /

SI ANG YI TING, STEPHANIE

Contact No.: 65476414

Signature Of Informant:

Date/Time:

11/10/2019 11:38

Classification Of Case:

Authentication Stamp  
NP168



Signature :

SN 114

**Singapore Police Force**

## Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)  
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960  
ROAD TRANSPORT ACT, 1987 (MALAYSIA)  
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

<b>Certificate Number</b> : 5090866144-02	<b>Cover</b> : Third Party, Fire & Theft
1. Index mark and Registration Number of Vehicle	: <b>FY8192Z</b>
Chassis Number	: LBPPCJLB040203991
2. Name of Policyholder	: M2M TECHNOLOGIES PTE LTD
3. Effective Date of Insurance	: 15 Dec 2018
4. Expiry Date of Insurance	: 14 Dec 2019
5. Persons or Classes of Persons entitled to drive#	
(a) The Policyholder.	
(b) Any other person who is driving on the Policyholder's order or with his/her permission.	
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.	
6. Limitations as to Use#	
(a) Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession.	
This Policy does not cover	
(a) Use for hire or reward.	
(b) Use for racing, pace-making, reliability trial or speed-testing.	
(c) Use for the carriage of goods (other than samples) in connection with any trade or business.	
(d) Use for any purpose in connection with the Motor Trade.	
# Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.	

EXCESS (SECTION 1)	: N/A
EXCESS (SECTION 2)	: N/A
EXCESS (THEFT OUTSIDE SINGAPORE)	: PLEASE REFER OVERLEAF
INSURE WITH COE	: YES
NAMED DRIVER (1)	: N/A
NAMED DRIVER (2)	: N/A
HIRE PURCHASE COMPANY	: N/A
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : ABWIN PTE LTD (00000614234)  
Date of Issue : 27 Nov 2018 06:56 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED



Countersigned By:

Authorised Officer



Chief Executive

[> Back to OneMotoring](#)

## Enquire Vehicle Transfer Fee

### Vehicle Details

Vehicle No.  
**FY8192Z**

Make / Model  
**YAMAHA / YBR125**

Vehicle Type :  
**P00 - Passenger Motorcycle/Autocycle/Moped**

Vehicle Attachment 1 :  
**No Attachment**

Vehicle Scheme :  
**Normal**

Chassis No. :  
**LBPPCJLB040203991**

Propellant :  
**Petrol**

Engine No. :  
**JYM154FMI04407199**

Motor No. :  
**-**

Engine Capacity :  
**124 cc**

Power Rating :  
**-**

Maximum Power Output :  
**-**

Maximum Laden Weight :

-

Unladen Weight :

**106 kg**

Year Of Manufacture :

**2004**

Original Registration Date :

**13 Jan 2005**

Lifespan Expiry Date :

-

COE Category :

**D - Motorcycle**

PQP Paid :

**\$2,185.00**

COE Expiry Date :

**12 Jan 2020**

Road Tax Expiry Date :

**08 Nov 2019**

PARF Eligibility Expiry Date :

-

Inspection Due Date :

**08 May 2020**

Intended Transfer Date :

**29 Oct 2019**

CO2 Emission :

-

CEV/VES Rebate Utilised Amount :

-

CO Emission :

-

HC Emission :

-

NOx Emission :

-

PM Emission :

## Fees To Be Paid For Transfer

Transfer Fees	\$25.00
Road Tax Renewal - 6 months (09 Nov 2019 to 12 Jan 2020)	\$18.00

## Message

The fees above do not include any late road tax fees, which apply if road tax or lay-up has expired. You can use the digital service Enquire Road Tax Payable to check if there are any late road tax fees.

Any road tax that has been paid for the vehicle will be transferred to the next owner.

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

Print

OK →

Save as PDF

Copy as Text

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	950K

Vehicle Details

Vehicle No.:	FY8192Z
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Oct 2019
Vehicle Make:	YAMAHA
Vehicle Model:	YBR125
Primary Colour:	Blue
Manufacturing Year:	2004
Engine No.:	JYM154FMI04407199
Chassis No.:	LBPPCJLB040203991
Maximum Power Output:	-
Open Market Value:	\$1,264.00
Original Registration Date:	13 Jan 2005
First Registration Date:	13 Jan 2005
Transfer Count:	3
Actual ARF Paid:	\$190.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	12 Jan 2020
COE Category:	D - Motorcycle
COE Period(Years):	5
PQP Paid:	\$2,185.00
COE Rebate Amount:	\$197.00
<b>Total Rebate Amount:</b>	<b>\$197.00</b>

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 15 Oct 2019



## ...CLAIM SUBFOLDER...(Pending for Survey Report)



































## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Oct 2019		15 Oct 2019 10:45 <a href="#">Edit Adj Rpt</a>	<b>\$50.00</b> <a href="#">Edit Estimates</a>	<b>\$50.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	*, Co. Reg. No.: 0								
Main Claimant:	<b>M2M TECHNOLOGIES PTE LTD</b> , Co. Reg. No.: 200309950K								
Vehicle Reg. No.:	<b>FY8192Z</b>	Date of Loss:	11/10/2019 07:00 - :59 [176 Months and 28 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / SNM19D204836C02</b>	Policy/Cover Note No.:	DMCVSN30640519000						
Vehicle Reg. No. (Insured):	<b>GBJ8038M</b>	Policy No. (Claimant):	5090866144-02						
		Excess:	\$500.00						
Repairer:	<b>Erofia Motor Trading Pte Ltd (KAKI BUKIT)</b> 1 KAKI BUKIT AVE 6 #02-62, 417883 Kaki Bukit - Tel:								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Tan Kah Leong</b> - 63896193]								
Claimant's Insurer:	<b>NTUC Income Insurance Co-operative Ltd (HQ)</b> - Tel:								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MARCUS CHUA</b> ] ... [Final Rpt due 24/10/2019]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*FY8192Z (SNM19D204836C02)  
[GBJ8038M]  
TP  
M2M TECHNOLOGIES PTE LTD  
Oct 11 2019 7:00AM  
[-]  
Erofia Motor Trading Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View		View in Browser	
Photos/Images										3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)									Thumbnail	Print
1	17/10/19 09:55	General View									Load JPG	<input checked="" type="checkbox"/>
2	17/10/19 09:55	Odometer Reading									Load JPG	<input checked="" type="checkbox"/>
3	17/10/19 09:55	General View									Load JPG	<input checked="" type="checkbox"/>
4	17/10/19 09:55	General View									Load JPG	<input checked="" type="checkbox"/>
5	17/10/19 09:55	General View									Load JPG	<input checked="" type="checkbox"/>
6	17/10/19 09:55	General View									Load JPG	<input checked="" type="checkbox"/>
7	17/10/19 09:55	General View									Load JPG	<input checked="" type="checkbox"/>
8	17/10/19 09:55	General View									Load JPG	<input checked="" type="checkbox"/>
9	17/10/19 09:55	General View									Load JPG	<input checked="" type="checkbox"/>
10	17/10/19 09:55	General View									Load JPG	<input checked="" type="checkbox"/>
11	17/10/19 09:55	General View									Load JPG	<input checked="" type="checkbox"/>
12	17/10/19 09:55	General View									Load JPG	<input checked="" type="checkbox"/>
13	17/10/19 09:55	General View									Load JPG	<input checked="" type="checkbox"/>
14	17/10/19 09:55	General View									Load JPG	<input checked="" type="checkbox"/>
15	17/10/19 09:55	General View									Load JPG	<input checked="" type="checkbox"/>
16	17/10/19 09:55	General View									Load JPG	<input checked="" type="checkbox"/>
17	17/10/19 09:55	General View									Load JPG	<input checked="" type="checkbox"/>
18	17/10/19 09:55	General View									Load JPG	<input checked="" type="checkbox"/>
19	17/10/19 09:55	General View									Load JPG	<input checked="" type="checkbox"/>
20	17/10/19 09:55	General View									Load JPG	<input checked="" type="checkbox"/>
21	17/10/19 09:55	General View									Load JPG	<input checked="" type="checkbox"/>
22	17/10/19 09:55	General View									Load JPG	<input checked="" type="checkbox"/>
23	17/10/19 09:55	General View									Load JPG	<input checked="" type="checkbox"/>
24	17/10/19 09:55	General View									Load JPG	<input checked="" type="checkbox"/>
25	17/10/19 09:55	General View									Load JPG	<input checked="" type="checkbox"/>
26	17/10/19 09:55	General View									Load JPG	<input checked="" type="checkbox"/>
27	17/10/19 09:55	General View									Load JPG	<input checked="" type="checkbox"/>
28	17/10/19 09:55	General View									Load JPG	<input checked="" type="checkbox"/>
29	17/10/19 09:55	General View									Load JPG	<input checked="" type="checkbox"/>
30	17/10/19 09:55	General View									Load JPG	<input checked="" type="checkbox"/>
31	17/10/19 09:55	General View									Load JPG	<input checked="" type="checkbox"/>
32	17/10/19 09:55	General View									Load JPG	<input checked="" type="checkbox"/>
33	17/10/19 09:55	General View									Load JPG	<input checked="" type="checkbox"/>
34	17/10/19 09:55	General View									Load JPG	<input checked="" type="checkbox"/>

## Linked Accident Report Documents

			View <span>View in Browser</span>		
Assessment Reports			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	VAC (Kaki Bukit)		Thumbnail	Print
1	15/10/19 10:24	Accident Statement		Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>	

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)		Thumbnail	Print
No	Finalized On	VAC (Kaki Bukit)		Thumbnail	Print
1	15/10/19 10:14	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
2	15/10/19 10:14	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
3	15/10/19 10:14	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
4	15/10/19 10:14	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
5	15/10/19 10:14	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
6	15/10/19 10:14	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
7	15/10/19 10:14	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)		Thumbnail	Print
1	15/10/19 10:24	Accident Sketch Plan		Load JPG	<input checked="" type="checkbox"/>
2	15/10/19 10:24	Accident Sketch Plan		Load JPG	<input checked="" type="checkbox"/>
3	15/10/19 10:24	Accident Sketch Plan		Load JPG	<input checked="" type="checkbox"/>
4	15/10/19 10:24	Accident Sketch Plan		Load JPG	<input checked="" type="checkbox"/>
5	15/10/19 10:24	Accident Sketch Plan		Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119018140/UQF3E2

Date: 17/10/2019

## REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN30640519000  
 Claimant Vehicle No: FY8192Z Insured Vehicle No: GBJ8038M  
 Date of Loss: 11/10/2019 Nature of Claim: TP Claim No: SNM19D204836C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: FY8192Z  
 Make & Model: YAMAHA YBR125, 124cc (M) Engine No: JYM154FMI04407199  
 Reg. Date: 13/01/2005 (Man. Year: 2004) Chassis No: LBPPCJLB040203991  
 Colour: Blue Odometer: 41821 km  
 Engine Capacity: 124 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 80/90-18 Rear Tyre Size: 3.60-18  
 Front Left Side: FKR 6 mm Rear Left Side: FKR 6 mm  
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 15/10/2019

Date Inspected: 15/10/2019 Inspected At:

Erofia Motor Trading Pte Ltd (KAKI BUKIT)  
 1 KAKI BUKIT AVE 6 #02-62  
 Singapore 417883

Estimated Period of Repair: 0.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$400.00(est)

LTA REBATE : \$197.00

NETT VALUE : \$203.00

## REPAIR DETAILS

### Reference

**Part Source:** (Last Synchronised: 17 Oct 2019)

**Parts:** N/A YAMAHA YBR125 124cc (M) (Model not available in database)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for FY8192Z)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >