

22/03/2002

ASS. REC. BY:

REF:

CS/INC19018161/EV312

Special Instruction:

SUNAJOR: Steve

**ASSIGNMENT (Office)**From (Person): Theresa Vimala of INC Date/Time: 15 October 2019

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

**OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS**To Inspect Vehicle No: SCG 6128D Insured: SKZ 7039Bat Workshop m/s Tan Chong Motor Sales Pte Ltd Tel: 6703 8916of 913 Bukit Timah RoadPolicy No: \_\_\_\_\_ Claim No: MT/1059149-002

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 22/08/2019  
(Client's Record)

"wp"

**CA / REV / REP. / REV 24 HRS**

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 15/10/2019 @ 02:45pm Person Contacted: Zuhri Vehicle IN/OUT

Date/Time	Action/Instruction ( ✓ ) Estimate
	SCG 6128D: NA/INC19014900/C24 DOA: 22/08/2019
	SKZ 7039B: NA/INC19014900/C24 DOA: 22/08/2019
20/11/19	@ 12:28pm Zuhri said vehicle has not send in for repair

Survivor

Steve

REF:

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: 5CG 61280

Yr Regn: 30/5/17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan Qashqai

Colour

Grey

A/C: Insured / Std / NI / NA

Sp. Reading

62672

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: SJNFBAJ1141945450

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

R/Bal.

5

mm

Rear

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

22/8/19

D.O.I.

15/10/19

12:20pm

Survey held at

Tan Chay, Bukit Timah

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MK-81K

RECEIVED 25 NOV 2019

Date/Time, File Pass to?



: Proll. Report



: Final Report

1)

Date/Time, File Return to?

2) 25/11 - typist

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS. SI

) Photos

) Others

) ..

TOTAL

240

240

Report Format :

Lump Sum / I.B.I. (\$)

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

## Summer Lee (LKK Auto)

---

**From:** Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>  
**Sent:** Wednesday, 16 October, 2019 9:07 AM  
**To:** assignments  
**Subject:** RE: TP CASES FARMED OUT TO LKK ON 15/10/2019

Hi Lkk, here is the list of the OIC names etc...

With Regards

**Theresa Vimala**  
Senior Administrator  
Motor Insurance  
[www.income.com.sg](http://www.income.com.sg)

**income**  
made different



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.  
**Find out more at [Income.com.sg/careers](http://Income.com.sg/careers)**

**in** with you

---

**From:** Theresa Vimala D/O Balagangadharan  
**Sent:** Tuesday, 15 October 2019 10:07 AM  
**To:** assignments <assignments@lkkauto.com>  
**Cc:** Teng Ken Leong <kenleong.teng@income.com.sg>; Thio Tse Kiat <tsekiat.thio@income.com.sg>; Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>  
**Subject:** RE: TP CASES FARMED OUT TO LKK ON 15/10/2019

Dear LKK,

Please assist to survey the following vehicles .

SN	OIC	Claim No.	Survey Date	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	SERENE	MT/1066803-001	15/10/2019	SID3925Z	BAN CHOON MOTOR WORKS	3 PIONEER ROAD NORTH #01-14/15 SINGAPORE 628457	Perlin / 62641191		SIW7966C	7/10	
2	CHARLOTTE	MT/1064715-002	15/10/2019	GY8801M	MOTORWAY CAR CARE CENTRE PTE LTD	1094 LOWER DELTA ROAD MOTORWAY BUILDING SINGAPORE 169205	Annie Tew / 6571 9642	10:00-12:00	SKQ8849X	30/9	
3	JEFF	MT/1064107-002	15/10/2019	XE4320P	VFIX AUTO PTE LTD	26 CHIA PING ROAD SINGAPORE 619977	Weng Sheng / 6455 2957	14:00-16:00	SIH7384K	26/9	Owner waiting
4	JEFF	MT/1066455-002	15/10/2019	SIW7856L	AUTO INSURE PTE LTD	6 MARSILING LANE	Sam Goh / 9743 6363		SIW9804D	11/10	
5	DAVID	MT/1066634-001	15/10/2019	SLN3940B	AUTO INSURE PTE LTD	6 MARSILING LANE	Geraldine Lim / 9743 6363		SGR6525K	10/10	
6	HELENA	MT/1059149-002	15/10/2019	SCG6128D	TAN CHONG MOTOR SALES PTE LTD	913 BUKIT TIMAH ROAD SINGAPORE 589623	ZUHRI / 67038916	10:00-12:00	SKZ7039B	22/8	Owner waiting
7	HUEY HUEY	MT/1062604-002	15/10/2019	GBD3120Y	TAN CHONG MOTOR SALES PTE LTD	913 BUKIT TIMAH ROAD SINGAPORE 589623	ZUHRI / 67038916	10:00-12:00	GBB3923H	16/9	Owner waiting

**Please contact workshops.**

Please revert to officer-in-charge after survey.

Thank you.

With Regards

**Theresa Vimala**  
Senior Administrator  
Motor Insurance  
T +65 6430 7898  
[www.income.com.sg](http://www.income.com.sg)



**in** with  
you

At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.  
**Find out more at [Income.com.sg/careers](http://Income.com.sg/careers)**

---

#### Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	721C
<b>Vehicle Details</b>	
Vehicle No.:	SCG6128D
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Oct 2019
Vehicle Make:	NISSAN
Vehicle Model:	QASHQAI 2.0 CVT ABS D/AIRBAG 2WD 5DR S/R
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	MR20457488W
Chassis No.:	SJNFBAJ11U1945450
Maximum Power Output:	106.0 kW (142 bhp)
Open Market Value:	\$19,507.00
Original Registration Date:	30 May 2017
First Registration Date:	30 May 2017
Transfer Count:	0
Actual ARF Paid:	\$19,507.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 May 2027
PARF Rebate Amount:	\$14,630.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	29 May 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,001.00
COE Rebate Amount:	\$40,391.00
<b>Total Rebate Amount:</b>	<b>\$55,021.00</b>

The information contained herein is correct as at 15 Oct 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	24/08/2019 12:24
Date Of Accident	22/08/2019 22:20
Exact Location Of Accident	BUKIT BATOK WEST AVE 8 JUNCTION BUKIT BATOK WEST
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SCG6128D
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TAN YOKE HONG
NRIC No	S7110721C
Email Address	POKODOY@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97822985
Alternative Phone No	OFFICE-96902419

### Vehicle Particulars

Manufacturer	NISSAN
Model	QASHQAI 2.0 CVT ABS D/AIRBAG 2WD 5DR S/R
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	10838041
Cover Note Number	N.A

### Driver

Name of Driver	TAN LI YI
NRIC No	S9923803H
Date Of Birth	25/07/1999
Occupation	INDOOR
Date Of Driving Pass	21/05/2019
Driving Experience	0 YEAR AND 3 MONTH
Gender	FEMALE
Mobile Number	(LOCAL) +65-97822985
Fax Number	
Contact Number	
EEmail Address	CHERILYNNTAN@GMAIL.COM

Address	NA
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : CELINE LIM GENDER: : FEMALE
Passenger 2	NAME: : LYNN GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

I was inside the pocket at a junction and the traffic was on red. I had to stop my vehicle. Suddenly I felt an impact from my rear vehicle. I later realised that the vehicle from my rear had hit the rear of my vehicle, We exchange particulars. No injury involved.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	NA
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKZ7039B
Vehicle Make/Model/Colour	AUDI / A4 1.4 TFSI S TRONIC / BLUE
Details Of Properties	N.A
Vehicle Category	PRIVATE CAR
Name of Driver	LOKE MUN KONG
NRIC/Passport Number	S7029711F
Contact Number	81836258
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

**SKETCH PLAN****IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
 

I understand, acknowledge, agree and consent that:

  - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
    - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
    - (ii) investigating the accident and/or my claims;
    - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
    - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
    - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
  - (b) all Insurers who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
  - (c) my Personal Information may/are be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


VERIFIED BY AJAX MARS  
REPORTING OFFICER

Mohammad Azaly Bin Abdullah

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre  
Personnel

**Sketch Plan**

TAN CHONG MOTOR SALES PTE. LTD.  
911, BUKIT TIMAH ROAD  
SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS  
WORKSHOP : BUKIT TIMAH  
CONTACT NO : 4694091  
REFERENCE : INS/IC/ZHR/0448/2019  
DATE : 13-SEP-2019

NTUC INCOME INSURANCE CO-OPERATIVE LIMITED  
73 BRAS BASAH ROAD #05-01  
NTUC TRADE UNION HOUSE  
S(189556)  
TEL : 65947060  
FAX : 63381504  
ATTN:MOTOR CLAIM MANAGER

OWNER'S NAME : MR TAN YOKE HONG (CHEN YUFENG)  
ADDRESS : 2B HONG SAN WALK  
#13-08  
S(689048)  
TELEPHONE NO : 97822985

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM  
POLICY NO : TPSKZ7039B  
VEHICLE NO : SCG6128D  
MODEL CODE : FDRARBZJ11EWAFJJ-  
MODEL/YEAR : NISSAN QASHQAI 2.0  
ENGINE NO : MR20457488W-J11WW  
CHASSIS NO : SJNFBAJ11U1945450  
MILEAGE : 1 KM  
DATE IN : 13/09/2019  
LIABILITY : 0.00  
EXCESS CLAUSE : 0.00  
ESTIMATE BY : MUHAMMAD ZUHRI  
ACCIDENT DATE : 13/09/2019

**DIRECT SETTLEMENT**

**OWNER CLAIMING LOSS OF USE / RENTAL**

**CAR AT WORKSHOP / CAR NOT AT WORKSHOP**

**KINDLY REVERT TO ME ASAP**

**EMAIL : zuhri@tanchong.com**

**OFFICE : 67038916 FAX : 64697472**

13.09.19

TAN CHONG MOTOR SALES PTE. LTD.  
BUKIT TIMAH W/SHOP  
SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SCG6128D

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 RSI	R/INSTALL OR RENEW REVERSE SENSOR,NECS ADJUSTMENT FUNCTION TEST	110.00	/
2 SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	50.00	X
3 ZZ/001	CHECK LIGHTING	48.00	/
4 ZZ/002	REPAIR RR END PANEL & RENEW RR BUMPER	560.00	280
5 ZZ/003	S/PAINT RR END PANEL & RR BUMPER (2 TONE)	600.00	350
TOTAL LABOUR CHARGES		1368.00	

TAN CHONG MOTOR SALES PTE. LTD.  
BUKIT TIMAH W/SHOP  
SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SCG6128D

		DAMAGED PARTS & PRICES			REMARKS
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	
1	SENSOR ASSY	28438-HV03A			232.00 ?
2	SUNDRIES	NPN			50.00 20
3	BRACKET-BUMPER RH ?	85220-4EA0A	38.90		
4	BRACKET-BUMPER LH ?	85221-4EA0A	38.90		
5	FINISHER-REAR B X NM	85071-4EA0A	18.80		
6	CLI(1.3X10) / NK	01553-05933	13.00		
7	CANOE RIVET(7.1X2) / NK	76882-0M000	14.20		
8	CLIP(8X3) / NK	85284-JD00A	24.00		
9	CROMMET(2.7X4) / NK	63846-5V000	10.80		
10	FASCIA-RR BUMP / CAT	85022-4EA0H	796.70		
SUB TOTAL			955.30	0.00	282.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			191.06	0.00	0.00
GRAND TOTAL			764.24	0.00	282.00
OVERALL TOTAL			1046.24		

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.  
 BUKIT TIMAH W/SHOP  
 SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SCG6128D

TOTAL LABOUR CHARGES	1368.00
TOTAL SPARE PARTS CHARGES	1046.24
GRAND TOTAL	2414.24 *

\* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

Store (LKK) will be L 15/10/19, 12.30 P  
 3 day  
 P/P  
 Ry Bel Sp

LKK Auto Consultants hence notify  
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PLS NOTE : This estimate is based on visual inspection of the  
 affected vehicle. Should we require further labour  
 charges & spare parts in the process of repairs, we  
 shall inform you accordingly.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19018161/Evf3e2

73 BRAS BASAH ROAD

Date: 04-12-2019

#05-01 NTUC TRADE UNION HOUSESINGAPORE

189556



ATTN : HELENA

Code: INC

#### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKZ 7039B	Veh. Inspected	SCG 6128D
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1059149-002	Excess (\$)	0.00
Assign From	THERESA VIMALA	Assign Date	15/10/2019

#### 2. Vehicle Particulars & Condition

Make & Model	NISSAN QASHQAI	c.c	1997
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	SJNFBAJ11U1945450	Colour	GREY
Odometer	62672 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

#### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R19	BRIDGESTONE	5 mm
L/H Front Tyre	225/45 R19	BRIDGESTONE	5 mm
R/H Rear Tyre	225/45 R19	BRIDGESTONE	5 mm
L/H Rear Tyre	225/45 R19	BRIDGESTONE	5 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

#### 5. General Information

Accident Date	22/08/2019	Inspect Date / Time	15/10/2019 ( 12:12 PM )
Survey held at	913 BUKIT TIMAH ROAD		
Repairer	TAN CHONG MOTOR SALES PTE LTD		

#### 5a. Remarks

A)THE VEHICLE HAS NOT SEND IN FOR REPAIRS. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SCG 6128D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	BRACKET-BUMPER RH (N)	* CHECK	38.90	-
1	BRACKET-BUMPER LH (N)	* CHECK	38.90	-
1	FINISHER-REAR B (N)	NOT NECESSARY	18.80	-
10	CLI @\$1.30 (N)	NECESSARY	13.00	13.00
2	CANOE RIVET @\$7.10 (N)	NECESSARY	14.20	14.20
3	CLIP @\$8.00 (N)	NECESSARY	24.00	24.00
4	CROMMET @\$2.70 (N)	NECESSARY	10.80	10.80
1	FASCIA-RR BUMP (N)	CUT	796.70	796.70
	LESS 20% DISCOUNT		-191.06	-171.74
			764.24	686.96
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SENSOR ASSY (SN)	* CHECK	232.00	-
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
			282.00	20.00
<b><u>LABOUR</u></b>				
	R/INSTALL OR RENEW REVERSE SENSOR, NECS ADJUSTMENT FUNCTION TEST.		110.00	110.00
	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA.	NOT NECESSARY	50.00	-
	CHECK LIGHTING.		48.00	48.00
	REPAIR RR END PANEL & RENEW RR BUMPER.		560.00	280.00
	S/PAINT RR END PANEL & RR BUMPER (2 TONE).		600.00	350.00
			-	-
			-	-
			-	-
			-	-
			1,368.00	788.00
<b>GRAND TOTAL</b>			<b>2,414.24</b>	<b>1,494.96</b>



RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$294.24 NETT)			1,494.96
---	--	--	----------

Report Ref No. CS/INC19018161/Evf3e2

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.