

INS. CASE OWNER:

CC4/LPC1901 8182, K663/2

LKK:
IDAC:

Surveyor:

tsc

DOI:

ASSIGNMENT

19/10/19

Date / Time:

14/10/19

Registered in Merimen:

Pre-assign / CCU / FTE

GBB 84854



Insured Vehicle No.:

Claim No.:

19/10/19/1605/02501

Name of Insured:

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :\$S

D.O.A.:

10/10/19

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SGW 80m L

INSRS:
WSP:
Tel:
Liability:
RMKS:WSP
111INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

14/10/19 - X

14/10/19 - X

STAGE

DATE / PIC

Non-Reporting hr (1st):

Non-Reporting hr (2nd):

Non-Reporting hr (Final):

Notification hr (if non-pickup):

Call OI:

After call hr to OI:

Documentation Check List: Handler Typist

Notification hr (if non-pickup)

After call hr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

45 \$S 1,750

(3 days) Reduction:

46 %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

\$S

Loss of Rental (LOR):

\$S

(days)

Loss of Use (LOU):

\$S

(\$ x days)

Loss of Income (LOI):

\$S

(\$ x days)

LOR only ☐LOU only ☐LOR + LOU ☐LOR + LO ☐

(Tick only one)

GIA/LTA Search

\$S

Medical:

\$S

Disbursement:

\$S

(e.g. Tow/ Independent)

Legal Cost

\$S

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$350

Total:

\$S

Global Sum \$S:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

\$S

Name 1:

Payee 2: (Strike if N.A.)

\$S

Name 2:

Payee 3: (Strike if N.A.)

\$S

Name 3:

Excluded LOR - ask to submit
WP. Informed to submit
claim to lawyer - 13/11/19

ASS. REC. BY:

REF: LPC/

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frit / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

File pass to

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐

: Prell. Report

☐

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS - SI

F - RS

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.
TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 289438/00J

12.OCT 2019

Lonpac Insurance BHD
100 Beach Road #19-00
Shaw Tower
S 189702

Attn : Motor claim dept-3rd party claim
Claiming against your insured vehicle no: G888485Y
Accident involving vehicle no: SJW8025L/G888485Y
DOA: 10/10/2019 AT Moulmein Road exit TO CTE

Dear officer incharge
Re: Estimate cost of repair to SJW8025L
To supply—

Description	Qty	Amount
Rear bumper	1 CM	862.00 N ✓
Rear bumper reflector	1 R	76.00 N X
Rear bumper retainer @23N	2 R	46.00 N X
End panel	1 R	506.00 N X
Rear bumper tow cover	1 R	46.00 N ✓
Rear bumper lower	1 R	392.00 N ✓
Parts		1,928.00 N
Nett parts less 10%		192.80
		1,735.20

Reverse sensor
Rear number plate w bracket
To remove damaged parts and attachments
Repair/reshape dented areas
Replace/align all parts into position
To spray paint

CM 220.00 200N
R 60.00 45N

700.00 350
500.00 450

3,215.20

**Please arrange to survey the vehicle-ASAP,thank you



Karen
6456 9830

LXX Auto Consultants hence notify the Repairer of the following:

- To survey (submitter) spray painting
- To display damaged parts during survey
- Parts prices are subject to confirmation
- Third party survey is also "Without Prejudice" basis
- An (original) quotation is allowed
- Supplementary items must be included and request to be approved from Insurance Company

Authorised by Repairer
Signature:
Date:

Not Authorised
L/Ring @ 1750h
Merry After Paint
3 days



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC4/LPC19018182/Kkb3

Date: 16.10.2019

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SJW8025L

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 15.10.2019 at the premises of M/s Wei Lee Motor Works and have the following to report:-

Workshop Estimate Amount	: S\$	3,215.20
Revised Estimate Amount	: S\$	1,750.00
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:
The vehicle sustained damages at the
Rear Portion



Comments/Present Status:
Damages Consistent
Estimated normal period for repairs: 3 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.
TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

12, OCT 2019

Lonpac Insurance BHD
100 Beach Road #19-00
Shaw Tower
S 189702

*Not Authorised
C/L Rep @ 1750h
Mummy After Paint
3 days*

Attn : Motor claim dept-3rd party claim
Claiming against your insured vehicle no: GBB8485Y
Accident involving vehicle no: SJW8025L/GBB8485Y
DOA: 10/10/2019 AT Moulmein Road exit TO CTE

Dear officer incharge
Re: Estimate cost of repair to SJW8025L
To supply—

Description	Qty	Amount
Rear bumper	1 <i>CM</i>	862.00 N ✓
Rear bumper reflector	1 <i>R</i>	76.00 N X
Rear bumper retainer @23N	2 <i>R</i>	46.00 N X
End panel	1 <i>R</i>	506.00 N X
Rear bumper tow cover	1 <i>Mit</i>	46.00 N ✓
Rear bumper lower	1 <i>Red 1 Bu</i>	392.00 N ✓
Parts		1,928.00 N
Nett parts less 10%		192.80
		1,735.20

Reverse sensor
Rear number plate w bracket
To remove damaged parts and attachments
Repair/reshape dented areas
Replace/align all parts into position
To spray paint

*CM 220.00 200N
R 60.00 45N*

*700.00 350
500.00 450*

3,215.20

**Please arrange to survey the vehicle-ASAP,thank you



*Karen
6456 9830*

OKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Witness Presider" basis
- No legal implication(s) is allowed
- Supplementary invoice must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

813C

Vehicle Details

Vehicle No.:

SJW8025L

Vehicle to be Exported:

Yes

Intended Deregistration Date:

25 Oct 2019

Vehicle Make:

MITSUBISHI

Vehicle Model:

LANCER 1.5 MIVEC SPORTS AT ABS D/AB

Primary Colour:

Black

Manufacturing Year:

2010

Engine No.:

4A910142957

Chassis No.:

JMYSRCY2AAU001461

Maximum Power Output:

80.0 kW (107 bhp)

Open Market Value:

\$17,666.00

Original Registration Date:

21 Apr 2010

First Registration Date:

21 Apr 2010

Transfer Count:

2

Actual ARF Paid:

\$17,666.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

20 Apr 2020

PARF Rebate Amount:

\$8,833.00

Intended COE Rebate Details

COE Expiry Date:

20 Apr 2020

COE Category:

A - Car (1600cc & below)

COE Period(Years):

10

QP Paid:

\$28,389.00

COE Rebate Amount:

\$1,386.00

Total Rebate Amount:

\$10,219.00

The information contained herein is correct as at 12 Oct 2019

OK

Nivitha (LKK Auto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Monday, 14 October 2019 12:38 PM
To: assignments@lkkauto.com
Cc: MT_Claim_SG; weileemotorworks@gmail.com
Subject: FW: ACCIDENT INVOLVING GBB8485Y & SLW8025Y ON 10.10.2019 [External Confidential]

Lonpac External - Confidential

Dear Nivitha,

Kindly proceed as requested.

P: Karin

T: 1.17p.m

V: In

E: ✓


Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



Lonpac External - Confidential data is for use by authorised external parties only.

From: karen Seah [mailto:weileemotorworks@gmail.com]
Sent: Monday, 14 October, 2019 12:30 PM
To: GERALD POH WEE BIN
Subject: Re: ACCIDENT INVOLVING GBB8485Y & SLW8025Y ON 10.10.2019 [External General]

Vehicle no: SJW8025L

Hi gerald

We would like to have Kenneth (Kenneth.kong@LKK) to survey the vehicle.

Thank you.

On Mon, Oct 14, 2019 at 12:05 PM GERALD POH WEE BIN <geraldpoh@lonpac.com> wrote:

Lonpac External - General

WITHOUT PREJUDICE

Our Ref : 19/19/19/VC05/022501

Dear Karen,

We append the list of our Motor surveyors for your attention:-

1	Sharan Bin Sharif
2	Jackson Quek
3	Paul Thanapal
4	Aw Po Huat (Andrew)
5	Nicholas Tey
6	Mohd Taufik
7	Kenneth
8	Marcus Chua
9	Mohd Rasul
10	Adrian Ling

Please revert.


Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

--
Best Regards,

Karen Seah

Wei Lee Motor Works
Block 9 Sin Ming Industrial Estate
#01-32 Singapore 575644
Tel: 6456 9830
Fax: 6458 0128
Company registration: 269436/00J

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC19018182/Kkb3q2

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 27-11-2019



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBB 8485Y	Veh. Inspected	SJW 8025L
Policy No.		Coverage (\$)	0.00
Claim No.	19/19/19/VC05/022501	Excess (\$)	0.00
Assign From	GERALD	Assign Date	14/10/2019

2. Vehicle Particulars & Condition

Make & Model	mitsubishi LANCER EX (A)	c.c	1499
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	JMYSRCY2AAU001461	Colour	METALLIC BLACK
Odometer	216577	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	CONTINENTAL	4 mm
L/H Front Tyre	205/60 R16	CONTINENTAL	4 mm
R/H Rear Tyre	205/60 R16	CONTINENTAL	8 mm
L/H Rear Tyre	205/60 R16	CONTINENTAL	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	10/10/2019	Inspection Date	15/10/2019
Survey held at	WEI LEE MOTOR WORKS BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 SINGAPORE 575644.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJW 8025L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (N)	CRACKED	862.00	862.00
1	REAR BUMPER REFLECTOR (N)	SERVICEABLE	76.00	-
2	REAR BUMPER RETAINER @\$23.00 (N)	SERVICEABLE	46.00	-
1	END PANEL (N)	TO REPAIR SEE LABOUR	506.00	-
1	REAR BUMPER TOW COVER (N)	MISSING	46.00	46.00
1	REAR BUMPER LOWER (N)	DENTED / BUCKLED	392.00	392.00
	LESS 10% DISCOUNT		-192.80	-130.00
			1,735.20	1,170.00
SPECIAL NETT ITEMS				
1	REVERSE SENSOR (SN)	CRACKED	220.00	200.00
1	REAR NUMBER PLATE W BRACKET (SN)	BENT	60.00	45.00
			280.00	245.00
LABOUR				
	TO REMOVE DAMAGED PARTS AND ATTACHMENTS REPAIR/RESHAPE DENTED AREAS REPLACE /ALIGN ALL PARTS INTO POSITION.INCLUSIVE OF THE REPAIR OF END PANEL.		700.00	350.00
	TO SPRAY PAINT.		500.00	450.00
			1,200.00	800.00
GRAND TOTAL			3,215.20	2,215.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,750.00

Report Ref No. CC4/LPC19018182/Kkb3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.